

PAGE: 1/1

Reissued: 18-Feb-08

| rtoloodod: 10 l | 00 00 | | | | |
|--|---------------------------|-----------------|-------------------------|----------------------|--|
| Model: Campa | ri-MF1L | D | ate: 04-Oct-06 | No.: G959001b | |
| RTB Reissue The items in bol | d italics have been ch | anged. | | | |
| Subject: Firmwar | re Release History(Engine | Prepared by: T. | Prepared by: T.Shintani | | |
| From: 1st Tech. S | Support Sec. Service Supp | oort Dept. | | | |
| Classification: | Troubleshooting | ☐ Part inform | nation | on required | |
| | ☐ Mechanical | ☐ Electrical | ☐ Serv | rice manual revision | |
| | ☐ Paper path | ☐ Transmit/r | eceive | ofit information | |

Other (

This RTB has been issued to announce the firmware release information for the Engine.

| Version | Program No. | Effective Date |
|---------|-------------|---------------------------|
| 6.05 | G959605 | February 2008 production |
| 6.04 | G959604 | January 2008 production |
| 6.00 | G959600 | September 2006 production |

☐ Product Safety

| Version | Symptom Corrected |
|---------|---|
| 6.05 | Symptom corrected: Scanner Lock problem happened while closing the print cover after "Initializing" and doing "PC scan" or "Memory stick scan". Output format of fonts does not align with table in form printing. (GFPR#RA07040001) Abnormal printing of ruled lines in form printing. (GFPR#RA7060001) |
| 6.04 | Minor changes applied. |
| 6.00 | 1st Mass Production |

RICOH

Technical Bulletin

PAGE: 1/2

| Model: Campari-MF1L | | | Dat | Date: 27-Mar-07 | | No.: RG959002 |
|--|-------------------|-------------|----------|-----------------|-----------|--------------------|
| Subject: Countermeasure for Machine stall problem | | | Prepared | d by: T. S | Shintani | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | | | | |
| Classification: | ☐ Troubleshooting | ☐ Part info | ormat | tion | | required |
| | | ☐ Electric | al | | ☐ Service | ce manual revision |
| | ☐ Paper path | ☐ Transm | it/rec | eive | ☐ Retrof | fit information |
| | ☐ Product Safety | Other (| |) | | |

Symptom

The machine stalls just before printing out a fax. "Printing..." or "Please Wait..." is then displayed on the operation panel.

Note:

- In some cases, the condition cannot be cleared by turning the main power off/on.
- This symptom has only been reported in the NA and EU markets. This has not been reported in the China or Asia markets.

Cause

Firmware specification.

Solution

Production line:

The firmware was modified to correct this symptom.

Applied from: Feb. 2007 production (see below for cut-in S/N).

New versions:

C1: Ver. 6.10 **C1L: Ver. 6.04**

Warehouse stock:

The modified firmware has been installed in some machines in warehouse stock (see S/N below).

Machines in the field:

1. In as many cases as possible, request customers to upgrade the firmware to the new versions mentioned above.

Note: The Printer Setting Utility necessary to do the procedure is already contained in the CD-ROM provided with the machine. (The firmware upgrade procedure for customers will be provided).

2. If the customers cannot upgrade the firmware by themselves, send a CE to the site to upgrade the firmware.

Note: See the Firmware Upgrade Procedure for CEs on the next page.

- 3. For customers whom you cannot contact, send a CE to the site to upgrade the firmware if these customers report the symptom.
- 4. If the machine condition is such that the firmware upgrade cannot be performed:
 - Replace the main board, or
 - Turn the machine off and leave it unused for at least 43 hours



PAGE: 2/2

Model: Campari-MF1L Date: 27-Mar-07 No.: RG959002

Firmware Upgrade Procedure

- 1. Turn the machine main power switch on.
- 2. Connect the PC to the machine with a USB cable.
- 3. Open the Printer Setting Utility on the PC.
- 4. Upgrade the firmware to the latest version (see version names above).
- 5. Press the following keys, in order: Menu \rightarrow # \rightarrow 1 \rightarrow 9 \rightarrow 3 \rightarrow #
- 6. If the new firmware version is displayed, push the "Clear/Stop" button.
- 7. If the new firmware version is not displayed, do Steps 2-6 again.

If you need more information to do this procedure, see the Service Manual.

Serial Number Information

The new firmware is installed on the following machines:

Production line:

Product code: Q959 -17 -27 -21 -29 From **Q9178600001** onward

Warehouse stock:

Product code: Q959-17

Warehouse in Japan: **Q9169600001 to Q9169600360** (360 machines)

Warehouse in N.A. (REI): All machines with two blue labels () attached near the

barcode on the outer box (1.116 machines).

• Product code: G959-27

Warehouse in EU (BoZ): All machines with two blue labels () attached near the

barcode on the outer box (4,318 machines).

RICOH

Technical Bulletin


| P | Α | G | E | : | 1 | ľ |
|---|---|---|---|---|---|---|
| | | | | | | |


| Model: Model CM-C1L | | | Date: 24-Jul-09 | | 09 | No.: RG959003 |
|--|--|---|-----------------|-----------------------|---------|---|
| Subject: Scanner Unit (Scanner Assembly) | | | | Prepared by: Y. Gaman | | |
| From: 1st Tech. 9 | Support Sec. Service Support D | Dept. | | | | |
| Classification: | ☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety | ☐ Part info ☐ Electric ☐ Transm ☐ Other (| al | | Service | n required ce manual revision fit information |

Change: The lower scanner cover was deleted and the scanner unit was newly registered. **Reason:** The parts vendor stopped supplying the cover as an individually replaceable part.

B273/G959

| Old part | New part | Description | Q'ty | Int | Page | Index | Note |
|----------|----------|-----------------------|------|-----|------|-------|------|
| number | number | | | | | | |
| | B2739810 | Scanner Unit | 1 | - | 15 | * | |
| B2739582 | | Cover - Scanner Lower | 0 | - | 15 | 13 | |





RICOH

Technical Bulletin

| PA | G | E: | 1 | 11 |
|----|--------|----|---|----|
| | \sim | | | |


| Model: CM-C1L | | | Date: 21-Aug-09 | | -09 | No.: RG959004 |
|---------------------------------------|--------------------------------|--------------------|-----------------|------------|-------|----------------------------------|
| Subject: Exit Roller (Frame Assembly) | | | Prepare | d by: Y. C | Gaman | |
| From: 1st Tech. | Support Sec. Service Support | Dept. | | | | |
| Classification: | ☐ Troubleshooting ☐ Mechanical | ☐ Part information | | tion | | n required ce manual revision |
| | ☐ Paper path ☐ Product Safety | ☐ Transm | it/rec | eive) | | fit information |

Change: The assembly in the table below (P/N H9149725) was divided into two parts.

Reason: The Parts Catalog was corrected.

<G959>

| Old Part Number | New Part Number | Description | Q'ty | Int | Page | Index | Note |
|--------------------|--------------------|------------------|------|-------|------|-------|------|
| H9149725 | H9149725 | EXIT ROLLER POLE | 1 | 0/0 | 14 | 38→48 | |
| 119149723 | G1449752 | EXIT ROLLER | 4 | . 0/0 | 14 | 38→49 | |



| K | JH |
|---|----|

PAGE: 1/2

| Model: CM-C1L | | | Date: 02-Jun-10 | | No.: RG959005 |
|------------------|------------------------------|-------------|-----------------|--------------|------------------------|
| Subject: Parts (| Catalog correction | | | Prepared by: | K. Nakano |
| From: 2nd Overs | eas Tech Support Sec. 2nd Po | QM Dept | | | |
| Classification: | ☐ Troubleshooting | ⊠ Part info | ormat | tion 🗌 Ac | tion required |
| | ☐ Mechanical | ☐ Electric | al | ☐ Se | ervice manual revision |
| | ☐ Paper path | ☐ Transm | it/rec | eive 🗌 Re | etrofit information |
| | Other () | | | ☐ Tie | er2 |

Change: The following service parts are added.

Reason:

Requests from the field.


| New Part # | Description | Q'ty | Page | Index | Note |
|------------|----------------------------|------|------|-------|------|
| G9601101 | IDEAL GEAR MA ASS'Y (RoHs) | 1 | 17 | 19 | |
| B1739804 | GEAR DRIVE16 | 1 | 17 | 20 | |
| G1449609 | GEAR 25/15 | 1 | 17 | 21 | |
| G1449729 | SPRING - BEARING | 2 | 17 | 22 | |

8.FUSING UNIT ASSEMBLY (B273)



Date: 02-Jun-10 No.: RG959005

PAGE: 2/2



| | п |
|--|---|

PAGE: 1/1

| Model: CM-C1L | | Date: 06-Sept-10 | | 0 | No.: RG959006 | |
|---|-----------------|------------------|------------------------|-------|---------------|-------------------|
| Subject: Parts Catalog correction | | | Prepared by: K. Nakano | | | |
| From: 2nd Overseas Tech Support Sec. 2nd PQM Dept | | | | | | |
| Classification: | Troubleshooting | □ Part informat | | ion | | required |
| | ☐ Mechanical | ☐ Electric | al | | Servic | e manual revision |
| | ☐ Paper path | ☐ Transmit/rec | | ceive | | fit information |
| | Other () | | | | Tier2 | |

Change: The following parts' descriptions are corrected.

| Old / New Part # | G1449705 / G9601032 | H9149713 / G9601031 | | |
|------------------|---------------------------|---------------------------|--|--|
| Old Description | Solenoid – Pick Up (RoHs) | Solenoid – Bypass (RoHs) | | |
| New Description | Solenoid – Bypass (RoHs) | Solenoid – Pick Up (RoHs) | | |
| Int. | O/O | O/O | | |
| Page | 15 | 15 | | |
| Index | 29 | 30 | | |
| Part's image | | | | |
| Note | Yellow wire is attached | | | |

Reason:

The parts' descriptions and the parts' actual functions do not match each other.