RIGON **Technical Bulletin** No. RTB-001 SUBJECT: Service manual correction DATE:Nov. 15, '96 PAGE: 1 of 4 PREPARED BY: T. Itai FROM: 2nd Field Information Dept. QAC CHECKED BY: S. Fujii **CLASSIFICATION:** MODEL: AD1 Revision of service manual Information only ☐ Troubleshooting Retrofit Information Other

The following parts of the service manual have been corrected.

1. Copying Speed in Multicopy mode, page 1-2

- Wrong -

	A4 sideways/ 11"x8 _{1/2} "	A3/11"x17"	B4/8 _{1/2} "x14"
No optional memory	15	9	10
With 4MB or 8MB optional memory	20	11	12

- Correct -

	A4 sideways/ 11"x8 _{1/2} "	A3/11"x17"	B4/8 _{1/2} "x14"
Non-memory copy mode (1 to 1 copy)	15	9	10
Memory copy mode	20	11	12

2. COPY PROCESS, Overview, page 1-12

The discharge brush bias has been changed from +2 kV to - 2 kV.



No. RTB-001

SUBJECT: Service manual correction

DATE: Nov. 15, '96 PAGE: 2 of 4

3. ORIGINAL SIZE DETECTION IN PLATEN MODE, page 2-4 Second paragraph from the bottom, second sentence

- Wrong -

This can cause excess toner to be transfered to the transfer roller, so users should be instructed to always set the paper lengthwise on the by-pass tray. This problem occurs for the first page only. The registration sensor detects the length of the first page, and will assume that the following sheets of copy paper are the same length.

- Correct -

However, in this machine, for each page, the data signal to the laser diode is stopped to match the copy paper length detected by the registration sensor.

4. LASER EXPOSURE, Overview, page 2-18 The polygon motor speed

	Resolution (dpi)	Modes
Wrong	400 dpi	Copy, Fax, and Printer
Correct	400 dpi	Copy and Printer

5. PAPER SEPARATION AND TRANSPORTATION, page 2-57 First paragraph, second sentence

- Wrong -

The high voltage supply board [B] applies a constant dc voltage, +2 kV (When), or +2.5 kV (from......) to the discharge brush.

- Correct -

The high voltage supply board [B] applies a constant dc voltage, **-2 kV** (When), or **-2.5 kV** (from......) to the discharge brush.

6. ENERGY SAVER MODE, COPIER/PRINTER, page 2-66 In the block diagram

- Wrong -

Auto Shut Off Mode

CPU/GAPD On

- Correct -

Auto Shut Off Mode

CPU/GAPD Off



No. RTB-001

SUBJECT: Service manual correction

DATE: Nov. 15, '96 PAGE: 3 of 4

7. Power Consumption, page 2-70 Note column for Night Mode Level 2

- Wrong -

If an incoming call (ringing signal) is detected, or if the user tries to send a fax, the machine goes into Night Mode Level 1.

- Correct -

If an incoming call (ringing signal) is detected, the machine goes into Night Mode Level 1.

8. SP mode no. 4-417, page 4-16

	Wrong	Correct
no. 7	SBU Test 1	No function
no. 8	SBU Test 2	
no. 9	SBU Test 3	

9. PM TABLE

The discharge brush should be treated as a PM part.

AROUND THE DRUM						
EM 100k 200k 300k NOTE						
Discharge Brush		R	R	R		




No. RTB-001

SUBJECT: Service manual correction

DATE: Nov. 15, '96

PAGE: 4 of 4

11. MSU BOARD/BICU BOARD, page 6-36The callouts should be corrected as follows.



RIGOH	Technical Bulletin		No. RTB-002			
SUBJECT: Caution about not m	nixing different size originals with l	DF-43	DATE: Nov. 15, '96 PAGE: 1 of 1			
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	FROM: 2nd. F	ield Info	ormation Dept. QAC			
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of service manual Information only Other	MOD	EL: AD-1			
Instruct customers not to the DF-43.	mix different size originals whe	n feedir	ng them with			
Note: The same width of comode only.	originals, such as A4 and A3, can	be mixe	ed in facsimile			
Reason:						
original table. Therefore, wh	size will be detected when the or en mixing different size originals of be used for all pages of the origin	on the ta				
Symptoms when mixing d	ifferent original sizes:					
In copying mode: - The machine will select the copy paper size to match the maximum original size In auto reduce/enlarge mode with the designated copy paper size, the reproduction ratio will be selected to match the maximum original size.						
In facsimile mode: - When mixing the same wide properly.	dth of originals, the facsimile trans	mission	will be made			
 If mixing originals with diffe 	erent widths, the originals with a s argin at the left end, as originals v	maller w	vidth will be canned with the			

REVISED ON: NOVEMBER 30, '96

RIGON

Technical Bulletin

No. RTB-003 (V2.0)

SUBJECT:	Black Dot reproduction can be reduced	DATE: Nov. 30, '96
		DAGE 4 60

PAGE: 1 of 3

CHECKED BY: S. Fuiii

PREPARED BY: T. Itai for

FROM: 2nd. Field Information Dept. QAC

CLASSIFI	CATION:
----------	---------

Action Required

Troubleshooting

Retrofit Information

Information only

Other

MODEL:

AD-1

If there are black dots on the copy, especially when making generation copies, take the following countermeasures.

Causes:

- 1. The AD-1 scanner is very sensitive, so it will reproduce tiny specks on the exposure glass or faint dots on a original in the copy.
- 2. When using the document feeder, the DF exposure glass may be smudged from originals.

Recommended Measures:

1. Change the MTF filter and Threshold level settings as follows.

	SP Mode	Default Setting	Recommended Setting as a Countermeasure
MTF Filter	4-407-2*	7	4
Threshold Level	4-418-1	48	55

- * :The current MTF Filters (SP modes 4-407-1 to 4) are for greyscale mode. Fax mode always uses binary mode (refer to page 13 of the copier's operating instructions) so these filters have no influence on fax mode.
- *: With the new version of the ROM, new MTF filters have been added for text mode with binary picture processing (Black and White text originals), and they are independent of the above filters. Refer to "Additional Information" in this RTB.

REVISED ON: NOVEMBER 30, '96

RIGOH

Technical Bulletin

No. RTB-003 (V2.0)

SUBJECT: Black dot reproduction can be reduced

DATE: Nov. 15, '96

PAGE: 2 of 3

2. After changing the MTF filter and Threshold level, if you still find an unacceptable level of black dots on the copy, or poor reproduction of a low contrast original, such as one written in pencil, do the following.

Change the MTF filter and Threshold levels by referring to the following table. A table value of "0" is the result of using the settings recommended on the previous page (MTF Filter: 4, Threshold: 55). The default setting is "+5" (MTF Filter: 7, Threshold: 48).

- Using a lower table value decreases the amount of black dots, but will reduce the reproduction of low contrast originals.
- Increasing the value will increase the reproduction of low contrast originals, but black dot reproduction will also increase.

		(Weak)	\leftarrow MTF Filter \rightarrow		(Strong)
		0	4	7	6
(High)	64	-7	-5	-2	-1
1	55	-6	0	+1	+3
Threshold	48	-4	+2	+5	+7
↓ (Low)	40	-3	+4	+6	+8

3. If you find black dots when using the document feeder, clean the exposure glass.

ADDITIONAL INFORMATION:

With the new ROM version (ROM version E for North American models or D for European models), the following two MTF filters have been added for text mode with binary picture processing (designated for black/white text mode). The current filters of SP Modes 4-407-1 to 4 are for text mode with grayscale processing. Use these SP Modes with the new ROM version for binary picture processing mode.

- 1) SP Mode 4-407-8: For reproduction ratios of 25 % 83% (use the table below)
- 2) SP Mode 4-407-9: For reproduction ratios of 84% 400% (use the above table)

		(Weak)	← MTF	Filter \rightarrow	(Strong)
		2	0	4	7
(High)	64	-6	- 4	-1	+1
1	55	-5	0	+2	+4
Threshold	48	-3	+3	+6	+8
↓ (Low)	40	-2	+5	+7	+9

REVISED ON: NOVEMBER 30, '96

RIGOH

Technical Bulletin

No. RTB-003 (V2.0)

SUBJECT: Black dot reproduction can be reduced

DATE: Nov. 15, '96 PAGE: 3 of 3

The new ROM and the change of the default settings (described in "Recommended Measures") have been incorporated into the production machines as follows.

Model Code	Model	Production Machine	Serial Number
A193-10	Nashuatec	November	A106110001
A193-15	Savin	October	6A76100001
A193-17	Ricoh-North America	October	A7226100001
A193-55	Lanier	November	L5026110001
A193-27	Ricoh - EU	October	A72226100531

RIGOH	Technical	Bulletin		No. RTB-004
SUBJECT: Perform TD Sense installation	or Intial Setting (SF	9 mode 2-801) at		DATE: Nov. 15, '96 PAGE: 1 of 1
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	July D	FROM: 2nd. Fie	eld Info	rmation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of s	service manual only	MODI	EL: AD-1
At installation of the AD-1, perform the TD Sensor Initial Setting as shown below before making copies. Problems:				
The following problems may occur when the TD Sensor Initial Setting is not done at the time of installation for the AD-1.				
1. Blank areas at 20 mm machine).	intervals at the rig	ht end of copies (rear er	nd of the

- 2. Smearing on copies
- 3. Dirty Background
- 4. SC 393

Causes:

- 1. The developer supply level in the development unit does not become uniform until after about 30 seconds of mixing after setting the PCU.
- 2. The Q/M (charged level) of the developer does not become stable until after running 20 A3 or DLT copies.
- 3. The detection of the TD sensor is unstable until the developer supply level in the development unit becomes uniform, causing excessive toner supply.

Measures:

- 1. Before making copies, perform the TD Sensor Initial Setting by using SP Mode 2-801. Refer to page 4-9 of the Service Manual.
- 2. After completing the TD Sensor Initial Setting, make 20 copies of A3 or DLT size.

RIGOH	Technical	Bulletin		No. RTB-005
SUBJECT: Operation Procedur while making memo		ssion of fax mess	ages	DATE: Nov. 15, '96 PAGE: 1 of 1
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	July	FROM: 2nd. Fie	ld Info	rmation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	☐ Revision of s☐ Information of S☐ Other	service manual only	MOD	EL: AD-1
Instruct the customers to to while making memory copi		steps to transm	nit facs	simile mail
Problem :				
Multiple copying with the me following sequence when tra	mory copy operatinsmitting fax mes	on will be susper sages while copy	ided ui	nder the
1. Place the facsimile origin	nal in the documer	nt feeder.		
2. Switch the mode to facsi	mile transmission			
Reason:				
The AD-1 recognizes the original then suspends the current m		the feeder as a	copyin	g operation, so it
Measure:				
Instruct the customers to swithe document feeder.	tch the mode to fa	acsimile first, then	place	the original in

RIGOH	Technical	Bulletin		No. RTB-006
SUBJECT: Use the face-up tra- labels , or OHP she		hick paper, post o	cards,	DATE: Nov. 15, '96 PAGE: 1 of 1
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	John John Marie Control	FROM: 2nd. Fie	eld Info	rmation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MOD	EL: AD-1
Instruct customers to use 157 g/m2 , or 21 to 42 lbs)	the face up tray post cards, labe	when copying or els, or OHP shee	n thick ts.	paper (81 to
Note: This instruction is not written in the Operating Instructions. Instruct your customers at installation or at the next visit.				
Problem: When copying those kinds of paper using the face down tray, paper jams occur.				
when copying those kinds o	n paper using the	race down tray, p	aper ja	ams occur.

RIGOH	Technical	Bulletin		No. RTB-007	
SUBJECT: SC900 (Total Cour (fuse #5 on the PS	•	by blown fuse		DATE: Nov. 30, '96 PAGE: 1 of 1	
PREPARED BY: T. Itai CHECKED BY: S. Fujii	13417	FROM: 2nd Fiel	ld Infor	mation Dept. QAC	
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	☐ Revision of ☐ Information ☐ Other	service manual only	MOD	EL: AD -1	
When SC900 (Total Counter Error) occurs, check whether or not fuse #5 of the PSU has blown out. Add "Fuse #5 of the PSU has blown out" into your service manual as one of the possible causes of SC900.					
Fuse #5 is located at the upper left of the PSU board. The second of the 3 fuses is fuse #5.					
Caution: The fuse may be blown our while the power switch is o disconnecting the connectors.	n. Be sure to turn	of the paper tray u	init is c	disconnected fore	

RIGOH	Technical	Bulletin		No. RTB-008
SUBJECT: Cautions when setting	ng up the copier a	t your office		DATE: Nov. 30, '96 PAGE: 1 of 1
PREPARED BY: T. Itai CHECKED BY: S. Fujii		FROM: 2nd Fie	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MOD	EL: AD-1
Before installing the AD-1 at precautions.	the customer's of	fice, please take	the foll	owing
Perform TD Sensor Initial tape. Do not transport the when the seal is removed.	copier without pe	oving the develop rforming TD sens	ment u sor initia	nit sealing al setting
2. Do not set the toner bottle	into the holder.	Install it at your c	ustome	er's office.
When you run test copies, copies should not be high				
Reason :				
If the precautions listed above the Q/M (charge level) of the supply and toner scattering r	developer has st	abilized, causing	excess	sive toner
If the precautions have not b -Clean up the scattered tone -You may find dirty backgrou	r.	eral pages.		

Technical Bulletin

PAGE: 1/1

MB Correction

Reissue date: 15-May-97

The items in bold italic have been corrected or added.

Model: AD-1 (DF43) Date		e: 15-May-97		No: 9		
Subject: Replacement of the Original Holder Sheet		Prepared by: M.Horiike				
From: QAC 2nd I	Field Information Dept.					
Classification:	Troubleshooting	☐ Part inf				n required
	☐ Mechanical	☐ Electric	aı	∐ Se	ervi	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive 🗌 R	etro	fit information
	☐ Other ()					

When the original holder sheet (P/N A6281615) needs to be changed, paste a new sheet over the current one.

Note:

The maximum number of sheets that can be pasted on top of each other is limited to two. When it necessary to paste more sheets (1 original sheet and 2 pasted sheets), please replace the following 3 parts at the same time.

- -Original Holder Bracket (A6281613)
- -Original Holder Pad (A6281614)
- -Original Holder Sheet (A6281615)

RIGOH	Technical	Bulletin		No. RTB-010
SUBJECT: Caution when feeding	g a folded or curl	ed original		DATE: Nov. 30, '96 PAGE: 1 of 1
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	July D	FROM: 2nd Field	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MOD	EL: AD-1 (DF43)
Instruct customers to proceed curled original.	I in the following	manner when fee	ding a	folded or
Problem: When feeding a folded or cur Original jam may occur. Set xxx paper in tray" or	•	rg. size." message	e appe	ars.
Causes: 1. A folded or curled origina 2. The tail end of originals is 3. The original length senso	s held up while pi	ressing Start butto	on.	
Reason: When feeding a folded or cur leading to a gap between the the length sensor cannot deter	original and the	paper length sens	inal ma sor. In	ay not lay flat, this condition,
Measures :				
 When copying a folded or -Use the platen cover instering -Straighten the originals be 	ead of the docume		ıble.	
 When a defective sensor n Check to see whether the original table by using SP 	LCD displays the	e same original si	ze as i	s set on the

RIGOH	Technical	Bulletin	I	No. RTB-011
SUBJECT: SC120 after transpor	ting the copier			DATE: Nov. 30, '96 PAGE: 1 of 2
PREPARED BY: T. Itai CHECKED BY: S. Fujii for	13419	FROM: 2nd Fie	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of s	service manual only	MODI	EL: AD1

SC120 may occur after:

- the copier was transported, or
- the scanner rear cover was removed and placed back on.

If either of these conditions occur, please take the following measures.

Causes:

- 1. If transporting AD-1 with the scanner in the home position, the scanner will hit the HP sensor and the sensor will become unfastened.
- 2. If you happen to push the HP sensor after the scanner rear cover has been removed, the sensor will become unfastened.

Measures:

- 1. When the problem occurs, make sure that the sensor is properly fastened.
- 2. Insert the additional mylar sheet between the sensor latch and the bracket if necessary. (The part number is xxxxxxxxxx.) This mylar sheet has been incorporated into the production machines as follows.

Model Code	Model	Production Month	Serial Number
A193-10	Nashuatec		
A193-15	Savin		
A193-17	Ricoh - North America		
A193-55	Lanier		
A193-27	Ricoh - EU		

How to set the mylar sheet:

Attach the mylar sheet as shown in the following illustration.

Caution:

- 1. Attach the mylar sheet after the sensor is mounted on the bracket.
- 2. Make sure that the latch for the sensor is properly inserted through the hole in the mylar sheet.





No. RTB-011

SUBJECT: SC120 after transporting the copier

DATE: Nov. 30, '96

PAGE: 2 of 2





RIGOH	Technical	Bulletin	ļ	No. RTB-012
SUBJECT: Installation Procedur	e for the paper e	nd feeler		DATE: Nov. 30, '96 PAGE: 1 of 1
PREPARED BY: T. Itai CHECKED BY: S. Fujii for	July 1	FROM: 2nd Fiel	d Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of s	service manual only	MODI	EL: AD-1


<Installation Procedure>

- 1. Set the thin part of the shaft (1 in the Illustration) into the holder.
- 2. Slide the paper end feeler to the rear and slide the wider part of the shaft into the holder (2 in the Illustration).
- 3. Put the snap ring on the thin part of the shaft.

<Confirmation>

Pull the paper end feeler up slightly to confirm that it is securely in place.

<ll>Illustration>



RIGOH	Technical	Bulletin	No. RTB-013
SUBJECT: ROM Board			DATE: Nov. 30, '96 PAGE: 1 of 1
PREPARED BY: T. Itai for CHECKED BY: S. Fujii	Jamph -	FROM: 2nd Fiel	ld Information Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MODEL: AD-1
<symptom></symptom>			
The jumper pins for the out come off.	side of the connec	ctors (pin nos. 36	to 70) on the BiCU
<cause></cause>			
The jumper pins were not fi in the first shipment (28pcs-	ixed securely by tl +10pcs for RDG).	ne resin adhesive	on the ROM boards
<action required=""></action>			
If you find the one of the RO shown in the illustration below	OM boards mention	oned above, pleas	se apply tape as
(Illustration)			
6	5 4	3	

RIG			Tec	hnical	Bulle	etin	N	lo. RTB-014	
SUBJECT:	ROM His	tory (AD1	I-FAX op	tion)				DATE: Dec. 15, '96 PAGE: 1 of 2	;
PREPAREI CHECKED		•	13/13/19	de la	FROM	1: 2nd Fie	eld Inform	nation Dept. QAC	
Trouble	CATION: Required shooting Informatio	on		Revision of nformation Other		manual	MODE	L: AD1	
We inform y (For the US	•		history 1	for the AD	1-Fax op	tion.			
A1945581	File No. (A194uxx)	Version	Total C.SUM	SUM(0H)	SUM(0L)	SUM(1H)	SUM(1L)	Production	
С	03	1.23	DD95	CB2A	27F0	BD19	72 A 5	1st Mass Prod.	

05 (For the European/Asian Model)

04

Ε

1.29

1.38

E6D7

EAAE

A1945582	File No. (A194exx)	Version	Total C.SUM	SUM(0H)	SUM(0L)	SUM(1H)	SUM(1L)	Production
В	02	1.23	3A44	0A20	FC8A	691F	FEBA	1st Mass Prod.
С	03	1.29	3270	D0F9	39CD	F1E6	19A3	November Prod. 96
D	04	1.38	3745	FA2F	B98C	C966	E8B9	December Prod. 96

83C2

A99A

47BC

919A

E9BD

5C74

7F1A

5A3A

November Prod. 96

December Prod. 96

(For European 2nd Language)

A1945585	File No.	Version	Total C.SUM	SUM(0H)	SUM(0L)	SUM(1H)	SUM(1L)	Production
Α		1.38		E09E	340F	6301	B2A2	December Prod. 96

		EU/	
Symptom corrected	US	ASIA	EU2
When the handset is picked up at ringing signal detection, the reception is disconnected and the reception job rarely remains internally. In this case, the display is not going to "Handset Mode" even if the handset is picked up, or "line is busy" is displayed for direct tx from the ADF.	E	D	А
In manual tx mode with the handset, the operator presses the Start key and hangs up the handset at the same time. Then the transmission job remains internally. In this case, both transmission and reception are not available, or "Handset mode" is always displayed. This problem can be solved by picking up and hanging up the handset again.	E	D	А
The chain dial function is not used by the on-hook or handset mode.	Е	D	Α
When the machine stores a letter-size original using image rotation, the compression does not succeed. Then the job is reset if the original is complicated, and it is scanned in photo mode.	E	-	-

了 の に に の に の に る に る に る に る に る に る に る に る に る に る に る に る に る に る に る に る に に る に 。 に る に る に る に る に る に る に る に る に る に る に に る に る に る に る に る に る に る に る に る に る に に る に る に る に る に る に る に る に る に る に る に に る に	υпл
மு	リロリ

No. RTB-014

С

SUBJECT: ROM History (AD1-FAX option) DATE: Dec. 15, '96 PAGE: 2 of 2 After entering the personal code and going to the fax mode in the personal code transmission mode, if a programmed key (Quick dial) is used, the personal code is not Ε D Α printed on the JOURNAL report. New Bit Switches are added for some reports. Ε D Α System SW 1F-Bit 1: When a memory overflow or storing jam occurs, the Memory Storage Report and Memory Transmission Report are not printed out. 0: OFF(Default)-Print 1: ON-No print User SW 03-Bit 2: Memory Storage Report is printed automatically. 0: OFF(Default) 1: ON-Print System SW 1E-Bit 1: The method of erasing files when the memory is full 0: Only a page is eraced 1: The file is eraced. *The combination of the above bit switches: OFF **OFF** ON ON User SW 03: OFF System SW 1F: **OFF** ON ON Memory Storage OK Χ 0 Χ 0 Memory Storage NG 0 Χ Χ 0 O=Memory Storage Report Continuing after the 0 0 Χ Χ is printed out. memory is full (by System SW 1E-Bit1) Only for Belgium approval: When the communication is finished while the handset is still picked up, the buzzer must sound till the handset is hung up. D Α G3 SW 0F-Bit 1 : 0:Buzzer is ON 1:Buzzer is OFF *The default of this bit is 0 for Belgium. If there is a conflict between G3 Reception (analog port) and iG3 Transmission (digital D С port), the Communication LED turns on and is locked. When the operator picks up the handset and dials using a quick or a speed dial then hangs up the handset during dialing, the display always shows "Handset Mode". ① When the handset is hung up then picked up again within 1 second after pressing the Start D С key in non-memory Tx mode, the display always shows "Handset Mode". ① If the operator makes the transmit operation or presses the Stop key, the display locks. *If the handset is hung up then picked up again under condition ①, the display is not locked. When a ringing signal comes in when going into the night mode, the machine goes into the night mode and goes back to Ready. Then the power failure report is printed out. (The file D С no. and communication mode on the JOURNAL are wrong.) New User Switch for Forwarding: User Switch 0E (SW14) bit5: 0 - Off (Default) 1 - On *All received files are forwarded to the transfer address. D C *On the user parameter list, the following description is not printed. "Forwarding all received files ON/OFF" In the date input mode, the display shows "24hr format" instead of "12hr format". D The download and upload function from FCU board to FCU board with the feature card do С D not work. С French version only: The TEL number of quick and speed dials cannot be corrected. German versiononly: Wording correction (5 wordings) С --

Spanish version only: A default setting was changed. *G3 Switch 0F bit 0 $^{\circ}$ 0 \rightarrow 1



D

REVISED ON: JANUARY 15, '97

RIG		Te	echnical	Bulleti	n	N	o. RTB-	015A
SUBJECT: F	ROM History	(AD1 Copy	Version)				DATE: Ja PAGE: 1	
PREPARED CHECKED I	_		Jan	FROM: 2	2nd Fie	ld Info	ormation Dep	ot. QAC
CLASSIFICA Action Re Troubles Retrofit In	equired		Revision of Information Other	f service ma	anual	MOI	DEL: AD1	
We inform y (For the US		mware histo	ory for AD1.					
A1935532	File No. (A193uxx)	Version	Total C.SUM	SUM(0H)	SUM((OL)	Produ	ction
D	04	1.16	55DD	178E	3E4	·F	1st Mass Prod	•
E	05	1.23	FB24	B285	489	F I	November Pro	d. '96
F	06	1.31	F96B	F66D	02F	E I	December Pro	d. '96
G	07	1.33	5D03	2ECA	2E3	39 L	January Prod.	'97
(For the Eur	opean/Asiar	n Model)						
A1935533	File No. (A193exx)	Version	Total C.SUM	SUM(0H)	SUM(· ′	Produ	
С	103	1.16	B574	E4C1	D0E		<u>1st Mass Prod</u>	
<u>D</u>	104	1.23	FC4B	98CE	637		November Pro	
E	105	1.31	0ADC	41C5	C91		December Pro	
F	107	1.33	4C77	CFF3	7C8	34	January Prod.'	1
DI 1 0 1 1		- 1 - 1 - 1 - 1	m corrected				USA	EU/Asia
adjusted using	g 7 settings. E	ach setting ha	anned low cont as different gan lode: SP4-998,	nma correction		teristic	s, G	F
			er negative\po:				G	F
	rs when the do d after closing		during memor	y copying if th	e start		G	F
			s initialized wh	en the main s	witch is	turned	G	F
SC921-Memo	ory Access Erro		ne door during	memory outpu	ıt		F	E
			itch off/on after			n SP	F	E
	v PCU Detect	is added to th	e Input checks) .			F	Ε.
			d to Salesman		е.		F	E
SP mode can		when the ma	in switch is tur			to the	F	Е
The finisher is		mode.					F	Е
		I from the AD	F, the Start ke	v can he dete	cted As	a resu		D
_	document size		., a.o otari no	, 34 30 4010			_	_

The ARDF is supported.

RIGOH	Technical	Bulletin	j	No. RTB-016
SUBJECT: Dirty background ca	used by ammonia	a gas		DATE: Dec. 15, '96 PAGE: 1 of 1
PREPARED BY: K. Ugaeri CHECKED BY: S. Fujii for	Jan	FROM: 2nd Fiel	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MODI	EL: AD1
<sympton> If the AD1 is installed by a machine, its developer is chang occur.</sympton>				
<cause> The developer is changed by the</cause>	e ammonia gas.			
<action required=""></action> Ricoh is now investgating the refor ammonia. At the moment, we no influence from anmonia gas.	ould you ask you			

RIGOH	Technical	Bulletin	l	No. RTB-017
SUBJECT: False Indication of S	C101			DATE: Dec. 15, '96 PAGE: 1 of 2
PREPARED BY: T. Itai CHECKED BY: S. Fujii for	Jung	FROM: 2nd Fiel	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of Information Other	service manual only	MOD	EL: AD1
The false SC101 indication may normal by the following the instr		following conditio	ns. It (can be reset to
Symptom: After turning the main switch on "Ready". Though SC101 can be procedures nor toggling the main switch on the procedures nor toggling the main sequence Conditions: The problem occurs when the following BICU software versions 55) and "D" for European software. 1. In SP mode 4-417 IPU "Test 2. The test pattern was printed was 1. The main switch was turned of the With the operations listed above with the operations listed above the software, this problem have software, this problem have 1. By using SP mode 4-417, selections is selected.	reset by toggling in switch can reset by toggling in switch can reset bllowing operation is: "E" for US soft are models (destined and prints, on with the Copy Month, and soft are soft in second to the condition is to reset to no switch the condition is the condition in switch the condition is the condition in switch the condition is the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch can reset to no switch the condition in switch the conditi	s were made on ware models (despect to normal operation codes 19, 2 de of the test patted de Display. After the main switch of the software and operating co	either thating commaching stination 22, 26, erns was tch is to differ formalition.	ne SC resetting anditions. les with the codes 10, 15, 17, 27, 29, 65) as selected. urned back on. or European
or. 2. Toggle the ac switch from off	to on.			



No. RTB-017

SUBJECT: False Indication of -SC101 DATE: Dec. 15, '96


PAGE: 2 of 2

Additional Information:

SC101 is a new SC Code and has been added to the original SC Codes from the BICU software version "E" for US software and "D" for European software to diagnose the following problem.

- -Level of Service Call Condition: A
- -Definition: The referenced white pattern wasn't detected properly.
- -Possible Causes:
 - -Defective Exposure Lamp
 - -Defective Exposure Lamp Harness
 - -Defective SBU
 - -Defective SBU Harness

RIGOH	Technical	Bulletin		No. RTB-018
SUBJECT: Paper Feed Jam, F	aper Skew			DATE: Jan. 15, '97 PAGE: 1 of 2
PREPARED BY: K. Ugaeri CHECKED BY: S. Fujii for	Jung	FROM: 2nd Fie	ld Infor	mation Dept. QAC
CLASSIFICATION: Action Required Troubleshooting Retrofit Information	Revision of s	service manual only	MOD	EL: AD1
Action: Check to see if the edge of the burrs or scratches. Measure:	ne corner separator	that touches the	paper	has
Remove burrs or scratches b 2. Check the amount of overlap below.			•	·



Specifications:

- 1) The overlap amount must be:
 - 5.7 ± 1.2 mm with the AD-1 Paper Tray
 - 6.0 ± 1.2 mm with the Optional Paper Tray
- 2) The difference in the amount of overlap between the front and rear of the corner separator must be within 1.5 mm.


Countermeasure:

If the overlap amount isn't within the above specifications, the corner separator may have been deformed. Reform the separator or replace if necessary.

Reference:

Depending on the conditions, the following problems may arise.

- when the difference of the amount of overlap between the front and rear of the separator is greater than 1.5 mm ------ Paper Skew
- when the amount of overlap is greater than the specifications ----- Misfeed
- when the overlapped amount is less than the specifications ----- Double Feed



Technical Bulletin

RTB Correction

Reissue date: 15-Apr-97

The items in bold italic have been corrected or added.

Model: AD1 (DF	- 43)	Date: 28-	Feb-97	No: 019	1/2
Subject: Black	stripes		Prepare	d by: K. Ugaeri	
From: QAC 2nd	Field Information Dept.		Checked	d by: S. Fujii	noue
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	Part informa Electrical Transmit/rec		☐ Action required ☐ Service manual rev ☐ Retrofit information	

SYMPTOM


Black stripes when using the sheet scanner

CAUSE

Dust on the exposure glass.

SOLUTION

1. The *three* mylars have been added on the original scale (A6283192) to prevent the scanning position on the exposure glass from becoming dirty.



Model: AD1 (DF43) Date: 28-Feb-97 No: 019 2/2

Because the contact position of the original becomes dirty with paper dust, it has been moved from the scanning position by using mylars.




Fig. 2

2. The surface of the exposure glass has been treated by the mater replant process.

Note: This exposure glass has a white mark. This mark must be at the bottom rear side at installation.




Fig. 3


Model: AD1		Date: 28-	Feb-97	No: 020	1/2
Subject: No drive in the Transport section			Prepared by: K. Ugaeri		
From: QAC 2nd Field Information Dept.			Checked by: S. Fujii		
Classification:		Part information		☐ Action required	
	☐ Mechanical ☐	☐ Electrical		Service manual revision	
	☐ Paper path ☐	☐ Transmit/receive		☐ Retrofit information	
	☐ Other ()				

SYMPTOM

The Timing Belt of the transport section is not driven.


CAUSE

When the operator removes jammed paper from the exit of the transport section, the tightener (G0204333) will go over the boss on the guide plate (G0204409).



SOLUTION

A stopper has been added on the guide plate.



Technical Bulletin

Model: AD1 Date: 28-Feb-97 No: 020 2/2

MODEL NAME	V/ Hz	Option for	JAPAN PRODUCTION	
			CODE	SERIAL NUMBER
nashuatec D420	115/60	U.S.A	A193 - 10	A107010001~
SAVIN 9920DP	115/60	U. S. A., CANADA	A193 - 15	6A76120001~
Aficio 200	115/60	U. S. A., CANADA	A193 - 17	A7226110001~
Aficio 200	115/60	TAIWAN	A193 - 19	(A722702~)
Gestetner 3220	220/50	EUROPE	A193 - 22	AH26120001~
Infotec 4201	220/50	EUROPE	A193 - 26	3L01260001~
Aficio 200	220/50	EUROPE	A193 - 27	A7226110598~
Aficio 200	220/50	EUROPE	A193 - 29	A7226122087~
Lanier 5020MFD	115/60	U. S. A.	A193 - 55	L5026120516~
Lanier 5020MFD	220/50	EUROPE	A193 - 65	L5026120780~

Technical Bulletin


Model: AD1		Date: 28-	Feb-97	No: 021	1/1
Subject: Toner Scattering in Duplex mode			Prepared by: K. Ugaeri		
From: QAC 2nd Field Information Dept.			Checked by: S. Fujii		
Classification:		□ Part information		☐ Action required	
	☐ Mechanical ☐	Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/receive		☐ Retrofit information	
	☐ Other ()				

SYMPTOM

Toner scattering around the halftone image on the rear page in duplex mode.


CAUSE

After transferring the image from the drum, there is an electric potential gap between the white and the black areas. The toner scattering occurs before the discharging by the discharge brush.



SOLUTION

The shape of the discharge brush has been changed. The top of the new brush is closer to the transfer roller.



Old part number	New part number	Description	Page	Index
G020 3870	A193 3870	Discharge Brush	35	28

^{*} The new part is available from December 1996 production.

Technical Bulletin

Model: AD1 (DF43)		Date: 28-	Feb-97	No: 022	1/1
Subject: Front G		Prepared by: Horiike			
From: QAC 2nd		Checked by: S. Fujii			
Classification:	☐ Troubleshooting	Part informa	tion		
	☐ Mechanical ☐ Electrical			Service manual revision	
	☐ Paper path ☐	☐ Transmit/rec		☐ Retrofit information	
	Other ()				

SYMPTOM

The left cover cannot be closed.


CAUSE

The Front or Rear Guide Plate was accidentally turned to the left when the operator removed a jammed original, because these plates are difficult to see.

SOLUTION

The color of the Front and Rear Guide Plates has been changed from black to a clear color.

	Current	New
Front Guide Plate	A628 1218B	A628 1218C
Rear Guide Plate	A628 1219B	A628 1219C



Technical Bulletin


Model: AD1		Date: 28-	Feb-97	No: 023	1/2
Subject: Lever in the transfer unit			Prepared by: K. Ugaeri		
From: QAC 2nd I		Checked by: S. Fujii			
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()			n Action required Service manual revision	

SYMPTOM

The transfer unit cannot be installed.

CAUSE

When the PCU is not installed completely, the side plate is shifted to the front and the lever of the transfer unit may come in contact with the side plate.



SOLUTION

The corner of the lever has been cut to prevent the lever from coming in contact with the side plate of the PCU.



Technical Bulletin


Model: AD1 Date: 28-Feb-97 No: 023 2/2

MODEL NAME	V/ Hz	Option for	JAPAN PRODUCTION	
		•	CODE	SERIAL NUMBER
nashuatec	115/60	U. S. A	A193 - 10	A107010001~
D420				
SAVIN 9920DP	115/60	U. S. A., CANADA	A193 - 15	6A76120001~
Aficio 200	115/60	U. S. A., CANADA	A193 - 17	A7226110047~
Aficio 200	115/60	TAIWAN	A193 - 19	(A722702~)
Gestetner 3220	220/50	EUROPE	A193 - 22	AH26120001~
Infotec 4201	220/50	EUROPE	A193 - 26	3L01260001~
Aficio 200	220/50	EUROPE	A193 - 27	A7226120787~
Aficio 200	220/50	EUROPE	A193 - 29	A7226122087~
Lanier	115/60	U. S. A.	A193 - 55	L5026120516~
5020MFD				
Lanier	220/50	EUROPE	A193 - 65	L5026120780~
5020MFD				


Model: AD1 (DF43)		Date: 28-Feb-97		No: 024	1/1	
Subject: Original Jam Decal			Prepared by: Horiike			
From: QAC 2nd Field Information Dept			Checked by: S. Fujii			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()		Part informa Electrical Fransmit/rec		☐ Action required ☐ Service manual revi ☐ Retrofit information	sion

To make the removal procedure for a jammed original easier to understand, the drawing on the decal has been changed

OLD



NEW



Technical Bulletin

PAGE: 1/2

Model: AD1			Date	Date: 19-Mar-97		No: 25
Subject: Paper Jam (LG size with the finisher)				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.				Checked by: S. Fujii		
Classification:	☐ Troubleshooting	□ Part inf	ormation		☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Servic	ce manual revision
	☐ Paper path	☐ Transm	nit/rec	eive	☐ Retro	fit information
	☐ Other ()					

SYMPTOM


Legal size paper jam with the finisher.

CAUSE

When Legal size paper is fed out to the finisher, the edge of the paper scratches against a rib on the Junction and the paper jams.

SOLUTION

A rib has been added to the Junction Gate inside the Legal paper width.



Technical Bulletin

PAGE:2/2

Model: AD1 Date: 19-Mar-97 No: 25

MODEL NAME	V/ Hz	Option for	JAPAN I	PRODUCTION
			CODE	SERIAL NUMBER
nashuatec D420	115/60	U.S.A	A193 - 10	A106110001
SAVIN 9920DP	115/60	U. S. A., CANADA	A193 - 15	6A76120001~
Aficio 200	115/60	U. S. A., CANADA	A193 - 17	A7226110285~
Aficio 200	115/60	TAIWAN	A193 - 19	(A722701~)
Gestetner 3220	220/50	EUROPE	A193 - 22	AH26120001~
Infotec 4201	220/50	EUROPE	A193 - 26	3L01260001~
Aficio 200	220/50	EUROPE	A193 - 27	A7226120787
Aficio 200	220/50	EUROPE	A193 - 29	A7226122087~
Lanier 5020MFD	115/60	U. S. A.	A193 - 55	L5026120516~
Lanier 5020MFD	220/50	EUROPE	A193 - 65	L5026120780~

Technical Bulletin

PAGE: 1/1

RTB Correction

Reissue date: 15- Jun -97

The items in bold italic have been corrected and the illustrations have changed as shown below.

Model: AD-1			Dat	ate: 19-Mar-97		No: 26A
Subject: Paper jam				Prepared by: M.Horiike		
From: QAC 2nd I	Field Information Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	⊠ Part inf □ Electric □ Transm	al		Servi	n required ce manual revision fit information

SYMPTOM


Paper jam from the paper tray unit (PS 330).

CAUSE

The paper contacted the uneven edge of the upper guide paper feed.

SOLUTION

The shape of the upper guide - paper feed has been changed from January Production '97.



Model: AD-1

Classification:

Technical Bulletin

☐ Transmit/receive

			TAGLITT		
	Dat	e: 19-Mar-97	No: 27		
ector		Prepared by: K.	Ugaeri		
	Checked by: S. Fujii				
□ Part inf	orma	tion Actio	Action required		
☐ Electrical ☐ Service manual revision			ice manual revision		

☐ Retrofit information

PAGE-1/1

SYMPTOM

Wrong detection by the paper size detector.

Other (

Subject: Wrong detection by the paper size detector

☐ Mechanical☐ Paper path

☐ Troubleshooting


From: QAC 2nd Field Information Dept.

CAUSE

When the paper tray cover was bent, the pins on the paper size detector could not reach the paper size detector switch.

SOLUTION

The position of the switch has been shifted to the front by changing the shape of the Support - Paper Tray (G0202676) from January '97 production.



Technical Bulletin

PAGE: 1/2

RTB Correction

Reissue date: 15-May-97

The items in bold italic have been corrected or added.

Model: AD1 Date			e: 19-Mar-97	No: 28	
Subject: Dog - ear or Contact noise				Prepared by: K.Ugaeri	
From: QAC 2nd Field Information Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other (☐ Part inf ☐ Electric ☐ Transm	al	_ ☐ Servi	n required ce manual revision fit information
	Other ()				

SYMPTOM

①Dog - ear.

2Contact noise.

CAUSE

- 1) The burrs of the corner separator
- 2 Noise caused when the corner separator and paper tray come in contact.

SOLUTION

- ①The burrs of the corner separator have been removed with the addition of the press process.
- ②A sponge sheet has been added on the corner separator.

(Current)(New) $G0202561 \rightarrow G0202573A$ (Front Paper Separator) $G0202568 \rightarrow G0202558A$ (Rear Paper Separator)

Technical Bulletin

PAGE:2/2

Model: AD1 Date: 19-Mar-97 No: 28

MODEL NAME	V/ Hz	Option for	JAPAN I	PRODUCTION
			CODE	SERIAL NUMBER
nashuatec D420	115/60	U.S.A	A193 - 10	_
SAVIN 9920DP	115/60	U. S. A., CANADA	A193 - 15	6A76120001
Aficio 200	115/60	U. S. A., CANADA	A193 - 17	A7226120149
Aficio 200	115/60	TAIWAN	A193 - 19	(A722704~)
Gestetner 3220	220/50	EUROPE	A193 - 22	AH27020901
Infotec 4201	220/50	EUROPE	A193 - 26	3L00370001
Aficio 200	220/50	EUROPE	A193 - 27	A7227020749
Aficio 200	220/50	EUROPE	A193 - 29	A7227021345
Lanier 5020MFD	115/60	U. S. A.	A193 - 55	L5026120572
Lanier 5020MFD	220/50	EUROPE	A193 - 65	L502021685

Technical Bulletin

PAGE: 1/2

Model: AD1 (SR210)				Date: 16-Apr-97		No: 29
Subject: MAIN CONTROL BOARD DAMAGE				Prepared by: M.Horiike		
From: QAC 2nd Field Information Dept.				Checked by: M.Iwasa		
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part inf ☐ Electric ☐ Transm	al		Servic	n required ce manual revision fit information

SYMPTOM

Arcing occurs and a surge current flows into the main control board (P/N A666-5550) of the AD-1 Finisher when the power cord is plugged into the power source of the main frame (copier) while power is applied. This may result in possible damage to IC116 and /or IC110 on the main control board.

CAUSE

The main control board has a zener diode in its 5-volt circuit which works to maintain the voltage (5V) of the circuit by passing the surge current to the ground. However, some diodes do not work effectively when a large current rushes in, and they allow voltage to rise over the tolerant voltage level for IC116 and IC110.

SOLUTION

Another type of zener diode has been added to the main control board of the Finisher in parallel with the existing one to keep the voltage of the 5-volt line by quickly by-passing the surge current to ground. A modification bulletin will be issued later.

ACTION REQUIRED

The appropriate installation procedure for the Finisher is clearly described in the service manual and is as follows.

CAUTION

Unplug the copier power cord and turn off the main switch before starting the following procedure


If the Finisher is installed in accordance with the proper procedure, no problems will occur.

Please make sure that <u>both the main switch (Red) and the AC switch (Black) are turned OFF or the copier power cord</u> is unplugged before installing the Finisher.

Technical Bulletin

PAGE:2/2

Model: AD1 (SR210) Date: 16-Apr-97 No: 29



Note

If only the main switch (Red) is turned off, power is still applied to the Finisher. The AC switch (Black) should also be turned off to shut down the power to the Finisher.

Technical Bulletin

PAGE: 1/1


Model: AD1			Date: 30-Apr-97		No: 30	
Subject: Bracket for the handset option				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.				Checked by: S. Fujii		ujii
Classification:	☐ Troubleshooting	□ Part inference □	orma	ation Action required		n required
	☐ Mechanical	☐ Electric	al	☐ Se	ervio	ce manual revision
	☐ Paper path	☐ Transm	iit/rec	eive 🗌 R	etro	fit information
	☐ Other ()					

In some countries, the optional handset is available for the Aficio 200. To install the optional handset, use the bracket which is included in the Fax Unit Option, Type 250. Also, correct the installation procedure in the Service Manual on page 3-12 as follows.

4.HANDSET

4.INSTALLATION PROCEDURE

NOTE: The optional handset may not be available in some countries.



- 1.Install the bracket [A] (2 screws), as shown.
 - * The bracket [A] in the carton box of the Fax Unit Option Type 250 must be used.
- 2. Remove the label [B] from the handset cradle [C]. Install the cradle on the bracket [A] (2 screws), then replace the label [B].
- 3. Install the handset [D] as shown. Connect the handset cord to the "TEL " jack [E] on the machine.

Technical Bulletin

PAGE: 1/3

RTB Correction

Reissue date: 15-Jun- 97

Illustrations have been added as shown below.


Model: AD1 Date				e: 30-Apr-97	No: <i>031B</i>
Subject: Copy Quality(Dirty Background)				Prepared by: K.Ugaeri	
From: QAC 2nd I					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part inf☐ Electric☐ Transm	al	Servi	n required ce manual revision fit information

SYMPTOM

Dirty background or the black spots appear on the background of the copy.

Action required


First check whether the problem is related to printing or scanning. Then follow the steps listed below.




Model: AD1


Date: 30-Apr-97 No: **031B**


*





PAGE: 2/3





- (1) Change SP2-999 from 0 to 1 (Manual).
- (2) Change SP2-996 from 140 to 255.


Suffix G (EU/ASIA)

- (3) Make 10 A4-size sky shot copies.
 if the background is still dirty, make more sky shots.
- (4) Make a free run for 3 min.
- (5) Initialize the developer again using SP2-801.
- (6) Read Vcont at installation with SP2-997-1.
- (7) Put the above data from step (6) into SP2-996-1.
- (8) Set SP2-999 from 1 to 2.

PAGE: 3/3

Model: AD1 Date: 30-Apr-97 No: 031B

Scanning problem



Technical Bulletin

PAGE: 1/1

Model: AD1			Date	e: 30-Apr-97	No: 32	
Subject: Service Manual Correction (Key Counter)				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.				Checked by: S. Fujii		
Classification:	Troubleshooting	☐ Part inf	orma		on required	
	☐ Mechanical	☐ Electric	al	⊠ Serv	rice manual revision	
	☐ Paper path	☐ Transm	ıit/rec	ceive 🗌 Retr	ofit information	
	☐ Other ()					

- 1. To improve the installation procedure for the key counter holder, the following step should be added after step 11.
 - 12. Change the value of SP5-113 to "1".
- 2. The following SP mode should be corrected.

Incorrect

Class	Class 3		Function	Settings
1 and 2				
5-113		Option Counter Type	Japanese version only Do not change the value	

Correct

Class	Class 3		Function	Settings
1 and 2				
5-113		Option	Selects the optional counter	0: No
		Counter Type	type.	1: Key Counter
		7,1		2: Key Card
				3: Coin Lock 1
				4: Coin Lock 2
			After installing the optional key counter, this value should be set to "1".	
			Settings from 2 to 4 are used in the Japanese version only.	

Technical Bulletin

PAGE: 1/2

RTB Correction

Reissue date: 15-May -97

The items in bold italics have been corrected or added.

Model: AD1				Date: 15-Jan-97		No: <i>15B</i>
Subject: ROM History (AD1 Copy Version)				Prepared by: K.Ugaeri		
From: QAC 2nd I	Field Information Dept.					
Classification:	☐ Troubleshooting	☐ Part inf	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	nit/rec	ceive	⊠ Retro	fit information
	☐ Other ()					

We hereby inform you of the firmware history for the AD1. For USA Models

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
Е	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97

For European/Asian Models

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
Е	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97

^{*}Versions 1.35 and 1.36 are not released via Files.

For European 2nd Language Models

A6485510(OH)	File No.		Total			
A6485511(OL)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
Ε	205	1.43EU2	4BC4	DE26H	6D9E	March Prod.'97

Technical Bulletin

Model: AD1 Date: 15-Jan-97 No: 15B

Symptom Corrected	USA	EU/ Asia
When the RAM was cleared with SP5-801, the white level and the standard white plate density at the factory were erased.	L	K
Toner scattering around black areas of the image on the rear side of duplex copies. The default of the separation output voltage was changed. SP2-901-1→ -1800 SP2-901-2→ -1800 SP2-901-3→- 2500	К	J
SP2-901-4→- 2500 A blank sheet is printed out when the start key is pressed if the memory is full. The scanning restarts after printing the scanned image and then the first original jams.	, J	Н
Dirty Background. 1) Toner Density (SP2-911) was changed from 2 to 3 (Lighter) 2) Free run time at PCU Installation was changed from 1 min. to 3 min.	Н	G
Black Spots in the scanned image - A scanned low contrast image can be adjusted using 7 settings. Each setting has different gamma correction characteristics, MTF filter and threshold level (new SP mode SP4-998,999)	G :	F
Dirty background on white images aftemegative\positive reversal.	G	F
SC321 appears when the door is opened during memory copying if the start key is pressed after closing the door.	G	F
The development bias setting (SP2-201) is initialized when the main switch is turned off.	G	F
SC921-Memory Access Error After a paper jam while opening the door during memory output.	F	E
SC101 appears when turning the main switch off/on after the IPU test pattern in SP mode.	F	Е
SP5-803: New PCU Detect is added to the input checks.	F	Е
Memory copy priority of SP5-945 is added to Salesman Program Mode	F	Ε
SP-mode cannot be cleared when the main switch is turned off/on after going to the interrupt copy mode from SP mode.	F	E
The finisher is supported.	F	Е
While feeding out an original from the ADF, the Start key can be pressed. Then the incorrect document size is detected.	E	D
The ARDF is supported.	Е	D



PAGE: 2/2

Technical Bulletin

PAGE: 1/3

RTB Correction

Reissue date: 15-May-97

The items in bold italic have been corrected or added.

Model: AD1				e: 15-Dec-96	No: 14A	
Subject: ROM History (AD1-FAX option)				Prepared by: K.Ugaeri		
From: QAC 2nd I	Field Information Dept.					
Classification:	☐ Troubleshooting	☐ Part inf	orma	tion	n required	
	☐ Mechanical	☐ Electric	al	☐ Servi	ce manual revision	
	☐ Paper path	☐ Transm	nit/rec	ceive 🛛 Retro	fit information	
	☐ Other ()					

We inform you of the firmware history for the AD1-Fax option.

For USA Models

A1945581	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194uxx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.23	DD95	CB2A	27F0	BD19	72A5	1st Mass Prod.
D	04	1.29	E6D7	83C2	E9BD	47BC	7F1A	November Prod.'96
E	05	1.38	EAAE	A99A	5C74	919A	5A3A	December Prod.'96
F	06	1.48	5029	5D2A	E457	1FF3	4ED2	March Prod.'97
G	07	1.58	2AEF	27EO	FD88	286A	E367	May Prod.'97

For European/Asian Models

A1945582	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194exx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.23	3A44	0A20	FC8A	691F	FEBA	1st Mass Prod.
С	03	1.29	3270	D0F9	39CD	F1E6	19A3	November Prod.'96
D	04	1.38	3745	FA2F	B98C	C966	E8B9	December Prod.'96
E	05	1.48	3745	FA2F	B98C	C966	E8B9	March Prod.'97
F	06	1.58	8D00	FFBE	C502	1BB4	55FE	May Prod.'97

Technical Bulletin

PAGE:2/3

Model: AD1 Date: 15-Dec-96 No: 14A

For European 2nd Language Models

A1945585	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
			C.SUM	(OH)	(OL)	(1H)	(1L)	
Α	01	1.38	F398	E170	B392	56E5	EB06	December Prod.'97
В	02	1.48	E08A	B674	46C1	DDFC	29C9	March Prod.'97
С	03	1.58	5494	87A5	28B5	B595	F1DF	May Prod.'97

	110		
Symptom corrected	US	EU/	EU
		ASIA	2
The Two-in-one Function from HLT to LT size paper is not working.	G	F	С
New System Switch When closed network is enabled and the ID is not programmed, all reception is disabled (this is a specification). A System Switch has been added to modify this. Switch 1E Bit 4. When closed network is turned on and the ID is not set: (0: Closed network is not available. 1: Only transmission is available.	G	F	С
New System Switch The display of the remote terminal ID at Alredial: Switch 1E Bit 5 0: RTI/CSI is displayed. 1: The input Fax Number is displayed.	G	F	С
LCT and duplex tray are supported.	G	F	С
New HDD is supported.	G	F	С
NEST card option is supported.	G	F	С
In the G3or G4 receiving mode, when the memory is full at the first block of any page, a part of the previous page is missing.	F	E	В
Receiving error in G4 mode (When it is waiting for RSSP (or RSSN) after sending CONN, the machine displays "communication error" if DISC comes.	F	E	В
The periodical auto service call function does not work.	F	E	В
For Canada only The number of redials in Canada is changed to meet the CS-03 standard. System switch OF The setting for Canada (10h) is added. If the above switch is set to 10h, the number of redials (Communication switch 10) is set to 02h.		E	В

Model: AD1

Technical Bulletin

Date: 15-Dec-96 No: 14A

PAGE:3/3

Symptom corrected	US	EU/	EU2
		ASIA	
For the Netherlands only Marketing Requirements 1. Dialing method Default setting: PD DTMF (User switch 1A/bit 0.1 0.1) 2. Default setting of Transmision mode: Memory Transmission Immediate Transmision (User switch 00/bit 6 1) 3. International Access code: 00 FF		E	В
For Austria only Marketing Reguirements 1. Dialing method Default setting: PD DTMF (User switch 1A/bit 0.1 0.1) 2. Default setting of Transmission mode: Memory Transmission Immediate Transmission (User switch 00 bit 6 1) 3. Number of redials: 5 10 (Communication switch 10/bit 0-4) 4. Redial interval in Memory Transmission: 5min. 1min. (Communication switch 12/bit 0-7)		Ε	В
For New Zealand only The ringing detection time is changed. NCU parameters 07 & 0.8 : 010 015		E	В
For Australia only Tx time of 2100Hz is changed from 2.7s to 3.5s.		Ε	В
When the handset is picked up during ringing signal detection, the reception is disconnected but the reception job occasionally remains in the machine. In this case, the display does not go to "Handset Mode" even if the handset is picked up, or "line is busy" is displayed when directtx is made from the ADF.	E	D	A
In manual tx mode with the handset, the operator presses the Start key and hangs up the handset at the same time. Then the transmission job remains in the machine. In this case, transmission and reception are both not available or "Handset mode" is always displayed. This problem can be solved by picking up the handset again.	Е	D	A
The chain dial function cannot be used in on-hook or handset mode.	E	D	Α
When the machine stores a letter-size original using image rotation, the compression does not succeed, then the job is reset if the original is a complicated image scanned in photo mode.	E		

Technical Bulletin

PAGE: 1/1

Model: AD1-E (Printer Controller)				Date: 30-Jun-97		No: 33
Subject: AD1-E Printer Controller Launching				Prepared by: A.Nakajima		
From: QAC 2nd	Field Information Dept.					
Classification:	☐ Troubleshooting	☐ Part inf	orma	tion 🗌 A	ctior	n required
	☐ Mechanical	☐ Electric	al		ervi	ce manual revision
	☐ Paper path	☐ Transm	nit/rec	eive 🗌 F	Retro	fit information
	Other (Launching Informa	tion)				

The new Printer Controller is going to be issued as an optional device for the AD1-E copier.

This RTB clarifies the differences between the printer controller for AD1 and AD1-E.

The new printer controller has been developed as an optional device for AD1-E by changing the video clock and the firmware of the AD1 controller. In addition to the AD1 printer controller, the AD1-E controller supports paper feeding from the LCT. Supported paper sizes fed from the LCT in printer mode are 8 1/2" x 11" (L) and A4 (L). The controllers for AD1 and AD1-E are not interchangeable, though both of them can be physically installed on either copier. If the AD1 controller is installed in the AD1-E (or the opposite way round), abnormally enlarged (or reduced) print images may result. The service procedures; e.g. installation, troubleshooting, are the same as for the AD1 controller.

The other optional devices and software related to the printer controller (Printer Hard Disk, Network Interface Card, Printer Drivers, and Utilities) can be used in both machines.

Summary of Differences

Item	AD1 Controller	AD1-E Controller
Model Code	A643	A805
Maximum Print Speed	20 ppm	25 ppm
Firmware	Unique	Unique
Video Clock	62.616 MHz	79.314 MHz
LCT Feeding	Not supported (Note 1)	Supported

Note 1:

The LCT can be selected with the printer driver, though it cannot be installed on the machine. This is because the AD1 and AD1-E printer controllers use the same driver. If a user selects the LCT with the driver, paper will be fed from the default tray.

Model: AD1-Dup	lex (AD330)		Date	e: 1-July-	97	No: 34
Subject: Paper jam		Prepared by: K.Hattori		lattori		
From: QAC 2nd	Field Information Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	Part informat Electrical Transmit/rec			Service	n required ce manual revision fit information

SYMPTOM

The misfeed location "Z" is displayed and the machine stops.

CAUSE

If the Lower Guide Plate (G6944730) is bent upwards, component ① lifts up component ② of the Inverter Feeler(G6944735).

This moves component ③ of the Inverter Feeler closer to the Photointerrupter (AW020075). Then, the Inverter Feeler may often vibrate after the paper passes.

This may lead to the Inverter Feeler interfering with the signals from the Photointerrupter.




Figure 1

PAGE: 2/3

Model: AD1-Duplex (AD330)

Date: 1-July-97

No: 34

SOLUTION

The Inverter Feeler normally rests on the Upper Guide Plate if it is free. Replace or reshape the Lower Guide Plate if you find a gap between the Inverter Feeler and the Upper Guide Plate, because the uplifted Lower Guide Plate has lifted up the Feeler.




Figure 2

ACTIION REQUIRED

Please replace the Lower Guide Plate as described below.

- 1. Check the gap between the Inverter Feeler and Upper Guide Plate.
- 2. Remove the Snap Ring.
- 3. Remove the Upper Guide Plate.
- 4. Remove the Lower Guide Plate.
- 5. Attach the new or reformed Lower Guide Plate. (* See the next page.)
- 6. Attach the Upper Guide Plate.
- 7. Attach the Snap Ring.

PAGE: 3/3

Model: AD1-Duplex (AD330) Date: 1-July-97 No: 34

* How to modify the Lower Guide Plate.

- 1. Place the stand on a box-shaped object.
- 2. Put the center of the Lower Guide Plate face down on the stand.
- 3. Push both edges gently. **Caution:** If you push there too hard, the Lower Guide Plate will bend the other way.
- 4. Put a scale on the reshaped Lower Guide Plate.
- 5. Check the gap between the scale and the plate from a to b. If the gap is almost gone, the plate has been modified correctly.




Figure 3

RIGOH

Technical Bulletin

chnical **B**ulletin Page: 1/3

MB Correction

Reissue date: 30-Nov-97

The items in bold italic have been corrected or added.

Model: AD1-Printer Type 250		Date	e: 23-Jul-97	No: 35B	
Subject: Firmware and Software History			Prepared by: K.Ugaeri		
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	Part informati		□ Serv	n required ice manual revision ofit information

- A. Firmware for Controller Type 250.
- 1. History and Checksum List.

Ver	Check	Sum	Released on
	U23	U24	
1.35 1.32	3301 8FD5	1D08 3EFD	'97.9.30 '97.8.26
1.26 (1.24) (1.21) 1.08 1.07 1.06	3EC3 F38F 7A04 59BA 901F 5DAD	64E8 AC48 AC4F F0C2 6D97 1E45	'97.6.10 Temporary ('97.5.28) Temporary ('97.5.20) '97.4.2 '97.2.2 '96.12.17
1.03			1st Mass Prod. ('96.12.5)

2.Corrected Symptom

	Ver.
When printing a banner page in a staple job, the banner page is printed incorrectly.	
Resource saving on the test page indicate "1219 kbytes allocated of 1219 kbytes available." It should be "0 Kbytes allocated of"	1.35
When printing in Raster mode with custom paper size setting, output is incorrect.	
The Line Per Page setting value in the PCL menu was changed after power was switched off/on.	
While data is in the print queue, if you press the Job Reset key, some problems may occur.	
While data is in the print queue, either Memory Overflow or Lock Up occured. (Acrobat, Page Maker)	1.32
After printing 300 dpi data, only half of the 600 dpi data is printed out,.	
Image cut off if the previous job was printed using long edge feed (300 dpi) and the current job is printed with short edge feed (300 dpi).	
After printing data for a small paper size, if you print data for a bigger paper size, only data to fill the previous pape size is printed out.	



Model: AD1-Printer Type 250

Technical Bulletin

Date: 23-Jul-97 No: 35B

PAGE: 2/3

	Ver.
After printing a job using staple mode, if sending another job which changed the Page Protection Mode from the previous job's setting, sometimes it does not work, and the data stays in the print queue.	1.32
When setting User Code, if you send data to print while the LCD shows "Input user code", it does not work without pressing the offline / online key even if you input the User Code.	
Side-to-side motion of the finisher does not work in the energy save and night timer mode.	
The demo page cannot be printed. (*This is a problem only for version 1.24)	1.26
Lock Up occurs occasionally while the printing data is being stored on the HDD due to a sector control failure.	
Lock-up when the job reset button is pressed during data storage.	(1.24)
The finisher is supported.	
Print overrun because of access time to HDD. The band buffer is increased from 660KB to 4MB. * * If the controller has a HDD, more than 4MB of SIMM memory must be added.	(1.21)
General Protection Fault during Landscape Printing in Raster mode.	
Output of a Genoa FTS file is different from that of HP (* *Genoa FTS file).	
Page ordering is wrong. (* * For duplex printing, interleave on, and interrupt copying)	1.08
The printer hangs up when printing word data with lines shaded with colors as HP/GL. (* Duplex printing, HP/GL mode and colored lines)	1.07
Paper jam in Duplex mode when an A4 size page is printed on A3 paper.	



Technical Bulletin

PAGE: 3/3

Model: AD1-Printer Type 250 Date: 23-Jul-97 No: 35B

B. Driver Software for Win 3.1/Win 95

1. History List

Ver	Released on			
2.00	<i>'97.7.9</i>			
1.30	'97.5.19			
1.21	'97.4.2			
1.10	'97.2.2			
1.00	1st Mass Prod.('96.12.5)			

2. Corrected Symptom

	Ver.
 Even if setting True Type Mode to "Down Load as True Type", it is output as a bit image. When printing Hound.doc with Win 3.1, a part of the Univers Font was printed incorrectly. When setting B5 Env.in the Bypass Tray, WinPanel shows "Add F4 paper into Bypass Tray." When installing Win95 driver by Add Printer, the help File was not installed. 	2.00
The finisher is supported.	1.30
In Raster mode, a part of the graphic data cannot be printed correctly.	1.21
Power Point for Windows 95 cannot print raster Images.	1.10

C. Host Panel for DOS

1.History List

Ver	Released on
1.02	'97.5.25
1.01	'97.4.2
1.00	1st Mass Prod. ('96.12.5)

2. Corrected Symptom

	Ver.
Profile which has the Host Panel setting information in Duplex mode cannot be opened correctly.	1.02
TBA (To Be Announced)	1.01

Technical Bulletin

PAGE: 1/1

MB Correction

Reissue date: 22-Aug-97

The items in bold italic have been corrected or added.

Model: AD1-Pap	er Tray Unit (PS330)		Dat	e: 23-Jul-97	No: 36B
Subject: Noise			Prepared by: K.I	Jgaeri	
From: QAC 1st F	Field Information Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical	☐ Part informate			n required ce manual revision
	☐ Paper path☐ Other ()	☐ Transn	nit/red	ceive	ofit information

SYMPTOM

Noise from the bushing of the transport roller (AF02 0377).

CAUSE

The surfaces of some transport rollers were rough.

SOLUTION

Lubricate the bushing if the noise occurs.

*On the production line, they have been selecting the transport roller and lubricating the bushing from *March production '97.*

Caution

Do not use a chemical oil. When this type of oil is used, the same problem will occur again.

Use a machine oil (mineral oil).


Technical Bulletin

PAGE: 1/3

Model: AD1-Printer Controller Type 250		Date	te: 23-Jul-97		No: 37	
Subject: Print Overrun Memory Overflow Problem			Prepared by: K.Ugaeri			
From: QAC 2nd I	Field Information Dept.					
Classification:		Part information		tion		required
	☐ Mechanical	Electric	:al		□ Service	ce manual revision
	☐ Paper path	☐ Transmit/rec		eive	Retro	fit information
	Other ()					

This RTB reports the mechanism & countermeasure for the Print Overrun problem and the Memory Overflow problem in the printer controller type 250.

1. Data flow in the controller unit



- a. I/O Buffer for receiving and sending data.
- b. Stores the operation language software(such as PCL and PJL).
- c. Manages downloaded resources (such as Fonts and Macros).
- d. Holds and processes data from incoming print jobs.
- e. Image video buffer for sending video data to the engine to print.
- f. *When the HDD is installed, it is used only for the sorting function.

If the sorting function is selected, the data is stored in the HDD.

*With HDD, the SIMM memory must be more than 4MB from Ver.1.21 firmware.

Technical Bulletin

PAGE: 2/3

Model: AD1-Printer Controller Type 250 Date: 23-Jul-97 No: 37

2. Memory Overflow Mechanism

This means that there was not enoughprinter memory for the language requested for the print job.

If the user sends a print job which will use lots of memory, it might cause a memory overflow. Memory overflow might happen at points b, c, and d above. When memory overflow happens and the user presses the continue key, the printer prints only part of the page. This problem can be solved by adding SIMM memory (8 MB or more).

3. Print Overrun Mechanism

This means that the data sent to the printer was too complex. It will happen only while printing the data (preparing image data and sending image data to the engine at the same time). If the print job is so complex that the printer cannot complete the image for the engine, then print overrun will happen.

- Case 1: HDD Access Time -

This happens if the data takes too long to move because of the limit on HDD access time. This problem with the HDD can be solved by updating the firmware to version 1.21 or later and adding SIMM memory (more than 4 MB). The printer will allocate 4 MB for the image buffer (point e in the diagram) if the HDD is installed with firmware version 1.21 or later. After all the pages of one job are stored on the hard disk, the printer will move the image data from the hard disk to the image buffer until the image buffer is used up, and then it will tell the engine to start. Paper sizes smaller than A4 or LT should not have this problem.

- Case 2: HDD Reading Error -

This happens if there is an error when reading from the HDD. Vibrations from the duplex unit may cause this problem. To alleviate the problem, the HDD bracket has been modified with four rubber cushions. When the HDD is installed on the controller, use new brackets to protect the HDD from reading errors caused by vibration. ROJ will provide new brackets for all HDDs which were shipped with old brackets.

Technical Bulletin

PAGE: 3/3

Model: AD1-Printer Controller Type 250 Date: 23-Jul-97 No: 37

- Case 3: HDD sector control failure -

The sector information is controlled by the firmware. But this information is occasionally damaged by a firmware bug and this problem or a hang-up problem happens. This problem has been solved by the firmware version 1.26.

- ->If the finisher and the HDD are installed on the printer, use the following:
 - * Firmware version 1.26
 - * Driver version 1.30
 - * New HDD bracket

Technical Bulletin

PAGE: 1/4

RTB Correction

Reissue date: 22-Aug -97

The items in bold italics have been corrected or added.

Model: AD1				e: 15-Jan-97	No: <i>15D</i>
Subject: ROM History (AD1 Copier Version)				Prepared by: K	Ugaeri
From: QAC 2nd I	Field Information Dept.				
Classification:	☐ Mechanical ☐ Electrical		al	☐ Sen	on required vice manual revision ofit information
	☐ Paper path ☐ Other ()	☐ Transm	III/TEC	zerve 🖂 neti	ont information

We hereby inform you of the firmware history for the AD1.

(For the USA Model)

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
E	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
М	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97

(For the European/Asian Model)

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
Е	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97
L	111A	1.48	7218	5558	1CC0	May Prod.'97
М	112	1.54	AAA8	7837	3271	June Prod.'97

^{*}Versions 1.35 and 1.36 are not released via files.

Technical Bulletin

PAGE: 2/4

Model: AD1 Date: 15-Jan-97 No: **15D**

(For European 2nd Language)

A6485510(OL)	File No.		Total		
A6485511(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
Е	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F

(For European 3rd Language)

	301	1.57EU3	9DBB	C908	D4B3
A6485515(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
A6485514 (OL)	File No.		Total		

(For European 4th Language)

A6485516 (OL)	File No.		Total		
A6485517(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390

Technical Bulletin

PAGE: 3/4

Model: AD1 Date: 15-Jan-97 No: **15D**

Symptoms Corrected	USA	EU/	EU2
		Asia	
New SP Mode	N	М	G
SP-006-4: ARDF Main-Scan Magnification for the rear side.			
Specification	N	M	G
When the trays do not have the same size of paper in different orientations,			
the machine continues to print using the sort function even if the Rotate			
Sort function is selected.(The previous version software stops the copy job when one of the trays is empty.)			
The stapler may not work when the printer feeds out a stapled copy while feeding out paper into the finisher in copy or fax mode.	N	M	G
When 2 sheets of paper remain in the Duplex Unit and the printer prints in duplex mode, the printer image will be printed on the rear side of the remaining paper.	N	М	G
SP5-808: The 3 languages cannot be selected with the previous software version.		M	G
If a duplex copy is made with the ADF, Duplex Unit and 12M Memory and the original is jammed, the jammed original cannot be copied correctly during recovery.	М	L	F
Paper jam when paper is fed from the 3rd tray immediately after feeding the paper from the 4th tray (A jam or Y jam) with the following paper types. * 3rd Tray has paper less than 288mm length (A4 \Box) 4th Tray has paper 289mm to 401mm length (A4 \Box)	M	L	F

Technical Bulletin

PAGE: 4/4

Model: AD1 Date: 15-Jan-97 No: **15D**

A1935532	A193-10	A193-15	A193-17	A193-55
E	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	_	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	_	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	_	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	_	L5027042480~
М	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~
Ε	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~
G	AH27020001~	3L00270001~	_	_	L5027011424~
Н	AH27020951~		A7227021026~	A7227021345~	L5027021685~
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~
К	TBA	3L00470001~	TBA	TBA	TBA
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~
М	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~

Technical Bulletin

PAGE: 1/4

RTB Correction

Reissue date: 31-Aug -97

The items in bold italics have been corrected or added.

Model: AD1 Date				e: 15-Jan-97	No: <i>15E</i>
Subject: ROM H	istory (AD1 Copy Version)			Prepared by: K.l	Jgaeri
From: QAC 2nd	Field Information Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part inf☐ Electric☐ Transm	al	 ☐ Servi	n required ice manual revision ofit information

We hereby inform you of the firmware history for the AD1.

(For the USA Model)

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
Е	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
M	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97
P	13	1.60	3042	A726	891C	August Prod.'97
R	14	1.62	5B56	CF0D	8C49	September Prod.'97

(For the European/Asian Model)

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
E	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97
L	111A	1.48	7218	5558	1CC0	May Prod.'97
M	112	1.54	AAA8	7837	3271	June Prod.'97
N	113	1.60	1FE3	AEE1	7102	August Prod.'97
P	114	1.62	794C	90BE	E88E	September Prod.'97

^{*}The versions 1.35 and 1.36 are not released via Files.

Technical Bulletin

PAGE: 2/4

Model: AD1 Date: 15-Jan-97 No: **15E**

(For European 2nd Language)

A6485510(OL)	File No.		Total		
A6485511(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F
J	209	1.60EU2	AE02	2277	8B8B
K	210	1.62EU2	CB8A	0ACC	C0BE

(For European 3rd Language)

A6485514 (OL) A6485515(OH)	File No. (A193exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
A0403313(O11)	301	1.57EU3	9DBB	C908	D4B3
Α	302	1.60EU3	390A	FD07	3C03
В	303	1.62EU3	C69E	D5E3	F0BB

(For European 4th Language)

A6485516 (OL)	File No.		Total		
A6485517(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390
Α	402	1.60EU4	4490	FDEF	46A1
В	403	1.62EU4	A30C	D9E5	C927

(For China)

A6485512 (OL)	File No.		Total		
A6485513(OH)	(A193CHxx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	04	1.62CH	B020	B056	FFCA

(For Taiwan)

	File No.		Total		
A1935534	(A193TWxx)	Version	C.SUM	SUM(OH)	SUM(OL)
В	03	1.62TW	C05F	3BA0	94BF

Model: AD1

Technical Bulletin

Date: 15-Jan-97 No: **15E**

PAGE: 3/4

Symptom Corrected	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
For the USA only A new SP mode is added. SP5-950: LG size paper detection in the by pass tray. ∗ When this function is selected and LT size paper is put in the by-pass tray, the machine detects it as LG size paper.	R		_		_	_	
For the USA only Compliance with the Energy Star standard.	R	_	_	_	_	_	
After a fax transmission using the ARDF with the stamper, the registration of the 1st sheet copied using the ARDF is delayed.	R	P	К	В	В	E	В
A new SP mode is added. SP5-945:1= When one of the trays is empty, the paper end indicator (red LED) lights.	P	N	J	A	A	D	A
The DF Jam display is cleared by lifting the DF up and down	P	N	J	Α	A	D	A



RICOH

Technical Bulletin

PAGE: 4/4

Model: AD1 Date: 15-Jan-97 No: **15E**

A1935532	A193-10	A193-15	A193-17	A193-55
Е	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	_	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	_	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	_	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	_	L5027042480~
M	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~
Р	TBA	TBA	TBA	TBA
R	TBA	TBA	TBA	TBA

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~
Ε	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~
G	AH27020001~	3L00270001~	_	_	L5027011424~
Н	AH27020951~	_	A7227021026~	A7227021345~	L5027021685~
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~
Κ	TBA	3L00470001~	TBA	TBA	TBA
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~
М	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~
N	TBA	TBA	TBA	TBA	TBA
Р	TBA	TBA	TBA	TBA	TBA

PAGE: 1/5

RTB Correction

Reissue date: 22-Aug- 97

Illustrations have been added as shown below.


Model: AD1		e: 30-Apr-97	No: <i>031C</i>		
Subject: Copy Q	uality (Dirty Background)	Prepared by: K.Ugaeri			
From: QAC 2nd	Field Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part inf ☐ Electric ☐ Transm	al	☐ Servi	n required ce manual revision fit information


SYMPTOM

Dirty background or black spots appear on the background of copies.

Action required

First check whether the problem is related to printing or scanning. Then follow the steps listed below.





PAGE: 2/5

- * Set the toner density to 2 (normal) with SP2-911.
- (1) Change SP2-999 from 0 to 1 (Manual).
- (2) Change SP2-996 from 140 to 255 (using the zoom key).
- * Toner is not supplied with this setting.
- (3) Make 10 sky shot copies (A4 size) to reduce the toner density.
 - -if the background is still dirty, make more sky shots.
- (4) Make a free run for 3 min.
- (5)Initialize the developer again with SP2-801.
- * When SC393 is displayed, the initialization is not completed. In this case, go to step (10).
- (6)Read Vcont at installation with SP2-997-1.
- (7)Put the value read in (6) above into SP2-996-1.
- (8)Set the SP2-999 from 1 to 2

(10) Put "200" into SP2-996-1.

- * The 200 is an approximate Vcont value. The exact Vcont value can be calculated by the procedure shown on the next page.
- (11) When the toner density is light, change the toner density to 3 or 4 using SP2-911. (12) End.


(9) End.

Reference How to find the correct V cont value

- (1) Use SP2-220 to display the TD sensor output voltage on the LCD.
- (2) Make a white copy and read the output voltage.
- (3) When it is not within $2\pm0.2V$, find the expected V cont value by using the table below.


TD sensor	0.1	0.2	0.3	0.4	0.5	0.6	0.7	8.0
output voltage								
Vcont value	160	165	170	175	180	185	190	195

- * See below for a detailed calculation method.
- (4) Put the above Vcont value into SP2-996-1.
- 1. The expected Vcont value can be calculated using the formula below.




Example:

- 1. TD sensor output value: 0.5V
- 2. Difference from 2V: 1.5V
- 3. Expected Vcont value: 255-1.5+0.2x10=180
- 2. Relation between TD sensor output value and Toner Density.




* When the toner density becomes darker, the TD sensor output becomes lower than 2V.

3. Relation between Vcont value and TD sensor output value.



* When the Vcont value becomes higher, the TD sensor output becomes low.

Scanning problem



PAGE: 1/4

Model: FX4, FX6	Date	ate: 31-Aug-97		No: 005		
Subject: Novell Nest Autoroute Function				Prepared by: S.Yoshio		
From: 2nd Techn						
Classification:	☐ Troubleshooting	☐ Part inf	ormat	tion	Action	n required
	☐ Mechanical	☐ Electric	al	⊠ Servi		ce manual revision
	☐ Paper path ☐ Transmit/rece		eive	Retro	fit information	
	Other ()					

The NEST card has been released for Nest Autoroute function in fax machines and for fax units in the AD series.

This technical bulletin contains the revisions to the Nest Autoroute service manual. Procedures for reading and writing user-programmed data by RDS have been added. Only the Installation section was changed.

For details on the models that can use the NEST card, please check the product launch information for the models.

RC	RE	ASIA	
*	*	*	



Model: FX4, FX6, FX6MK2, FX6CD, FX7, LX7, LSO, AD1 | Date: 31-Aug-97 | No: 005

INSTALLATION
INSTALLING THE NEST CARD

May 20th,1997

PAGE: 2/4

2.2. INSTALLING THE NEST CARD

△ CAUTION

Before installing the NEST card, do the following:

- 1.Print out all messages stored in the memory.
- 2.Print out the lists of user programmed items and the system parameter list.

2.2.1. Function Upgrade Card Type 140 Plus Novell® NESTTM

Note

 The following installation procedure initializes (erases) all the user-programmed data stored in the card, if the Function Upgrade Card already installed in the machine is replaced with a NEST card.

Installation Procedure (Without a Function Upgrade Card)

- Turn off the main switch.
- Install the battery on the NEST card.
- Turn on the battery switch.
- Install the NEST card in the slot.
- Turn on the main switch.
- Print the system parameter list and make sure that "NEST" is listed as an option on the list.

Installation Procedure (Replacing a Function Upgrade Card with the NEST card)

- Read and back-up the user-programmed data stored in the Function Upgrade Card with RDS.
- Turn off the main switch.
- Remove the Function Upgrade Card from the slot.
- Install the battery on the NEST card and turn on the battery switch.
- Install the NEST card in the slot.
- Turn on the main switch.
- Print the system parameter list and make sure that "NEST" is listed as an option on the list.
- Write the backed-up data to the NEST card.



te: 31-Aug-97 No: 005

Model: FX4, FX6, FX6MK2, FX6CD, FX7, LX7, LSO, AD1 Date: 31-Aug-97

INSTALLATION

PAGE: 3/4

May 20th,1997

INSTALLING THE NEST CARD

When the NEST card is replaced with another NEST card, do the following so the machine can recognize the new card.

- 1. Turn off the main switch
- 2. Remove the old card.
- 3. Turn on the machine without the card and turn off.
- 4. Install the new card.
- 5. Turn on the main switch.

△ CAUTION

The IC card contains a lithium battery.

The danger of explosion exists if a battery of this type is incorrectly replaced. Replace only with the same or an equivalent type recommended by the manufacturer. Discard used batteries in accordance with the manufacturer's instructions.



Model: FX4, FX6, FX6MK2, FX6CD, FX7, LX7, LSO, AD1 Date: 31-Aug-97 No: 005

INSTALLATION
INSTALLING THE NEST CARD

May 20th,1997

PAGE: 4/4

2.2.2. Feature Expander Type 100 2M Plus Novell NEST

Note

 The following installation procedure initializes (erases) all the data stored in the card, if the Feature Expander already installed in the machine is replaced with a NEST card.

Installation Procedure

- Turn off the main switch.
- Install the NEST card in the slot in the machine.
- Turn on the main switch.
- Print the system parameter list and make sure that "NEST" is listed as an option on the list.

When the NEST card is replaced with another NEST card, do the following so the machine can recognize the new card.

- 1. Turn off the main switch.
- 2. Remove the old card.
- 3. Turn on the machine without the card and then turn off.
- 4. Install the new card.
- 5. Turn on the main switch.

RIGOH

Technical Bulletin

PAGE: 1/1

Model: AD-1Printer Controller Type 250 Date				te: 5-Sep-97		No: 38
Subject: New models				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.						
Classification:	Troubleshooting	☐ Part inf	orma	tion	☐ Action	n required
	☐ Mechanical	Electric	al	☐ Servi		ce manual revision
☐ Paper path ☐ Transmit/		☐ Transmit/receive ☐ Retr		⊠ Retro	fit information	
	Other ()					

The AD1 Printer Type 250 Controllers corresponding to the finisher have been newly launched. These models includes the firmwave version 1.26 and the driver version 2.00.

The new product codes are:

For USA

- 1. A643-07 for Ricoh (Previous model : A643-00)
- 2. A643-17 for Gestetner (Previous model: A643-10)
- 3. A643-18 for Savin (Previous model : A643-20)
- 4. A643-19 for Lanier (Previous model : A643-30)

For Europe

5. A643-08 ALL Previous models: A643-01

When installing a controller on an AD-1 with a finisher, use these models.

Note: The previous models also can be used by changing the firmware to ver 1.26 or higher, and the driver to ver 2.00 or higher.

D	П	മ	ጠ	叩
	Ш	(6)	(0)	빎

PAGE: 1/1

Model: AD1-Printer Controller Type250 Date						No: 39	
Subject: All Black Printout					Prepared by: K.Ugaeri		
From: QAC 1st Field Information Dept.							
Classification:	Troubleshooting	g Part informat		tion [Action	required	
		☐ Electric	al		Servic	e manual revision	
	☐ Paper path	☐ Transmit/rec		eive [Retrof	fit information	
	Other ()						

SYMPTOM

All black printout in copy, fax, and printer mode.

CAUSE

Defective controller board; the image data signal from the controller is a constant "Low" (black).

The data signals from copy, fax, and the printer go through same OR processing, so all printed images become black.

SOLUTION

Change the controller board.

RIGOH

Technical Bulletin

PAGE: 1/3

RTB Correction

Reissue date: 5-Sep-97

The items in bold italic have been corrected or added.

Model: AD1 Date			te: 15-Dec-96		No: <i>14B</i>	
Subject: ROM History (AD1-FAX option)				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.						
Classification:	Troubleshooting	☐ Part informat		tion	Action	required
	☐ Mechanical	☐ Electric	al	☐ Servi		e manual revision
	☐ Paper path	☐ Transmit/rece		it/receive ⊠ Retro		fit information
	Other ()					

We inform you of the firmware history for AD1-Fax option.

(For USA Models)

A1945581	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194uxx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.23	DD95	CB2A	27F0	BD19	72A5	1st Mass Prod.
D	04	1.29	E6D7	83C2	E9BD	47BC	7F1A	November Prod.'96
E	05	1.38	EAAE	A99A	5C74	919A	5A3A	December Prod.'96
F	06	1.48	5029	5D2A	E457	1FF3	4ED2	March Prod.'97
G	07	1.58	2AEF	27EO	FD88	286A	E367	May Prod.'97
Н	08	1.77	43BO	3357	84BC	EAA2	C5F4	August Prod.'97

(For European/Asian Models)

A1945582	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194exx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.23	3A44	0A20	FC8A	691F	FEBA	1st Mass Prod.
С	03	1.29	3270	D0F9	39CD	F1E6	19A3	November Prod.'96
D	04	1.38	3745	FA2F	B98C	C966	E8B9	December Prod.'96
Е	05	1.48	3745	FA2F	B98C	C966	E8B9	March Prod.'97
F	06	1.58	8D00	FFBE	C502	1BB4	55FE	May Prod.'97
(G)	07t	1.78	C19B	E4F1	FF0B	9B9F	3290	Temporary
G	07	1.79	C2A4	E4F2	FF14	9B9F	3290	August Prod.'97



PAGE: 2/3

Model: AD1 Date: 15-Dec-96 No: 14B

(For European 2nd Language)

A1945585	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
			C.SUM	(OH)	(OL)	(1H)	(1L)	
А	01	1.38	F398	E170	B392	56E5	EB06	December Prod.'97
В	02	1.48	E08A	B674	46C1	DDFC	29C9	March Prod.'97
С	03	1.58	5494	87A5	28B5	B595	F1DF	May Prod.'97
(D)	04t	1.78	77E2	2CD4	372E	23DD	8FB4	Temporary
D	04	1.79	3D4C	2F88	6AFD	121C	2E4F	August Prod.'97

(For China)

A194	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	A194cxx		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.77	AB3E	C008	DDA3	7D7E	479B	August Prod.'97

(For Taiwan)

A194	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	A194txx		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.77	D672	7BEE	6E00	46A5	D572	August Prod.'97



PAGE: 3/3

Model: AD1 Date: 15-Dec-96 No: 14B

Symptom corrected	US	EU/	EU2	China	Taiwan
		ASIA			
For PTT Approval	_	G	D	В	С
1. Dial pulse signal from the other terminal was detected as a ringing signal. (France)					
2. Busy tone sometimes cannot be detected. This is solved by using two frequencies , 400 Hz and 900 Hz. (New Zealand)					
3. Interval between the dial pulses is out of specification. *Specification: 1000 ms. (New Zealand)					
Received files cannot be printed out from the HDD. When a small amount of data (less than 2K Bytes) is received and the communication is finished before writing to the HDD is finished, the data is not completely transferred to the HDD.	Н	G	D	В	С
In ISDN G3 mode, when a call comes from a PSTN G3 machine, the fax number stored in the machine's own Quick Dial 01 is displayed for a few seconds instead of the called terminal identification.	Н	G	D	В	С
Only for the Netherlands Dial Tone cannot be detected when the dial tone frequency lower limit (PSTN: Address 480406 ~ 7, PABX: Address 480419 ~ A) is less than 255 Hz. This problem happens with ver 1.29 or higher.	Н	(G)	(D)	В	С

RIGOH

Technical Bulletin

PAGE: 1/4

Model: AD1-E			Date	e: 15-Oct-97		No: 40
Subject: ROM Hi	story (AD1-E Copy Version)			Prepared by:	K.U	gaeri
From: QAC Field						
Classification:	Troubleshooting	Part informat		tion Action I		required
		Electric	al	☐ Se	ervic	ce manual revision
	☐ Paper path	☐ Transmit/rec		smit/receive 🛛 Retr		fit information
	Other ()					

We hereby inform you of firmware history for the AD1-E. (Copy)

For USA Models

A2245532	File No. (A224uxx)	Version	Total C.SUM	SUM(OH)	SUM(OH)	Production
D	01	1.18	7766	6521	1245	1st Mass Prod.
Е	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97

For European/Asian Models

A2245533	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
С	102	1.24EU1	F12D	8333	6DFE	August Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97

For European 2nd Language

A8105510(OL) A8105511(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU2	F29A	D4BF	1DDB

For European 3rd Language

A8105514(OL) A8105515(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	302	1.24EU3	2C91	F73A	3557
В	303	1.26EU3	649F	D770	8D2F



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 40

PAGE: 2/4

For European 4th Language

A8105516(OL) A8105517(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	402	1.24EU4	7A6A	F8BC	81AE
В	403	1.26EU4	E7F9	DA9F	0D5A

For the China Version

A8105512(OL) A8105513(OH)	File No. (A224CHxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	_	1	1	1	_

For the Taiwan Version

A2245534	File No. (A224TWxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	_	_	_	_	_



PAGE: 3/4

Model: AD1-E Date: 15-Oct-97 No: 40

Symptom Corrected	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
For the USA only	Н	_	_	_	_	_	_
A new SP mode is added.							
SP5-950: LG size paper detection on the by pass tray.							
* When this function is selected and LT ☐ size is inserted							
in the by-pass tray, the machine detects it as $LG \square$							
size paper.							
For the USA only	Н	_	_	_	_	_	_
To meet the Energy Star standard.							
After fax transmission using the ARDF with a stamper, the	Н	D	В	В	В	_	_
registration of the 1st copied paper by the ARDF is delayed.							
A new SP has been added.	F	С	Α	Α	Α	_	_
SP5-949:1= When one of the trays is empty, the paper end							
indicator (red LED) lights.							
The DF Jam display is cleared by lifting the DF up and down	F	С	Α	Α	Α	_	_
New SP Mode	Е						
SP6-006-4: ARDF Main-Scan Registration for the rear side.							
Specification	E						
When the trays do not have paper of the same size in different							
orientations, the machine continues to print using the sort							
function even if Rotate Sort is selected. (The previous software							
version stops the copy job when one of the trays is empty)							
The stapler may not work when the printer feeds out a stapled	E						
copy while feeding out the paper into the finisher in copy							
or fax mode.							
When two sheets of paper remain in the Duplex Unit and the	E						
printer prints in duplex mode, the printout will be made on the							
rear side of the paper remaining in the duplex unit.							



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 40

PAGE: 4/4

A2245532	A224-10	A224-15	A224-17	A22455
E	AK87070001~	9A37060001~	A7427060001~	L027080001~
F	AK87080023~	9A37080001~	A7427080001~	_
Н	AK87090001~	9A37090001~	A7427090001~	L027090031~

A2245533	A224-22	A224-26	A224-27	A224-29	A224-65
С	AK97070543~	3P30870001~	A7427080601~	A7427081501~	_
D	AK97090001~	3P30970001~	A7427090305~	A7427091035~	L0247090216~



PAGE: 1/3

Model: AD1-E			Date	te: 15-Oct-97		No: 41	
Subject: ROM History (AD1-E-FAX Option)					Prepared by: K.Ugaeri		
From: QAC Field	Information Dept.						
Classification:	☐ Troubleshooting	☐ Part inf	orma	tion	☐ Action	n required	
ļ	☐ Mechanical	Electric	al		☐ Service	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	□ Retro	fit information	
	☐ Other ()						

We inform you of the firmware history for AD1-E Fax option.

For the USA Model

A2255581	File No. (A225uxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	8BFA	1E6A	0E7F	8BEA	297B	1st Mass Prod.
В	02	1.42	5263	428B	6E43	AC89	D020	August Prod.'97

For the European/Asian Mode

A2255582	File No. (A225uxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	101	1.23	69B7	4A50	03D5	A175	A0E2	1st Mass Prod.
В	102	1.44	B8D4	1860	628D	C933	C347	August Prod.'97

For European 2nd Language

A2255585	File No. (A225exx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	201	1.23	9B94	ABF0	CD23	2F39	A571	1st Mass Prod.
В	202	1.44	33BE	2E1B	00C5	7330	E7F9	August Prod.'97

For European 3rd Language

A2255587	File No. (A225exx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	301	1.44	D106	F2A8	4FC6	CD50	8940	1st Mass Prod.



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 41

PAGE: 2/3

For the China Version

A2255586	File No. (A225cxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	FD76	933E	5C23	67C0	A353	1st Mass Prod.
В	02	1.42	A51B	C542	D6A2	0C23	6979	September Prod. '97

For the Taiwan Version

A2255584	File No. (A225txx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	0603	CF1A	54ED	74EA	AD16	1st Mass Prod.
В	02	1.42	F868	27F5	6104	69F5	AD64	September Prod. '97

Symptom corrected	US	EU/ ASIA	EU2	EU3	China	Taiwan
For PTT Approval 1. Dial pulses from the other terminal were detected as a ringing signal. (France) 2. Busy tone sometimes cannot be detected. It is solved by using two frequencies, 400 Hz and 900 Hz. (New Zealand) 3. The interval between the dial pulses is out of specification. *Specification: 1000 ms. (New Zealand)	_	В	В	A	В	В
Received files cannot be printed out from the HDD. When a small amount of data (less than 2 kbytes) is received and the communication is finished before writing to the HDD is finished, the data is not completely written to the HDD.	В	В	В	A	В	В
In ISDN G3 mode, when a call comes from a PSTN G3 machine, the fax number stored in Quick Dial 01 is displayed for a few seconds instead of the called terminal identification.	В	В	В	A	В	В
Only for the Netherlands Dial tone cannot be detected. When the dial tone frequency lower limit (PSTN: Address 480406~7, PABX: Address 480419~A) is less than 255HZ, this problem may occur. This problem happens with software version 1.29 or higher.	_	В	В	A	В	В



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 41

PAGE: 3/3

A2255581	A225-01	A225-06	A225-07	A225-08
В	A7567090071~	AN67090001~	9A47090001~	L025709146~

A2255582	A225–02	A225–03	A225-04	A225-09	A225–10
В	A7567081811~	A7567092653~	A7567083005~	A7567093083~	AN97100001~

PAGE: 1/5

RTB Correction

Reissue date: 20-Oct- 97

The illustrations have added as shown below.


Model: AD1/AD1-E Dat			Date	ə: 30-Apr-97	No: <i>031D</i>
Subject: Copy Quality (Dirty Background)				Prepared by: K.	Ugaeri
From: QAC 2nd F					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part info ☐ Electric ☐ Transm	al	 ☐ Servio	n required ce manual revision fit information

SYMPTOM

Dirty background or black spots appear on the background of copies.

Action required

First check whether the problem is related to printing or scanning. Then follow the steps listed below.



Drum Fatigue

Change the image density level in ADS mode to a lighter setting with SP5-106 to prevent more black dots from being made in generation copy mode.


Default : 4 Lightest: 1



TEST CHART 5-2-1

Technical Bulletin

Model: AD1 Date: 30-Apr-97 No: *031D*




PAGE: 2/5

- (1) Change SP2-999 from 0 to 1 (Manual).
- (2) Change SP2-996 from 140 to 255 (using the Zoom key).
- * Toner is not supplied with this setting.
- (3) Make 10 sky shot copies (A4 size) to reduce the toner density.
 -If the background is still dirty, make more sky shots.
- (4) Make the free run for 9 minutes using SP5-901.
- (5) Put "200" (for AD1) or "180" (for AD1 E) into SP2-996-1.
- (6) Make a free run for 3 minutes with SP5-901 again.
- (7) Remove and clean the PCU and the transfer unit to prevent toner scattering. Install them in the machine again.
- (8) Print out Pattern 12 using SP5-902-12.
- (9) End.
- *When the toner density is too light, change the toner density to 1 or 2 using SP2-911.

PAGE: 3/5

Model: AD1 Date: 30-Apr-97 No: 031D

Scanning problem



RIGOH

Technical Bulletin

PAGE: 1/5

Model: AD1/AD1	-E		Date	e: 20-Oct-9	97	No: 42
Subject: Dirty Background Problem				Prepared by: K.Ugaeri		
From: QAC Field	Information Dept.					
Classification:	☐ Troubleshooting	☐ Part inf	orma	tion	☐ Action	n required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	nit/rec	eive	☐ Retrof	fit information
	Other ()					

Symptom: Dirty Background (Overtoning)

Cause: Too much toner was supplied to the PCU because of a low q/m in the toner due to the following conditions.

- 1. After pre-setting the machine, it was not used for a few days.
- 2. Low copy volume machines had this problem after a vacation of more than 3 weeks.
- 3. Chemical reaction with ammonia gas, etc.

Action Required

AT INSTALLATION

Initialize twice with SP2-801 at installation.

* Even if the machine is pre-set in the laboratory, do it again at installation. If the machine does not run after pre-setting the machine, the q/m will go down drastically.


PAGE: 2/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42

-TEMPORARY COUNTERMEASURE-

IN THE FIELD

If the dirty background problem occurs, do the following adjustment as noted in. RTB 31D




Drum Fatigue

Change the image density in ADS mode to a lighter setting with by SP5-106 to prevent more black dots from being made in generation copy mode.

Default: 4 Lightest: 1

PAGE: 3/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42



- (1) Change SP2-999 from 0 to 1 (Manual).
- (2) Change SP2-996 from 140 to 255 (using the Zoom key).
- * Toner is not supplied with this setting.
- (3) Make 10 sky shot copies (A4 size) to reduce the toner density.
 -If the background is still dirty, make more sky shots.
- (4) Make the free run for 9 minutes using SP5-901.
- (5) Put "200" (for AD1) or "180" (for AD1 E) into SP2-996-1.
- (6) Make a free run for 3 minutes with SP5-901 again.
- (7) Remove and clean the PCU and the transfer unit to prevent toner scattering. Install them in the machine again.
- (8) Print out Pattern 12 using SP5-902-12.
- (9) End.
- *When the toner density is too light, change the toner density to 1 or 2 using SP2-911.



PAGE: 4/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42

-PERMANENT COUNTERMEASURE-

The firmware will be improved for this problem as follows.

This firmware will be available from the middle of October production '97.

1. The default of the Vcont value will be corrected.

```
AD1: approx 140 (Current) ---> 10 is added to the default. (150:New for USA)
---> 20 is added to the default. (160:New for EU/ASIA)
AD1E: approx 120 (Current) ---> 10 is added to the default. (130:New for USA)
---> 20 is added to the default. (140: New for EU/ASIA)
```

- 2. Initializing time will be longer. When a new PCU is installed, the machine initializes the PCU to attain a sufficient q/m for the toner. Its time has been changed from 3 min to 5 min.
- 3. Mixing time will be added.

The required mixing time for the developer will be calculated by comparing the difference between the previous VT and the latest one. The latest VT will be checked when the main switch is turned on or the machine is not for used more than 12 hours.

The table below will decide the mixing time.

r	
ı	=
ı	= 1
ı	
٠,	

Previous VT - Latest VT	Mixing Time (s)
-0.1	10
-0.2	30
-0.3	100
-0.4	300
0.4-	500

The developer will be mixed for 30 s. after every printing job. Then, 30 s will be deducted from the required mixing time (determined by the above table) till it is over.

Note

If the machine is not run for a long time (at the week-end or during a vacation), the machine will maintain the mixing of the developer unit to keep a sufficient toner q/m.



PAGE: 5/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42

4. The Vt value is corrected.

Ę


If any mixing time (item 3) remains, the Vt value is corrected as shown in the table below.

Remaining mixing time (s)	Vt correction
-100	0
-200	0.1
-300	0.4
-500	0.4

Note

If mixing time remains, Vt is corrected and toner is not supplied as easily.

* Items 3 and 4 are not available in Manual setting mode (SP2-999).





Technical Bulletin

Model: Printer Controller Type 250 (HDD Option)			e: 17-Oct-9	7	No: 43	
Subject: HDD Bracket for AD1 printer controller				Prepared	l by: κ.υ	gaeri
From: QAC Field Information Dept.						
Classification:	Troubleshooting	☐ Part info	ormat	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Servic	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information

PAGE: 1/2

The HDD bracket has been modified for the print-overrun problem caused by vibration from the duplex unit (refer to RTB37). These new brackets have been available from June production in 1997 (the cut-in serial number is A7327060001-)

Ricoh has prepared and sent the following Q'ty of the new bracket kits for the old HDD in the field.

Europe 1176 sets 1194 sets USA Asia 119 sets


☐ Mechanical ☐ Paper path Other (

*Kit number: A6439900 HDD Bracket Kit

This kit consists of the following parts.

① AA161125 Bushing – HDD	4 pcs
②A1935840 HDD Bracket	1 pc
③A1935842 Grounding plate – HDD	1 pc
	4 pcs
©03130050B Philips Pan Head Screw - M3x5	1 pc
©07120030W Nut -M3	2 pcs
A6438612 Instruction Guide	1 sheet

If you have the print overrun problem on an AD1 with a duplex unit or when you visit a customer whose machine has the old HDD bracket, please change the bracket to a new type.



PAGE: 2/2

Model: Date: 17-Oct-97 No: 43

Printer Hard Disk Type 250 (Machine Code: A643) INSTALLATION PROCEDURE

For Machine Code: A193 and A224 Copiers

THIS OPTION MUST BE INSTALLED BY A CUSTOMER SERVICE REPRESENTATIVE WHO HAS COMPLETED THE TRAINING COURSE ON THE BASE COPIER AND THIS OPTION.


△CAUTION

Before installing an optional unit, do the following:

- 1. If the FAX unit is installed, print out all messages stored in the memory, the lists of user-programmed items, and the system parameter list.
- 2. Turn off the main and the ac switches, and disconnect the power cord.

NOTE: • If the printer controller is already installed, remove the printer controller before attempting to install the printer hard disk.

 At least 6MB of memory are required on the printer controller for hard disk installation.
 If insufficient memory is installed in the printer controller, "Add memory 4MB or more," will be displayed.



- 1. Attach the grounding plate [A] to the hard disk drive [B]. (1 screw, 2 nuts)
- 2. Attach the four rubber bushings [C] to the bracket [D], as shown.
- Install the hard disk onto the bracket assembly (4 stepped screws).
 Note: Ensure the grounding plate feet are in contact with the bracket.

RIGOH

Technical Bulletin

PAGE: 1/2

Model: Printer Controller Type 250/251 Date		te: 15-Nov-97		No: 44		
Subject: ADAM/ADAM-E Printer Limitations				Prepared	d by: s.T	omoe
From: QAC Field Information Dept.						
Classification:	Troubleshooting	☐ Part inf	orma	tion	☐ Action	n required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	nit/rec	eive	Retro	fit information
	⊠ Other ()					

The limitations of the ADAM/ADAM-E printer controller are as shown below.

ADAM/ADAM-E printer controller limitations

No	Description	Recommendations/	Note
		Countermeasures	
1	There is no close button (X icon) at the upper-right corner of the task bar to close the printer properties window in the Print Setup menu.	* Press "OK" or "Cancel" button to close the printer properties window. * Click anywhere on the task bar , the close button (X icon) will appear at the right corner of the task bar.	
2	When a jam occurs in the Finisher at W1 or W2, the jam position is indicated in both WinPanel and the operation panel display only with W and does not specify whether it is W1 or W2.	Check both W1 and W2 when there is a jam at the W position in the finisher.	ADAM can recognize a jam at only the W position at W1 or W2 in the finisher.
3	WinPanel does not indicate the Toner Near End status.		"Add Toner" is shown on the WinPanel when toner ends.
4	If you perform initialization to format the Hard Disk while Data is coming in (when the Data-in indicator is blinking), the ADAM-E printer hangs up.	Format the Hard Disk while the printer is idle (no data in the buffer).	It is generally regarded as not possible to initialize the HDD while data is coming in.
5	When you print a Photoshop file	Print the file using the "High", "Mid" or "Low" print quality setting in the Photoshop printer setup window. Do not choose "draft print".	The ADAM-E Printer Driver does not support "draft print" in the Photoshop application.
6	While printing (data in buffer to print job), if you take the printer off-line and try to print a PCL font list, the printer hangs up.	Print the PCL fonts list while the printer is idle (no data in buffer).	It is generally regarded as not possible to print Printer Fonts while printing a job.



PAGE: 2/2

Model: Printer Controller Type 250/251 Date: 15-Nov-97 No: 44

No	Description	Recommendations/	Note
		Countermeasures	
7	Mode: Raster + Graphic Quality: Mid or Low", Freehand 5.0 files cannot be printed properly. Only a part of the image gets printed and the rest of the image is missing.		The limitation is unique for Freehand 5.0 and occurs with HP 5si as well. With Freehand 7.0, there is no such limitation. The default setting of the printer driver is "High".
8	When you print a Pagemaker file with "Graphic Mode: Raster + Graphic Quality: Mid or low" setting, rotated text cannot be printed properly.	Print with Graphic Quality: High.	The default setting of the printer driver is "High".
9	When you print a Pagemaker file using Windows 3.1 with "Graphic Mode: Raster + Graphic Quality: High, Mid or low", you will get horizontal black lines on photographic images.	Print with Graphic Mode: HP/GL.	
10	More than one set of Acrobat 2.0 files cannot be printed.	Upgrade Acrobat 2.0 to 3.0.	The limitation is unique for Acrobat 2.0. With Acrobat 3.0, there is no such limitation.

⊓₪	\bigcap	ПΠ
∐ԼԽ	(0)	

PAGE: 1/2

Model: AD1E-Printer Type 251 Da			Date	e: 30-Nov-9	97	No: 45
Subject: Firmware and Software History				Prepared by: K.Ugaeri		
From: QAC Field	Information Dept.					
Classification:	Troubleshooting	☐ Part inf	orma	tion	Action	n required
	☐ Mechanical	Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transmit/red		eive	□ Retrof	fit information
	Other ()					

A. Firmware for Controller Type 251.1. History and checksum List.

Ver	Check Sum		Released on
	U23	U24	
5.13 5.09 5.04	DB12 0E06	A541 D22F	'97.9.30 '97.8.26 1st Mass Prod.

2.Corrected Symptoms

	Ver.
When printing a banner page in a staple job, the banner page is printed incorrectly.	
Resource saving on the test page indicates "1219 kbytes allocated of 1219 Kbytes available." It should be "0 kbytes allocated of"	5.13
When printing with raster mode and custom paper size setting, output is incorrect.	
After printing a job using staple mode, if sending another job which changed the Page Protection Mode from the previous job's setting, sometimes it does not work, and the data stays in the print queue.	5.09
When setting a User Code, if you send data to print while the LCD shows "Input user code", it does not work without pressing the offline / online key even if you input the User Code.	



Model: AD1E-Printer Type 251 Date: 30-Nov-97 No: 45

PAGE: 2/2

- B. Driver Software for Win 3.1/Win 95
- 1. History List

Ver	Released on		
2.00	1st Mass Prod.		

- C. Host Panel for DOS
- 1. History List

Ver	Released on	
1.02	1st Mass Prod.	

Technical Bulletin

PAGE: 1/4

RTB Correction

Reissue date: 15-Dec-97

The items in bold italic have been corrected or added.

Model: AD1			Date	e: 15-Dec-97	No: 14C	
Subject: ROM History (A	D1-FAX Option)		Prepared by: K.Ugaeri			
From: QAC 2nd Field Info	ormation Dept.					
Classification:	Troubleshooting	☐ Part information		tion	n required	
		☐ Electric	al	☐ Servi	ce manual revision	
	☐ Paper path	☐ Transm	nit/rec	eive 🛛 Retro	fit information	
	Other ()					

Firmware history for the AD1-Fax option.

USA Model

A1945581	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194uxx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.23	DD95	CB2A	27F0	BD19	72A5	1st Mass Prod.
D	04	1.29	E6D7	83C2	E9BD	47BC	7F1A	November Prod.'96
E	05	1.38	EAAE	A99A	5C74	919A	5A3A	December Prod.'96
F	06	1.48	5029	5D2A	E457	1FF3	4ED2	March Prod.'97
G	07	1.58	2AEF	27EO	FD88	286A	E367	May Prod.'97
Н	08	1.77	43BO	3357	84BC	EAA2	C5F4	August Prod.'97

European/Asian Model

A1945582	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194exx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.23	3A44	0A20	FC8A	691F	FEBA	1st Mass Prod.
С	03	1.29	3270	D0F9	39CD	F1E6	19A3	November Prod.'96
D	04	1.38	3745	FA2F	B98C	C966	E8B9	December Prod.'96
Е	05	1.48	3745	FA2F	B98C	C966	E8B9	March Prod.'97
F	06	1.58	8D00	FFBE	C502	1BB4	55FE	May Prod.'97
(G)	07t	1.78	C19B	E4F1	FF0B	9B9F	3290	Temporary
G	07	1.79	C2A4	E4F2	FF14	9B9F	3290	August Prod.'97
Н	08	1.80	A450	E271	3B61	930F	E8EF	October Prod.'97



PAGE: 2/4

Model: AD1 Date: 15-Dec-97 No: 14C

European 2nd Language

A1945585	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194oxx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
А	01	1.38	F398	E170	B392	56E5	EB06	December Prod.'97
В	02	1.48	E08A	B674	46C1	DDFC	29C9	March Prod.'97
С	03	1.58	5494	87A5	28B5	B595	F1DF	May Prod.'97
(D)	04t	1.78	77E2	2CD4	372E	23DD	8FB4	Temporary
D	04	1.79	3D4C	2F88	6AFD	121C	2E4F	August Prod.'97
Ε	05	1.80	A63A	3372	A541	0793	FBF9	October Prod.'97

For European 3rd Language

A194	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	A194pxx		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.80	385B	D3CF	9ABE	01CD	019D	October Prod.'97

China

A194	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	A194pxx		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.80	AB3E	C008	DDA3	7D7E	479B	August Prod.'97

Taiwan

A194	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	A194txx		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.77	D672	7BEE	6E00	46A5	D572	August Prod.'97

Model: AD1

Technical Bulletin

Date: 15-Dec-97 No: 14C

PAGE: 3/4

Symptoms corrected	US	EU/	EU2	EU3	China	Taiwan
Cympionis corrected		ASIA				
The PC FAX (TR29) Option is supported	 	Н	E	В	_	_
For PTT Approval 1. Dial pulse signal from the other terminal was detected as a ringing signal. (France) 2. Busy tone sometimes cannot be detected. It is solved by using two frequencies, 400 Hz and 900 Hz. (New Zealand) 3. Interval between the dial pulses is out of specification. *Specification: 1000 ms. (New Zealand)	_	G	D		В	С
Received files cannot be printed out from the HDD. When a small amount of data (less than 2 kbytes) is received and the communication is finished before writing to the HDD is finished, the data is not completely transferred the HDD.	Н	G	D		В	С
In ISDN G3 mode, when a call comes from a PSTN G3 machine, the fax number stored in the machine's own Quick Dial 01 is displayed for a few seconds instead of the called terminal identification.	Н	G	D		В	С
Only for the Netherlands Dial Tone cannot be detected when the dial tone frequency lower limit (PSTN: Address 480406 ~ 7, PABX: Address 480419 ~• A) is less than 255 Hz. This problem happens with ver 1.29 or higher.	Н	(G)	(D)		В	С
The Two-in-one Function from HLT to LT size paper is not working.	G	F	С			
New System Switch When closed network is enabled and the ID is not programmed, all reception is disabled (this is a specification). A System Switch has been added to modify this. Switch 1E Bit 4. When closed network is turned on and the ID is not set: 0: Closed network is not available. 1: Only transmission is available.	G	F	С			
New System Switch The display of the remote terminal ID at AI redial: Switch 1E Bit 5 0: RTI/CSI is displayed. 1: The input Fax Number is displayed.	G	F	С			
The LCT and duplex tray are supported.	G	F	С			
The new HDD is supported.	G	F	С			
The NEST card option is supported.	G	F	С			
In the G3or G4 receiving mode, when the memory is full at the first block of any page, a part of the previous page is missing.	F	Е	В			
Receiving error in G4 mode When it is waiting for RSSP (or RSSN) after sending "CONN", the machine displays "communication error" if "DISC" comes.	F	E	В			

Technical **B**ulletin

PAGE: 4/4

Model: AD1	Date: 15-Dec-	No: 14C
	97	

Cumptom powered	US	EU/	EU2	EU3	China	Taiwan
Symptom corrected	00	ASIA	LUZ	200	Offilia	Taiwaii
The periodical auto service call function does not work.	F	Е	В			
For Canada only The number of redials in Canada is changed to meet the CS-03 standard. System switch 0F The setting for Canada (10h) is added. If the above switch is set to 10h, the number of redials (Communication switch 10) is set to 02h.	_					
For the Netherlands only Marketing Requirments 1. Dialling method default setting: PD changed to DTMF (User switch 1A/bit 0.1 changed to 0.1) 2. Default setting of Transmision mode: Memory Tx changed to Immediate Tx (User switch 00/bit 6 changed to 1) 3. International Access code: 00 changed to FF	_	Е	В			
For Austria only Marketing Requirments 1. Dialling method default setting: PD changed to DTMF (User switch 1A/bit 0.1 changed to 0.1) 2. Default setting of Transmission mode: Memory Tx changed to Immediate Tx (User switch 00/bit 6 changed to 1) 3. Number of redials: 5 changed to 10 (Communication switch 10/bit 0-4) 4. Redial interval in Memory Transmission: 5 min. changed to 1 min. (Communication switch 12/bit 0-7)	_	Е	В			
For New Zealand only The ringing detection time is changed. NCU parameters 07 & 0.8 : 010 changed to 015	_	E	В			
For Australia only Tx time of 2100 Hz is changed from 2.7 s to 3.5 s.	_	Е	В			
When the handset is picked up during ringing signal detection, the reception is disconnected but the reception job occasionally remains in the machine. In this case, the display does not go to "Handset Mode" even if the handset is picked up, or "line is busy" is displayed when directtx is made from the ADF.	E	D	A			
In manual tx mode with the handset, the operator presses the Start key and hangs up the handset at the same time. Then the transmission job remains in the machine. In this case, transmission and reception are both not available or "Handset mode" is always displayed. This problem can be solved by picking up the handset again.	E	D	A			
The chain dial function cannot be used in on-hook or handset mode.	E	D	Α			
When the machine stores a letter-size original using image rotation, the compression does not succeed, then the job is reset if the original is a complicated image scanned in photo mode.	E	_	_			

Technical Bulletin

PAGE: 1/5

RTB Correction

Reissue date: 15-Dec -97

The items in bold Italics have been corrected or added.

Model: AD1			Date	e: 15-Jan-97	No: 15F
Subject: ROM H	story (AD1 Copy Version)	Prepared by: K.Ugaeri			
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	Part informat Electrical Transmit/rece		☐ Servi	n required ce manual revision fit information

Firmware history for the AD1. USA

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
E	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
M	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97
Р	13	1.60	3042	A726	891C	August Prod.'97
R	14	1.62	5B56	CF0D	8C49	September Prod.'97
Τ	16	1.70	8D31	65E0	2751	October Prod.'97

Europe/Asia

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
E	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97
L	111A	1.48	7218	5558	1CC0	May Prod.'97
М	112	1.54	AAA8	7837	3271	June Prod.'97
N	113	1.60	1FE3	AEE1	7102	August Prod.'97
Р	114	1.62	794C	90BE	E88E	September Prod.'97
R	116	1.70	2208	D8BC	494C	October Prod.'97

^{*}Versions 1.35 and 1.3 are not released via Files.



PAGE: 2/5

Model: AD1 Date: 15-Jan-97 No: 15F

European 2nd Language

A6485510(OL)	File No.		Total		
A6485511(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F
J	209	1.60EU2	AE02	2277	8B8B
K	210	1.62EU2	CB8A	0ACC	C0BE
М	212	1.70EU2	4159	<i>50F0</i>	F069

European 3rd Language

A6485514 (OL)	File No.		Total		
A6485515(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	301	1.57EU3	9DBB	C908	D4B3
Α	302	1.60EU3	390A	FD07	3C03
В	303	1.62EU3	C69E	D5E3	F0BB
D	305	1.70EU3	006B	8E5E	720D

European 4th Language

A6485516 (OL)	File No.		Total		
A6485517(OH)	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390
Α	402	1.60EU4	4490	FDEF	46A1
В	403	1.62EU4	A30C	D9E5	C927
D	405	1.70EU4	3973	9405	A56E

China

A6485512 (OL)	File No.		Total		
A6485513(OH)	(A193CHxx)	Version	C.SUM	SUM(OH)	SUM(OL)
Е	04	1.62CH	B020	B056	FFCA
Н	07	1.70CH	1893	3AEA	DDA9

Taiwan

	File No.		Total		
A1935534	(A193TWxx)	Version	C.SUM	SUM(OH)	SUM(OL)
В	03	1.62TW	C05F	3BA0	94BF
Ε	06	1.70TW	470D	87F1	BF1C

Model: AD1

Technical Bulletin

Date: 15-Jan-97 No: 15F

PAGE: 3/5

Symptom Corrected	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
Dirty background problem (Refer to RTB 42)	T	R	М	D	D	Н	E
-Vt correction							
-Mixing time							
New SP mode	T	R	М	D	D	Н	E
•SP2-994: Vcont offset							
•SP9-999-14: Additional Mixing time display							
For the USA only	_						
New SP mode.	R						
SP5-950: LG size paper detection in the by pass tray.							
st When this function is selected and LT \square size paper is put							
in the by-pass tray, the machine detects it as $$ LG $$ \Box							
size paper.							
For the USA only	R						
Compliance with the Energy Star standard.							
After a fax transmission using the ARDF with the stamper,	R	Р	K	В	В	Е	В
the registration of the 1st sheet copied using the ARDF is							
delayed.							
New SP mode	Р	N	J	Α	Α	D	Α
SP 5-949							
0: Normal operation (during copying, if a tray empties, the paper							
end indicator does not light if paper in another tray can be used;							
the indicator will light if the user selects an empty tray)							
1: When one of the trays is empty, the indicator lights							
The DF Jam display is cleared by lifting the DF up and down	Р	N	J	Α	Α	D	Α
New SP Mode	N	М	G				
SP 6 -006-4: ARDF Main-Scan Registration for the rear side.							
Specification	N	М	G				
When the trays do not have the same size of paper in different							
orientations, the machine continues to print using the sort							
function even if the Rotate Sort function is selected.(The previous							
version software stops the copy job when one of the trays is							
empty.)							
The stapler may not work when the printer feeds out a stapled	N	М	G				
copy while feeding out paper into the finisher in copy or fax mode.	N.						
When 2 sheets of paper remain in the Duplex Unit and the printer	N	М	G				
prints in duplex mode, the printer image will be printed on the rear							
side of the remaining paper.		N 4					
SP5-808: The 3 languages cannot be selected with the previous		М	G				
software version.	М	L	F				
If a duplex copy is made with the ADF, Duplex Unit and 12M	IVI	L	「				
Memory and the original is jammed, the jammed original cannot							
be copied correctly during recovery.	М	1	F				
Paper jam when paper is fed from the 3rd tray immediately after	IVI	_	'				
feeding the paper from the 4th tray.(A jam or Y jam) with the following paper types.							
* 3rd Tray has paper of length less than 288 mm (A4 🔲)							
4th Tray has paper of length 289mm to 401mm (A4 🔲)							
4th tray has paper or length 209mm to 40 mm (A4 🗀)							



Technical Bulletin

PAGE: 4/5

Model: AD1 Date: 15-Jan-97 No: 15F

When the RAM was cleared with SP5-801, the white level and	L	K	Е		
the standard white plate density set at the factory were erased.	_	'`	_		
Toner scattering around black areas of the image on the rear	K	J			
side of duplex copies. The default of the separation output	• • •				
voltage was changed.					
✓SP2-901-1→-1800					
SP2-901-2→ -1800					
SP2-901-3→- 2500					
SP2-901-4→- 2500					
A blank sheet is printed out when the start key is pressed if the	J	Н			
memory is full. The scanning restarts after printing the scanned					
image and then the first original jams.					
Dirty Background.	Н	G			
1) Toner Density (SP2-911) was changed from 2 to 3 (Lighter).					
2) Free run time at PCU installation was changed					
from 1 min. to 3 min.					
Black Spots in the scanned image - A scanned low contrast	G	F			
image can be adjusted using 7 settings. Each setting has					
different gamma correction characteristics, MTF filter and					
threshold level (new SP mode: SP4-998,999)					
Dirty background on white images after negative\positive	G	F			
reversal.					
SC321 appears when the door is opened during memory	G	F			
copying if the start key is pressed after closing the door.					
The development bias setting (SP2-201) is initialized when the	G	F			
main switch is turned off.					
SC921-Memory Access Error	F	E			
After a paper jam while opening the door during memory output.					
SC101 appears when turning the main switch off/on after the	F	E			
IPU test pattern in SP mode.					
SP5-803: New PCU Detect is added to the input checks.	F	Е			
Memory copy priority of SP5-945 is added to Salesman	F	Е			
Program Mode.					
SP mode cannot be cleared when the main switch is turned	F	E			
off/on after going to the interrupt copy mode from SP mode.					
The finisher is supported.	<u> </u>	E			
While feeding out an original from the ADF, the Start key can be	Ε	D			
pressed. Then the incorrect document size is detected.					
The ARDF is supported.	Е	D			

PAGE: 5/5

Model: AD1 Date: 15-Jan-97 No: 15F

A1935532	A193-10	A193-15	A193-17	A193-55
Е	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	_	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	_	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	_	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	_	L5027042480~
М	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~
Р	A107080001~	6A77080001~	A7227080001~	L5027085441~
R	A107090001~	6A77090001~	A7227090001~	L5027096321~
T	TBA	TBA	TBA	ТВА

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65	A193-69
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~	
Е	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~	
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~	
G	AH27020001~	3L00270001~			L5027011424~	
Н	AH27020951~	_	A7227021026~	A7227021345~	L5027021685~	
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~	
K	TBA	3L00470001~	TBA	TBA	TBA	
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~	
М	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~	
N	AH27080001~	3L00870001~	A7227080969~	A7227081769~	L5027085755~	
Р	AH27090001~	3L00970001~	A7227090881~	A7227092701~	L5027096431~	A7227092891~
R	TBA	TBA	TBA	TBA	TBA	

A1935534	A193-19
В	A7227090821~

Technical Bulletin

PAGE: 1/4

MB Correction

Reissue date: 15-Dce-97

The items in bold italics have been corrected or added.

Model: AD1-E			Date	e: 15-Oct-97	No: 40A
Subject: ROM History (AD1-E Copy Version)				Prepared by: K.	Jgaeri
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	Part inf	al	☐ Serv	n required ice manual revision ofit information

Firmware history for the AD1-E (Copy)

USA Model

A2245532	File No. (A224uxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production
D	01	1.18	7766	6521	1245	1st Mass Prod.
Е	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97
К	06	1.30	432E	144E	2EE0	October Prod. '97

European /Asian Model

A2245533	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
С	102	1.24EU1	F12D	8333	6DFA	August Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97
F	105	1.30EU1	6F80	F07D	7F03	October Prod. '97

European 2nd Language

A8105510(OL) A8105511(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU3	649F	D770	8D2F
D	205	1.30EU3	76E6	6ED6	0810

PAGE: 2/4

Model: AD1-E Date: 15-Oct-97 No: 40A

European 3rd Language

A8105514(OL) A8105515(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	302	1.24EU3	2C91	F73A	3557
В	303	1.26EU3	649F	D770	8D2F
D	305	1.30EU3	6B26	4D86	1DA0

European 4th Language

A8105516(OL) A8105517(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	402	1.24EU4	7A6A	F8BC	81AE
В	403	1.26EU4	E7F9	DA9F	0D5A
D	405	1.30EU4	A7C1	4EF5	58CC

China Version

A8105512(OL) A8105513(OH)	File No. (A224CHxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	1	ı	1	1	_

Taiwan Version

A2245534	File No. (A224TWxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	_	_	-	-	_



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 40A

PAGE: 3/4

Symptom Corrected	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
Dirty background Problem (Refer to RTB 42)	K	F	D	D	D	_	_
-Vt correction							
-Mixing time							
New SP mode	K	F	D	D	D	_	_
•SP2-994: Vcont offset							
•SP9-999-14: Additional Mixing time display							
For the USA only	Н	_	_	_	_	_	_
New SP mode							
SP5-950: LG size paper detection on the by pass tray.							
st When this function is selected and LT \square size paper is put							
in the by-pass tray, the machine detects it as $LG \square$							
size paper.							
For the USA only	Н	_	_	_	_	_	_
To meet the Energy Star standards.							
After fax transmission using the ARDF with a stamper, the	Н	D	В	В	В	_	_
registration of the 1st copied paper by the ARDF is delayed.							
A new SP has been added.	F	С	Α	Α	Α	_	_
SP5-949:1= When one of the trays is empty, the paper end							
indicator (red LED) lights.							
The DF Jam display is cleared by lifting the DF up and down	F	С	Α	Α	Α	_	_
New SP Mode	Е						
SP6-006-4: ARDF Main-Scan Registration for the rear side.							
Specification	Е						
When the trays do not have paper of the same size in different							
orientations, the machine continues to print using the sort							
function even if Rotate Sort is selected. (The previous software							
version stops the copy job when one of the trays is empty)							
The stapler may not work when the printer feeds out a stapled	Е						
copy while feeding out the paper into the finisher in copy							
or fax mode.							
When two sheets of paper remain in the Duplex Unit and the	Е						
printer prints in duplex mode, the printout will be made on the							
rear side of the paper remaining in the duplex unit.							





PAGE: 4/4

Model: AD1-E Date: 15-Oct-97 No: 40A

A2245532	A224-10	A224-15	A224-17	A22455
E	AK87070001~	9A37060001~	A7427060001~	L027080001~
F	AK87080023~	9A37080001~	A7427080001~	_
Н	AK87090001~	9A37090001~	A7427090001~	L027090031~
K	TBA	TBA	TBA	TBA

A2245533	A224-22	A224-26	A224-27	A224-29	A224-65
С	AK97070543~	3P30870001~	A7427080601~	A7427081501~	_
D	AK97090001~	3P30970001~	A7427090305~	A7427091035~	L0247090216~
F	TBA	TBA	TBA	TBA	TBA

Technical Bulletin

PAGE: 1/3

MB Correction

Reissue date: 15-Dce-97

The items in bold Italics have been corrected or added.

Model: AD1-E Date			e: 15-Dec-97	No: 41A		
Subject: ROM History (AD1-E-FAX Option)				Prepared by: K.Ugaeri		
From: QAC Field Infor	mation Dept.					
Classification:	Troubleshooting	Part info	orma	tion	n required	
	☐ Mechanical	☐ Electric	al	☐ Servi	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	ceive 🛛 Retro	fit information	
	Other ()					

Firmware history for the AD1-E Fax option.

USA Model

A2255581	File No. (A225uxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	8BFA	1E6A	0E7F	8BEA	297B	1st Mass Prod.
В	02	1.42	5263	428B	6E43	AC89	D020	August Prod.'97

European/Asian Model

A2255582	File No. (A225exx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	69B7	4A50	03D5	A175	A0E2	1st Mass Prod.
В	02	1.44	B8D4	1860	628D	C933	C347	August Prod.'97
С	03	1.48	A559	17AD	588A	CC68	37CF	October Prod.'97

European 2nd Language

A2255585	File No. (A225oxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	9B94	ABF0	CD23	2F39	A571	1st Mass Prod.
В	02	1.44	33BE	2E1B	00C5	7330	E7F9	August Prod.'97
С	03	1.48	A73F	2F37	3F7E	6A45	EBC1	October Prod.'97

European 3nd Language

A2255587	File No. (A225pxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.44	D106	F2A8	4FC6	CD50	8940	1st Mass Prod.
В	02	1.48	3A07	F808	870A	C4D6	D4FD	October Prod.'97



Model: AD1-E

Technical Bulletin

Date: 15-Dec-97 No: 41A

PAGE: 2/3

China Version

A2255586	File No. (A225cxx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	FD76	933E	5C23	67C0	A353	1st Mass Prod.
В	02	1.42	A51B	C542	D6A2	0C23	6979	September Prod. '97

Taiwan Version

A2255584	File No. (A225txx)	Version	Total C.SUM	SUM (OH)	SUM (OL)	SUM (1H)	SUM (1L)	Production
Α	01	1.23	0603	CF1A	54ED	74EA	AD16	1st Mass Prod.
В	02	1.42	F868	27F5	6104	69F5	AD64	September Prod. '97

Symptom corrected	US	EU/	EU2	EU3	China	Taiwan
		ASIA				
The PC FAX (TR29) option is supported.	_	С	С	В	_	_
For PTT Approval 1. Dial pulses from the other terminal were detected as a ringing signal. (France) 2. Busy tone sometimes cannot be detected. It is solved by using two frequencies, 400 Hz and 900 Hz. (New Zealand) 3. The interval between the dial pulses is out of specification. *Specification: 1000 ms. (New Zealand)	_	В	В	A	В	В
Received files cannot be printed out from the HDD. When a small amount of data (less than 2 kbytes) is received and the communication is finished before writing to the HDD is finished, the data is not completely written to the HDD.	В	В	В	A	В	В
In ISDN G3 mode, when a call comes from a PSTN G3 machine, the fax number stored in Quick Dial 01 is displayed for a few seconds instead of the called terminal identification.	В	В	В	A	В	В
Only for the Netherlands Dial tone cannot be detected. When the dial tone frequency lower limit (PSTN: Address 480406~7, PABX: Address 480419~A) is less than 255HZ, this problem may occur. This problem happens with software version 1.29 or higher.	_	В	В	A	В	В

Model: AD1-E

Technical Bulletin

Date: 15-Dec-97 No: 41A

A2255581	A225-01	A225-06	A225-07	A225-08
В	A7567090071~	AN67090001~	9A47090001~	L025709146~

A2255582	A225–02	A225–03	A225–04	A225–09	A225–10
В	A7567081811~	A7567092653~	A7567083005~	A7567093083~	AN97100001~
С	TBA	TBA	TBA	TBA	TBA

Technical Bulletin

PAGE: 1/5

MB Correction

Reissue date: 15-Dce-97

The items in bold Italics have been corrected or added.

Model: AD1/AD1	-E		Date	e: 20-Oct-97	No: 42A
Subject: Dirty Background Problem			Prepared by: K.U	Jgaeri	
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part info	al	☐ Servi	n required ce manual revision fit information

Symptom: Dirty Background (Overtoning)

Cause: Too much toner was supplied to the PCU because of a low q/m in the toner due to the following conditions.

- 1. After pre-setting the machine, it was not used for a few days.
- 2. Low copy volume machines had this problem after a vacation of more than 3 weeks.
- ${\it 3. Chemical \ reaction \ with \ ammonia \ gas, \ etc.}$

Action Required:

The new BICU Firmware has been released for the dirty background problem for the following versions.


(AD1)	(AD1E)
A1935532 Ť (USA)	A2245532 K (USA)
A1935533 R (EU/Asia)	A2245533 F (EU/Ásia)
A6485570 M (EU2)	A8105570 D (EU2)
A6485573 D (EU3)	A8105573 D (EU3)
A6485574 D (EU4)	A8105574 D (EU4)
A6485572 H (China)	• •
A1935534 E (Taiwan)	

The new firmware has the countermeasure in which not too much toner is supplied, as shown on the attached sheets (refer to the 4th and 5th pages). Download the above software into the BICU board at installation or at emergency maintenance using the attached procedure if the machine has the previous version software.

PAGE: 2/5


Model: AD1/AD1-E Date: 20-Oct-97 No: 42A

Upgrade Procedure



PAGE: 3/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42A





Model: AD1/AD1-E Date: 20-Oct-97 No: 42A

< PERMANENT COUNTERMEASURE >

The firmware will be improved for this problem as follows.

This firmware will be available from the middle of October production '97.

1. The default of the Vcont value will be corrected.

AD1 : approx 140 (Current) ---> 10 is added to the default. (150: New for USA)

---> 20 is added to the default. (160: New for EU/ASIA)

PAGE: 4/5

AD1E: approx 120 (Current) ---> 10 is added to the default. (130: New for USA)

---> 20 is added to the default. (140: New for EU/ASIA)

The added value is stored in the new SP mode 2-994.

- 2. Initializing time will be longer. When a new PCU is installed, the machine initializes the PCU to attain a sufficient q/m for the toner. Its time has been changed from 3 min to 5 min.
- 3. Mixing time will be added.

The required mixing time for the developer will be calculated by comparing the difference between the previous VT and the latest one. The latest VT will be checked when the main switch is turned on or the machine is not used for more than 12 hours.



The table below will decide the mixing time.

Previous VT - Latest VT Mixing Time (s)

9
10
30
100
300
500

The developer will be mixed for 30 s after every printing job.

Then, 30 s will be deducted from the required mixing time (determined by the above table) till it is over.

Note

If the machine is not run for a long time (at the week-end or during a vacation), the machine will maintain the mixing of the developer unit to keep a sufficient toner q/m.



PAGE: 5/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42A

4. The Vt value is corrected.

If any mixing time (item 3) remains, the Vt value is corrected as shown in the table below.


п	$\overline{}$
п	=
п	_
п	

Remaining mixing time (s)	Vt correction
-100	0
-200	0.1
-300	0.4
-500	0.4

Note

If mixing time remains, Vt is corrected and toner is not supplied as easily.

* Items 3 and 4 are not available in Manual setting mode (SP2-999).



Technical Bulletin

Model: ISDN Option				ate: 15-Dec-97		No: 46
Subject: US National ISDN				Prepared by: K.Hattori		
From: IPP Busine						
Classification:	☐ Troubleshooting ☐ Mechanical	☐ Part informat		_ ⊠ s	ervi	n required ce manual revision
	☐ Paper path ☐ Other ()	Transm	iit/rec	eive 🔲 R	etro	fit information

This bulletin informs the settings required when the machine is connected to the US National ISDN network

Models: ADAM

Subscriber Number

Input the subscriber number given by the telephone company at:

1.G4 SUBSCRIBER NO.1 (MAIN)

2.G3 SUBSCRIBER NO.1 (MAIN)

• SPID Number (Service Profile Identification Number)

Input the SPID number given by the telephone company at :

1.G4 SUBSCRIBER NO.2 (Sub)

2.G3 SUBSCRIBER NO.2 (Sub)

Note: Input a "_" (pause) before the SPID number.

G4 Internal Switches

SW No.	Bit	Setting	Definition
SW11	Bit 1	0: Dynamic TEI	Type of TEI used (Layer 2) (Default)
SW13	Bit 2	1: Yes	Attachment of calling party number (L3 SET UP)
	Bit 5	1: Yes	Attachment of channel information element (L3 CONN)
SW14	Bit 0	1: Speech	ISDN G3 information transfer capability (L3)
	Bit 5	1: Keypad facility	Called ID mapping (L3)
SW15	Bit 7	1: On	Transmission of STAT in reply to STAT_ENQ received in the U0 state.
SW19	Bit 0	1: Permanent	Permanence of the link (L2)
	Bit 2	1: On	SPID procedure (L2)
	Bit 3	1: On	G4 SPID procedure (L2)

Note: After completing a G4 service mode operation, turn off the machine and turn it back on to make the new settings take effect.

PAGE: 1/1

Classification:

Technical Bulletin

Part information

Electrical

Date: 15-Dec-97

J (PAGL. 1/1						
e: 15-Dec-97 No: 47							
Prepared by: K.U	lgaeri						
ion	n required						

☐ Service manual revision

☐ Retrofit information

DACE: 1/1

☐ Paper path ☐ Transmit/receive Other (

☐ Mechanical

Model: PS330 (Paper Tray for AD1/AD1-E)

SYMPTOM: Paper jam

Subject: Paper Feed Roller

From: QAC Field Information Dept.

CAUSE: Paper skewing or no feed from PS330 (Paper Tray)


Countermeasure: The diameter of the paper feed roller has been modified from 30\$\phi\$ to

32\$\phi\$ to improve paper feed.

Action Required: Ricoh has prepared a countermeasure roller kit for the machines in the field and sent them to each subsidiary.

> RC: 2150 sets (4 rollers/set) RE: 3750 sets (4rollers/set) RH: 374 sets (4rollers/set)

* Use these new rollers for machines which have the paper jam problem.



Technical Bulletin

PAGE: 1/4

RTB Correction

Reissue date: 15-Jan-98

The items in bold italic have been corrected or added.

Model: AD1		e: 15-Dec-97	No: 14D			
Subject: ROM History (AD1-FAX Option)				Prepared by: K.Ugaeri		
From: QAC 2nd Field Information Dept.						
Classification:	☐ Troubleshooting ☐ Part informa		ormat	tion	required	
	☐ Mechanical	☐ Electrica	al	☐ Service	e manual revision	
	☐ Paper path ☐ Transmit/rec		eive 🗵 Retrot	fit information		
	☐ Other ()					

AD1-Fax option firmware history.

USA

A1945581	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194uxx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
С	03	1.23	DD95	CB2A	27F0	BD19	72A5	1st Mass Prod.
D	04	1.29	E6D7	83C2	E9BD	47BC	7F1A	November Prod.'96
E	05	1.38	EAAE	A99A	5C74	919A	5A3A	December Prod.'96
F	06	1.48	5029	5D2A	E457	1FF3	4ED2	March Prod.'97
G	07	1.58	2AEF	27EO	FD88	286A	E367	May Prod.'97
Н	08	1.77	43BO	3357	84BC	EAA2	C5F4	August Prod.'97

Europe/Asia

A1945582	File No.	Version	Total	SUM	SUM	SUM	SUM	Production
	(A194exx)		C.SUM	(OH)	(OL)	(1H)	(1L)	
В	02	1.23	3A44	0A20	FC8A	691F	FEBA	1st Mass Prod.
С	03	1.29	3270	D0F9	39CD	F1E6	19A3	November Prod.'96
D	04	1.38	3745	FA2F	B98C	C966	E8B9	December Prod.'96
E	05	1.48	ABC7	EEBA	0F84	A0D9	0943	March Prod.'97
F	06	1.58	8D00	FFBE	C502	1BB4	55FE	May Prod.'97
(G)	07t	1.78	C19B	E4F1	FF0B	9B9F	3290	Temporary
G	07	1.79	C2A4	E4F2	FF14	9B9F	3290	August Prod.'97
Н	08	1.80	A450	E271	3B61	930F	E8EF	October Prod.'97

Technical Bulletin

PAGE: 1/4

MB Correction

Reissue date: 15-Jan-98

The items in bold italics have been corrected or added.

Model: AD1-E		Date: 15-Oct-97		No: 40B	
Subject: ROM Hi	story (AD1-E Copy Version)		Prepared by: K.l	Jgaeri	
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	Part inf Electric	al	☐ Servi	n required ce manual revision fit information

AD1-E (Copy) firmware history.

USA

A2245532	File No. (A224uxx)	Version	Total C.SUM	SUM(OH)	SUM(<i>OL</i>)	Production
D	01	1.18	7766	6521	1245	1st Mass Prod.
E	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97
K	06	1.30	432E	144E	2EE0	October Prod. '97

Europe/Asia

A2245533	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
С	102	1.24EU1	F12D	8333	6DFA	August Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97
F	105	1.30EU1	6F80	F07D	7F03	October Prod. '97

Europe 2nd Language

A8105510(OL) A8105511(OH)	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU 2	F29A	D4BF	1DDB
D	205	1.30EU 2	76E6	6ED6	0810

Technical Bulletin

PAGE: 1/5

MB Correction

Reissue date: 31-Jan-97

The items in bold Italics have been corrected or added.

Model: AD1/AD1	-E	Date: 20-Oct-97		No: 42B		
Subject: Dirty Background Problem				Prepared by: K.Ugaeri		
From: QAC Field Information Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part inf ☐ Electric ☐ Transm	al	☐ Servi	n required ice manual revision ofit information	

Symptom: Dirty Background (Overtoning)

Cause: Too much toner was supplied to the PCU because of a low q/m in the toner due to the following conditions.

- 1. After pre-setting the machine, it was not used for a few days.
- 2. Low copy volume machines had this problem after a vacation of more than 3 weeks.
- 3. Chemical reaction with ammonia gas, etc.

Action Required:

The new BICU Firmware have been released for the dirty background problem from the following versions.

(AD1)	(AD1E)
A1935532 Ť (USA)	A2245532 K (USA)
A1935533 R (EU/Asia)	A2245533 F (EU/Asia)
A6485570 M (EU2)	A8105570 D (EU2)
A6485573 D (EU3)	A8105573 D (EU3)
A6485574 D (EU4)	A8105574 D (EU4)
A6485572 H (China)	
A1935534 E (Taiwan)	


The new firmware has the countermeasure in which not too much toner is supplied, as shown on the attached sheets (refer to the 4th and 5th pages).

Download the above software into the BICU board at installation or at emergency maintenance using the attached procedure if the machine has the previous version software.

PAGE: 2/5


Model: AD1/AD1-E Date: 20-Oct-97 No: 42A

Upgrade Procedure



PAGE: 3/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42A





PAGE: 4/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42B

DETAILS

The firmware has been improved to deal with this problem as shown below.

1. The default of the Vcont value will be corrected.

```
AD1: approx 140 (Current) ---> 10 is added to the default. (150: New for USA) ---> 20 is added to the default. (160: New for EU/ASIA) AD1E: approx 120 (Current) ---> 10 is added to the default. (130: New for USA) ---> 20 is added to the default. (140: New for EU/ASIA) The added value is stored in the new SP mode 2-994.
```

- 2. Initializing time will be longer. When a new PCU is installed, the machine initializes the PCU to attain a sufficient q/m for the toner. Its time has been changed from 3 min to 5 min.
- 3. Mixing time will be added.

The required mixing time for the developer will be calculated by comparing the difference between the previous VT and the latest one. The latest VT will be checked when the main switch is turned on or the machine is not used for more than 12 hours.



The table below will decide the mixing time.

Previous VT - Latest VT	Mixing Time (s)
-0.1	10
-0.2	30
-0.3	100
-0.4	300
0.5-	500

The developer will be mixed for 30 s after every printing job.

Then, 30 s will be deducted from the required mixing time (determined by the above table) till it is over.

Note

If the machine is not run for a long time (at the week-end or during a vacation), the machine will maintain the mixing of the developer unit to keep a sufficient toner q/m.



PAGE: 5/5

Model: AD1/AD1-E Date: 20-Oct-97 No: 42B

4. The Vt value is corrected.

If any mixing time (item 3) remains, the Vt value is corrected as shown in the table below.


_			
Г	_		í
П	_	_	
П	_		
П		Z	,
4	_		

Remaining mixing time (s)	Vt correction
-100	0
-200	0.1
-300	0.4
-500	0.4

Note

If mixing time remains, Vt is corrected and toner is not supplied as easily.

* Items 3 and 4 are not available in Manual setting mode (SP2-999).





PAGE: 1/3

RTB Correction

Reissue date: 15-Jun-98

The items in bold italics have been corrected or added.

The illustration has changed as shown below.

Model: AD1(LCT	Option)		Date	e: 31-Jan-98	No: 48A
Subject: Paper ja	am and Noise			Prepared by: K.	Jgaeri
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	⊠ Part inf ☐ Electric ☐ Transm	al	_ ☐ Serv	n required ice manual revision ofit information

During an internal test, the following problems were found and some parts have been improved from December production '97.

SYMPTOM

- 1. The grounding plate (A6676151) was broken at installation.
- 2. Paper jam
- 3. Noise

CAUSE

- 1. When the LCT is installed on the main frame, the spring plate might be cracked.
- 2. When the dust rubbed off the timing belt gets between the timing pulley and the drive shaft, the rotation of the pulley is affected and paper jams might occur.
- 3. Rotation noise from the relay roller (but the noise level is still within specification)

COUNTERMEASURE


1. When installing the LCT, take care not to press the grounding plate too hard.

Permanent countermeasure

The shape of the grounding plate has been modified (A6676151->A6676151A) and RCL will supply the countermeasure parts to each subsidiary.

RC: 50 sets RE: 80 sets RH: 20 sets







PAGE: 2/3

Model: AD1(LCT Option) Date: 31-Jan-98 No: 48A

2. Clean the drive shaft of the timing pulleys (P7 – Index 24,25,27).

Permanent Countermeasure

To prevent this problem in the LCT, the material of the shaft and the shape of the pulley and collar have been modified to reduce the dust from the timing belt and to prevent the dust from getting into the pulley. RCL will supply the countermeasure parts to each subsidiary.

RC: 100 sets RE: 160 sets RH: 40 sets


1. AA140627 → AA140693 Drive Shaft – Feed Roller

2. H5154713 → A6672615 *Timing Pulley Collar – 6x8*

3. H5154714 → A6672616 *Timing Pulley – 22Z*

X/O as a combination

The interchangeability for these parts is available as a combination.






PAGE: 3/3

Model: AD1(LCT Option) Date: 31-Jan-98 No: 48A

3. Lubricate the shaft of the feed rollers.

Permanent Countermeasure

To reduce the rotation noise from the relay roller, a fly wheel is added to stabilize the rotation. The material of the shaft and the shape of the timing pulley have been modified.





PAGE: 1/3

RTB Correction

Reissue date: 15-Feb-98

The items in bold italic have been corrected or added.

Model: AD1-Print	ter Type 250		Date	e: 23-Jul-97	No: 35C
Subject: Firmwar	e and Software History			Prepared by: K.U	Jgaeri
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path	☐ Part inf☐ Electric☐ Transm	al	☐ Servi	n required ce manual revision ofit information
	Other ()				

- A. Firmware for Controller Type 250.1. History and Checksum List.

Ver	Check Sum		Released on
	U23	U24	
1.37	C722	1E0C	'97.12.17
1.35	3301	1D08	'97.9.30
1.32	8FD5	3EFD	'97.8.26
1.26	3EC3	64E8	'97.6.10
(1.24)	F38F	AC48	Temporary ('97.5.28)
(1.21)	7A04	AC4F	Temporary ('97.5.20)
1.08	59BA	F0C2	'97.4.2
1.07	901F	6D97	'97.2.2
1.06	5DAD	1E45	'96.12.17
1.03			1st Mass Prod. ('96.12.5)

2.Corrected Symptom

	Ver.
In the Dutch version, the expressions of "On" and "Off" are incorrect.	1.37
When printing a banner page in a staple job, the banner page is printed incorrectly.	
Resource saving on the test page indicates "1219 kbytes allocated of 1219 kbytes available." It should be "0 Kbytes allocated of"	1.35
When printing in Raster mode with custom paper size setting, output is incorrect.	
The Line Per Page setting value in the PCL menu was changed after power was switched off/on.	
While data is in the print queue, if you press the Job Reset key, some problems may occur.	
While data is in the print queue, either Memory Overflow or Lock Up occured. (Acrobat, Page Maker)	1.32
After printing 300 dpi data, only half of the 600 dpi data is printed out,.	
Image cut off if the previous job was printed using long edge feed (300 dpi) and the current job is printed with short edge feed (300 dpi).	
After printing data for a small paper size, if you print data for a bigger paper size, only data to fill the previous paper size is printed out.	



PAGE: 2/3

Model: AD1-Printer Type 250 Date: 23-Jul-97 No: 35C

	Ver.
After printing a job using staple mode, if sending another job which changed the Page Protection Mode from the previous job's setting, sometimes it does not work, and the data stays in the print queue.	1.32
When setting User Code, if you send data to print while the LCD shows "Input user code", it does not work without pressing the offline / online key even if you input the User Code.	
Side-to-side motion of the finisher does not work in the energy save and night timer mode.	
The demo page cannot be printed. (*This is a problem only for version 1.24)	1.26
Lock-up occurs occasionally while the printing data is being stored on the HDD due to a sector control failure.	
Lock-up when the job reset button is pressed during data storage.	(1.24)
The finisher is supported.	
Print overrun because of access time to HDD. The band buffer is increased from 660KB to 4MB. * * If the controller has a HDD, more than 4MB of SIMM memory must be added.	(1.21)
General Protection Fault during Landscape Printing in Raster mode.	
Output of a Genoa FTS file is different from that of HP (* *Genoa FTS file).	
Page ordering is wrong. (* * For duplex printing, interleave on, and interrupt copying)	1.08
The printer hangs up when printing word data with lines shaded with colours as HP/GL. (* Duplex printing, HP/GL mode and coloured lines)	1.07
Paper jam in Duplex mode when an A4 size page is printed on A3 paper.	



PAGE: 3/3

Model: AD1-Printer Type 250 Date: 23-Jul-97 No: 35C

B. Driver Software for Win 3.1/Win 95

1. History List

Released on
'97.12.17
·97.7.9
'97.5.19
'97.4.2
'97.2.2
1st Mass Prod.('96.12.5)

2. Corrected Symptoms

	Ver.
1) When you set Lines Per Page to a small value and print Landscape data, the top margin will be shifted down.	2.11
2) PageMaker 6.5 and Word Perfect 8.0, duplex setting is disabled (grayed out) in the application's setting boxes.	
 3) Help file (1) The wording "External Tray (F/U)" has been deleted. This may confuse users who don't understand that External Tray and External Tray (F/U) are the same thing. (2) In the Staple section, the first sentence contains a mistake. (3) In the Printer Memory section, it says that the printer self test page shows the memory size in KB. The test page actually shows it in MB. 4) The default setting of Page Protect is changed from On to Auto. 5) A driver installation error occurs when you install using Add Printer. 	
 Even if setting True Type Mode to "Download as True Type ", it is output as a bit image. When printing Hound.doc with Win 3.1, a part of the Univers Font was printed incorrectly. When setting B5 Env.in the Bypass Tray, WinPanel shows "Add F4 paper into Bypass Tray." When installing Win95 driver by Add Printer, the help File was not installed. 	2.00
The finisher is supported.	1.30
In Raster mode, a part of the graphic data cannot be printed correctly.	1.21
Power Point for Windows 95 cannot print raster Images.	1.10

C. Host Panel for DOS

1. History List

Ver	Released on
1.02	'97.5.25
1.01	'97.4.2
1.00	1st Mass Prod. ('96.12.5)

2. Corrected Symptom

	Ver.
Profile which has the Host Panel setting information in Duplex mode cannot be opened correctly.	1.02
TBA (To Be Announced)	1.01

Technical Bulletin

PAGE: 1/2

MB Correction

Reissue date: 15-Feb-98

The items in bold italics have been corrected or added.

Model: AD1E-Printer Type 251		Date: 30-Nov-97		No: 45A	
Subject: Firmware and Software History			Prepared by: K.Ugaeri		
From: QAC Field Information Dept.					
Classification:	Troubleshooting	☐ Part inf	orma	tion	on required
	☐ Mechanical	☐ Electric	al	☐ Serv	ice manual revision
	☐ Paper path	☐ Transm	nit/rec	eive 🛛 Retr	ofit information
	Other ()				

- A. Firmware for Controller Type 251.
- 1. History and checksum List.

Ver	Check Sum		Released on
	U23	U24	1
5.15 5.13	8C25 DB12	AC42 A541	' 97.12.17 '97.9.30
5.09 5.04	0E06	D22F	'97.8.26 1st Mass Prod.

2.Corrected Symptoms

	Ver.
For the Dutch version, the expressions of "On" and "Off" are incorrect.	5.15
When printing a banner page in a staple job, the banner page is printed incorrectly.	
Resource saving on the test page indicates "1219 kbytes allocated of 1219 Kbytes available."	5.13
It should be "0 kbytes allocated of"	
When printing with raster mode and custom paper size setting, output is incorrect.	
After printing a job using staple mode, if sending another job which changed the Page Protection Mode from the previous job's setting, sometimes it does not work, and the data stays in the print queue.	5.09
When setting a User Code, if you send data to print while the LCD shows "Input user code", it does not work without pressing the offline / online key even if you input the User Code.	



PAGE: 2/2

Model: AD1E-Printer Type 251 Date: 30-Nov-97 No: 45A

B. Driver Software for Win 3.1/Win 95

1. History List

Ver	Released on
2.11	'97.12.17
2.00	1st Mass Prod.

2. Corrected Symptom

	Ver.
1) When you set Lines Per Page to a small value and print Landscape data, the top margin will be shifted down.	2.11
2) Pagemaker 6.5 and Word Perfect 8.0, duplex setting is disabled (grayed out) in the application's setting boxes.	
3) Help file	
(1) The wording "External Tray (F/U)" has been deleted. This may confuse users who don't understand that External Tray and External Tray (F/U) are the same thing.	
(2) In the Staple section, the first sentence contains a mistake.	
(3) In the Printer Memory section, it says that the printer self test page shows the memory size in KB. The test page actually shows it in MB.	
4) The default setting of Page Protect is changed from On to Auto.	
5) A driver install error occurs when you install using Add Printer.	

C. Host Panel for DOS

1. History List

Ver	Released on		
1.02	1st Mass Prod.		

በ@@	ПП
	Ш

PAGE: 1/1

Model: Adam Da		Date: 15-Feb-98		98	No: 49	
Subject: PC-Fax Expander Type 250		Prepared by: Y. Furuya				
From: Technical Service Department.						
Classification:	Troubleshooting	☐ Part inf	ormat	tion	☐ Action	n required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	$oxed{\boxtimes}$ Other (Service manual for	new option))			

The service manual for the PC-Fax Expander Type 250 (12 pages) follows.

SERVICE MANUAL PC-FAX EXPANDER TYPE 250

TABLE OF CONTENTS

1. OVERALL INFORMATION	
1.1 SPECIFICATIONS	
1.2 FEATURES	
2. DETAILED DESCRIPTIONS	2
2.1 AT COMMANDS AND RESPONSES	
2.1.1 Class 0 commands	
2.1.2 Class 2 commands	
2.2 CLASS 2 FAX COMMUNICATION	4
2.2.1 Direct transmission	
2.2.2 Memory transmission	
2.2.3 Direct reception	
2.2.4 Memory reception	5
2.3 SCANNING AND PRINTING	
2.3.1 SCANNING	6
2.3.2 PRINTING	6
3. INSTALLATION	7
4. SERVICE TABLES AND PROCEDURES	
4.1 SERVICE MODE FUNCTIONS	
4.1.1 PC protocol dump list	
4.2 BIT SWITCHES	
4.3 USER PARAMETERS	9
5. PARTS LIST	

25 February 1998 SPECIFICATIONS

1. OVERALL INFORMATION

1.1 SPECIFICATIONS

Item	Description	
PC Fax Interface	EIA/TIA Class 2	
	(Class 1 is not supported)	
Host Interface Connector	EIA/TIA RS232C	
	DB25 female connector	
Scanner	TWAIN interface	
	Maximum resolution: 200 x 200 dpi	

1.2 FEATURES

- Class 2 fax transmission directly from a host PC (PC fax application required)
- □ Class 2 fax transmission through SAF memory (PC fax application required)
- Class 2 fax reception directly to a host PC (PC fax application required)
- Class 2 fax reception through SAF memory (PC fax application required)
- □ Local printing from a PC fax application (PC fax application required)
- □ Local scanning from the machine's scanner using TWAIN API (CFM Twain driver required)

2. **DETAILED DESCRIPTIONS**

2.1 AT COMMANDS AND RESPONSES

2.1.1 CLASS 0 COMMANDS

Command	Function	Remarks
ATA	Answer	
ATD	Dial	
ATE	Command echo	
ATH	Switch-hook control	
ATI	Identification	
ATL	Speaker volume	
ATM	Speaker control	
ATP	Set pulse dial as default	The machine returns OK,
ATQ	Result code display	but the function is not
ATS	S register	supported.
ATT	Set tone dial as default	
ATV	Result code form	
ATX	Extended result codes	The machine returns OK, but the function is not supported.
ATZ	Reset	
AT&C	DCD option	The machine returns OK,
AT&D	DTR option	but the function is not supported.
AT&F	Restore factory configuration	


2.1.2 CLASS 2 COMMANDS

Command	Function	Remarks
AT+FCLASS?	Service class	The machine responds "22".
AT+FMFR?	Identify manufacturer	The machine responds "RICOH(CF1)".
AT+FLID	Local ID string	
AT+FBOR	Phase C data bit order	
AT+FCR	Capability to receive	The machine returns OK, but the function is not supported.
AT+FDCC	DCE capability parameters	
AT+FDIS	Current session parameters	
AT+FDT	Data transmission	
AT+FET	Transmit page punctuation	
AT+FDR	Phase C receive data	
AT+FMDL?	Identify model	The machine responds "PC-FAX EXPANDER (CF1)".

Command	Function	Remarks
AT+FREV?	Identify revision	The machine responds with FCU ROM version and release date.
AT+FAA	Adaptive answer	The machine returns OK,
AT+FPHCTO	Phase C timeout	but the function is not
AT+FECM	ECM parameter	supported.
AT+FBUG	Session manager reporting parameter	
AT+FPTS	Page transfer status	
AT+FAXERR	Fax error value	The machine returns OK, but the function is not supported.
AT+FDCS	Current session results	
AT+FCQ	Copy quality capability parameter	The machine returns OK, but the function is not supported.
AT+FK	Session termination	
+FHNG	Call termination with status	
+FCON	Facsimile connection response	
+FCSI	Report the CSI	
+FTSI	Report the TSI	
+FCFR	Indicate CFR	

2.2 CLASS 2 FAX COMMUNICATION

2.2.1 DIRECT TRANSMISSION




A824D001.WMF

The host computer sends commands and image data to the machine through the DIU during transmission.

NOTE: 1) Group dials programmed in the machine cannot be used.

- 2) ISDN G4 numbers programmed in quick or speed dials cannot be used.
- 3) If ISDN is selected for G3 communication (system switch 0A, bit 6), the G3 numbers must have been programmed in quick or speed dial.
- 4) T.30 optional protocols (e.g., BFT) are not supported by class 2 fax communication.

2.2.2 MEMORY TRANSMISSION




A824D002.WMF

The host computer sends destination number(s) and image data to the machine through the DIU during transmission. The machine stores the image in the SAF memory, then makes a fax transmission.

NOTE: 1) If the memory overflows while storing the first page into SAF memory, the machine does not start the transmission.

- If the memory overflows while storing the second or subsequent page into SAF memory, the machine transmits all the successfully stored pages.
- 3) When fax numbers programmed in the machine's quick or speed dials are specified using the PC fax application, all the specified numbers must have been programmed in the fax machine.
- 4) T.30 optional protocols (e.g., BFT) are not supported by class 2 fax communication.

2.2.3 DIRECT RECEPTION




A824D003.WMF

The machine transfers received image data directly to the host PC without storing it into SAF memory.

NOTE: 1) If the host PC is not ready to receive a fax message, the machine receives the message into SAF memory.

- 2) Even if the SAF memory is full, the machine starts fax reception. However, the machine will not continue reception if the host computer is not ready to receive a message.
- 3) The "Number of rings to answer" parameter in the PC fax application must not exceed 4.

2.2.4 MEMORY RECEPTION



A824D004.WMF


The machine receives a fax message in the SAF memory, then transfers data to the host computer after the reception has finished. The machine prints the received message after transferring data to the host if user parameter 20 – bit 4 is set to "1: Print".

NOTE: 1) If an error occurs due to cable disconnection, the PC fax application must be restarted to receive the message.

- 2) Memory reception is not possible when forwarding is enabled.
- 3) Manual reception from the PC fax application is not supported.
- 4) The "Number of rings to answer" parameter in the PC fax application must not exceed 4.

2.3 SCANNING AND PRINTING

2.3.1 SCANNING




A824D005.WMF

The machine scans an original into page memory, then transfers the data to the host PC. The data is sent to the application through the CFM Twain driver.

NOTE: 1) The maximum resolution is 200 x 200 dpi.

2.3.2 PRINTING



A824D006.WMF

The machine receives print data into SAF memory as fax image data, then prints it after all the data has been transferred from the host PC.

The destination number "0000" informed from the host PC identifies a print job.

NOTE: 1) If SAF memory runs out while receiving print data, the machine prints up to the successfully received data.

- 2) The machine cannot receive print data while printing a message from the SAF memory. The data will be received after printing.
- 3) If a fax destination is specified together with the print destination "0000", the destinations specified after "0000" will be delayed until the machine prints all pages in the message.

3. INSTALLATION


THIS OPTION MUST BE INSTALLED BY A CUSTOMER SERVICE REPRESENTATIVE WHO HAS COMPLETED THE TRAINING COURSES ON THE BASE COPIER AND THIS OPTION.

NOTE: 1) Never install telephone wiring during a lightning storm.


- 2) Never install telephone jacks in wet locations unless the jack is specifically designed for wet locations.
- 3) Never touch uninsulated telephone wires or terminals unless the telephone line has been disconnected at the network interface.
- 4) Use caution when installing or modifying telephone lines.
- 5) Avoid using a telephone (other than a cordless type) during an electric storm. There may be a remote risk of electric shock from lightning.
- 6) Do not use an telephone to report a gas leak in the vicinity of the leak.

ACAUTION

Before installing this option, switch off the main and ac switches, and disconnect the power cord.



- 1. Remove the rear cover [A] (6 screws).
- 2. Remove the bracket [B] (2 screws), or the fax unit [C] if it has been installed in the machine (13 screws, 2 brackets, 2 connectors).



- 3. Remove the cover [D] from the left side cover.
- 4. Remove the ISDN G4 interface from the fax unit if it is present (2 screws, 1 connector).
- 5. Remove two hexagonal screws [E] from the DIU.
- 6. Install the DIU (RS232C interface) [F] in the fax unit (4 screws, 2 of them are the hexagonal screws removed in the previous step).
- 7. Connect the harness [G] from the DIU to CN506 on the FCU as shown, and put back the ISDN G4 interface if it was removed in step 4.
- 8. Install the fax unit [C] (13 screws, 2 brackets, 2 connectors), and the rear cover [A] (6 screws).
- 9. Turn on the machine and print the system parameter list. If "TR29" appears in the "Option" section of the system parameter list, go on to step10. Otherwise, check the ROM version or the cable connections.

FCU ROM Versions which support this option

- A1945582H or later
- A1945585E or later
- A1945587B or later
- A2255582C or later
- A2255585C or later
- A2255587B or later
- 10. Follow the Operator's Manual for how to connect the machine to a host computer, how to set up the machine and the computer, if required.
 - **NOTE:** 1) A "straight-through" shielded serial cable is required, but it is not enclosed in this option.
 - 2) One end of the serial cable must have a DB25 male type connector to be connected to the DIU.

4. SERVICE TABLES AND PROCEDURES

4.1 SERVICE MODE FUNCTIONS

4.1.1 PC PROTOCOL DUMP LIST

Use this function to check the AT commands and responses that are exchanged between a host computer and the machine.

Refer to section 2.1 for details of the supported AT commands.

- 1. Enter service mode, and select 05 "Protocol Dump".
- 2. Select 3 "PC Protocol List", then press Start.

4.2 BIT SWICTHES

Syst	System Switch 1C					
No	FUNCTION	COMMENTS				
0	PC-DIU communication record on the Journal 0: Disabled 1: Enabled	1: Communications between the DIU and a host PC are logged on the Journal. Also, the Data-in LED turns on while data is coming in and going out to the PC. Be sure to reset this bit to "0" after a test.				
1 to 7	Not used	Do not change the settings.				

4.3 USER PARAMETERS

Usei	User Switch 20						
No	FUNCTION	COMMENTS					
0	Class 2 transmission 0: Direct tx 1: Memory tx	O: Image data is sent directly from a host during communication. 1: Image data is sent to the fax machine's SAF					
	1. Memory ix	memory before starting a fax communication, then it is sent by the fax machine.					
1	Addition of fax TTI in class 2 memory transmission 0: Disabled 1: Enabled	1: The machine adds its TTI to all the messages sent through SAF memory. This setting is effective only when bit 0 is set to "1".					
2	Message received to: 0: Fax 1: PC	0: Received messages are printed at the machine.1: Received messages are transferred to the host PC.					

Usei	User Switch 20						
No	FUNCTION	COMMENTS					
3	Class 2 reception 0: Direct rx 1: Memory rx	O: Received messages are transferred to the host PC directly during fax communication. 1: Received messages are stored in the SAF memory during reception. Then they are transferred to the host PC after reception has been completed.					
4	Message printout in class 2 memory rx 0: Disabled 1: Enabled	1: A message received into memory is printed after it has been transferred to the host PC.					
5	Checkered mark on printouts from a PC 0: Disabled 1: Enabled	1: The machine prints a checkered mark on a document printed through the DIU.					
6 to 7	Not used	Do not change the settings.					

Usei	User Switch 21				
No	FUNCTION	COMMENTS			
0	Scan density for the "Light" sett	ing in scanner mode.			
to	$ (1) \qquad (0) \qquad (1) $				
3	$\begin{bmatrix} 0 \\ 0 \\ 0 \\ 0 \end{bmatrix} = Level \begin{bmatrix} 1 \\ 0 \\ 0 \end{bmatrix} = Level \begin{bmatrix} 2 \\ 0 \\ 0 \end{bmatrix} = \begin{bmatrix} 1 \\ 0 \\ 0 $	= Level 3			
4	Scan density for the "Dark" setti	ing in scanner mode.			
to 7	$\begin{bmatrix} 1 \\ 0 \\ 1 \\ 0 \end{bmatrix} = Level 5 \begin{bmatrix} 0 \\ 1 \\ 1 \\ 0 \end{bmatrix} = Level 6 \begin{bmatrix} 1 \\ 1 \\ 1 \\ 0 \end{bmatrix} = \begin{bmatrix} 1 \\ 1 \\ 0 \end{bmatrix} = $	= Level7			

5. PARTS LIST

Index	Part Number	Name	Q'ty/Unit
1	A2255172	PCB - DIU	1
2	A2255290	Harness – DIU-FCU	1
3	04513006B	Screw – M3 x 6	3

Technical Bulletin


PAGE: 1/2

Model: AD1 (New DF65 Option) Date			te: 15-Mar-98		No: 50	
Subject: New Model for AD1E			Prepared by: K.Ugaeri		gaeri	
From: QAC Field Information Dept.						
Classification:	☐ Troubleshooting	☐ Part inf	ormat	tion	Action	n required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	ıit/rec	eive	☐ Retrof	fit information
	⊠ Other ()					

We hereby inform you that a new ARDF has been launched with a new trailing edge sensor to speed up ARDF scanning for the AD1E (25 cpm). New product codes are as follows.

Product Code	Model Name	Current Product Code
A661-50	DF65 for Gestetner	A661-10
A661-30	DF65 for Savin	A661-15
A661-57	DF65 for Ricoh	A661-17
A661-66	DF65 for Danka	A661-26
A661-60	DF65 for Lanier	A661-55

New product can be installed on the AD1 and the AD1E. When installed on the AD1E, please change the dip switch on the ARDF control board from Normal to Ex position as shown the instruction manual. The different parts list between new product and old one is attached (Scanning speed with AD1E: 20cpm by 1 to 1 copy).



The old product can also be used with the AD1 and AD1E (its scanning speed for both models is 15 cpm for 1 to 1 copying).


Model: AD1 (New DF65 Option) Date: 15-Mar-98 No:50

Different parts between old and new DF65

	New Part Number	Description	Index No
1.	A6612211	Side Fence	5-16
2.	A6615760	Relay Harness - Original Tray	5-22
3.	A6615765	Relay Harness - Trailing Edge Sensor	5-48 (new)
4.	A6612165C	Original Table Bracket	5-29
5.	A6612232	Bracket - Trailing Edge Sensor	5-49 (new)
6.	A6612141D	Front Original Table	5-47
7.	A6615510	ARDF Control Board 2	13-21
8.	AW010066	Photosensor-PS-R50D1-B	5-23 (new)

Note

Items 1, 2, 4, 6, & 7 can be used for the old DF65. Refer to MB no.2 for the DF65. To standardize the service spare parts, you can use new parts for old DF65 units in the field.



Technical Bulletin

PAGE: 1/2

Model: AD1			Date	ate: 15-Jun-98		No: 51
Subject: China version information				Prepared by: S.Tomoe		omoe
From: QAC Field Information Dept.						
Classification: Troubleshooting		☐ Part information ☐ Ac		Action	required	
	☐ Mechanical	Electric	al		Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive \square	Retrof	fit information
	⊠ Other ()					

The China version was launched in February 1998. This RTB clarifies the differences between the Asia version (A193-27) and this version.

1. Model Name and Machine Code

Version	Machine code	Model Name		
China version	A193-69	Aficio 200		

2. Technical information

All specifications for the China version are exactly the same as for the Asia version.

3. Parts Information

The following are unique part numbers for the China version.

- A193 -

Part Number	Description	Index No.	Page
A1935094	BICU Board (CHN)	3	45
A1935715	Power Supply Cord (CHN)	16	47
A1937365	Decal – Main (CHN)	6	63
A1937366	Decal – AC Switch (CHN)	8	63
A2041297 (new)	Sheet – Service Tel.	23	7
A1938606	Operating Instructions – Copy (CHN)	10	63
A6848606	Operating Instructions – Main (CHN)	11	63


- Printer -

Part Number	Description	Index No.	Page
A1937367	Decal – Copy/Printer	8	25



PAGE: 2/2

Model: AD1 Date: 15-Jun-98 No: 51



Technical Bulletin

PAGE: 1/1

MB Correction

Reissue date: 15-Sep-98

The items in bold italics have been corrected or added.

Model: AD1 & AD1E Da			Date	e: 31-Jul-98	No: 52A
Subject: Light Copies			Prepared by: K.Ugaeri		
From: QAC Field	Information Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part info	al	 □ Servi	n required ce manual revision ofit information

Symptom

After making a few hundred copies, the image density becomes lighter and lighter

Cause

If the monthly copy volume is higher than 3K, the machine with new firmware from ver1.70 for AD1 and ver1.30 for AD1E may have this problem because of the lack of the toner supply.

Action required

- A. If the customer has this problem and their copy volume is higher than 3K, change the following SP modes to ensure that the toner density is enough.
- 1. To ensure sufficient density:
- (1) Change SP2-999 to 1 for the manual mode and input 100 into SP2-996.
- (2) Make few copies until the density is sufficient.
- (3) Change back SP2-999 to 0 for the factory setting mode.
 - *Caution: Do not keep it in the manual mode. Otherwise too much toner will be added.
- 2. To maintain a sufficient image density:
 - (1) Set SP2-201 for development bias adjustment to -700V.
 - (2) Set SP2-994 for offset value of the Vcont setting to 0.
 - (3) Set SP2-911 for the image density selection to 1 (Dark).
- B. If the customer has this problem and their copy volume is less than 3K, change the following SP mode.
- 1. To ensure sufficient density:
- (1) Change SP2-999 to 1 for the manual mode and input 100 into SP2-996.
- (2) Make a few copies until the density is sufficient.
- (3) Change back SP2-999 to 0 for the factory setting mode.
 - *Caution: Do not keep it in the manual mode. Otherwise too much toner will be added.
- 2. To maintain a sufficient image density:
- (1) Set SP2-201 for the development bias adjustment to -700V.
- (2) Set SP2-911 for the image density selection to 1 (Dark).

If the density is still light even after the above action, please contact a Ricoh sales branch.

Technical Bulletin

PAGE: 1/5

RTB Correction

Reissue date: 31-Jul-98

The items in bold Italics have been corrected or added.

Model: AD1			Date	e: 15-Jan-97	No: 15G
Subject: ROM History (AD1 Copy Version)				Prepared by: K.U	Igaeri
From: QAC Field Information Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part info ☐ Electric ☐ Transm	al	☐ Servi	n required ce manual revision fit information

AD1 firmware history USA

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
E	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
М	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97
Р	13	1.60	3042	A726	891C	August Prod.'97
R	14	1.62	5B56	CF0D	8C49	September Prod.'97
Т	16	1.70	8D31	65E0	2751	October Prod.'97
V	17	1.72	2708	2870	FE98	February Prod.'98

Europe/Asia

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
E	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97
L	111A	1.48	7218	5558	1CC0	May Prod.'97
М	112	1.54	AAA8	7837	3271	June Prod.'97
N	113	1.60	1FE3	AEE1	7102	August Prod.'97
Р	114	1.62	794C	90BE	E88E	September Prod.'97
R	116	1.70	2208	D8BC	494C	October Prod.'97
S	117	1.72	76BE	909E	E620	February Prod. '98

^{*}The versions 1.35 and 1.3 are not released as files.



Model: AD1

Technical Bulletin

Date: 15-Jan-97

No: 15G

PAGE: 2/5

European 2nd Language

A6485570	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
Е	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F
J	209	1.60EU2	AE02	2277	8B8B
K	210	1.62EU2	CB8A	0ACC	C0BE
M	212	1.70EU2	4159	50F0	F069
N	213	1.72EU2	8982	08DC	80A6

European 3rd Language

A6485573	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	301	1.57EU3	9DBB	C908	D4B3
Α	302	1.60EU3	390A	FD07	3C03
В	303	1.62EU3	C69E	D5E3	F0BB
D	305	1.70EU3	006B	8E5E	720D
E	306	1.72EU3	BA31	2700	9331

European 4th Language

A6485574	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390
Α	402	1.60EU4	4490	FDEF	46A1
В	403	1.62EU4	A30C	D9E5	C927
D	405	1.70EU4	3973	9405	A56E
E	406	1.72EU4	78ED	301F	48CE

China

A6485572	File No.		Total		
	(A193CHxx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	04	1.62CH	B020	B056	FFCA
Н	07	1.70CH	1893	3AEA	DDA9
J	08	1.72CH	690B	C1A7	A764

Taiwan

	File No.		Total		
A1935534	(A193TWxx)	Version	C.SUM	SUM(OH)	SUM(OL)
В	03	1.62TW	C05F	3BA0	94BF
Е	06	1.70TW	470D	87F1	BF1C
F	07	1.72TW	A7C2	0C5B	9B67

PAGE: 3/5

Model: AD1 Date: 15-Jan-97 No: 15G

Symptom Corrected	L	JSA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
The tables for Vt correction & mixing time are changed.		V	S	N	E	E	J	F
Pre.Vt-Latest Vt Mixing Time Remaining Vt Correction	on							
~ 0.1 10 Mixing time								
~ 0.2 ~ 0.3 50								
~ 0.5 300 400 0.4								
0.5 ~ 500 450 0.6 0.8								
		Т	R	M	D	D	Н	E
Dirty background problem (Refer to RTB42) -Vt correction		1	н	IVI	ט ן	ט	н	
-Mixing time								
New SP mode		Т	R	М	D	D	Н	E
•SP2-994: Vcont offset		'	• • • • • • • • • • • • • • • • • • • •	101			''	_
•SP9-999-14: Additional mixing time display								
For the USA only								
New SP mode		R						
SP5-950: LG size paper detection on the by pass tray.								
* When this function is selected and LT size is put								
in the by-pass tray, the machine detects it as LG								
size paper.								
For the USA only		R						
To meet the Energy Star standard.								
After a fax transmission through ARDF with a stammer, the		R	Р	K	В	В	Е	В
registration of the 1st copied paper by ARDF is delayed.								
New SP mode.		Р	N	J	Α	Α	D	Α
SP5-949:1= When one of the trays is empty, the paper end								
indicator (red LED) lights.		_			_			
The DF Jam display is cleared by lifting the DF up and down		Р	N	J	Α	Α	D	Α
New SP Mode		N	М	G				
SP6-006-4: ARDF Main-Scan Registration for the rear side.		N.I	N 4	G				
Specification		N	М	G				
When the trays do not have paper of the same size in different	nı							
orientations, the machine continues to print using the sort function even if Rotate Sort is selected. (The previous softwa	ro							
version stops the copy job when one of the trays is empty)	16							
The stapler may not work when the printer feeds out a staple	Ч	N	М	G				
copy while feeding out the paper into the finisher in copy or fa		.,	•••					
mode.								
When two sheets of paper remain in the Duplex Unit and the		N	М	G				
printer prints in duplex mode, the printout will be made on the								
rear side of the paper remaining in the duplex unit.								
SP5-808: The three languages cannot be selected using the	_	_	М	G				
previous software version N								

Technical Bulletin

PAGE: 4/5

Model: AD1 Date: 15-Jan-97 No: 15G

If a divides again in made with the ADE Divides Unit and 10M	N.4				
If a duplex copy is made with the ADF, Duplex Unit and 12M	М	L	F		
Memory and the original is jammed, the jammed original cannot					
be copied correctly during recovery.					
Paper jam when paper is fed from the 3rd tray immediately after	M	L	F		
feeding the paper from the 4th tray.(A jam or Y jam) with the					
following paper types.					
* 3rd Tray has paper of length less than 288mm (A4 🔲)					
4th Tray has paper of length 289mm to 401mm (A4 🔲)					
When the RAM was cleared with SP5-801, the white level and	L	K	Е		
the standard white plate density set at the factory were erased.			_		
Toner scattering around black areas of the image on the rear	K	J			
side of duplex copies. The default of the separation output					
voltage was changed.					
SP2-901-1→ -1800					
SP2-901-2→ -1800					
SP2-901-3→- 2500					
SP2-901-4→- 2500					
012 001 1 7 2000					
A blank sheet is printed out when the start key is pressed if the	J	Н			
memory is full. The scanning restarts after printing the scanned					
image and then the first original jams.					
Dirty Background.	Н	G			
1) Toner Density (SP2-911) was changed from 2 to 3 (Lighter).	٠.				
2) Free run time at PCU installation was changed					
from 1 min. to 3 min.					
	G	F			
Black Spots in the scanned image - A scanned low contrast	G				
image can be adjusted using 7 settings. Each setting has					
different gamma correction characteristics, MTF filter and					
threshold level (new SP mode: SP4-998,999)		_			
Dirty background on white images after negative\positive	G	F			
reversal.					
SC321 appears when the door is opened during memory	G	F			
copying if the start key is pressed after closing the door.					
The development bias setting (SP2-201) is initialized when the	G	F			
main switch is turned off.					
SC921-Memory Access Error	F	Е			
After a paper jam while opening the door during memory output.		_			
SC101 appears when turning the main switch off/on after the	F	Е			
IPU test pattern in SP mode.	'	_			
SP5-803: New PCU Detect is added to the input checks.	F	Е			
	F	E			
Memory copy priority of SP5-945 is added to Salesman Program Mode.	「				
SP mode cannot be cleared when the main switch is turned	F	Е			
	「				
off/on after going to the interrupt copy mode from SP mode.	F	Е			
The finisher is supported	-				
While feeding out an original from the ADF, the Start key can be	E	D			
pressed. Then the incorrect document size is detected.					
The ARDF is supported.	E	D			

PAGE: 5/5

Model: AD1 Date: 15-Jan-97 No: 15G

A1935532	A193-10	A193-15	A193-17	A193-55
E	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	_	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	_	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	-	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	-	L5027042480~
М	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~
Р	A107080001~	6A77080001~	A7227080001~	L5027085441~
R	A107090001~	6A77090001~	A7227090001~	L5027096321~
Τ	A107100001~	6A77100001~	A7227100006~	L5027117581~
V	A108020001~	6A78020001~	A7228020001~	L5028019178~

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65	A193-69
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~	
Е	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~	
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~	
G	AH27020001~	3L00270001~	_	_	L5027011424~	
Н	AH27020951~	_	A7227021026~	A7227021345~	L5027021685~	
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~	
K	TBA	3L00470001~	TBA	TBA	TBA	
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~	
М	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~	
N	AH27080001~	3L00870001~	A7227080969~	A7227081769~	L5027085755~	
Р	AH27090001~	3L00970001~	A7227090881~	A7227092701~	L5027096431~	A7227092891~
R	AH27100463~	3L01070007~	A722710771~	A7227102371~	L5027118101~	A727102531~
S	AH28020001~	3L00280001~	A72280011266~	A7228011756~	L5028019336~	A7228043126~

F	A7228042025~
В	A7227090821~
A1935534	A193-19

Technical Bulletin

PAGE: 1/4

MB Correction

Reissue date: 31-Jul-98

The items in bold italics have been corrected or added.

Model: AD1-E			Date: 15-Oct-97		No: 40C
Subject: ROM History (AD1-E Copy Version)			Prepared by: K		Jgaeri
From: QAC Field Information Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part inf☐ Electric☐ Transm	al	☐ Servi	n required ce manual revision ofit information

AD1-E (Copy) firmware history.

USA

A2245532	File No. (A224uxx)	Version	Total C.SUM	SUM(OH)	SUM(<i>OL</i>)	Production
D	01	1.18	7766	6521	1245	1st Mass Prod.
Е	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97
K	06	1.30	432E	144E	2EE0	October Prod. '97
L	07	1.32	DECC	12FA	CBC2	November Prod.'97
М	08	1.33	A5B9	A28F	032A	February Prod.'98

Europe/Asia

Н	107	1.33EU1	3D82	8357	BA2B	February Prod.'98
G	106	1.32EU1	AD8D	EF92	BDFB	November Prod.'97
F	105	1.30EU1	6F80	F07D	7F03	October Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97
С	102	1.24EU1	F12D	8333	6DFA	August Prod. '97
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
A2245533	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production



PAGE: 2/4

Model: AD1-E Date: 15-Oct-97 No: 40C

European 2nd Language

A8105570	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU2	F29A	D4BF	1DDB
D	205	1.30EU2	76E6	6ED6	0810
E	206	1.32EU2	6349	6E3B	F50E
F	207	1.33EU2	EE69	0204	EC65

European 3rd Language

A8105573	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	302	1.24EU3	2C91	F73A	3557
В	303	1.26EU3	649F	D770	8D2F
D	305	1.30EU3	6B26	4D86	1DA0
E	306	1.32EU3	EE17	646C	89AB
F	307	1.33EU3	FE7F	D5DD	28A2

European 4th Language

A8105574	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
А	402	1.24EU4	7A6A	F8BC	81AE
В	403	1.26EU4	E7F9	DA9F	0D5A
D	405	1.30EU4	A7C1	4EF5	58CC
E	406	1.32EU4	DFE0	4E0F	91D1
F	407	1.33EU4	8EEA	DAFC	B3EE

China

A8105512(OL) A8105513(OH)	File No. (A224CHxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	_	_	_	_	_

Taiwan Version

A2245534	File No. (A224TWxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
_	_	_	-	_	_



No: 40C

PAGE: 3/4

Model: AD1-E Date: 15-Oct-97

Symptom Corrected	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
The tables for Vt correction & mixing time have been changed.	М	Н	F	F	F	_	_
Pre.Vt-Latest Vt Mixing Time ~ 0.1 10 ~ 0.2 30 ~ 0.3 50 ~ 0.5 300 0.5 ~ 500 450 0.6 500 0.8							
AD1E Only After initializing the developer, the transfer current is supplied until making a copy, turning the main switch off and on, or opening the front cover.	L	G	Ε	Ε	Ε	-	-
Dirty background problem (Refer to RTB42) -Vt correction -Mixing time	K	ш	D	D	D	_	_
New SP mode •SP2-994: Vcont offset •SP9-999-14: Additional mixing time display	K	Ш	D	D	D	_	_
For the USA only New SP mode SP5-950: LG size paper detection on the by pass tray. * When this function is selected and LT = size is put in the by-pass tray, the machine detects it as LG = size paper.	H		_	_	_	_	
For the USA only To meet the Energy Star standard.	Н	-	_	-	_	-	-
After a fax transmission through ARDF with a stamper, the registration of the 1st copied paper by ARDF is delayed.	Н	D	В	В	В	_	_
New SP mode. SP5-949:1= When one of the trays is empty, the paper end indicator (red LED) lights.	F	С	Α	A	A	_	_
The DF Jam display is cleared by lifting the DF up and down New SP Mode SP6-006-4: ARDF Main-Scan Registration for the rear side.	E	С	Α	Α	A		_
Specification When the trays do not have paper of the same size in different orientations, the machine continues to print using the sort function even if Rotate Sort is selected. (The previous software version stops the copy job when one of the trays is empty)	Ш						
The stapler may not work when the printer feeds out a stapled copy while feeding out the paper into the finisher in copy or fax mode.	E						
When two sheets of paper remain in the Duplex Unit and the printer prints in duplex mode, the printout will be made on the rear side of the paper remaining in the duplex unit.	E						

PAGE: 4/4

Model: AD1-E Date: 15-Oct-97 No: 40C

A2245532	A224-10	A224-15	A224-17	A22455
E	AK87070001~	9A37060001~	A7427060001~	L027080001~
F	AK87080023~	9A37080001~	A7427080001~	_
Н	AK87090001~	9A37090001~	A7427090001~	L027090031~
K	AK87100001~	9A37100001~	A7427100021~	L027111066~
L	AK87120001~	9A37120001~	A7427120001~	L027121721~
М	AK88020001~	9A38020001~	A7428020001~	L0248022670~

A2245533	A224-22	A224-26	A224-27	A224-29	A224-65
С	AK97070543~	3P30870001~	A7427080601~	A7427081501~	_
D	AK97090001~	3P30970001~	A7427090305~	A7427091035~	L0247090216~
F	AK97100001~	3P31070001~	A7427100176~	A7427101246~	_
G	AK97110001~	3P31170001~	A7427110081~	A7427110881~	L0247111341~
Н	AK98020001~	3P30280001~	A7428030351~	A7428020101~	L0248023356~

Technical Bulletin

PAGE: 1/5

RTB Correction

Reissue date: 31-Aug-98

The items in bold Italics have been corrected or added.

Model: AD1		e: 15-Jan-97	No: 15H		
Subject: ROM Hi	story (AD1 Copy Version)	Prepared by: K.Ugaeri			
From: QAC Field					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part info ☐ Electric ☐ Transm	al	☐ Ser	on required vice manual revision rofit information

AD1 firmware history USA

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
E	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
М	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97
Р	13	1.60	3042	A726	891C	August Prod.'97
R	14	1.62	5B56	CF0D	8C49	September Prod.'97
Т	16	1.70	8D31	65E0	2751	October Prod.'97
V	17	1.72	2708	2870	FE98	February Prod.'98
W	18	1.73	0BF0	1A1D	F1D3	September Prod.'98

Europe/Asia

	File No.		Total				
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production	
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.	
D	104	1.23	FC4B	98CE	637D	November Prod.'96	
Е	105	1.31	OADC	41C5	C917	December Prod.'96	
F	107	1.33	4C77	CFF3	7C84	January Prod.'97	
G		1.35				January Prod.'97	
Н		1.36				January Prod.'97	
J	110	1.38	ACCC	2927	8353	February Prod.'97	
K	111	1.43	F537	6510	9027	March Prod.'97	
L	111A	1.48	7218	5558	1CC0	May Prod.'97	
М	112	1.54	AAA8	7837	3271	June Prod.'97	
N	113	1.60	1FE3	AEE1	7102	August Prod.'97	
Р	114	1.62	794C	90BE	E88E	September Prod.'97	
R	116	1.70	2208	D8BC	494C	October Prod.'97	
S	117	1.72	76BE	909E	E620	February Prod. '98	
Τ	118	1.73	4C5F	714E	DB11	September Prod.'98	

^{*} Versions 1.35 and 1.3 are not released as files.



PAGE: 2/5

Model: AD1 Date: 15-Jan-97 No: 15H

European 2nd Language

A6485570	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F
J	209	1.60EU2	AE02	2277	8B8B
K	210	1.62EU2	CB8A	0ACC	C0BE
М	212	1.70EU2	4159	50F0	F069
N	213	1.72EU2	8982	08DC	80A6
Р	214	1.73EU3	9E75	EC59	B21C

European 3rd Language

A6485573	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	301	1.57EU3	9DBB	C908	D4B3
Α	302	1.60EU3	390A	FD07	3C03
В	303	1.62EU3	C69E	D5E3	F0BB
D	305	1.70EU3	006B	8E5E	720D
Ē	306	1.72EU3	BA31	2700	9331
F	307	1.73EU3	3774	27A0	0FD4

European 4th Language

A6485574	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390
Α	402	1.60EU4	4490	FDEF	46A1
В	403	1.62EU4	A30C	D9E5	C927
D	405	1.70EU4	3973	9405	A56E
E	406	1.72EU4	78ED	301F	48CE
F	407	1.73EU4	1D07	11EC	0BEB

China

A6485572	File No.		Total		
	(A193CHxx)	Version	C.SUM	SUM(OH)	SUM(OL)
E	04	1.62CH	B020	B056	FFCA
Н	07	1.70CH	1893	3AEA	DDA9
J	08	1.72CH	690B	C1A7	A764
K	09	1.73CH	D423	A74A	2CD9

Taiwan

A1935534	File No. (A193TWxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
В	03	1.62TW	C05F	3BA0	94BF
Е	06	1.70TW	470D	87F1	BF1C
F	07	1.72TW	A7C2	0C5B	9B67
G	08	1.73TW	59DD	FB05	5ED8

Model: AD1

Technical Bulletin

Date: 15-Jan-97 No: 15H

PAGE: 3/5

Symptom	Symptoms Corrected (New Items only – for old ones, see previous bulletins)							USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN			
Copy quali	-	-															
*When the																	
transfer cu	rren	t mu	st b	e de	creas	ed using S	SP2-3	301-3	3. W	ith							
the new tal	ble, i	it caı	n be	adju	ısted	to a lower	rang	je.									
Current Ta	able	(SP2	2-30 ⁻	1-3)	-	New Tabl	e (SI	22-30	01-3	<u> </u>							
Table No./	0	1	2	3		Table No./	Ò	1	2	3		_	_	_	_		_
Paper width 275•	15	17	19	21		Paper width 275•	8	11	14	17	W	Τ	P	F	F	K	G
250• 275	15	17	19	21		250• 275	10	12	15	17							
200• 250	15	17	19	21	\rightarrow	200• 250	12	14	16	17							
• 200	15	17	19	21		• 200	14	15	16	17							
		Λ.			ı					^							
	г) Defau	ılt						Do	个 fault							
SC544 is s				onlo	vod u	than tha m	oobii	no ol			W	T	P	F	F	Κ	G
	SC544 is sometimes displayed when the machine shifts to						"	,	^	_	'		G				
	night mode or pre-heat mode.																
	When paper longer than A4 is fed in a toner near end							W	T	P	F	F	K	G			
condition,	not (enou	ıgh t	one	r is sı	upplied.											



PAGE: 4/5

Model: AD1 Date: 15-Jan-97 No: 15H

A1935532	A193-10	A193-15	A193-17	A193-55
E	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	-	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	-	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	-	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	-	L5027042480~
M	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~
Р	A107080001~	6A77080001~	A7227080001~	L5027085441~
R	A107090001~	6A77090001~	A7227090001~	L5027096321~
Т	A107100001~	6A77100001~	A7227100006~	L5027117581~
V	A108020001~	6A78020001~	A7228020001~	L5028019178~
W	TBA	TBA	TBA	TBA

PAGE: 5/5

Model: AD1 Date: 15-Jan-97 No: 15H

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~
E	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~
G	AH27020001~	3L00270001~	-	-	L5027011424~
Н	AH27020951~	-	A7227021026~	A7227021345~	L5027021685~
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~
K	TBA	3L00470001~	TBA	TBA	TBA
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~
M	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~
N	AH27080001~	3L00870001~	A7227080969~	A7227081769~	L5027085755~
Р	AH27090001~	3L00970001~	A7227090881~	A7227092701~	L5027096431~
R	AH27100463~	3L01070007~	A722710771~	A7227102371~	L5027118101~
S	AH28020001~	3L00280001~	A72280011266~	A7228011756~	L5028019336~
T	TBA	TBA	TBA	TBA	TBA

A6485572	A193-69
E	A7227092891~
Н	A7227102531~
J	A7228043126~
K	TBA

A1935534	A193-19
В	A7227090821~
F	A7228042025~
G	TBA

Technical Bulletin

PAGE: 1/4

MB Correction

Reissue date: 31-Aug-98

The items in bold italics have been corrected or added.

Model: AD1-E			Date	e: 15-Oct-97	No: 40D
Subject: ROM History (AD1-E Copy Version)				Prepared by: K.L	Jgaeri
From: QAC Field					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part info	al	☐ Servi	n required ce manual revision fit information

AD1-E (Copy) firmware history.

USA

A2245532	File No.	Version	Total	SUM(OH)	SUM(OL)	Production
	(A224uxx)		C.SUM	, ,	,	
D	01	1.18	7766	6521	1245	1st Mass Prod.
Е	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97
K	06	1.30	432E	144E	2EE0	October Prod. '97
L	07	1.32	DECC	12FA	CBC2	November Prod.'97
M	08	1.33	A5B9	A28F	032A	February Prod.'98
N	09	1.34	67BC	73E2	F3DA	September Prod.'98

Europe/Asia

A2245533	File No.	Version	Total	SUM(OH)	SUM(OL)	Production
	(A224exx)		C.SUM			
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
С	102	1.24EU1	F12D	8333	6DFA	August Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97
F	105	1.30EU1	6F80	F07D	7F03	October Prod. '97
G	106	1.32EU1	AD8D	EF92	BDFB	November Prod.'97
Н	107	1.33EU1	3D82	8357	BA2B	February Prod.'98
J	108	1.34EU1	C46A	790E	4B5C	September Prod.'98

European 2nd Language

A8105570	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU2	F29A	D4BF	1DDB
D	205	1.30EU2	76E6	6ED6	0810
Е	206	1.32EU2	6349	6E3B	F50E
F	207	1.33EU2	EE69	0204	EC65
G	208	1.34EU2	153D	F11B	2422



PAGE: 2/4

Model: AD1-E Date: 15-Oct-97 No: 40D

European 3rd Language

A8105573	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	302	1.24EU3	2C91	F73A	3557
В	303	1.26EU3	649F	D770	8D2F
D	305	1.30EU3	6B26	4D86	1DA0
Е	306	1.32EU3	EE17	646C	89AB
F	307	1.33EU3	FE7F	D5DD	28A2
G	308	1.34EU3	3DF8	C1D0	7C28

European 4th Language

A8105574	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
	\ - /				
Α	402	1.24EU4	7A6A	F8BC	81AE
В	403	1.26EU4	E7F9	DA9F	0D5A
D	405	1.30EU4	A7C1	4EF5	58CC
Е	406	1.32EU4	DFE0	4E0F	91D1
F	407	1.33EU4	8EEA	DAFC	B3EE
G	408	1.34EU4	6B87	C26F	A918

China

A8105512(OL) A8105513(OH)	File No. (A224CHxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
-	-	-	-	-	-

Taiwan

A2245534	File No. (A224TW xx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
-	-	-	-	-	-



Model: AD1-E

Technical Bulletin

Date: 15-Oct-97 No: 40D

PAGE: 3/4

Symptoms	Symptoms Corrected (New items only – for previous items,				USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN						
			see	old :	ler k	oulletins)						Asia					
Copy qualit	ty in	dup	lex ı	mod	e	•											
*When the	qual	lity c	of the	e rea	ar si	ide copy is	poc	r, th	e ad	ded							
transfer cui																	
the new tab						_			_								
Currernt Ta	able	(SP2	2-301	l-3)		New Table	e (SF	<u> 2-30</u>	1-3)								
Table No./ Paper width	0	1	2	3		Table No./ Paper width	Ó	1	2	3	N	J	G	G	G	_	_
275•	14	16	18	20	Ī	275•	8	11	14	16							
250• 275	16	18	20	22	\rightarrow	250• 275	10	13	16	18							
200• 250	18	20	22	24]	200• 250	12	15	18	20							
• 200	19	21	23	25		• 200	14	17	19	21							
		Λ.								1							
	D	eˈfau	lt						D	efault							
SC544 is so	SC544 is sometimes displayed when the machine shifts to				N	J	G	G	G	_	_						
	night mode or pre-heat mode.																
When pape	When paper longer than A4 is fed in a toner near end				N	J	G	G	G	_	_						
condition, r	ondition, not enough toner is supplied.																



PAGE: 4/4

Model: AD1-E Date: 15-Oct-97 No: 40D

A2245532	A224-10	A224-15	A224-17	A22455
E	AK87070001~	9A37060001~	A7427060001~	L027080001~
F	AK87080023~	9A37080001~	A7427080001~	_
Н	AK87090001~	9A37090001~	A7427090001~	L027090031~
K	AK87100001~	9A37100001~	A7427100021~	L027111066~
L	AK87120001~	9A37120001~	A7427120001~	L027121721~
М	AK88020001~	9A38020001~	A7428020001~	L0248022670~
N	TBA	TBA	TBA	TBA

A2245533	A224-22	A224-26	A224-27	A224-29	A224-65
С	AK97070543~	3P30870001~	A7427080601~	A7427081501~	_
D	AK97090001~	3P30970001~	A7427090305~	A7427091035~	L0247090216~
F	AK97100001~	3P31070001~	A7427100176~	A7427101246~	_
G	AK97110001~	3P31170001~	A7427110081~	A7427110881~	L0247111341~
Н	AK98020001~	3P30280001~	A7428030351~	A7428020101~	L0248023356~
J	TBA	TBA	TBA	TBA	TBA

RIGOH

Technical Bulletin

PAGE: 1/4

Model: AD1			Date	e: 31-Aug-98	No: 53
Subject: Factory change information				Prepared by: S.	Готое
From: QAC Field Information Dept.					
Classification: Troubleshooting Mechanical Paper path		☐ Part inf ☐ Electric ☐ Transm	al	☐ Serv	n required ice manual revision ofit information
	⊠ Other ()				

The factory for the 115 V version of the AD1 will be changed from Japan to Korea from September production. This RTB informs the new AD1 which will be made in Korea.

Machine Code and Model Name

Brand	Ricoh	Gestetner	Savin
Machine Code	A264-17	A264-10	A264-15
Model Name	Aficio 200	3220	9920DP

1. Parts Information

1.1 The following parts will be made in Korea. These parts will be orderable using the same part number as for the A193 machine.

No.	Description	Index	Page
1	Release Spring	14	19
2	Paper Guide	8	15
3	Lower Rear Cover	6	9
4	Scanner Left Cover	3	7
5	Upper Rear Cover	10	7
6	Scanner Right Cover	11	7
7	Lower Cover - Operation Panel	1	7
8	Middle Left Cover	4	9
9	Rear Right Cover	12	9
10	Lower Right Cover	14	9
11	Front Cover	18	7
12	Lower Exit Cover	21	9
13	Left Exit Cover	15	49
14	Right Exit Cover	26	49
15	Left Front Cover	17	7
16	Right Front Cover	16	7
17	Cap – G4	7	9



PAGE: 2/4

Model: AD1 Date: 31-Aug-98 No: 53

No.	Description	Index	Page
18	Cap - Sorter	22	9
19	Cap - NCU	8	9
20	Cap - CSS	10	9
21	Cap - Memory	9	9
22	Cap – IC Card	2	9
23	Cap – RS232C	1	9
24	Cap – Paper Tray Unit	11	9
25	Left Original Scale	4	7
26	Rear Original Scale	6	7
27	Upper Harness Guide	4	25
28	Paper Size Detector (LT)	7	17
29	Fusing Unit (115V)	*	33
30	Fusing Unit Frame	24	33
31	BICU Board (115V)	3	45
32	IOC Board	6	45
33	MSU – 4MB	4	45
34	Mother Board	27	45
35	Relay Harness – Scanner Unit	14	45
36	Relay Harness – Polygon Mirror Motor	5	27
37	DC Harness – Mother Board	22	45
38	Harness – Power Supply Board	19	45
39	Harness – Operation Switch	13	49
40	Harness – Fusing Lamp	20	45
41	Harness – Key Counter	18	45
42	Harness – Mother Board	23	45
43	LD Unit Harness	1	27
44	DC Power Supply Board	10	45
45	Left Relay Guide	8	51
46	Right Shielding Plate	2	21
47	Right Duct	2	35
48	Inner Cover – Paper Feed Tray	18	9
49	Cap – Inverter Unit	20	9
50	Front Side Fence	5	17
51	Rear Side Fence	6	17



PAGE: 3/4

Model: AD1 Date: 31-Aug-98 No: 53

No.	Description	Index	Page
52	Guide Plate – Vertical Transport	16	21
53	Release Lever – Bottom Plate	9	17
54	Release Arm – Paper End Feeler	24	21
55	Paper Tray Cover	1	17
56	Front Stopper Lever	16	17
57	Support - Paper Tray - Right	15	9
58	Support - Paper Tray - Left	19	9
59	Spring – 2.4N	34	43
60	Cover – By-pass Table	2	15
61	Right Side Fence – By-pass Feed Table	5	15
62	Left Side Fence – By-pass Feed	3	15
63	Bottom Plate – By-pass Table	7	15
64	Stay – By-pass Feed	19	19
65	Cover – Feed Roller Shaft	27	19
66	Upper Fusing Cover	5	33
67	Guide Plate – Feed Down	26	39
68	Shaft – Transport Roller	20	37
69	Left Cover Tray	2	39
70	Sub Copy Tray - FU	1	39
71	Exit Relay Roller	8	39
72	Exit Roller - FD	10	39
73	Right Vertical Guide	4	39
74	Inverter Unit Connector	13	47
75	By-pass Feed Sensor	9	15
76	Harness – Paper Size Detector	17	9
77	Harness – Paper End Sensor	21	21
78	Harness – Fan Motor	17	45
79	Harness – Humidity Sensor	16	49
80	Harness – Registration Sensor	28	19
81	Harness – Main Motor	4	41
82	Lower Left Cover	3	9
83	By-pass Feed Shaft	29	19
84	Upper Rear Guide – Paper Tray	4	21
85	Upper Front Guide – Paper Tray	3	21
86	Exposure Glass – A3T – 3.2	5	7
87	Lens Holder Ass'y	9	23



PAGE: 4/4

Model: AD1 Date: 31-Aug-98 No: 53

1.2 For the -15 machine

The -15 machine will be changed to an OEM generic version. So, the following part numbers will be changed.

A193-15 machine	A624-15 machine	Description	Index	Page
A1931453	A1931451	Operation Panel Ass'y	2	7
A1931498	A1931458	Key Top - Memory	13	13
A1931496	A1931461	Key Top – 10 Key	11	13
A1931491	A1931477	Key Top - Start	6	13
A1931492	A1931478	Key Top – Clear Mode	7	13
A1931493	A1931479	Key Top - Interrupt	8	13
A1931494	A1931480	Key Top – Program Mode	9	13
A1931495	A1931481	Key Top - Clear	10	13
A1931497	A1931483	Key Top - LCD	12	13
A1931499	A1931485	Key Top - Internal	14	13
A1931449	A1931486	Key Top - Behind	15	13
A1937224	A1937226	Front Door	14	7

The following part will not be used.

A193-15 machine	A624-15 machine	Description	Index	Page
A1337112		Emblem (SVN)	15	7

വ	ЭΠГ
)) <u> </u>

PAGE: 1/2

Model: AD1/AD1-E			Dat	te: 15-Nov-98	No.: 54
Subject: Copy Jam History Codes and P to P Diagram				Prepared by: S.T	omoe
From: GTSS Field Information Dept.					
Classification:	Troubleshooting	☐ Part info	rma†	tion Action	n required
1	☐ Mechanical	☐ Electrica	al	☐ Servi	ce manual revision
	☐ Paper path	☐ Transmit/red		eive Retro	fit information
·	Other (Service manual corr	rection)			

- 1. The jam codes in the copy jam history display, which are listed on page 4-38 should be corrected as follows.
 - 1. Jam code correction

Incorrect Jam Code	Correct Jam Code	Meaning
100	124	Duplex entrance sensor not activated.
124	100	Duplex turn sensor not activated.

2. The following new jam codes should be added.

Jam Code	Meaning
1	Jam detected just after power is switched on
60	Registration sensor not activated (from LCT)
61	LCT relay sensor not activated
160	Finisher entrance sensor not activated
161	Finisher entrance sensor remained activated by paper
162	Finisher exit sensor not activated
163	Finisher exit sensor remained activated by paper
164	Finisher jogger unit paper sensor not activated
165	Finisher jogger unit paper sensor remained activated by paper
166	Finisher inverter sensor not activated
167	Finisher inverter sensor remained activated by paper



PAGE: 2/2

Model: AD1/AD1-E Date: 15-Nov-98 No.: 54

2. Point to Point Diagram

CN157-8 and CN157-11 of the IOCSS board should be exchanged as follows. Also, correct the service manual, page 7-11.

Point to Point	Service Manual	Correct	Incorrect
Page 1/2 Location B-17	Page 7-11 Section 3.1	CN 157-8 Upper Exit Sensor	CN 157-11 Upper Exit Sensor
	Sensors	CN157-11 Lower Exit Sensor	CN157-8 Lower Exit Sensor

RIGOH

Technical Bulletin

PAGE: 1/6

Reissued: 29-Mar-00 RTB Correction

The items in bold Italics have been corrected or added.

Model: AD1			Date: 15-Jan-97		•	No: 15j
Subject: ROM Hi		Prepared by: K		by: K.U	gaeri	
From: Technical	Services Dept., GTS Division					
Classification:	☐ Troubleshooting	Part information		ion		required
	☐ Mechanical	Electrica	ıl		Servi	ce manual revision
	☐ Paper path	☐ Transmit	t/rec	eive [☑ Retrof	fit information
	Other ()					

Firmware history for the AD1.

- USA Model -

	File No.		Total			
A1935532	(A193uxx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
D	04	1.16	55DD	178E	3E4F	1st Mass Prod.
Е	05	1.23	FB24	B285	489F	November Prod.'96
F	06	1.31	F96B	F66D	02FE	December Prod.'96
G	07	1.33	5D03	2ECA	2E39	January Prod.'97
Н		1.35				January Prod.'97
J		1.36				January Prod.'97
K	10	1.38	A7FE	FB14	ACEA	February Prod.'97
L	11	1.43	BA4B	536A	66EI	March Prod.'97
М	11A	1.48	F9D6	3029	C9AD	May Prod.'97
N	12	1.54	7413	3D1A	36F9	June Prod.'97
Р	13	1.60	3042	A726	891C	August Prod.'97
R	14	1.62	5B56	CF0D	8C49	September Prod.'97
T	16	1.70	8D31	65E0	2751	October Prod.'97
V	17	1.72	2708	2870	FE98	February Prod.'98
W	18	1.73	0BF0	1A1D	F1D3	September Prod.'98
Y	20	1.75	89F2	02F7	86FB	March Prod. '99

- European/Asian Model -

	File No.		Total			
A1935533	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)	Production
С	103	1.16	B574	E4C1	D0B3	1st Mass Prod.
D	104	1.23	FC4B	98CE	637D	November Prod.'96
Е	105	1.31	OADC	41C5	C917	December Prod.'96
F	107	1.33	4C77	CFF3	7C84	January Prod.'97
G		1.35				January Prod.'97
Н		1.36				January Prod.'97
J	110	1.38	ACCC	2927	8353	February Prod.'97
K	111	1.43	F537	6510	9027	March Prod.'97
L	111A	1.48	7218	5558	1CC0	May Prod.'97
M	112	1.54	AAA8	7837	3271	June Prod.'97
N	113	1.60	1FE3	AEE1	7102	August Prod.'97
Р	114	1.62	794C	90BE	E88E	September Prod.'97
R	116	1.70	2208	D8BC	494C	October Prod.'97
S	117	1.72	76BE	909E	E620	February Prod. '98
Т	118	1.73	4C5F	714E	DB11	September Prod.'98
W	120	1.75	4840	0B94	3CAC	March Prod. '99

^{*}Versions 1.35 and 1.3 are not released via Files.



PAGE: 2/6

Reissued: 29-Mar-00

Model: AD1 Date: 15-Jan-97 No: 15j

- European 2nd Language -

A6485570	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
Е	205	1.43EU2	4BC4	DE26H	6D9E
F	205A	1.48EU2	09F5	CC25	3DD0
G	206	1.54EU2	E768	F05C	F70C
Н	208	1.57EU2	E765	F056	F70F
J	209	1.60EU2	AE02	2277	8B8B
K	210	1.62EU2	CB8A	0ACC	C0BE
М	212	1.70EU2	4159	50F0	F069
N	213	1.72EU2	8982	08DC	80A6
Р	214	1.73EU3	9E75	EC59	B21C
R	216	1.75EU2	7E27	8168	FCBF

- European 3rd Language -

A6485573	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	301	1.57EU3	9DBB	C908	D4B3
Α	302	1.60EU3	390A	FD07	3C03
В	303	1.62EU3	C69E	D5E3	F0BB
D	305	1.70EU3	006B	8E5E	720D
E	306	1.72EU3	BA31	2700	9331
F	307	1.73EU3	3774	27A0	0FD4
Н	309	17.5EU3	6CFA	0D13	5FE7

- European 4th Language -

	T				
A6485574	File No.		Total		
	(A193exx)	Version	C.SUM	SUM(OH)	SUM(OL)
	401	1.57EU4	1DF0	CA60	5390
Α	402	1.60EU4	4490	FDEF	46A1
В	403	1.62EU4	A30C	D9E5	C927
D	405	1.70EU4	3973	9405	A56E
E	406	1.72EU4	78ED	301F	48CE
F	407	1.73EU4	1D07	11EC	0BEB
Н	409	1.75EU4	7DB1	0CFB	70B6

- China Version -

A6485572	File No.		Total		
	(A193CHxx)	Version	C.SUM	SUM(OH)	SUM(OL)
Е	04	1.62CH	B020	B056	FFCA
Н	07	1.70CH	1893	3AEA	DDA9
J	80	1.72CH	690B	C1A7	A764
K	09	1.73CH	D423	A74A	2CD9
M	11	1.75CH	C817	33D6	9441

RIGOH

Technical Bulletin

PAGE: 3/6

Reissued: 29-Mar-00

Model: AD1 Date: 15-Jan-97 No: 15j

- Taiwan Version -

	File No.		Total		
A1935534	(A193TWxx)	Version	C.SUM	SUM(OH)	SUM(OL)
В	03	1.62TW	C05F	3BA0	94BF
Е	06	1.70TW	470D	87F1	BF1C
F	07	1.72TW	A7C2	0C5B	9B67
G	08	1.73TW	59DD	FB05	5ED8
J	10	1.75TW	B845	9643	2202



PAGE: 4/6

Reissued: 29-Mar-00

Model: AD1 Date: 15-Jan-97 No: 15j

	110 1	F	EL 10	EL!A	E114	01.17	T) 6 (5)
Symptom Corrected (New/corrected items only – for old	USA	EU/ Asia	EU2	EU3	EU4	CHN	TWN
ones, see previous bulletins)							
White copy problem on 1st scanning.	Y	W	R	Н	Н	М	J
A. Two new SP modes have been added:							
1. SP4- 916-1: Scanner lamp off counter Default: 120min Range: 0-300min							
2. SP4 -916-2: Scanner lamp warm-up time Default: 200ms Range: 0-500ms							
If the scanner lamp remains off for 120 minutes or longer in between the first and second scans of each job, the machine will allow the scanner 120 ms for warm-up (default).							
B. When the scanner lamp is turned on for the first time after the main power switch has been turned on, the machine allows the scanner 300 ms for warm-up.							
Warm up time							
B							
Power switch ON Start key First Job Second Job 120 min 200ms A-1 A-2							



PAGE: 5/6

Reissued: 29-Mar-00

Model: AD1 Date: 15-Jan-97 No: 15j

A1935532	A193-10	A193-15	A193-17	A193-55
Е	A10611001~	6A76100001~	A7226100001~	L5026110066~
F	-	6A76120001~	A7226110154~	L5026120516~
G	A107010001~	6A76120026~	A7226120149~	L5027011010~
Н	ı	6A77020001~	A7227010410~	L5027021541~
J	A107020001~	6A77020241~	-	L5027021563~
K	A107030001~	6A77020438~	A7227020001~	L5027031945~
L	A107040001~	6A77040001~	-	L5027042480~
M	A107050001~	6A77050001~	A7227050001~	L5027053186~
N	A107060036~	6A77060001~	A7227060001~	L5027063876~
Р	A107080001~	6A77080001~	A7227080001~	L5027085441~
R	A107090001~	6A77090001~	A7227090001~	L5027096321~
Т	A107100001~	6A77100001~	A7227100006~	L5027117581~
V	A108020001~	6A78020001~	A7228020001~	L5028019178~
W	A108090001~	6A78090001~	A7228090001~	L5028092927~
Y	-	-	-	L0529037236~

PAGE: 6/6

Reissued: 29-Mar-00

Model: AD1 Date: 15-Jan-97 No: 15j

A1935533	A193-22	A193-26	A193-27	A193-29	A193-65
D	AH26110001~	3L01160001~	A7226101023~	A7226101492~	L5026110271~
E	AH26120001~	3L01260001~	A7226111703~	A7226122087~	L5026120780~
F	AH27010001~	3L00170001~	A7226121305~	A7227012021~	L5027011216~
G	AH27020001~	3L00270001~	ı	ı	L5027011424~
Н	AH27020951~	-	A7227021026~	A7227021345~	L5027021685~
J	AH27020967~	3L00370001~	A7227030441~	A7227031491~	L5027032180~
K	TBA	3L00470001~	TBA	TBA	TBA
L	AH27040251~	3L00570001~	A7227042629~	A7227052269~	L5027053561~
M	AH27060960~	3L00670001~	A7227060651~	A7227062571~	L5027064111~
N	AH27080001~	3L00870001~	A7227080969~	A7227081769~	L5027085755~
Р	AH27090001~	3L00970001~	A7227090881~	A7227092701~	L5027096431~
R	AH27100463~	3L01070007~	A722710771~	A7227102371~	L5027118101~
S	AH28020001~	3L00280001~	A72280011266~	A7228011756~	L5028019336~
T	AH28090001~	3L00980001~	A7228090494~	A7228091104~	L5028093202~
W	AH29030294~	3L00390001~	A7229030021~	A7229032398~	L5029037451~

A6485572	A193-69
E	A7227092891~
Н	A7227102531~
J	A7228043126~
K	-
М	A7229081098~

A1935534	A193-19
R	A7227090821~
Ь	A7227090621~
F	A7228042025~
· .	A1220042020**
G	A7228090449~
J	A7229030001~



PAGE: 1/4

Reissued date 29-Mar-00 RTB Correction

The items in bold italics have been corrected or added.

Model: AD1-E Date			e: 15-Oct-97	No: 40f	
Subject: ROM History (AD1-E Copy Version)			Prepared by: K.Ugaeri		
From: QAC Field Information Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part info ☐ Electrica ☐ Transmi	al	Servi	n required ce manual revision fit information

Firmware history for the AD1-E (Copy)

USA Model

A2245532	File No.	Version	Total	SUM(OH)	SUM(OL)	Production
	(A224uxx)		C.SUM			
D	01	1.18	7766	6521	1245	1st Mass Prod.
E	02	1.20	01F7	98CE	6929	June Prod. '97
F	03	1.24	D441	9943	3AFE	August Prod. '97
Н	04	1.26	C879	5895	6FE4	September Prod. '97
K	06	1.30	432E	144E	2EE0	October Prod. '97
L	07	1.32	DECC	12FA	CBC2	November Prod.'97
М	08	1.33	A5B9	A28F	032A	February Prod.'98
N	09	1.34	67BC	73E2	F3DA	September Prod.'98
Q	11	1.36	DF85	E4C8	FABD	March Prod.'99

European /Asian Model

A2245533	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)	Production
В	101	1.20EU1	46A8	65C6	E0E2	1st Mass Prod.
С	102	1.24EU1	F12D	8333	6DFA	August Prod. '97
D	103	1.26EU1	6693	55DF	10B4	September Prod. '97
F	105	1.30EU1	6F80	F07D	7F03	October Prod. '97
G	106	1.32EU1	AD8D	EF92	BDFB	November Prod.'97
Н	107	1.33EU1	3D82	8357	BA2B	February Prod.'98
J	108	1.34EU1	C46A	790E	4B5C	September Prod.'98
L	110	1.36EU1	F872	24D1	D3A1	March Prod.'99



PAGE: 2/4

Reissued date 29-Mar-00

Model: AD1-E	Date: 15-Oct-97	No: 40f

European 2nd Language

A8105570	File No.	Version	Total	SUM(OH)	SUM(OL)
	(A224exx)		C.SUM		
А	202	1.24EU2	9FB1	FAE8	A4C9
В	203	1.26EU2	F29A	D4BF	1DDB
D	205	1.30EU2	76E6	6ED6	0810
Е	206	1.32EU2	6349	6E3B	F50E
F	207	1.33EU2	EE69	0204	EC65
G	208	1.34EU2	153D	F11B	2422
J	210	1.36EU2	0717	AA5A	5CBD

European 3rd Language

A8105573	File No. (A224exx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
Α	302	1.24EU3	2C91	F73A	3557
В	303	1.26EU3	649F	D770	8D2F
D	305	1.30EU3	6B26	4D86	1DA0
Е	306	1.32EU3	EE17	646C	89AB
F	307	1.33EU3	FE7F	D5DD	28A2
G	308	1.34EU3	3DF8	C1D0	7C28
J	310	1.36EU3	4D07	5E6C	EE9B

European 4th Language

A8105574	File No.	Version	Total	SUM(OH)	SUM(OL)
	(A224exx)		C.SUM		
Α	402	1.24EU4	7A6A	F8BC	81AE
В	403	1.26EU4	E7F9	DA9F	0D5A
D	405	1.30EU4	A7C1	4EF5	58CC
Е	406	1.32EU4	DFE0	4E0F	91D1
F	407	1.33EU4	8EEA	DAFC	B3EE
G	408	1.34EU4	6B87	C26F	A918
J	410	1.36EU4	3F54	6149	DE0B

China Version

A8105512(OL) A8105513(OH)	File No. (A224CHxx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
-	-	-	-	-	-

Taiwan Version

A2245534	File No. (A224TW xx)	Version	Total C.SUM	SUM(OH)	SUM(OL)
-	-	-	-	-	-

PAGE: 3/4

Reissued date 29-Mar-00

Model: AD1-E Date: 15-Oct-97 No: 40

Symptom Corrected (New/corrected items only – for old	USA	EU/	EU2	EU3	EU4	CHN	TWN
ones, see previous bulletins)		Asia					
	Υ	W	R	Н	Н	М	J
White copy problem on 1st scanning.		• • •	'`	l ''	''	IVI	
A. Two new SP modes have been added:							
1. SP4 -916-1: Scanner lamp off counter							
Default: 120 min							
Range: 0-300 min							
· ·							
2. SP4 -916-2: Scanner lamp warm-up time							
Default: 200 ms							
Range: 0-500 ms							
range. 0 000 ms							
If the scanner lamp remains off for 120 min or longer (in							
between each job), the machine will allow the scanner 120 ms							
for warm-up (default).							
B. When the scanner lamp is turned on for the first time							
after the main power switch has been turned on, the							
machine allows the scanner 300 ms for warm-up.							
Marma un tima							
Warm up time Power switch ON							
Start key Start key Start key Second Jo							
300ms 120 min 200ms							
300ms 120 min 200ms							
↑ ↑ ↑							
B A-1 A-2							
, , , , , , , , , , , , , , , , , , ,							

PAGE: 4/4

Reissued date 29-Mar-00

Model: AD1-E Date: 15-Oct-97 No: 40f

A2245532	A224-10	A224-15	A224-17	A22455
E	AK87070001~	9A37060001~	A7427060001~	L027080001~
F	AK87080023~	9A37080001~	A7427080001~	_
Н	AK87090001~	9A37090001~	A7427090001~	L027090031~
K	AK87100001~	9A37100001~	A7427100021~	L027111066~
L	AK87120001~	9A37120001~	A7427120001~	L027121721~
M	AK88020001~	9A38020001~	A7428020001~	L0248022670~
N	AK88090001~	9A38090001~	A7428090001~	L0248094106~
Q	AK89030001~	9A39090001~	A7429090001~	L0249036677~

A2245533	A224-22	A224-26	A224-27	A224-29	A224-65
С	AK97070543~	3P30870001~	A7427080601~	A7427081501~	_
D	AK97090001~	3P30970001~	A7427090305~	A7427091035~	L0247090216~
F	AK97100001~	3P31070001~	A7427100176~	A7427101246~	_
G	AK97110001~	3P31170001~	A7427110081~	A7427110881~	L0247111341~
Н	AK98020001~	3P30280001~	A7428030351~	A7428020101~	L0248023356~
J	AK98090001~	3P30980001~	A7428090576~	A7428091241~	L0248094201~
L	AK99030001~	3P30390001~	A7429030471~	A7429041178~	L0249036811~