Modification Bulletin

PAGE: 1/1

Model: SP3 Date			e: 15-Feb-98	No: 1		
Modified Article: Bushing for Development			Prepared by: E.Fukuyama			
From: QAC Field Information Dept.						
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To im	nprove	ve reliability ⁽)		
	☐ Part standardization	Other				

The following part has been added as a service part.

Please add this to your parts catalog.

Old part Number	New part Number	Description	Qty	Int	Page	Index	Note
	AA080200	Bushing -6x12x12	2		49	19	

			JAPAN PRODUCTION			
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER		
Gestetner 3240 Nashuatec D440	120/60	USA, CANADA, S. AMERICA	A195- 10	AG97120001		
Savin 9940DPC	120 / 60	USA	A195- 15	6A97110001		
RICOH Aficio 401	120/60	USA, CANADA, S. AMERICA	A195- 17	A7207110001		
Gestetner 3240 Nashuatec D440 Rex Rotary 2840	220,230, 240/50,60Hz	EUROPE, ASIA	A195- 22	AG97110001		
Infotec 5402 MF	220,230, 240/50,60Hz	EUROPE	A195- 26	3K91170001		
RICOH Aficio 401	220,230, 240/50,60Hz	EUROPE, ASIA	A195- 27	A7207110366		
Lanier	120/60	USA, CANADA, S. AMERICA	A195-55	L5047110841		
Lanier	220,230, 240/50,60Hz	EUROPE	A195-65	L504111001		

በመሰ	иш
וושונו))lill

PAGE: 1/1

Model: SP3 Date			e: 15-Mar-98	No: 2	
Modified Article: Controller HDD			Prepared by: A.Tokoyama		
From: QAC Field Information Dept.					
Reason for	Parts catalog correction	⊠ Venc	lor ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly ☐ To improve		nprove	e reliability ()
	☐ Part standardization	☐ Other			

Due to discontinuation of the HDD, the model of the HDD for the printer controller has been changed as follows.

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
G6905723	H5157119	HDD – MK0803MAT	1	O/O	89	5	

വ്യ	П
(比(0)	اآاا

Model: SP3			Date: 15-Mar-98		No: 3
Modified Article: Controller Board and Scanner Kit			Prepared by: A.Tokoyama		
From: QAC Field Information Dept.					
Reason for	□ Parts catalog correction	☐ Venc	lor ch	ange 🔲 To r	neet standards
Modification: ☐ To facilitate assembly ☐ To improv		To improve reliability ()			
	☐ Part standardization	☐ Other			

The following parts should be corrected.

Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
A6491805	A6491804	Ferrite Core – TFC 23-11-14	1		91	5	
A6495218	A6495217	IC – IDT74FCT244CTS0	1		109	12	

PAGE: 1/1

	牊
いいいり	ΙПΙ

PAGE: 1/1

Model: SP3 Date			e: 15-Mar-98	No: 4		
Modified Article: Controller Board			Prepared by: A.Tokoyama			
From: QAC Field Inf	From: QAC Field Information Dept.					
Reason for	Reason for Parts catalog correction Vendo			ange 🔲 To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To in	nprove	ve reliability ⁽)		
	☐ Part standardization	Othe	r			

Due to a vendor change, the IC on the printer controller has been changed as follows.

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
A6495202	A6495240	IC - MBM29F040A	1	O/O	109	3	



PAGE: 1/2

Model: SP3		Date	e: 30-Apr-98	No: 5
Modified Article: Vibrating Plate		Prepared by: E.F	ukuyama	
From: QAC Field Inf	ormation Dept.			
Reason for	Parts catalog correction	☐ Vendor ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly	□ To improve	e reliability ()
	☐ Part standardization	□ Other		

To improve the durability of the vibrating plate mylar in the duplex unit, the shape of the vibrating plate has been changed.

Problem


Mylar damage

Cause

The mylar should move as shown in Figure 1, but after repeated use of the 50-sheet stack mode in the duplex unit, the mylar may curl as shown in Figure 2. If the mylar becomes deformed as shown in Figure 2, then its movement will resemble that shown in Figure 3. If this movement is repeated, then section A of the mylar will be damaged.

Countermeasure

To prevent the mylar from curling, the shape of the bracket has been changed so that the mylar will bend as shown in Figure 4 below.



Old part	New part	Description	Qty	Int	Page	Index	Note
number	Number						
A1544623	A1544626	Vibrating Plate	2	1	65	26	



PAGE: 2/2

Model: SP3 Date: 30-Apr-98 No: 5

			JAPAN PR	ODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NO.
Gestetner 3240 Nashuatec D440	120/60	USA, CANADA, S. AMERICA	A195- 10	AG97120001
Savin 9940DPC	120/60	USA	A195- 15	6A97100001
RICOH Aficio 401	120/60	USA, CANADA, S.AMERICA	A195- 17	A7207100001
Gestetner 3240 Nashuatec D440 Rex Rortary 2840	220, 230 240/ 50,60Hz	EUROPE, ASIA	A195- 22	AG87090001
Infotec 5402 MF	220, 230, 240/ 50,60Hz	EUROPE	A195- 26	3K90870001
RICOH Aficio 401	220, 230, 240/ 50,60Hz	EUROPE, ASIA	A195- 27	A7207080001
Lanier	120/ 60	USA, CANADA, S.AMERICA	A195- 55	L5047090001
Lanier	220, 230, 240/ 50,60Hz	EUROPE	A195- 65	L5047080001

Modification Bulletin


PAGE: 1/1

Model: SP3 Date		ate	: 30-Apr-98	No: 6	
Modified Article:	Duplex Guide Mylar	Prepared by: A. Sasaki		Sasaki	
From: QAC Field In	formation Dept.				
Reason for Modification:	☑ Parts catalog correction☑ To facilitate assembly	☐ Vendor o			neet standards)
ivioanication.	Part standardization	 □ Other			

Please add the following part to the parts catalog.

Please refer to the illustration below for the attachment position of the mylar.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
		Duplex Guide Mylar	1		65	49	New Index



Modification Bulletin

PAGE: 1/2


Model: SP3			Date	e: 30-Apr-98	No: 7
Modified Article: Spring Clutch - Duplex Tray Bottom Plate			Prepared by: A. Sasaki		
From: QAC Field Information Dept.					
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly)	
	\square Part standardization	Othe	r		

To reduce no-feed jams in the duplex unit caused by insufficient pressure from the bottom plate, the shape of the spring clutch has been changed. To distinguish between the old and new clutches, the color of the sleeve has been changed from white to blue.

The insufficient pressure occurs when the clutch turns in the direction which tightens the spring. This is because when the sleeve hits the spring hook, the spring cannot turn completely, so the bottom plate cannot be lifted up to the highest position.

To prevent the sleeve from hitting the spring hook, a 4.5-mm wide section of the sleeve has been cut away as shown.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AB040015	AB040017	Spring Clutch – Tray Bottom Plate	1	X/O	65	35	





PAGE: 2/2

Model: SP3 Date: 30-Apr-98 No: 7

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195-10	AG98030001
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195-15	6A68040001
Ricoh Aficio 401	120/60	USA, Canada,	A195-17	A7208030001
		S. America		
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22	AG88030001
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220, 230, 240/	Europe	A195-26	3K90380001
	50, 60			
Ricoh Aficio 401	220, 230, 240/	Europe, Asia	A195-27	A7208030618
	50, 60			
Lanier	120/60	USA, Canada,	A195-55	L5048032432
		S. America		
Lanier	220, 230, 240/	Europe	A195-65	L5048032447
	50, 60			

Modification Bulletin


PAGE: 1/1

Model: SP3 D			Date	e: 30-Apr-98	No: 8
Modified Article: 9	Article: Seals on the Cleaning Blade Bracket			Prepared by: E.Fukuyama	
From: QAC Field Int	formation Dept.				
Reason for	□ Parts catalog correction	☐ Vend		— ,	neet standards
Modification:	☐ To facilitate assembly	☐ To im	prove	e reliability ()
	☐ Part standardization	Other			

The following parts have been added as service parts.

Please add them to your parts catalog.

Old part Number	New part Number	Description	Qty	Int	Page	Index	Note
	AA151809	Rear Seal	2		51	25	New Index
	AA151807	Shield:Blade:Front	1		51	26	New Index
	AA151782	Shield:Blade:Rear	1		51	27	New Index



	咒
յլտլա	朏

PAGE: 1/1

Model: SP3 Date			te: 30-Apr-98	No: 9
Modified Article: 1	Thermistor	Prepared by: A. Sasaki		Sasaki
From: QAC Field In	formation Dept.			
Reason for	☐ Parts catalog correction	☐ Vendor c	hange	meet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability ())
	□ Part standardization	Other		

To standardize parts with new models, the following part has been changed.

	Old part number	New part number	Description		Int	Page	Index	Note
I	A1345266	A1344071	Thermistor	1	O/O	57	9	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195-10	AG98020001
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195-15	6A68020001
Ricoh Aficio 401	120/60	USA, Canada, S. America	A195-17	A7208010217
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22	AG88020001
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220, 230, 240/ 50, 60	Europe	A195-26	3K90280001
Ricoh Aficio 401	220, 230, 240/ 50, 60	Europe, Asia	A195-27	A7208020641
Lanier	120/60	USA, Canada,	A195-55	L5048022126
		S. America		
Lanier	220, 230, 240/ 50, 60	Europe	A195-65	L5048022306

ገጢሰ	儿儿
](K)(I)[[]

PAGE: 1/1

Model: SP3 Date:			e: 30-Apr-98	No: 10	
Modified Article: Hard Disk			Prepared by: A.	Sasaki	
From: QAC Field Information Dept.					
Reason for	Parts catalog correction	☐ Vendo	r cha	ange 🔲 To n	neet standards
Modification:		☐ To improve reliability ())
	☐ Part standardization	Other			

The hard disk has been changed because production of the old type is discontinued. The capacity of the hard disk has been changed from 1.7 GB to 1.05 GB.

Since the capacity of the hard disk used in this machine is 1.0 GB, it is not necessary to change any SP modes or ROMs even when the hard disk is replaced with a new one.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
A1337885	A1337892	Hard Disk 1.05 GB	1	O/O	81	2	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195-10	AG97120001
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195-15	6A67110001
Ricoh Aficio 401	120/60	USA, Canada,	A195-17	A7207110001
		S. America		
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22	AG87110001
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220, 230, 240/	Europe	A195-26	3K91170001
	50, 60			
Ricoh Aficio 401	220, 230, 240/	Europe, Asia	A195-27	A7207110366
	50, 60			
Lanier	120/60	USA, Canada,	A195-55	L5047110841
		S. America		
Lanier	220, 230, 240/	Europe	A195-65	L5047111001
	50, 60			

	ПП
U(U)	П

PAGE: 1/1

Model: SP3	Date	e: 31-May-98	No: 11	
Modified Article: NIC and Scanner Option			Prepared by: A.	Tokoyama
From: QAC Field	Information Dept.			
Reason for	□ Parts catalog correction	☐ Vendor ch	ange	neet standards
Modification:		☐ To improve reliability ()		
	☐ Part Standardization	☐ Other		

The following parts should be corrected.

Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
A6515100	A6515110	Scanner Board	1		91	1	
A7325110	A7320530	Network Board - Ether	1		91	4	
A7335110	A7330530	Network Board - Token	1		91	4	

	叮
(G(0)	

Modified Article: Fusing Unit

From: QAC Field Information Dept.

Model: SP3

Reason for

Modification:

Modification Bulletin

Date: 31-May-9			8	No: 12
Prepared			by: A.	Sasaki
☐ Vendor change			☐ To m	neet standards
☐ To improve reliability			()

PAGE: 1/1

The following parts have been registered as service parts.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Please add them to your parts catalog.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
	A1337501	Fusing Unit – 115V	1		57	#	
	A1337506	Fusing Unit – 230V	1		57	#	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195-10	
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195-15	
Ricoh Aficio 401	120/60	USA, Canada,	A195-17	
		S. America		
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22	
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220, 230, 240/	Europe	A195-26	
	50, 60			
Ricoh Aficio 401	220, 230, 240/	Europe, Asia	A195-27	
	50, 60			
Lanier 5040 MFD	120/60	USA, Canada,	A195-55	
		S. America		
Lanier 5040 MFD	220, 230, 240/	Europe	A195-65	
	50, 60			

	ПГ
(G(0)	

Modified Article: Parts Catalog Correction

From: QAC Field Information Dept.

Model: SP3

Reason for

Modification:

Modification Bulletin

	Date: 31-May-98			No: 13
		Prepared	l by: S.	Tomoe
☐ Vendor change		☐ To n	neet standards	
☐ To improve reliability			()

PAGE: 1/1

The following part number should be corrected. Please correct your part catalog.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
A1343164	A2173163	Bracket - Toner Holder	1	·	45	17	

Other

			1		
			JAPAN PRODUCTION		
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER	
Gestetner 3240	120/60	USA, Canada,	A195-10		
Nashuatec D440		S. America			
Savin 9940DPC	120/60	USA	A195-15		
Ricoh Aficio 401	120/60	USA, Canada,	A195-17		
		S. America			
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22		
Nashuatec D440	50, 60				
Rex Rotary 2840					
Infotec 5402 MF	220, 230, 240/	Europe	A195-26		
	50, 60				
Ricoh Aficio 401	220, 230, 240/	Europe, Asia	A195-27		
	50, 60				
Lanier 5040 MFD	120/60	USA, Canada,	A195-55		
		S. America			
Lanier 5040 MFD	220, 230, 240/	Europe	A195-65		
	50, 60				

ገጦጠ	ПΠ
](60)	INI

PAGE: 1/2

Model: SP3 Date		e: 31-Aug-98	No: 14		
Modified Article: Pick-off Pawl Pressure Spring			Prepared by: E.Fukuyama		
From: QAC Field Info	ormation Dept.				
Reason for	□ Parts catalog correction	☐ Vend	or ch	ange 🔲 To m	neet standards
Modification:		\square To improve reliability $\qquad (\qquad)$)
	☐ Part standardization	Other	r		

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AA066250	AA066311	Pressure Spring	1	X/O	53	12	
AA066251	AA066312	Pressure Spring	1	X/O	53	14	

To reduce wear on the drum caused by the pick-off pawls, the pressure applied to the pick-off pawls by the pressure springs has been reduced.

To differentiate between the new and old parts, the new parts are coloured black.



PAGE: 2/2

Model: SP3 Date: 31-Aug-98 No: 14

			JAPAN PROD	UCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195- 10	AG98070001
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195- 15	6A68070001
Ricoh Aficio 401	120/60	USA, Canada,	A195- 17	A7208060890
		S. America		
Gestetner 3240	220,230, 240/	Europe, Asia	A195- 22	AG88070001
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220,230, 240/	Europe	A195- 26	3K90780001
	50, 60			
Ricoh Aficio 401	220,230, 240/	Europe, Asia	A195- 27	A7208070551
	50, 60			
Lanier 5040 MFD	120/60	USA, Canada,	A195- 55	Aug. 98 production
		S. America		
Lanier 5040 MFD	220,230, 240/	Europe	A195- 65	L5048082702
	50, 60			



PAGE: 1/2

Reissued: 10-Jul-00

	Model: SP3	Date: 31-Aug-98	No.: MA195015a
--	------------	-----------------	----------------

MB Correction

The new part number of the Operation Panel Board has been corrected.

Modified Article: Operation Panel ROM Modification			Prepared	by: E. Fukuyama
From: Technical Services Dept., GTS Division				
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To meet standards
Modification:	☐ To facilitate assembly			()
	☐ Part standardization	☐ Other		

Old part	New part	Description	Qty	Int	Page	Index	Note
number	Number						
A1337704	A1337770	Operation Panel Board	1	X/O	15	18	
A1337731	A1337747	ROM : Operation Panel	1	X/O	15	17	

Symptom

The image on the touch screen is blurred.

Cause

The background pattern for the touch screen is not suitable. Blurring occurs when there are small letters or the letters are bunched together.

Countermeasure

The ROM for the operation panel board has been modified so that the background pattern is now different. The new ROM has been used starting from the June production runs.



Model: SP3

Modification Bulletin

Date: 31-Aug-98 No.: MA195015a

PAGE: 2/2

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/ 60	USA, Canada, S.	A195-10	AG98060001
Nashuatec D440		America		
Savin 9940DPC	120/ 60	USA	A195-15	6A68060001
Ricoh Aficio 401	120/ 60	USA, Canada, S. America	A195-17	A7208060001
Gestetner 3240 Nashuatec D440 Rex Rotary 2840	220, 230, 240/ 50, 60	Europe, Asia	A195-22	AG99060001
Infotec 5402 MF	220, 230, 240/ 50, 60	Europe	A195-26	3K90680001
Ricoh Aficio 401	220, 230, 240/ 50, 60	Europe, Asia	A195-27	A7208050688
Lanier 5040 MFD	120/ 60	USA, Canada, S. America	A195-55	
Lanier 5040 MFD	220, 230, 240/ 50, 60	Europe	A195-65	L5048082702

Modification Bulletin

PAGE: 1/1

Model: SP3		e: 30-Sep-98	No: 16		
Modified Article: M	lain Switch	Prepared by: E. Fukuyama			
From: QAC Field Inf	ormation Dept.				
Reason for	Parts catalog correction	☐ Venc	lor ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly	⊠ To in	nprov	e reliability ()
	☐ Part standardization	Othe	r		

Use of a neutral cleaner to clean the main switch may weaken the switch and result in damage. To prevent damage to the main switch, the materials of the switch have been changed.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
12042421	12042467	Main Switch	1	O/O	79	113	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 3240	120/60	USA, Canada,	A195-10	AG98060001
Nashuatec D440		S. America		
Savin 9940DPC	120/60	USA	A195-15	6A68050001
Ricoh Aficio 401	120/60	USA, Canada,	A195-17	A7208050001
		S. America		
Gestetner 3240	220, 230, 240/	Europe, Asia	A195-22	AG88060001
Nashuatec D440	50, 60			
Rex Rotary 2840				
Infotec 5402 MF	220, 230, 240/ 50, 60	Europe	A195-26	5K90580014
Ricoh Aficio 401	220, 230, 240/ 50, 60	Europe, Asia	A195-27	A7208050541
Lanier 5040 MFD	120/60	USA, Canada, S. America	A195-55	
Lanier 5040 MFD	220, 230, 240/ 50, 60	Europe	A195-65	L5048082702

Modification Bulletin

PAGE: 1/1

MB Correction

Reissue date: 15-Oct-98

The items in bold italics have been corrected or added.

Model: SP3 Date			e: 30-Sep-98	No: 17	
Modified Article: Post Script Board			Prepared by: E.	Fukuyama	
From: QAC Field Information Dept.					
Reason for	☐ Parts catalog correction	☐ Vend	dor ch	ange 🔲 To n	neet standards
Modification: ☐ To facilitate assembly ☐ To impr			nprove	e reliability ⁽)
	□ Part standardization	Othe	r		

Since the PostScript ROM is no longer in production, a substitute for it is now used. At the factory the PostScript Board is installed on the Printer Controller Board and the data is written into the firmware. However, to write the firmware into the new ROM, the firmware of the boot ROM of the Printer Controller Board was modified. This modification is to the Boot ROM and is not a new PostScript ROM version. To differentiate the new and old PostScript Boards, the part numbers have been changed.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
A6505100	A6505400	Post Script Board	1	O/O	91	3	

Implemented from Lot No. 87022156 (same for all shipping destinations)

Modification Bulletin

PAGE: 1/1

Model: SP3 Date				e: 30-Sep-98	No: 18
Modified Article: C	Controller Board	Prepared by: E. Fukuyama			
From: QAC Field Information Dept.					
Reason for	Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly	☐ To in	nprove	e reliability ()
	□ Part standardization	Othe	r		

Since the PostScript ROM is no longer in production, a substitute for it is now used. At the factory, the PostScript Board is installed on the Printer Controller Board and the data is written into the firmware. However, to write the firmware into the new ROM, the firmware of the boot ROM of the Printer Controller Board was modified. This modification is to the Boot ROM and is not a new Printer Controller ROM version. To differentiate the new and old Controller Boards, the part numbers have been changed.

	Old part	New part	Description	Qty	Int	Page	Index	Note
r	number	number						
Α	6495100	A6495400	Printer Controller Board	1	0/0	89	6	

Implemented from Lot No. 84020001 (same for all shipping destinations)

	儿儿
แ็ดแ)[[]

PAGE: 1/1

Model: SP3 Date					8	No.: 19	
Modified Article:	Ozone Filter			Prepared	by: E.	Fukuyama	_
From: GTSS Field	Information Dept						
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization☐		prove	ange e reliability	☐ To n	neet standards)	

The ozone filter has been changed because production of the old one has been discontinued.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
AA010083	AA010098	Ozone Filter – 64x45x30	1	O/O	77	5	


ിഥി	ПΠ

PAGE:	1/1
-------	-----

Model: SP3		Da	te: 15-Jan-99	No: 20
Modified Article: 1	st Scanner		Prepared by: S.	Tomoe
From: GTS and S D	ivision			
Reason for	□ Parts catalog correction	☐ Vendor c	hange 🔲 To	meet standards
Modification:	☐ To facilitate assembly	☐ To impro	ve reliability ()
	☐ Part standardization	☐ Other		

The following parts have been added. Please correct your parts catalog.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
		Front Terminal	1		35	21	
	A1341773	Rear Terminal	1		35	22	



$\Pi \cap$	ጋ(0)	П
ЦU	贤(0)	뷟

PAGE: 1/1

Model: SP3		Da	te: 31-Mar-9	9	No.: 21
Modified Article: I	Pick-off Pawl Pressure Spring		Prepared	l by: E.	Fukuyama
From: GTSS Field I	nformation Dept				
Reason for	□ Parts catalog correction	☐ Vendor c	hange	☐ To r	neet standards
Modification:	☐ To facilitate assembly	☐ To impro	ve reliability	()
	☐ Part standardization	☐ Other			

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AA036311	AA066323	Pressure Spring: Front	1	X/O	53	12	
AA066312	AA066324	Pressure Spring: Rear	1	X/O	53	14	

To reduce the wear on the drum caused by the pick-off pawls, the tension of the pressure spring of the pick-off pawl has been changed from 98mN to 40mN. The old part is black while the new part is silver. Since further production of the SP3 is not planned, the modification only relates to service parts.

PAGE: 1/2

Model: SP3		Dat	e: 30-Apr-99	9	No.: MA195022
Modified Article:	Duplex Guide Plate		Prepared	l by: E.	Fukuyama
From: Technical Se	ervice Dept., GTS Division				
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly		e reliability	()
	☐ Part standardization	☐ Other			

To prevent paper jams in the duplex unit, a mylar has been added to the duplex guide plate. Due to this modification, the part number has been changed.

Symptom

After paper has been stacked in the duplex unit, paper jams occur when the paper is fed back into the machine.


Cause

The mylar on the duplex guide plate slips downward.

Countermeasure

To prevent the mylar from shifting downward, a reinforcement mylar has been added.

Old part Number	New part Number	Description	Qty	Int	Page	Index	Note
A1344662	A2174517	Duplex Guide Plate	1	X/O	65	25	
	A2174695	Reinforcement Mylar	1	X/X	65	50	



When installing the reinforcement mylar to prevent occurrences of this problem, please refer to the installation procedures shown on the next page.




PAGE: 2/2

Model: SP3 Date: 30-Apr-99 No.: MA195022

Reinforcement Mylar Installation Procedures

If the reinforcement mylar is not properly attached, the effectiveness of this modification is adversely affected.


1. Before attaching the reinforcement mylar, clean the guide plate with alcohol.



2. After the guide plate has completely dried, align the bottom of the guide plate and the bottom of the reinforcement mylar.

Note:

- ① Make sure that the mylar does not protrude beyond the edges of the guide plate
- 2 Make sure that there are no air bubbles under the mylar.
- 3After attaching the mylar, press down hard on the mylar to make sure that it is firmly attached.






PAGE: 1/1

Model: SP3	I: SP3 Date: 31-May-9				No.: MA195023
Modified Article:	Paper Feed Unit - Lower		Prepared	by: E.	Fukuyama
From: Technical S	Service Dept., GTS Division				
Reason for	□ Parts catalog correction	☐ Vendor	change	☐ To r	neet standards
Modification:	☐ To facilitate assembly	☐ To impro	ove reliability	()
	☐ Part standardization	☐ Other			

The following parts have been added. Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	A13427250	Paper Feed Unit – Lower	1		19	41	





PAGE: 1/1

Model: SP3 Date:				e: 15-Oct-99	e: 15-Oct-99 No.: MA19				
Modified Article: ⊦	larness and LD Unit			Prepared	by: E. I	Fukuyama			
From: Technical Ser									
Reason for	□ Parts catalog correction	☐ Vend	or ch	ange	☐ To m	neet standards			
Modification:	☐ To facilitate assembly	☐ To im	prove	e reliability	()			
	☐ Part standardization	☐ Other	r						

An error has been discovered in the parts catalogue. Please delete both index number 3 on page 37 (A1345396 - Harness LD Unit 115V) as well as the corresponding part in the illustration on page 36. This part is actually included in an assembly listed on page 41.

The assembly is comprised of this small part mentioned above, a relay connector and a harness that is listed on page 41 as: Index number 6, P/N A2175392, Harness - LSD. In the corresponding illustration on page 41, please draw in the part mentioned above (which was listed on p.37 as index no.3) so that it appears attached to the relay connector of the harness already in the illustration (i.e. index no.6, A2175392).

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A1345396	Delete	Harness – LD Unit (115V)	1->0		37	3	

The illustration does show the harness connected to the LD Unit on page 38, but the harness is not included under parts number A1342085 and A1337173. The part number for the LD Unit harness is mentioned under index number 5 on page 37 (A1345396 and A1337774).



Modified Article: Parts Catalog Correction From: Technical Service Dept., GTS Division

Model: SP3

Reason for

Modification:

Modification Bulletin

	Date	e: 15-Oct-99	9	No.: MA195025		
arts Catalog Correction	Prepared by: E. Fukuyama					
vice Dept., GTS Division						
Parts catalog correction	☐ Vendor ch	ŭ	☐ To m	neet standards		
☐ To facilitate assembly	☐ To improv	e reliability	()		

PAGE: 1/1


The Copy Tray Slide (index no.1), Copy Tray Guide (index no.2) and Copy Tray (index no. 30) should be deleted from the illustration on page 10.

Other

Index number 30 listed on page 11 refers to the energy star decal. Index numbers 1 and 2 both refer to the decals that were not included in the original illustration.

Please adjust your illustrations accordingly as shown below.

Part standardization






PAGE:	1/1
-------	-----

Model: SP3	odel: SP3 Dat		Date	e: 15-Dec-9	9	No.: MA195026		
Modified Article: Light Filter-G530/G533				Prepared by: E.Fukuyama				
From: Technical S	ervices Dept., GTS Division							
Reason for	Parts catalog correction	☐ Vendor ch		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reli		e reliability	()		
	☐ Part standardization	Other	-					

The following part has been added as a service part. Please add this to your parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	AA011041	Light Filter-G530/G533	1	•	37	26	

14.OPTICS SECTION 2 (A195)



ገጦጠ	ПП
](6(0)	聞

PAGE: 1/1

Model: SP3	Model: SP3 Date		ate	e: 06-Sep-0	1	No.: MA195027		
Modified Article: Electrical Spring Clutch			Prepared	by: E. I	Fukuyama	_		
From: Technical Se	ervices Dept., GTS Division							
Reason for	☐ Parts catalog correction		cha	ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To impr	rove	ereliability	()		
	☐ Part standardization	☐ Other						

The following part has been changed due to discontinued production:

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AX210046	AX210082	Electrical Spring Clutch	1-1	0/0	71	27	

Modification Bulletin

PAGE: 1/1

Model: SP3 Date			e: 25-Apr-02	2	No.: MA195028			
Modified Article: Development unit				Prepared by: Y.Urushihara				
From: Technical Services sec. Service Planning Dept.								
Reason for	□ Parts catalog correction	☐ Vendor cha		ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	()		
	☐ Part standardization	☐ Other						

Please correct your Parts Catalogue as follows.

Incorrect	Correct	Description	Q'ty	Int	Page	Index	Note
part number	part number						
A1343051	A2173050	Development unit	1		47	16	

19.DEVELOPMENT UNIT 1 (A195)

