D	П	മ	ጠ	叩
	Ш	(6)	(0)	빎

PAGE: 1/1

Model: AD50 Date			e: 15-Feb-98	No: 1	
Modified Article: Bushing for Development Unit		Prepared by: E.Fukuyama			
From: QAC Field Inf	ormation Dept.				
Reason for	□ Parts catalog correction	☐ Venc	lor ch	ange 🔲 To n	neet standards
Modification: ☐ To facilitate assembly ☐ To in		nprove	e reliability ()	
	☐ Part standardization	☐ Othe	r		

The following part has been added as a service part.

Please add this to your parts catalog.

Old part Number	New part Number	Description	Qty	Int	Page	Index	Note
	AA080200	Bushing - 6x12x12	2		49	19	

RIGOH

Modification Bulletin


PAGE: 1/1

Model: AD50 Da			e: 30-Apr-98	No: 2
Modified Article: Duplex Guide Mylar		Prepared by: A. Sasaki		
From: QAC Field Inf	ormation Dept.			
Reason for	Parts catalog correction	Uendor ch	nange 🔲 To r	neet standards
Modification: ☐ To facilitate assembly ☐ To		☐ To improv	/e reliability ()
	☐ Part standardization	Other		

Please add the following part to the parts catalog.

Please refer to the illustration below for the attachment position of the mylar.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
	A1344670	Duplex Guide Mylar	1		65	49	New
							Index



RIGOH

Modification Bulletin

PAGE: 1/2


Model: AD50 Da			Date	e: 30-Apr-98	No: 3
Modified Article: Spring Clutch - Duplex Tray Bottom Plate			Prepared by: A. Sasaki		
From: QAC Field Info	ormation Dept.				
Reason for	Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards
Modification: ☐ To facilitate assembly ☐		⊠ To im	nprove	e reliability ()
Part standardization O			r		

To reduce no-feed jams in the duplex unit caused by insufficient pressure from the bottom plate, the shape of the spring clutch has been changed. To distinguish between the old and new clutches, the color of the sleeve has been changed from white to blue.

The insufficient pressure occurs when the clutch turns in the direction which tightens the spring. This is because when the sleeve hits the spring hook, the spring cannot turn completely, so the bottom plate cannot be lifted up to the highest position.

To prevent the sleeve from hitting the spring hook, a 4.5-mm wide section of the sleeve has been cut away as shown.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AB040015	AB040017	Spring Clutch – Tray Bottom Plate	1	X/O	65	35	





PAGE: 2/2

Model: AD50 Date: 30-Apr-98 No: 3

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120/60	USA, Canada,	A217-10	AN3805xxxx
Nashuatec D4850		S. America		
Savin 9950DP	120 / 60	USA	A217-15	9A78030001
Ricoh Aficio 500	120/60	USA, Canada,	A217-17	A7608030001
		S. America		
Gestetner 2850e	220, 230, 240/	Europe, Asia	A217-22	AN28030001
Nashuatec D4850	50, 60			
Rex Rotary 8250E				
Infotec	220, 230, 240/	Europe	A217-26	3P70380001
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Europe	A217-27	A7608030072
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Asia	A217-29	A7608030169
	50, 60			

RIGOH

Modification Bulletin


PAGE: 1/1

Model: AD50 D			Date	e: 30-Apr-98	No: 4
Modified Article: S	Seals on the Cleaning Blade B	de Bracket Prepared by: E.Fukuy		ukuyama	
From: QAC Field Inf	formation Dept.				
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly	☐ Vend		ange	neet standards)
iviouilication.	Part standardization	☐ Other		- · · · · · · · · · · · · · · · · · · ·	

The following parts have been added as service parts.

Please add them to your parts catalog.

Old part	New part	Description	Qty	Int	Page	Index	Note
Number	Number						
	AA151809	Rear Seal	2		51	25	New Index
	AA151807	Shield:Blade:Front	1		51	26	New Index
	AA151782	Shield:Blade:Rear	1		51	27	New Index



	咒
յլտլա	朏

PAGE: 1/1

Model: AD50 Date		9: 30-Apr-98	No: 5		
Modified Article: Thermistor			Prepared by: A. Sasaki		
From: QAC Field In	formation Dept.				
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards
Modification: To facilitate assembly		☐ To in	nprove	e reliability ()
	□ Part standardization	☐ Othe	r		

To standardize parts with new models, the following part has been changed.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
A1345266	A1344071	Thermistor	1	O/O	57	5	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120/60	USA, Canada,	A217-10	AN38020001
Nashuatec D4850		S. America		
Savin 9950DP	120 / 60	USA	A217-15	9A78020001
Ricoh Aficio 500	120/60	USA, Canada,	A217-17	A7608020001
		S. America		
Gestetner 2850e	220, 230, 240/	Europe, Asia	A217-22	AN28020001
Nashuatec D4850	50, 60			
Rex Rotary 8250E				
Infotec	220, 230, 240/	Europe	A217-26	3P70280001
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Europe	A217-27	A7608030072
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Asia	A217-29	A7608020101
	50, 60			

ገጢሰ	儿儿
](K)(I)[[]

PAGE: 1/1

Model: AD50 Date				e: 30-Apr-98	No: 6
Modified Article: Hard Disk			Prepared by: A. Sasaki		
From: QAC Field Information Dept.					
Reason for	Parts catalog correction	☐ Vendor change ☐ To meet standards			neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability☑ Other		prove reliability ()	
	☐ Part standardization				

The hard disk has been changed because the production of the old one is discontinued. The capacity of the hard disk has been changed from 1.7 GB to 1.05 GB.

Since the capacity of the hard disk used in this machine is 1.0 GB, it is not necessary to change any SP modes nor any ROMs even if the hard disk is replaced with a new one.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
A1337885	A1337892	Hard Disk 1.05 GB	1	O/O	81	2	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120/60	USA, Canada,	A217-10	AN37110001
Nashuatec D4850		S. America		
Savin 9950DP	120 / 60	USA	A217-15	9A77110001
Ricoh Aficio 500	120/60	USA, Canada,	A217-17	A7607110001
		S. America		
Gestetner 2850e	220, 230, 240/	Europe, Asia	A217-22	AN27110001
Nashuatec D4850	50, 60			
Rex Rotary 8250E				
Infotec	220, 230, 240/	Europe	A217-26	3P701170001
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Europe	A217-27	A7607110521
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Asia	A217-29	A7607110921
	50, 60			

	ПП
U(U)	П

Model: AD50

Reason for

Modification:

Modified Article: Fusing Unit

From: QAC Field Information Dept.

Modification Bulletin

Date: 31-May-9)8	No: 7
Prepared			l by: A.	Sasaki
☐ Vendor change			☐ To n	neet standards
☐ To improve reliability			()

PAGE: 1/1

The following parts have been registered as service parts.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Please add them to your parts catalog.

Old part	New part	Description		Int	Page	Index	Note
number	number						
	A2177105	Fusing Unit – 115V	1		57	#	
	A2177405	Fusing Unit – 230V	1		57	#	

			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120/60	USA, Canada,	A217-10	
Nashuatec D4850		S. America		
Savin 9950DP	120 / 60	USA	A217-15	
Ricoh Aficio 500	120/60	USA, Canada,	A217-17	
		S. America		
Gestetner 2850e	220, 230, 240/	Europe, Asia	A217-22	
Nashuatec D4850	50, 60			
Rex Rotary 8250E				
Infotec 5511DZ	220, 230, 240/	Europe	A217-26	
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Europe	A217-27	
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Asia	A217-29	
	50, 60			

	ПП
U(U)	П

Model: AD50

Reason for

Modification:

Modified Article: Parts Catalog Correction

From: QAC Field Information Dept.

Modification Bulletin

Date: 31-May-9			8	No: 8
Prepared			l by: S.	Tomoe
☐ Vendor change			☐ To m	neet standards
☐ To improve reliability			()

PAGE: 1/1

The following part number should be corrected. Please correct your part catalog.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part number	New part number	Description	Qty	Int	Page	Index	Note
A1343164		Bracket - Toner Holder	1		45	17	

Other

			14541	DDODLIGTION
			JAPAN	PRODUCTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120/60	USA, Canada,	A217-10	
Nashuatec D4850		S. America		
Savin 9950DP	120 / 60	USA	A217-15	
Ricoh Aficio 500	120/60	USA, Canada,	A217-17	
		S. America		
Gestetner 2850e	220, 230, 240/	Europe, Asia	A217-22	
Nashuatec D4850	50, 60			
Rex Rotary 8250E				
Infotec 5511DZ	220, 230, 240/	Europe	A217-26	
	50, 60			
Ricoh Aficio 500	220, 230, 240/	Europe	A217-27	
	50, 60	-		
Ricoh Aficio 500	220, 230, 240/	Asia	A217-29	
	50, 60			

	ПП
)[[]

PAGE: 1/2

Model: AD50			Date	e: 31-Aug-98	No: 9
Modified Article: P	ick-off Pawl Pressure Spring			Prepared by: E.F.	ukuyama
From: QAC Field Info	ormation Dept.				
Reason for	□ Parts catalog correction	☐ Vend	or ch	ange 🔲 To n	neet standards
Modification:	☐ To facilitate assembly	☐ To im	prove	e reliability ()
	☐ Part standardization	Other	•		

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AA066250	AA066311	Pressure Spring	1	X/O	53	12	
AA066251	AA066312	Pressure Spring	1	X/O	53	14	

To reduce the wear on the drum caused by the pick-off pawls, the pressure applied to the pick-off pawls by the pressure springs has been reduced.

To differentiate between the new and old parts, the new parts are coloured black.



Model: AD50 Date: 31-Aug-98 No: 9

PAGE: 2/2

			JAPAN PRODUCTION		
MODEL NAME	V/ Hz	DESTINATIO N	CODE	SERIAL NUMBER	
Gestetner 2850e nashuatec	120/60	USA, Canada, S. America	A217- 10	AN38070001	
Savin 9950DP	,120/ 60	UAS	A217-15	9A78070001	
RICOH Aficio 500	120/60	USA, Canada, S. America	A217- 17	A7608070001	
Gestetner 2850e Nashuatec D4850 Rex Rotary	220,230,240/ 50, 60	Europe, Asia	A217- 22	Aug. 98 production	
Infotec 5510DZ	220,230,240/ 50, 60	Europe	A217- 26	3P70780001	
Ricoh Aficio 500	220,230,240/ 50, 60	Europe	A217- 27	A7608070201	
Ricoh Aficio 500	220,230,240/ 50, 60	Asia	A217- 29	A7608080055	



PAGE: 1/2

MB Correction

Reissue date: 15-Sep-98

The items in bold italics have been corrected.

Model: AD50			Date: 31-Aug-98		No: 10		
Modified Article: Operation Panel ROM Modification				Prepared by: E.Fukuyama			
From: QAC Field Information Dept.							
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☐ Part standardization	☐ Vend☐ To im☐ Other	prove	ange	neet standards)		

Old part	New part	Description	Qty	Int	Page	Index	Note
number	Number						
A2177704	A2177770	Operation Panel Board	1	X/O	15	18	
A2177731	A2177747	ROM : Operation Panel	1	X/O	15	17	

Symptom

The image on the touch screen is blurred.

Cause

The background pattern for the touch screen is not suitable. Blurring occurs when there are small letters or the letters are bunched together.

Countermeasure

The ROM for the operation panel board has been modified so that the background pattern is now different. The new ROM has been used starting from the June production runs.



Model: AD50

Modification Bulletin

Date: 31-Aug-98 No: 10

PAGE: 2/2

	ICTION			
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
RICOH Aficio 500	120V/ 60Hz	USA, CANADA, S. AMERICA	A217- 17	A7608060001
RICOH Aficio 500	240,220,240 V / 50, 60 Hz	EUROPE, ASIA	A217- 27	A7608060151
RICOH Aficio 500	240,220,240 V / 50, 60 Hz	ASIA	A217- 29	A7608060226
Savin 9950DP	120V/ 60 Hz	USA	A217- 15	9A78060001
Gestetner 2850e	120V/60Hz	USA, CANADA, S. AMERICA	A217- 10	AN38070001
Nashuatec D4850	120V/ 60Hz	USA, CANADA, S. AMERICA	A217- 10	AN38070001
Gestetner 2850e	240,220,240 V / 50, 60 Hz	EUROPE, ASIA	A217- 22	3P70680001
Nashuatec D4850	240,220,240 V / 50, 60 Hz	EUROPE, ASIA	A217- 22	3P70680001
Rex Rotary 8250E	240,220,240 V / 50, 60 Hz	EUROPE ,ASIA	A217- 22	3P70680001
Infotec 5511DZ	240,220,240 V / 50, 60 Hz	EUROPE	A217- 26	3P70680001

	儿儿
แ็ดแ)[[]

PAGE: 1/1

Model: AD50 Date			e: 30-Sep-98	No: 11	
Modified Article: Main Switch			Prepared by: E.Fukuyama		
From: QAC Field Inf	ormation Dept.				
Reason for	Parts catalog correction	☐ Vend	lor ch	ange	neet standards
Modification:	☐ To facilitate assembly	⊠ To im	nprove	e reliability ()
	☐ Part standardization	☐ Othe	r		

Use of a neutral cleaner to clean the main switch may weaken the switch and result in damage. To prevent damage to the main switch, the materials of the switch have been changed.

Old part number	New part Number	Description	Qty	Int	Page	Index	Note
12042421	12042467	Main Switch	1	0/0	79	113	

			JAPAN PRODU	ICTION
MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Gestetner 2850e	120V/60Hz	USA, CANADA,	A217- 10	AN38070001
Nashuatec D4850		S. AMERICA		
Savin 9950DP	120V/ 60 Hz	USA	A217- 15	9A78060001
RICOH Aficio 500	120V/ 60Hz	USA, CANADA, S. AMERICA	A217- 17	A7608060001
Gestetner 2850e		EUROPE, ASIA	A217- 22	3P70680001
Nashuatec D4850	240,220,240			
Rex Rotary 8250E	V / 50, 60 Hz			
Infotec 5511DZ	240,220,240 V / 50, 60 Hz	EUROPE	A217- 26	3P70680001
RICOH Aficio 500	240,220,240 V / 50, 60 Hz	EUROPE, ASIA	A217-27	A7608060151
RICOH Aficio 500	240,220,240 V / 50, 60 Hz	ASIA	A217- 29	A7608060226

	ПП
U(U)	П

PAGE: 1/1

Model: AD50			Date	Date: 15-Feb-99		No.: 12	
Modified Article: T	erminal			Prepared	by: M.	Ishihara	
From: GTSS Field Ir	nformation Dept						
Reason for	Parts catalog correction	⊠ Vend		· ·	☐ To n	neet standards	
Modification:	☐ To facilitate assembly ☐ Part standardization	☐ To im	•	e reliability	(,	

The old part became unavailable at the previous vendor. So the vendor was changed and the part number was changed accordingly.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
11010475	A2174085	Terminal	1	O/O	57	104	

$\Pi \cap$	ጋ(0)	П
ЦU	贤(0)	빏

PAGE: 1/1

Model: AD50			Date	e: 31-Mar-9	No.: 13	
Modified Article:	odified Article: Pick-off Pawl Pressure Spring om: GTSS Field Information Dept		Prepared by: E. Fu		Fukuyama	
From: GTSS Field	Information Dept					
Reason for	□ Parts catalog correction	☐ Vendo	r cha	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To imp	rove	e reliability	()
	☐ Part standardization	☐ Other				

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
AA036311	AA066323	Pressure Spring: Front	1	X/O	53	12	
AA066312	AA066324	Pressure Spring: Rear	1	X/O	53	14	

To reduce the wear on the drum caused by the pick-off pawls, the tension of the pressure spring of the pick-off pawl has been changed from 98mN to 40mN. The old part is black while the new part is silver. Since further production of the AD50 is not planned, the modification only relates to service parts.

Model: AD50			Date	e: 30-Apr-99	epared by: E. Fukuyama		
Modified Article: D	Ouplex Guide Plate			Prepared	by: E.	Fukuyama	
From: Technical Se	rvice Dept., GTS Division						
Reason for	Parts catalog correction	☐ Vendoi	r cha	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly		rove	e reliability	()	
	☐ Part standardization	Other					

To prevent paper jams in the duplex unit, a mylar has been added to the duplex guide plate. Due to this modification, the part number has been changed.

Symptom

After paper has been stacked in the duplex unit, paper jams occur when the paper is fed back into the machine.


Cause

The mylar on the duplex guide plate slips downward.

Countermeasure

To prevent the mylar from shifting downward, a reinforcement mylar has been added.

Old part	New part	Description	Qty	Int	Page	Index	Note
Number	Number						
A1344662	A2174517	Duplex Guide Plate	1	X/O	65	25	
	A2174695	Reinforcement Mylar	1	X/X	65	50	



When installing the reinforcement mylar to prevent occurrences of this problem, please refer to the installation procedures shown on the next page.




PAGE: 2/2

Model: AD50 Date: 30-Apr-99 No.: MA217014

Reinforcement Mylar Installation Procedures

If the reinforcement mylar is not properly attached, the effectiveness of this modification is adversely affected.


1. Before attaching the reinforcement mylar, clean the guide plate with alcohol.



2. After the guide plate has completely dried, align the bottom of the guide plate and the bottom of the reinforcement mylar.

Note:

- ① Make sure that the mylar does not protrude beyond the edges of the guide plate
- 2 Make sure that there are no air bubbles under the mylar.
- 3After attaching the mylar, press down hard on the mylar to make sure that it is firmly attached.



$\Pi \cap$	ጋ(0)	П
ЦU	贤(0)	빏


PAGE: 1/1

Model: AD50			Date	e: 31-May-9	9	No.: MA217015
Modified Article: F	Paper Feed Unit - Lower			Prepared	by: E.	Fukuyama
From: Technical Se	rvice Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To im	nprov	e reliability	()
	☐ Part standardization	☐ Othe	r			

The following parts have been added. Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	A1342750	Paper Feed Unit – Lower	1		19	41	

5.TRAY PAPER FEED (A217)






PAGE:	1	/1
-------	---	----

Model: AD50 Date				e: 15-Sep-9	9	No.: MA217016
Modified Article:	Bracket: Original Size Sensor	Prepared	by: E.	Fukuyama		
From: Technical S	ervice Dept., GTS Division					
Reason for	Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
		☐ To improve reliability		e reliability	()
		Other	r			

The following part has been registered as a service part. Please add this to your parts catalog.

Part number	Description	Q'ty	Page	Index
A130 1828	Bracket - Original Size Sensor	1	37	21







PAGE: 1/1

Model: AD50		e: 15-Oct-99	9	No.: MA217017		
Modified Article: ⊦	larness and LD Unit	Prepared	by: E.	Fukuyama		
From: Technical Se	rvice Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
Modification:		☐ To im	prove	e reliability	()
	☐ Part standardization	☐ Other				

An error has been discovered in the parts catalogue. Please delete both index number 3 on page 37 (A2175392 - Harness - Polygon Mirr) as well as the corresponding part in the illustration on page 36. This part is actually included in an assembly listed on page 41.

The assembly is comprised of this small part mentioned above, a relay connector and a harness that is listed on page 41 as: Index number 6, P/N A2175392, Harness - LSD. In the corresponding illustration on page 41, please draw in the part mentioned above (which was listed on p.37 as index no.3) so that it appears attached to the relay connector of the harness already in the illustration (i.e. index no.6, A2175392).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2175392	Delete	Harness – Polygon Mirr	1->0		37	3	

The illustration does show the harness connected to the LD Unit on page 40, but the harness is not included under parts number A2172085. The part number for the LD Unit harness is mentioned under index number 5 on page 37 (A1337774).




PA	GE:	1/1

Model: AD50 Date				e: 15-Dec-9	9	No.: MA217018
Modified Article:	Light Filter-G530/G533	Prepared	by: E.F	- ukuyama		
From: Technical S	Services Dept., GTS Division					
Reason for	☐ Parts catalog correction	☐ Vendo	or ch	ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		prove	e reliability	()	

The following part has been added as a service part. Please add this to your parts catalog.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	AA011041	Light Filter-G530/G533	1	1	37	22	



በመጠ	ПП

Modification:

Modification Bulletin

Model: AD50			e: 06-Sep-0)1	No.: MA217019
Modified Article:	Electrical Spring Clutch	Prepared	by: E.	Fukuyama	
From: Technical S	ervices Dept., GTS Division				
Reason for	Parts catalog correction		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improv	e reliability	()

PAGE: 1/1

The following part has been changed due to discontinued production:

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX210046	AX210082	Electrical Spring Clutch	1-1	0/0	71	8	

☐ Other

RICOH

Modification Bulletin

PAGE: 1/1

Model: AD50 Da					06	No.: MA217020
Modified Article:	Ball Bearing	Prepared	l by: K. Ha	mada		
From: 1st Tech. Su	ipport Sec. Service Support [Dept.				
Reason for	☐ Parts catalog correction		cha	ange	Other	
Modification:	☐ To facilitate assembly	☐ To impro		e reliability	☐ To me	et standards
	Part standardization [afety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AE030003	A2323559	Ball Bearing – 30x42x7	2-2	0/0	57	14	

Change/Reason: Vendor change. (The old part was discontinued from production).