Reissued: 06-Feb-15

RICOH

Model: MET-C1ab/ MET-C1cde/MET-C1yz/MET-C1yz_SOP/ Z-C2/Z-C2_SOP/ CH-C1 Office/ <i>OR-C2/Cor-C1/Cor-C1_SOP/K-C4</i> / <i>Gim-MF1a/Gim-MF1b/Gim-MF1d/Gim-P1c/Gim-P1d/BR-C1/</i> <i>Leo-C1/Leo-P1</i>	Date: 13-Mar-14	No.: RD147059a
DTP Deigous		

RTB Reissue

The items in *bold italics* have been corrected or added.

Subject: Firmware	Prepared by: N. Yoshida		
From: 1st Tech Se			
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 Part information Electrical Transmit/receive Other (Firmware) 	 Action required Service manual revision Retrofit information Tier 2

Important Information about Normal/Smart Panel Firmware Updates

- When updating machine firmware, make sure **NOT** to install Smart Panel supported firmware on a machine with a normal operation panel (and vice-versa). If you do, the machine may not function as designed and product warranty may not apply.
- To avoid this, when updating the firmware, make sure that the numbers next to "NEW" and "ROM" are **the same** on the operation panel.
- If you install the wrong firmware, repeat the update procedure and check the numbers mentioned above.

This RTB has been issued to announce the firmware release information for the **SD card for Fonts Type D.**

Version	Program No.	Effective Date	Availability of RFU
0.00	M1095277	1st Mass production	Available

Note: Definition of Availability of RFU via @Remote "Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected	
0.00	1st Mass production	1st Mass production

Technical Bulletin

PAGE: 1/2

Model: Gim-P1a Dat			te: 23-Feb	-15	No.: RM171002	
Subject: Service manual revision			Prepared by: T.Suzuki			
From: 3rd Tech.	Support Sec. Service Support I	Dept,				
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info Electrica Transmi	al		—	required e manual revision it information

Important Information about the Debug Tool

• How to get the debug tool:

The debug tool is located on the GKM server ([TA] Troubleshooting Assistant: Support Utilities).

Answer: ID 183038 FAQ: ID 183038

• How to use the debug tool:

The PDF manual for the debug tool is located on the GKM server ([TR] KIBO Controller Model's Technical Reference) at the following URL: KIBO_Controller Debug_Log collection_Technical _Reference_v1.0.ppt

Answer: ID 191534 FAQ: ID 191534

• Service Manual revision:

The Service Manual for the KIBO controller based Gimlet was revised (see next page).

Technical Bulletin

Model: Gim-P1a

Date: 23-Feb-15

No.: RM171002

Service Manual revision

"gawk" was deleted from the list circled in red.

Note: This is because gawk is included in the dbgmon.exe file.

Debug Log

Overview

To check the machine's operational status, obtain the following log entries from the machine.

Log entries to obtain

- · Log entries on the machine operation and parameters.
- · Log entries on the changes to the machine status
- · Only log entries for the controller (not including log entries for the engine)

Output format

Text format

What you need

To obtain log entries from PC

- A laptop PC with a compatible OS
- PC console (dbgmon.exe)
- gawk

Technical Bulletin

Reissued: 25-Jun-15

Model: Gim-P1a

Date: 09-Mar-15

No.: RM171003a

RTB Reissue					
Subject: Dirty reverse side of printing sheets			Prepared by: J.Kitagawa		
From: 1st Tech S	Service Sect., MFP/P Tech Ser	vice Dept.			
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part informat Electrical Transmit/rec Other (Action required Service manual revision Retrofit information Tier 2 	

Change: The shapes and/or material of the following parts were changed.


- 1. The maximum height of the guide rib of the exit guide stay was shortened.
- 2. The material and shape of the electrode plate cover was changed.
- 3. The shape of the transfer stay was changed as shown in the illustration.

Reason: To further minimize staining on the printed paper.

Note: The reverse side of the printed sheets may get dirty when the sheets pass through the area indicated in the illustration.


Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
M1603861	M1603865	COVER:ELECTRODE PLATE:SEPARATION:2	1 - 1	X/X	18	13	X/O as a
M1603851	M1603866	GUIDE:EXIT:STAY:TRANSFER:2	1 - 1	X/X	18	3	set
M1603850	M1603870	STAY:TRANSFER	1 - 1	X/X	18	2	

Important: These three parts need to be installed **together as a set**.



Technical Bulletin

Reissued: 25-Jun-15



Mass production

MODEL NAME	DESTINATION	CODE	SERIAL NUMBER	Producted Date
SP3600DN	NA	M171-17	T635H103664	2015.01.23
	CHN	M171-21	T634HC00701	2014.12.11
	EU/AA	M171-27	T634HC00001	2014.12.10



Model: Gim-P1a Dat			ate: 9-Mar-	15	No.: RM171004	
Subject: Part c	atalog correction			Prepared	d by: J.Kita	agawa
From: 3rd Tech	Service Sect., MFP/P Tech Se	rvice Dept.				
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part infor Electrica Transmit	I			required e manual revision t information

Change: The following part was deleted. Instead, the components are available as individual service parts.

Reason: Difficulty in supplying the operational panel as an assembled unit.

Note: The individual parts (indexes 2-10, 101) are still available.

Incorrect part number	Correct part number	Description	Q'ty	Page	Index	Note
M1711411	-	OPERATION PANEL:ASS'Y	1	4	1	
M1711413	-	OPERATION PANEL:CHN:ASS'Y	1	4	1	For China




Model: Gim-P1a

Date: 9-Mar-15

No.: RM171004

2. Operation Panel



Technical Bulletin

PAGE: 1/1

Model: Gim-P1a Date: 19-Ma			Date: 19-Mar-1	5	No.: RM171006
Subject: Importa	Prepared by: T.Suzuki				
From: 3rd Tech. Support Sec. Service Support Dept.					
Classification:	Mechanical	 Part info Electrica Transmi Other (al [] t/receive []	Servic	required e manual revision it information

Service Manual Revision

An important note was added.

Replacement and Adjustment, Electrical Components, Controller board Pg. 95

IMPORTANT:

Do the following to reconfigure ID2 when you replace the KIBO controller board.

- Configuring ID2
- 1. Access SP mode from the operation panel
- 2. Execute SP5-870-003 (Common KeyInfo Initialize)
- 3. Reboot the machine.

• Verifying configuration results

- 1. Access SP mode.
- 2. Check the configuration results inside the following SPs.
 - SP5-811-002 (Machine serial: Display) ID2 has been configured correctly if the display is in the following format:
 - SP5-811-003 (Enter SP mode on Operation panel: ID2 Code Display)
 ID2 has been configured correctly if the display is in the following format:
 ■■■□□□□□□▲▲▲▲▲▲▲

Product code (3 digits)
Spaces (6)
A A A A A A : Serial number (8 digits)

Note: SP values set with the KIBO controller are **not** carried over when the controller board is replaced.

Technical Bulletin


PAGE: 1/1

Model: Gim-P1a			Da	Date: 26-May-15 No.: RM1710			
Subject: SEAL:STAY:FRAME:REAR:B				Prepared by: H.K.			
From: 1st Tech S	Service Sect., MFP/P Tech Service	vice Dept.					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info Electrica Transmi	al		Servic	required e manual revision it information	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	M1601047	SEAL:STAY:FRAME:REAR:B	0 - 2		34	*39	

*: New index

Change/Reason: The part number was missing from the Parts Catalogue.



Technical Bulletin

PAGE: 1/2


Model: Gim-P1a Dat			ate: 27-Mag	y-15	No.: RM171008
Subject: LED Leve	er Decal		Prepared	by: H.K.	
From: 1st Tech Service Sect., MFP/P Tech Service Dept.					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part inform			required e manual revision it information

Old part New part Description number number	Q'ty	Int	Page	Index	Note
M1601934 DECAL:OPERATE:LEVER:LED	0 - 1		8	*20	

*: New Index

Change: An instructional decal for the LED lever was added.

Reason: To facilitate easier operation of the LED lever.



Model: Gim-P1a

Date: 27-May-15

No.: RM171008

SHINDO Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Savin SP 3600DN	115/60	USA	M171-17	T634HCxxxxx
Lanier SP 3600DN				
Ricoh SP 3600DN				
Gestetner SP 3600DN	220/50	Europe, Asia	M171-27	T634HCxxxxx
Nashuatec SP 3600DN				
Rex Rotary SP 3600DN				
Lanier SP 3600DN				
Ricoh SP 3600DN				
Ricoh SP 3600DN	220/50	China	M171-21	T634HCxxxxx

Technical Bulletin

PAGE: 1/1

Model: Gim-P1a Dat				te: 25-Jun-	·15	No.: RM171009
Subject: PCU:EXP:ASS'Y					d by: H.K.	
From: 1st Tech S						
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part infor Electrical Transmit	I		Servic	required e manual revision it information

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
M1600141		PCU:EXP:ASS'Y	1 - 0		6	23	

Change: The PCU: EXP:ASS'Y was deleted.


Reason: This is not registered as a spare part (only as a Supply item).

Technical Bulletin

Model: Gim-P1a			ate:	25-Jun-15	No.: RM171010		
Subject: Part catalog correction "Fusing Section 1" Prepared by: J.Kitagawa							
From: 1st Tech S	Service Sect., MFP/P Tech Servic						
Classification:		Part inform	natio		n required		
	Mechanical	Electrical		Electrical		Servic	ce manual revision
	Paper path	Transmit/rec		ve 🗌 Retroi	fit information		
	Product Safety	Other ()	🗌 Tier 2			

Change: Geometry of these parts has changed.

Incorrect part number	Correct part number	Description	Q'ty	Page	Index	Note
-	M1604138	GROUND PLATE:HOT ROLLER	1	20	32	
-	M1604139	RESISTOR:1GOHM	1	20	33	
-	M1604141	WASHER:DIA10.1:DIA6.0:0.6T	1	20	34	



Technical Bulletin

PAGE: 1/1

Model: Gim-P1 a			Date: 26-Ju	n-15	No.: RM171011
Subject: Part c	atalog correction "Exterio	Prepare	d by: J.Kita	agawa	
From: 1st Tech S	Service Sect., MFP/P Tech Ser				
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part inform			required e manual revision t information

Change: The following part has been added.

Old part number	New part number	Description	Q'ty	Page	Index	Note
-	AA000267	DECAL:POWER SOURCE:EARTH:I-GRAY:ABS	1	2	12	For EU Only

Technical Bulletin

PAGE: 1/1

Model: Gimlet-P1a			Dat	te: 21-Jul-	15	No.RM171012
Subject: Part catalog correction "Paper Feed 1"					d by: N.Ya	asuda
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info	al		Servic	required e manual revision it information

Change: The following part number was corrected.

Incorrect part number	Correct part number	Description		Page	Index	Note
M1602620	M1712620	HOLDER:FRICTION PAD:ADHESION	1	12	13	

6. Paper Feed 1

Index No.	Part No.	Description	Q'ty Per Assembly
1	M1712550	PAPER TRAY:REAR:250 SHEET FEED UNIT:ASS'Y	1
2	M1712560	END FENCE:250 SHEET FEED UNIT:ASS'Y	1
3	M1712666	SHEET:SPONGE:SIDE FENCE:250 SHEET FEED UNIT	1
4	M0752610	COMPRESSION SPRING:LOCK:SIDE FENCE	3
5	M1602563	LEVER:LOCK:END FENCE	1
6	M1602572	DECAL:OPERATION INSTRUCTIONS:TRAY:REAR	1
7	M1712600	PAPER TRAY:FRONT:250 SHEET FEED UNIT:SUB-ASS'Y	1
8	B0902869	GEAR:16Z	1
9	M1712602	SHEET:HOLDER:250 SHEET FEED UNIT:FRONT	1
10	M1712605	GUIDE:PAPER TRAY:250 SHEET FEED UNIT:FRONT	1
11	M1712606	INDICATOR:PAPER VOLUME SENSOR:PAPER TRAY:250 SHEET FEED UNIT	1
12	M0212609	STOPPER:CASSETTE	2
13	M1602620	HOLDER:FRICTION PAD:ADHESION	1
14	M1602623	COMPRESSION SPRING:SEPARATION	1
15	M1602630	TRAY BOTTOM PLATE: ADHESION	1
16	M1712627	TENSION SPRING: TRAY BOTTOM PLATE: 250 SHEET FEED UNIT	2
17	M1712640	SIDE FENCE: RIGHT: 250 SHEET FEED UNIT: ASS'Y	1
18	M1602655	LEVER:LOCK:SIDE FENCE:TRAY	1
19	M1602641	HOLDER:PINION	1
20	M1712660	SIDE FENCE:LEFT:250 SHEET FEED UNIT:ASS'Y	1
21	GA063084	COMPRESSION SPRING:AUXILIARY:SIDE FENCE	2
22	M1602668	ARM:TRAY BOTTOM PLATE	2
23	M1602680	DIAL:PAPER SIZE SENSOR:TRAY:CHN:ASS'Y	1
	M1602687	DIAL:PAPER SIZE SENSOR:TRAY:EXP:ASS'Y	1
24	M1602681	DECAL:DIAL:PAPER SIZE SENSOR:TRAY:CHN	1
	M1602682	DECAL:DIAL:PAPER SIZE SENSOR:TRAY:EXP	1
25	M1602683	CLICK:DIAL:PAPER SIZE SENSOR:TRAY	1
26	M1602631	GRIP:PAPER TRAY	1
27	M1712691	COVER:TRAY:250 SHEET FEED UNIT:FRONT	1
28	M1602693	DECAL:PAPER SET DIRECTION	1
29	M1602590	TIGHTENER:SPRING PLATE:TRAY:ASS'Y	2
30	M1712607	SEAL:TRAY:REAR:EU,CHN:250 SHEET FEED UNIT	2

Index No.	Part No.	Description	Q'ty Per Assembly
30	M1712608	SEAL:TRAY:REAR:NA:250 SHEET FEED UNIT	2
31	GF013001	PAD:BASE	1
32	M1712675	SEAL:SIDE FENCE:LEFT REAR	1
101	04503008N	TAPPING SCREW:3X8	
102	04503010N	TAPPING SCREW:3X10	
103	04543006Q	TAPPING SCREW:3X6	

Technical Bulletin

Model: GIM-P1a Dat			te: 23-Jul-	15	No.:RM171013			
Subject: Poor fus		Prepared	d by: Y. G	iaman				
From: 3rd Tech S	From: 3rd Tech Service Sect., MFP/P Tech Service Dept.							
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 Part info Electrica Transmit Other (al		Servic	required e manual revision it information		

SYMPTOM


Toner is not properly fixed when printed on a recommended type of plain paper.

CAUSE

The lever is set to the low position for envelope printing.

SOLUTION

Raise the lever to the high position.



Note:

Lower this lever only when printing on envelopes.

After installing the device or replacing the fusing unit, make sure to raise the lever.

Technical Bulletin

Reissued: 13-Mar-17

Model: Gim-P1a

Date: 13-Nov-15

No.: RM171014a

RTB Reissue


The items in *bold italics* have been corrected or added.

Subject: Part Catalog correction : Transfer Guide			Prepared by: H. Morishima			
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.						
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 Part information Electrical Transmit/rec Other ([Action required Service manual revision Retrofit information Tier 2 		

Old part	New part	Description	Q'ty	Int	Index	Note
number	number					
M1603850	M1603870	STAY:TRANSFER	1	X/X	2	
	M1603877	SPONGE:TRANSFER/	1	X/X	16	
		SEPARATION UNIT:LEFT				
	M1603878	SPONGE:TRANSFER/	1	X/X	17	
		SEPARATION UNIT:RIGHT				
	M1603879	SHEET:TRANSFER UNIT:	2	X/X	18	
		TONER CATCHPAN				
M1603881	M1603880	GUIDE:TRANSFER ROLLER:	1	X/X	15	
		CLICK:ASS'Y				
M1603854	M1603874	GUIDE:TRANSFER ROLLER:	1	X/X	6	
		CLICK				
M1603855	M1603875	SHEET:GUIDE:TRANSFER	1	X/X	7	
		ROLLER:CLICK				



Reissued: 13-Mar-17



Change

- A cut-out was applied to the right and left edges of the front paper guide of the transfer roller.
- Sponges and sheets were added to the transfer stay.

Reason


To avoid black band stains caused by dropped toner on the front paper guide of the transfer roller.

With this modification, dropped toner goes around the right and left edges of the front paper guide and accumulates on the transfer stay.

Old

Technical Bulletin

Reissued: 13-Mar-17



New



IMPORTANT

This modification has compatibilities. Since the old transfer stay cannot be replaced in the field and the stay of the old type is compatible only with the front paper guide of the old type, when replacing the front paper guide of an old machine, make sure to procure the old type.

This modification allows usage of the PCDU even after exceeding 23K by modifying SP5-931-003*. However, DO NOT modify this SP on machines manufactured prior to this modification, because the front paper guide and transfer stay are both of the old type and will cause toner accumulation on the front paper guide when reaching approximately 23K.

Cut-in serial number:



Reissued: 13-Mar-17

Model: Gim-P1a	Date: 13-Nov-15	No.: RM171014a
----------------	-----------------	----------------

Shindoh (China) Production

MODEL NAME	DESTINATION	CODE	SERIAL NUMBER
Ricoh SP3610DN	USA	M171-17	T636H100070
	Europe, Asia	M171-27	T635HA01189

Technical Bulletin


PAGE: 1/1

Model: Gim-P1a			Da	te:12-Jan-1	6	No.: RM171015
Subject: Parts Ca Frame	atalog Correction - New Guides		Preparec	l by: Nori	to Yasuda	
From: 1st Tech	Service Sec. MFP/P Tech Se	ervice Dept	t.			
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info	al			required e manual revision t information

The following parts were registered as service parts.

Old part number	New part number	Description	Q'ty	Page	Index	Note
number	number					
-	M1601920	GUIDE:PCU:LEFT UPPER	1	42	41	
-	M1601921	GUIDE:PCU:RIGHT UPPER	1	42	42	

21. Main Frame Section



Technical Bulletin


PAGE: 1/1

Model: Gim-P1a			Dat	e: 17-Feb-	-16	No.: RM171016
Subject: Part Cat section	alog Correction -Missing p/n in		Prepared	d by: Nor	ito Yasuda	
From: 1st Tech	Service Sec. MFP/P Tech Se	ervice Dep	t.			
Classification:	Mechanical	 ☑ Part info ☑ Electrica ☑ Transm ☑ Other (al		Servic	required e manual revision it information

Part number of the upper cover was missing from the parts catalog and its index number was incorrect. Please make the following correction to your part catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	M1711231	COVER:UPPER:P1_A	1		1	12	

1. Exterior



Technical Bulletin

Model: Gim-P1/M1			Date: 9-May-16		No.: RM158035
Subject: Troublest	Prepared by: K.Nakano				
From: Group 2, 1st Field Quality Management Dept.					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 Part inform Electrical Transmit/re Other (Action re Service n Retrofit in Tier 2 	nanual revision

SYMPTOM

Multi-feeds occur under the following conditions:

- Paper is loaded in the tray before the tray is empty, or
- The paper used has relatively high surface friction characteristics

CAUSE

- Oil from the hands of the operator is absorbed by the paper when loaded. This creates high friction between the bottom sheet of this stack and the top sheet of the stack already in the tray. As a result, these sheets tend to stick together when fed.
- Paper whose surface friction characteristics are relatively high will tend to stick together when fed.

SOLUTION

Install Spring #1 mentioned below. If this is not successful, install Spring #2.

Note:

- These springs work to increase the paper separation pressure.
- The pressure of the spring already installed is about 3.1N. When Spring #1 or #2 is installed, paper non-feeds may occur or the sound of the pick-up roller picking the paper may be audible.

Spring #1

P/N	Description	Pressure	Color
M1589002	SEPARATION SPRING 4N GIMLET	4N	Silver

Spring #2

P/N	Description	Pressure	Color
M1589003	SEPARATION SPRING 5N GIMLET	5N	Black

Technical Bulletin


PAGE: 1/2

Model: Gim-P1a			Dat	e: 7-Oct-1	6	No.: RM171017
Subject: Catalog correction : Electrical Components			Prepared	d by: Y. G	aman	
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.						
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part infor Electrical Transmit	I			required e manual revision t information

Change: The following part numbers were corrected.

Incorrect	Correct	Description	Q'ty	Page	Index	Note
part number	part number					
M1605508	M1715010	PCB:BCU:ASS'Y	1	32	2	
M1715010	-		1	32	3	
M1605506	M1605515	GROUND PLATE: POWER PACK	1	32	11	
-	M1605506	BRACKET: POWER PACK	1	32	23	

16. Electrical Components Section



Technical Bulletin

PAGE: 2/2

Model: Gim-P1a

Date: 7-Oct-16

No.: RM171017

16. Electrical Components Section

Index No.	Part No.	Description	Q'ty Per Assembly
1	D1495686	PCB:DCSW	1
2	M1605508	COIL SPRING:TERMINAL:POWER PACK	5
3	M1715010	PCB:BCU:ASSY	1
4	AZ230267	POWER SUPPLY UNIT:DOM/NA:674.6W	1
	AZ230269	POWER SUPPLY UNIT:EU/AA/CHN:009.9W	1
5	AZ320187	POWER PACK:CDVT:GIM	1
6	AA143592	SCREW:4X8	1
7	M1605120	PCB:SENSOR:TONER END SENSOR	1
8	M1605507	TERMINAL:POWER PACK:ASSY	1
9	M1605500	BRACKET: POWER SUPPLY UNIT	1
10	M1605501	COVER:FRONT:POWER SUPPLY UNIT	1
11	M1605508	BRACKET:POWER PACK	1
12	M1715708	PCB:CTL:KIBO:GIM-P1A:ASSY	1
13	M1715510	C/T BOX:P1A	1
14	M1715512	PANEL:C/T BOX:P1A	1
15	M1715518	BRACKET:BCU:LEFT MIDDLE	1
16	M1715519	BRACKET:BCU:LEFT LOWER	1
17	M1605555	CLAMP:TWISTLOCK	2
18	M1605022	POWER PACK:ASS'Y	1
19	M1601934	DECAL:OPERATE:LEVER:LED	1
20	M1715533	SHEET:INSULATION:KIBO	1
21	M1715534	SHEET:INSULATION:AUX:KIBO	2
22	M1715535	SHEET:INSULATION:AUX2:KIBO	1
23			

Index No.	Part No.	Description	Q'ty Per Assembly
101	11050762	CLAMP:LWS-0711A	
102	14077677	EEPROM:BR24T64-W	
103	04503008N	TAPPING SCREW:3X8	
104	04513006N	TAPPING SCREW:3X8	
105	08046123	HEXAGONAL BOLT:W/WASHER:M3X8	
106	03130030N	PAN HEAD SCREW:M3X3	

Technical Bulletin

PAGE: 1/1

Model: Gim-P1a			Dat	ate: 20-Oct-16		No.: RM171018
Subject: Manual Correction - SP Mode			Prepared by: Y. Gaman			
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.						
Classification:	TroubleshootingPart informMechanicalElectricalPaper pathTransmit/rProduct SafetyOther (al		Servic	required e manual revision it information

Service Manual Correction

Appendices > SP Mode Tables > Main SP Tables-5 > SP5-XXX (Mode)

The following note was added to SP 5-305-101.

5305	[Auto Off Set] DFU					
	Auto Off Limit Set					
5-305-101	Set Disp	C*	[0 to 1/1/1/step]			

DFU: Design or Factory Use.

Note

DO NOT change this setting.

Technical Bulletin

PAGE: 1/2

Model: Gim-P1aRS(Europe) D			Dat	ate: 15-Nov-16		No.: RM171019
Subject: Service document revision for M0AQ			Prepared	d by: Y. G	aman	
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.						
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info	al		Servic	required e manual revision it information

Gim-P1aRS (M0AQ) was added as a new model to the Gim-P1 series, targeting only the EU market.

Due to this addition, the Service Manual and TTP for M171 were revised. The description "M171" was changed to "**M171/M0AQ**" in both of these documents.

Note that the following components are unique to M0AQ and are not interchangeable with other models:

- Toner cartridge
- PCDU
- PCB

Revisions made to the Field Service Manual and Parts Catalog are as follows.

- Field Service Manual revision

P.16 Consumables for M0AQ

Item	Machine Code	Remarks	Yield
Print Cartridge SP 400E	M947-27	NEW	5,000 pages (ISO)
Print Cartridge SP 400LE	M948-27	NEW	2,500 pages (ISO)
Photo Conductor Unit SP 400	M906-04	NEW	20,000 pages (3P/J)

Model: Gim-P1cRS(Europe)

Date: 15-Nov-16

No.: RM158037

P.17 Other Yield Parts

	Yield – Condition		Compa	tibility
	Yield	Condition	User Mainten	ance Model
	(Page)		M171	M0AQ
High Yield Toner for M171	6,000	ISO	Available	N/A
Low Yield Toner for M171	3,000	ISO	Available	N/A
High Yield Toner for M0AQ	5,000	ISO	N/A	Available
Low Yield Toner for M0AQ	2.500	ISO	N/A	Available
Standard PCDU for M171	20,000	3P/J	Available	N/A
Standard PCDU for M0AQ	20,000	3P/J	N/A	Available

- Parts Catalog revision (Service parts for M0AQ)

Section	P/N	Description	Page	Index
Electrical Components	M0AQ5010	PCB:BCU:RS:ASS'Y	32	2




PAGE: 1/5

Reissued: 17-Mar-17

Model: Gim-P1a Date: 9-De		ec-16	No.: RM171020b					
RTB Reissue The items in <i>bold italics</i> were changed or added.								
-	odification Announce o abnormal substanc		Prepared	by: K. Nakano				
From: 3rd Tech Se	From: 3rd Tech Service Sect., MFP/P Tech Service Dept.							
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 ☑ Part inform ☑ Electrical ☑ Transmit/r ☑ Other (Action re	nanual revision			

SYMPTOM

Black line or white line appears on prints in the feeding direction along with unwanted toner on the charge cleaning roller at the line position.




Technical Bulletin

Reissued: 17-Mar-17

Model: Gim-P1a	Date: 9-Dec-16	No.: RM171020b
----------------	----------------	----------------

CAUSE

1. A foreign substance enters the machine via the intake fan.




2. Paper dust accumulates inside the paper path.



3. A foreign substance adheres to the paper loaded in the tray and on the bypass.



Paper dust or other foreign substance adheres to the drum, gets caught between the drum and cleaning blade, and/or chips the surface of the blade.



At such a location, the cleaning blade cannot clean toner out from the PCDU, causing a black line on prints. Gradually the unremoved toner transfers to the charge roller and charge cleaning roller. When it comes to a certain level, the charge roller cannot charge sufficiently, causing a white line on prints.

Technical Bulletin

Reissued: 17-Mar-17


Model: Gim-P1a Date: 9-Dec-16 No.: RM171020b	Model: Gim-P1a	Date: 9-Dec-16	No.: RM171020b
--	----------------	----------------	----------------


SOLUTION

On the Production Line

A filter sheet is added to prevent the entry of abnormal substances coming from the intake fan.

Inside of the right cover:





m171m0021


Old P/N	New P/N	Description	Q'ty	I/C
-	M1711227 (M1719900)*	FILTER:DUST:P1A	1	-

* For field modification only

Cut-In Serial number

P1a	: M171-17/-21/-27	: T636HA00001~
P1aRS	: M0AQ-27	: Y696HA00001~

In the Field



Old P/N	New P/N	Description	Q'ty	I/C
-	M1589900	FILTER UNIT	1	-

Remove any paper dust or other foreign substance from the paper path, paper loaded in the tray, and paper tray.



Reissued: 17-Mar-17

Model: Gim-P1a

Date: 9-Dec-16 No.: RM171020b

INSTALLATION PROCEDURE

Step	Detail	Reference
1	Take off the Velcro.	Property and the second s
2	Peel off the double-sided tape on the Velcro (A) taken off in Step 1.	A Deal lead
3	Attach (A) on the right above the inlet in the right cover.	SP 3600DN SP 3600SF SP 3610SF SP 3610SF



PAGE: 5/5

Reissued: 17-Mar-17

Model:	Gim-P1a	Date: 9-Dec-16	No.: RM171020b
4	Peel off the double-sided tape on the other Velcro.		
5	 Set the top side of the Velcro. Attach the double-sided tape on the bottom side of the Velcro. 		
6	Check that the filter fully covers the inlet.		Durnos


Technical Bulletin

PAGE: 1/4

Model: Gim-P1a Date: 9-De			ec-16	No.: RM171021	
	shooting for PCDU Line nce from intake fan.	Prepared I	oy: K. Nakano		
From: 3rd Tech Service Sect., MFP/P Tech Service Dept.					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part inform		Action red Service n Retrofit ir Tier 2	nanual revision

SYMPTOM

Black line or white line appears on prints in the feeding direction along with toner on the charge cleaning roller at the line position.




Τ	I	
	nnicai	B ulletin

Model: Gim-P1a

Date: 9-Dec-16

CAUSE

Abnormal substance comes inside from the intake fan, then it adheres on the drum. Then the abnormal substance which adheres to the drum is caught and/or chips the cleaning blade.





At such a location, the cleaning blade cannot clean toner out from the PCDU, causing black lines on prints. Gradually this toner transfers to the charge roller and charge cleaning roller. When it comes to a certain level, the charge roller cannot charge sufficiently, causing white lines on prints.

SOLUTION

A filter sheet is added to prevent the entry of abnormal substances coming from intake fan.

Inside of the right cover:





m171m0021

Old P/N	New P/N	Description	Q'ty	I/C
-	M1711227	FILTER:DUST:P1A	1	-

<u>Cut-in serial numbers</u>

P1a : M171-17/-21/-27 : T636HA00001~

P1aRS : M0AQ-27 : Y696HA00001~



Model: Gim-P1a

Date: 9-Dec-16

No.: RM171021

INSTALLATION PROCEDURE

Step	Detail	Reference
1	Pull the paper feed tray [A] out completely to detach it.	160081
2	Press the release button and open the front cover [A].	m171m0018
3	Open the rear cover [A].	m158m0011
4	Remove the four screws [A].	

PAGE: 4/4

Model	: Gim-P1a		Date: 9-Dec-16	No.: RM171021
5	Release the hooks (refer to the picture for the location of the hooks) and remove the right cover.		m171m	n0021
6	Align the cut-out portions and attach the filter to the right cover. Make sure that the surface of the filter is sufficiently tensioned.	Cut-out		Cut-out
7	Make sure there is no peeling or incomplete attachment at the edges highlighted in yellow.			
8	Re-attach the right cover and the paper feed tray.		-	

Technical Bulletin

PAGE: 1/2


Model: Gim-P1a		Date: 7-Fe	b-17	No.: RM171022	
Subject: Troublest	nooting for Paper No Feed	Prepared by: K.Nakano			
From: Printer Sec.,	MFP/P FQM Dept.				
Classification:	ation:Image: TroubleshootingImage: Part informationImage: MechanicalImage: ElectricalImage: Paper pathImage: Transmit/receiveImage: Product SafetyImage: Other (Control)			Action re Service r Retrofit ir	nanual revision

SYMPTOM

"Paper No Feed" jam occurs (Jam Code: 3, 4, 5).

CAUSE

- A) The end fence may be kicked a few notches back by the loaded paper if the fence is adjusted after the paper is loaded.
- B) The end fence may be pushed back when the paper is loaded if the catches (1) do not lock the tray extension.



CXC607



Model: Gim-P1a

Date: 7-Feb-17

No.: RM171022


SOLUTION

For cause (A):

Advise the user to fix the position of the end fence **before** loading the paper (as mentioned in the Operator's Instructions). If the user uses only A4SEF, Letter SEF, or A5 SEF, then the end fence can be fixed in place using the following screw:

P/N	Description	Necessary Q'ty
04583010N	HEXAGON HEAD TAPPING SCREW:3X10	1

Tray shown flipped back:




Options for fixing the end fence in place:



For cause (B)

Advise the user to lock the catches and **NOT** to extend the tray when loading A4-SEF or smaller paper sizes (as mentioned in the Operator's Instructions). If the user uses only A4SEF or smaller paper sizes, then the catches can be fixed in place (both sides) using the following screws:

P/N	Description	Necessary Q'ty
04583010N	HEXAGON HEAD TAPPING SCREW:3X10	4



Technical Bulletin

PAGE: 1/1


Model: Gim-P1 a	l		Dat	e: 31-Jul-1	17	No.: RM171023	
Subject: Parts Catalog Correction					Prepared by: Taiga Itoh		
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:	lassification: Troubleshooting Zert inform		orma	tion	Action	required	
	Mechanical	Electric	al		Servic	e manual revision	
	Paper path	🗌 Transm	it/rec	eive	Retrof	it information	
	Product Safety	Other ()	Tier 2		

Change: The following parts were registered as service parts.

Reason: To meet requests received from the field.

Old part	New part	Description	Q'ty	Page	Index	Note
number	number					
-	M1602749	SHEET:GUIDE:MPT:LOWER	2	13	37	
-	M1602751	SHEET:ENTRANCE:MIDDLE:ROLLER	1	13	38	
-	M1602756	INSULATING SHEET:ENTRANCE:MF	2	13	36	

5. Manual Feed Section 2



Technical Bulletin

PAGE: 1/1

Model: Gim-P1 a Da					-17	No.: RM171024		
Subject: Sevice Manual revision					Prepared by: Taiga Itoh			
From: 1st Tech. S	Support Sec. Service Support							
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info Electrica Transmit Other (ıl		Servic	required e manual revision it information		

Change/Reason: Service Manual revision

Revised "toner cartridge" to "PCDU" on <u>71</u> page of the service manual.

Before revision

7936	[PCDU Log] Displays the ID chip log data in the toner cartridge.
//00	Displays the ID chip log data in the toner cartridge.



After revision

7936	[PCDU Log]
7930	Displays the ID chip log data in the PCDU.

Technical Bulletin

Model: Gim-P1a Dat					17	No.: RM171025	
Subject: Service Manual Correction:SP3-098-001					Prepared by: Taiga Itoh		
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:	Classification: Troubleshooting Part inform Mechanical Electrical Paper path Transmit/r Product Safety Other (al		Servic	required e manual revision it information	

Change/Reason: Providing an additional explanation to service manual

Main SP Tables-3

SP3-XXX (Process)

3098	[Days Before End] Switches the near end timing: da	ys befo	ore end toner
3-098-001	Toner	E*	[0 to 2 / 1 / 1/step] 0: earlier 1: normal 2: later

"earlier" means that you are prompted 7 days (959 pages) before toner end.

"normal" means that you are prompted 5 days (685 pages) before toner end.

"later" means that you are prompted 3 days (411 pages) before toner end.

Technical Bulletin

PAGE: 1/1

Model: Gim-P1a			Date: 11-Sep-18			No.: RM171026
Subject: Manual Correction:SC277-10			Prepared by: Taiga Itoh			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	Troubleshooting	Part info	ormat	tion	Action	required
	🗌 Mechanical	Electrica	al		Servic	e manual revision
	Paper path	🗌 Transmi	it/rec	eive	Retrofi	it information
	Product Safety	🗌 Other ()	Tier 2	

Change/Reason: Adding explanations to service manual

SC No.	Level	Error Name/Error Condition/Major Cause/Solution			
	LEDA communication error				
		The head type data was read three times in succession			
		(277-00)			
SC277-00		Defective ASIC			
SC277-10	D	Defective LEDA			
002// 10		(277-10)			
		LEDA power source error			
		 Turn the main power OFF and then ON. 			
		Replace the LED head			

Add the following

- Check and connect the FFC.
- Replace the FFC between the BiCU and LED head.
- Replace the BiCU

PAGE: 1/2

Model: Gim-P1a			Date: 25-Sep-18		-18	No.: RM171027
Subject: Manual Correction: SPs to switch the near end timing			Prepared	d by: E. N	Vakamura	
From: 1st Tech. S	Support Sec. Service Support D	Dept.				
Classification:	Troubleshooting	Part info	ormat	tion	Action	n required
	Mechanical	Electric	al		Servic	e manual revision
	Paper path	Transm	it/rec	eive	Retrof	fit information
	Product Safety	Other ()	Tier 2	

Service Manual Revision

RICOH

- Added information on the relation between the UP and SP settings for switching the near end timing.
- Added detailed information for each setting.

3098	[Days Before End] Switches the near end timing: days before end toner				
3-098-001	Toner	E*	[0 to 2 / 1 / 0: earlier 1: normal 2: later	/ 1/step] RTB 49 Information added	

7952	[Days Before End] Switch the timing of the near end: Days until the end.			
7-952-001	Maintenance Kit	E*	[0 to 2 / 1 / 1/step] 0: Earlier 1: Normal 2: Later	
7-952-002	PCDU	E*	[0 to 2 / 1 / 1/step] 0: Earlier 1: Normal 2: Later	

Technical Bulletin

Model: Gim-P1a

Date: 25-Sep-18 No.

No.: RM171027

3800	[Days Before End] Switches the near end timing: days before end toner			
3-800-001	Waste Toner	E*	[0 to 2 / 1 / 1/step] 0: earlier 1: normal 2: later	

The relation between the UP and SP settings for switching the near-end timing is shown below:

	Toner	Maintenance Kit	PCDU	Waste Toner
UP setting	Available (*)	Available (*)	Available (*)	Not Available
SP setting	3-098-001	7-952-001	7-952-002	3-800-001

*Note: Menu > Maintenance > General Settings > Replacement Alert

A description of the setting values is shown below:

UP setting value	SP setting value	FSM Notify timing		Printable pages
Notify Sooner	0	earlier	7 days before end (*)	959 (*)
Normal	1	normal	5 days before end (*)	685 (*)
Notify Later	2	later	3 days before end (*)	411 (*)

*Important Notice:

- The figures above are intended only as an example and are calculated based on the following conditions:
 - A4 (LT)
 - 6% image coverage ratio
 - 3P/J
 - APV: 3.0k prints/month
- The printing habits of the customer (document type, job size, image density, etc.) will have a substantial impact on the toner cartridge's actual page yield. Accordingly, the actual number of days and/or pages that the machine can print with the remaining toner may vary considerably.

PAGE: 1/1

Model: Gim-P1a			Date: 18-Feb-19		No.: RM171028
Subject: Troubleshooting for @Remote certification update fail					b y: Y.Tamaoka
From: Overseas Field info Sec. OP/OS PQM Dept					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	 Part information Electrical Transmit/receive Other () 		Action re Service n Retrofit ir	nanual revision

SYMPTOM

The following messages are displayed on the operation panel and in WIM, triggering unnecessary communication between the device and @Remote gateway.

Operation panel:

"@Remote Cert. update failed", "Please call service"

WIM:

"Failed to update @Remote certificate"

CAUSE

Bug with controller firmware.

SOLUTION

Update the controller firmware to Ver. 1.16 or later.

Technical Bulletin

PAGE: 1/1

Model: Gim-P1, MF1/1.5			Date: 4-Apr-19		No.: RM158056
Subject: Troubleshooting: Defect of waste toner collecting auger					by: Y. Tamaoka
From: Overseas Field Info Sec., OP/OS FQM Dept., QAC					
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Electrical		Action re Service n Retrofit ir	nanual revision

SYMPTOMS

One of more of the following occurs:

- Black lines/streaks
- Toner drops on prints
- Mechanical noise from the PCDU
- SC440

CAUSE

The intake filter on the right cover is not cleaned while the machine is used with Energy Saver disabled.

When the machine is used under these conditions, the intake filter clogs, causing the machine internal temperature to rise. The toner in the waste toner path hardens and sticks to the path, preventing the toner collection auger from functioning correctly.

SOLUTION

If the symptom occurs, do the following:

- 1. Replace the PCDU with a new one.
- 2. Then, enable Energy Saver **and/or** clean the intake filter with a wet cloth.