

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 30-May-16 | No.: RD223005 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: Inserter_CFEEDER_E           |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **Inserter\_CFEEDER\_E**.

| Version   | Program No. | Effective Date      | Availability of RFU |
|-----------|-------------|---------------------|---------------------|
| 00.100:03 | D3D75300A   | 1st Mass production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version   | Modified Points or Symptom Corrected |
|-----------|--------------------------------------|
| 00.100:03 | 1st Mass production                  |

|              |                 |               |
|--------------|-----------------|---------------|
| Model: MT-C6 | Date: 30-May-16 | No.: RD223006 |
|--------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: LCT_MAUI-E                   |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **LCT\_MAUI-E**.

| Version   | Program No. | Effective Date      | Availability of RFU |
|-----------|-------------|---------------------|---------------------|
| 01.010:01 | D3D65510A   | 1st Mass production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version   | Modified Points or Symptom Corrected |
|-----------|--------------------------------------|
| 01.010:01 | 1st Mass production                  |

**Reissued: 04-Aug-16**

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 30-May-16 | No.: RD223013a |
|--------------|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: Web Uapl                     |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Web Uapl**.

| Version            | Program No.             | Effective Date                       | Availability of RFU     |
|--------------------|-------------------------|--------------------------------------|-------------------------|
| <b><i>1.02</i></b> | <b><i>D2235549C</i></b> | <b><i>August 2016 production</i></b> | <b><i>Available</i></b> |
| 1.01               | D2235549B               | 1st Mass production                  | Available               |

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

| Version            | Modified Points or Symptom Corrected  |
|--------------------|---|
| <b><i>1.02</i></b> | <b><i>Symptom corrected:</i></b> <ul style="list-style-type: none"> <li><b><i>Web Image Monitor might time out if the device is turned on and goes in and out of Energy Saver Mode 100 times before it is turned off.</i></b></li> <li><b><i>Web Image Monitor might encounter a "404 Not Found" error when attempting to display a list of stored files from a link sent via email.</i></b></li> </ul> |
| 1.01               | 1st Mass production   |

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 30-May-16 | No.: RD223014 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: XPS                          |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **XPS**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 1.01    | D3D45738A   | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.01    | 1st Mass production                  |

**Reissued: 27-Dec-16**

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 30-May-16 | No.: RD223016b |
|--------------|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: PCL                          |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **PCL**.

| Version     | Program No.             | Effective Date                        | Availability of RFU     |
|-------------|-------------------------|---------------------------------------|-------------------------|
| <b>1.03</b> | <b><i>D2235557D</i></b> | <b><i>January 2017 production</i></b> | <b><i>Available</i></b> |
| 1.02        | D2235557C               | August 2016 production                | Available               |
| 1.01        | D2235557B               | 1st Mass production                   | Available               |

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

| Version     | Modified Points or Symptom Corrected  |
|-------------|---|
| <b>1.03</b> | <b><i>Symptom corrected:</i></b><br>- <b><i>PCL macros that were uploaded to the HDD cannot be printed. (GFPR#RE16080014)</i></b><br>- <b><i>When characters that contain the incorrect TrueType font data are printed, not only are incorrect characters missing but so are correct characters that follow incorrect characters. (GFPR#RE16030046)</i></b> |
| 1.02        | Symptom corrected:<br>Some lines of text and/or dotted lines might be missing when using the PCL overlay macro. (GFPR#RC16040013)   |
| 1.01        | 1st Mass production   |

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 30-May-16 | No.: RD223018 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: PS3                          |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **PS3**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 1.00    | D3D45731A   | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.00    | 1st Mass production                  |

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 30-May-16 | No.: RD223020 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: RPCS                         |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **RPCS**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 3.20.14 | D2235556B   | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 3.20.14 | 1st Mass production                  |

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 30-May-16 | No.: RD223022 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: Inserter_CFEEDER_F           |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **Inserter\_CFEEDER\_F**.

| Version   | Program No. | Effective Date      | Availability of RFU |
|-----------|-------------|---------------------|---------------------|
| 00.100:03 | D3CN5310A   | 1st Mass production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version   | Modified Points or Symptom Corrected |
|-----------|--------------------------------------|
| 00.100:03 | 1st Mass production                  |



**Reissued: 11-Oct-16**

|                               |                 |                |
|-------------------------------|-----------------|----------------|
| Model: MT-C6/ CH-C2/ CH-C2Pro | Date: 30-May-16 | No.: RD223023a |
|-------------------------------|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: ADF_SINAI-D                  |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **ADF\_SINAI-D**.

| Version                 | Program No.             | Effective Date                    | Availability of RFU         |
|-------------------------|-------------------------|-----------------------------------|-----------------------------|
| <b><i>01.000:04</i></b> | <b><i>D3AZ5550E</i></b> | <b><i>1st Mass production</i></b> | <b><i>Not Available</i></b> |
| <b><i>00.160:04</i></b> | <b><i>D3AZ5550D</i></b> | <b><i>1st Mass production</i></b> | <b><i>Not Available</i></b> |

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

| Version                 | Modified Points or Symptom Corrected |
|-------------------------|--------------------------------------|
| <b><i>01.000:04</i></b> | <b><i>1st Mass production</i></b>    |
| <b><i>00.160:04</i></b> | <b><i>1st Mass production</i></b>    |

Reissued: 13-Dec-16

|   |                 |                |
|---|-----------------|----------------|
| Model: Lef-C1, GR-C2_SOP, MET-C2ab, MET-C2cde, MET-C2yz, MT-C6, Gim-MF1.5dM, <b>Brz-MF1,CH-C2,Cor-C1.5,MET-P2,GR-C3</b> | Date: 29-Jan-16 | No.: RD259013e |
|---|-----------------|----------------|

## RTB Reissue

The items in bold italics have been corrected or added.

|  |   |   |
|--|---|---|
| Subject: Firmware Release Note: BluetoothService for eDC     |   | Prepared by: T. Tachibana   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware)       |
|  |   | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **BluetoothService for eDC**.

| Version | Program No.      | Effective Date        | Availability of RFU |
|---------|------------------|-----------------------|---------------------|
| 1.01    | D2411465B_forEDC | April 2016 production | Not Available       |
| 1.0     | D2411465A_forEDC | 1st Mass production   | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 1.01    | <p><b>Other changes:</b></p> <ul style="list-style-type: none"> <li>- <b><i>New Model Supported.</i></b></li> </ul> <p>---</p> <p>Symptom corrected:<br/>Preinstalled applications can be accidentally uninstalled from Web Image Monitor.</p> <p>Other changes:</p> <ul style="list-style-type: none"> <li>- Support for the MP 6503SP/MP 7503SP/MP 9003SP.</li> <li>- Support for the MP 402SPF.</li> </ul> |
| 1.0     | 1st Mass production   |

Reissued: 02-Mar-17

|   |                 |                |
|---|-----------------|----------------|
| Model: Brz-P1, Brz-MF1, BR-C2, BR-P2, CH-C1 Office/ <b>Pro</b> ,<br><b>Cor-C1.5</b> , <b>Gim-MF1.5dM</b> , <b>GR-C3</b> , MT-C6, MET-C2ab, MET-C2cde,<br>MET-C2yz, <b>MET-P2</b> , <b>Midas-P3</b> , <b>Vesta-P1d_15S</b> | Date: 23-May-16 | No.: RD255020b |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: OptionSD FONT                |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **OptionSD FONT**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 0.00    | D3BC5277    | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 0.00    | 1st Mass production                  |

**Reissued: 25-May-16**

|   |                 |                |
|---|-----------------|----------------|
| Model: MET-C2ab/MET-C2cde/MET-C2yz/<br><i>Brz-MF1/MT-C6/Gim-MF1.5dM</i> | Date: 13-May-16 | No.: RD239016a |
|---|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: PCL Font                     |   | Prepared by: M. Kumagai   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **PCL Font**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 1.09    | D2415586    | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**
**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.09    | 1st Mass production                  |

|   |                 |                |
|---|-----------------|----------------|
| Model: <b>Mo-C2/MET-C2ab/MET-C2cde/MET-C2yz/<br/>Brz-MF1/MT-C6/Gim-MF1.5dM/CH-C2/CH-C2Pro</b> | Date: 04-Mar-16 | No.: RD262032a |
|---|-----------------|----------------|

|  |   |   |  |
|--|---|---|--|
| Subject: Firmware Release Note: PS3 Font               |   | Prepared by: Y. Kurohashi   |  |
| From: 1st PP Tech Service Sect., PP Tech Service Dept. |   |   |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **PS3 Font**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 1.17    | D2415681    | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

“Available” The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.17    | 1st Mass production                  |

Reissued: 14-Nov-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br>Lef-C1/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brz-MF1/<br>GR-C2/Gim-MF1.5dM/ <b>CH-C2/MET-P2/GR-C3</b> | Date: 29-Jan-16 | No.: RD259023d |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: StopKeyWidget for eDC        |  |  | Prepared by: T. Tachibana                        |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **StopKeyWidget for eDC**.

| Version | Program No.      | Effective Date       | Availability of RFU |
|---------|------------------|----------------------|---------------------|
| 1.01    | D2411436B_forEDC | June 2016 production | Not Available       |
| 1.00    | D2411436A_forEDC | 1st Mass production  | Not Available       |

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected   |
|---------|--|
| 1.01    | Symptom corrected:<br>Applications can be uninstalled from Web Image Monitor.<br><br>--<br><b><i>New Model Supported</i></b> |
| 1.00    | 1st Mass production  |

Reissued: 03-Oct-16

|  |                 |                |
|--|-----------------|----------------|
| Model:<br>Lef-C1/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brz-MF1/<br>GR-C2/Gim-MF1.5dM | Date: 29-Jan-16 | No.: RD259025e |
|--|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: EcoInfoWidget for eDC        |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **EcoInfoWidget for eDC**.

| Version            | Program No.                    | Effective Date                        | Availability of RFU         |
|--------------------|--------------------------------|---------------------------------------|-----------------------------|
| <b><i>1.06</i></b> | <b><i>D2411437F_forEDC</i></b> | <b><i>October 2016 production</i></b> | <b><i>Not Available</i></b> |
| 1.05               | D2411437E_forEDC               | August 2016 production                | Not Available               |
| 1.04               | D2411437D_forEDC               | June 2016 production                  | Not Available               |
| 1.03               | D2411437C_forEDC               | May 2016 production                   | Not Available               |
| 1.02               | D2411437B_forEDC               | April 2016 production                 | Not Available               |
| 1.01               | D2411437A_forEDC               | 1st Mass production                   | Not Available               |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version            | Modified Points or Symptom Corrected  |
|--------------------|---|
| <b><i>1.06</i></b> | <b><i>Minor change.</i></b>   |
| 1.05               | Minor change.   |
| 1.04               | Support for the MP 402SPF and MP C306ZSP/C406ZSPF   |
| 1.03               | Symptom corrected:<br>- Minor bug correction  |
| 1.02               | Symptom corrected:<br>Preinstalled applications can be accidentally uninstalled from Web Image Monitor. |
| 1.01               | 1st Mass production   |

Reissued: 03-Oct-16

|  |                 |                |
|--|-----------------|----------------|
| Model:<br>Lef-C1/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brz-MF1/<br>GR-C2/Gim-MF1.5dM | Date: 29-Jan-16 | No.: RD259026f |
|--|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: TonnerWidget for eDC         |  |  | Prepared by: T. Tachibana                        |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **TonnerWidget for eDC**.

| Version            | Program No.                    | Effective Date                        | Availability of RFU         |
|--------------------|--------------------------------|---------------------------------------|-----------------------------|
| <b><i>1.05</i></b> | <b><i>D2411434G_forEDC</i></b> | <b><i>October 2016 production</i></b> | <b><i>Not Available</i></b> |
| 1.04               | D2411434F_forEDC               | June 2016 production                  | Not Available               |
| 1.03               | D2411434E_forEDC               | April 2016 production                 | Not Available               |
| 1.02               | D2411434D_forEDC               | April 2016 production                 | Not Available               |
| 1.01               | D2411434C_forEDC               | March 2016 production                 | Not Available               |
| 1.00               | D2411434B_forEDC               | 1st Mass production                   | Not Available               |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version            | Modified Points or Symptom Corrected   |
|--------------------|--|
| <b><i>1.05</i></b> | <b><i>Symptom corrected:<br/>Remaining amount of toner displayed on the widget is incorrect.</i></b>                                     |
| 1.04               | Symptom corrected:<br>- Minor bug correction<br><br>Other changes:<br>Support for the MP C306ZSP/C406ZSPF.<br>Support for the MP 402SPF. |
| 1.03               | Symptom corrected:<br>- Preinstalled applications can be accidentally uninstalled from Web Image Monitor.                                |
| 1.02               | Other changes:<br>Minor changes made to improve reliability.   |
| 1.01               | Symptom Corrected:<br>Several application names were incorrect.  |
| 1.00               | 1st Mass production  |



Reissued: 14-Nov-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br>Lef-C1/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brz-MF1/<br>GR-C2/Gim-MF1.5dM/ <b>CH-C2/MET-P2/GR-C3</b> | Date: 29-Jan-16 | No.: RD259029e |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: ProgramInfoService for eDC   |  |  | Prepared by: T. Tachibana                        |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **ProgramInfoService for eDC**.

| Version | Program No.      | Effective Date        | Availability of RFU |
|---------|------------------|-----------------------|---------------------|
| 1.18    | D2411438D_forEDC | June 2016 production  | Not Available       |
| 1.17    | D2411438C_forEDC | April 2016 production | Not Available       |
| 1.16    | D2411438B_forEDC | 1st Mass production   | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 1.18    | Symptom corrected:<br>- Minor bug correction<br><br>--<br><b><i>New Model Supported</i></b> |
| 1.17    | Other changes:<br>Minor changes made to improve reliability.                                |
| 1.16    | 1st Mass production   |

Reissued: 13-Jan-17

|  |                 |                |
|--|-----------------|----------------|
| Model: Lef-C1/Brz-MF1/CH-C2/CH-C2 Pro/Cor-C1.5/<br>Gim-MF1.5dM/GR-C2/GR-C3/MT-C6/MET-C2ab/<br>MET-C2cde/MET-C2yz | Date: 29-Jan-16 | No.: RD259033k |
|--|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: SimpleCopy for eDC           |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **SimpleCopy for eDC**.

| Version            | Program No.                    | Effective Date                        | Availability of RFU         |
|--------------------|--------------------------------|---------------------------------------|-----------------------------|
| <b><i>1.17</i></b> | <b><i>D2411443P_forEDC</i></b> | <b><i>January 2017 production</i></b> | <b><i>Not Available</i></b> |
| 1.16               | D2411443N_forEDC               | December 2016 production              | Not Available               |
| 1.15               | D2411443M_forEDC               | October 2016 production               | Not Available               |
| 1.13.1             | D2411443L_forEDC               | August 2016 production                | Not Available               |
| 1.11               | D2411443J_forEDC               | June 2016 production                  | Not Available               |
| 1.10               | D2411443H_forEDC               | May 2016 production                   | Not Available               |
| 1.09               | D2411443G_forEDC               | May 2016 production                   | Not Available               |
| 1.08               | D2411443F_forEDC               | April 2016 production                 | Not Available               |
| 1.07               | D2411443E_forEDC               | March 2016 production                 | Not Available               |
| 1.05               | D2411443D_forEDC               | March 2016 production                 | Not Available               |
| 1.04               | D2411443C_forEDC               | February 2016 production              | Not Available               |
| 1.03               | D2411443B_forEDC               | 1st Mass production                   | Not Available               |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version            | Modified Points or Symptom Corrected   |
|--------------------|--|
| <b><i>1.17</i></b> | <b><i>Other Changes:<br/>Design of the "Reset" button has been modified.</i></b>   |
| 1.16               | Minor change.  |
| 1.15               | Minor change.  |
| 1.13.1             | Symptom corrected:<br>- Minor bug correction   |
| 1.11               | Symptom corrected:<br>- Preinstalled applications can be accidentally uninstalled from Web Image Monitor<br><br>Other changes:<br>- Minor changes to the UI. |
| 1.10               | Support for the MP 402SPF.<br><br>Symptom corrected:<br>- Minor bug correction   |

Reissued: 13-Jan-17

|  |                 |                |
|--|-----------------|----------------|
| Model: Lef-C1/Brz-MF1/CH-C2/CH-C2 Pro/Cor-C1.5/<br>Gim-MF1.5dM/GR-C2/GR-C3/MT-C6/MET-C2ab/<br>MET-C2cde/MET-C2yz | Date: 29-Jan-16 | No.: RD259033k |
|--|-----------------|----------------|

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 1.09    | Symptom corrected:<br>- Minor bug correction  |
| 1.08    | Symptom corrected:<br>Preinstalled applications can be accidentally uninstalled from Web Image Monitor. |
| 1.07    | Other changes:<br>Minor changes made to improve reliability.  |
| 1.05    | Symptom Corrected:<br>Some of the words are incorrect in several languages.                             |
| 1.04    | Symptom Corrected:<br>Some of the wording in English was incorrect.                                     |
| 1.03    | 1st Mass production   |

Reissued: 17-Nov-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br>Lef-C1/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brz-MF1/<br>GR-C2/Gim-MF1.5dM/ <b>MET-P2/CH-C2/GR-C3</b> | Date: 29-Jan-16 | No.: RD259034h |
|---|-----------------|----------------|

## RTB Reissue

 The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: LanguageWidget for eDC       |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **LanguageWidget for eDC**.

| Version            | Program No.                    | Effective Date                         | Availability of RFU         |
|--------------------|--------------------------------|--|-----------------------------|
| <b><i>1.06</i></b> | <b><i>D2411431H_forEDC</i></b> | <b><i>December 2016 production</i></b> | <b><i>Not Available</i></b> |
| 1.05               | D2411431G_forEDC               | October 2016 production                | Not Available               |
| 1.04               | D2411431F_forEDC               | August 2016 production                 | Not Available               |
| 1.03               | D2411431E_forEDC               | June 2016 production                   | Not Available               |
| 1.02               | D2411431D_forEDC               | April 2016 production                  | Not Available               |
| 1.01               | D2411431C_forEDC               | March 2016 production                  | Not Available               |
| 1.00               | D2411431B_forEDC               | 1st Mass production                    | Not Available               |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version            | Modified Points or Symptom Corrected  |
|--------------------|---|
| <b><i>1.06</i></b> | <b><i>Minor change.</i></b>   |
| 1.05               | Minor change.   |
| 1.04               | Minor change.   |
| 1.03               | Symptom corrected:<br>Applications can be uninstalled from Web Image Monitor.<br><br>Other changes:<br>Support for the MP C306ZSP/C406ZSPF.<br>Support for the MP 402SPF.<br>Support for the MP 6503SP/MP 7503SP/MP 9003SP. |
| 1.02               | Symptom corrected:<br>Minor bug correction.   |
| 1.01               | Symptom Corrected:<br>Several application names were incorrect.   |
| 1.00               | 1st Mass production   |

**Reissued: 31-May-16**

|  |                 |                |
|--|-----------------|----------------|
| Model: <b>Mo-C2/MET-C2ab/MET-C2cde/MET-C2yz/MT-C6/Brazil-MF1</b> | Date: 04-Mar-16 | No.: RD262033a |
|--|-----------------|----------------|

**RTB Reissue**

The items in bold italics have been corrected or added.

|  |   |   |  |
|--|---|---|--|
| Subject: Firmware Release Note: Font EXP               |   | Prepared by: Y. Kurohashi   |  |
| From: 1st PP Tech Service Sect., PP Tech Service Dept. |   |   |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Font EXP**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 1.00    | D2415581    | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**
**"Available"** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.00    | 1st Mass production                  |

Reissued: 06-Jun-16

|  |                 |                |
|--|-----------------|----------------|
| Model: GR-C2_SOP, <b><i>Mo-C2, Lef-C1, MET-C2ab, MET-C2cde, MET-C2yz, MT-C6, Brz-MF1</i></b> | Date: 30-Jul-15 | No.: RD196026a |
|--|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: IWnnIME for eDC              |   | Prepared by: C. Shimaji   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **IWnnIME for eDC**.

| Version | Program No.     | Effective Date      | Availability of RFU |
|---------|-----------------|---------------------|---------------------|
| 2.3.3   | D1961403_forEDC | 1st Mass production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 2.3.3   | 1st Mass production                  |

Reissued: 24-Nov-16

|   |                 |                |
|---|-----------------|----------------|
| Model: GR-C2_SOP, Mo-C2, Lef-C1, MET-C2ab, MET-C2cde, MET-C2yz, MT-C6, Brz-MF1, Gim-MF1.5, CH-C2, MET-P2, <b>Cor-C1.5</b> | Date: 30-Jul-15 | No.: RD196038c |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: iWnnIME for eDC              |   | Prepared by: C. Shimaji   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **iWnnIME for eDC**.

For Korean

| Version | Program No.     | Effective Date      | Availability of RFU |
|---------|-----------------|---------------------|---------------------|
| 1.0.0   | D1961406_forEDC | 1st Mass production | Not Available       |

For Simplified Chinese

| Version | Program No.     | Effective Date      | Availability of RFU |
|---------|-----------------|---------------------|---------------------|
| 1.0.0   | D1961404_forEDC | 1st Mass production | Not Available       |

For Traditional Chinese

| Version | Program No.     | Effective Date      | Availability of RFU |
|---------|-----------------|---------------------|---------------------|
| 1.0.0   | D1961405_forEDC | 1st Mass production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

For Korean

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.0.0   | 1st Mass production                  |

For Simplified Chinese

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.0.0   | 1st Mass production                  |

For Traditional Chinese

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 1.0.0   | 1st Mass production                  |

Reissued: 14-Dec-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br><b>Lef-C1/ Brz-MF1/CH-C2/Cor-C1.5/</b><br><b>Gim-MF1.5dM/ GR-C2/GR-C3/MT-C6/</b><br><b>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2</b> | Date: 10-Jun-16 | No.: RD259045a |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: NFCPlugin for eDC            |   | Prepared by: H. Morishima   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **NFCPlugin for eDC**.

| Version | Program No.     | Effective Date       | Availability of RFU |
|---------|-----------------|----------------------|---------------------|
| 2.12.00 | D2411452_forEDC | June 2016 production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 2.12.00 | <p>Specification Change:</p> <p>- The previously packaged QuickCardAuth firmware was divided into five individual firmware.</p> <p>&lt;before&gt;<br/>QuickCardAuth</p> <p>&lt;after&gt;<br/>QuickCardAuth<br/>ICCardDispatcher<br/>NFCPlugin<br/>USBCardPlugin<br/>BLEPlugin</p> <p>Symptom corrected:<br/>Applications can be uninstalled from Web Image Monitor.</p> |



Reissued: 14-Dec-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br><b>Lef-C1/ Brz-MF1/CH-C2/Cor-C1.5/</b><br><b>Gim-MF1.5dM/ GR-C2/GR-C3/MT-C6/</b><br><b>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2</b> | Date: 10-Jun-16 | No.: RD259046a |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: USBCardPlugin for eDC        |   | Prepared by: H. Morishima   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **USBCardPlugin for eDC**.

| Version | Program No.     | Effective Date       | Availability of RFU |
|---------|-----------------|----------------------|---------------------|
| 2.12.00 | D2411459_forEDC | June 2016 production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected   |
|---------|--|
| 2.12.00 | <p>Specification Change:</p> <ul style="list-style-type: none"> <li>- The previously packaged QuickCardAuth firmware was divided into five individual firmware.</li> </ul> <p>&lt;before&gt;<br/>QuickCardAuth</p> <p>&lt;after&gt;<br/>QuickCardAuth<br/>ICCardDispatcher<br/>NFCPlugin<br/>USBCardPlugin<br/>BLEPlugin</p> <p>Symptom corrected:<br/>Applications can be uninstalled from Web Image Monitor.</p> |

Reissued: 13-Dec-16

|   |                 |                |
|---|-----------------|----------------|
| Model:<br><b>Lef-C1/ Brz-MF1/CH-C2/Cor-C1.5/<br/>Gim-MF1.5dM/ GR-C2/GR-C3/MT-C6/<br/>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2</b> | Date: 10-Jun-16 | No.: RD259047a |
|---|-----------------|----------------|

## RTB Reissue

The items in bold italics have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: BLEPlugin for eDC            |   | Prepared by: N. Yasuda  |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **BLEPlugin for eDC**.

| Version | Program No.     | Effective Date       | Availability of RFU |
|---------|-----------------|----------------------|---------------------|
| 2.12.00 | D2411466_forEDC | June 2016 production | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 2.12.00 | <p><b><i>New Model Supported.</i></b></p> <p>---</p> <p>Specification Change:<br/>The previously packaged QuickCardAuth firmware was divided into five individual firmware.</p> <p>&lt;before&gt;<br/>QuickCardAuth</p> <p>&lt;after&gt;<br/>QuickCardAuth<br/>ICCardDispatcher<br/>NFCPlugin<br/>USBCardPlugin<br/>BLEPlugin</p> |

|  |   |  |   |
|--|---|--|---|
| Model: MT-C6   |   | Date: 1-Jul-16   | No.: RD223024   |
| Subject: FSM correction on USB device server notes     |   | Prepared by: K. Moriizumi  |   |
| From: 3rd Tech Service Sect., MFP/P Tech Service Dept. |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (      ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Service Manual Correction:

If the USB Device Server Option Type M19 is installed, the machine will wake up from the energy save mode and print without having to disable the energy save mode. Therefore, please delete the notes below from your field service manual.

### 2. Installation

#### > USB Device Server Option Type M19

##### > Installation

##### > Notes for Energy Save Mode Setting

#### **Notes for Energy Save Mode Setting**

If the machine which has this option enters into the Energy Save Mode, you cannot print because this will cause a communication error. Follow the procedure below to disable the Energy Save Mode function.

1. Press [Features Settings] on the operation panel.
2. Press [Administrator Tools] in [System Settings].
3. Press [Energy Saver Mode to Disable Print Server].
4. Press [Disable Mode].
5. Press [OK].
6. Press [Features Settings].

|                     |                 |               |
|---------------------|-----------------|---------------|
| Model: <b>MT-C6</b> | Date: 10-Aug-16 | No.: RD223025 |
|---------------------|-----------------|---------------|

|  |  |  |  |
|--|--|--|--|
| Subject: Firmware Release Note: Option IPDS                  |  | Prepared by: K. Moriizumi                            |  |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |  |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information            | <input type="checkbox"/> Action required         |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical                  | <input type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive            | <input type="checkbox"/> Retrofit information    |
|  | <input type="checkbox"/> Product Safety  | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2       |

This RTB has been issued to announce the firmware release information for the **Option IPDS**.

| Version | Program No. | Effective Date      | Availability of RFU |
|---------|-------------|---------------------|---------------------|
| 8.633   | D3D45712    | 1st Mass production | Available           |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------|--------------------------------------|
| 8.633   | 1st Mass production                  |

Reissued: 16-Dec-16

|  |                 |                |
|--|-----------------|----------------|
| Model:<br>Lef-C1/ Brz-MF1/CH-C2/Cor-C1.5/<br>Gim-MF1.5dM/ GR-C2/GR-C3/MT-C6/<br>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2 | Date: 29-Jan-16 | No.: RD259032i |
|--|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: QRCodeforSDC for eDC         |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **QRCodeforSDC for eDC**.

| Version | Program No.      | Effective Date                        | Availability of RFU |
|---------|------------------|---------------------------------------|---------------------|
| 2.1.2   | D2411453F_forEDC | <b><i>January 2017 production</i></b> | Not Available       |
| 2.1.1   | D2411453E_forEDC | July 2016 production                  | Not Available       |
| 2.1.0   | D2411453D_forEDC | May 2016 production                   | Not Available       |
| 2.0.1   | D2411453C_forEDC | February 2016 production              | Not Available       |
| 2.0.0   | D2411453B_forEDC | 1st Mass production                   | Not Available       |

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected   |
|---------|--|
| 2.1.2   | <p><b><i>Other changes:</i></b></p> <ul style="list-style-type: none"> <li>- <b><i>New Model Supported.</i></b></li> </ul> <p>Symptom corrected:</p> <ul style="list-style-type: none"> <li>- The QR code application quits when opening the settings in Taiwanese models.</li> </ul> <p>On the Griffin-C2_ch, before installing an application or updating to a new version, the CheetahSystem firmware needs to be updated to v1.09 D2411420K) or later.</p>   |
| 2.1.1   | <p>Symptom corrected:</p> <p>When Smart Device Connector is installed, it takes a shorter amount of time for the device to start up.</p>   |
| 2.1.0   | <p>Symptom corrected:</p> <p>Applications can be uninstalled from Web Image Monitor.</p> <p>Other changes:</p> <ul style="list-style-type: none"> <li>- If Smart Device Connector has not been installed on the device, when the smart device reads the QR code on the Smart Operation Panel, the screen will navigate to the Smart Device Connector website.</li> <li>- Support for the MP 6503SP/MP 7503SP/MP 9003SP, MP 402SPF and MP C306ZSP/C406ZSPF.</li> <li>- Before installing or updating an application, the CheetahSystem firmware needs to be updated to v1.09 (D2411420K) or later.</li> </ul> |

Reissued: 16-Dec-16

|  |                 |                |
|--|-----------------|----------------|
| Model:<br>Lef-C1/ Brz-MF1/CH-C2/Cor-C1.5/<br>Gim-MF1.5dM/ GR-C2/GR-C3/MT-C6/<br>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2 | Date: 29-Jan-16 | No.: RD259032i |
|--|-----------------|----------------|

| Version | Modified Points or Symptom Corrected  |
|---------|---|
| 2.0.1   | Other changes:<br>Minor changes made to improve reliability.<br><br>---<br>1st mass production for Mo-C2<br><br>---<br>Symptom Corrected:<br>Some of the wording in English was incorrect.<br><br>Other changes:<br>Support for Bluetooth Low Energy in Smart Device Connector. |
| 2.0.0   | 1st Mass production   |

Reissued: 19-Jan-17

|   |                 |                |
|---|-----------------|----------------|
| Model: Lef-C1/Brz-MF1/ CH-C2/CH-C2 Pro/Cor-C1.5/<br>Gim-MF1.5dM/GR-C2/GR-C3/<br>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2/ MT-C6 | Date: 08-Feb-16 | No.: RD259038g |
|---|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: QuickCardAuth for eDC        |   | Prepared by: T. Tachibana   |   |
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **QuickCardAuth for eDC**.

| Version               | Program No.                    | Effective Date                        | Availability of RFU         |
|-----------------------|--------------------------------|---------------------------------------|-----------------------------|
| <b><i>2.12.04</i></b> | <b><i>D2411468A_forEDC</i></b> | <b><i>January 2017 production</i></b> | <b><i>Not Available</i></b> |
| 2.12.01               | D2411468_forEDC                | June 2016 production                  | Not Available               |
| 2.01.25               | D2411451F_forEDC               | April 2016 production                 | Not Available               |
| 2.01.24               | D2411451E_forEDC               | April 2016 production                 | Not Available               |
| 2.01.22               | D2411451D_forEDC               | March 2016 production                 | Not Available               |
| 2.01.20               | D2411451C_forEDC               | 1st Mass production                   | Not Available               |

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

| Version               | Modified Points or Symptom Corrected   |
|-----------------------|--|
| <b><i>2.12.04</i></b> | <b><i>Specification Change</i></b><br>- <b><i>Modified the API to adhere to the Talkback accessibility function in Android OS for visually impaired people.</i></b>  |
| 2.12.01               | Additional model information:<br>- New Model Supported.<br><br>Symptom corrected:<br>- Applications can be uninstalled from Web Image Monitor.<br><br>Before installing or updating an application, the CheetahSystem firmware needs to be updated to v1.09 (D2411420K) or later.  |
| 2.01.25               | Symptom corrected:<br>- Applications can be uninstalled from Web Image Monitor.  |
| 2.01.24               | Symptom Corrected:<br>When using Quick Card Authentication:<br>- Even if the card reader setting in Screen Features is disabled, the login screen for the card is still displayed.<br>- If logging in to Web Image Monitor fails, a message stating that the login failed is displayed on the operation panel even though the operation panel is not being used. |
| 2.01.22               | Symptom Corrected:<br>Some of the words are incorrect in several languages.  |

Reissued: 19-Jan-17

| Model: Lef-C1/Brz-MF1/ CH-C2/CH-C2 Pro/Cor-C1.5/<br>Gim-MF1.5dM/GR-C2/GR-C3/<br>MET-C2ab/MET-C2cde/MET-C2yz/MET-P2/Mo-C2/ MT-C6 |  | Date: 08-Feb-16 | No.: RD259038g |
|---|--|-----------------|----------------|
| Version   | Modified Points or Symptom Corrected   |                 |                |
| 2.01.20   | 1st Mass production<br><br>Symptom Corrected:<br>- Some of the wording in English was incorrect.<br><br>Other Changes:<br>- Modified the login message in Quick Card Authentication. |                 |                |



**Reissued: 23-Aug-16**

|                     |                 |                |
|---------------------|-----------------|----------------|
| Model: CH-C1/ MT-C6 | Date: 20-May-13 | No.: RD135020d |
|---------------------|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected.

|   |   |   |   |
|---|---|---|---|
| Subject: Firmware Release Note: MailBOX_CS4010              |   | Prepared by: K.Hamada   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept |   |   |   |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **MailBOX\_CS4010**.

| Version                 | Program No.             | Effective Date                     | Availability of RFU         |
|-------------------------|-------------------------|------------------------------------|-----------------------------|
| <b><i>01.020:03</i></b> | <b><i>D7085300E</i></b> | <b><i>July 2016 production</i></b> | <b><i>Not available</i></b> |
| 01.020:02               | D7085300D               | December 2015 production           | Not available               |
| 01.010:02               | D7085300C               | February 2014 production           | Not available               |
| 01.000:02               | D7085300B               | November 2013 production           | Not available               |
| 00.500:02               | D7085300A               | 1st Mass production                | Available                   |

**Note: Definition of Availability of RFU via @Remote**
**“Available”** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

| Version                 | Modified Points or Symptom Corrected  |
|-------------------------|---|
| <b><i>01.020:03</i></b> | <b><i>Symptom corrected:<br/>The machine stalls when a copy is printed out to the Mail Box after recovering from energy saver mode.</i></b>   |
| 01.020:02               | Other changes:<br>MP 6503SP/7503SP/9003SP supported.  |
| 01.010:02               | Symptom Corrected:<br>SC670 may occur on MP C6502/8002 with CS4010, when continuous print jobs are ejected to different trays of CS4010.<br><br>Important:<br>If CS4010 is installed with MPC6502/8002, please be sure to upgrade this CS4010 firmware (01.010:02) and engine firmware (1.29:08) together as a set. |
| 01.000:02               | Symptom corrected:<br>Jams when feeding paper longer than 284.0mm (Ex. A3 paper) with the Punch feature.  |
| 00.500:02               | 1st Mass production   |

|   |   |   |   |
|---|---|---|---|
| Model: MT-C6  |   | Date: 25-Aug-16   | No.: RD223026   |
| Subject: Information on part number changes:<br>Smart Operation Panel's PCB |   | Prepared by: E.Hinata   |   |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept.                      |   |   |   |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (      ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Information on part number changes

Preinstalled applications in Smart Operation Panel v2.0 for the MP C306/406 will be updated to unify the part numbers for all preinstalled applications in the MP C306/406 to match the part numbers in the MP 305 and later models. The PCBs changed to be common in these models as follows in line with the changes of the application. This bulletin is to inform you of the notification regarding the change to the new part numbers and the replacement procedure, which will affect the following models:

- MP 305 (D259)
- MP C3004/3504/4504/5504/6004 (D238/D239/D240/D241/D242), MP C2004/2504 (D243/D244)
- MP 6503/7503/9003 (D223/D224/D225)

### For China

| Old part number | New part number | Description                             | Old Q'ty | New Q'ty | Int |
|-----------------|-----------------|---|----------|----------|-----|
| D2411531        | D2411536        | PCB:MAIN:METIS-C2_CHN:<br>PROGRAM:ASS'Y | 1        | 1        | O/O |

### For other regions

| Old part number | New part number | Description                         | Old Q'ty | New Q'ty | Int |
|-----------------|-----------------|-------------------------------------|----------|----------|-----|
| D2411530        | D2411535        | PCB:MAIN:METIS-C2:<br>PROGRAM:ASS'Y | 1        | 1        | O/O |

Model: MT-C6

Date: 25-Aug-16

No.: RD223026

**Caution:**

**When replacing the PCBs or Operation panel ass'y, follow the procedure below.**

- 1) Replace the hardware parts, PCBs or Operation panel ass'y.**
- 2) Turn ON the main power.**
- 3) Press OK at the message 'Changing the settings. Please wait.'**
- 4) Enter the SP mode.**
- 5) Set the value according to the model and press [Execute] in SP5-761-001: Smart Operation Panel Setting: Restore the default Home screen].**

| <b>Option</b>          | <b>Model</b>                                       | <b>Remarks</b>  |
|------------------------|--|---|
| <b>0<br/>(Default)</b> | <b>MP C306/406</b>                                 | <b>The screen appears as if there are no options.</b> |
| <b>1</b>               | <b>Models other than MP C306/406 and MP CW2201</b> |   |
| <b>2</b>               | <b>MP CW2201</b>                                   |   |

**Note:**

**If you do not set the SP above, home screen for other model will be appeared.**

|  |   |  |   |
|--|---|--|---|
| Model: MT-C6   |   | Date: 1-Sep-16   | No.: RD223027   |
| Subject: The default value of the "Permit SSL/TLS Communication" setting has been changed from "Ciphertext Priority" to "Ciphertext/Cleartext" |   | Prepared by: Y.Shiga   |   |
| From: 1st Tech. Support Sec. Service Support Dept.   |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## At machine installation

The default value of the "Permit SSL/TLS Communication" setting has been changed from "Ciphertext Priority" to "Ciphertext/Cleartext" depending on the Network Support firmware version:

- "Ciphertext Priority" will be the default in devices that have Network Support v16.31 or earlier installed from mass production.
- "Ciphertext/Cleartext" will be the default in devices that have Network Support v16.32 or later installed from mass production.

Note: Configurations will not be automatically changed when the firmware is updated.

## Cut-in Serial Numbers

Network Support v16.32 has been applied to device in the factory as of the following serial numbers:

| Name    | Destination. | Product Code | Serial #     |
|---------|--------------|--------------|--------------|
| MP 6503 | TWN          | D223-19      | G656C800001~ |
|         | CHN          | D223-21      | G656C800001~ |
|         | AA           | D223-29      | G656C800001~ |
|         | EU           | D223-67      | G656J800001~ |
|         | NA           | D223-90      | G656C800001~ |
|         | EU           | D223-91      | G656C790098~ |
| MP 7503 | TWN          | D224-19      | G666C800001~ |
|         | CHN          | D224-21      | G666C800001~ |
|         | LA           | D224-25      | G666L800001~ |
|         | AA           | D224-29      | G666C800001~ |
|         | NA           | D224-57      | G666L800001~ |
|         | EU           | D224-67      | G666J800001~ |
| MP 9003 | TWN          | D225-19      | G676C800001~ |
|         | CHN          | D225-21      | G676C800001~ |
|         | LA           | D225-25      | G676L800001~ |
|         | AA           | D225-29      | G676C800001~ |
|         | NA           | D225-57      | G676L800001~ |
|         | EU           | D225-67      | G676J800001~ |
|         | NA           | D225-90      | G676C800001~ |
|         | EU           | D225-91      | G676C790014~ |

|  |   |   |   |
|--|---|---|---|
| Model: MT-C6   |   | Date: 3-Oct-16  | No.: RD223028   |
| Subject: Service Manual Correction: HDD Encryption     |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

## Service Manual Revision

**Step 7** of the procedure “**How to do a forced start-up with no encryption key**” in the service manual was deleted.

Target models: D223/D224/D225

## Service Manual

Main Chapters > Installation > Security Setting > HDD Encryption > Encryption Key Restoration

### How to do a forced start-up with no encryption key

If the encryption key back-up has been lost, follow the procedure below to do a forced start-up.

#### ★ Important

The HDD will be formatted after the forced start-up.  
 Encrypted data will be deleted.  
 User settings will be cleared.

1. Prepare an SD card.
2. Create a directory named “restore\_key” inside the root directory of the SD card. Then, save the “nvram\_key.txt” file using the following name:  
     /restore\_key/nvram\_key.txt
3. Create a text file and write "nvclear".

#### ★ Important

Write this string at the head of the file.  
 Use all lower-case letters.  
 Do not use quotation marks or blank spaces.  
 It is judged that a forced start has been selected when the content of "nvclear" is executed and the machine shifts to the alternate system (forced start).

4. Confirm that a message is displayed on the LCD telling to insert the SD card that contains the encryption key.
5. Turn off the main power.
6. Insert the SD card that contains the encryption key into SD card slot 2 (the lower slot).
- ~~7. Turn on the main power.~~
8. Turn on the main power switch, the machine automatically clear the HDD encryption.
9. Turn off the main power when the machine has returned to normal status.
10. Remove the SD card from SD card Slot 2.
11. Turn on the main power.

Model: MT-C6

Date: 3-Oct-16

No.: RD223028

12. Memory clear SP5-801-xx (Exclude SP-5-801-001: All Clear and SP-5-801-002: Engine), and clear SP5-846-046: address book.
13. Set necessary user settings in User Tools menus.

|  |  |   |  |
|--|--|---|--|
| Model: MT-C6   |  | Date: 17-Oct-16   | No.: RD223031  |
| Subject: Manual Correction: SC9xx                      |  | Prepared by: K. Moriizumi   |  |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |  |   |  |
| Classification:  | <input checked="" type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

## Service Manual Revision

The descriptions in **bold** were added.

Service Manual: Top Page >Main Chapters >Troubleshooting> SC900:  
Miscellaneous>SC900

|       |   |   |     |
|-------|---|---|-----|
| SC954 | D | Printer image setting error   |     |
|       |   | The settings required for image processing using the printer controller are not sent from the BiCU.   |     |
|       |   | ▪ Software defective  |     |
| SC955 | D | Memory setting error  |     |
|       |   | The settings that are required for image processing using the memory are not sent from the BiCU.  |     |
|       |   | ▪ Software defective  |     |
| SC965 | B | Print Start error   |     |
|       |   | During print processing, another command to start printing was received.  |     |
|       |   | Software bug  |     |
| SC994 | C | Operation Panel Management Records Exceeded   | CTL |
|       |   | An error occurred because the number of records exceeded the limit for images managed in the service layer of the firmware. This can occur if there are too many application screens open on the operation panel. |     |
|       |   | No action required because this SC does not interfere with operation of the machine.  |     |

Model: MT-C6

Date: 17-Oct-16

No.: RD223031

| <b>SC995</b> | <b>D</b> | <b>CPM setting error</b>   | <b>CTL</b> |
|--------------|----------|--|------------|
| <b>01</b>    |          | <ul style="list-style-type: none"><li>▪ Defective BCU</li><li>▪ NVRAM Replacement error</li></ul>  |            |
|              |          | <ul style="list-style-type: none"><li>▪ Install the previous NVRAM.</li><li>▪ Input the serial number with SP5-811-004, and turn the main power switch off and on.</li></ul>             |            |
| <b>02</b>    |          | <ul style="list-style-type: none"><li>▪ Defective NVRAM</li><li>▪ Defective controller</li></ul>   |            |
|              |          | <ul style="list-style-type: none"><li>▪ Update the controller firmware.</li><li>▪ Install a new NVRAM, and turn off and on the main power switch after SC995-002 has occurred.</li></ul> |            |
| <b>03</b>    |          | <ul style="list-style-type: none"><li>▪ Incorrect type controller installed</li><li>▪ Defective controller</li></ul>   |            |
|              |          | <ul style="list-style-type: none"><li>▪ Replace the controller with the correct type.</li></ul>  |            |
| <b>04</b>    |          | <ul style="list-style-type: none"><li>▪ Incorrect model controller installed.</li></ul>  |            |
|              |          | <ul style="list-style-type: none"><li>▪ Replace the controller with the correct model.</li></ul>   |            |



|   |   |   |  |
|---|---|---|--|
| Model: MT-C6  |   | Date: 30-Nov-16   | No.: RD223033  |
| Subject: DO NOT install FAX firmware v02.00.00/03.00.00 |   | Prepared by: Y. Taniguchi   |  |
| From: Field Quality Management Group1, FQM Dept.        |   |   |  |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

### Important Notice about GWFCU Firmware v02.00.00/03.00.00

- **DO NOT install** GWFCU firmware **v02.00.00** (D2235546C) or **v03.00.00** (D2235546D) on machines in the field.
- This is because these versions have the following firmware bug.

### SYMPTOM

When attempting to send a folder, the memory is consumed and prevents the machine from receiving any documents for an extended period.

### CAUSE

Bug with GWFCU firmware.

### SOLUTION

Install a latest GWFCU firmware version (v04.00.00 or newer).

Scheduled for release: 30th of Nov. 2016

| Firmware Name | P/N       | Version  |
|---------------|-----------|----------|
| GWFCU3.8-13   | D2235546E | 04.00.00 |

|   |   |   |   |
|---|---|---|---|
| Model: MT-C6  |   | Date: 1-Dec-16  | No.: RD223034   |
| Subject: Important note: Model NAME PLATE decal for TWN |   | Prepared by: K.Yamamoto   |   |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept.  |   |   |   |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |


## Important Note about Model Name Plate decal on the MT-C6 (Taiwan Model Only)

- Replace the decal as shown below. This is required for all MFP models sold in Taiwan because of the regulation concerning application for certification.

**ATTACH this decal** ("SP" is printed after the model number):



**REMOVE this decal**



### Procedure:

1. Remove the old decal (shown above under "Remove this decal").
2. Clean the attachment area with alcohol.
3. **Important:** Make sure to completely remove the adhesive from this surface.
3. Attach the new decal so that it stays fixed in place in the indented area shown below.



|              |                |               |
|--------------|----------------|---------------|
| Model: MT-C6 | Date: 1-Dec-16 | No.: RD223034 |
|--------------|----------------|---------------|

**Cut-in Serial Numbers:**

The correct decal have affected from November 2016 production.

| Product code: | Product name: | GER: | Cut-in S/N   |
|---------------|---------------|------|--------------|
| D22319        | MP6503SP      | TWN  | G656CC1XXXX~ |
| D22419        | MP7003SP      |      | G666CC1XXXX~ |
| D22519        | MP9003SP      |      | G676CB1XXXX~ |

|  |   |  |  |
|--|---|--|--|
| Model: MT-C6   |   | Date: 12-Dec-16  | No.: RD223035  |
| Subject: Transfer Belt Unit                            |   | Prepared by: K. Moriizumi  |  |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |   |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

**Change:** Transfer belt

**Reason:** Vendor change

### Action:

- When replacing with a new transfer belt or with a new transfer belt unit, do the check procedure below to verify if the belt or the unit is of the old vendor or the new vendor.
- If replaced with a transfer belt of the new vendor, modify the image transfer related SP settings as instructed.

### Procedure


#### 1. Verify the following:

- Part number of the new transfer belt or the transfer belt unit you have procured
- Lot number of the transfer belt requiring the replacement  
(The lot number is printed toward the edge on the inside of the belt.)

#### Belt of the Old vendor

Part number: D2233897 : FLAT BELT-TRANSFER:TOYO (for MP 6503/7503/9003)  
 D2233857 : TRANSFER UNIT:M-C6:TOYO (for MP 6503/7503)  
 D2253857 : TRANSFER UNIT:M-C6E:TOYO (for MP 9003)

Lot number



- Letter in the middle
- Printed in Black
- 9 digits

#### Belt of the New vendor

Part number: D2233898 : FLAT BELT-TRANSFER:SUMITOMO (for MP 6503/7503/9003)  
 D2233859 : TRANSFER UNIT:M-C6:SUMITOMO (for MP 6503/7503)  
 D2253859 : TRANSFER UNIT:M-C6E:SUMITOMO (for MP 9003)

Lot number



- Starts with the prefix "S"
- Printed in Yellow
- 10 digits

Model: MT-C6

Date: 12-Dec-16

No.: RD223035

2. If there is a change in the vendor, make the following SP modifications.

**For MP 6503 SP / 7503 SP**

|                     | Old vendor<br>(Toyo)<br>Belt: D2233897<br>Unit: D2233857 | New vendor<br>(Sumitomo)<br>Belt: D2233898<br>Unit: D2233859 |
|---------------------|--|--|
| SP2-301-001 and 002 | 75   | 65   |
| SP2-301-003         | 80   | 75   |
| SP2-301-011 to 014  | 75   | 65   |
| SP2-301-015 and 016 | 80   | 75   |
| SP2-301-033 to 036  | 75   | 65   |
| SP2-301-037 to 051  | 100  | 80   |
| SP2-301-101 and 102 | 75   | 50   |
| SP2-301-103         | 85   | 75   |
| SP2-301-111 to 114  | 75   | 50   |
| SP2-301-133 to 136  | 75   | 50   |
| SP2-301-137 to 151  | 100  | 80   |

**For MP 9003 SP**

|                     | Old vendor<br>(Toyo)<br>Belt: D2233897<br>Unit: D2253857 | New vendor<br>(Sumitomo)<br>Belt: D2233898<br>Unit: D2253859 |
|---------------------|--|--|
| SP2-301-001 and 002 | 85   | 80   |
| SP2-301-003         | 90   | 80   |
| SP2-301-011 to 014  | 85   | 80   |
| SP2-301-015 and 016 | 90   | 80   |
| SP2-301-033 to 036  | 85   | 80   |

Model: MT-C6

Date: 12-Dec-16

No.: RD223035

- Install the new transfer belt so that the edge printed with the lot number faces the front of the machine. This will allow easy identification of the lot number when the belt may require replacement again in the future.

## Notes:

- Failing to perform the SP modification may cause image quality problems (short vertical lines or blurred image) depending on the operating environment and paper type. In such case, check the SP settings and modify as necessary.
- Clearing the NVRAM will initialize the SP values. If the NVRAM is cleared, check the belt to identify the vendor and modify the SP values by referring to the table described above.
- The following sheet is included as an accessory to the transfer belt and the transfer belt unit manufactured by both old and new vendors. The instructions in this sheet are identical to the contents of this bulletin.

**When Replacing the Transfer Belt / Unit**

When replacing the transfer belt / unit, be sure to check / change the SP number by referring to the table below.

Target models

MP 8503 SP / MP 7503 SP / MP 9003 SP  
(Other models are not subject to this change.)

Setting details

| MP 6503 SP / MP 7503 SP   |   |   |
|---|---|---|
|   | Transfer belt / transfer unit part number   |   |
|   | Belt: D2233897<br>Unit: D2233857  | Belt: D2233898<br>Unit: D2233859  |
| Identification method<br>(Serial number on the back<br>of the belt) | An English alphabet in the<br>middle of the part number<br><br><b>6518A8023</b><br><small>Ink color: black / 9 digits</small> | "S" prefixed to the part<br>number<br><br><b>S602238208</b><br><small>Ink color: yellow / 10 digits</small> |
| SP number and setting value to be checked                           |   |   |
| SP2-301-001 and 002   | 75  | 65  |
| SP2-301-003   | 80  | 75  |
| SP2-301-011 to 014  | 75  | 65  |
| SP2-301-015 and 016   | 80  | 75  |
| SP2-301-033 to 036  | 75  | 65  |
| SP2-301-037 to 051  | 100   | 80  |
| SP2-301-101 and 102   | 75  | 50  |
| SP2-301-103   | 85  | 75  |
| SP2-301-111 to 114  | 75  | 50  |
| SP2-301-133 to 136  | 75  | 50  |
| SP2-301-137 to 151  | 100   | 80  |


  

| MP 9003 SP  |   |   |
|---|---|---|
|   | Transfer belt / transfer unit part number   |   |
|   | Belt: D2233897<br>Unit: D2233857  | Belt: D2233898<br>Unit: D2233859  |
| Identification method<br>(Serial number on the back<br>of the belt) | An English alphabet in the<br>middle of the part number<br><br><b>6518A8023</b><br><small>Ink color: black / 9 digits</small> | "S" prefixed to the part<br>number<br><br><b>S602238208</b><br><small>Ink color: yellow / 10 digits</small> |
| SP number and setting value to be checked                           |   |   |
| SP2-301-001 and 002   | 85  | 80  |
| SP2-301-003   | 90  | 80  |
| SP2-301-011 to 014  | 85  | 80  |
| SP2-301-015 and 016   | 90  | 80  |
| SP2-301-033 to 036  | 85  | 80  |

\*When the settings are not changed, depending on the operating environment or paper types, abnormal images (short vertical lines or blurred images) may result. If this is the case, be sure to check / change the setting.

\*When replacing the transfer belt, so that it can be identified easily, place the lot number that is printed on the inside edge so that it is at the front side of the machine.

D2233-3873


  
92233873

|  |   |   |  |
|--|---|---|--|
| Model: MT-C6   |   | Date: 30-Nov-16   | No.: RD223xxx  |
| Subject: Time of switch into Sleep and Low Power mode is wrong |   | Prepared by: K.Yamamoto   |  |
| From: 1st FQM Sect., 1st FQM Dept.                             |   |   |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## SYMPTOM

Some of the User Mode default values for Sleep mode and Low Power mode are incorrect.

### Incorrect:

Sleep mode: **60 min.** (All models)

Low Power mode: **15 min.** (All models)

### Correct:

Sleep mode: **60 sec.** (Model a (65cpm), Model c (75cpm))

**900 sec.** (Model e (90cpm))

Low Power mode: **60 sec.** (All models)

## CAUSE

The defaults in the System/Copy firmware were incorrect.

Model: MT-C6

Date: 30-Nov-16

No.: RD223xxx

**SOLUTION**

Do the following:

1. Ask the user for permission to change the values for Sleep mode and Low power mode (the time until the machine shifts to these modes).
2. Update the System/Copy firmware to **Ver.1.04** (D2235540G) **or later**.
3. Change the User Mode values for Sleep mode and Lower Power mode to the **Correct** values shown on the previous page.

User Settings => Timer Setting => Time of switch into Sleep mode / Time of switch into Low Power mode

**Note:** Step 3 is necessary because the User Mode settings will not be changed by updating the firmware alone.



Model: MT-C6

Date: 30-Nov-16

No.: RD223xxx

**Cut-in Serial Numbers:**

| Version                     | Destination                  | Name                | Product Code | Cut-in S/N   |
|-----------------------------|------------------------------|---------------------|--------------|--------------|
| Model MT-C6a                | Taiwan                       | Ricoh MP 6503SP     | D223-19      | G656C910001~ |
|                             |                              | Gestetner MP 6503SP |              |              |
|                             | China                        | Ricoh MP 6503SP     | D223-21      | G656C920001~ |
|                             | Asia / Korea                 | Ricoh MP 6503SP     | D223-29      | G656C950001~ |
|                             |                              | Gestetner MP 6503SP |              |              |
|                             | North America /Latin America | Ricoh MP 6503SP     | D223-57      | G656L800736~ |
|                             |                              | Savin MP 6503SP     |              |              |
|                             |                              | Lanier MP 6503SP    |              |              |
| Model MT-C6c                | Taiwan                       | Ricoh MP 7503SP     | D224-19      | G666C910001~ |
|                             |                              | Gestetner MP 7503SP |              |              |
|                             | China                        | Ricoh MP 7503SP     | D224-21      | G666C920001~ |
|                             | Asia / Korea                 | Ricoh MP 7503SP     | D224-29      | G666C950001~ |
|                             |                              | Gestetner MP 7503SP |              |              |
|                             | North America /Latin America | Ricoh MP 7503SP     | D224-57      | G666K800515~ |
|                             |                              | Savin MP 7503SP     |              |              |
|                             |                              | Lanier MP 7503SP    |              |              |
| Model MT-C6eprprip<br>ort12 | Taiwan                       | Ricoh MP 9003SP     | D225-19      | G676C910001~ |
|                             |                              | Gestetner MP 9003SP |              |              |
|                             | China                        | Ricoh MP 9003SP     | D225-21      | G676C920001~ |
|                             | Asia/Korea                   | Ricoh MP 9003SP     | D225-29      | G676C950001~ |
|                             |                              | Gestetner MP 9003SP |              |              |
|                             | North America /Latin America | Ricoh MP 9003SP     | D225-57      | G676L800231~ |
|                             |                              | Savin MP 9003SP     |              |              |
|                             |                              | Lanier MP 9003SP    |              |              |
|                             | Europe                       | Ricoh MP 9003SP     | D225-67      | G676J800124~ |
|                             |                              | NRG MP 9003SP       |              |              |

**Reissued: 17-Jan-17**

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 16-Dec-16 | No.: RD223037a |
|--------------|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** were corrected.

|  |  |   |   |
|--|--|---|---|
| Subject: Cannot send/receive faxes (Memory Full / Remain in the machine) |  | Prepared by: Y. Taniguchi   |   |
| From: 1st FQM Sect., 1st FQM Dept.                                       |  |   |   |
| Classification:  | <input checked="" type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## ***Important***

***There are two independent problems about the fax function (“Memory reaches full” and “Document is waiting and remains in the machine”). They are not related directly but the symptoms and countermeasures is similar, so they are mentioned together in this RTB.***

### **Problem 1: Memory reaches full**

#### **SYMPTOM**

“FAX memory is reached limit” is displayed and the machine cannot receive or send faxes when all of the following conditions are met:

- 1) Forwarding is enabled.
- 2) The transmission destination type for Forwarding is set to [Folder].
- 3) HDD is installed.
- 4) A large document is received.

**Note:** This corresponds roughly to 320 A4-sized pages of a normal text document, or fewer pages in the case of images (Example: 6 A3-sized pages of a C4 color chart printed).

#### **CAUSE**

Under the conditions explained above, invalid data is received (copied) into fax memory. The machine cannot copy the data to the HDD (which is normal when using Forward to Folder), and continues to retry for up to 72 hours. As a result, the fax memory is locked during this time, and the machine cannot send or receive faxes.

#### **SOLUTION**

##### **On the Production line**

FCU Firmware is modified so that the default value of the third digit from the bottom of SP1-104-003 is “0”. The setting value means invalid data will not be stored in fax memory.

**Reissued: 17-Jan-17****Model: MT-C6****Date: 16-Dec-16****No.: RD223037a****Problem 2: Document is waiting and remains in the machine****SYMPTOM**

***Faxes that require internal communication with the HDD cannot be sent and remain in the machine, and the Transmission Failure Report is not printed out. Customers may be unaware of non-transmission.***

***Conditions:***

- 1). Capturing Device Log function is enabled (Default: enable).***
- 2). Capturing Device Log accesses the HDD just as the machine switches to Sleep Mode.***
- 3). The fax is sent using a feature that requires internal communication with the HDD, i.e.:***

***Preview Before Transmission***

***Remote Fax (either as the Main machine or Sub machine)***

***Sending the document stored in Document Server***

**CAUSE**

***When the conditions 1) and 2) described above are met, the line of communication between the HDD and machine is locked and remains locked. Fax features that require internal communication with the HDD use this same line, which then prevents fax transmission.***

**SOLUTION*****On the Production line***

***FCU Firmware is modified to release the line of communication between the machine and HDD under the conditions described above.***

**Reissued: 17-Jan-17**

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 16-Dec-16 | No.: RD223037a |
|--------------|-----------------|----------------|

***Important:***

*In the case of troubleshooting either problem, please do the following procedure in order to prevent both problems.*

**SOLUTION** In the field

- 1) Update the GWFCU firmware to the following version or later:

| Firmware Name | P/N       | Version  |
|---------------|-----------|----------|
| GWFCU3.8-13   | D2235546E | 04.00.00 |

- 2) Set the **third digit from the bottom** of **FAX SP1-104-003** to **"0"** ("Delete invalid data").

Note: This is because the SP value will not be changed if only the firmware is updated. Only the default value is changed by the firmware update.

**Reissued: 05-Jan-17**

|  |                 |                |
|--|-----------------|----------------|
| Model: AI-C2/AP-C3/AT-C3/MT-C5/Ch-C1/Cor-C1/MET-C1ab/MET-C1ab_ch/MET-C1cde/MET-C1cde_ch/MET-C1yz/MET-C1yz_ch/MET-C2ab/MET-C2cde/MET-C2yz/OR-C2/OR-C2_ch/ <b>MT-C6/Ch-C2/Cor-C1.5</b> | Date: 23-Feb-12 | No.: RD129022c |
|--|-----------------|----------------|

**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Firmware Release Note: SG3-ND                       |   | Prepared by: M. Kumagai   |   |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **SG3-ND**.

| Version          | Program No.            | Effective Date                         | Availability of RFU     |
|------------------|------------------------|--|-------------------------|
| <b><i>09</i></b> | <b><i>D3BV5570</i></b> | <b><i>November 2016 production</i></b> | <b><i>Available</i></b> |
| 08               | D5455575B              | June 2015 production                   | Available               |
| 07               | D5455575A              | 1st Mass production                    | Available               |

**Note: Definition of Availability of RFU via @Remote**
**"Available":** The firmware can be updated via RFU or SD card.

**"Not available":** The firmware can only be updated via SD card.

| Version          | Modified Points or Symptom Corrected                                     |
|------------------|--|
| <b><i>09</i></b> | <b><i>By changed the standard of FAX, the firmware is corrected.</i></b> |
| 08               | Symptom corrected:<br>Only Japanese domestic market                      |
| 07               | 1st Mass production  |

|  |   |   |   |
|--|---|---|---|
| Model: MT-C6   |   | Date: 30-Jan-17   | No.: RD223038   |
| Subject: How to Adjust the Screen Angle                |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

This bulletin provides the instruction for changing the angle of the operation panel screen.

## Screen Angle Adjustment Procedure

1. Place the operation panel upside down.
2. Remove the fixing screws (x2).



3. To adjust the tilting angle, loosen the following two screws.




Model: MT-C6

Date: 30-Jan-17

No.: RD223038

4. Lift the lower cover [A] and align it with the ribs [B].



d257a4420

5. Fix the ribs and lower cover with the screws you removed in Step 2. The photo below shows the screw attached to the right hand side.



×1

d257a4421

Model: MT-C6

Date: 30-Jan-17

No.: RD223038

6. Tighten the two screws loosened in Step 3, to fix the angle.





|  |   |   |   |
|--|---|---|---|
| Model: MT-6  |   | Date: 21-Feb-17   | No.: RD223039   |
| Subject: DO NOT install CheetahSystem firmware v1.21 and package all containing cheetah system |   | Prepared by: T. Kiyohara  |   |
| From: Field Quality Management Group1, FQM Dept.   |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## Important Notice about Cheatah System v1.21 and package\_ALL containing CheetahSystem v1.21

**DO NOT install** Cheatah System v1.21 and package\_ALL containing CheetahSystem v1.21 on machines in the field.

This is because these versions have the following firmware bug.

**Note:** These versions are no longer released/available.

### SYMPTOM

Some Smart SDK application for only RHQ get deleted with CheetahSystem v1.21.

Note:

If this symptom occurs, cannot reinstall the Smart SDK application.

**Affected model:** Met-C2abcdeyz, Met-P2, Gr-C2/C3, Brz-MF1, Ch-C2, Cor-C1.5, Lef-C1, Mt-C6

### CAUSE

Bug with the SDK application for RHQ.

Detail:

This cause is the combination between a side effect of V1.21 and a SDK application's manifest file.

The production signature of the smart SDK application is not correct in RHQ region.

The manifest file for the development is still remained in the application.

The other hand, Cheetah system is added the bata signification function that expired application is deleted since version 1.21.

Therefore this application is un-installed by the bata signification function.

### SOLUTION

Do either of the following:

- Install a newer Cheetah System firmware latest version (v1.22).

Scheduled for release: the early of March, 2017

Model: MT-6

Date: 21-Feb-17

No.: RD223039

- Install a newer package firmware latest version.

Scheduled for release: the end of March, 2017

- Install an older Cheetah System firmware version or older package firmware.

|  |   |   |   |
|--|---|---|---|
| Model: MT-C6   |   | Date: 1-Mar-17  | No.: RD223040   |
| Subject: Staple Capacity                               |   | Prepared by: K. Moriizumi   |   |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

## Service Manual Correction

Top Page > Appendices > 1. Machine Specification > Option Equipment Specifications > Finisher SR4120 (D3CG) > Stapler

### Stapler

|                   |                  |                  |   |
|-------------------|------------------|------------------|---|
| Stapling Capacity | Same Paper Size  | <b>65 sheets</b> | A4, 8 $\frac{1}{2}$ " x11" or smaller   |
|                   |                  | <b>65 sheets</b> | B4, 8 $\frac{1}{2}$ " x14" or larger  |
|                   | Mixed Paper Size | <b>65 sheets</b> | A4 LEF + A3 SEF,<br>B5 LEF + B4 SEF,<br>8 $\frac{1}{2}$ " x11" LEF + 11" x17" SEF |

Top Page > Appendices > 1. Machine Specification > Option Equipment Specifications > Booklet Finisher SR4130 (D3CH) > Stapler

### Stapler

|                   |                  |                  |  |
|-------------------|------------------|------------------|--|
| Staples Capacity* | Same Paper Size  | <b>65 sheets</b> | A4, 8 $\frac{1}{2}$ " x 11" or smaller                                     |
|                   |                  | <b>65 sheets</b> | B4, 8 $\frac{1}{2}$ " x 14" or larger                                      |
|                   | Mixed Paper Size | <b>65 sheets</b> | A4 LEF & A3 SEF, B5 LEF & B4 SEF, 8 $\frac{1}{2}$ "x11" LEF & 11" x17" SEF |
|                   | Booklet Stapling | <b>20 sheets</b> | <b>64.0 ~ 80.0 g/m<sup>2</sup><br/>(17.1 ~ 20 lb. Bond)</b>                |

|  |  |   |  |
|--|--|---|--|
| Model: MT-C6   |  | Date: 10-Aug-17   | No.: RD223042  |
| Subject: Manual Correction: SC530                      |  | Prepared by: K. Moriizumi   |  |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |  |   |  |
| Classification:  | <input checked="" type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

## Service Manual Revision

SC530-13, -14, -15, -16 are Japan only, and SC530-17, -18, -19 have been added.

The meaning of SC530-17 is the same as SC530-13. The following SC codes have the same meaning:

SC530-13 -> SC530-17

SC530-14 -> N/A

SC530-15 -> SC530-18

SC530-16 -> SC530-19

Service Manual: Top Page >Main Chapters >Troubleshooting> SC500: Feed, Transport, Duplex, and Fusing

|          |  |  |
|----------|--|--|
| SC530-13 |  | <b>PFU fan 1 error Japan Only</b>  |
|          |  | After the fan turns on, the fan lock signal is checked at 1 sec. intervals.  |
|          |  | <ul style="list-style-type: none"> <li>Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> <li>The lock signal should remain LOW during normal operation.</li> <li>The fan stopped and then the machine stopped.</li> </ul> |
|          |  | <ul style="list-style-type: none"> <li>Fan motor overload due to an obstruction.</li> <li>Fan motor connector, harness loose, broken, defective.</li> <li>Fan motor defective.</li> </ul>  |
| SC530-14 |  | <ul style="list-style-type: none"> <li>Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> <li>Inspect harness, connector and replace if damaged.</li> <li>Replace PFU fan 1.</li> </ul>   |
|          |  | <b>Paper feed unit fan 2 error Japan Only</b>  |
|          |  | After the fan turns on, the fan lock signal is checked at 1 sec. intervals.  |
|          |  | <ul style="list-style-type: none"> <li>Due to an obstruction or other problem, the lock signal went</li> </ul>   |

| Model: MT-C6 |  | Date: 10-Aug-17  | No.: RD223042 |
|--------------|--|--|---------------|
|              |  | <p>HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</p> <ul style="list-style-type: none"> <li>▪ The lock signal should remain LOW during normal operation.</li> <li>▪ The fan stopped and then the machine stopped.</li> </ul>  |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Fan motor overload due to an obstruction.</li> <li>▪ Fan motor connector, harness loose, broken, defective.</li> <li>▪ Fan motor defective.</li> </ul>  |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> <li>▪ Inspect harness, connector and replace if damaged.</li> <li>▪ Replace PFU fan 2.</li> </ul>   |               |
| SC530-15     |  | <b>Paper feed unit fan 3 error Japan Only</b>  |               |
|              |  | <p>After the fan turns on, the fan lock signal is checked at 1 sec. intervals.</p> <ul style="list-style-type: none"> <li>▪ Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> <li>▪ The lock signal should remain LOW during normal operation.</li> <li>▪ The fan stopped and then the machine stopped.</li> </ul>  |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Fan motor overload due to an obstruction.</li> <li>▪ Fan motor connector, harness loose, broken, defective.</li> <li>▪ Fan motor defective.</li> </ul>  |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> <li>▪ Inspect harness, connector and replace if damaged.</li> <li>▪ Replace PFU fan 3.</li> </ul>   |               |
| SC530-16     |  | <b>Paper feed unit fan 4 error Japan Only</b>  |               |
|              |  | <p><b>Note:</b> The machines of this series have four trays in Japan, and machines in areas outside Japan have three trays. Tray 1 is a tandem tray, but Tray 1 in Japan is smaller.</p> <p>After the fan turns on, the fan lock signal is checked at 1 sec. intervals.</p> <ul style="list-style-type: none"> <li>▪ Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> <li>▪ The lock signal should remain LOW during normal operation.</li> <li>▪ The fan stopped and then the machine stopped.</li> </ul> |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Fan motor overload due to an obstruction.</li> <li>▪ Fan motor connector, harness loose, broken, defective.</li> <li>▪ Fan motor defective.</li> </ul>  |               |
|              |  | <ul style="list-style-type: none"> <li>▪ Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> </ul>   |               |

Model: MT-C6

Date: 10-Aug-17

No.: RD223042

|  |  |  |
|--|--|--|
|  |  | <ul style="list-style-type: none"> <li>Inspect harness, connector and replace if damaged.</li> <li>Replace PFU fan 4.</li> </ul> |
|--|--|--|

|          |  |  |
|----------|--|--|
| SC530-17 |  | PFU fan 1 error  |
|          |  | After the fan turns on, the fan lock signal is checked at 1 sec. intervals.  |
|          |  | <ul style="list-style-type: none"> <li>Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> <li>The lock signal should remain LOW during normal operation.</li> <li>The fan stopped and then the machine stopped.</li> </ul> |
|          |  | <ul style="list-style-type: none"> <li>Fan motor overload due to an obstruction.</li> <li>Fan motor connector, harness loose, broken, defective.</li> <li>Fan motor defective.</li> </ul>  |
|          |  | <ul style="list-style-type: none"> <li>Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> <li>Inspect harness, connector and replace if damaged.</li> <li>Replace PFU fan 1.</li> </ul>   |

|          |  |  |
|----------|--|--|
| SC530-18 |  | Paper feed unit fan 3 error  |
|          |  | After the fan turns on, the fan lock signal is checked at 1 sec. intervals.  |
|          |  | <ul style="list-style-type: none"> <li>Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> <li>The lock signal should remain LOW during normal operation.</li> <li>The fan stopped and then the machine stopped.</li> </ul> |
|          |  | <ul style="list-style-type: none"> <li>Fan motor overload due to an obstruction.</li> <li>Fan motor connector, harness loose, broken, defective.</li> <li>Fan motor defective.</li> </ul>  |
|          |  | <ul style="list-style-type: none"> <li>Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li> <li>Inspect harness, connector and replace if damaged.</li> <li>Replace PFU fan 3.</li> </ul>   |

|          |  |   |
|----------|--|---|
| SC530-19 |  | Paper feed unit fan 4 error   |
|          |  | <p><b>Note:</b> The machines of this series have four trays in Japan, and machines in areas outside Japan have three trays. Tray 1 is a tandem tray, but Tray 1 in Japan is smaller.</p> <p>After the fan turns on, the fan lock signal is checked at 1 sec. intervals.</p> <ul style="list-style-type: none"> <li>Due to an obstruction or other problem, the lock signal went HIGH 1.5 s after the fan turned on and remained HIGH for 6 consecutive counts.</li> </ul> |

Model: MT-C6

Date: 10-Aug-17

No.: RD223042

|  |  |  |
|--|--|--|
|  |  | <ul style="list-style-type: none"><li>▪ The lock signal should remain LOW during normal operation.</li><li>▪ The fan stopped and then the machine stopped.</li></ul>   |
|  |  | <ul style="list-style-type: none"><li>▪ Fan motor overload due to an obstruction.</li><li>▪ Fan motor connector, harness loose, broken, defective.</li><li>▪ Fan motor defective.</li></ul>  |
|  |  | <ul style="list-style-type: none"><li>▪ Inspect the area around the fan for obstructions that could interfere with the rotation of the fan blades.</li><li>▪ Inspect harness, connector and replace if damaged.</li><li>▪ Replace PFU fan 4.</li></ul> |
|  |  |  |

|   |   |  |   |
|---|---|--|---|
| Model: MT-C6  |   | Date: 25-May-17  | No.: RD223041   |
| Subject: CC-CERTIFIED IN 2016 Machine                 |   | Prepared by: T.Suzuki  |   |
| From: Technical Support Sect, Product Marketing Dept. |   |  |   |
| Classification:                                       | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (            ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

This RTB describes the requirements for installing models in the MP 6503/7503/9003 series as a CC-CERTIFIED MACHINES compliant with IEEE Std 2600.2™-2009

Do the following eleven steps if you want to install the MP 6503/7503/9003 series models as a CC-CERTIFIED MACHINE compliant with IEEE Std 2600.2™-2009.

Note: Machines in production are CC-certified beginning in May 2017.

Important: If you perform with accessing SP mode, the machine become the different condition as when CC certification was attained.

1. Make sure the customer has received the English language Operating Instructions (O/I) shown in the page 9-11.

Important:

- For installations in the EU market, make sure this is the Ricoh-genuine O/I.
- To ensure that the O/Is are Ricoh-genuine, make sure that the part numbers match those listed in the table on page 9. Also make sure that the contents are Ricoh-genuine and there is no suspicious point. (The P/N are normally printed on the back cover).
- Tell the customer that those manuals evaluated for CC certification are the manuals listed in The list of Operating Instructions (O/I).
- Tell the customer to see the Online Document Set 1 from the following URL:  
[https://support-download.com/services/device/ccmanual/MP6503/en/booklist/int/index\\_book.htm](https://support-download.com/services/device/ccmanual/MP6503/en/booklist/int/index_book.htm)
- Tell the customer to see the Online Document Set 2 from the following URL:  
<https://support-download.com/services/device/ccmanual/MP6503/en/pdf/User.html>
- Tell the customer to see the Online Document Set 3 from the following URL:  
<https://support-download.com/services/device/ccmanual/MP6503/en/pdf/DriverInstall.html>
- Tell the customer to see the Online Document Set 4 from the following URL:  
<https://support-download.com/services/device/ccmanual/MP6503/en/pdf/Oss.html>
- Tell the customer to download the Online Document Set 5 (the information about the authentication based on the CC certification system) from the following URL:  
[https://support-download.com/services/device/ccmanual/mp\\_6503\\_7503\\_9003/en/download\\_admin.html](https://support-download.com/services/device/ccmanual/mp_6503_7503_9003/en/download_admin.html)  
[https://support-download.com/services/device/ccmanual/mp\\_6503\\_7503\\_9003/en/download\\_user.html](https://support-download.com/services/device/ccmanual/mp_6503_7503_9003/en/download_user.html)

2. Tell the customer to read the “Notes for Administrators: Using This Machine in a



Model: MT-C6

Date: 25-May-17

No.: RD223041

Network Environment Compliant with IEEE Std 2600.2™-2009”.

See the following pages for Step 3 to Step 11.

Model: MT-C6

Date: 25-May-17

No.: RD223041

3. Confirm that no suspicious parts or devices are attached to the peripheral.

By comparing the peripheral and the images in "2. Installation" and "Internal Options" in "MP 6503SP/MP 7503SP/MP 9003SP Machine Code:D223/D224/D225 Field Service Manual", confirm that no suspicious parts or devices are attached to the USB, LAN, and SD Card Slot of the peripheral.

By comparing the ADF and the images in "4. Replacement and Adjustment" and "ADF" in "MP 6503SP/MP 7503SP/MP 9003SP Machine Code:D223/D224/D225 Field Service Manual", confirm that no suspicious parts or devices are attached to the ADF cable.

4. Install Fax Option Type M25.

By comparing the fax unit and the images in "1. Installation", "Fax Option Type M25", and "Accessories" in "Fax Option Type M25 Machine Code: D3D5 Field Service Manual", confirm that no suspicious parts or devices are attached to the fax unit.

Install Fax Option Type M25.

For the detailed installation procedure, see "Fax Option Type M25" in "1. Installation", Fax Option Type M25 Machine Code: D3D5 Field Service Manual.

5. Hide Administrator Password Change Screen

If the "Program/Change Administrator" screen is displayed at startup, execute SP5-755-002 (Hide Administrator Password Change Scrn).

6. Setting "Smart Operation Panel mode" to "Secure boot"

In the SP5-748-101 (Op Type Action Setting), set "bit2: Smart Operation Panel mode" to "1".

7. Setting "Web Service Access Ctrl:Rest WebService (Lower 4bits)" to "on"

In the SP5-848-025 (Web Service Access Ctrl:Rest WebService (Lower 4bits)), set bit0 to "1".

8. Setting "On Board USB" to "0"

In the SP5-985-002 (On Board USB), set "On Board USB" to "0".

9. Setting "Auto Update Setting" to "0"

In the SP5-886-111 (Auto Update Setting), set "Auto Update Setting" to "0".

10. Enabling the Encryption Settings

Enable the encryption settings described in service manual, and execute [Format All Data].

Hand the customer the printout of the encryption key that is printed when enabling the encryption settings.

11. Check firmware versions.

If the customer requests exactly the same condition as when CC certification was attained, install the versions shown in the table below. If not, make sure that firmware

Model: MT-C6

Date: 25-May-17

No.: RD223041

versions of the machine are the same as or later than the ones in the table.

- If the customer wants to install the machine in the same condition as when CC Certification was first attained, install the exact versions shown in the table below.
  - If the customer wants to install the machine as an equivalent of the condition as when CC certification was first attained, install the versions shown in the table below or later.
- If you are not sure which of these the customer prefers, confirm this with your Sales department.

Model: MT-C6

Date: 25-May-17

No.: RD223041

Firmware versions with which the MP 6503/7503/9003 models first achieved CC-CERTIFICATION:

Model: MT-C6

Date: 25-May-17

No.: RD223041

| Firmware Name:   | Version: | Firmware Number: |
|------------------|----------|------------------|
| System/Copy      | 1.06     | D2235540J        |
| Web Support      | 1.03     | D2235548D        |
| Network Support  | 16.36    | D2235552G        |
| Fax              | 02.00.00 | D2235544C        |
| RemoteFax        | 03.00.00 | D2235545D        |
| Scanner          | 01.01    | D2235547C        |
| Web Uapl         | 1.02     | D2235549C        |
| NetworkDocBox    | 1.02     | D2235550D        |
| animation        | 1.00     | D2235551B        |
| Printer          | 1.03     | D2235554E        |
| RPCS             | 3.20.14  | D2235556B        |
| Font EXP         | 1.00     | D2415581         |
| PCL              | 1.03     | D2235557D        |
| PCL Font         | 1.09     | D2415586         |
| PDF              | 1.01     | D2235560B        |
| PS3 Font         | 1.17     | D2415681         |
| Java VM v12 std  | 12.47.01 | D2235562F        |
| Data Erase Onb * | 1.05     | D2625244         |
| GWFCU3.8-13(WW)  | 04.00.00 | D2235546E        |
| PowerSaving Sys  | F.L3.06  | D2235543A        |
| M2a_System       | 1.20     | D2411420X        |
| M2a_BLEPlugin    | 2.12.00  | D2411466         |
| M2a_BluetoothSe  | 1.01     | D2411465B        |
| M2a_cspf         | 2.02.00  | D1961430B        |
| M2a_ICCdDisptch  | 2.12.04  | D2411450A        |
| M2a_iWnn         | 2.3.3    | D1961403         |
| M2a_iWnn_Hang    | 1.0.0    | D1961406         |
| M2a_iWnn_Hans    | 1.0.0    | D1961404         |
| M2a_iWnn_Hant    | 1.0.0    | D1961405         |
| M2a_LegacyUI     | 1.13.1   | D2411427P        |
| M2a_MeidaPrtScn  | 1.15     | D2411447N        |
| M2a_NFCPlugin    | 2.12.00  | D2411452         |
| M2a_PrinterInfo  | 1.10     | D2411458L        |
| M2a_PrinterSJob  | 1.60     | D2411446L        |
| M2a_ProgramInfo  | 1.18     | D2411438D        |
| M2a_QRCode_SDC   | 2.1.2    | D2411453F        |
| M2a_QuickCdAuth  | 2.12.01  | D2411468         |
| M2a_SimpleCopy   | 1.16     | D2411443N        |
| M2a_SimpleFAX    | 1.11     | D2411445L        |
| M2a_SimpleScan   | 1.12     | D2411444N        |
| M2a_SmartCopy    | 1.20     | D2411454Q        |
| M2a_SmartFAX     | 1.17     | D2411457M        |
| M2a_SmartScan    | 1.11     | D2411456L        |

Model: MT-C6

Date: 25-May-17

No.: RD223041

| Firmware Name:  | Version:              | Firmware Number: |
|-----------------|-----------------------|------------------|
| M2a_USBCdPlugin | 2.12.00               | D2411459         |
| M2a_WEcoInfo    | 1.06                  | D2411437F        |
| M2a_WFaxInfo    | 1.02                  | D2411435D        |
| M2a_WLanguage   | 1.06                  | D2411431H        |
| M2a_WStopKey    | 1.01                  | D2411436B        |
| M2a_WTonner     | 1.05                  | D2411434G        |
| M2a_zoo         | 1.04.01               | D2411467G        |
| M_1679852032    | 1.0.4.1(1.8.0<br>.79) | D2411470         |
| M_1679852544    | 1.00                  | D1961459         |
| Engine          | 1.06:02               | D2235127E        |
| ADF             | 01.000:04             | D3AZ5550E        |

\* If the Data Erase Onb version is not the same as shown in the table, contact your supervisor. (This version is never upgraded).

Ic Key and Ic Ctlr versions with which the MP 6503/7503/9003 models first achieved CC-CERTIFICATION:

| Hardware: | Version: |
|-----------|----------|
| Ic Ctlr   | 03       |
| Ic Key    | 01020d0c |

If the Ic Key and Ic Ctlr versions are not the same as shown in the table, contact your supervisor. (This version is never upgraded).

These versions can be confirmed from the operation panel.

MultiLink-Panel

Model: MT-C6

Date: 25-May-17

No.: RD223041

| Firmware Name:                       | Version:          | Firmware Number: |
|--------------------------------------|-------------------|------------------|
| Firmware                             | 1.20              | D2411420X        |
| Keymicon                             | 6.11              | D2411423         |
| Application Site                     | 1.04.01           | D2411467G        |
| Bluetooth Authentication Plugin      | 2.12.00           | D2411466         |
| BluetoothService                     | 1.01              | D2411465B        |
| Change Langs. Widget                 | 1.06              | D2411431H        |
| Copy                                 | 1.20              | D2411454Q        |
| CSPF                                 | 2.02.00           | D1961430B        |
| Eco-friendly Widget                  | 1.06              | D2411437F        |
| Fax                                  | 1.17              | D2411457M        |
| Fax RX File Widget                   | 1.02              | D2411435D        |
| ICCardDispatcher                     | 2.12.04           | D2411450A        |
| iWnn IME                             | 2.3.3             | D1961403         |
| iWnn IME Chinese(Simplified) Pack    | 1.0.0             | D1961404         |
| iWnn IME Chinese(Traditional) Pack   | 1.0.0             | D1961405         |
| iWnn IME Korean Pack                 | 1.0.0             | D1961406         |
| LegacyUI type-1                      | 1.13.1            | D2411427P        |
| LegacyUIData                         | 1.00              | D2235551B        |
| Print/Scan(Memory Storage Device)    | 1.15              | D2411447N        |
| Printer                              | 1.10              | D2411458L        |
| ProgramInfoService                   | 1.18              | D2411438D        |
| Proximity Card Reader Support Plugin | 2.12.00           | D2411459         |
| Quick Card Authentication Config     | 2.12.01           | D2411468         |
| Quick Copy                           | 1.16              | D2411443N        |
| Quick Fax                            | 1.11              | D2411445L        |
| Quick Print Release                  | 1.60              | D2411446L        |
| Quick Scanner                        | 1.12              | D2411444N        |
| RemoteConnect Support                | 1.0.4.1(1.8.0.79) | D2411470         |
| RemoteSupportService                 | 1.00              | D1961459         |
| Scanner                              | 1.11              | D2411456L        |
| Smart Device Connector               | 2.1.2             | D2411453F        |
| Standard IC Card Plugin              | 2.12.00           | D2411452         |
| Stop Widget                          | 1.01              | D2411436B        |
| Supply Info Widget                   | 1.05              | D2411434G        |

Model: MT-C6

Date: 25-May-17

No.: RD223041

The list of Operating Instructions (O/I)

<For North America>

Paper Documents

- D223-7206 Read This First
- D195-7543A Notes for Using This Machine Safely
- D223-7238 For Users of This Product
- D219-7457 Notes to Users in the United States of America
- D219-7460 Note to users in Canada
- D256-8998 Note to users
- D223-7235 Start Guide
- D241-7237 SOFTWARE LICENSE AGREEMENT
- D241-7178 NOTICE TO USERS

Online Document Set 1

- D223-7280 About This Machine
- D223-7281 Copy/Document Server
- D223-7282 Fax
- D223-7283 Print
- D223-7284 Scan
- D223-7285 Troubleshooting
- D223-7286 Connecting the Machine/ System Settings
- D223-7287 Security Guide
- D223-7288 Extended Feature Settings
- D223-7289 PostScript 3

Online Document Set 2

- D223-7277 User Guide

Online Document Set 3

- D223-7278 Operating Instructions Driver Installation Guide

Online Document Set 4

- D223-7264 About Open Source Software License

Online Document Set 5

- D146-7587 Notes on Security Functions
- D223-7261 Notes for Administrators:  
Using This Machine in a Network Environment  
Compliant with IEEE Std 2600.2™-2009

<For Europe>

Paper Documents

- D223-7205 Read This First



Model: MT-C6

Date: 25-May-17

No.: RD223041

- D195-7543A Notes for Using This Machine Safely
- D223-7238 For Users of This Product
- D150-1468A Note to users EU Countries
- D256-8998 Note to users
- D219-7068A Start Guide
- D241-7237 SOFTWARE LICENSE AGREEMENT
- D094-7823 As this machine is not a household appliance,  
it does not conform to ErP Directive 2009/125/EC  
which was revised in 2013.
- D241-7178 NOTICE TO USERS

## Online Document Set 1

- D223-7280 About This Machine
- D223-7281 Copy/Document Server
- D223-7282 Fax
- D223-7283 Print
- D223-7284 Scan
- D223-7285 Troubleshooting
- D223-7286 Connecting the Machine/ System Settings
- D223-7287 Security Guide
- D223-7288 Extended Feature Settings
- D223-7289 PostScript 3

## Online Document Set 2

- D223-7277 User Guide

## Online Document Set 3

- D223-7278 Operating Instructions Driver Installation Guide

## Online Document Set 4

- D223-7264 About Open Source Software License

## Online Document Set 5

- D146-7587 Notes on Security Functions
- D223-7261 Notes for Administrators:  
Using This Machine in a Network Environment  
Compliant with IEEE Std 2600.2™-2009

## <For Asia>

### Paper Documents

- D223-7207 Read This First
- D223-7236 Notes for Using This Machine Safely
- D223-7238 For Users of This Product
- D256-8998 Note to users

Model: MT-C6

Date: 25-May-17

No.: RD223041

- D223-7235 Start Guide
- D241-7237 SOFTWARE LICENSE AGREEMENT
- D241-7178 NOTICE TO USERS

## Online Document Set 1

- D223-7280 About This Machine
- D223-7281 Copy/Document Server
- D223-7282 Fax
- D223-7283 Print
- D223-7284 Scan
- D223-7285 Troubleshooting
- D223-7286 Connecting the Machine/ System Settings
- D223-7287 Security Guide
- D223-7288 Extended Feature Settings
- D223-7289 PostScript 3

## Online Document Set 2

- D223-7277 User Guide

## Online Document Set 3

- D223-7278 Operating Instructions Driver Installation Guide

## Online Document Set 4

- D223-7264 About Open Source Software License

## Online Document Set 5

- D146-7587 Notes on Security Functions
- D223-7261 Notes for Administrators:  
Using This Machine in a Network Environment  
Compliant with IEEE Std 2600.2™-2009



Reissued: 22-Nov-17

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 17-Nov-17 | No.: RD223043a |
|--------------|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** were corrected or added.

|   |   |  |  |
|---|---|--|--|
| Subject: Parts Catalog Correction: Operation Panel PCBs |   | Prepared by: K. Moriizumi  |  |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept.  |   |  |  |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

| Old part number | New part number  | Description   | Q'ty | Int | Page     | Index            |
|-----------------|--|---|------|-----|----------|------------------|
| D2411523        |  D2965430 | PCB:CHEETAH_G2:ONE_COMON:ASS'Y<br><b><i>(EU/NA/AA/KOR//TWN)</i></b> | 1    | XX  | <b>3</b> | <b><i>10</i></b> |
| D2411535        |  |   |      | XX  | <b>3</b> | <b><i>11</i></b> |
| D2411523        |  D2965431 | PCB:CHEETAH_G2:ONE_COMON:ASS'Y<br><b><i>(CHN)</i></b>               | 1    | XX  | <b>3</b> | <b><i>10</i></b> |
| D2411536        |  |   |      | XX  | <b>3</b> | <b><i>11</i></b> |

## Change/Reason:

Two Operation Panel PCBs have been combined into one PCB.



|  |  |                           |               |
|--|--|---------------------------|---------------|
| Model: MT-C6   |  | Date: 5-Dec-17            | No.: RD223045 |
| Subject: Manual Correction: SC663, SC900               |  | Prepared by: K. Moriizumi |               |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |  |                           |               |
| Classification:  | <input checked="" type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required<br><input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Product Safety <input type="checkbox"/> Other (      ) <input checked="" type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |                           |               |

## Service Manual Revision

Descriptions of SC663-00 and SC900-00 were missing from the service manual.





Please refer to the SC663-00 and SC900-00 descriptions below.

|          |   |  |
|----------|---|--|
| SC663-00 | D | IOB reset error  |
|          |   | The IOB rest signal was detected abnormal.   |
|          |   | <ul style="list-style-type: none"> <li>There is an electrical noise from the inside of machine.</li> <li>IOB defective.</li> </ul>   |
|          |   | <ul style="list-style-type: none"> <li>Cycle the main power off/on.</li> <li>Replace IOB.</li> </ul>   |
| SC900-00 | A | Electric counter error   |
|          |   | The electric total counter value is out of specification.<br>Error is detected when increasing the total counter.  |
|          |   | <ul style="list-style-type: none"> <li>Unexpected NV-RAM is attached.</li> <li>NV-RAM defective.</li> <li>NV-RAM data corrupted.</li> <li>Data written to unexpected area because of extra factor etc.</li> <li>The count requested by the SRM on receiving PRT is not completed.</li> </ul> |
|          |   | Replace the NV-RAM   |

|   |  |  |  |
|---|--|--|--|
| Model: MT-C6  |  | Date: 24-Jan-18  | No.: RD223046  |
| Subject: Trouble shooting: Smart Operation Panel Issues |  | Prepared by: Y. Taniguchi  |  |
| From: Field Quality Management Group1, FQM Dept.        |  |  |  |
| Classification:   | <input checked="" type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input checked="" type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

Notice: There are two types of electrical board construction in SOP for this model (1 board type and 2 boards type).

## Troubleshooting for the Smart Operation Panel (2 boards type)

| No | Symptom   |          | Cause  | Solution   |
|----|---|----------|--|--|
| 1  | Both the Smart Operation Panel and the blue LED on the operation panel do not turn on.<br>  | HW       | The Smart Operation Panel cannot be supplied with electrical power.  | 1. Reconnect the USB cable between the BiCU and the Smart Operation Panel.<br>2. Replace the USB cable.<br>3. Replace the Main board.<br>4. Replace the Sub board.<br>5. Replace the BiCU. |
| 2  | The Smart Operation Panel does not turn on, but the blue LED on the operation panel turns on.<br>  | HW       | The Smart Operation Panel can be supplied with electrical power (blue LED lamp), but nothing can be displayed on the LCD.  | 1. Reconnect the LCD I/F cable.<br>2. Replace the LCD unit.<br>3. Replace the Sub board.<br>4. Replace the LCD I/F cable.  |
| 3  | A splash (blue) screen or "Please wait" message stays on the display.<br><br> | SW<br>HW | The Smart Operation Panel and LCD can be supplied with electrical power, but software issues occur during the boot-up sequence.<br>Firmware or eMMC data on the Main board is defective. | 1. Update the Cheetah System firmware to the latest version in recovery mode.<br>2. Do a factory reset.<br>3. Replace the Main board.  |





HW: Hardware issue, SW: Software issue

Model: MT-C6

Date: 24-Jan-18

No.: RD223046

**Troubleshooting for the Smart Operation Panel (1 board type)**

| No | Symptom   |          | Cause   | Solution   |
|----|---|----------|---|--|
| 1  | Both the Smart Operation Panel and the blue LED on the operation panel do not turn on.<br>   | HW       | The Smart Operation Panel cannot be supplied with electrical power.   | <ol style="list-style-type: none"> <li>1. Reconnect the USB cable between the BiCU and the Smart Operation Panel.</li> <li>2. Replace the USB cable.</li> <li>3. Replace the Board.<br/>Replace the BiCU.</li> </ol> |
| 2  | The Smart Operation Panel does not turn on, but the blue LED on the operation panel turns on.<br>   | HW       | The Smart Operation Panel can be supplied with electrical power (blue LED lamp), but nothing can be displayed on the LCD.   | <ol style="list-style-type: none"> <li>1. Reconnect the LCD I/F cable.</li> <li>2. Replace the LCD unit</li> <li>3. Replace the Board</li> <li>4. Replace the LCD I/F cable.</li> </ol>                              |
| 3  | A splash (blue) screen or "Please wait" message stays on the display.<br><br> | SW<br>HW | The Smart Operation Panel and LCD can be supplied with electrical power, but software issues occur during the boot-up sequence.<br>Firmware or eMMC data on the Board is defective. | <ol style="list-style-type: none"> <li>1. Update the Cheetah System firmware in recovery mode.</li> <li>2. Do a factory reset.</li> <li>3. Replace the Board.</li> </ol>   |

HW: Hardware issue, SW: Software issue

Model: MT-C6

Date: 24-Jan-18

No.: RD223046

## Components to Check during Troubleshooting

1. Main board (2 boards type only)



2. Sub board (2 boards type only)




3. Board (1 board type only)



4. USB cable



5. Connection between USB cable and Board or Sub board






Model: MT-C6


Date: 24-Jan-18

No.: RD223046

## 6. Connection between USB cable and BiCU



## 7. LCD unit



## 8. LCD I/F cable



Model: MT-C6

Date: 24-Jan-18

No.: RD223046

## How to distinguish the type of electrical board construction

PCB construction type is distinguishable from the prefix (4 digits) of SOP parts number shown on SOP back side. "D196", "D223", "D241", "D261", "D263", "M0AJ" and "D296" are two PCBs type. Others are One PCB type.

[Example for One PCB type]



|  |   |   |  |
|--|---|---|--|
| Model: MT-C6   |   | Date: 30-Jan-18   | No.: RD223047  |
| Subject: SC555 occur due to wrong size of thermistor bracket |   | Prepared by: K.Yamamoto   |  |
| From: 1st FQM Sect., 1st FQM Dept.                           |   |   |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## SYMPTOM

SC555 occurs.

## CAUSE

The bracket for the side/rear internal thermistor is not the optimum size, which prevents the thermistor from contacting the hot roller correctly. As a result, the machine cannot detect the correct temperature of the hot roller.

## SOLUTION

Replace the bracket with the modified one (D2234195)


| Old part number | New part number | Description                   | Q'ty | Int | Note |
|-----------------|-----------------|-------------------------------|------|-----|------|
| D2234196        | D2234195        | BRACKET:THERMISTOR:INNER BACK | 1    | X/O | -    |

**Note:** The new bracket has a blue paint mark (initial lot) or has an additional hole (subsequent lots).


Old (B0654422)



New (D2234195)



or



## Cut-in Serial Numbers:

Applied to the production line from December 2016

|  |   |   |   |
|--|---|---|---|
| Model: MT-C6                                     |   | Date: 8-Feb-18  | No.: RD223048   |
| Subject: DO NOT install Legacy UI firmware v1.20 |   | Prepared by: T. Kiyohara  |   |
| From: Field Quality Management Group1, FQM Dept. |   |   |   |
| Classification:                                  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## IMPORTANT Notice about Legacy UI Firmware v1.20

- **DO NOT install** the following Legacy UI firmware on machines in the field:

**Note: These versions are no longer released/available.**

- This is because with this version, the following symptoms occur with the Smart Operation Panel when Legacy mode is used.
  - Cannot access user settings.
  - Legacy application cannot boot-up.
  - "Please wait" remains displayed.

**Affected models:** Met-C2abcdeyz, Met-C2.1abcdeyz, Met-P2, Cor-C1.5, Cor-P1.5, Brz, Ch-C2, Gim-MF1.5, Gr-C2, Gr-C3, Le-C1 and Mt-C6

- To avoid this, install Legacy UI **v1.19 or older**.

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

**RTB Reissue**

The items in ***bold italics in red*** were corrected or added.

|  |  |   |   |
|--|--|---|---|
| Subject: Service manual Revision -Capturing Debug Logs-  |  | Prepared by: A. Shigeta                   |   |
| From: 2nd Technical Support Sect., Service Strategy Dept |  |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information | <input type="checkbox"/> Action required                    |
|  | <input type="checkbox"/> Mechanical      | <input type="checkbox"/> Electrical       | <input checked="" type="checkbox"/> Service manual revision |
|  | <input type="checkbox"/> Paper path      | <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Retrofit information               |
|  | <input type="checkbox"/> Product Safety  | <input type="checkbox"/> Other (      )   | <input type="checkbox"/> Tier 2                             |

**Service Manual Correction**

Log capturing information was corrected and added in ***red*** in the following section of the Service Manual:

**6. System Maintenance > Capturing Debug Logs**

---

**Overview**

---

With this feature, you can save debug logs that are stored in the machine (HDD or operation panel) on an SD card. This function allows the Customer Engineer to save and retrieve error information for analysis. The Capturing Log feature saves debug logs for:

- Controller ***device log including operation log***
- Engine ***device log***
- Operation panel ***log***
- ***FCU device log***

**★ Important**

- In older models, a technician enabled the logging tool after a problem occurred. After that, when the problem had been reproduced, the technician was able to retrieve the debug log.
- However, this new feature saves the debug logs whenever a problem occurs, and then this log can be saved to an SD card.
- You can retrieve the debug logs with an SD card without a network.
- Analysis of the debug log is effective for problems caused by the software. Analysis of the debug log is not valid for the selection of defective parts or problems caused by hardware.
- ***Make sure to shut down and reboot the machine once before retrieving the Debug Logs. Otherwise, the latest settings may not be collected when the debug logs are retrieved.***

**Reissued : 2-Nov-18**

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

## Types of debug logs that can be saved

| Type  | Storage Timing  | Destination (maximum storage capacity)   |
|---|---|--|
| Controller debug log (GW debug log)<br><i>Controller device log including operation log</i> | <ul style="list-style-type: none"> <li>• Saved at all times</li> </ul>  | HDD (4 GB). Compressed when written to an SD card from the HDD (from 4 GB to about 300 MB)<br><i>HDD (4 GB) or SD card connected to the service slot.</i><br><i>When the data gets over 4.0 GB, the older data is deleted.</i> |
| Engine debug device log   | <ul style="list-style-type: none"> <li>• When an engine SC occurs</li> <li>• When paper feeding/output stop by jams</li> <li>• When the machine doors are opened during normal operation</li> </ul>   | HDD (up to 300 times)<br><i>HDD or SD card connected to the service slot (Up to 300 times)</i>   |
| Operation panel debug log   | <ul style="list-style-type: none"> <li>• <del>When a controller SC occurs</del></li> <li>• <del>When saving by manual operation with the Number keys and the Reset key (Press "Reset", "0", "1" and "C" (hold for 3 seconds))</del></li> <li>• When the operation unit detects an error</li> <li>• When the operation panel detects an error</li> </ul> | <del>Operation panel (400 MB / Up to 30 times)</del><br><del>When updating the firmware for the operation panel, the debug logs are erased.</del><br><i>Memory in the operation panel.</i>                                     |
| <i>FCU device log</i>   | <ul style="list-style-type: none"> <li>• <i>When a specified amount of FCU device log is stored in the FCU. If fax application is unavailable (e.g. not installed), the machine does not transfer the log.</i></li> </ul>   | <i>HDD or SD card connected to the service slot</i>  |

Debug logs are not saved when:

- Memory is being erased
- Data encryption equipment is being installed
- Firmware configuration is being changed
- There is a power outage (power cord disconnected accidentally)
- The machine is shutdown normally with the power switch and data write to the HDD cannot be completed.

For example, when shutdown starts immediately after a paper jam occurs or the front door is opened or closed, the machine needs about 5 sec. to save the debug log after the machine stops completely.

Reissued : 2-Nov-18

Model: MT-C6

Date: 9-Oct-18

No.: RD223049a

- Power supply to the HDD is off because of energy saving (engine OFF mode /STR mode)

• *When one of the following SCs occurs: SC672, SC816, SC819, SC878, SC899, SC859, SC860, SC863, or SC864*

**Note**

*The following logs are not saved:*

- *Logs related to the energy saver mode (Engine-off, suspend-mode, or other cases)*
  - *Network communication log*
  - *Logs related to NRS*
  - *IP-FAX log*
  - *Access log for unauthorized users (guests)*
- *HTTP session timeout log*
- *Auto log-out log*
- *IC card related log*
- *Authorization for Fax*

**Note**

*The default save destination is the HDD. Except when it cannot be saved to the HDD for some reason, there is no need to change from the HDD to an SD card.*

*If you want to change the save destination to an SD card, do the following.*

- 1. Set SP5-858-002 (Collect Machine Info: Save To) to "1 (SD)".*
- 2. Execute SP5-858-003 (Collect Machine Info: Make Log Trace Dir) to make a folder for the log in the SD card.*
- 3. Turn the power switch OFF and ON.*

• *It is recommended to use the SD card (8 GB) provided as a service part. The part number of the SD card that is registered as a service part is "B6455040".*

## Operation Log Security

---

The following operation logs related to security are never saved.

- User ID
- Password
- IP address
- Telephone number
- Encryption key
- Transition to SP mode

The following operation logs are never saved.

- Number keys (0 to 9) on the operation panel

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

- Soft keyboard on the touch panel display
- External keyboard

## Retrieving Debug Logs

Retrieve debug logs to identify the date of occurrence and details about problems.

- Analysis of the debug log is effective for problems caused by the software.
- Analysis of the debug log cannot identify defects in parts or problems caused by hardware.

## Procedure for Retrieving Device logs *via Operation Panel*

### ★ Important

- *Retrieve device logs to identify the date of occurrence of the problems and to find details of the problems.*
  - *e.g.: At around 8:00 am on March 10, an engine stall occurred. The operation panel does not respond. Turn the main power supply off / on.*
  - *Analysis of the device log is effective for problems caused by the software. Analysis of the device log is not valid for the selection of defective parts or problems caused by hardware.*
1. Insert the SD card into the slot on the left side of the operation panel **or the service slot**.



d223c3777

### ★ Important

*It is recommended to use the SD card (2 GBs\* or 8 GBs\*\*) provided as a service part. This is because the log data can be acquired much faster than when using commercially available SD cards.*

- *Format the SD card by using SD Formatter from Panasonic before copying the logs: [https://www.sdcard.org/downloads/formatter\\_3/](https://www.sdcard.org/downloads/formatter_3/) (free software)*
- *Insert the SD card into the machine's service slot instead of the SD slot on the side of the operation panel.*
- \* *The part number of the SD card with 2 GBs that is registered as a service part is "B6455030".*
- \*\* *The part number of the SD card with 8 GBs that is registered as a service part is "B6455040".*



Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

2. Turn ON the main power ~~then~~ Enter SP mode.

3. Enter SP mode.

4. Specify the date that the problem occurred in SP5-858-101 (Occurrence Date) by setting it to the year -month-day calendar format

• For example, if a problem occurred on February 1, 2015, the date should be set to “20150201”, as shown above.

• Be sure to confirm the date when the problem occurred before obtaining the logs.

5. Specify the number of days to collect the logs in SP5-858-102(Days of Tracing).

• “2” is set by default, which is the minimum needed for investigating the problem.

• A value of “1” to “180” can be set.


6. Execute SP 5-858-111 (Acquire All info & Logs) to copy all of the log types to an SD card. It is possible to obtain the logs separately by the following SPs.

| SP                              | Function  |
|---------------------------------|---|
| <del>5857-103</del> SP5-858-111 | All debug log<br><i>All of the information and logs that are collected by executing the SPs from SP5-858-121 to SP5-858-145, and SMC.</i> |
| SP5-858-121                     | Configuration page  |
| SP5-858-122                     | Font page   |
| SP5-858-123                     | Print settings list   |
| SP5-858-124                     | Print Error log   |
| SP5-858-131                     | Fax information (whether the fax destinations are included or not depends on the setting of SP5-858-103.)                                 |
| SP5-858-141                     | Controller log, engine log, operation panel log, FCU, and SMC.  |
| <del>5857-104</del> SP5-858-142 | Controller debug log  |
| <del>5857-105</del> SP5-858-143 | Engine debug log  |
| <del>5857-107</del> SP5-858-144 | Operation panel log   |
| SP5-858-145                     | FCU log   |
| SP5-992-001                     | SMC   |

7. After executing the SP for copying the information and/or logs, a confirmation screen will appear. To proceed with obtaining the information and/or logs, tap "Execute". When the transfer is finished, the machine will display "Completed" on the operation panel.

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



## ★ Important

- The length of time needed to transfer the debug log data can be affected by the type and format of the SD card. Formatting the SD card with Panasonic SD Formatter (freeware) is recommended.

*Transfer time may be affected by the type or format of the SD card.* The approximate time required for the transfer of the following debug logs are:


- Controller *device log* (GW *device log*): 2 to 20 min.
- Engine debug *device log*: 2 min.
- Operation *panel device log*: 2 to 20 min.

*If the estimated time is not calculated due to an error, an error code will be displayed.*

| Error Code | Description  |
|------------|--|
| -1         | <i>Other.</i>  |
| -2         | <i>No SD card is inserted in the service slot or in the SD slot on the side of the operation panel. In this case, insert an SD card into either of the SD slots.</i> |
| -3         | <i>The SD card is locked. In this case, unlock the SD card, as shown below.</i>  |

**Reissued : 2-Nov-18**

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



4. Make sure that the SD card access LED is off, then remove the SD card.

**Note**

*The process of obtaining logs fails in the following cases:*

- When the size of the logs to obtain exceeds the amount of space available on the SD card.
- When the SD card is removed while the logs are being copied to it.
- When the SD card is not formatted.

If you see the "Failed" message, remove the SD card, cycle the machine off/on, and then repeat this procedure from Step 2.

## *Procedure for Retrieving Device logs via Web Image Monitor*

1. Access the following URL and logon as an administrator:


*[http://\[IP address or host name\]/web/entry/df/websys/direct/getSysInfo.cgi](http://[IP address or host name]/web/entry/df/websys/direct/getSysInfo.cgi)*

d238m0884

2. Specify the date that the problem occurred and the number of days to download the logs. If the fax destinations need to be included in the fax information, set "On" as "Obtain Fax Destination(s) Information". Then click "Download".

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



d238m0885


## Note

- "3" is set by default for "Number of days, including date fault occurred, to obtain". However "2", which is the minimum needed for investigating the problems, is recommended for reducing the downloading time.
- "Obtain Fax Destination(s) Information" is set to "Off" by default.

3. The confirmation screen will appear and the information and/or logs will start downloading. To proceed to download the information and/or logs, wait for the open-or-save dialog to appear.

## Note

- To cancel downloading, click "Cancel".
- To reconfigure some settings, click "Download again".
- Operation panel when downloading the logs:



d238m0887

4. After a while, the open-or-save dialog will appear. Specify where to download and save the file.



d238m0888

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

**Note**

The debug logs are saved with the following file names. These names are the same as the files downloaded with SD card.

Debug logs are saved with the following file names.

| Debug Log   | Filename Format  |
|---|--|
| Controller(GW)<br><i>Controller log<br/>(mmesg)</i> | <i>/LogTrace/[the model number]/watching/[yyyymmdd_hhmmss]_[a unique value].gz</i>   |
| Engine <i>device<br/>log</i>                        | <i>/LogTrace/[Machine Serial]/engine/[yyyymmdd_hhmmss].gz</i>  |
| Operation<br>panel <i>log</i>                       | <i>/LogTrace/[the model number]/opepanel/[yyyymmdd_hhmmss].tar.gz</i>  |
| <i>SMC</i>  | <i>/LogTrace/[the model number]/smc/[the model<br/>number]_[5992XXX]_[yyyymmdd]_[hhmmss].csv</i>   |
| <i>Configuration<br/>page</i>                       | <i>/LogTrace/[the model number]/gps/ConfigurationPage/ ConfigurationPage_<br/>[yyyymmdd_hhmmss].csv</i>  |
| <i>Font page</i>                                    | <ul style="list-style-type: none"> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PCL_[the page<br/>number]_[yyyymmdd_hhmmss].jpg</i></li> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PDF_[the page<br/>number]_[yyyymmdd_hhmmss].jpg</i></li> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PS_[the page<br/>number]_[yyyymmdd_hhmmss].jpg</i></li> </ul> |
| <i>Print settings<br/>list</i>                      | <ul style="list-style-type: none"> <li><i>• /LogTrace/[the model<br/>number]/gps/PrintSettingList/PrintSettingList_RPGL_[yyyymmdd_hhmmss].txt</i></li> <li><i>• /LogTrace/[the model<br/>number]/gps/PrintSettingList/PrintSettingList_RTIF_[yyyymmdd_hhmmss].csv</i></li> </ul>   |
| <i>Error log</i>                                    | <i>/LogTrace/[the model number]/gps/ErrorLog/[yyyymmdd_hhmmss].csv</i>   |
| <i>Fax<br/>information</i>                          | <i>/LogTrace/[the model number]/faxreport/[yyyymmdd_hhmmss].csv</i>  |
| <i>FCU debug<br/>log</i>                            | <i>/LogTrace/[Machine Serial]/fcu-log/[yyyymmdd_hhmmss].gz</i>   |

|  |   |   |   |
|--|---|---|---|
| Model: MT-C6   |   | Date: 20-Nov-18   | No.: RD223050   |
| Subject: Installing Procedure of Extra Filter Unit     |   | Prepared by: K. Moriizumi   |   |
| From: 2nd Tech Service Sect., MFP/P Tech Service Dept. |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

The extra filter unit has been added to match the new BAM regulation for European models.

Please refer to the following procedures for the additional installation from the January 2019.

### Accessory Check

The additional accessories inside of the tray 1 as below.




Check the accessories and their quantities against the list:

Model: MT-C6

Date: 20-Nov-18

No.: RD223050

| No. | Description        | Q'ty |
|-----|--------------------|------|
| 1.  | Extra Filter Cover | 1    |
| 2.  | Bracket            | 1    |
| 3.  | Screw              | 1    |
| 4.  | Extra Filter Unit  | 1    |



Model: MT-C6

Date: 20-Nov-18

No.: RD223050

**Installation extra filter unit**


1. Remove the filter cover. (2 screws)



2. Attach the screw bracket (1 screw).



3. Attach the extra filter unit. (1 screw and 1 hook)





4. Attach the extra filter cover. (2 screw)



# Technical Bulletin

PAGE: 1/1

|  |   |  |   |
|--|---|--|---|
| Model: MT-C6   |   | Date: 21-Dec-18  | No.: RD223051   |
| Subject: Service manual Revision -Memory specification-  |   | Prepared by: A. Shigeta  |   |
| From: 2nd Technical Support Sect., Service Strategy Dept |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (      ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Service Manual Correction

Memory information was corrected in *red* in the following section of the Service Manual:

### 1. Machine Specifications > General Specifications

---

## Copier

---

## Specification

---

|              |                  |
|--------------|------------------|
| Memory       | 4 GB <i>2 GB</i> |
| HDD Capacity | 320 GB           |

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

## RTB Reissue

The items in ***bold italics in red*** were corrected or added.

|  |   |   |   |
|--|---|---|---|
| Subject: Service manual Revision -Capturing Debug Logs-  |   | Prepared by: A. Shigeta   |   |
| From: 2nd Technical Support Sect., Service Strategy Dept |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Service Manual Correction

Log capturing information was corrected and added in ***red*** in the following section of the Service Manual:

### 6. System Maintenance > Capturing Debug Logs

## Overview

With this feature, you can save debug logs that are stored in the machine (HDD or operation panel) on an SD card. This function allows the Customer Engineer to save and retrieve error information for analysis. The Capturing Log feature saves debug logs for:

- Controller ***device log including operation log***
- Engine ***device log***
- Operation panel ***log***
- ***FCU device log***

### ★ Important

- In older models, a technician enabled the logging tool after a problem occurred. After that, when the problem had been reproduced, the technician was able to retrieve the debug log.
- However, this new feature saves the debug logs whenever a problem occurs, and then this log can be saved to an SD card.
- You can retrieve the debug logs with an SD card without a network.
- Analysis of the debug log is effective for problems caused by the software. Analysis of the debug log is not valid for the selection of defective parts or problems caused by hardware.
- ***Make sure to shut down and reboot the machine once before retrieving the Debug Logs. Otherwise, the latest settings may not be collected when the debug logs are retrieved.***

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

## Types of debug logs that can be saved

| Type  | Storage Timing  | Destination (maximum storage capacity)   |
|---|---|--|
| Controller debug log (GW debug log)<br><i>Controller device log including operation log</i> | <ul style="list-style-type: none"> <li>Saved at all times</li> </ul>  | HDD (4 GB). Compressed when written to an SD card from the HDD (from 4 GB to about 300 MB)<br><i>HDD (4 GB) or SD card connected to the service slot.</i><br><i>When the data gets over 4.0 GB, the older data is deleted.</i> |
| Engine debug <i>device</i> log  | <ul style="list-style-type: none"> <li>When an engine SC occurs</li> <li>When paper feeding/output stop by jams</li> <li>When the machine doors are opened during normal operation</li> </ul>   | HDD (up to 300 times)<br><i>HDD or SD card connected to the service slot (Up to 300 times)</i>   |
| Operation panel debug log   | <ul style="list-style-type: none"> <li><del>When a controller SC occurs</del></li> <li><del>When saving by manual operation with the Number keys and the Reset key (Press "Reset", "0", "1" and "C" (hold for 3 seconds))</del></li> <li>When the operation unit detects an error</li> <li>When the operation panel detects an error</li> </ul> | <del>Operation panel (400 MB / Up to 30 times)</del><br><del>When updating the firmware for the operation panel, the debug logs are erased.</del><br><i>Memory in the operation panel.</i>                                     |
| <i>FCU device log</i>   | <ul style="list-style-type: none"> <li><i>When a specified amount of FCU device log is stored in the FCU. If fax application is unavailable (e.g. not installed), the machine does not transfer the log.</i></li> </ul>   | <i>HDD or SD card connected to the service slot</i>  |

Debug logs are not saved when:

- Memory is being erased
- Data encryption equipment is being installed
- Firmware configuration is being changed
- There is a power outage (power cord disconnected accidentally)
- The machine is shutdown normally with the power switch and data write to the HDD cannot be completed.

For example, when shutdown starts immediately after a paper jam occurs or the front door is opened or closed, the machine needs about 5 sec. to save the debug log after the machine stops completely.

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

- Power supply to the HDD is off because of energy saving (engine OFF mode /STR mode)

• *When one of the following SCs occurs: SC672, SC816, SC819, SC878, SC899, SC859, SC860, SC863, or SC864*

**Note**

*The following logs are not saved:*

- *Logs related to the energy saver mode (Engine-off, suspend-mode, or other cases)*
  - *Network communication log*
  - *Logs related to NRS*
  - *IP-FAX log*
  - *Access log for unauthorized users (guests)*
- *HTTP session timeout log*
- *Auto log-out log*
- *IC card related log*
- *Authorization for Fax*

**Note**

*The default save destination is the HDD. Except when it cannot be saved to the HDD for some reason, there is no need to change from the HDD to an SD card.*

*If you want to change the save destination to an SD card, do the following.*

- 1. Set SP5-858-002 (Collect Machine Info: Save To) to "1 (SD)".*
  - 2. Execute SP5-858-003 (Collect Machine Info: Make Log Trace Dir) to make a folder for the log in the SD card.*
  - 3. Turn the power switch OFF and ON.*
- *It is recommended to use the SD card (8 GB) provided as a service part. The part number of the SD card that is registered as a service part is "B6455040".*

## Operation Log Security

The following operation logs related to security are never saved.

- User ID
- Password
- IP address
- Telephone number
- Encryption key
- Transition to SP mode

The following operation logs are never saved.

- Number keys (0 to 9) on the operation panel

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

- Soft keyboard on the touch panel display
- External keyboard

## Retrieving Debug Logs

Retrieve debug logs to identify the date of occurrence and details about problems.

- Analysis of the debug log is effective for problems caused by the software.
- Analysis of the debug log cannot identify defects in parts or problems caused by hardware.

## Procedure for Retrieving Device logs *via Operation Panel*

### ★ Important

- *Retrieve device logs to identify the date of occurrence of the problems and to find details of the problems.*
  - *e.g.: At around 8:00 am on March 10, an engine stall occurred. The operation panel does not respond. Turn the main power supply off / on.*
  - *Analysis of the device log is effective for problems caused by the software. Analysis of the device log is not valid for the selection of defective parts or problems caused by hardware.*
1. Insert the SD card into the slot on the left side of the operation panel **or the service slot**.



d223c3777

### ★ Important

*It is recommended to use the SD card (2 GBs\* or 8 GBs\*\*) provided as a service part. This is because the log data can be acquired much faster than when using commercially available SD cards.*

- *Format the SD card by using SD Formatter from Panasonic before copying the logs: [https://www.sdcard.org/downloads/formatter\\_3/](https://www.sdcard.org/downloads/formatter_3/) (free software)*
- *Insert the SD card into the machine's service slot instead of the SD slot on the side of the operation panel.*
- \* *The part number of the SD card with 2 GBs that is registered as a service part is "B6455030".*
- \*\* *The part number of the SD card with 8 GBs that is registered as a service part is "B6455040".*

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

2. Turn ON the main power ~~then~~ Enter SP mode.

3. Enter SP mode.

4. Specify the date that the problem occurred in SP5-858-101 (Occurrence Date) by setting it to the year -month-day calendar format

• For example, if a problem occurred on February 1, 2015, the date should be set to “20150201”, as shown above.

• Be sure to confirm the date when the problem occurred before obtaining the logs.

5. Specify the number of days to collect the logs in SP5-858-102(Days of Tracing).

• “2” is set by default, which is the minimum needed for investigating the problem.

• A value of “1” to “180” can be set.


6. Execute SP 5-858-111 (Acquire All info & Logs) to copy all of the log types to an SD card. It is possible to obtain the logs separately by the following SPs.

| SP                              | Function  |
|---------------------------------|---|
| <del>5857-103</del> SP5-858-111 | All debug log<br><i>All of the information and logs that are collected by executing the SPs from SP5-858-121 to SP5-858-145, and SMC.</i> |
| SP5-858-121                     | Configuration page  |
| SP5-858-122                     | Font page   |
| SP5-858-123                     | Print settings list   |
| SP5-858-124                     | Print Error log   |
| SP5-858-131                     | Fax information (whether the fax destinations are included or not depends on the setting of SP5-858-103.)                                 |
| SP5-858-141                     | Controller log, engine log, operation panel log, FCU, and SMC.  |
| <del>5857-104</del> SP5-858-142 | Controller debug log  |
| <del>5857-105</del> SP5-858-143 | Engine debug log  |
| <del>5857-107</del> SP5-858-144 | Operation panel log   |
| SP5-858-145                     | FCU log   |
| SP5-992-001                     | SMC   |

7. After executing the SP for copying the information and/or logs, a confirmation screen will appear. To proceed with obtaining the information and/or logs, tap "Execute". When the transfer is finished, the machine will display "Completed" on the operation panel.

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



## ★ Important

- The length of time needed to transfer the debug log data can be affected by the type and format of the SD card. Formatting the SD card with Panasonic SD Formatter (freeware) is recommended.

*Transfer time may be affected by the type or format of the SD card.* The approximate time required for the transfer of the following debug logs are:

- Controller *device log* (GW *device log*): 2 to 20 min.
- Engine debug *device log*: 2 min.
- Operation *panel device log*: 2 to 20 min.


*If the estimated time is not calculated due to an error, an error code will be displayed.*

| Error Code | Description  |
|------------|--|
| -1         | <i>Other.</i>  |
| -2         | <i>No SD card is inserted in the service slot or in the SD slot on the side of the operation panel. In this case, insert an SD card into either of the SD slots.</i> |
| -3         | <i>The SD card is locked. In this case, unlock the SD card, as shown below.</i>  |



Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



4. Make sure that the SD card access LED is off, then remove the SD card.

**Note**

*The process of obtaining logs fails in the following cases:*

- When the size of the logs to obtain exceeds the amount of space available on the SD card.
- When the SD card is removed while the logs are being copied to it.
- When the SD card is not formatted.

If you see the "Failed" message, remove the SD card, cycle the machine off/on, and then repeat this procedure from Step 2.

## Procedure for Retrieving Device logs via Web Image Monitor

1. Access the following URL and logon as an administrator:

[http://\[IP address or host name\]/web/entry/df/websys/direct/getSysInfo.cgi](http://[IP address or host name]/web/entry/df/websys/direct/getSysInfo.cgi)

d238m0884

2. Specify the date that the problem occurred and the number of days to download the logs. If the fax destinations need to be included in the fax information, set "On" as "Obtain Fax Destination(s) Information". Then click "Download".

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|



d238m0885


**Note**

- "3" is set by default for "Number of days, including date fault occurred, to obtain". However "2", which is the minimum needed for investigating the problems, is recommended for reducing the downloading time.
- "Obtain Fax Destination(s) Information" is set to "Off" by default.

3. The confirmation screen will appear and the information and/or logs will start downloading. To proceed to download the information and/or logs, wait for the open-or-save dialog to appear.

**Note**

- To cancel downloading, click "Cancel".
- To reconfigure some settings, click "Download again".
- Operation panel when downloading the logs:



d238m0887

4. After a while, the open-or-save dialog will appear. Specify where to download and save the file.



d238m0888

Reissued : 2-Nov-18

|              |                |                |
|--------------|----------------|----------------|
| Model: MT-C6 | Date: 9-Oct-18 | No.: RD223049a |
|--------------|----------------|----------------|

**Note**

*The debug logs are saved with the following file names. These names are the same as the files downloaded with SD card.*

Debug logs are saved with the following file names.

| Debug Log   | Filename Format  |
|---|--|
| Controller(GW)<br><i>Controller log<br/>(mmesg)</i> | <i>/LogTrace/[the model number]/watching/[yyyymmdd_hhmmss]_[a unique value].gz</i>   |
| Engine <i>device<br/>log</i>                        | <i>/LogTrace/[Machine Serial]/engine/[yyyymmdd_hhmmss].gz</i>  |
| Operation<br>panel <i>log</i>                       | <i>/LogTrace/[the model number]/opepanel/[yyyymmdd_hhmmss].tar.gz</i>  |
| <i>SMC</i>  | <i>/LogTrace/[the model number]/smc/[the model number]_[5992XXX]_[yyyymmdd]_[hhmmss].csv</i>   |
| <i>Configuration<br/>page</i>                       | <i>/LogTrace/[the model number]/gps/ConfigurationPage/ ConfigurationPage_[yyyymmdd_hhmmss].csv</i>   |
| <i>Font page</i>                                    | <ul style="list-style-type: none"> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PCL_[the page number]_[yyyymmdd_hhmmss].jpg</i></li> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PDF_[the page number]_[yyyymmdd_hhmmss].jpg</i></li> <li><i>• /LogTrace/[the model number]/gps/FontPage/FontPage_PS_[the page number]_[yyyymmdd_hhmmss].jpg</i></li> </ul> |
| <i>Print settings<br/>list</i>                      | <ul style="list-style-type: none"> <li><i>• /LogTrace/[the model number]/gps/PrintSettingList/PrintSettingList_RPGL_[yyyymmdd_hhmmss].txt</i></li> <li><i>• /LogTrace/[the model number]/gps/PrintSettingList/PrintSettingList_RTIF_[yyyymmdd_hhmmss].csv</i></li> </ul>   |
| <i>Error log</i>                                    | <i>/LogTrace/[the model number]/gps/ErrorLog/[yyyymmdd_hhmmss].csv</i>   |
| <i>Fax<br/>information</i>                          | <i>/LogTrace/[the model number]/faxreport/[yyyymmdd_hhmmss].csv</i>  |
| <i>FCU debug<br/>log</i>                            | <i>/LogTrace/[Machine Serial]/fcu/[yyyymmdd_hhmmss].gz</i>   |

Reissued : 16-Jan-19

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 20-Nov-18 | No.: RD223050a |
|--------------|-----------------|----------------|

## RTB Reissue

The items in ***bold italics*** were corrected or added.

|  |   |  |   |
|--|---|--|---|
| Subject: Installing Procedure of Etra Filter Unit      |   | Prepared by: K. Moriizumi  |   |
| From: 2nd Tech Service Sect., MFP/P Tech Service Dept. |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (      ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

***For the model MT-C6a/c only. (MP 6503 and MP 7503)***

The extra filter unit has been added to match the new BAM regulation for European models.

Please refer to the following procedures for the additional installation from the January 2019.

## Accessory Check

The additional accessories inside of the tray 1 as below.




Check the accessories and their quantities against the list:

Reissued : 16-Jan-19

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 20-Nov-18 | No.: RD223050a |
|--------------|-----------------|----------------|

| No. | Description        | Q'ty |
|-----|--------------------|------|
| 1.  | Extra Filter Cover | 1    |
| 2.  | Bracket            | 1    |
| 3.  | Screw              | 1    |
| 4.  | Extra Filter Unit  | 1    |



Reissued : 16-Jan-19

Model: MT-C6

Date: 20-Nov-18

No.: RD223050a

## Installation extra filter unit

1. Remove the filter cover. (2 screws)



2. Attach the screw bracket (1 screw).



3. Attach the extra filter unit. (1 screw and 1 hook)



Reissued : 16-Jan-19

|              |                 |                |
|--------------|-----------------|----------------|
| Model: MT-C6 | Date: 20-Nov-18 | No.: RD223050a |
|--------------|-----------------|----------------|

4. Attach the extra filter cover. (2 screw)



# Technical Bulletin

PAGE: 1/1

|  |   |  |   |
|--|---|--|---|
| Model: MT-C6   |   | Date: 21-Dec-18  | No.: RD223051   |
| Subject: Service manual Revision -Memory specification-  |   | Prepared by: A. Shigeta  |   |
| From: 2nd Technical Support Sect., Service Strategy Dept |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (      ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Service Manual Correction

Memory information was corrected in *red* in the following section of the Service Manual:

### 1. Machine Specifications > General Specifications

---

## Copier

---

## Specification

---

|              |                  |
|--------------|------------------|
| Memory       | 4 GB <i>2 GB</i> |
| HDD Capacity | 320 GB           |



|  |   |   |   |
|--|---|---|---|
| Model: MT-C6                                     |   | Date: 7-Jan-19  | No.: RD223052   |
| subject: DO NOT install Legacy UI v1.23          |   | Prepared by: T. Kiyohara  |   |
| From: Field Quality Management Group1, FQM Dept. |   |   |   |
| Classification:                                  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input checked="" type="checkbox"/> Tier 2 |

## IMPORTANT Notice about Legacy UI v1.23

- **DO NOT install** the following Legacy UI firmware on machines in the field.

**Note:** These versions are no longer released/available.

| Firmware  | version     | P/N              |
|-----------|-------------|------------------|
| Legacy UI | <b>1.23</b> | D2411439_for EDC |


### Affected models:

Brz-MF1/Ch-C2/Ch-C2Pro/Cor-C1.5/Cor-P1.5/Gim-MF1.5dM/Gr-C2\_ch/Gri-C3/Lef-C1b/MT-C6/Met-C2.1abyz/Met-C2.1cde/Met-C2abyz/Met-C2cde/Met-P2(EXP)

- This is because there is a bug with the operation panel feature.

Specifically:

With firmware combination **#3** below, the Home button is not displayed, making it impossible to switch between applications.



| Comb. | CheetahSystem | LegacyUI      | Result |
|-------|---------------|---------------|--------|
| 1     | 1.30 or older | 1.22 or older | Good   |

# Technical Bulletin

PAGE: 2/2

|              |                |               |
|--------------|----------------|---------------|
| Model: MT-C6 | Date: 7-Jan-19 | No.: RD223052 |
|--------------|----------------|---------------|

|          |                      |                      |                       |
|----------|----------------------|----------------------|-----------------------|
| 2        | 1.31 or newer        | 1.22 or older        | Good                  |
| <b>3</b> | <b>1.30 or older</b> | <b>1.23 or newer</b> | <b>Problem occurs</b> |
| 4        | 1.31 or newer        | 1.23 or newer        | Good                  |

- To ensure this does not occur, ~~downgrade the Legacy UI to ver. 1.22.~~ **Update the Cheetah System to 1.31 or newer.**

|  |   |  |   |
|--|---|--|---|
| Model: Martini-C6  |   | Date: 25-Jun-19  | No.: RD223053   |
| Subject: Parts Catlog Correction: CTL board and Firmware |   | Prepared by: Akira Shigeta   |   |
| From: 2nd Tech Service Sect., MFP/P Tech Service Dept.   |   |  |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input checked="" type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5 |

The controller boards have been changed with the System/Copy firmware.

| Old part number | New part number | Description                | Q'ty | Int |
|-----------------|-----------------|----------------------------|------|-----|
| D2235330        | D2235334        | PCB:SERVICE:CTL:M-C6_A_EXP | 1    | O/O |
| D2235331        | D2235335        | PCB:SERVICE:CTL:M-C6_C_EXP | 1    | O/O |
| D2235332        | D2235336        | PCB:SERVICE:CTL:M-C6_E_EXP | 1    | O/O |

And System/Copy Firmware Version has been changed as below.

D2235540     ->     D2235565

Version 1.17     Version 1.18

## Caution

There is interchangeability between the new CTL board and the firmware.

Old System/Copy firmware (version 1.17) cannot be used for new CTL board.

If you use a new CTL board, do not downgrade the System/Copy firmware to version 1.17.

If the old System firmware is installed to the new CTL board, SC878 (TPM authentication error) will occur.

If SC878 occurs after downgrading the firmware, the CTL board has to be replaced to solve the SC878.

## Change/Reason:

An IC on the CTL board has been discontinued. The new IC is not compatible with the old one and required a firmware change.

|              |                 |               |
|--------------|-----------------|---------------|
| Model: MT-C6 | Date: 19-Sep-19 | No.: RD223054 |
|--------------|-----------------|---------------|

|  |   |   |   |
|--|---|---|---|
| Subject: Service manual Revision -SC720-80-              |   | Prepared by: A. Shigeta   |   |
| From: 2nd Technical Support Sect., Service Strategy Dept |   |   |   |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

## Service Manual Correction

The description in **red** for SC720-80 was corrected in the following section of the Service Manual:

### 7. Troubleshooting > SC700: Peripherals

#### SC 700: Peripherals

|          |   |  |
|----------|---|--|
| SC720-80 | D | Overload protection circuit error 3 (3K/2K Finisher)   |
|          |   | A blown fuse interrupted the overload protection circuit.  |
|          |   | <ul style="list-style-type: none"> <li>• Interlock power circuit harness, switch is loose, broken, defective.</li> <li>• Motor harness, connector is loose, broken, or defective.</li> <li>• Solenoid harness, connector is loose, broken, or defective.</li> <li>• Solenoid defective.</li> <li>• Motor defective.</li> </ul>   |
|          |   | <ul style="list-style-type: none"> <li>• Inspect the interlock power protection circuit harness, connector, and confirm that switch is installed correctly.</li> <li>• Inspect all motor, solenoid harnesses, connectors and replace if damaged.</li> <li>• <del>Use SP6007 (ADF Input Check) and SP6008 (ADF Output Check) to check the operation of all finisher motors, solenoids and replace if defective.</del></li> <li>• Inspect main board harnesses, connectors.</li> <li>• <del>Replace ADF main board.</del></li> </ul> |

|   |   |   |   |
|---|---|---|---|
| Model: MT-C6  |   | Date: 16-Oct-19   | No.: RD223055   |
| Subject: Service Manual Revision -Fusing SC Clear-      |   | Prepared by: A. Shigeta   |   |
| From: OC Technical Support Sect., Service Strategy Dept |   |   |   |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

### Service Manual Correction

The descriptions in **red** are corrected in the following section of the Service Manual:

## 4. Replacement and Adjustment > Before You Begin

### Important SP Codes: Machine Information, Servicing

Here are quick summaries of SP codes that give you useful information about the machine, and some common SP codes you will need during the maintenance.

#### Commonly Used During Servicing

| Item            | SP No.      | Function  |
|-----------------|-------------|---|
| Fusing SC clear | <b>5810</b> | Fusing unit SC errors disable the machine until the problem is corrected. <b>Do this SP to release the machine interface for servicing. Execute the CE reset by entering and exiting the SP mode. After exiting the SP mode, power cycle the machine.</b> |

## 7. Troubleshooting > Self-Diagnostic Mode

### Service Call Codes

#### Service Call Conditions

| Level | Display  | How to reset   |
|-------|--|--|
| A     | Fatal error. The SC is displayed on the operation panel, and the machine cannot be used (safety related SC). | Execute CE reset <b>with SP5810</b> by <b>entering and exiting the SP mode</b> , and then <b>cycle the machine off/on power cycle the machine.</b> |
| B     | When a function is selected, the SC is displayed on the operation panel, and the machine cannot be used.     | <b>Cycle the machine off/on. Power cycle the machine.</b>  |
| C     | No display on the operation panel, and the machine can be used.  | Count only logging.  |
| D     | The SC is displayed on the operation panel, and the machine cannot be used (machine-error SC).               | <b>Cycle the machine off/on. Power cycle the machine.</b>  |

## 7. Troubleshooting > Service Call Conditions

### Service Call Conditions

There are 4 levels of service call conditions.

| Level | Definition   | Reset Procedure  |
|-------|--|--|
| A     | Fusing unit SCs displayed on the operation panel. The machine is disabled. The user cannot reset the SC.   | This is a fatal error. The machine cannot be used until the service technician <del>releases it for servicing with SP5810</del> excuses CE reset by entering and exiting the SP mode, solves the problem, and then <del>cycles the machine off/on</del> power cycle the machine. |
| B     | SCs that disable only the features that use the defective item. Although these SCs are not shown to the user under normal conditions, they are displayed on the operation panel only when the defective feature is selected. | <del>Turn the main power switch off/on.</del> Power cycle the machine.   |
| C     | SCs that are not shown on the operation panel. They are internally logged.   | Logging only. The SC code is logged but not displayed.   |
| D     | Cycling the machine off/on resets SCs displayed on the operation panel. These are re-displayed if the error occurs again.  | <del>Cycle the machine off/on</del> Power cycle the machine with the power switch.   |

## 7. Troubleshooting > SC540 to SC545

### Before You Begin

This section is a summary of some of the most common fusing unit SC codes that require your attention.

- These are fatal fusing unit errors. Once one of these SC codes appears, the machine cannot be used until the service technician ~~releases it for servicing with SP5810~~ clears the error by entering and exiting the SP mode, solves the problem, and then ~~cycle the machine off/on~~ power cycle the machine.
- There are three machines in this series (D223, D224, and D225). Make sure all replacement parts are the correct ones for the machine you are servicing.

|              |                 |               |
|--------------|-----------------|---------------|
| Model: MT-C6 | Date: 18-Oct-19 | No.: RD223056 |
|--------------|-----------------|---------------|

|   |   |  |  |
|---|---|--|--|
| Subject: Part number for Developer Type 24              |   | Prepared by: A. Shigeta  |  |
| From: OC Technical Support Sect., Service Strategy Dept |   |  |  |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

**Applied models:** MT-C1/C2/C3/C3.5/C4/C5/C6

**Change:** The service part number for the developer was changed.

**Reason:** The developer for the NA market will be supplied from RCL.

| Old part number | New part number | Description        | Q'ty | Int | Target Destination |
|-----------------|-----------------|--------------------|------|-----|--------------------|
| B0649645        | B0649640        | DEV TYPE 24 BK PRT | 1    | O/O | NA                 |

|   |   |   |   |
|---|---|---|---|
| Model: MT-C6  |   | Date: 4-Dec-19  | No.: RD223057   |
| Subject: Service Manual Revision: NVRAM replacement procedure |   | Prepared by: A. Shigeta   |   |
| From: OC Technical Support Sect., Service Strategy Dept       |   |   |   |
| Classification:   | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input checked="" type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |


## Service Manual Correction

The description for the NVRAM replacement procedure was corrected, marked in **red**, in the following section of the Service Manual:

### 4. Replacement and Adjustment > PCBs, HDD

#### BICU NVRAM

1. Refer to the SMC report provided with the machine at installation.
2. Do **SP5990-001** to print out a complete, current SMC report.
3. Turn the machine off.
4. Remove the SD card slot cover, insert an SD card in SD Card Slot 2, and then turn the machine on.
5. Do **SP5824-001** (NVRAM Data Upload) to copy the data from NVRAM onto the SD card.
6. Turn the machine off, and then unplug the machine from its power source.
7. Remove the upper rear cover and controller box cover. page 488
8. Remove the BICU. page 872
9. Replace the old NVRAM on the BICU with the new NVRAM.



d223c3467

10. Connect the machine to its power source, and then turn the machine on.
11. Open **SP5131**, and then select your location.



Model: MT-C6

Date: 4-Dec-19

No.: RD223057

12. Enter the ID number for the new NVRAM.

**Note**

- ~~This is not the same number entered for the NVRAM with **SP5811-04** (Machine Serial Number Set — Set BCU).~~
- You have to enter the same number as SP5811-04 (Machine Serial Number Set - Set BCU).
- Contact your supervisor for instructions on how to procure and enter this number. If this number is not entered correctly, the machine will return SC195-00 or display "Fusing Unit Setting Error."

13. Power cycle the machine.

14. Insert into SD Card Slot 2 the SD card with the data you copied earlier with **SP5824**, and then do **SP5825** (NVRAM Download) to download (copy) the data to the new NVRAM.

15. Turn the machine off and remove the SD card from SD Card Slot 2.

16. Turn the machine on.

17. Use the User Tools and SP code settings as needed.

18. Power cycle the machine to enable the settings.