## Technical Bulletin

PAGE:	1/34
-------	------

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2			Date: 31-Jun-	-08	No.: RD257000e
Subject: Troubleshooting			Prepared by	: H. Kame	da, H. Kobayashi
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting	☐ Part inf	ormation	☐ Action	required
	☐ Mechanical	☐ Electric	al	☐ Service	ce manual revision
	☐ Paper path	Transm	nit/receive	☐ Retrof	fit information
	☐ Product Safety	Other (	)		

This bulletin is a troubleshooting guide for symptoms that have occurred in the past, all with known solutions. For most items below, there are related MBs and RTBs containing modification details and adjustment procedures.

**Note:** This RTB is numbered "000" since the information contained in it has already been announced.

## Technical Bulletin

**PAGE: 2/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2	Date: 31-Jun-08	No.: RD257000e

## **Table of contents**

1.	Paper Feed Errors 5 Wrong paper size Paper size not recognized Paper mismatch Poor feeding Jam Custom paper
2.	Copy Process
3.	Connectivity
4.	Printing/Scanning
5.	Operation Panel

Buttons active/inactive at the wrong time

# Technical Bulletin

**PAGE: 3/34** 

Model: Model Ch-C2	Date: 31-Jun-08 No.: RD257000e
Wrong screen displayed Reboots Applications appear unexpectedly Resets to default Wrong paper size displayed Wrong value displayed Icon missing Icon not correct Button missing Program missing Cannot exit screen Touch panel not responding Panel does not turn on LEDs Blue screen Black screen 'Please wait' Wording errors Legacy mode	
6. Security	18
7. Error Codes and Messages	50, 583, 621, 672, 673, 687, 720, 721, 816, 819, 843,
8. Optional Units	25

## Technical Bulletin

PAGE: 4/34

Updated: End of June 2018: Changes in bold italics

M	lodel: Model Ch-C2	Date: 31-Jun-08	No.: RD257000e
9.	Image Problems		29
10.	Mechanical/Electrical Fusing cleaning unit Drawer Power stops suddenly Motor does not stop Noise		30
11.	Others		31

# Technical Bulletin

PAGE: 5/34

**Updated: End of June 2018:** Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 1. Paper Feed Errors

Subject	Symptom	RTB#	Cause	Solution	Note
Wrong	The paper size of the	D259	MediaPrtScn for	Install version 1.17 or	
paper size	bypass tray set from a	022k	eDC firmware	later	
	widget is not applied to print jobs				
Wrong paper size	When printing via AirPrint	D258 5778F	PDF firmware	Install version 1.03 or later	
Wrong paper size	If a pre-requisite is not installed and the pre-requisite instruction page gets printed, it is falsely printed on 8.5 x 11 size paper and the B/w counter counts up.	Service	Pack 01	Color Controller E-24B Ver.1.0 firmware	
Paper size not recognized	The engine does not recognize the paper size		atch FIT 101721960 P1 FIT101716374 fo		
Paper mismatch	When using custom paper, after backing up and restoring the paper library	D261 5760J	System/Copy firmware	Install version 1.07 or later	
Paper	When A4 SEF printing		atch FIT 101721960		
mismatch	specifies a paper tray for slip sheets	Install S	P1 FIT101716374 for	r E-44B	
Poor feeding	Texture paper from the mainframe trays	D261 5760J	System/Copy firmware	Install version 1.07 or later	
Jam	Paper caught between the paper guide and the shift tray.	D3CH 5300S	Finisher_SR4120/ 4130 firmware	Install version 01.120:05 or later	
Jam	Cover Interposer Tray CI4020 (D712) + Multi- Folding Unit FD4000 (D615) + Booklet Finisher SR5080 (D3CA) or Finisher SR5070 (D3CB); after the last sheet of a job is fed from the Cover Interposer	D712 5510C	Inserter_CI4020 firmware	Install version 02.020:04 or later	
Jam	Jam 29	D257 035	Curled paper hits the edge of the gate pawl sheet in the paper exit unit, or jammed paper hits this edge when a jam is cleared	If the machine does not print out many solid images, remove the gate pawl sheet. If the machine prints out many solid images, replace the gate pawl with the new part (D2587048)	
Jam	Jam153/159/167 with corner stapling	D258 5522	Engine firmware	Install version 1.13:02 or later	
Jam	JAM154 or JAM155 when printing a booklet on A3 paper	D3CH 5300T	Finisher_SR4120 /4130 firmware	Install version 01.130:05 or later	

# Technical Bulletin

**PAGE: 6/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Custom paper	The minimum and maximum settable	D241 1443T	SimpleCopy firmware	Install version 1.21 or later	
	values of a custom paper size are wrong if the unit of measurement is set to millimeters	D241 1447T	MediaPrtScn firmware	Install version 1.20 or later	

# Technical Bulletin

**PAGE: 7/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 2. Copy Process

Subject	Symptom	RTB#	Cause	Solution	Note
Fusing	If the machine receives a job that prints at low speed, the fusing lamps do not turn on and fusing is not done.	D257 001c	Engine firmware	Install version 1.08:02 or later	



# Technical Bulletin

**PAGE: 8/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 3. Connectivity

Subject	Symptom	RTB#	Cause	Solution	Note
@Remote	@Remote registration via external appliances does not work	D257 001b	Engine firmware	Install version 1.07:02 or later	
Network connection	If the device has not been for a while, functions that require a network connection fail.	D257 010a	Network Support firmware	Install version 16.44 or later	
Machine goes off line	If log tracing on Web Image Monitor is cancelled just after using the function	D258 5760Q D261 5760P	System/Copy firmware	Install version 1.12 or later	
Fax	Fax Memory Unit Type M26 is installed: Part of a fax image is missing (sending or receiving)	D257 020	Communication error between the Fax Control Unit and the Fax Memory Unit.	Replace the Fax Memory Unit with the modified one (P/N D2429901)	
Fax	Cannot send or receive	D257 022	If invalid data is received into fax memory, the machine cannot copy the data to the HDD, and continues to retry for up to 72 hours. As a result, the fax memory is locked.	Do both of the following: Update the GWFCU3.8- 14 firmware to version 02.00.00 Set bit 2 of Fax SP1- 104-003 to "0" ("Delete invalid data").	
Fax	Sending a fax using AirPrint causes an error on the first page	D257 004b	Fax firmware	Install version 04.00.00 or later	
Fax	Wrong fax application starts	D259 012s	Cheetah System firmware	Install version 1.20 or later	
Fax	Fax function does not work if the SNTP time setting and STR setting are enabled	D258 5762G	Fax firmware	Install version 05.00.00 or later	
Fax	The machine cannot receive an IP-FAX from a Canon machine	D258 5763E	Remote Fax firmware	Install version 04.00.00 or later	
Fax	A sending error occurs with PC-FAX	D258 5763E	Remote Fax firmware	Install version 04.00.00 or later	
Fax	Freezes when printing a received fax	D258 5762H	Fax firmware	Install version 06.00.00 or later	
Fax	Cannot be transmitted if Global Scan is installed	D258 5780L D258 5780L	Java VM v12 for eDC Java VM v12 Update Tool	Install version 12.56.00 or later Install version 12.56.00 or later	
Fax	If temporary memory overflows when storing a fax, the machine cannot use fax for two days	D258 5755F	GWFCU3.8- 14(WW) firmware	Install version 04.00.00 or later	

# Technical Bulletin

**PAGE: 9/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Fax	If temporary memory	D258	GWFCU3.8-	Install version 04.00.00	
	overflows when the	5755F	14(WW) firmware	or later	
	machine receives a fax,				
	fax reception is canceled				
	and the Job Log records a				
_	user cancellation	D0=0			
Fax	When sending a fax via	D258 5762J	Fax firmware	Install version 07.00.00	
	SmartSDK, images are	5/62J		or later	
	missing or output at the wrong size				
Fax	When Hook Dial is	D258	Fax firmware	Install version 07.00.00	
ιαλ	pressed or when Manual	5762J	i ax iiiiiwaie	or later	
	Entry is selected, the	37020		or later	
	SmartFax application				
	crashes				
Fax	Cannot get the fax	D258	Network Support	Install version 16.50 or	
	transmission result using	5769K	firmware	later	
	FTP				
Email	When a group with 500	D259	SimpleScan for	Install version 1.10 or	
	email destinations is	030h	eDC firmware	later	
	selected in Quick				
	Scanner, email addresses				
	in that group cannot be				
0	selected	DOES	AAA ballaad C	In tall was in 100	
Cannot	Scanned data as PDF file	D258	Web Uapi firmware	Install version 1.06 or	
download	using Chrome to download from a URL	5766E	Mob Honi firm	later	
	download Holli a URL	D261 5766D	Web Uapi firmware	Install version 1.05 or later	
Cannot	When using WIM, a PDF	D258	Web Uapi firmware	Install version 1.07 or	
download	or PDF/A file stored in the	5766F	.705 Supriminware	later	
	Document Server is not	D261	Web Uapi firmware	Install version 1.06 or	
	downloaded when clicked	5766E		later	
Wrong	When sending a scanned	D258	Network Support	Install version 16.48 or	
document	or fax document using the	5769H	firmware	newer.	
sent	Hotfolder plug-in for				
	GlobalScan or				
	StreamlineNX, the wrong				
	document was sent and				
	the original document may				
	be lost.				
WIM	Cannot access the	D258	Fax firmware	Install version 06.00.00	
\A/IN/	machine using WIM	5762H	Notwork Des Des	or later	
WIM	Cannot access the	D258	Network DocBox	Install version 1.01 or	
WIM	machine using WIM The list of installed	5770D D258	firmware	later Install version 1.11 or	
V V IIVI	applications is not	5760P	System/Copy firmware	later	
	displayed in Extended	D261	minwait	later	
	Feature Info on WIM	5760N			
Address	If you the exported	D258	System/Copy	Install version 1.11 or	
book	address book from	5760P	firmware	later	
2001	Device Manager NX, the	D261			
	export data cannot be	5760N			
	imported				

# **T**echnical **B**ulletin

**PAGE: 10/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Address	When the device is using	D258	System/Copy	Install version 1.11 or	
book	"Card Authentication	5760P	firmware	later	
	Package" or another	D261			
	custom authentication,	5760N			
	some fields in the address				
	book on the device are				
	not overwritten				
Machine	In ADF silent mode, when	D258	Engine firmware	Install version 1.15:02 or	
disconnects	receiving a print job	5522B		later	

# Technical Bulletin

**PAGE: 11/34** 

**Updated: End of June 2018:** Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 4. Printing/Scanning

Subject	Symptom	RTB#	Cause	Solution	Note
Cannot		D257	System/Copy	Install version 1.03 or	
scan		002b	firmware	later	
Cannot scan	Job fails when "Download File Directly From URL Link" is enabled	D257 006a	Scanner firmware	Install version 1.03 or later	
Cannot scan	When many scan jobs are scanned from an application that is based on SmartSDK	D258 5764H	Scanner firmware	Install version 01.04 or later	
Cannot scan	Cannot use the Scanner application if the device was accessed from Web Image Monitor just before scanning is finished	D258 5764L	Scanner firmware	Install version 01.07 or later	
Cannot print		D257 002b	System/Copy firmware	Install version 1.03 or later	
Cannot print	Job fails if PS driver is installed	D257 010b	Network Support firmware	Install version 16.45 or later	
Cannot print	When trying to control jobs while a job is suspended	D259 020i	PrinterInfo for eDC firmware	Install version 1.11 or later	
Cannot print	Executing the Factory Default function will prevent the Fiery from printing jobs	FIT101614628.ps		Color Controller E-24B Ver.1.0 firmware	
Cannot print	"Please wait. The paper tray is being used by another function", is shown	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
Cannot copy	Banner paper (paper length is more than 480 mm) cannot be copied	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
Cannot copy	When the device has just gone into energy saver mode, even if a copy job is sent from a SmartSDK application	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
Printing	When the device is in	D258	Network Support	Install version 16.49 or	
stops	STR mode	5769J	firmware	later	
Printing stops	IPDS printing stalls if IPDS jobs are printed continuously	D258 5772K D261 5772J	Printer firmware  Printer firmware	Install version 1.06 or later Install version 1.05 or later	
Job files not deleted	When a scan job is conducted from the simplified screen	D257 006a	Scanner firmware	Install version 1.03 or later	

# Technical Bulletin

**PAGE: 12/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Job files not	The captured image file	D258	Scanner firmware	Install version 01.06 or	11010
deleted	is not deleted and	5764K		later	
	remains on the hard disk				
Drivers	Cannot install PS driver	D257	Network Support	Install version 16.45 or	
	by USB cable from	010b	firmware	later	
	macOS				
Drivers	Can select coated paper	D257	Printer firmware	Install version 1.01 or	
	even if a compatible tray	012a		later	
	is not installed	D257	PDF firmware	Install version 1.01 or	
		014a		later	
PCL	PCL macros that were	D257	PCL firmware	Install version 1.03 or	
	uploaded to the HDD	013b		later	
	cannot be printed				
IPDS	IPDS form creation fails	D258	Printer firmware	Install version 1.06 or	
	when specifying a	5772K		later	
	custom paper size	D261	Printer firmware	Install version 1.05 or	
		5772J		later	
IPDS	Some characters in the	D258	Printer firmware	Install version 1.06 or	
	IPDS form name are	5772K		later	
	distorted	D261	Printer firmware	Install version 1.05 or	
1000	16 1000 6 14b	5772J	Dainte of Comment	later	
IPDS	If an IPDS form with an	D258 5772L	Printer firmware	Install version 1.07 or	
	unsupported Cross	_		later	
	Feed Dimension value is added, a Feed	D261 5772L			
	Dimension error	3//ZL			
	appears instead of a				
	Cross Feed Dimension				
	error				
IPDS	An IPDS form with a	D258	Printer firmware	Install version 1.07 or	
	custom size cannot be	5772L		later	
	applied to trays	D261			
		5772L			
Job not	When "Tracking	Gene	Java VM v12 for	Install version 12.44.01	
processed	Permission" and "Stop	087k	eDC	or later	
	Printing" are enabled in	Gene	Java VM v12	Install version 12.44.01	
	"Enhanced Print Volume	088i	Update Tool	or later	
	Limitation"				
Job not	When the display	D259	PrinterInfo for	Install version 1.11 or	
completed	language is changed	020i	eDC firmware	later	
	while controlling a job	D.CC	555.6		
Job	When printing PDF data	D258	PDF firmware	Install version 1.02 or	
cancelled	that includes	5778E		later	
	overprinting via PDF				
File pet	Direct Print	Daga	Madia Dut Cara fair	Install version 4.47 or	
File not	PDF files that have long,	D259	MediaPrtScn for	Install version 1.17 or	
printed	multibyte filenames are	022k	eDC firmware	later	
Cannot	not printed	D250	Scanner firmware	Install version 01.04 or	
	When scanning from	D258 5764H	Scanner IIIIIware	later	
open file	Mac OS X 10.12 by	3704H		Ialei	
	using AirPrint, the output file cannot be opened in				
	the viewer				
	LITO VICANOI				
		1		1	

# Technical Bulletin

**PAGE: 13/34** 

Updated: End of June 2018: Changes in bold italics

Cubic of	Cumarata	DTD#	Carras	Colustian	Nete
Subject	Symptom	RTB#	Cause	Solution	Note
Cannot open file	After sending mail including a URL link of a PDF file scanned by OCR, when the device is	D261 5760L	System/Copy firmware	Install version 1.09 or later	
	turned off and on, the PDF file cannot be accessed by clicking the URL.				
Remaining print time	Display is incorrect for jobs printed from the document server	D258 5760K D261 5760J	System/Copy firmware	Install version 1.07 or later	
Some sets not printed	If an original jams in the sample copy of a stapled job, the first set is not printed	D258 5760K D261 5760J	System/Copy firmware	Install version 1.07 or later	
Printing result not as expected (not specified)	For the second and subsequent pages while PCL5 host printing	D258 5775F	PCL firmware	Install version 1.05 or later	
Printing result not as expected (not specified)	Images in Postscript or PDF jobs which require a lot of memory	D258 5778F	PDF firmware	Install version 1.03 or later	
OCR	OCR cannot recognize characters if converting scanned image to searchable PDF	D258 5760M D261 5760L	System/Copy firmware	Install version 1.09 or later	
Capture	Does not operate normally if the Media Link Board is installed	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
Scan to Email	Fails if OCR is set and a document over 51 pages is sent by Scan to Email	D258 5764K	Scanner firmware	Install version 01.06 or later	
Scan to Folder	Device automatically restarts	D258 5769K	Network Support firmware	Install version 16.50 or later	
Scan to Folder	If a host name is resolved to multiple IP addresses by NBNS, the device tries to connect to only the first resolved IP address	D258 5769K	Network Support firmware	Install version 16.50 or later	
Scan to Folder	Fails when a HP device is working on the same subnet	D258 5769K	Network Support firmware	Install version 16.50 or later	
Scan to Folder	Network browsing fails	D258 5769K	Network Support firmware	Install version 16.50 or later	

# Technical Bulletin

**PAGE: 14/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Scan to	The device freezes	D258	Network Support	Install version 16.50 or	
Folder	during data transmission	5769K	firmware	later	
	when doing Scan to				
	Folder with SMBv2/v3				
Scan to	When doing Scan to	D258	Network Support	Install version 16.50 or	
Folder	Folder in a high-load	5769K	firmware	later	
	network environment,				
	the device status gets				
	stuck on sending and				
	the scanner becomes				
Scan to	unusable	D258	Notwork Cumport	Install version 16.51 or	
Folder	When doing Scan to Folder using	5769L	Network Support firmware	later	
Folder	SMBv2/v3, if the device	3709L	IIIIIWaie	later	
	receives UDP				
	communication from				
	the outside to the port				
	used by SMBv2/v3,				
	Scan to Folder fails				
Wrong file	When scanning from	D258	Scanner firmware	Install version 01.06 or	
format	SmartSDK applications,	5764K		later	
	files are stored in PDF/A				
	format even when trying				
	to store the files in				
10/mm	TIFF/JPEG format	DOEO	0		
Wrong file format	When scanning with	D258 5764L	Scanner firmware	Install version 01.07 or	
iormat	AirPrint in MacOS X	5/64L		later	
	10.12 or later, the device sends a full color JPEG				
	even if specifying a				
	black and white JPEG.				
Job does	If process control runs	D258	Engine firmware	Install version 1.15:02 or	
not resume	during a job	5522B		later	
Others	Cancelling a scan job	D258	Scanner	Install version 01.09 or	
	while the preview is	5764N	firmware	later	
	displayed causes the				
	information of the				
	captured image file to				
	be recorded				
	incorrectly				

# Technical Bulletin

**PAGE: 15/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 5. Operation Panel

Subject	Symptom	RTB#	Cause	Solution	Note
Freezes	If searching for a custom paper entry in the media library	D257 002c	System/Copy firmware	Install version 1.04 or later	
Freezes	When the Start button is pressed after recovering from Energy Saver mode.	D260 001b	System/Copy firmware	Install version 1.06 or later	
Freezes	Pressing the interrupt key on the standard operation panel causes the display to freeze	D261 5760N	System/Copy firmware	Install version 1.11 or later	
Freezes	At start up or after recovering from the energy saving mode	D241 1425D D241 1429D	Cheetah System firmware	Install version 1.27 or later	
Freezes	When the SOP and the application settings are exported using the backup function	D241 1425F D241 1429F	Cheetah System firmware	Install version 1.27.2 or later	
Button does not work	The Start button does not work if the Log-out button is pressed after removing an original jam.	D257 002d D260 001a	System/Copy firmware	Install version 1.05 or later	
Button does not work	The "Continue Printing" button does not work after pressing the "Stop" key while copying from the exposure glass	D241 1443S	SimpleCopy firmware	Install version 1.20 or later	
Wrong language	If the language is changed in the language widget, "Please wait" is displayed in the previous language when Quick Scanner is reopened	D259 030h	SimpleScan for eDC firmware	Install version 1.10 or later	
Buttons active/inactive at the wrong time	If the key counter is canceled during scanning, the job reset button remains on the operation panel	D259 030i	SimpleScan for eDC firmware	Install version 1.11 or later	

# Technical Bulletin

**PAGE: 16/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Wrong screen displayed	Pressing the "To the print screen" button in the Adjustment Setting for Skilled Operators menu navigates to the copy screen.	D260 001b	System/Copy firmware	Install version 1.06 or later	
Wrong screen displayed	After printing, the file selection screen is not displayed	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Wrong screen displayed	If "Interrupt mode" is pressed in a Legacy application, the home screen is displayed instead of the original application after "Interrupt mode" is released	D258 5760S	System/Copy firmware	Install version 1.14 or later	
Reboots	While entering sleep mode; may be followed by SC819/SC672	D259 012u	Cheetah System firmware	Install version 1.22.2 or later	
Applications appear unexpectedly		D259 012u	Cheetah System firmware	Install version 1.22.2 or later	
Resets to default	The screen switches to the default setting of Function Priority when connected to a USB device such as a keyboard	D259 035m	LegacyUI for eDC firmware	Install version 1.15.1 or later	
Wrong paper size displayed	Tray 1, after the display language is changed	D259 020i	PrinterInfo for eDC firmware	Install version 1.11 or later	
Wrong value displayed	The device's HDD capacity is not displayed correctly	D258 5780J D258 5780J	Java VM v12 for eDC firmware Java VM v12 Update Tool	Install version 12.51.01 or newer	
Icon missing	SDK application icon not displayed after recovering from energy saving mode	D258 5780K D258 5780K	Java VM v12 for eDC firmware Java VM v12 Update Tool	Install version 12.54.00 or newer	
Icon missing	The Fiery icon does not appear in copier mode after recovering from the energy saver mode	D261 5760L	System/Copy firmware	Install version 1.09 or later	
Icon missing	SDKJ application icon not displayed on the home screen	D241 1425 D241 1429	Cheetah System firmware	Install version 1.23 or later	

# Technical Bulletin

PAGE: 17/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Icon not	The yellow mark not	D241	SmartCopy	Install version 1.25 or	
correct	displayed on the	1454X	firmware	later	
	'Other Settings' icon	D241	Cheetah System	Install version 1.27 or	
	even if one of the	1425D	firmware	later	
	'Other Settings' is	D241			
	enabled	1429D			
Button missing	"Apply" button	D258	System/Copy	Install version 1.09 or	Update
	missing from several	5760M	firmware	later	Animation to
	confirmation screens	D261			v1.02 or later
	in User Tools	5760L			also
Program	The copier program	D258	System/Copy	Install version 1.09 or	
missing	registered on the	5760M	firmware	later	
	operation panel	D261			
	disappears after	5760L			
	turning the main				
01 "	switch off and on.	DOES	F C	In tall was a constant	
Cannot exit	Cannot exit the job	D258	Fax firmware	Install version 05.00.00	
screen	stop screen if the	5762G		or later	
	SNTP time setting				
	and STR setting are enabled				
Touch panel	After recovering from	D261	Keymicon	Install version 2.23 or	
not responding	energy saving mode	7385D	firmware	later	
Touch panel	After the machine	D241	Legacy UI	Install version 1.22 or	
not	stalled during ARFU	1427Z	firmware	later	
responding					
Panel does not		D257	Power not	Follow the instructions in	
turn on		043	supplied to the	the RTB	
			operation panel		
LEDs	Blue LED does not	D257		Follow the instructions in	
	turn on	043		the RTB	
Blue screen	Blue screen appears	D257	Software issues	Follow the instructions in	
		043		the RTB	
Black screen	After switching the	D241	PrinterSJob	Install version 1.75 or	
	user or the display	1446R	firmware	later	
	language, a black				
	screen is displayed for a few seconds				
	when opening				
	Quick Print Release				
'Please wait'		D257	Software issues	Follow the instructions in	
I loado wait		043	201111410100000	the RTB	
Wording errors	Incorrect wording of	D261	Web Support	Install version 1.08 or	
	"Remote Panel	5765L	firmware	later	
	Operation" in the	D258	Web Support	Install version 1.09 or	
	menu of Web Image	5765L	firmware	later	
	Monitor				
Legacy mode	Problems with the	D257	Do not use	Use v1.19 or earlier.	
	Smart Operation	044	Legacy UI		
	Panel when Legacy		Firmware v1.20		
ĺ	mode is use				

# Technical Bulletin

**PAGE: 18/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 6. Security

Symptom	RTB#	Cause	Solution	Note
User code authentication does not work in SDK applications	D257 001b	Engine firmware	Install version 1.07:02 or later	
Printing does not start even after entering the user code	D257 002d D260 001a	System/Copy firmware	Install version 1.05 or later	
Fails if the device is set to use "IEEE 802.1X" and "TLS1.2" is set to "active"	D257 010d	Network Support firmware	Install version 16.46 or later	
"User Code Authentication": No alert sound for an invalid entry	D259 030h	SimpleScan for eDC firmware	Install version 1.10 or later	
The DSDK application fails to connect to the LDAP server when using Kerberos authentication	Gene 087p Gene 088n	Java VM v12 for eDC Java VM v12 Update Tool	Install version 12.47.01 or later Install version 12.47.01 or later	
The user code is cleared when transitioning to the Home screen	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
User usage restrictions do not come into effect if authentication is enabled in Quick Card Authentication	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
If some characters are included in a user name, login authentication is not done correctly	D258 5760Q D261 5760P	System/Copy firmware	Install version 1.12 or later	
Encryption key cannot be restored	D257 002a	System/Copy firmware	Install version 1.02 or later	
Cannot log in	D257	System/Copy firmware	Install version 1.03 or later	
Cannot login with card reader	D259	Cheetah System firmware	Install version 1.20 or later	
Users forcefully logged off while printing or previewing a print.	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
	User code authentication does not work in SDK applications  Printing does not start even after entering the user code  Fails if the device is set to use "IEEE 802.1X" and "TLS1.2" is set to "active"  "User Code Authentication": No alert sound for an invalid entry  The DSDK application fails to connect to the LDAP server when using Kerberos authentication  The user code is cleared when transitioning to the Home screen  User usage restrictions do not come into effect if authentication  If some characters are included in a user name, login authentication is enabled in Quick Card Authentication  If some characters are included in a user name, login authentication is not done correctly Encryption key cannot be restored  Cannot login with card reader  Users forcefully logged off while printing or previewing	User code authentication does not work in SDK applications  Printing does not start even after entering the user code  Tails if the device is set to use "IEEE 802.1X" and "TLS1.2" is set to "active"  "User Code Authentication": No alert sound for an invalid entry  The DSDK application fails to connect to the LDAP server when using Kerberos authentication  The user code is cleared when transitioning to the Home screen  User usage restrictions do not come into effect if authentication is enabled in Quick Card Authentication  If some characters are included in a user name, login authentication is enabled in Quick Card Authentication  If some characters are included in a user name, login authentication is not done correctly  Encryption key cannot be restored  Cannot login with card reader  Users forcefully logged off while printing or previewing	User code authentication does not work in SDK applications  Printing does not start even after entering the user code  Fails if the device is set to use "IEEE 802.1X" and "TLS1.2" is set to "active"  "User Code Authentication": No alert sound for an invalid entry  The DSDK application fails to connect to the LDAP server when using Kerberos authentication  The user code is cleared when transitioning to the Home screen  User usage restrictions do not come into effect if authentication is enabled in Quick Card Authentication  If some characters are included in a user name, login authentication is enabled in Quick Card Authentication  If some characters are included in a user name, login authentication is enabled in Quick Card Authentication  If some correctly Encryption key cannot be restored  Cannot log in  D259 Cannot log in with card reader  Users forcefully logged off while printing or previewing  D259 MediaPrtScn for eDC System/Copy firmware  Engine firmware  System/Copy firmware  System/Copy firmware  System/Copy firmware  D257 System/Copy firmware  D258 System/Copy firmware  System/Copy firmware  D257 O02a  MediaPrtScn for O02a  Cheetah System firmware  D259 MediaPrtScn for O02b MediaPrtScn for O02c D259 MediaPrtScn for	User code authentication does not work in SDK applications Printing does not start even after entering the user code code

# Technical Bulletin

**PAGE: 19/34** 

Updated: End of June 2018: Changes in bold italics

	1 -				
Subject	Symptom	RTB#	Cause	Solution	Note
Login/logout	Login screen shown after swiping with an IC card	D241 1425 D241 1429	Cheetah System firmware	Install version 1.23 or later	
Login/logout	Cannot login using Bluetooth in Smart Device Connector	D241 1425B D241 1429B	Cheetah System firmware	Install version 1.25 or later	
Login/logout	Cannot logout if the device is accessed from Web Image Monitor just before scanning is finished	D258 5764L	Scanner firmware	Install version 01.07 or later	
Login/logout	It takes time to login after authenticating the card	D258 5760Q D261 5760P	System/Copy firmware	Install version 1.12 or later	
Login/logout	Cannot log in if the machine repeatedly enters and exits Energy Saver Mode	D258 5760R D261 5760Q	System/Copy firmware	Install version 1.13 or later	
Service mode lock	Normal users can change the service mode lock setting	D257 002d			
SSL	SSL3.0 is possible even if it was disabled	D257 010d	Network Support firmware	Install version 16.46 or later	
SSL	SSL communication fails between an application and the Windows operating system	Gene 087k Gene 088i	Java VM v12 for eDC Java VM v12 Update Tool	Install version 12.44.01 or later Install version 12.44.01 or later	
Vulnerabilities	"Master Key" vulnerability	D259 012q	Cheetah System firmware	Install version 1.18 or later	
Logs	When using WIM to change the password policy in the "Extended Security" menu, the access log is not recorded	D258 5765G D261 5765G	Web Support firmware Web Support firmware	Install version 1.05 or later Install version 1.04 or later	

# Technical Bulletin

**PAGE: 20/34** 

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 7. Error Codes

Subject	Symptom	RTB#	Cause	Solution	Note
SC285		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
SC325	After a non-feed jam	D258 5522B	Engine firmware	Install version 1.15:02 or later	
SC348		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
SC374	After recovery from toner end	D257 001c	Engine firmware	Install version 1.08:02 or later	
SC374		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
SC496		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
SC515		D258 5522B	Engine firmware	Install version 1.15:02 or later	
SC525-01	When the bypass tray unit is opened/closed	D258 5522	Engine firmware	Install version 1.13:02 or later	
SC550	Pro models: After replacing the fusing belt	D258 5522A	Engine firmware	Install version 1.14:02 or later	
SC583		D257 040	The D2 fusing unit lever hits the machine frame and breaks if the cover of the fusing unit does not close properly.	Replace the fusing unit D2 lever with the new part (D2584372)	
SC621	When switching to power off or energy saving mode	D258 5522B	Engine firmware	Install version 1.15:02 or later	
SC672-11	When recovering from Energy Saver Mode	D257 002d D260 001a	System/Copy firmware	Install version 1.05 or later	
		D261 7385D	Keymicon firmware	Install version 2.23 or later	
SC672	Reboots after entering sleep mode	D259 012u	Cheetah System firmware	Install version 1.22.2 or later	
SC672	After recovering from sleep mode	D258 5760K D261 5760J	System/Copy firmware	Install version 1.07 or later	

# Technical Bulletin

PAGE: 21/34

**Updated: End of June 2018:** Changes in bold italics

Cubicot	Symmtom	DTD #	Correc	Colution	Note
Subject SC673-10	Symptom When turning on the	<b>RTB #</b> D258	Cause System/Copy	Solution Install version 1.07 or	Note
30073-10	When turning on the	5760K	System/Copy firmware		
	power		Illimware	later	
		D261			
00007	NAME and the street of the str	5760J	0	Landall constant 4.40 an	
SC687	When restarting a	D258	System/Copy	Install version 1.10 or	
	large print job	5760N	firmware	later	
		D261			
		5760M			
SC720	Broken guide cover	D257	A piece of the	Check between the	
	(finisher)	026	cover falls into the	guide and the exterior	
			machine, and the	cover and remove any	
			guide cannot	broken pieces.	
			return to home		
			position		
SC720-35	If a jam occurs at a	D260	FINISHER_Colum	Install version 01.040:03	
	location other than the	009a	bia-D firmware	or later	
	stapler tray but the				
	stapler unit is pulled				
	out and pushed back in				
SC720-70	Running 3 staple jobs	D3CA	FINISHER_Colum	Install version 01.050:03	
0012010	in a row	5620E	bia-D firmware	or later	
SC721-35	After replacing the	D3CA	FINISHER Colum	Install version 01.060:03	
30721-33	staple cartridge	5620E	bia-D firmware	or later	
CC016 00		D258			
SC816-98	While the system		System/Copy	Install version 1.08 or	
	enters the STR mode	5760L	firmware	later	
		D258	PowerSaving Sys	Install version F.L3.08.1	
		5761C	firmware	or later	
		D261	System/Copy	Install version 1.08 or	
		5760K	firmware	later	
SC819	Reboots after entering	D259	Cheetah System	Install version 1.22.2 or	
	sleep mode	012u	firmware	later	
SC819	After removing a jam	D258	System/Copy	Install version 1.07 or	
	that occurred while	5760K	firmware	later	
	printing a large job that	D261			
	fully consumes the	5760J			
	printer memory.				
SC819	After reboot	D258	System/Copy	Install version 1.07 or	
		5760K	firmware	later	
		D261			
		5760J			
SC819	After updating firmware	D258	Network Support	Install version 16.50 or	
00010	remotely	5769K	firmware	later	
SC843-02	. cinotory	D241	Cheetah System	Install version 1.24.1 or	
500-0-0Z		1425A	firmware	later	
		D241	miniwale	latel	
		1429A			
CC04E While up	While undetine		System/Cor:	Install version 4 07 ar	
SC845	While updating a	D258	System/Copy	Install version 1.07 or	
	package firmware	5760K	firmware	later	
		D261			
		5760J			
SC899	After updating the	D257	System/Copy	Install version 1.04 or	
	smart operation panel	002c	firmware	later	
	application/firmware				
	via ARFU				

# Technical Bulletin

**PAGE: 22/34** 

Updated: End of June 2018: Changes in bold italics

Ck!4	Come = f = ==	DTD#	Co	Colutton	N-4-
Subject	Symptom	RTB#	Cause	Solution	Note
SC899	When logging out	D257	Fax firmware	Install version 03.00.00	
2000	When "Erase All	004a	Noticed Compant	or later Install version 16.46 or	
SC899		D257 010d	Network Support firmware	later	
SC899	Memory" is done		Java VM v12 for	Install version 12.47.01	
50899	When doing location-	Gene	eDC		
	free printing or	087p		or later	
	authentication by using	Gene	Java VM v12	Install version 12.47.01	
20000	a solution product	088n	Update Tool	or later	
SC899	When receiving IP fax	D258	RemoteFax	Install version 03.00.00	
20000	M/h a na maintine na DDE	5763D	firmware	or later	
SC899	When printing a PDF file that contains	D258 5778E	PDF firmware	Install version 1.02 or later	
		31100		later	
	graphics or text via PDF Direct				
SC899	When printing a	D258	PDF firmware	Install version 1.02 or	
30099	document that has	5778E	PDF IIIIIIwale	later	
	fewer than four colors	31100		later	
SC899	for CMYK specified	D258	Java VM v12 for	Install version 12.49.00	
5099	When performing on- demand printing with	5780H	eDC	or later	
	the Enhanced Locked	376011	Java VM v12	Install version 12.49.00	
	Print		Update Tool		
2000		Dago	PCL firmware	or later Install version 1.04 or	
SC899	When printing a PCL	D258	PCL IIIIIware		
	job which contains	5775E		later	
	images via host printing				
SC899	When scanning a	D258	Scanner firmware	Install version 01.04 or	
50099	document with OCR	5764H	Scarifier fiffiware	later	
SC899	If there is a large	D258	PDF firmware	Install version 1.03 or	
50099	number of different	5778F	PDF IIIIIIwale	later	
	characters used in a	3776		latei	
	print job				
SC899	When printing via PDF	D258	PDF firmware	Install version 1.03 or	
50099	Direct if a job includes	5778F	1 Di ililiwale	later	
	more than 500 pages	37701		later	
SC899	In wireless LAN	D258	Network Support	Install version 16.49 or	
50099	infrastructure mode, if	5769J	firmware	1	
	changing the settings	37030	Illiliwale	later	
	when the PSK in				
	WPA2-PSK is empty				
SC899	If logging in from a	D258	Java VM v12 for	Install version 12.56.00	
2000	keyboard	5780L	eDC	or later	
	,	D258	Java VM v12	Install version 12.56.00	
		5780L	Update Tool	or later	
SC899	When doing Scan to	D258	Network Support	Install version 16.50 or	
	Folder	5769K	firmware	later	
SC899	When a duplex job	D261	System/Copy	Install version 1.14 or	
<del></del>	exceeds the max	5760R	firmware	later	
	allowable pages	0.001			
SC899	When executing SP5-	D258	System/Copy	Install version 1.15 or	
	846-052 (Restore All	5760T	firmware	later	
	Addr Book)	D261			
	1.22.2000	5760S			
	i	0,000	I	i	

# Technical Bulletin

PAGE: 23/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Causa	Solution	Note
Subject SC899	Symptom When rebooting the		Cause atch FIT 101662931		Note
30099	Fiery following a		91 FIT 101662931 P1 FIT101716374 fo		
	restoration of a backup	install 5	1 1111110171037410	1 L-440	
	file that contains paper				
	catalog data				
SC919	If the filename includes	Service	Pack 01	Color Controller E-24B	
	"%", Fiery service exits			Ver.1.0 firmware	
	before printing				
SC990	After an SC reboot, if	D258	Printer firmware	Install version 1.06 or	
	the dialog window	5772K		later	
	stating that the	D261	Printer firmware	Install version 1.05 or	
	automatic reboot has	5772J		later	
	occurred is not closed,	D258	System/Copy	Install version 1.11 or	
	SDK-J applications	5760P	firmware	later	
SC990	cannot be started	D258	System/Copy	Install version 1.11 or	
30990	After cancelling scanning	5760P	firmware	later	
	Scarring	D261	Illiliwale	later	
		5760N			
SC991	When "Erase All	D257	Network Support	Install version 16.46 or	
	Memory" is done	010d	firmware	later	
SC991	After cancelling	D258	System/Copy	Install version 1.11 or	
	scanning	5760P	firmware	later	
		D261			
		5760N			
SC997	When OCR is set and	D258	Scanner firmware	Install version 01.06 or	
	a document over 256	5764K		later	
	pages is scanned				
SC998	If Streamline NX and	D258	Java VM v12 for	Install version 12.54.00	
	CAP v2 are installed	5780K	eDC firmware	or newer	
		D258 5780K	Java VM v12		
SC998	When the machine is	D241	Update Tool Cheetah System	Install version 1.24.1 or	
30990	woken from sleep	1425A	firmware	later	
	mode by the proximity	D241	iiiiiwaic	later	
	sensor	1429A			
SC998	When powering on, if	D258	System/Copy	Install version 1.09 or	
	an ESA application is	5760M	firmware	later	
	set as a function	D261			
	priority	5760L			
Java VM	When doing location-	Gene	Java VM v12 for	Install version 12.47.01	
related SC	free printing or	087p	eDC	or later	
	authentication by using	Gene	Java VM v12	Install version 12.47.01	
10 : 1 0	a solution product	088n	Update Tool	or later	
"Quick Scanner		D259	SimpleScan for	Install version 1.10 or	
isn't		030h	eDC firmware	later	
responding. Do you want to					
close it?"					
Error message		D257	System/Copy	Install version 1.03 or	
(unspecified)		002b	firmware	later	
Alert not	Jam alert does not	D260	System/Copy	Install version 1.06 or	
displayed	appear after a paper	001b	firmware	later	
· I- · J · ·	size mismatch	1		_	

# Technical Bulletin

PAGE: 24/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Wrong error	A message about the	D259	Application Site	Install version 1.04.05 or	
message/ code	Application Site closing	037h	for eDC firmware	later	
	appears after				
	correcting a setting				
Mrang arrar	error for the drum unit SC544-00 mistakenly	D258	Engine firmwere	Install version 1.13:02 or	
Wrong error message/ code	detected when SC665-	5522	Engine firmware	later	
message/ code	04 occurs	3322		latei	
"Please wait"	When the Printer	D259	PrinterInfo for	Install version 1.11 or	
1 lodge wait	application is opened	020i	eDC firmware	later	
	after the device				
	resumes from sleep				
	mode				
'Please wait'	After pressing an	D258	System/Copy	Install version 1.07 or	
	application icon on the	5760K	firmware	later	
	touch panel very soon	D261			
	after going into Energy	5760J			
'Please wait'	Saver mode	D044	1	Install consists 4 04 an	
Please wait		D241 1427Y	Legacy UI firmware	Install version 1.21 or later	
Error not	After the device is	D259	PrinterInfo for	Install version 1.11 or	
displayed	restarted, error	020i	eDC firmware	later	
aispiayea	messages are not	0201	CDO IIIIIIWaic	later	
	displayed				
Error not	Error messages briefly	D259	MediaPrtScn for	Install version 1.17 or	
displayed	appear and then	022k	eDC firmware	later	
	disappear				
Other	An error message	D241	Cheetah System	Install version 1.24.1 or	
	indicates that part of	1425A	firmware	later	
	the import failed when	D241			
	executing "Export" and	1429A			
Other	"Import" in user tools Notifications are not	D258	Cycete me/Comy	Install version 1.11 or	
Other		5760P	System/Copy firmware	later	
	displayed in MFP applications even if key	3700F	Illiliwale	ialei	
	counter management				
	or external charge unit				
	management is				
	enabled				
Other	A backup failure	D258	System/Copy	Install version 1.15 or	
	message appears	5760T	firmware	later	
	when executing SP5-	D261			
	846-051 (Backup All	5760S			
	Addr Book)				

# Technical Bulletin

PAGE: 25/34

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 8. Optional Units

Subject	Symptom	RTB#	Cause	Solution	Note
Applications	Cheetah Business	M923	SharedFolderPrint	Install version 2.0.1 or	
	Application closes	003d	firmware	later	
	unexpectedly if a cover				
	feeder is installed				
Applications	Failure when uploading	D259	Cheetah System	Install version 1.18 or	
	files to a web server	012q	firmware	later	
	via a web application				
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
	17 x 22 paper in the	021g	eDC firmware	later	
	input tray is displayed				
• " "	as 11 x 17	D0=0	5		
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
	The application screen	021g	eDC firmware	later	
	is blacked out when it				
A	is reopened	DOFO	Deinte of Lab for	lastallassasias 4.50 as	
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
	Cannot start after the	021g	eDC firmware	later	
	device resumes				
	operating from energy-				
Applications	saving mode Printer Bit Switch #12-	D259	PrinterSJob for	Install version 1.59 or	
Applications	5 does not behave		eDC firmware		
		021g	eDC IIIIIwale	later	
Applications	properly Wrong Product ID	D259	PrinterSJob for	Install version 1.60 or	
Applications	used	021h	eDC firmware	later	
Applications	Measurements shown	D259	SimpleScan for	Install version 1.10 or	
Applications	in Quick Scanner are	030h	eDC firmware	later	
	not correct	00011	CDO IIIIIWaic	later	
Applications	Various problems with	D259	SimpleScan for	Install version 1.11 or	
Applications	Quick Scanner	030i	eDC firmware	later	
Applications	Destinations missing	D259	SimpleScan for	Install version 1.12 or	
, ipplications	from Quick Scanner	030j	eDC firmware	later	
Applications	SDK applications not	Gene	Java VM v12 for	Install version 12.44.01	
	behaving correctly	087k	eDC	or later	
		Gene	Java VM v12	Install version 12.44.01	
		088i	Update Tool	or later	
Applications	Cannot use required	Gene	Java VM v12 for	Install version 12.47.01	
	version of Java VM	087p	eDC	or later	
	after replacing the	Gene	Java VM v12	Install version 12.47.01	
	controller board	088n	Update Tool	or later	
Applications	Java VM does not	Gene	Java VM v12 for	Install version 12.47.01	
	recognize a change in	087p	eDC	or later	
	relationship between	Gene	Java VM v12	Install version 12.47.01	
the ho	the host name and the	088n	Update Tool	or later	
	IP address on the DNS				
	server				
Applications	Scanner application	D259	SmartScan for	Install version 1.13 or	
	ends abnormally	019k	eDC firmware	later	
Applications	The application aborts	D259	MediaPrtScn for	Install version 1.17 or	
	while trying to print via	022k	eDC firmware	later	
	the bypass tray.	<u>                                      </u>			

# Technical Bulletin

PAGE: 26/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Applications	The application is	D259	MediaPrtScn for	Install version 1.17 or	
	unresponsive when	022k	eDC firmware	later	
	many jobs via ADF are				
	scanned.				
Applications	Some Smart SDK	D284	Firmware bug	Install newer Cheetah	
	applications are	027		System firmware	
	deleted with				
	CheetahSystem v1.21.				
Applications	Cannot install	D258	Java VM v12 for	Install version 12.51.01	
	applications remotely	5780J	eDC firmware	or newer	
		D258	Java VM v12		
		5780J	Update Tool		
Applications	Device Manager NX	D258	Java VM v12 for	Install version 12.54.00	
	Enterprise cannot	5780K	eDC firmware	or newer	
	retrieve information	D258	Java VM v12		
	about applications	5780K	Update Tool		
	installed on the device.				
Applications	GlobalScan NX fails to	D258	Java VM v12 for	Install version 12.54.00	
	apply profiles or	5780K	eDC firmware	or newer	
	retrieve device	D258	Java VM v12		
	information when using	5780K	Update Tool		
	the AdminTool				
Applications	Notifications are not	D258	Printer firmware	Install version 1.06 or	
	displayed in MFP	5772K		later	
	applications even if key	D261	Printer firmware	Install version 1.05 or	
	counter management	5772J		later	
	or external charge unit				
	management is				
	enabled				
Applications	Remote un-installation	D258	System/Copy	Install version 1.11 or	
	for Streamline NX does	5760P	firmware	later	
	not work	D261			
		5760N			
Applications	Java VM does not	D258	System/Copy	Install version 1.11 or	
	recognize a change in	5760P	firmware	later	
	relationship between	D261			
	the host name and the	5760N			
	IP address on the DNS				
	server	D044			
Applications	After starting Web	D241	Cheetah System	Install version 1.27 or	
	Browser NX,	1425D	firmware	later	
	Application Site cannot	D241			
	be started from Screen	1429D			
A P C	SP Mode	Dose	0	Leafall and 1.4.12	
Applications	The quota notification	D258	System/Copy	Install version 1.12 or	
	cannot be displayed in	5760Q	firmware	later	
	some SmartSDK	D261			
	applications	5760P			
Applications	An SDK application	D258	Java VM v12 for	Install version 12.59.01	
	stops suddenly due to	5780M	eDC firmware	or newer	
	increased memory		Java VM v12		
	usage		Update Tool		
Applications	Legacy applications do	D241	Legacy UI	Install version 1.21 or	
	not open	1427Y	firmware	later	

# Technical Bulletin

**PAGE: 27/34** 

Updated: End of June 2018: Changes in bold italics

Symptom	RTB#	Cause	Solution	Note
martSDK WebAPI ug with serverless ansfer requests for evice logs	D258 5770E	Network DocBox firmware	Install version 1.02 or later	Note
martSDK WebAPI ug with the temporary ser authentication nction	D258 5770E	Network DocBox firmware	Install version 1.02 or later	
neets are not stapled duplex booklet jobs at contain solid nages	D707 001e	Finisher_SR4110 firmware	Install version 01.210:04 or newer.	
ith corner stapling	D258 5522	Engine firmware	Install version 1.13:02 or later	
ay up/down LED bes not light when vitch is pressed	D707 001e	Finisher_SR4110 firmware	Install version 01.210:04 or newer.	
expected finishing obtions not applied; over Interposer Tray (4020 (D712) + Multipolding Unit FD4000 (0615) + Booklet (03CA) or Finisher R5070 (D3CB); after the last sheet of a job fed from the Cover terposer	D712 5510C	Inserter_CI4020 firmware	Install version 02.020:04 or later	
ystem Updates does ot activate	D3CD 001	Color Controller E-24B Ver.1.0 firmware	Install required patch(es).	
ne Fiery cannot print ter executing the actory Default nction	D3CD 002	Color Controller E-24B Ver.1.0 firmware	Install required patch(es).	
the Fiery connects to e printer while the inter is shutting own, the Fiery screen bes not appear on the inter operation panel e next time the inter is powered on	D261 5760N	System/Copy firmware	Install version 1.11 or later	
ystem Updates does of activate even if nabled	FIT101614628		Color Controller E-24B Ver.1.0 firmware	
ne controller sponds to a ommunication rgeted to a different address	FIT101670677		Color Controller E-24B Ver.1.0 firmware	
ne cor spond mmul rgeted	ntroller Is to a nication I to a different	troller FIT1016 Is to a nication It to a different	FIT101670677 Is to a nication It to a different	troller FIT101670677 Color Controller E-24B Is to a hication It to a different

# **T**echnical **B**ulletin

**PAGE: 28/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Fiery controller	Fiery becomes unresponsive while duplicating a huge number of jobs when the printer is in STR mode	Service I	Pack 01	Color Controller E-24B Ver.1.0 firmware	
Fiery controller	Control Bar information does not match the Job settings	Service I	Pack 01	Color Controller E-24B Ver.1.0 firmware	



# Technical Bulletin

PAGE: 29/34

**Updated: End of June 2018:** Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 9. Image Problems

Subject	Symptom	RTB#	Cause	Solution	Note
Abnormal image (not	When sending or receiving an IP-Fax.	D257 018b	GWFCU3.8-14(WW) firmware	Install version 02.00.00 or later	
specified) Output not good (not specified)	When a particular PDF file is printed with specific tray alignment settings	Install S	I P1 FIT101716374 for E	I -44B	
Output not good (not specified)	A problem with the cleaning blade of the transfer belt	D258 5522C	Engine firmware	Install version 1.16:02 or later	
Lines	Horizontal lines at 40 mm intervals	D257 023	Error at the factory: too much lubricant was applied to the cleaning blade, and it goes to the charge roller	Execute SP2-222- 001 (Chg Roll Cleaning: Execute all) twice. If the symptom still occurs, execute this SP until the lines disappear.	
Low image density	When the print speed is changed	D257 001e	Engine firmware	Install version 1.10:02 or later	
Low image density		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
Color registration		D257 029	A bracket has come loose and the ITB roller cannot rotate.	Work through the procedure in the RTB.	
Function not working	3-edge full bleed works only for two edges	D258 5520H D258	Engine firmware System/Copy	Install version 1.11:02 or later Install version 1.07	
		5760K D261 5760J	firmware	or later	
Background	Image background is filled in	D258 5775E	PCL firmware	Install version 1.04 or later	
Part of image blacked out	A pattern put on top of an image or graphic is blacked out	D258 5775E	PCL firmware	Install version 1.04 or later	
Grainy image		D260 022	A: Surface of the paper is rough B:Limitation of the development process	A: Adjust the AC transfer bias (if that does not work, change the process speed setting). B: Change the screen settings in the Fiery printer driver.	See the RTB for the exact procedure to follow.
Incorrect color	Too light when printing on custom paper	D261 5772H	Printer firmware	Install version 1.04 or later	

# Technical Bulletin

PAGE: 30/34

**Updated: End of June 2018:** Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 10. Mechanical/Electrical

Subject	Symptom	RTB#	Cause	Solution	Note
Fusing cleaning unit	Web-end is not cleared even after installing a new fusing unit.	D257 001c	Engine firmware	Install version 1.09:02 or later	
Drawer	The drawer lock is not released if the operator turns the main power OFF/ON without clearing a fusing SC.	D257 001e	Engine firmware	Install version 1.10:02 or later	
Power stops suddenly	At installation	D257 031 D260 017	Due to a change in factory procedure, a harness tube in the fusing unit was damaged, causing it to contact a metal plate	If the harness tube is damaged, cover the harness and the edge of the bracket with Teflon tape. See the RTB for how to do this. The recommended Teflon tape is 3M PTFE Film tape 5490 (24mm).	
Motor does not stop	If JAM 360 occurs, the transfer motor does not stop.	D3CH 5300S	Finisher_SR4120/41 30 firmware	Install version 01.120:05 or later	
Noise	A problem with the cleaning blade of the transfer belt	D258 5522C	Engine firmware	Install version 1.16:02 or later	



# Technical Bulletin

PAGE: 31/34

Updated: End of June 2018: Changes in bold italics

Model: Model Ch-C2 Date: 31-Jun-08 No.: RD257000e

#### 11. Others

Subject	Symptom	RTB#	Cause	Solution	Note
Machine stalls	When sending or	D257	GWFCU3.8-	Install version 02.00.00	
	receiving an IP-Fax.	018b	14(WW) firmware	or later	
Machine stalls	When receiving a print job while performing engine adjustments after the end of the previous print job	D257 001e	Engine firmware	Install version 1.10:02 or later	
Machine stalls	If the Cover Interposer runs out of paper during the job and the tray is reloaded with paper incorrectly	D258 5760K D261 5760J	System/Copy firmware	Install version 1.07 or later	
Machine stalls	If a job includes text outside the printable area of the page	D258 5778F	PDF firmware	Install version 1.03 or later	
Machine stalls	When OCR is set and a document over 256 pages is scanned, the Scanner application freezes	D258 5764K	Scanner firmware	Install version 01.06 or later	
Machine stalls	When image log capture is enabled and a lot of jobs are performed, the capture cannot be executed and the device will freeze	D258 5770D	Network DocBox firmware	Install version 1.01 or later	
Machine stalls	When printing a heavy-duty job	D258 5775G	PCL firmware	Install version 1.06 or later	
Machine stalls	When the trailing edge rides on the trailing edge press lever in a shift job.	D3CA 5620F	FINISHER_Colum bia-D firmware	Install version 01.060:03 or later	
Machine stalls	In Energy Saver mode, freezes during the first backup after the firmware is installed	D284 043	Bug with the operation panel backup feature after Cheetah System firmware ver 1.27 is installed	Don't install ver 1.27. If the error occurs, disable the operation panel backup feature in the Cheetah SP mode	
Machine	If the widgets	D241	LanguageWidget	Install version 1.10 or	
stalls	reboot during a	1431K	firmware	later	
	firmware update	D241 1434H	TonerWidget	Install version 1.06 or	
		1434H D241	firmware EarlnfoWidget	later Install version 1.04 or	
		1435F	FaxInfoWidget firmware	later	
		D241	EcoInfoWidget	Install version 1.07 or	
		1437G	firmware	later	

# Technical Bulletin

PAGE: 32/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Machine stalls	When executing SP5-846-052 (Restore All Addr Book)	D258 5760T D261 5760S	System/Copy firmware	Install version 1.15 or later	
Machine reboots	The operation panel become blurred and lines appear, and then the machine reboots	D241 1425A D241 1429A	Cheetah System firmware	Install version 1.24.1 or later	
Machine reboots	After cancelling scanning	D258 5760P D261 5760N	System/Copy firmware	Install version 1.11 or later	
Machine is slow	Startup takes a long time if Streamline NX and CAP v2 are installed	D258 5780K D258	Java VM v12 for eDC firmware Java VM v12	Install version 12.54.00 or newer	
Machine is slow	Slow to output the first page using PDF Direct Print when the print data contains a large number of pages	5780K D258 5778F	Update Tool PDF firmware	Install version 1.03 or later	
Machine is slow	It takes time to resume a job if it is suspended while the	D258 5772K D261	Printer firmware Printer firmware	Install version 1.06 or later Install version 1.05 or	
	device is in Energy Saver mode	5772J	1 101	later	
Machine is slow	Printing via CAPv2/ELPv2 is slow	D258 5780L D258	Java VM v12 for eDC Java VM v12	Install version 12.56.00 or later Install version 12.56.00	
		5780L	Update Tool	or later	
Machine is slow	It takes a long time to print a file generated by Delphi with PCL5/PS	D258 5522B	Engine firmware	Install version 1.15:02 or later	
Reports/Logs	Problems with the Journal (fax report)	D257 004a	Fax firmware	Install version 02.00.00 or later	
Reports/Logs	If the device is abnormally turned off, the collect logs settings are initialized and the log data is not transferred after that	D258 5770F	Network DocBox firmware	Install version 1.03 or later	
Counters	Documents printed from PCFAX are not counted up.	D257 005a	RemoteFax firmware	Install version 02.00.00 or later	

# Technical Bulletin

**PAGE: 33/34** 

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Counters	After installing a new	D258	Engine firmware	Install version 1.12:02 or	11010
	waste toner bottle,	5520J		later	
	the counter cannot				
	be reset by opening				
	and closing the front				
	door				
Energy saver	Does not wake up	D259	Cheetah System	Install version 1.18 or	
mode	from sleep mode	012q	firmware	later	
Energy saver	Cannot recover from	D261	Keymicon	Install version 2.23 or	
mode	energy saver mode	7385D	firmware	later	
Energy saver	Cannot enter energy	D258	Scanner firmware	Install version 01.08 or	
mode	saver mode	5764M	Customs/Comu	later	
Initialization	No initialization after PM	D260 001b	System/Copy	Install version 1.06 or	
Firmware	RFU (Remote	D257	firmware Engine firmware	later Install version 1.10:02 or	
update	Firmware Update) is	001e	Engine iliniware	later	
upuate	not successful if	0016		later	
	started while MUSIC				
	or process control is				
	currently under way				
Firmware	Error 22 occurs when	D241	Cheetah System	Install version 1.27 or	
update	updating via ARFU	1425D	firmware	later	
		D241			
		1429D			
Firmware	E228 occurs when	D241	Cheetah System	Install version 1.27 or	
update	updating via SD card	1425D	firmware	later	
		D241			
		1429D	14 " 5 (0 (		
System reset	System auto-reset	D259	MediaPrtScn for	Install version 1.17 or	
Cottings are	not working If the Java VM	022k D258	eDC firmware Java VM v12 for	later Install version 12.49.00	
Settings are ignored	parameters are	5780H	eDC	or later	
ignored	changed remotely,	370011	Java VM v12	Install version 12.49.00	
	the changes do not		Update Tool	or later	
	take effect even after		opuato 1001	or later	
	rebooting				
Settings are	Renamed job name	Service	Pack 01	Color Controller E-24B	
ignored	is not honored and			Ver.1.0 firmware	
	does not appear in				
	Job Properties of the				
	printer operation				
	panel		T.,		
Settings not	SMB client timeout	D258	Network Support	Install version 16.50 or	
applied	configuration is not	5769K	firmware	later	
Correctly	correctly applied	DOCO	Facine firms	Install version 4.40.00	
Cannot make	When the new BICU	D258	Engine firmware	Install version 1.13:02 or	
settings	board is installed, serial number	5522		later	
	information cannot be				
	input.				
Cannot make	A3 size cannot be	D258	Scanner firmware	Install version 01.04 or	
settings	specified in macOS	5764H	Coamic illiliwale	later	
	when scanning by	373-11			
	using AirPrint				
	1 22mg/ mr /mr	<u> </u>		1	

# Technical Bulletin

PAGE: 34/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note		
Cannot make settings	When scanning from Mac OS X 10.12 by using AirPrint, the resolution is always 200 dpi.	D258 5764H	Scanner firmware	Install version 01.04 or later			
Cannot make settings	User Tools cannot be accessed	D241 1425D D241 1429D	Cheetah System firmware	Install version 1.27 or later			
Cannot make settings	User settings cannot be accessed	D241 1427Y	Legacy UI firmware	Install version 1.21 or later			
Cannot make settings	"Black point compensation" does not appear in Command Work Station		Install patch FIT101640279 for E-24B Install SP1 FIT101716374 for E-44B				
Setting in wrong menu	Auto Tray Selection appears in Configure		atch FIT101642747 fo P1 FIT101716374 fo				
Cannot operate the machine	When using DHCP Option204, "Setting change" is displayed on the operation panel, and users cannot operate the device	D258 5769J	Network Support firmware	Install version 16.49 or later			
Function not working	In "Printing text and serial numbers" mode, blank text with serial numbers cannot be copied	D258 5760M D261 5760L	System/Copy firmware	Install version 1.09 or later			
Function not working	SP5-850-003 not working	D261 5760M	System/Copy firmware	Install version 1.10 or later			