Technical Bulletin

PAGE: 1/8

Reissued: 18-Oct-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178001c

RTB Reissue

The items in bold italics have been added.

	a italioo haro boon addo			
Subject: Firmwar	re Release Note: NIB		Prepared	d by: H.Matsui
From: PPBG/Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical	☐ Part informa☐ Electrical	tion	☐ Action required ☐ Service manual revision
	☐ Paper path ☐ Other ()	☐ Transmit/rec	eive	☐ Retrofit information

This RTB has been issued to announce the firmware release information for the NIB.

Version	Program No.	Effective Date
7.06	G1786092E	August 2009 production.
7.04	G1786092D	August 2009 production.
7.03	G1786092C	March 2009 production.
7.02	G1786092B	1st Mass production.

Version	Modified Points or Symptom Corrected
7.06	1. Windows Authentication fails if the username or password includes lower-case European characters.
	2. The device's SMB timeout was too short (1sec). This caused problems when being used across subnets. For this reason, it has been increased to 10 sec.
	3. The printer's IP address lease renewal request is incorrectly formatted and rejected by DHCP relay agents. This will result in a loss of connectivity that lasts until the printer reinitializes the network connection (10 seconds).
	4. Windows authentication might fail on a domain controller whose hostname contains 2 byte characters.
	5. When the device IP address and DNS server location are obtained from DHCP, the domain specified by the device setting "IPv4 > Domain Name > Specify" will be overwritten by the domain obtained from DHCP.
	6. If the MFP/LP has a statically configured IP address and domain, it always sends a HELO using just its hostname. SMTP servers that require client HELOs to include the client's FQDN will close the connection. The result of this was that the MFP/LP was unable to send emails.
	7. Unable to retrieve the Windows group name from a Windows 2008 R2 server during Windows Authentication. Because of this, logged in users will only be granted the "Available Functions" specified for them in the Addressbook.
	8. The device is unable to assign group privileges to a logged in user if that group has a name consisting of more than 20 bytes. To address this issue, the supported group name length will be increased to 40 bytes.
	9. The printer's Windows Authentication function is unable to use Kerberos when being authenticated on a Windows 2008 or Windows 2008 R2 server. The printer will still be successfully authenticated because it is able to fail back to NTLMv2.

RICOH Technical Bulletin

PAGE: 2/8

Model: AC	G-P1	D	ate: 18-Sep-08	No.: RG1780
Version	Modif	fied Points or Sym	nptom Corrected	
	10. If the printer's IP address will not be able to printer is rebooted.	to browse the netw	vork (using Scan to	
	Please refer to <appendix Ensure to follow the proce *Please make sure that AL</appendix 	edures when upda	ting.	concurrently
	Program Name	Program No.	Version	oncurrently.
	System	G1786091H	2.06	
	Websystem	G1786093E	1.53	
	Network Support (NCS)	G1786092E	7.06	
	Engine Engine	G1785252P	3.007:12	
	LCDC	NA:G1785971C	1.03	
	LCDC	EU:G1785971C	1.03	
	Animation	G1786094B	2.2	
	Language	G1785979A	1.03	
	Fiery Server	- a1700070A	4.0	
		<u> </u>		
	* Update to the following	versions is require	d for all peripherals	s listed below.
		Program No.	Version	
	CI5010	B8355510F	V2.071:4	2
	SR5000	B8305102P	V1.820:5	9
	RB5000	Main:D3925510E	V1.290:0	4
		Sub: D3925520C	V1.060:0	1
	GB5000			
	P-Binder_B1	D3915020C	V0.28	
	P-Binder_B2	D3915070B	V0.19	
	P-Binder_B3	D3915730A	V0.13	
	P-Binder_B4	D3915120B	V0.15	
	P-Binder_B5	D3915170A	V0.25	
	BK5000	B8365550B	V2.17:15	
	SK5000			
	1 st stacker	D3645620C_P1	V4.08:15	
	2 nd stacker	D3645620C_P2		
	Buffer Pass Unit	M3791702C	V2.030:0	<i>5</i>
	Type 5000			
	Note			
	Make sure to update	tne peripnerais in	ı oraer oı proximity	y to the main
	frame.	autivaly by salasi	ting coverel nevinb	avala
	Do not update conse For CREOOL 5 boord			erais.
	 For GB5000, 5 board For RB5000, 2 board 			
7.04	Correction involving a proconnect another Window	vs Vista PC or Wind	dows Server 2008 to	the machine via
	1Psec connection 5 min connection of the first P			

PAGE: 3/8

Reissued: 18-Oct-10

Model: AC	G-P1		Date: 18-Sep-08	No.: RG178001
Version	Modified Points or Symptom Corrected			
	connection to the machine.			
	Please refer to <appendix 1=""> for update procedures.</appendix>			
	Ensure to follow the procedures when updating.			
	*Please make sure that ALI	_ versions listed b	elow are updated concu	urrently.
	Program Name	Program No.	Version	
	System	G1786091G	2.05	
	Websystem	G1786093E	1.53	
	Network Support (NCS)	G1786092D	7.04	
	Engine	G1785252G	3.000:12	
	LCDC	NA:G17859710		
		EU:G1785972		
	Animation	G1786094B	2.2	
	Language	G1785979A	1.03	
	Fiery Server	-	4.0	
	* Update to the following ve	reione ie roquiroe	l for all poriphorals listos	l bolow
	Opdate to the following ve	Program No.	Version	Delow.
	CI5010	B8355510F	V2.071:42)
	SR5000	B8305102P	V1.820:59	
	RB5000	Main:D392551		
		Sub: D392552		
	GB5000			
	P-Binder_B1	D3915020C	V0.28	
	P-Binder_B2	D3915070B	V0.19	
	P-Binder_B3	D3915730A	V0.13	
	P-Binder_B4	D3915120B	V0.15	
	P-Binder_B5	D3915170A	V0.25	
	BK5000	B8365550B	V2.17:15	
	SK5000	D0045000 D4	1/4 00:40	
	1 st stacker	D3645620_P1	V4.02:12	
	2 nd stacker Buffer Pass Unit	D3645620_P2 M3791702A	V1.000:03)
	Type 5000	W3/91/02A	V 1.000.03	2
	Note			
		he peripherals in	order of proximity to the	he main frame.
			ing several peripherals	
	• For GB5000, 5 boards			
	For RB5000, 2 boards	s can be updated	I consecutively.	
7.03	*Please make sure that ALI		•	urrently.
	Program Name	Program No.	Version	
	System	G1786091E	2.03	
	Network Support (NCS)	G1786092C	7.03	
	Engine LCDC	G1785252E	2.000:12	
	Language	NA:G1785971E G1785979	3 1.01 1.01	
	Websystem	G1786093C	1.01	
	Littobayotom	1 417 000300	1.01	



PAGE: 4/8

Reissued: 18-Oct-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178001c
--------------	-----------------	----------------

Version	Modified Points or Symptom Corrected		
	Websystem	G1786093C	1.01
	Fiery Server	-	3.0
	* Update to the following ver	sions is required for all perip	oherals listed below.
	Program Name	Program No.	Version
	SR5000 Finisher	B8305102M	1.60
	Cover Interposer Tray CI5010	B8355510E	02.070
	Ring Binder RB5000	Main:D3925510D Sub :D3925520B	Main:1.280:04 Sub :1.050:01
	High Capacity Stacker SK5000	1st:D3645620_P1 2nd:D3645620_P2	4.02:12
	Booklet Finisher BK5000	B8365550B	2.17
	* For the Ring Binder RB500 1. Newly supported periphoral periphoran periphoral periphoral periphoral periphoral periphoral peripho	attempt to select and update 00, Main and Sub shall be u erals: gh Capacity Stacker SK5000	multiple Firmware at once. pdated together. O, PLOCKMATIC,GBC
7.02	as the device can no lo	•	OCE, resulting in a 30990



PAGE: 5/8

Reissued: 18-Oct-10

Model: AG-P1 Date: 18-Sep-08 No.: RG178001c

<Appendix 1>

Please ensure to follow the procedures for the update.

The firmware of GW controller needs to be updated at a time.


NOTE: This problem will not occur with the Aegis-C1.

Make sure to update in the order since there is the order also for the other firmware.

NOTE:

- Do not do remote-update.
- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

Start Confirm present Engine Version Diagnostic Report (SP5990-005)



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 6/8

Reissued: 18-Oct-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178001c

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

1 of Alogio of		
Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

. c. / tog.c c .		
Program name	Program No.	Version
Engine	D0165252D	V3.000:12

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 7/8

Reissued: 18-Oct-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178001c
--------------	-----------------	----------------

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version	
Animation	G1786094B	V2.2	

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

. c g.c c .			
Program name	Program No.	Version	
Language	G1785980A	V1.06	

Program name	Program No.	Version
Language	G1785979A	V1.03

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 8/8

Reissued: 18-Oct-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178001c

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

PAGE: 1/4

Reissued: 07-Jul-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178002h

RTB Reissue

The items in **bold italics** have been added.

THE ROTTIC III DO	ia itanoo have been adae	уч.		
Subject: Firmware Release Note: System/Copy		Prepared by: H. Matsui		
From: PPBG Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting	☐ Part informat	tion	Action required
	☐ Mechanical	Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

This RTB has been issued to announce the firmware release information for the **System/Copy.**

Version	Program No.	Effective Date	Availability of RFU
2.08	G1786091K	May 2011 production	Not available
2.07	G1786091J	December 2010 production	Not available
2.06	G1786091H	October 2009 production	Not available
2.05	G1786091G	August 2009 production	Not available
2.04	G1786091F	May 2009 production	Not available
2.03	G1786091E	March 2009 production.	Not available
1.02	G1786091D	January 2009 production.	Available
1.01	G1786091C	October 2008 production.	Available
1.00.1	G1786091B	1st Mass production.	Available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptoms Adjusted
2.08	Modified Point Counting method for blank pages for Printer has been changed
2.07	Modified Point Following issues have been fixed SC 86x appears after turning on a machine. Punch unit could not detect. When paper end appears and recovered from it, paper shifted in middle of job, or paper did not shifted at end of job. Modified PM counter for "Filter: Oil Tank" Machine can now saddle stitch custom size paper by using Plocmatic New SP has been added SP-7941-128: Drive Distance: Near End Standard Value: Filter: Oil tank SP7-953-128: Page Counter: Near End Standard Value: Filter: Oil tank Apply Condition This software needs to be updated with following software.
	Aegis C1

[&]quot;Available": The firmware can be updated via RFU or SD card.

PAGE: 2/4

Reissued: 07-Jul-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178002h
--------------	-----------------	----------------

Model: AG-P1			Date: 18-Sep-08	No.: RG1780
		Programme num	ber Version	
	Engine	G1785252Q	3.008:12	
	System/ Copy	G1786091J	2.07	
	System/ Copy	G1786088A	2.03	
	(For French, instead of			
	above system, please			
	use this one)			
	Websys	G1786093F	1.54	
	Webuapl	D0166095D	1.13	
	Install tool	G1786099D	1.03	
	OpePanel (NA)	G1785971D	1.04	
	OpePanel(EU)	G1785972D	1.03	
	Language Install	G1785979B	1.04	
		Aries Lt C1		
		Programme num	ber Version	
	Engine	M0785252D	1.006:12	
	System/ Copy	M0786091A	2.07	
	System/ Copy	M0786092	2.07	
	(For French, instead of			

G1786093F

G1786099D

OpePanel (NA) 1.04 G1785971D OpePanel(EU) G1785972D 1.03 Language Install G1785979B 1.04

2.06 Modified Point:

- To make the Controller made from Infoprint works collectively with Aegis P1.
- To display SC 919 properly, when external controller is disconnected. Previously, when the external controller was disconnected, shutdown message appeared rather than displaying SC 919.

1.54

1.03

Apply condition

above system, please

use this one)

Websys Install tool

Apply to the machine working properly with System version 2.05. For the machine with system version older than 2.05, previously update the system version to 2.05, and then update it to 2.06.

2.05 Please refer to <appendix 1> for update procedures. Ensure to follow the procedures when updating.

*Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	G1786091G	2.05
Websystem	G1786093E	1.53
Network Support(NCS)	G1786092D	7.04
Engine	G1785252G	3.000:12
LCDC	NA:G1785971C	1.03
Animation	G1786094B	2.2
Language	G1785979A	1.03

Technical Bulletin

PAGE: 3/4

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

Language	G1785979A	1.03
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	V1.000:03
Type 5000		

Note

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

1. The adjustable range of the fusing temperature

The adjustable maximum value has been modified from 200 degrees to 205 degrees.

2. The adjustable range of "Idle Time: After Reload"

The adjustable maximum value of "Idle Time: After Reload" has been modified from 15 minutes to 60 minutes.

3. The modification of SP from target to not target of "NVRAM clear"

When "NVRAM clear" was excused, the following SP value also had been cleared.

Therefore, the status of use becomes unclear, and the exchange at the appropriate timing might be impossible.

To prevent this, the SP has been removed from the target at the "NVRAM clear" time.

SP1-902-001: Web Consumption

SP1-903-001: Web: Total Page Counter

SP1-903-002: Web: Total Motor Rotation Time

SP1-904-014: Oil End Counter

4. The countermeasure for toner blister

The following modification will be enforced for the countermeasure control for toner blister. The additional SP are (1), (4), (5) and (6).

(1) The addition of the toner blister countermeasure mode switching

[New SP] SP1-208-001 Toner Blister Control Blister 0:OFF 1:ON * The default 0: OFF. When it is ON, the following (2) – (6) become effective.

Technical Bulletin

PAGE: 4/4

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

- (2) Eliminating pressure while warming-up (The pressure has been modified to be eliminated except during printing.)
- (3) Imminent pressure control just before printing (Immediately apply pressure before printing.) The pressure roller is nipped immediately before printing, and it is changed to the printing mode.
- (4) Setting "the pressure reloading temperature" and "the waiting temperature" at 90 degrees. [New SP] Toner Blister Control Press Roll

SP1-208-002 Ctr: Reload[70to160/90/1 degrees] SP1-208-003 Ctr: Idle: Reload[70to160/90/1 degrees]

SP1-208-004 Ctr: Standby: Normal Temp[70to160/90/1 degrees] SP1-208-005 Ctr: Standby: Low Temp[70to160/90/1 degrees] SP1-208-006 Ctr: Standby: High Temp[70to160/90/1 degrees]

(5) Setting the pressure roller temperature at 90 degrees while pre-rotation.

[New SP] Toner Blister Control Press Roll

SP1-208-007 Thin: Press Roll Temp [70to160/90/1 degrees] SP1-208-008 Normal: Press Roll Temp [70to160/90/1 degrees] SP1-208-009 Middle: Press Roll Temp [70to160/90/1 degrees] SP1-208-010 Thick1: Press Roll Temp [70to160/90/1 degrees] SP1-208-011 Thick2: Press Roll Temp [70to160/90/1 degrees] SP1-208-012 Thick3: Press Roll Temp [70to160/90/1 degrees]

(6) The low-power control when toner blister countermeasure control is switched on The pressure roller setting temperature is set at 90 degrees.

[New SP] Toner Blister Control Press Roll

SP1-208-013 Temp: Low Power Mode [70to150/90/1 degrees]

5. The modification of the control of winding the fusing web

When removing the jammed paper by rotating the fusing knob after the occurrence of paper jam, the surface waviness of the web occurs by the rotation of the fusing belt.

"The fusing belt" rotates at the same time when the operation of web winding is enforced after the paper jam is processed.

Therefore, the surface waviness is not completely solved; the web is winded in and it is exhaled into the cleaning unit at worst.

The operation after paper jam processing has been modified for improvement:

The control is modified to rotate the fusing belt after "the operation of web winding" is completely finished

6. Correspondence to concentration variation by temperature change in the machine

It is likely to become a non-standard printing extra density due to the VL decrease because of the temperature rise in the machine, and SC367 occurs in the worst case.

The occurrence is seen especially when changing into FC mode after printing in large quantity in black mode.

Both "before entering into the start-up sequence when printing is demanded" and "at switchover time from black mode to FC mode", the potential ProCon (process control) will be enforced when the temperature in the machine has been changed more than 2 degrees from when the ProCon is enforced last time.

According to this, the following SP is newly added.

Before Job Process Control

SP3-555-003: Temperature Range ON/OFF

*0:ON 1:OFF

SP3-555-004: Temperature Range

0to99/2/1 degrees

7. Specification modification of "short idle time" ProCon and "temperature change" ProCon

PAGE: 5/5

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

If the low coverage printing is repeated after "short idle time" ProCon or "temperature change" ProCon, the development γ (gamma) will drop to the lower limit and the appropriate image density may not be obtained.

For improving this, the execution condition of the toner density adjustment of "short idle time" ProCon and "temperature change" ProCon has been modified.

The condition after modification is the same as the execution condition of "job end ProCon"

The toner density adjustment is executed upon the satisfaction of the following conditions.

(1) When the development γ (the detected value) is lower than 1.2.

(2) When the absolute value of $\Delta \gamma$ =the development γ (the targeted value) – the development γ (the detected value) is over 0.2.

8. "Short idle time" ProCon

There have been cases that the density depression after short idle time (30 minutes to 6 hours) occurs

The density depression in this case can be avoided by executing the potential ProCon before the job.

However, only the way to correspond was to change the time interval of the "short idle time" ProCon from 6 hours(default) to 30 minutes because there was no potential ProCon mode that is executed automatically by idling for a short time (more than 30 minutes) at the moment.

However, the "short idle time" ProCon contains developer agitation, adjustment of toner density, fade removal mode and oil removal mode as a set.

The problem was that the waiting time until the ending of ProCon is too long (for a maximum of about 4 minutes) and the toner is uselessly consumed.

Therefore, the mode that executes only the potential ProCon after idling for a short time (about 30 minutes) is newly added.

The potential ProCon execution mode is newly added upon the satisfaction of the following conditions.

[Timing of call]

Before entering into the start-up sequence when printing is demanded

[Execution condition]

- The idling time from the end of the last job is more than the setting value of SP3-555-002 (Before Job ProCon Idling Time).
- The idling time is less than the setting value of SP3-554-002 (Init ProCon Set Non-use Time Setting).

The following SP are newly added with the above modification.

SP3-555-001: Before Job Procon Short Idle Time ON/OFF 0:ON *1:OFF

SP3-555-002: Before Job Procon Idling Time 0to999/20/1min

- 9. Support of Buffer Pass Unit Type 5000 and Perfect Binder GB5000
- 10. Support of EFI Paper Catalog function

Paper settings from CWS, PrinterDriver are now rewritable.

- 11. Symptom of SC991 occurrence when setting the InfoPrint manufactured toner has been corrected.
- 12. Support of a newly added function of the Engine, which enables an easy test solid print by pressing a button in the User Tools
- 2.04 * Please be sure to use the following as a set for updating.

System Vesion2.04

Technical Bulletin

PAGE: 6/6

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

Engine Version2.001:12 Web support version1.51

Please apply the above <u>only</u> for machines operated under the following preconditions.

preconditions:		
Program Name	Program No.	Version
System	G1786091E	2.03
Network Support(NCS)	G1786092C	7.03
Engine	G1785252E	2.000:12
LCDC	NA:G1785971B	1.01
	EU:G1785972B	
Language	G1785979	1.01
Websystem	G1786093C	1.01

1. Implementation of firmware-sharing of Aegis-Base unit(M064) and Aegis-P1 (G178)

This allows M064 and G178 to be used with the common firmware.

2. Color Controller E80 correspondence

"6:QX100" is set by SP5193-001(External Controller Info. Settings) when installing Color Controller E80 onto Aegis-base unit (M064).

(Not used for G178)

- 3. The correction of the defect that it is stopped at the 5th sheet when doing duplex printing of SMC output
- 4. The correction of the defect of generating SC990 and being reactivated when printing several jobs

The defect that it is stopped by error occurrence when competition of "page number specification deletion demand" and "file deletion demand" occurs during printing of several jobs has been corrected.

5. The correction of the defect of generating SC990 when printing again after jam occurrence

[Occurring Case]

Number of the pages: 1,000 pages

Paper jam occurred when printing 500 pages => SC990 occurred when printing again after releasing jam

If "page number specification deletion demand" and "file deletion demand" compete for processing when restarting the printing after releasing jam, the page information of "page definition table" controlling registered page will be broken.

If page entry and deletion are repeated by continuing printing at this condition, MCS will delete unprinted page improperly, and SC990 will occur at printing demand of deleted page.

2.03 *Please make sure that ALL versions listed below are updated concurrently.

2.00	I leade make date that the verdicho hoted below are apaated demonstrative		
	Program Name	Program No.	Version
	System	G1786091E	2.03
	Network Support(NCS)	G1786092C	7.03
	Engine	G1785252E	2.000:12

Technical Bulletin

PAGE: 7/7

Reissued: 07-Jul-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178002h
--------------	-----------------	----------------

Engine	G1785252E	2.000:12
LCDC	NA:G1785971B	1.01
	EU:G1785972B	
Language	G1785979	1.01
Websystem	G1786093C	1.01
Fiery Server	-	3.0

* Update to the following versions is required for all peripherals listed below.

Program Name	Program No.	Version
SR5000 Finisher	B8305102M	1.60
Cover Interposer Tray CI5010	B8355510E	02.070
Ring Binder RB5000	Main:D3925510D	Main:1.280:04
	Sub :D3925520B	Sub :1.050:01
High Capacity Stacker	1st:D3645620_P1	4.02:12
SK5000	2nd:D3645620_P2	
Booklet Finisher BK5000	B8365550B	2.17

Note

*Peripherals must be updated ONE at a time, starting from the machines closest to the mainframe. Do NOT attempt to select and update multiple Firmware at once.

*For the Ring Binder RB5000, Main and Sub shall be updated together.

- Connections of the following peripherals are now available.
 Ring Binder RB5000, High Capacity Stacker SK5000, PLOCKMATIC, GBC
- 2. Stopping of the output function when the 5th sheet of the SMC Report is output, requiring a re-powering of the machine.
- 3. False automatic re-boot after an SC990 during a multiple print job.
- 4. SC990 occurrence when re-starting the print job after a jam.

1.02

- 1. Adjustments have been made for SC819 caused by memory leak when returning from Energy Saving.
- 2. Change in SP default value:

SP3-309-009: Oil removal mode Select mode between paper (feormer) default value: 0 "ON" depending on operating environment (revisd) default value: 1 "ON" at all times

3. Additions made in SP number:

SP3-309-008:Oil removal mode Select mode at Process Control
Oil Removal will automatically start during Process Control for Non-use Time
Setting.

SP3-309-014:Oil removal mode Interrupt ON/OFF

Selection of yes/no of Oil Removal during Interrupt

SP3-309-015:Oil removal mode Interrupt Thresh

Value of Thresh prints at Oil Removal in an Interrupt during print operation.

SP3-309-016:Oil removal mode Job End thresh

Value of Oil Removal Thresh prints after JobEnd.

SP3-309-017:Oil removal mode Both Sides

CounterCounter function for Both Sides printing.

4. Additions made in Function Setting SP for Oil Removal command manual. SP3-309-18:Oil removal mode Idling Time 1

Idling Time-1 after development of Toner Pattern for Oil Removal

SP3-309-19:Oil removal mode Idling Time 2

Idling Time-2 after development of Toner Pattern for Oil Removal

SP3-309-20:Oil removal mode Repeat Time

Number of Toner Pattern development for Oil Removal

5. Adjustments have been made involving trouble of toner refresh not functioning.

Technical Bulletin

PAGE: 8/8

Reissued: 07-Jul-10

Model: AG-P1		Date: 18-Sep-08	No.: RG178002h
6. Adjustments have been made involving trouble in SRA3 not reading a double count despite "1: Double count" is set for "A3/DLT Double Count (SP5-104-001)" *Use combination of System:1.02 & engine:1.108:11 to operate.			•
1.01	Trouble has been solved for the appearance the machine being in a non-functioning cornote. In the case of update from V0.95.1 version or its prescribed (Super SP mode) on the initial reboot after updating. How to enter to Super SP mode. 1. Clear/Modes button 1,0,7 Clear button (3 2. Press "SYSTEM" button pressing "Enter". Enter to Super SP mode and execute "SP5-892. 2. Power off/on after execution.	ndition. evious version, please execut seconds) << usual SP mod button	e SP5-892-001
1.00.1	1st Mass production.		

Technical Bulletin

PAGE: 9/9

Reissued: 07-Jul-10

Model: AG-P1 Date: 18-Sep-08 No.: RG178002h

<Appendix 1>

Please ensure to follow the procedures for the update.


The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware. NOTE:

Do not do remote-update.

- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 10/10

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApI	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Engine	D0165252D	V3.000:12

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 11/11

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aeais-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version
Animation	G1786094B	V2.2

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Language	G1785980A	V1.06

Program name	Program No.	Version
Language	G1785979A	V1.03

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 12/12

Reissued: 07-Jul-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178002h

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

PAGE: 1/7

Reissued: 29-Dec-10

Model: AG-P1 Date: 18-3	Sep-08 No.: RG178003d	
-------------------------	-----------------------	--

RTB Reissue

The items in **bold italics** have been added

Subject: Firmware Release Note: WebSystem		Prepared by: H.Matsui		
From: PPBG Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting	☐ Part informa	tion	☐ Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

This RTB has been issued to announce the firmware release information for the WebSystem.

Version	Program No.	Effective Date	Availability of RFU
1.54	G1786093F	December 2010 production	Not available
1.53	G1786093E	August 2009 production	Not available
1.51	G1786093D	May 2009 production	Available
1.01	G1786093C	December 2008 production.	Available
1.00	G1786093B	1st Mass production.	Available

[&]quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptoms Adjusted					
1.54	Modified Points: 1. Wordings have been added in accordance with the modification of the Oil Tank Filter PM counter controls. Please refer to <appendix 1=""> for update procedures. Make sure to follow the procedures when updating.</appendix>					
	Apply condition: Firmwares below to be applied together as a set.					
	Program Name Program No. Version					
	System G1786091J 2.07					
	Websystem G1786093F 1.54					
	Engine G1785252Q 3.008:12					
	LCDC NA:G1785971D 1.04 EU:G1785972D					
	Language	G1785979B	1.04			
1.53	 Incorrect character appearance on the Web Image Monitor "Printer Status Notification by E-Mail" screen in language environment other than English and Japanese has been corrected. Wordings for the E-mail notification function has been added accordingly with the support of the Buffer Pass Unit Type 5000. 					

Note: Definition of Availability of RFU "Available": The firmware can be updated via RFU or SD card.

PAGE: 2/7

Reissued: 29-Dec-10

Model: AG-P1		Date: 18-Sep-08	No.: RG178003	
Version	Modified Points or Symptoms Adjusted			
	Please refer to <appendix Ensure to follow the proced</appendix 			
	*Please make sure that AL	L versions listed b	elow are updated conc	urrently.
	Program Name	Program No.	Version	,
	System	G1786091G	2.05	
	Websystem	G1786093E	1.53	
	Network Support (NCS)	G1786092D	7.04	
	Engine	G1785252G	3.000:12	
	LCDC	NA:G1785971C EU:G17859720		
	Animation	G1786094B	2.2	
	Language	G1785979A	1.03	
	Fiery Server	-	4.0	
	* Update to the following ve	ersions is required	for all peripherals liste	d below.
		Program No.	Version	
	CI5010	B8355510F	V2.071:4	2
	SR5000	B8305102P	V1.820:5	9
	RB5000	Main: D39255	10E V1.290:0	4
		Sub: D3925520	C V1.060:0	1
	GB5000			
	P-Binder_B1	D3915020C	V0.28	
	P-Binder_B2	D3915070B	V0.19	
	P-Binder_B3	D3915730A	V0.13	
	P-Binder_B4	D3915120B	V0.15	
	P-Binder_B5	D3915170A	V0.25	
	BK5000	B8365550B	V2.17:15	
	SK5000	D0045000 D4	1/4 00:40	
	1 st stacker 2 nd stacker	D3645620_P1	V4.02:12	
	Buffer Pass Unit	D3645620_P2 M3791702A	V1.000:0	2
	Type 5000	W3791702A	V1.000.0	3
	•	cutively by selecti s can be updated		
1.51	* Please be sure to use System Vesion2.04 Engine Version2.001:12 Web support version1.5	<u>2</u> 51	, ,	
	Please apply the above of	nı <u>y</u> tor machines (operated under the fol	iowing
	preconditions.			
	Program Name System	Program No. G1786091E	Version 2.03	



PAGE: 3/7

Reissued: 29-Dec-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178003d
--------------	-----------------	----------------

Version	Modified Points or Symptoms Adjusted			
	System	G1786091E	2.03	
	Network Support (NCS)	G1786092C	7.03	
	Engine	G1785252E	2.000:12	
	LCDC	NA:G1785971B	1.01	
		EU:G1785972B		
	Language	G1785979	1.01	
	Websystem	G1786093C	1.01	
	 Implementation of firmware-sharing of Aegis-Base unit (M064) and Aegis-P1 (G178) This allows M064 and G178 to be used with the common firmware. Color Controller E80 correspondence 			
1.01	PnP table has been replaced to enable correspondence with multi-brands. Use combination of System:1.02 & engine:1.108:11 to operate.			
1.00	1st Mass production.			



PAGE: 4/7

Reissued: 29-Dec-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178003d
--------------	-----------------	----------------

<Appendix 1>

Please ensure to follow the procedures for the update.


The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware.

NOTE: • Do not do remote-update.

- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 5/7

Reissued: 29-Dec-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178003d
--------------	-----------------	----------------

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

. o. rogio o i			
Program name	Program No.	Version	
Engine	D0165252D	V3.000:12	

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 6/7

Reissued: 29-Dec-10

Model: AG-P1	Date: 18-Sep-08	No.: RG178003d
--------------	-----------------	----------------

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version
Animation	G1786094B	V2.2

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

<u> </u>			
Program name	Program No.	Version	
Language	G1785980A	V1.06	

D	I D N	11/	
Program name	Program No.	Version	
Language	G1785979A	V1.03	

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 7/7

Reissued: 29-Dec-10

Model: **AG-P1** Date: 18-Sep-08 No.: RG178003d

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

•

Technical Bulletin

PAGE: 1/6

Reissued: 05-Jan-11

Model: AG-P1	Date: 18-Sep-08	No.: RG178004b
--------------	-----------------	----------------

RTB Reissue

The items in **bold italics** have been corrected.

Subject: Firmware Release Note: Lcdc		Prepared	d by: H.Matsui	
From: PPBG Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical	☐ Part informa ☐ Electrical	tion	☐ Action required ☐ Service manual revision
	☐ Paper path ☐ Other ()	☐ Transmit/rec	eive	☐ Retrofit information

This RTB has been issued to announce the firmware release information for the Lcdc.

EUR

Version	Program No.	Effective Date	Availability of RFU
1.04	G1785972D	December 2010 production.	Available
1.03	G1785972C	August 2009 production.	Available
1.01	G1785972B	1st Mass production.	Available

USA

Version	Program No.	Effective Date	Availability of RFU
1.04	G1785971D	December 2010 production.	Available
1.03	G1785971C	August 2009 production.	Available
1.01	G1785971B	1st Mass production.	Available

Note: Definition of Availability of RFU

EUR/USA

Version	Modified Points or Symptom Corrected		
1.04	Wordings have been added in accordance with the modification of the Oil Tank Filter PM counter controls.		
	Please refer to <appendix 1=""> for update procedures. Make sure to follow the procedures when updating.</appendix>		
	Apply condition: Firmwares below to be applied together as a set.		
	Program Name Program No. Version		
	System	G1786091J	2.07
	Websystem	G1786093F	1.54
	Engine	G1785252Q	3.008:12
	LCDC	NA:G1785971D EU:G1785972D	1.04
	Language	G1785979B	1.04
1.03	 Support of Buffer Pass Unit Type 5000 and Perfect Binder GB5000 Support of a newly added function of the Engine, which enables an easy test solid print by pressing a button in the User Tools 		

[&]quot;Available": The firmware can be updated via RFU or SD card.

[&]quot;Not available": The firmware can only be updated via SD card.

PAGE: 2/6

Reissued: 05-Jan-11

Model: 🗚	G-P1	С	ate: 18-Sep-08	No.: RG178004
Version		ified Points or Syn		
	3. Support of animated gra	aphics for Buffer Pas	s Unit Type 5000 and	Fuser Knob
	Please refer to <appendix< td=""><td>1> for update proced</td><td>dures.</td><td></td></appendix<>	1> for update proced	dures.	
	Ensure to follow the proced			
	*Please make sure that AL	L versions listed held	ow are undated concu	rrently
	Program Name	Program No.	Version	ironay.
	System	G1786091G	2.05	
	Websystem	G1786093E	1.53	
	Network Support (NCS)	G1786092D	7.04	
	Engine	G1785252G	3.000:12	
	LCDC	NA:G1785971C	1.03	
		EU:G1785972C		
	Animation	G1786094B	2.2	
	Language	G1785979A	1.03	
	Fiery Server	-	4.0	
	* Undete to the following w	araiana ia raquirad fa	er all paripharala listad	holow
	* Update to the following ve	Program No.	Version	below.
	CI5010	B8355510F	V2.071:42	
	SR5000	B8305102P	V1.820:59	
	RB5000	Main : D3925510		
		Sub: D3925520C	· -	
	GB5000	000.0000000		
	P-Binder B1	D3915020C	V0.28	
	P-Binder_B2	D3915070B	V0.19	
	P-Binder B3	D3915730A	V0.13	
	P-Binder B4	D3915120B	V0.15	
	P-Binder B5	D3915170A	V0.25	
	BK5000	B8365550B	V2.17:15	
		+	<u> </u>	

Note

SK5000 1st stacker

2nd stacker

Type 5000

Buffer Pass Unit

• Make sure to update the peripherals in order of proximity to the main frame.

V4.02:12

V1.000:03

Do not update consecutively by selecting several peripherals.

D3645620_P1

D3645620_P2

M3791702A

- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

1.01 1st Mass production.



PAGE: 3/6

Reissued: 05-Jan-11

Model: AG-P1 Date: 18-Sep-08 No.: RG178004b

<Appendix 1>

Please ensure to follow the procedures for the update.

The firmware of GW controller needs to be updated at a time.


Make sure to update in the order since there is the order also for the other firmware.

NOTE:

- Do not do remote-update.
- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.

Start



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 4/6

Reissued: 05-Jan-11

Model: **AG-P1** Date: 18-Sep-08 No.: RG178004b

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

1 01 7 togio 0 1		
Program name	Program No.	Version
Engine	D0165252D	V3.000:12

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 5/6

Reissued: 05-Jan-11

Model: AG-P1	Date: 18-Sep-08	No.: RG178004b
--------------	-----------------	----------------

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version	
Animation	G1786094B	V2.2	

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

. e. 7.eg.e e :			
Program name	Program No.	Version	
Language	G1785980A	V1.06	

Program name	Program No.	Version	
Language	G1785979A	V1.03	

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 6/6

Reissued: 05-Jan-11

Model: **AG-P1** Date: 18-Sep-08 No.: RG178004b

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010 B8355510F		V2.071:42
SR5000	SR5000 B8305102P	
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

PAGE: 1/15

Reissued: 06-Jan-11

Model: AG-P1	Date: 14-Oct-08	No.: RG178005k
--------------	-----------------	----------------

RTB Reissue

The items in **bold italics** have been added.

Subject: Firmware Release Note: Engine			Prepared by: H. Matsui	
From: PPBG Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting	☐ Part informa	tion	Action required
		☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

This RTB has been issued to announce the firmware release information on the Engine.

Version	Program No.	Effective Date	Availability of RFU
3.008:12	G1785252Q	December 2010 production	Not available
3.007:12	G1785252P	September 2010 production	Not available
3.006:12	G1785252N	May 2010 production	Not available
3.005:12	G1785252M	April 2010 production	Not available
3.003:12	G1785252K	January 2010 production	Not available
3.002:12	G1785252J	November 2009 production	Not available
3.001:12	G1785252H	October 2009 production	Not available
3.000:12	G1785252G	August 2009 production	Not available
2.001:12	G1785252F	May 2009 production	Not available
2.000:12	G1785252E	March 2009 production	Not available
1.108:11	G1785252D	January 2009 production	Available
1.103:11	G1785252C	1st Mass production	Available

Note: Definition of Availability of RFU "Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptoms Adjusted			
3.008 :12	Modified Points:			
	1. Clearance of the fusing unit PM counter used to automatically clear the oil			
	filter PM counter. This counter will not be cleared filter even when			
	clearing the fusing u			
	Please refer to <appendix 1=""> for update procedures.</appendix>			
	Make sure to follow the procedures when updating.			
	Apply condition:			
	Firmwares below to be applied together as a set.			
	Program Name	Program No.	Version	
	System	G1786091J	2.07	
	Websystem	G1786093F	1.54	
	Engine	G1785252Q	3.008:12	
	LCDC	NA:G1785971D	1.04	
		EU:G1785972D		
	Language	G1785979B	1.04	
3.007 :12	Modified Points:			
	1. SC990 occurs in the following sequence.			
	(1)Paper is fed from tray3 (upper tray of A3LCT).			



PAGE: 2/15

Reissued: 06-Jan-11

Model: AG-P1		Date: 14-Oct-08	No.: RG178005	
Version	Modified Points or Symptoms Adjusted			
	 (2)Feed tray falsely switches from Tray3 to Tray4 (lower tray of A3LCT) (3)Pull out and push back in Tray3. (4)Feed tray switches back from Tray4 to Tray3, then SC990 occurs. 2. In a Perfect Binding job, cleaning of the charge in interrupted during job End Process Control causing abnormal image of banding in paper feed direction. 3. Machine remains in idle status when switching the output tray(for instance from the Shift tray to the Proof tray) and the paper runs out. 4. Machine alerts an SC and stops because the PM parts for the Perfect Binder are not counted and their life can not be detected. 			
3.006 :12	Modified Points:1. When a jam occurs, around the imaging the idle status.	area could run idle and r	naintain	
3.005 :12	2. Failure in the PM counter of the Cover Infection counted 3. Output of abnormal image; falsely general developments of the Cover Infection of SP values 5. Modification of SP values to resolve probect Apply condition: Apply condition: Apply to the machine working properly with Efor machines with Engine versions older that before upgrading to 3.005:12. Please upgrade all the peripheral firmwares of Additional information (in reference to Modified Failure in Toner Refreshing mode occurs with Please be informed that although the Engine released due to a defect, some machines in Eailure in Toner Refreshing mode (in reference Toner which is supposed to be put on the ITT Toner Refreshing mode is falsely overlapping excessive amount of toner for the belt cleaned contamination on the surface and/or edge of Conditions generating the stripes (in reference Process Control is executed when the mach continuously printing low coverage images of which are conditions where the developer unabnormal toner density is detected in this Preference of the process of deterior of the developer unabnormal toner density is detected in this Preference of the process of deterior of the developer unabnormal toner density is detected in this Preference of the process of deterior of the process of the process of deterior of the process of the p	ints: jam occurs, around the imaging area could run idle and maintain status. ints: n Toner Refreshing mode on the Engine firmware version 3.004:12 n the PM counter of the Cover Interposer in which the jobs weren't f abnormal image; falsely generated stripe pattern tion of fuser related SP values tion of SP values to resolve problem of black printed in low density tion: machine working properly with Engine version newer than 3.000:12. es with Engine versions older than 3.000:12, first upgrade to 3.000:12 adding to 3.005:12. add all the peripheral firmwares to the latest versions. Information (in reference to Modified Point 1) oner Refreshing mode occurs with Engine firmware version 3.004:12. Informed that although the Engine firmware version 3.004:12. In is supposed to be put on the ITB with intervals between the colors in shing mode is falsely overlapping among the colors resulting in mount of toner for the belt cleaner to remove. This may cause on on the surface and/or edge of the paper. Introl is executed when the machine goes into Stand-by mode either after or printing low coverage images or running the developer unit in idle, both onditions where the developer unit contains deteriorated developer. If need to suppose of deteriorated toner. Stripes appear on the use the toner is falsely put on the sheets instead of the ITB for disposal.		
	IMPORTANT information (in reference to Mo	odified Point 4)		



PAGE: 3/15

Reissued: 06-Jan-11					
Model: AG	G-P1	Date: 14	4-Oct-08	No.: RG178005	
Version	Modified Points or Symptoms Adjusted				
	Fuser related SP default values have been modified on this firmware. Please make sure to follow the below procedure when applying the firmware. a. Confirm whether the customer applies Special 3 or Special 6. b. If applied, print out SMC report. c. Upgrade the firmware. d. Re-input the fuser related values for the following SP settings by referring to the SMC report.				
	SP1-105- 208,209,210,211,212,213,214,215,218,219,220,221,222,223,224,225,226,227 SP1-108- 063,064,065,066,067,068,069,070,071,072,073,074,075,076,077,078,079,080, 081,082,083,084 SP1-905- 048,049,050,114,115,116 SP1-909- 057,058,059,060,061,074,076,077,078,079				
	to Modified Point 5) ■ $3-501-010: 0 \rightarrow 1$ ■ $3-561-031: -0.2 \rightarrow -0.05$ ■ $3-561-032: -0.1 \rightarrow 0.1$ ■ $3-561-033: 0 \rightarrow 0.3$ ■ $3-561-034: 0 \rightarrow 0.3$	 1 2 → -0.05 → 0.1 → 0.3 → 0.3 			
3.003:12	 3-561-035: 0.12 → 024 Modified Points: To prevent the failure of SK5000 full sensor LED lighting. To transmit the adjustment values of SR5000, such as poison of punch hole, to the main frame, when Plockmatic is attached. Countermeasure for obstacle of Perfect binder inserter, when nonstandard-size media is set. To prevent the occurrence of Jam, when outputting the stacker sample of media size mixed data. To prevent the occurrence of many Jam notifications when the registration is working abnormally. To Improve the failure of small job interval during the work for every 30 pages To prevent false positive of detecting SC, when the front door is open and removed the Fuser Unit. Usually it should not detect any SC. Changed the standard value for detecting the near end. (Changed the default SP values) Countermeasure against, "when output is in color mode, only black date comes out and YMC data do not come out and appeared as white." Apply condition: Apply condition: Apply to the machine working properly with Engine version newer than 3.000:12. For the machine with engine version older than 3.000:12, previously update the Engine version to 3.000:12, and then update it to 3.003:12. Updates to the following versions are required for all peripherals listed below. 				
	CI5010	Program No. B8355510F	Version V2.071:42		
	SR5000	B8305102P	V1.820:59		



PAGE: 4/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

Version	Modified Points or Symptoms Adjusted		
	SR5000	B8305102P	V1.820:59
	RB5000	Main: D3925510E	V1.290:04
		Sub: D3925520C	V1.060:01
	GB5000		
	P-Binder_B1	D3915020D	V0.310
	P-Binder_B2	D3915070D	V0.220
	P-Binder_B3	D3915730A	V1.19
	P-Binder_B4	D3915120B	V0.150
	P-Binder_B5	D3915170B	V0.260
	BK5000	B8365550B	V2.17:15
	SK5000		
	1 st stacker	D3645620_P1	V4.02:12
	2 nd stacker	D3645620_P2	
	Buffer Pass Unit	M3791702A	V1.000:03
	Type 5000		

Cause of "when output is in color mode, only black date comes out and YMC data do not come out and appeared as white."

When first printing in B/W mode, then if the full color printing mode begins within 127ms, after the last page of B/W print passes the Paper Transfer Roller, printing mode dose not change from B/W printing mode to full color printing mode, which causes this symptom. Due to a very small time interval, this symptom seldom occurs.

In the following cases, there is a possibility that this symptom might occurs.

- Printing Full color job soon after B/W job.
- When the process control takes place between B/W page and Full color paper, while printing.
- When B/W pages and Full color pages are mixed in one job.

We recommend you to update the Engine Firmware, in order to prevent this symptom from happening.

With changing the standard value for detecting the near end, following SP default values have changed

SP3-411-001 : 10 (times) \rightarrow 3 (times) SP3-411-002 : 10 (times) \rightarrow 3 (times) SP3-411-007 : 500 (g) \rightarrow 150 (g) SP3-411-008 : 500 (g) \rightarrow 150 (g)

These SP values were changed, because of making the values for measure against light spot / fire fly as default values. (refer to RG178077)



PAGE: 5/15

Reissued: 06-Jan-11

Model: AG	G-P1		Date: 14-Oct-08	No.: RG178005
Version	Modif	ied Points or S	Symptoms Adjusted	
3.002 :12	Modified Point: To prevent false positive of			
	Apply condition: Apply to the machine workin 3.001:12.	ng properly with	either Engine version 3.0	000:12 or
	For the machine with engine Engine version to 3.000:12,			update the
3.001 :12	JAM 146 occurrence conditi JAM146 does not occur whe Following conditions are wh Inserter +RB 5000 Inserter +SK 5000 Inserter +SK 5000 + Si Modified Point	en ZF 4000 is at en ZF 4000 is no		
3.001.12	To prevent false positive of Apply condition Apply to the machine working			
	Matters that require attention Updated Firmware for GB50 firmware to version 3.001:12 version as shown below.	000 is indicated i		
		Program No.	Version	
	GB5000 P-Binder_B1 P-Binder_B2 P-Binder_B3 P-Binder_B4 P-Binder_B5 Notes	D3915020D D3915070C D3915730A D3915120B D3915170B	V0.31 V0.21 V0.13 V0.15 V0.26	
	 Make sure to update the 	utively by selec	n order of proximity to the ting several peripherals d consecutively.	

<u>Technical Bulletin correction</u> <u>Appendix 1, 6. Peripheral Update: SK5000 version is corrected.</u>



PAGE: 6/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

Version Modified Points or Symptoms Adjusted

3.000:12

Please refer to <Appendix 1> for update procedures. Ensure to follow the procedures when updating.

*Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	G1786091G	2.05
Websystem	G1786093E	1.53
Network Support(NCS)	G1786092D	7.04
Engine	G1785252G	3.000:12
LCDC	NA:G1785971C	1.03
	EU:G1785972C	
Animation	G1786094B	2.2
Language	G1785979A	1.03
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main:D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	V1.000:03
Type 5000		

Note

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

1. The adjustable range of the fusing temperature

The adjustable maximum value has been modified from 200 degrees to 205 degrees.

2. The adjustable range of "Idle Time: After Reload"

The adjustable maximum value of "Idle Time: After Reload" has been modified from 15 minutes to 60 minutes.

3. The modification of SP from target to not target of "NVRAM clear"

When "NVRAM clear" was excused, the following SP value also had been cleared.

Therefore, the status of use becomes unclear, and the exchange at the appropriate timing might



RICOH Technical Bulletin

PAGE: 7/15

Reissued:	: 06-Jan-11	_		
Model: AG	G-P1	Date: 14-Oct-08	No.: RG178005	
Version	Modified Points or be impossible. To prevent this, the SP has been removed from th SP1-902-001: Web Consumption SP1-903-001: Web: Total Page Counter SP1-903-002: Web: Total Motor Rotation Time SP1-904-014: Oil End Counter	Symptoms Adjusted ne target at the "NVRAM cle		
	4. The countermeasure for toner blister The following modification will be enforced for the The additional SP are (1), (4), (5) and (6).	countermeasure control for	toner blister.	
	 (1) The addition of the toner blister countermeasure mode switching [New SP] SP1-208-001 Toner Blister Control Blister 0:OFF 1:ON * The default 0: OFF. When it is ON, the following (2) – (6) become effective. (2) Eliminating pressure while warming-up (The pressure has been modified to be eliminated except during printing.) 			
	(3) Imminent pressure control just before printing (The pressure roller is nipped immediately before p			
	(4) Setting "the pressure reloading temperature" and "the waiting temperature" at 90 degrees. [New SP] Toner Blister Control Press Roll SP1-208-002 Ctr: Reload[70to160/90/1 degrees] SP1-208-003 Ctr: Idle: Reload[70to160/90/1 degrees] SP1-208-004 Ctr: Standby: Normal Temp[70to160/90/1 degrees] SP1-208-005 Ctr: Standby: Low Temp[70to160/90/1 degrees] SP1-208-006 Ctr: Standby: High Temp[70to160/90/1 degrees]			
	(5) Setting the pressure roller temperature at 90 de [New SP] Toner Blister Control Press Roll SP1-208-007 Thin: Press Roll Temp [70to160/5 SP1-208-008 Normal: Press Roll Temp [70to16 SP1-208-009 Middle: Press Roll Temp [70to16 SP1-208-010 Thick1: Press Roll Temp [70to16 SP1-208-011 Thick2: Press Roll Temp [70to16 SP1-208-012 Thick3: Press Roll Temp [70to16	90/1 degrees] 60/90/1 degrees] 0/90/1 degrees] 0/90/1 degrees] 0/90/1 degrees]		
	(6) The low-power control when toner blister count The pressure roller setting temperature is set at 90 [New SP] Toner Blister Control Press Roll SP1-208-013 Temp: Low Power Mode [70to150]	0 degrees.	ned on	
	5. The modification of the control of winding the fu When removing the jammed paper by rotating the the surface waviness of the web occurs by the rota "The fusing belt" rotates at the same time when th paper jam is processed. Therefore, the surface waviness is not completely into the cleaning unit at worst. The operation after paper jam processing has bee The control is modified to rotate the fusing belt after finished.	fusing knob after the occurration of the fusing belt. the operation of web winding solved; the web is winded it an modified for improvement	is enforced after the n and it is exhaled	
	6. Correspondence to concentration variation by to lt is likely to become a non-standard printing extra temperature rise in the machine, and SC367 occu	density due to the VL decre		



PAGE: 8/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

Version Modified Points or Symptoms Adjusted

The occurrence is seen especially when changing into FC mode after printing in large quantity in black mode.

Both "before entering into the start-up sequence when printing is demanded" and "at switchover time from black mode to FC mode", the potential ProCon (process control) will be enforced when the temperature in the machine has been changed more than 2 degrees from when the ProCon is enforced last time.

According to this, the following SP is newly added.

Before Job Process Control SP3-555-003:Temperature Range ON/OFF *0:ON 1:OFF

SP3-555-004: Temperature Range 0to99/2/1 degrees

 $\overline{7}$. Specification modification of "short idle time" ProCon and "temperature change" ProCon If the low coverage printing is repeated after "short idle time" ProCon or "temperature change" ProCon, the development γ (gamma) will drop to the lower limit and the appropriate image density may not be obtained.

For improving this, the execution condition of the toner density adjustment of "short idle time" ProCon and "temperature change" ProCon has been modified.

The condition after modification is the same as the execution condition of "job end ProCon"

The toner density adjustment is executed upon the satisfaction of the following conditions.

- (1) When the development γ (the detected value) is lower than 1.2.
- (2) When the absolute value of $\Delta \gamma$ =the development γ (the targeted value) the development γ (the detected value) is over 0.2.

8. "Short idle time" ProCon

There have been cases that the density depression after short idle time (30 minutes to 6 hours) occurs.

The density depression in this case can be avoided by executing the potential ProCon before the job.

However, only the way to correspond was to change the time interval of the "short idle time" ProCon from 6 hours(default) to 30 minutes because there was no potential ProCon mode that is executed automatically by idling for a short time (more than 30 minutes) at the moment.

However, the "short idle time" ProCon contains developer agitation, adjustment of toner density, fade removal mode and oil removal mode as a set.

The problem was that the waiting time until the ending of ProCon is too long (for a maximum of about 4 minutes) and the toner is uselessly consumed.

Therefore, the mode that executes only the potential ProCon after idling for a short time (about 30 minutes) is newly added.

The potential ProCon execution mode is newly added upon the satisfaction of the following conditions.

[Timing of call]

Before entering into the start-up sequence when printing is demanded

[Execution condition]

- The idling time from the end of the last job is more than the setting value of SP3-555-002 (Before Job ProCon Idling Time).
- The idling time is less than the setting value of SP3-554-002 (Init ProCon Set Non-use Time Setting).

The following SP are newly added with the above modification.



PAGE: 9/15

Reissued: 06-Jan-11

Model: AG	G-P1		Date: 14-Oct-08	No.: RG178005
Version	Mod	ified Points or S	ymptoms Adjusted	
	SP3-555-001: Before Job Procon Short Idle Time ON/OFF 0:ON *1:OFF			
	SP3-555-002: Before Job Proce 0to999/20/1min	on Idling Time		
	9.Support of Buffer Pass Unit Type 5000 and Perfect Binder GB5000 10. Support of a newly added function of the Engine, which enables an easy test solid print by pressing a button in the User Tools			st solid print by
2.001 :12	* Please be sure to use the	ne following as a s	set for undating	
2.001.12	System Vesion2.04 Engine Version2.001:12 Web support version1.51	ic following as a c	section appearing.	
	Please apply the above <u>o</u> preconditions.	nly for machines	operated under the fo	llowing
	Program Name	Program No.	Version	
	System	G1786091E	2.03	
	Network Support(NCS)	G1786092C	7.03	
	Engine	G1785252E	2.000:12	
	LCDC	NA:G1785971E EU:G1785972E		
	Language	G1785979	1.01	
	Websystem	G1786093C	1.01	
Implementation of firmware-sharing of Aegis-Base unit(M064) ar P1(G178) This allows M064 and G178 to be used with the common firmware since to distinguish the serial number of M064. Color Controller E80 correspondence				

PAGE: 10/15

Reissued: 06-Jan-11

Model: AG-P1	Date: 14-Oct-08	No.: RG178005k
--------------	-----------------	----------------

V	B4114	ii d Dainta an Oranatana	A aliana ta al	
Version	Modified Points or Symptoms Adjusted			
2.000 :12	* Please make sure that ALL versions listed below are updated concurrently.			
	Program Name	Program No.	Version	
	System	G1786091E	2.03	
	Network Support(NCS)	G1786092C	7.03	
	Engine	G1785252E	2.000:12	
	LCDC	NA:G1785971B	1.01	
		EU:G1785972B		
	Language	G1785979	1.01	
	Websystem	G1786093C	1.01	
	Fiery Server	-	3.0	
	* Update to the following versions is required for all peripherals listed below.			
	Program Name	Program No.	Version	
	SR5000 Finisher	B8305102M	1.60	
	Cover Interposer Tray	B8355510E	02.070	
	CI5010			
	Ring Binder RB5000	Main:D3925510D	Main:1.280:04	
	ı	Sub :D3925520B	Sub :1.050:01	
	High Capacity Stacker	1st:D3645620_P1	4.02:12	
	SK5000	2nd:D3645620 P2		
	Booklet Finisher BK5000	B8365550B	2.17	
	Note			

- * Peripherals must be updated ONE at a time, starting from the machines closest to the mainframe. Do NOT attempt to select and update multiple Firmware at once.
- * For the Ring Binder RB5000, Main and Sub shall be updated together.
- 1. Connections of the following peripherals are now available. Ring Binder RB5000, High Capacity Stacker SK5000, PLOCKMATIC, GBC
- 2. Web Cleaning Unit: Near End/End Clear Error (RTB No. RG178040) has been corrected. Work procedure after the Web Cleaning Unit replacement can now follow the instructions prescribed in the Service Manual.
- 3. Correction of inability of +24V power source defect detection

PCB	Fuse Number	Supplied Voltage Name	SC numbers indicated on the display panel (SC Level D)	+24V SCs (SC Level C)
IOB 1	FU103 - 5A / 32v	+24V_1AINT	SC311	SC674-02
IOB 1	FU104 - 5A / 32v	+24V_2BINT	SC520	SC675-03
IOB 1	FU105 - 5A / 32v	+24V_2AINT	SC347	SC675-02
IOB 1	FU106 - 5A / 32v	+24V_4A	SC530-8	SC677-02
IOB 1	FU107 - 5A / 32v	+24V_4B	SC531-12	SC677-03
IOB 1	FU108 - 4A / 32v	+24VINTA	SC303	SC675-06
IOB 2	FU101 - 4A / 32v	+24VINTA	SC443	SC675-10
IOB 2	FU102 - 5A / 32v	+24V_3B	SC472	SC676-03
IOB 2	FU103 - 5A / 32v	+24V_3A	SC530-3	SC676-02
IOB 2	FU104 - 5A / 32v	+24V_3C	SC530-5	SC676-04

Note

- *The silkscreen print on the board indicates 32V, however, this is the rated voltage of the Fuse (circuit protector). Actual supply voltage is 24V entirely.
- *All +24V SCs involving trip of the circuit protector are only logging. Therefore, different SCs are indicated in appearance.

Technical Bulletin

PAGE: 11/15

Reissued: 06-Jan-11

Model: AG	Model: AG-P1 Date: 14-Oct-08 No.: RG178005k		
Version	Modified Points or Symptoms Adjusted		
2.000 :12	4. Falsely clearing of the machine number data when clearing Engine NV		
	5. Occurrence of JAM 20 when switched to the second LCT-Multi Bypass Tray		
	BY5000 from the mainframe bank.		
	6. PM counter newly added for the High Capacity Stacker SK5000		
1.108 :11	Malfunction has been restored involving the appearance of an alert signal		
	indicating a spanner mark when pulling out the trays.		
	2. Oil Removal function made available during process control for Interrupt,		
	JobEnd and Non-use Time Setting.		
	3. Change has been made in Oil Removal manual operation method.		
	4. Adjustments have been made for trouble occurrence of SC670 during		
	Clearing Engine Memory (SP5-801-002).		
	*Use combination of System:1.02 & engine:1.108:11 to operate.		
1.103:11	1st Mass production (October 2008)		



Technical Dulletin Page: 12/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

<Appendix 1>

Please ensure to follow the procedures for the update.


The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware.

NOTE:

- Do not do remote-update.
- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 13/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

. o. 7 tog.o o 1			
Program name	Program No.	Version	
Engine	D0165252D	V3.000:12	

For Aegis-P1

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 14/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version
Animation	G1786094B	V2.2

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

· · · · · · · · · · · · · · · · · · ·			
Program name	Program No.	Version	
Language	G1785980A	V1.06	

For Aegis-P1

Program name	Program No.	Version
Language	G1785979A	V1.03

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 15/15

Reissued: 06-Jan-11

Model: AG-P1 Date: 14-Oct-08 No.: RG178005k

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main: D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.02:12
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

•

Technical Bulletin

PAGE: 1/6

Reissued: 05-Jan-11

Model: Aegis-P1	Date: 14-Oct-08	No.: RG178006b
-----------------	-----------------	----------------

RTB Reissue

The items in **bold italics** have been corrected.

Subject: Firmware Release Note: Language Install		Prepared by: H.Matsui		
From: PPBG Service Planning Dept.				
Classification:	Troubleshooting	☐ Part informat	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☑ Other ()			

This RTB has been issued to announce the firmware release information for the **Language Install**

Version	Program No.	Effective Date	Availability of RFU
1.04	G1785979B	December 2010 production.	Not available
1.03	G1785979A	August 2009 production.	Not available
1.01	G1785979	1st Mass production.	Not available

Note: Definition of Availability of RFU

[&]quot;Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected				
1.04	Wordings have been added in accordance with the modification of the Oil Tank Filter PM counter controls.				
	Please refer to <appendix 1=""> for update procedures. Make sure to follow the procedures when updating.</appendix>				
	Apply condition: Firmwares below to be ap	plied together as a set.			
	Program Name	Program No.	Version		
	System	G1786091J	2.07		
	Websystem	G1786093F	1.54		
	Engine	G1785252Q	3.008:12		
	LCDC	NA:G1785971D EU:G1785972D	1.04		
	Language	G1785979B	1.04		
1.03			t Type 5000 and Fuser Knob.		
Support of a newly added function of the Engine, which enables an solid print by pressing a button in the User Tools					
	Please refer to <appendix 1=""> for update procedures. Ensure to follow the procedures when updating.</appendix>				
	*Please make sure that ALL				
	Program Name	Program No.	Version		



PAGE: 2/6

Reissued: 05-Jan-11

Model: Ae	gis-P1		Date: 14-0	Oct-08	No.: RG178006b
Version	Modi	ified Points or S	ymptom Co	orrected	
	System	G1786091G		2.05	
	Websystem	G1786093E		1.53	
	Network Support (NCS)	G1786092D		7.04	
	Engine	G1785252G		3.000:12	
	LCDC	NA:G17859710		1.03	
		EU:G17859720	C		
	Animation	G1786094B		2.2	
	Language	G1785979A		1.03	
	Fiery Server	-		4.0	
	* Update to the following ve	areione ie roquirod	for all perin	harale lietad	helow
	opuate to the following ve	Program No.	i loi ali peripi	Version	below.
	CI5010	B8355510F		V2.071:42	
	SR5000	B8305102P		V1.820:59	
	RB5000	Main : D39255	10E	V1.290:04	
		Sub: D3925520	OC	V1.060:01	
	GB5000				
	P-Binder_B1	D3915020C		V0.28	
	P-Binder_B2	D3915070B		V0.19	
	P-Binder_B3	D3915730A		V0.13	
	P-Binder_B4	D3915120B		V0.15	
	P-Binder_B5	D3915170A		V0.25	
	BK5000	B8365550B		V2.17:15	
	SK5000				
	1 st stacker	D3645620_P1		V4.02:12	
	2 nd stacker	D3645620_P2			
	Buffer Pass Unit	M3791702A		V1.000:03	
	Type 5000 Note				
	 Make sure to update 	the nerinherals in	order of pro	ovimity to th	ne main frame
	 Do not update consec 				
	• For GB5000, 5 board				
	• For RB5000, 2 boards				
1.01	1st Mass production.(Od	ctober 2008)			
	13t mass production.(Ot	Coder 2000)			



PAGE: 3/6

Reissued: 05-Jan-11

Model: **Aegis-P1** Date: 14-Oct-08 No.: RG178006b

<Appendix 1>

Please ensure to follow the procedures for the update.


The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware.

NOTE:

- Do not do remote-update.
- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 4/6

Reissued: 05-Jan-11

Model: Aegis-P1 Date: 14-Oct-08 No.: RG178006b

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

1 of Alogio of		
Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

1 01 7 togio 0 1		
Program name	Program No.	Version
Engine	D0165252D	V3.000:12

For Aegis-P1

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 5/6

Reissued: 05-Jan-11

Model: Aegis-P1	Date: 14-Oct-08	No.: RG178006b
-----------------	-----------------	----------------

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version
Animation	G1786094B	V2.2

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

<u> </u>			
Program name	Program No.	Version	
Language	G1785980A	V1.06	

For Aegis-P1

Program name	Program No.	Version	
Language	G1785979A	V1.03	

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

Technical Bulletin

PAGE: 6/6 Reissued: 05-Jan-11

Model: Aegis-P1 Date: 14-Oct-08 No.: RG178006b

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main: D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

PAGE: 1/8

Model: Aegis-P1 Dat			ate: 15-Oct-08		No.: RG178007	
Subject: Exit Idle Roller Replacement			Prepared by: N. lida			
From: PPBG QA/Service Planning Dept.						
Classification:		☐ Part informati		ation		required
		☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

Requirement for installation

When attaching an SR5000 finisher to Aegis P1, please make sure that the finisher was produced in April or later (SN: $15880400895 \sim$).

Symptom

When using coated paper and feeding lengthwise, creasing can occur. SR5000 which were manufactured during the period from April ~ September may have the potential for this problem, so it is necessary to apply the modification at installation, following the procedure below

Cause

Creasing is a result of the angle of the edge of the Exit Idle Roller.

Solution

Replace the Exit Idle Rollers when an SR5000 manufactured during the period April ~September 2008 is installed. The rollers that are necessary for the replacement are included with the Aegis-P1 as accessories.

Permanent Countermeasure

SR5000 manufactured from October will reflect this production change and will not require the replacement procedure.

Model: Aegis-P1

Date: 15-Oct-08 No.: RG178007

SR5000 Exit Idle Roller Replacement Procedure

Contents

Please replace the Exit Idle Roller included with the machine when installing the SR5000 when it is connected to the Pro C900.


Replacement procedure

1 . Removal of the cover

In order to replace the part, first remove the exterior covering.

1-1 Cover removal

Remove the top two screws and then the cover





Model: Aegis-P1

Technical Bulletin


Date: 15-Oct-08 No.: RG178007

PAGE: 3/8

1-2 Inner cover Remove the three screws and then the inner cover




$2\,.$ Paper ejection guide board : Removal of the Guide Board



Model: Aegis-P1 Date: 15-Oct-08 No.: RG178007

2-1 Removal of the Harness

Remove the harness connected to the paper ejection guide board. Remove the harness connected to the base by the terminal end through the hole in the side board





PAGE: 4/8

Harness protrudes here

Pull the harness inside



PAGE: 5/8

Model: Aegis-P1 Date: 15-Oct-08 No.: RG178007

2-2 Removal of the connection of the paper ejection guide board Pinch the spring, and pull it forward while holding it down.




Removed parts



2-3 Removal of the silencer Remove the silencer at the tip of the shaft of the paper ejection guide board





Model: Aegis-P1

Technical Bulletin

Date: 15-Oct-08 No.: RG178007

PAGE: 6/8


2-4 Removal of guideboard: Paper ejector

The paper ejection guide board is lifted. While raising the guide board toward the back, remove the front shaft first. After that, the guide board: paper ejector, is removed by pulling forward.



3 Removal of drive rollers Remove the guide board: paper ejection drive rollers

3-1 Dissasemble the guide board: paper ejector With the removal of the two screws, the sheets of metal can be separated







PAGE: 7/8


Model: Aegis-P1 Date: 15-Oct-08 No.: RG178007

3-2 Removal of drive rollers

With the removal of the screw holding down the driver rollers, the drive roller shaft (with rollers attached) can be removed



3-3 Replacement of the drive rollers



Remove the E-rings on either end of the shaft and replace the drive rollers



Model: Aegis-P1

Technical Bulletin

Date: 15-Oct-08 No.: RG178007

PAGE: 8/8

Caution when replacing

Because the trailing groove differs on both sides, please install the wider one on the guide board side



Please follow the reverse procedure when returning to original condition

Technical Bulletin

PAGE: 1/1

Reissued: 16-Oct-08

Model: Aegis-P1 EFI	Date: 14-Oct-08	No.: RG178008
---------------------	-----------------	---------------

Subject: Firmwar	re Release Note: System EFI		Prepared	d by: N.lida
From: PPBG QA/	Service Planning Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informa☐ Electrical☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information

This RTB is the release note for Patch File **1-YX34D_1.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-YX34D_1	Fiery keeps displaying "printing" and stops.

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s): None

Patch Update Procedure

- 1. Extract R0205007.exe until you get the 1-YX34D_1.ps file.
- 2. Download/Import the patch file "1-YX34D_1.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-YX34D".

Notes: The patch does not change the Fiery version.

Technical Bulletin

Reissued: 16-Oct-08

Model: Aegis-P1 EFI	Date: 14-Oct-08	No.: RG178009
---------------------	-----------------	---------------

Subject: Firmwar	e Release Note: System EFI		Prepared	by: N.lida
From: PPBG QA/	Service Planning Dept.			
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path	☐ Part informa☐ Electrical☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information
	⊠ Other ()			

This RTB is the release note for Patch File **1-ZPVPD.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-ZPVPD.ps	 Fiery does not recover to print after misfeed in the printing status After Jam Recovery, if Continue is pushed, the Jam Recovery message did not disappear from the display The engine prints the wrong data with only yellow when the original data is B&W.

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s):1-YX34D 1

Patch Update Procedure

- 1. Extract R0205009.exe until you get the 1-ZPVPD.ps file.
- 2. Download/Import the patch file "1-ZPVPD.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. From either Command Workstation or the Fiery LCD, select "Shut Down" and then "Reboot System"
- 5. Wait until the Fiery has come to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-ZPVPD".

Notes: The patch does not change the Fiery version.

PAGE: 1/1

Technical Bulletin

PAGE: 1/4

Model: Aegis-P1 Dat			te: 17-Oct-08		No.: RG178010	
Subject: SR5000 Belt tension adjustment			Prepared	d by: N.iid	da	
From: PPBG QA/	Service Planning Dept.					
Classification:		☐ Part info	orma	tion	Action	required
	☐ Mechanical ☐ Electrical		al		☐ Service	e manual revision
	☐ Paper path ☐ Transmit/red		it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

Slippage of the shift tray drive timing belt

.

CAUSE

When fully loaded with coated paper or high-density paper, or when paper sizes A3 and larger multi feed, slippage of the shift tray drive timing belt can occur. When the tension of either the front or rear belt slackens, the shift tray can slant and paper jams can occur.

SOLUTION

When this occurs, please follow the procedure below to adjust the tension of the drive belt.

Procedure for adjusting drive belt tension

① Remove the front and rear cover of the finisher








Model: Aegis-P1

Technical Bulletin


Date: 17-Oct-08 No.: RG178010


PAGE: 2/4

② Please remove the two brackets on the rear board



③ Please loosen the tightening screw of the front drive belt






PAGE: 3/4

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178010

④ Please remove the drive unit Please support the tray when removing the drive because it may fall





⑤ To adjust the belt's tension, please place sufficient weight on the tray.

As in the illustration below, if the proper amount of weight (three packs of 500 sheets each) is placed on the shift tray (B7063126), the standard center tension will be adjusted.



6 Please tighten the tension screw






Model: Aegis-P1


 Ulletin
 PAGE: 4/4

 Date: 17-Oct-08
 No.: RG178010

Please replace the drive unit



®Please connect the two brackets on the rear board



Model: Aegis-P1

Classification:

Technical Bulletin

	Date: 17-Oct-08		No.: RG178011		
Prepared by: N			ida		
☐ Part info	ormation	☐ Action	required		
☐ Electric	al	⊠ Servio	Service manual revision		

☐ Tier 2

☐ Retrofit information

PAGE: 1/1

One aspect of the procedure to remove the oil application unit (Service manual P368) has changed.

Other (

☐ Transmit/receive

)

Contents of alteration

The number of clamps has changed. Previous procedure

Subject: Removal of oil application unit


☐ Troubleshooting

☐ Mechanical


☐ Paper path

☐ Product Safety

From: PPBG QA/Service Planning Dept.



New procedure




Technical Bulletin


Model: Aegis-P1 Da			Dat	Date: 17-Oct-08		No.: RG178012
Subject: Pressure roller lamp replacement				Prepared	d by: N. ii	ida
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2	

Pressure roller lamp exchange procedure (Service Manual P365) change.

Contents of alteration


Previous procedure






PAGE: 1/1

New Procedure



- 3. Disconnect the connector [A] on the fusing unit rear side.
- 4. Pressure roller lamp rear holder [B] (F x 1)



Technical Bulletin

PAGE: 1/1


Model: Aegis-P1			Date: 17-Oct-08		08	No.: RG178013
Subject: Oil supply procedure at installation			Prepared by: N.		d by: N. Ii	ida
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	n required
		☐ Electrica	al		⊠ Service	ce manual revision
	☐ Paper path	☐ Transmit/receive		eive;	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

When installing, oil replenishment is necessary (Service manual P45), but there have been some changes to the replenishment procedure.

Contents of alteration

Previous procedure

As seen in the illustration below, oil was supplied at one place in the rear of the machine.



New Procedure

As in the illustration below, there are two oil supply ports through which the oil supply bottle can fill each half.



Technical Bulletin

PAGE: 1/2

Reissued:29-Jan-09

Model: Aegis-P1	Date: 17-Oct-08	No.: RG178014a
-----------------	-----------------	----------------

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Color registration check procedure change			Prepared by: N. lida		
From: PPBG QA/Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part informa	tion	Action required	
	☐ Mechanical	☐ Electrical		⊠ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

The Color Registration check and Ruled Line Check (Service Manual P206 – P207) procedure has changed.

Contents of the alteration

Color Registration check

The grid pattern output procedure has changed as per the content below.

- 1. Turn on the main power switch.
- 2. Enter the SP mode and then select SP2109-002 ("Select Pattern" < "Write Test Pattern").
- 3. Select the No.9 (9: 20mm Grid) pattern in the test pattern list, and then press "OK".
- 4. Press the "APL Window" button on the top of the LCD.
- 5. Select a paper size and print mode (simplex or duplex).
- 6. Make a color print from a PC (the Fiery print driver's test print page can be used)
- 7. Check that the grid lines for each color are superimposed correctly.

Notes

Only a black print is output when the "Print" button is pressed on the operation panel.

A color print job from a PC is needed for checking YMCK color registration errors. Also, the print data must include black, red, green and blue.




PAGE: 2/2

Reissued:29-Jan-09

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178014a

Ruled Line Check

- 1. Turn on the main power switch.
- 2. Enter the SP mode (System SP) and then select SP2109-002 ("Select Pattern" < "Write Test Pattern").



- 3. Select the No.9 (9: 20mm Grid) pattern in the test pattern list, and then press "OK".
- 4. Print out the 20mm grid pattern sample for each single color with SP2109-004.

There are 8 bits on the screen in SP2109-004. Each bit corresponds to a color. "0": Not selected, "1": Selected

- [1] for "Black". Press the "3" key on the operation panel if you want to select this color.
- [2] for "Cyan". Press the "2" key on the operation panel if you want to select this color.
- [3] for "Magenta". Press the "1" key on the operation panel if you want to select this color.
- [4] for "Yellow". Press the "0" key on the operation panel if you want to select this color.
- 5. Press the "APL Window" button on the top of the LCD.
- 6. Select a paper size and print mode (simplex or duplex).
- 7. Make a color print from a PC (the Fiery print driver's test print page can be used).
- 8. Check that the grid lines for each single color test pattern are not scratched.

Notes

Only a black print is output when the "Print" button is pressed on the operation panel.

A white sheet (non-printed) is output when the "Print" button is pressed during YMC color selection.

For YMC Ruled Line Check, a color print job from a PC is needed; the image must include relevant toner colors. The Test Print Page will not cause a "white sheet problem" because this test includes all toner colors of YMCK; output colors of black, red, green and blue.

Model: Aegis-P1			Dat	e: 17-Oct-	80	No.: RG178015
Subject: Electrical voltage at installation			Prepared	d by: N.iid	da	
From: PPBG QA	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Change of the position of the connector connecting the oil pump and the electrical voltage meter at installation.

Purpose

Depending on the electrical conditions of the installation location, because the voltage supplied to the oil pump from the AC Drive fluctuates, the electrical voltage from the outlet to which the mainframe is connected is measured in order to change to the optimum connector number. (Please measure when the mainframe power cord is not plugged in.) When this does not happen, the voltage supplied to the oil pump drops resulting in a decrease of available oil. Therefore this process must be carried out.

To ensure a constant voltage supply to the oil pump, the AC Drive has been altered.

AC Drive PCB See MB 32 **PAGE: 1/3**

Procedure

Depending on the type, please initiate the "Type NA: G178-17, 57" procedure on page 2 or the "Type EU: G178-27, 67" procedure on page 3.

PAGE: 2/3

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178015

Type: NA: G178-17, 57

Step 1

Please measure the voltage of the outlet to which the power cord of the mainframe is connected.


(Please measure it without the mainframe plugged in.)

Step 2

Switch the connection of the connector to the oil pump to the corresponding connector number.

Please be careful because the connector number changes according to frequency.

Frequency	Voltage	Connector No.	Insertion Position
	Less than 188V	CN614	Move the connector to 180V/200V
5011	188-205V	CN615	188V/208V: Currently being shipped at this position
50Hz	205-220V	CN616	Move the connector to 205V/225V
	220V or greater	CN617	Move the connector to 220V/240V
	Less than 200V	CN613	Move the connector to (170V)/190V
	200-208V	CN614	Move the connector to 180V/200V
	208-240V	CN615	188V/208V: Currently being shipped at this position
60Hz	225-240V	CN616	Move the connector to 『205V/225V
	240V or greater	CN617	Move the connector to 220V/240V



PAGE: 3/3

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178015

Type EU: G178-27, 67


Step 1

Please measure the voltage of the outlet to which the power cord of the mainframe is connected.

(Please measure it without the mainframe plugged in.)

Step 2Switch the connection of the connector to the oil pump to the corresponding connector number.

Frequency	Voltage	Connector No.	Insertion Position
	Less than 210V	CN613	Move the connector to 200V
	210-220V	CN614	Move the connector to 210V
50Hz	220-230V	CN615	Move the connector to 220V
	230-240V	CN616	230V: Currently being shipped at this position
	240V or greater CN617		Move the connector to 240V



Technical Bulletin

PAGE: 1/2

Model: Aegis-P1 Da			Dat	ate: 17-Oct-08		No.: RG178016
Subject: PM Clogged Tube			Prepared by: N. lida			
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	n required
		☐ Electrica	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

Regardless of the amount remaining, SC 332,333,334,335 or toner empty are displayed.

CAUSE

Due to solidification of the toner, the toner supply tube (flexible tube) can become clogged.

SOLUTION

The interior of the toner supply tube (flexible tube) must be vacuum cleaned every 400K PM.

Do not keep the toner bottle in the standing position.

Operation procedure

※ It is necessary to use a vacuum cleaner

1. Remove the toner bottles (At least half way)



2. Remove the rear unit



3. Remove the tube attached to the sub-hopper

PAGE: 2/2

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178016



4. Clean the tube with a vacuum cleaner





- 5. Repeat this process with all four colors
- 6. Connect the rear unit
- 7. Attach the toner bottle

1		

PAGE: 1/2

Model: Aegis-P1			Dat	Date: 17-Oct-08		No.: RG178017
Subject: Service Manual Modification				Prepared by: N. lida		
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electric	al		⊠ Servic	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Changes to the service manual.
Please see alterations and additions below.

Item	Туре	0 bject/ title	Content	M anualpage
	Yield Change	OPC Drum K	400K→1200K	P191
	Yield Change	0 zone Filters	400K→1200K	P 195
PM Parts Table	Yield Change	A3/DLT LCT Rollers	Pick Up Roller 1000K Feed→300K Feed Paper Feed Roller 1000K Feed→300K Feed Separation Roller 1000K Feed→300K Feed	P 196
	Name Change	0 ilTank Felt	0 ilTank Felt→0 ilTank Filter	P 193

Item	Туре	0 bject/title	Content	M anualpage
	M odification	0 ilSupply	oilcollection tube [E] <mark>→oilcollection tube [F]</mark> oilnear-end sensor [F]→ <mark>oilnear-end sensor [E]</mark>	P1174
	M odification	LaserUnit	Delete SP2-101-002 from hputProcedure forLaserUnitCK	P233
	M odification	LaserUnit	Delete SP2-101-002 from hput Procedure for Laser Unit YM	P234
0 ther Item s	M odification		FC:Less than 10.0 sec → 13.5sec BW:Less than 10.0 sec → 13.5sec	P1200
acai 5	M odification	DOS Unit Type F (B735)	DOS Unit Type F (\$735) → DOS Unit Type H (\$\infty\$377)	P 181
	A ddition	Checking the Output Quality	Note As for paper, "Use special paper 6"	P 58
	Addition	PM Counter	A lthough the total counter is set for single click, when using A $3/DLT$, The PM counter clicks twice.	P185
	Addition	Skew error code	W hen a skew occurs, J098 Paper M isfeed is displayed	P1168



PAGE: 2/2

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178017

Item	Type	0 b.ject/ title	Content	M anualpage
	. 100	o ogolog umas	Check if the developer in the development unit is stuck. Check the development motor operation with 0 utput Check &P5-804-162 to	4. Troubleshooting
	A dd i tion	SC 327	-165) after the development unit has been pulled out from the machine. 3. Confirm that development motor is receiving 24V (addition) 4. Check the hamess connection of the development motor. 5. Remove the obstruction around the development motor shaft. 6. Replace the development motor.	
		SC 460	(Troubleshooting Procedures) 3. Replace the DB RCB.	4. Troubleshooting Service Call Tables - 4 Page 497
		SC 543	Possble Cause) Defective DB DB2 (Troub Bshooting Procedures) 3. Replace the DB2.	4. Troubleshooting Service Call Tables - 5 Page 526
		SC 544	Possble Cause) Defective DB DB2 (Troubleshooting Procedures) 3. Replace the DB DB2.	4. Troubleshooting Service Call Tables - 5 Page 526-527
	Revision	SC 553	Possble Cause) Defective DB DB2 (Troubleshooting Procedures) 3. Replace the DB2.	4. Troubleshooting Service Call Tables - 5 Page 528-529
		SC 686	Possble Cause) DB PU defective (Troubleshooting Procedures) 2. Replace the DB PU.	4. Troubleshooting Service Call Tables - 6 Page 552
		SC563	Possble Cause) Defective PSU AC Drive Board Defective DB DB2 (Troubleshooting Procedures) 2. Replace the PSU AC Drive Board. 3. Replace the DB2.	4. Troubleshooting Service Call Tables - 5 Page 531
SC Related		SC547	Possble Cause) The electric breaker if turned off or faulty +6 VG NT is OFF f Bbase plate is faulty) Power relay is faulty ACD rive board is faulty) DB 2 Control board in faulty (Troub eshooting Procedures) Turn the electric breaker 0 N When that is not possble, or doesn't work, replace the breaker When the +6 VG NT (OB 2 CN 3 3 7-1) is OFF F BBase plate exchange ACD rive board exchange DB 2 Control board exchange	4. Troubleshooting Service Call Tables - 5 Page 527
	Addition	SC621	Possble Cause) Finisher VF bad cable connection PSU-G breakdown DB 2 breakdown BC U breakdown (Trouble shooting Procedures) Power OFF/ON Confirm Finisher VF cable connection or check for broken wires. Confirm Finisher Control base plate + 24V is ON. PSU-G is off: Replacement BCU Replacement	4. Troubleshooting Service Call Tables - 6 Page 539
	A UG EDII	SC622	Possble Cause) 4.CT I/F bad cable connection 4.CT +24V Malfimction of electric suppy hamess •DB2 Breakdown BCU Breakdown (Troubleshooting Procedures) •Power OFF/ON •Confirm LCT I/F cable connector and check for broken wires. •Confirm LCT +24V electric hamess connection and check broken wires. •DB2 Replacement BCU Replacement	4. Troubleshooting Service Call Tables - 6 Page 539
		SC 623	Possble Cause) 4.CT I/F bad cable connection 4.CT +24V Malfinction of electric suppy hamess •DB2 Breakdown BCU Breakdown (Troubleshooting Procedures) •Power OFF/ON Confirm LCT I/F cable connector and check for broken wires. 4.CT +24V electric hamess connection and check broken wires. •DB2 Replacement BCU Replacement	4. Troubleshooting Service Call Tables - 6 Page 539

Technical Bulletin

PAGE: 1/7

Model: Aegis-P1			Date: 17-Oct-08		80	No.: RG178018
Subject: Cooling Fan Unit Type 5000 Installation			Prepared by: N. lida			
From: PPBG QA	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electric	al		⊠ Servic	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	☐ Other ()	☐ Tier 2	

Please follow the installation procedure as listed below.

The purpose of mounting the Cooling Fan Unit Type 5000 is to cool the paper ejected from the SR5000. When paper with poor heat dissipation is stacked in large volumes, sometimes the toner does not set due to residual heat.

Cooling Fan Unit Type 5000 (Machine Code: B831)

INSTALLATION PROCEDURE

For Machine Code: B830 Finisher

NOTE: THIS UNIT MUST BE INSTALLED BY A CUSTOMER SERVICE REPRESENTATIVE WHO HAS COMPLETED THE TRAINING COURSES ON THE BASE MACHINE AND COOLING FAN UNIT.

Component Check


Check the quantity and condition of the accessories against the following list.

No.	Description	Q'ty
1	Cooling Fan Unit	1
2	Upper Cover	1
3	Lower Cover	1
4	Screw: M3x6	7



PAGE: 2/7


Model: Aegis-P1 Date: 17-Oct-08 No.: RG178018



Installation Procedure

⚠CAUTION:

Turn off the machine and unplug it from the power source before you start the installation procedure.




1. Remove the rear cover [A] of the finisher (B830) (F x 2).




PAGE: 3/7

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178018



b831i902

- 2. Lower the shift tray [2] if the shift tray is at the top position.
- 3. Remove the jogger unit cover [3] (x 2).






4. Align the hooks [4] [5] of the fan unit frame with the cutouts [6] [7] at the front and rear of the finisher frame.


b831i904

5. Put the front hook [4] into the front cutout [6] first, and then the rear hook [5] into the rear cutout [7].

PAGE: 4/7




6. Put the harness [8] of the cooling fan unit through the cutout [9] in the finisher frame and clamp the harness with the clamp [10].



7. Slide the cooling fan unit [11] to the rear side, and then tighten it with two screws.

Note

Use the screws which were removed in step 3




8. Connect the harness of the cooling fan unit to CN135 [12] on the finisher main board, and then clamp it with the seven clamps as shown above.


Technical Bulletin

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178018

PAGE: 5/7



- 1. Disconnect the harness [13] if the harness of the punch unit has been connected to CN135 [12], and then connect the harness of the cooling fan unit to CN135 [12].
- 2. Attach the harness [13] of the punch unit to the relay connector [14] of the cooling fan harness.
 - 3. Clamp the harness of the cooling fan unit with the seven clamps.
- 9. Reattach the rear cover of the finisher (F x 2).



10. Align the front tab [15] on the lower cover with the groove [16] under the cooling fan unit, and align the rear tab [17] with the groove [18].



PAGE: 6/7

Model: Aegis-P1 Date: 17-Oct-08 No.: RG178018



b831i911

11. Install the lower cover [19] under the cooling fan unit (F x 2).



b831i917

(3)



b831i918

- 12. Install the upper cover [20] in the cooling fan unit (F x 5).
- 13. Turn on the mainframe.
- 14. Turn on the power switch [21] of the cooling fan unit.
- 15. Check the operation of the cooling fan unit.

Technical Bulletin

) PAGE: 1/2

Reissued: 19-Nov-08

Model: Aegis-P1	Date: 27-Oct-08	No.:RG178019a
-----------------	-----------------	---------------

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: SC622 LCT communication Error			Prepared by: N. lida		
From: PPBG QA	Service Planning Dept.				
Classification:	☐ Troubleshooting	☐ Part informa	tion		
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/receive		☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

SC622 LCT communication Error may occur on machines that are equipped with *LCIT RT5020*

CAUSE

Because of incorrect wiring, the screw and harness of the tray interfere, and when the harness short-circuits, SC622 occurs.

SOLUTION

Please check the serial number at the time of installation or a visit, and when you have an applicable machine, attach the harness clamp (PN 11050008) according to the procedure below.

Object serial number M5880700001-M588070048

M5880800001-M588080039 M5880900001-M588090035

Shipments from RPL are already reworked in the factory.




PAGE: 2/2

Reissued: 19-Nov-08

Model: Aegis-P1 Date: 27-Oct-08 No.:RG178019a

Harness clamp attachment procedure.


1. Remove each paper tray



NOTE: Two persons are required for removing the trays.

2. Attach the harness clamp.

If the harness (PN D3555315B) was already damaged, replace it with a new one before performing this work.



3. Reinstall the paper trays.

NOTE: Two persons are required for reinstalling the trays.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 Date			e: 6-Nov-0)8	No.: RG178020	
Subject: Option firmware update			Prepared by: N.iida			
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part inf	orma	tion		n required
	☐ Mechanical ☐ Electrical		al	☐ Service manual		e manual revision
	☐ Paper path	☐ Transmit/rec		eceive Retrofit info		fit information
ļ	☐ Product Safety	Other ()	☐ Tier 2	

When installing, please make sure to use the newest version as listed below. Please download firmware from the "Firmware Download Center."

It is necessary to replace the ROM of the upgraded Z-folding Unit ZF4000. Please acquire and replace the ROM. The ROM part number is B6605551.

It is not necessary to perform an update on the Aegis-P1 and options shipped from **RPL** when kitting as they already have the latest version installed.

Firmware Version for October 2008

	Version	Serial number or later
Finisher SR5000	Ver.1.42 (B8305102K)	B830- 17 : L5880900097 ~
Booklet Finisher BK5000	Ver.2.17(B8365550A)	 B836-17
Cover Interposer Tray Cl5010	Ver.02.064(B8355510C)	B835- 57 : L6281000004 ~
Z-foldina Unit ZF4000	,	NA]B660-57 :K3081000089 ~ FU]B660-67 :K3080900091 ~



PAGE: 1/2

Reissued: 29-Nov-11

Model: AG-P1 Date: 02-Feb-09 No.: RG17802	1d
--	----

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: System/Copy FRA			Prepared by: H.Kawamura		
From: 1st PP Tech Service Sect., PP Tech Service Dept.					
Classification:	Troubleshooting	☐ Part informat	tion	Action required	
	☐ Mechanical	Electrical		Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the firmware release information for the System/Copy.

Note

This firmware is used in French speaking countries only. Please install this firmware when machine installing in French.

Version	Program No.	Effective Date
2.08FRA	G1786088C	December 2011 production
2.07FRA	G1786088B	December 2010 production
2.03FRA	G1786088A	May 2009 production
1.01 FRA	G1786088	1st Mass production.

Version	Modified Points or Symptom Corrected				
2.08FRA	Modified Point				
	Counting method for blank page for Printer has been changed				
2.07FRA	Modified Point				
	Following issues have been fixed				
	- SC 86x appears after turning on a machine.				
	- Punch unit could not detect.				
	- When paper end appears and recovered from it, paper shifted in middle of				
	job, or paper did not shifted at end of job.				
	- Modified PM counter for "Filter: Oil Tank"				
	- New SP has been added				
	SP-7941-128: Drive Distance: Near End Standard Value: Filter: Oil tank				
	SP7-953-128: Page Counter: Near End Standard Value: Filter: Oil tank				



PAGE: 2/2

Reissued: 29-Nov-11

Model: AG-P1		Date: 02-Feb-09	No.: RG178021d				
Version	Mod	lified Points or S	ymptom Corrected				
2.03FRA	This is the French-language version of System version2.03 (G1786091E).						
	*Please make sure that ALI	varsions listed b	olow are undated conc	urrontly			
	Program Name	Program No.	Version	Jirenily.			
	System	G1786088A	2.03FRA				
	Network Support (NCS)	G1786092C	7.03				
	Engine	G1785252E	2.000:12				
	LCDC	NA:G1785971E					
		EU:G1785972					
	Language	G1785979	1.01				
	Websystem	G1786093C	1.01				
	Fiery Server	-	3.0				
	* Update to the following ve			d below.			
	Program Name	Program No.		Version			
	SR5000 Finisher	B8305102M	1.60				
	Cover Interposer Tray	B8355510E	02.070				
	Ring Binder RB5000	Main:D3925510 Sub:D3925520					
	High Capacity Stacker SK5000	1st:D3645620_ 2nd:D3645620_					
	Booklet Finisher BK5000	B8365550B	2.17				
	Note						
	*Peripherals must be update						
	the mainframe. Do NOT						
	*For the Ring Binder RB500	00, Main and Sub	shall be updated toget	her.			
1.01 FRA	1st Mass production.						

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 EFI Dat			te: 21-Nov-08		No.: RG178022	
Subject: Firmware Release Note: System EFI			Prepared by: A.Tajima			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☐ Other (al		Service	required ce manual revision fit information

This RTB is the release note for Patch File **1-ZX2LD.ps** for ProC900 system version 1.01.

Patch File	Issue(s)		
1-ZX2LD	- "Aegis" is contained ICC profile name		
	- Hotfolder cannot be installed		

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s): None

Patch Update Procedure

- 1. Extract R0205012.exe until you get the 1-ZX2LD file.
- 2. Download/Import the patch file "1-ZX2LD.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-ZX2LD".

Notes: This patch does not change the Fiery version.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 EFI D			Dat	ate: 21-Nov-08		No.: RG178023
Subject: Firmware Release Note: System EFI			Prepared by: A.Tajima			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	Troubleshooting	☐ Part informa		tion		n required
		☐ Electrical		☐ Service n		ce manual revision
	☐ Paper path	path 🔲 Transmit/red		ceive Retrofit information		fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for Patch File **1-103CJ7.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-103CJ7.ps	- PS file created by the 3rd vendor software cannot be composed.
	 When printing the specific PDF with some copies set, fiery stops and the GW controller reboots.
	- Four one a part of the image is missing- Support "Minimum Thick" and "Thick 1" for Karun.
	- Error popup message for Window max is displayed. (SC994)

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s): 1-ZPVPD

Patch Update Procedure

- 1. Extract R0205013.exe until you get the 1-103CJ7 file.
- 2. Download/Import the patch file "1-103CJ7.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-103CJ7".

Notes: This patch does not change the Fiery version.

Technical Bulletin

Model: Aegis-P1			Dat	te: 27-Nov-	-08	No.: RG178024
Subject: Notes a	t the time of mainframe moven	nent		Prepared	d by: M.K	íudoh
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
ļ	☐ Mechanical	☐ Electrication	al		Service Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

The frame of the caster under the rear controller box is deformed.





PAGE: 1/2

CAUSE

When moving the machine along slopes from a pallet at machine installation, the frame of the caster [A] is deformed due to too much weight on the caster [A] of the rear controller box.

SOLUTION

A caution sheet, which shows how to correctly move the machine from the pallet, is attached to the front of the machine.


Furthermore, the frame strength of the caster under the rear controller box is improved from November mass production.


For the location of the caution sheet, refer to the pictures on the next page.



PAGE: 2/2

Model: Aegis-P1 Date: 27-Nov-08 No.: RG178024





Technical Bulletin

PAGE: 1/2

Model: Aegis-P1			Dat	:e: 27-Nov	-08	No.: RG178025	
Subject: De-curle	er problem			Prepared	d by: M. I	Kudoh	
From: PPBG QA/	Service Planning Dept.						
Classification:	Troubleshooting	☐ Part info	orma	tion		required	
		☐ Electric	al		Service	rice manual revision	
	☐ Paper path	☐ Transmit/rec		☐ Transmit/receive ☐ ☐		fit information	
	☐ Product Safety	☐ Other ()	☐ Tier 2		

SYMPTOM

The de-curler unit in some machines does not work properly.

CAUSE

The de-curler unit in some machines has not been properly adjusted.

SOLUTION

Input correct settings for the de-curler unit adjustment with SP1906-002 and 1906-003 (De-curler Setting > Default Position: Lower Path and Default Position: Upper Path) when servicing or installing the machine that is listed in the following tables.

For EU Models

Serial No.	Unit Serial No.	Current	Settings	Correct	Settings
		Lower Path	Upper Path	Lower Path	Upper Path
		(-002)	(-003)	(-002)	(-003)
S3281000117	K00HJ8100001	0.7	-2	0.6	-1.8
S3281000142	K00HJ8100039	1	-1.9	0.9	-1.7

For NA Models

FOR NA Models								
Serial No.	Unit Serial No.	Current	Current Settings		Settings			
		Lower Path	Upper Path	Lower Path	Upper Path			
		(-002)	(-003)	(-002)	(-003)			
S3281000001	K00HJ8100024	0.7	-1.8	0.6	-1.6			
S3281000002	K00HJ8100025	0.8	-1.8	0.7	-1.6			
S3281000003	K00HJ8100022	0.6	-2	0.5	-1.8			
S3281000004	K00HJ8090036	0.9	-1.9	0.8	-1.7			
S3281000005	K00HJ8090046	0.6	-1.8	0.5	-1.6			
S3281000008	K00HJ8090045	0.3	-1.7	0.2	-1.5			
S3281000009	K00HJ8100080	0.4	-1.5	0.3	-1.3			
S3281000010	K00HJ8090037	0.6	-1.6	0.5	-1.4			
S3281000011	K00HJ8090029	0.7	-1.8	0.6	-1.6			
S3281000013	K00HJ8100078	0.6	-1.5	0.5	-1.3			
S3281000016	K00HJ8100076	0.6	-1.8	0.5	-1.6			
S3281000017	K00HJ8100074	0.8	-1.9	0.7	-1.7			
S3281000018	K00HJ8100073	0.6	-1.8	0.5	-1.6			
S3281000019	K00HJ8100071	0.7	-1.8	0.6	-1.6			
S3281000020	K00HJ8100070	0.7	-1.8	0.6	-1.6			

Technical Bulletin

PAGE: 2/2

Model: Aegis-P1 Date: 27-Nov				ov-08	No.:	RG178025	
Serial No.	Unit Serial No.	Current	Set	tings	Co	Settings	
		Lower Path	U	pper Path	Lower Path		Upper Path
		(-002)		(-003)	(-002)	(-003)
S3281000023	K00HJ8100062	8.0		-1.8	0.7		-1.6
S3281000024	K00HJ8100082	0.6		-1.6	0.5		-1.4
S3281000026	K00HJ8100084	1		-1.9	0.9		-1.7
S3281000030	K00HJ8100088	0.9		-1.9	0.8		-1.7
S3281000031	K00HJ8100090	0.6		-1.7	0.5		-1.5
S3281000050	K00HJ8100113	1		-1.9	0.9		-1.7
S3281000053	K00HJ8100107	8.0		-1.8	0.7		-1.6
S3281000061	K00HJ8100126	-0.1		-1.7	-0.2		-1.5
S3281000062	K00HJ8100122	8.0		-1.9	0.7		-1.7
S3281000069	K00HJ8100121	0.2		-1.5	0.1		-1.3
S3281000070	K00HJ8100132	0.9		-1.9	8.0		-1.7
S3281000073	K00HJ8100138	0.6		-1.7	0.5		-1.5
S3281000087	K00HJ8100066	0.6		-1.7	0.5		-1.5
S3281000094	K00HJ8100052	0.6		-1.9	0.5		-1.7
S3281000100	K00HJ8100058	0.7		-1.8	0.6		-1.6
S3281000103	K00HJ8100064	0.7		-1.8	0.6		-1.6


Technical Bulletin

PAGE: 1/6

Model: Aegis-P1			Dat	e: 27-Nov	-08	No.: RG178026	
Subject: Notes o	f change of the oil Supply Unit			Prepare	d by: M.K	ludoh	
From: PPBG QA	Service Planning Dept.						
Classification:		☐ Part info	orma	tion	Action	required	
		☐ Electric	al		Service	e manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()	⊠ Tier 2		


SYMPTOM

When the proper tool for the spring removal is not used when removing the oil supply unit, an oil mark problem as shown below occurs.



CAUSE

If the spring of the oil supply unit is stretched by long-nose pliers when it is removed from the oil supply unit, the spring may be deformed. As a result, the pressure of the oil supply roller may become uneven and this causes an oil mark problem. Refer to the picture below.




PAGE: 2/6


Model: Aegis-P1 Date: 27-Nov-08 No.: RG178026

SOLUTION

When removing the spring from the oil supply unit, use this tool shown below.




Replacement Procedure for the Oil Supply Unit



g178r714

1. Remove the inner cover [A] for the fusing unit (${\mathscr{F}}$ x 3).




q178r501

2. Remove the fusing rear cover [B] (x 4).




PAGE: 3/6

Model: Aegis-P1 Date: 27-Nov-08 No.: RG178026




3. Open the jam removal cover [A].



g178r503a

4. Remove the screw [B] and disconnect two [C] connectors on the fusing unit front side (♠ x 4).




g178r504

5. Remove the screw [D] on the fusing unit rear side.


Model: Aegis-P1

Date: 27-Nov-08 No.: RG178026

PAGE: 4/6



6. Open the fusing upper frame [E] and then remove it.



7. Remove the two springs [F] (front: black spring, rear: silver spring) with the correct tool (spring hook).

\triangle CAUTION:

 Use the correct tool (spring hook) to remove the two springs [F] shown above. Otherwise, the two springs may be deformed and this can cause an oil mark problem on the outputs.

U Note

- When reinstalling the two springs [F], install them in the correct positions (black spring at front, and silver spring at rear).
- 8. Remove the spring stay [G] (x 2).




Model: Aegis-P1


Technical Bulletin


Date: 27-Nov-08 No.: RG178026

PAGE: 5/6




9. Remove the oil supply unit gear bracket [H] (F x 2)





- 10. Remove the screw [I] at the front side.
- 11. Fusing unit right cover [J] (F x 2)



g178r967


12. Oil supply unit [K]



PAGE: 6/6


Model: Aegis-P1 Date: 27-Nov-08 No.: RG178026

When installing a new oil supply unit



g178i546a

- 1. Open the cap [A] of the oil supply bottle.
- 2. Pour the fusing oil into the oil supply bottle [B] until the oil surface reaches the half-way point [C] of that bottle.



- 3. Apply the fusing oil along the oil supply roller [D], and then rotate the oil supply roller by using the gears [E].
- 4. Pour the rest of the fusing oil in the oil supply bottle into the oil pan [F] after installing the oil supply unit in the fusing unit.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1			Dat	e: 27-Nov-	-08	No.: RG178027
Subject: Extension	on of Print Ready time			Prepared	d by: M. I	Kudoh
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electric	al	⊠s		e manual revision
	☐ Paper path	☐ Transmit/rec		eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

SYMPTOM

The G178 printer or D016 copier does not get to the print ready condition within the first print or copy time.

CAUSE

The automatic fusing oil supplement for the G178 or D016 machine is executed if the machine is in the fusing oil near end condition when resetting the PM counter (except the fusing cleaning unit) in the fusing unit or after the machine has not been turned on for more than one week. The automatic fusing oil supplement takes 750 seconds.

SOLUTION


- 1. Check the machine condition before installing a new PM part for the fusing unit or turning on a machine which has not been turned on for more than one week.
- 2. Supply fusing oil to the fusing unit in the G178 or D016 machine if fusing oil near end has been displayed on the operation panel.

Technical Bulletin

PAGE: 1/2	PAG	E:	1/
-----------	-----	----	----

Model: Aegis-P1			Dat	e: 27-Nov	-08	No.: RG178028
Subject: The pro	tection for the rear controller be	ох		Prepare	d by: M. I	Kudoh
From: PPBG QA	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion		required
		☐ Electric	al		⊠ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

Protective cushions for the rear controller box are added in the accessories for the G178 printer.



Attach the protective cushions [A] which are included with the mainframe to both top corners of the rear controller box as shown above when installing the G178 printer.

PAGE: 1/18

Model: Aegis-P1			Dat	e: 27-Nov	-08	No.: RG178029
Subject: Informa	tion about ProC900 SP Mode			Prepared	d by: M.k	udoh
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electrica	al		⊠ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	⊠ Tier 2	

The Service Manual was corrected as follows:

• Add the following SP tables:

1710*	Image Pos:Sub (Image Position Adjustment: Sub Scan)
001	Front
	Adjusts the laser scanning timing in the sub scan direction.
	[-3 to 3 / 0 / 0.1 mm]

	Image Pos:Sub (Image Position Adjustment: Sub Scan)
001	Back Main U Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from tray 1 (mainframe; upper tray).
	[-3 to 3 / 0 / 0.1 mm]
002	Back Main L Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from tray 2 (mainframe; lower tray).
	[-3 to 3 / 0 / 0.1 mm]
007	Back By-Pass Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the by-pass tray (B833 option).
	[-3 to 3 / 0 / 0.1 mm]
800	Back A3LCT1 U Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the upper tray of the LCT MF
	(mainframe; tray 3).
	[-3 to 3 / 0 / 0.1 mm]
009	Back A3LCT1 L Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the lower tray of the LCT MF
	(mainframe; tray 4).
	[-3 to 3 / 0 / 0.1 mm]
010	Sub Back A3LCT2 U Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the upper tray of the A3 LCT (D355
	option).
	[-3 to 3 / 0 / 0.1 mm]
011	Sub Back A3LCT2 L Tray

Technical Bulletin

PAGE: 2/18

Model: Aegis-P1

Adjusts the laser scanning timing in the sub scan direction for the back side of paper fed from the lower tray of the A3 LCT (D355 option).

[-3 to 3 / 0 / 0.1 mm]

1720*	Image Pos:Main (Image Position Adjustment: Main Scan)
001	Front
	Adjusts the laser scanning timing in the main scan direction. [-3 to 3 / 0 / 0.1 mm]

	Image Pos:Main (Image Position Adjustment: Main Scan)
001	Back Main U Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from tray 1 (mainframe; upper tray).
	[-3 to 3 / 0 / 0.1 mm]
002	Back Main L Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from tray 2 (mainframe; lower tray).
	[-3 to 3 / 0 / 0.1 mm]
007	Back By-Pass Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the by-pass tray (B833 option).
	[-3 to 3 / 0 / 0.1 mm]
800	Back A3LCT1 U Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the upper tray of the LCT MF
	(mainframe; tray 3).
	[-3 to 3 / 0 / 0.1 mm]
009	Back A3LCT1 L Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the lower tray of the LCT MF
	(mainframe; tray 4).
	[-3 to 3 / 0 / 0.1 mm]
010	Sub Back A3LCT2 U Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the upper tray of the A3 LCT (D355
	option).
	[-3 to 3 / 0 / 0.1 mm]
011	Sub Back A3LCT2 L Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the lower tray of the A3 LCT (D355
	option).
	[-3 to 3 / 0 / 0.1 mm]

1730*	Skew Detect Disable (Skew Detection Disable)
001	Main U Tray

PAGE: 3/18

Model: Aeg	is-P1	Date	: 27-Nov-08	N	o.: RG178029
	Enables or disables the skew detect (mainframe; upper tray). [0 or 1 / 0 / -] 0: Skew detection ON (enabled)	ion for	r paper fed	from	tray 1
002	1: Skew detection OFF (disabled) Main L Tray				
002	Enables or disables the skew detect (mainframe; lower tray). [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	ion for	r paper fed	from	tray 2
007	By-Pass Tray				
	Enables or disables the skew detection pass tray (B833 option). [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	n for pa	aper fed fron	n the t	oy-
008	A3 LCT1 U Tray				
	Enables or disables the skew detectio tray of the LCT MF (mainframe; tray 3) [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	-	paper fed from	m the	upper
009	A3 LCT1 L Tray				
	Enables or disables the skew detection tray of the LCT MF (mainframe; tray 4) [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	•	paper fed fro	m the	lower
010	A3 LCT2 U Tray				
	Enables or disables the skew detection tray of the A3 LCT (D355 option). [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	n for p	paper fed from	m the	upper
011	A3 LCT2 L Tray				
	Enables or disables the skew detection tray of the A3 LCT (D355 option). [0 or 1 / 0 / -] 0: Skew detection ON (enabled) 1: Skew detection OFF (disabled)	n for p	paper fed fro	m the	lower

1761*	Side-to-Side Reg Disable (Side-to-Side Registration Disable)
001	Main U Tray

No.: RG178029 Date: 27-Nov-08

PAGE: 4/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1
	Enables or disables the side-to-side	registration adjustmen	t for
	paper fed from tray 1 (mainframe; up	•	
	[0 or 1 / 0 / -]		
	0: Side-to-side registration adjustmer	` ,	
	1: Side-to-side registration adjustmer	nt OFF (disabled)	
002	Main L Tray		
	Enables or disables the side-to-side		t for
	paper fed from tray 2 (mainframe; lov	wer tray).	
	[0 or 1 / 0 / -]	-4 ON (-)	
	0: Side-to-side registration adjustmen		
007	1: Side-to-side registration adjustmen	it OFF (disabled)	
007	By-Pass Tray Enables or disables the side-to-side	registration adjustmen	t for
	paper fed from the by-pass tray (B83	•	101
	[0 or 1 / 0 / -]	o option).	
	0: Side-to-side registration adjustmer	nt ON (enabled)	
	1: Side-to-side registration adjustmen	•	
008	A3 LCT1 U Tray		
	Enables or disables the side-to-side	registration adjustmen	t for
	paper fed from the upper tray of the I	LCT MF (mainframe; tr	ray 3).
	[0 or 1 / 0 / -]		
	0: Side-to-side registration adjustmen	,	
	1: Side-to-side registration adjustmen	nt OFF (disabled)	
009	A3 LCT1 L Tray		1.5
	Enables or disables the side-to-side	•	
	paper fed from the lower tray of the L	CT MF (maintrame; tr	ay 4).
	[0 or 1 / 0 / -] 0: Side-to-side registration adjustmer	nt ON (anahlad)	
	Side-to-side registration adjustment Side-to-side registration adjustment		
010	A3 LCT2 U Tray	it Of F (disabled)	
0.10	Enables or disables the side-to-side	registration adjustmen	t for
	paper fed from the upper tray of the	•	
	[0 or 1 / 0 / -]	, ,	
	0: Side-to-side registration adjustmer	nt ON (enabled)	
	1: Side-to-side registration adjustmer	nt OFF (disabled)	
011	A3 LCT2 L Tray		
	Enables or disables the skew detecti	on for paper fed from t	the lower
	tray of the A3 LCT (D355 option).		
	[0 or 1 / 0 / -]	-1 ONL /1 ! ! !	
	0: Side-to-side registration adjustmen	,	
	1: Side-to-side registration adjustmen	it OFF (disabled)	

19	905*	Nip Width Setting
		These SPs adjust the pressure roller position by controlling the
		pressure roller lift motor. If you set a longer time than before, the nip
		width between the fusing belt and pressure roller will be wider.
	011	Uncoated:Thin:L-Temp

PAGE: 5/18

Model: Aeg	jis-P1	Date: 27-Nov-08	No.: RG178029
	Adjusts the pressure roller position for	uncoated thin paper in	n low
	temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
012	Uncoated:Plain:L-Temp		
	Adjusts the pressure roller position for	uncoated plain paper	in low
	temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
013	Uncoated:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	uncoated middle thick	paper
	in low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
014	Uncoated:Thk1:L-Temp		
	Adjusts the pressure roller position for	th uncoated thick 1 pa	aper in
	low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
015	Uncoated:Thk2:L-Temp		
	Adjusts the pressure roller position for	uncoated thick 2 pape	er in low
	temperature mode.		
2.12	[40 to 2000 / 40 / 10 msec/step]		
016	Uncoated:Thk3:L-Temp		
	Adjusts the pressure roller position for	uncoated thick 3 pape	er in low
	temperature mode.		
0.47	[40 to 2000 / 40 / 10 msec/step]		
017	Coated1:Thin:L-Temp		and law.
	Adjusts the pressure roller position for	coated 1 and thin pap	er in low
	temperature mode.		
010	[40 to 2000 / 510 / 10 msec/step]		
010	Coated1:Plain:L-Temp Adjusts the pressure roller position for	coated 1 and plain no	nor in
	low temperature mode.	coated i and plant pa	per iii
	[40 to 2000 / 510 / 10 msec/step]		
019	Coated1:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	coated 1 and middle t	hick
	paper in low temperature mode.	oodiod i dila illiadio i	, more
	[40 to 2000 / 330 / 10 msec/step]		
020	Coated1:Thk1:L-Temp		
	Adjusts the pressure roller position for	coated 1 and thick 1 r	paper in
	low temperature mode.	'	'
	[40 to 2000 / 330 / 10 msec/step]		
021	Coated1:Thk2:L-Temp		
	Adjusts the pressure roller position for	coated 1 and thick 2	paper
	in low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
022	Coated1:Thk3:L-Temp		
	Adjusts the pressure roller position for	coated 1 and thick 3	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		

Technical Bulletin Date: 27-Nov-08

PAGE: 6/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG178029
023	Coated2:Thin:L-Temp		
	Adjusts the pressure roller position for	coated 2 and thin pa	per in
	low temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
024			
	Adjusts the pressure roller position for	coated 2 and plain page	aper in
	low temperature mode.		
025	[40 to 2000 / 510 / 10 msec/step]		
025	Coated2:Mid Thk:L-Temp Adjusts the pressure roller position for	r coated 2 and middle	thick
	paper in low temperature mode.	coaled 2 and middle	UIICK
	[40 to 2000 / 330 / 10 msec/step]		
026			
020	Adjusts the pressure roller position for	coated 2 and thick 1	paper
	in low temperature mode.		P P
	[40 to 2000 / 330 / 10 msec/step]		
027			
	Adjusts the pressure roller position for	coated 2 and thick 2	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
028			
	Adjusts the pressure roller position for	coated 2 and thick 3	paper
	in low temperature mode.		
029	[40 to 2000 / 40 / 10 msec/step] Coated3:Thin:L-Temp		
029	Adjusts the pressure roller position for	r coated 3 and thin na	ner in
	low temperature mode.	coated o and thin pa	per iii
	[40 to 2000 / 510 / 10 msec/step]		
030	Coated3:Plain:L-Temp		
	Adjusts the pressure roller position for	coated 3 and plain page	aper in
	low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
031			
	Adjusts the pressure roller position for	coated 3 and middle	thick
	paper in low temperature mode.		
032	[40 to 2000 / 330 / 10 msec/step]		
032	Coated3:Thk1:L-Temp Adjusts the pressure roller position for	coated 2 and thick 1	nanor
	in low temperature mode.	Coaled 5 and trick i	paper
	[40 to 2000 / 40 / 10 msec/step]		
033			
	Adjusts the pressure roller position for	coated 3 and thick 2	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
034	Coated3:Thk3:L-Temp		

PAGE: 7/18 No.: RG178029

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1
	Adjusts the pressure roller position for	or coated 3 and thick 3	paper
	in low temperature.		
	[40 to 2000 / 40 / 10 msec/step]		
035	Special1:Thin:L-Temp		
	Adjusts the pressure roller position for	or special 1 and thin pa	per in
	low temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
036	Special1:Plain:L-Temp		
	Adjusts the pressure roller position for	or special 1 and plain p	aper in
	low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
037			
	Adjusts the pressure roller position for	or special 1 and middle	thick
	paper in low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
038	Special1:Thk1:L-Temp		
	Adjusts the pressure roller position for	or special 1 and thick 1	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
039	Special1:Thk2:L-Temp		
	Adjusts the pressure roller position for	or special 1 and thick 2	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
040	Special1:Thk3:L-Temp		
	Adjusts the pressure roller position for	or special 1 and thick 3	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
041	Special2:Thin:L-Temp		
	Adjusts the pressure roller position for	or special 2 and thin pa	iper in
	low temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
042			
	Adjusts the pressure roller position for	or special 2 and plain p	aper in
	low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
043	Special2:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	or special 2 and middle	thick
	paper in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
044	Special2:Thk1:L-Temp		
	Adjusts the pressure roller position for	or special 2 and thick 1	paper
	in low temperature mode.		
	[40 to 2000 / 40 / 10 msec/step]		
045	Special2:Thk2:L-Temp		
	Adjusts the pressure roller position for	or special 2 and thick 2	paper
	in low temperature mode.	-	-
	[40 to 2000 / 40 / 10 msec/step]		

PAGE: 8/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG178029
046	Special2:Thk3:L-Temp		
	Adjusts the pressure roller position for	special 2 and thick 3	paper
	in low temperature mode.	·	
	[40 to 2000 / 40 / 10 msec/step]		
047	Special3:Thin:L-Temp		
	Adjusts the pressure roller position for	special 3 and thin pa	per in
	low temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
048	Special3:Plain:L-Temp		
	Adjusts the pressure roller position for	r special 3 and plain p	aper in
	low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		
049	Special3:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	r special 3 and middle	thick
	paper in low temperature mode.		
0.50	[40 to 2000 / 40 / 10 msec/step]		
050	Special3:Thk1:L-Temp		
	Adjusts the pressure roller position for	r special 3 and thick 1	paper
	in low temperature mode.		
054	[40 to 2000 / 40 / 10 msec/step]		
051	Special3:Thk2:L-Temp	canagial 2 and thick 2	nanar
	Adjusts the pressure roller position for	special 3 and thick 2	paper
	in low temperature mode. [40 to 2000 / 40 / 10 msec/step]		
052	Special3:Thk3:L-Temp		
002	Adjusts the pressure roller position for	special 3 and thick 3	naner
	in low temperature mode.	opoolar o arra triion o	ραροι
	[40 to 2000 / 40 / 10 msec/step]		
053	Special4:Thin:L-Temp		
	Adjusts the pressure roller position for	special 4 and thin pa	per in
	low temperature mode.	·	
	[40 to 2000 / 510 / 10 msec/step]		
054	Special4:Plain:L-Temp		
	Adjusts the pressure roller position for	r special 4 and plain p	aper in
	low temperature mode.		
	[40 to 2000 / 510 / 10 msec/step]		
055	Special4:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	r special 4 and middle	thick
	paper in low temperature mode.		
050	[40 to 2000 / 510 / 10 msec/step]		
056	Special4:Thk1:L-Temp	a a a a lat A a cal datat A	
	Adjusts the pressure roller position for	special 4 and thick 1	paper
	in low temperature mode.		
0.57	[40 to 2000 / 330 / 10 msec/step]		
057	Special4:Thk2:L-Temp		

PAGE: 9/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG178029
	Adjusts the pressure roller position for in low temperature mode. [40 to 2000 / 40 / 10 msec/step]	special 4 and thick 2	paper
058			
	Adjusts the pressure roller position for	special 4 and thick 3	paper
	in low temperature mode.	•	
	[40 to 2000 / 40 / 10 msec/step]		
059	Special5:Thin:L-Temp		
	Adjusts the pressure roller position for	special 5 and thin pa	per in
	low temperature mode.		
060	[40 to 2000 / 510 / 10 msec/step]		<u> </u>
060	Special5:Plain:L-Temp Adjusts the pressure roller position for	ongoigl 5 and plain n	oper in
	low temperature mode.	special 5 and plain p	aper in
	[40 to 2000 / 510 / 10 msec/step]		
061	Special5:Mid Thk:L-Temp		
	Adjusts the pressure roller position for	special 5 and middle	thick
	paper in low temperature mode.	•	
	[40 to 2000 / 330 / 10 msec/step]		
062	Special5:Thk1:L-Temp		
	Adjusts the pressure roller position for	special 5 and thick 1	paper
	in low temperature mode.		
200	[40 to 2000 / 330 / 10 msec/step]		
063		onesial Canal Haisle O	
	Adjusts the pressure roller position for in low temperature mode.	special 5 and thick 2	paper
	[40 to 2000 / 40 / 10 msec/step]		
064	Special5:Thk3:L-Temp		
	Adjusts the pressure roller position for	special 5 and thick 3	paper
	in low temperature mode.		F - F -
	[40 to 2000 / 40 / 10 msec/step]		
065	Special6:Thin:L-Temp		
	Adjusts the pressure roller position for	special 6 and thin pa	per in
	low temperature mode.		
066	[40 to 2000 / 510 / 10 msec/step]		
066	Special6:Plain:L-Temp Adjusts the pressure roller position for	enecial 6 and plain n	aner in
	low temperature mode.	special o and plain p	aper iii
	[40 to 2000 / 510 / 10 msec/step]		
067			
	Adjusts the pressure roller position for	special 6 and middle	thick
	paper in low temperature mode.	'	
	[40 to 2000 / 330 / 10 msec/step]		
068	Special6:Thk1:L-Temp		
	Adjusts the pressure roller position for	special 6 and thick 1	paper
	in low temperature mode.		
	[40 to 2000 / 330 / 10 msec/step]		

Technical Bulletin

PAGE: 10/18

Model: Aegis-P1 Date: 27-Nov-08 No.: RG178029 069 Special6:Thk2:L-Temp Adjusts the pressure roller position for special 6 and thick 2 paper in low temperature mode. [40 to 2000 / **40** / 10 msec/step] 070 Special6:Thk3:L-Temp Adjusts the pressure roller position for special 6 and thick 3 paper in low temperature mode. [40 to 2000 / **40** / 10 msec/step] 071 | Envelope:Thin:L-Temp Adjusts the pressure roller position for envelope and thin paper in low temperature mode. [40 to 2000 / **510** / 10 msec/step] 072 | Envelope:Plain:L-Temp Adjusts the pressure roller position for envelope and plain paper in low temperature mode. [40 to 2000 / **510** / 10 msec/step] 073 | Envelope:Mid Thk:L-Temp Adjusts the pressure roller position for envelope and middle thick paper in low temperature mode. [40 to 2000 / **330** / 10 msec/step] 074 Envelope:Thk1:L-Temp Adjusts the pressure roller position for envelope and thick 1 paper in low temperature mode. [40 to 2000 / **330** / 10 msec/step] 075 | Envelope:Thk2:L-Temp Adjusts the pressure roller position for envelope and thick 2 paper in low temperature mode. [40 to 2000 / **330** / 10 msec/step] 076 | Envelope:Thk3:L-Temp Adjusts the pressure roller position for envelope and thick 3 paper in low temperature mode. [40 to 2000 / **40** / 10 msec/step] 077 Uncoated:Thin:Over L-Temp Adjusts the pressure roller position for uncoated thin paper at a higher temperature than low temperature mode. [40 to 2000 / **510** / 10 msec/step] 078 Uncoated:Plain:Over L-Temp Adjusts the pressure roller position for uncoated plain paper at a higher temperature than low temperature mode. [40 to 2000 / **510** / 10 msec/step] 079 Uncoated:Mid Thk:Over L-Temp Adjusts the pressure roller position for uncoated middle thick paper at a higher temperature than low temperature mode. [40 to 2000 / **330** / 10 msec/step]

080 Uncoated:Thk1:Over L-Temp

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 11/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1	
	Adjusts the pressure roller position for higher temperature than low temperat	-	per at a	
	, , ,	ure mode.		
001	[40 to 2000 / 330 / 10 msec/step]			
081	Uncoated:Thk2:Over L-Temp	tuneseted thick 2 no	nor ot o	
	Adjusts the pressure roller position for		pei ai a	
	higher temperature than low temperat [40 to 2000 / 40 / 10 msec/step]	ure mode.		
082	Uncoated:Thk3:Over L-Temp			
002	Adjusts the pressure roller position for	uncoated thick 3 na	ner at a	
	higher temperature than low temperat	•	pci ai a	
	[40 to 2000 / 40 / 10 msec/step]	are mode.		
083	Coated1:Thin:Over L-Temp			
000	Adjusts the pressure roller position for	coated 1 and thin na	aner at a	
	higher temperature than low temperat		apci ai a	
	[40 to 2000 / 510 / 10 msec/step]	are mode.		
084	Coated1:Plain:Over L-Temp			
	Adjusts the pressure roller position for	coated 1 and plain r	naner at	
	a higher temperature than low temper		sapor at	
	[40 to 2000 / 510 / 10 msec/step]			
085	Coated1:Mid Thk:Over L-Temp			
	Adjusts the pressure roller position for coated 1 and middle thic			
	paper at a higher temperature than lov			
	[40 to 2000 / 330 / 10 msec/step]	·		
086	Coated1:Thk1:Over L-Temp			
	Adjusts the pressure roller position for	coated 1 and thick 1	paper	
	at a higher temperature than low temp	erature mode.		
	[40 to 2000 / 330 / 10 msec/step]			
087				
	Adjusts the pressure roller position for		2 paper	
	at a higher temperature than low temp	erature mode.		
	[40 to 2000 / 330 / 10 msec/step]			
088	Coated1:Thk3:Over L-Temp			
	Adjusts the pressure roller position for		3 paper	
	at a higher temperature than low temp	erature mode.		
000	[40 to 2000 / 40 / 10 msec/step]			
089	Coated2:Thin:Over L-Temp			
	Adjusts the pressure roller position for		aper at a	
	higher temperature than low temperat	ure mode.		
000	[40 to 2000 / 510 / 10 msec/step]			
090	Coated2:Plain:Over L-Temp	contod 2 and plain r	nanar at	
	Adjusts the pressure roller position for		paper at	
	a higher temperature than low temper	ature mode.		
001	[40 to 2000 / 510 / 10 msec/step]			
091	Coated2:Mid Thk:Over L-Temp	coated 2 and middle	thick	
	Adjusts the pressure roller position for paper at a higher temperature than lov			
	[40 to 2000 / 330 / 10 msec/step]	w temperature mode	•	
	[+0 to 2000 / 330 / To Hisec/step]			

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 12/18

Model: Aeg	is-P1 Date: 27-Nov-08 No.: RG	
092	Coated2:Thk1:Over L-Temp	
	Adjusts the pressure roller position for coated 2 and thick 1 paper	
	at a higher temperature than low temperature mode.	
	[40 to 2000 / 330 / 10 msec/step]	
093	Coated2:Thk2:Over L-Temp	
	Adjusts the pressure roller position for coated 2 and thick 2 paper	
	at a higher temperature than low temperature mode.	
004	[40 to 2000 / 40 / 10 msec/step]	
094	Coated2:Thk3:Over L-Temp	
	Adjusts the pressure roller position for coated 2 and thick 3 paper	
	at a higher temperature than low temperature mode.	
095	[40 to 2000 / 40 / 10 msec/step] Coated3:Thin:Over L-Temp	
093	Adjusts the pressure roller position for coated 3 and thin paper at a	
	higher temperature than low temperature mode.	
	[40 to 2000 / 510 / 10 msec/step]	
096		
	Adjusts the pressure roller position for coated 3 and plain paper at	
	a higher temperature than low temperature mode.	
	[40 to 2000 / 330 / 10 msec/step]	
097	Coated3:Mid Thk:Over L-Temp	
	Adjusts the pressure roller position for coated 3 and middle thick	
	paper at a higher temperature than low temperature mode.	
	[40 to 2000 / 330 / 10 msec/step]	
098	Coated3:Thk1:Over L-Temp	
	Adjusts the pressure roller position for coated 3 and thick 1 paper	
	at a higher temperature than low temperature mode.	
000	[40 to 2000 / 40 / 10 msec/step]	
099	Coated3:Thk2:Over L-Temp	
	Adjusts the pressure roller position for coated 3 and thick 2 paper at a higher temperature than low temperature mode.	
	[40 to 2000 / 40 / 10 msec/step]	
100	Coated3:Thk3:Over L-Temp	
100	Adjusts the pressure roller position for coated 3 and thick 3 paper	
	at a higher temperature than low temperature mode.	
	[40 to 2000 / 40 / 10 msec/step]	
101	Special1:Thin:Over L-Temp	
	Adjusts the pressure roller position for special 1 and thin paper at a	
	higher temperature than low temperature mode.	
	[40 to 2000 / 510 / 10 msec/step]	
102	Special1:Plain:Over L-Temp	
	Adjusts the pressure roller position for special 1 and plain paper at	
	a higher temperature than low temperature mode.	
	[40 to 2000 / 330 / 10 msec/step]	
103	Special1:Mid Thk:Over L-Temp	

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 13/18

			1
Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1
	Adjusts the pressure roller position for	•	thick
	paper at a higher temperature than lo	w temperature mode.	
	[40 to 2000 / 330 / 10 msec/step]		
104	Special1:Thk1:Over L-Temp		
	Adjusts the pressure roller position for		paper
	at a higher temperature than low temp	perature mode.	
	[40 to 2000 / 40 / 10 msec/step]		
105	Special1:Thk2:Over L-Temp	nk2:Over L-Temp	
	Adjusts the pressure roller position for	r special 1 and thick 2	paper
	at a higher temperature than low temp	perature mode.	
	[40 to 2000 / 40 / 10 msec/step]		
106	Special1:Thk3:Over L-Temp		
	Adjusts the pressure roller position for	r special 1 and thick 3	paper
	at a higher temperature than low temp		
	[40 to 2000 / 40 / 10 msec/step]		
107	Special2:Thin:Over L-Temp		
	Adjusts the pressure roller position for	r special 2 and thin pa	per at a
	higher temperature than low temperat		•
	[40 to 2000 / 510 / 10 msec/step]		
108	Special2:Plain:Over L-Temp		
	Adjusts the pressure roller position for	r special 2 and plain p	aper at
	a higher temperature than low temper		•
	[40 to 2000 / 330 / 10 msec/step]		
109	Special2:Mid Thk:Over L-Temp		
	Adjusts the pressure roller position for		thick
	paper at a higher temperature than lo	w temperature mode.	
	[40 to 2000 / 40 / 10 msec/step]		
110	<u> </u>		
	Adjusts the pressure roller position for		paper
	at a higher temperature than low temp	perature mode.	
	[40 to 2000 / 40 / 10 msec/step]		
111	Special2:Thk2:Over L-Temp		
	Adjusts the pressure roller position for		paper
	at a higher temperature than low temp	perature mode.	
110	[40 to 2000 / 40 / 10 msec/step]		
112			
	Adjusts the pressure roller position for		paper
	at a higher temperature than low temp	perature mode.	
110	[40 to 2000 / 40 / 10 msec/step]		
113	Special3:Thin:Over L-Temp		
	Adjusts the pressure roller position for		per at a
	higher temperature than low temperat	ture mode.	
	[40 to 2000 / 510 / 10 msec/step]		
114	Special3:Plain:Over L-Temp		
	Adjusts the pressure roller position for special 3 and plain paper at		
	a higher temperature than low temper	ature mode.	
	[40 to 2000 / 330 / 10 msec/step]		

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 14/18

Model: Aeg	is-P1 Date: 27-Nov-08	No.: RG1
115	Special3:Mid Thk:Over L-Temp	
	Adjusts the pressure roller position for special 3 and middle	thick
	paper at a higher temperature than low temperature mode.	
	[40 to 2000 / 40 / 10 msec/step]	
116	Special3:Thk1:Over L-Temp	
	Adjusts the pressure roller position for special 3 and thick 1	paper
	at a higher temperature than low temperature mode.	
4.4=	[40 to 2000 / 40 / 10 msec/step]	
117		
	Adjusts the pressure roller position for special 3 and thick 2	paper
	at a higher temperature than low temperature mode.	
118	[40 to 2000 / 40 / 10 msec/step]	
110	Special3:Thk3:Over L-Temp Adjusts the pressure roller position for special 3 and thick 3	naner
	at a higher temperature than low temperature mode.	paper
	[40 to 2000 / 40 / 10 msec/step]	
119	Special4:Thin:Over L-Temp	
	Adjusts the pressure roller position for special 4 and thin pa	per at a
	higher temperature than low temperature mode.	, , , , , , , , , , , , , , , , , , ,
	[40 to 2000 / 510 / 10 msec/step]	
120	Special4:Plain:Over L-Temp	
	Adjusts the pressure roller position for special 4 and plain p	aper at
	a higher temperature than low temperature mode.	
	[40 to 2000 / 510 / 10 msec/step]	
121	Special4:Mid Thk:Over L-Temp	
	Adjusts the pressure roller position for special 4 and middle	thick
	paper at a higher temperature than low temperature mode.	
400	[40 to 2000 / 510 / 10 msec/step]	
122	Special4:Thk1:Over L-Temp	nanar
	Adjusts the pressure roller position for special 4 and thick 1	paper
	at a higher temperature than low temperature mode. [40 to 2000 / 330 / 10 msec/step]	
123	Special4:Thk2:Over L-Temp	
120	Adjusts the pressure roller position for special 4 and thick 2	naner
	at a higher temperature than low temperature mode.	paper
	[40 to 2000 / 40 / 10 msec/step]	
124	Special4:Thk3:Over L-Temp	
	Adjusts the pressure roller position for special 4 and thick 3	paper
	at a higher temperature than low temperature mode.	1 - 1 -
	[40 to 2000 / 40 / 10 msec/step]	
125	Special5:Thin:Over L-Temp	
	Adjusts the pressure roller position for special 5 and thin pa	per at a
	higher temperature than low temperature mode.	
	[40 to 2000 / 510 / 10 msec/step]	
126	Special5:Plain:Over L-Temp	

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 15/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1
	Adjusts the pressure roller position for a higher temperature than low temper [40 to 2000 / 510 / 10 msec/step]		aper at
127	Special5:Mid Thk:Over L-Temp Adjusts the pressure roller position for special 5 and middle thick paper at a higher temperature than low temperature mode. [40 to 2000 / 330 / 10 msec/step]		
128	Special5:Thk1:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 330 / 10 msec/step]		paper
129	Special5:Thk2:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 40 / 10 msec/step]	special 5 and thick 2 perature mode.	paper
130	Special5:Thk3:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 40 / 10 msec/step]		paper
131	Special6:Thin:Over L-Temp Adjusts the pressure roller position for higher temperature than low temperat [40 to 2000 / 510 / 10 msec/step]		iper at a
132			
133	Special6:Mid Thk:Over L-Temp Adjusts the pressure roller position for paper at a higher temperature than lov [40 to 2000 / 330 / 10 msec/step]		thick
134	Special6:Thk1:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 330 / 10 msec/step]		paper
135	Special6:Thk2:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 40 / 10 msec/step]		paper
136	Special6:Thk3:Over L-Temp Adjusts the pressure roller position for at a higher temperature than low temp [40 to 2000 / 40 / 10 msec/step]		paper
137	Envelope:Thin:Over L-Temp Adjusts the pressure roller position for higher temperature than low temperat [40 to 2000 / 510 / 10 msec/step]		aper at a

Technical **B**ulletin

Date: 27-Nov-08 No.: RG178029

PAGE: 16/18

Model: Aeg	is-P1	Date: 27-Nov-08	No.: RG1
138	Envelope:Plain:Over L-Temp Adjusts the pressure roller position fo a higher temperature than low temper [40 to 2000 / 510 / 10 msec/step]		paper at
139	Envelope:Mid Thk:Over L-Temp Adjusts the pressure roller position fo paper at a higher temperature than lo [40 to 2000 / 330 / 10 msec/step]	•	thick
140	Envelope:Thk1:Over L-Temp Adjusts the pressure roller position fo at a higher temperature than low temperature to 2000 / 330 / 10 msec/step]		paper
141	Envelope:Thk2:Over L-Temp Adjusts the pressure roller position fo at a higher temperature than low temperature to 2000 / 330 / 10 msec/step]	•	paper
142	Envelope:Thk3:Over L-Temp Adjusts the pressure roller position fo at a higher temperature than low temperature to 2000 / 40 / 10 msec/step]	•	paper

1910*	Dbl-Feed Detect:Disable (Double Feed Detection: Disable)
001	Main U Tray
	Enables or disables double feed detection for paper fed from tray 1
	(mainframe; upper tray).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
002	Main L Tray
	Enables or disables double feed detection for paper fed from tray 2
	(mainframe; lower tray).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
007	By-Pass Tray
	Enables or disables double feed detection for paper fed from the by-
	pass tray (B833 option).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
200	1: Double feed detection OFF (disabled)
800	A3 LCT1 U Tray
	Enables or disables double feed detection for paper fed from the
upper tray of the LCT MF (mainframe; tray 3).	
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
000	1: Double feed detection OFF (disabled)
009	A3 LCT1 L Tray

Technical Bulletin

178029

PAGE: 17/18

Model: Aegis-P1	Date: 27-Nov-08	No.: RG1
Enables or disables double feed detect lower tray of the LCT MF (mainframe; t [0 or 1 / 0 / -] 0: Double feed detection ON (enabled) 1: Double feed detection OFF (disabled)	ray 4).	n the
010 A3 LCT2 U Tray		
Enables or disables double feed detect upper tray of the A3 LCT (D355 option) [0 or 1 / 0 / -] 0: Double feed detection ON (enabled) 1: Double feed detection OFF (disabled)).	n the
011 A3 LCT2 L Tray		
Enables or disables double feed detect lower tray of the A3 LCT (D355 option) [0 or 1 / 0 / -] 0: Double feed detection ON (enabled) 1: Double feed detection OFF (disabled)		n the

Selects the coated paper setting or uncoated paper setting for each paper type. O01 Special 1 For special paper 1 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting O02 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting O03 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting O05 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting O06 Special 6	1024*	LCT Depar Coloct
paper type. 001 Special 1 For special paper 1 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 002 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting	1924*	LCT Paper Select
O01 Special 1 For special paper 1 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting O02 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting O03 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting O04 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting O05 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		
For special paper 1 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 002 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		
[0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 002 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting	001	•
0: Uncoated paper setting 1: Coated paper setting 002 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		· · · · · · · · · · · · · · · · · · ·
1: Coated paper setting 002 Special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 1: Coated paper setting 1: Coated paper setting		
For special 2 For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		, ,
For special paper 2 [0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		
[0 or 1 / 1 / -] 0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting	002	
0: Uncoated paper setting 1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		
1: Coated paper setting 003 Special 3 For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		
For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		, , ,
For special paper 3 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		
[0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting	003	Special 3
0: Uncoated paper setting 1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		For special paper 3
1: Coated paper setting 004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		[0 or 1 / 0 / -]
004 Special 4 For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		0: Uncoated paper setting
For special paper 4 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting		1: Coated paper setting
[0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting 1: Coated paper setting	004	Special 4
0: Uncoated paper setting 1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		For special paper 4
1: Coated paper setting 005 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		[0 or 1 / 0 / -]
O05 Special 5 For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		0: Uncoated paper setting
For special paper 5 [0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting		1: Coated paper setting
[0 or 1 / 0 / -] 0: Uncoated paper setting 1: Coated paper setting	005	Special 5
0: Uncoated paper setting 1: Coated paper setting		For special paper 5
0: Uncoated paper setting 1: Coated paper setting		
1: Coated paper setting		
006 Special 6		· · · · · · · · · · · · · · · · · · ·
	006	Special 6

Technical Bulletin

PAGE: 18/18

Model: Aegis-P1 Date: 27-Nov-08 No.: RG178029

For special paper 6
[0 or 1 / **0** / -]
0: Uncoated paper setting 1: Coated paper setting

Technical Bulletin

PAGE: 1/4

Model: Fiery Controller		Dat	e: 25-Dec-	-08	No.: RG178030	
Subject: Start-up Failure in Pro C900 Controller		Prepared by: A. Tajima				
From: PPBG QA/	Service Planning Dept.					
Classification:		☐ Part info	ormat	tion		required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	\square Other ()	⊠ Tier 2	

SYMPTOM

Failure in the start-up of the Fiery System after turning on its power switch The symptoms appear in the following order.

- 1. The power of the Pro C900 is turned on
- 2. "Now Loading" appears on the operation panel
- 3. "Ready for Operation" appears for a split second on the operation panel
- 4. "Fiery has been disconnected..." appears on the operation panel
- 5. The power of the Pro C900 is once again turned on
- 6. "Please Wait" blinks on the operation panel

CAUSE

Capacity overload of the Fiery hard disk drive due to an excess of JobLog files

SOLUTION

Adjustments in the system software Patch release will be updated.

TENTATIVE SOLUTION UNTIL RELEASE OF REVISED SOFTWARE -Preventing System Failure -

System failure can be avoided by initializing JobLog files periodically. JobLog files inside the Fiery can be initialized by taking the following steps in the Command Workstation: Server menu - "JobLog" - "export and clear".

Make sure the AG-P1 printer is not printing when taking the following recovery steps.


1. Start Command Workstation under the username 'Administrator' (the default password is "Fiery.1") and make a connection to the Fiery.




PAGE: 2/4

Model: Fiery Controller Date: 25-Dec-08 No.: RG178030

2. In the Server menu, select "JobLog" - "export and clear".



3. Name the JobLog file and save in a suitable location.



According to our on-going analysis of the symptom, to avoid system failure, export of the log files is recommended when the number of jobs recorded reaches about 7000-10000.

System Recovery when Failure Occurs upon Start-up

If the system gets stuck, recovery is possible if you do the following steps.

System recovery will follow deletion of JobLog files. Recovery through this procedure will allow a prompt time saving re-installation of the system. As RCL will provide the batch file that enables you to delete JobLog files, please copy it to your Fiery desktop. Restart your operation by double-clicking the batch file.


1. Establish remote desktop connection from the client PC that is connected to the C900.




PAGE: 3/4

Model: Fiery Controller Date: 25-Dec-08 No.: RG178030

When the following image appears, type in the IP address of the EFI controller in the space circled in red, then click "Options".



Move to the "Local Resources" tab and place a check in "Disk drives" as circled in red then click "Connect".




- 2. Log in with the user name 'administrator'.
- 3. Select "RCL_recover.bat" from the client PC, right-click and "copy", then "paste" it on the EFI controller desktop logged-in through remote. (Drag & drop is not available between remote desktop and client PC.)

PAGE: 4/4

Model: Fiery Controller Date: 25-Dec-08 No.: RG178030

Double click on the icon of the file "RCL recover.bat" copied to the desktop.



- 4. The command prompt will start and begin its process. (The process will take 5-10 seconds after start-up.)
- 5. The command prompt will automatically close when the process is completed.
- 6. Shut off the main power on the AG-P1 printer main frame.
- 7. Wait for the EFI controller to automatically shut off.
 Check to see the LED digital number lights on the EFI controller go off. Shutdown will take approximately 4-5 minutes after main power is turned off.
- 8. Turn on the main power on AG-P1 printer main frame after the LED digital number lights on the EFI controller go off.

When the AG-P1 printer starts off normally following the above steps, the recovery procedure is now complete by making sure that all JobLogs have been cleared from CWS.

Technical Bulletin

PAGE: 1/5

Reissued: 09-Nov-12

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1,	Date: 11-May-06	No.: RB234014o
B-C3/C3.5/C4, DDP		

RTB Reissue

The items in bold italics have been added.

Subject: Controller firmware (Finisher)			Prepared by: J. Ohno	
From: 1st PP Tech Service Sect.,PP Tech Service Dept.				
Classification:	Troubleshooting	☐ Part informat	tion	Action required
		☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other (Firmv	vare)	☐ Tier 2

This RTB has been issued to announce the firmware release information for the Finisher.

Version	Program No.	Effective Date	Availability of RFU
02.050:64	B8305102V	December 2012 production Not available	
02.040:63	B8305102T	January 2012 production	Not available
02.030:62	B8305102S	March 2011 production	Not available
2.000:61	B8305102R	October 2010 production	Not available
1.900:60	B8305102Q	January 2010 production	Not available
1.820:59	B8305102P	Aug 2009 production	Not available
1.800:58	B8305102N	June 2009 production	Not available
1.600	B8305102M	March 2009 production	Not available
1.500	B8305102L	January 2009 production	Not available
1.420:51	B8305102K	August 2008 production	Not available
1.400:50	B8305102J	July 2008 production	Not available
1.310:48	B8305102H	May 2008 production	Not available
1.160	B8305102G	April 2007 production	Not available
1.140	B8305102F	November 2006 production	Not available
1.100	B8305102E	June 2006 production	Not available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected			
02.050:64	Symptoms corrected:			
	Jogging performance of the shift tray is poor when printing A5 SEF.			
02.040:63	Specification Changes: A span of 250msec to withhold the OFF signal was newly prescribed as a specification of the GBC Stream Punch.			
02.030:62	Specification Change: With the Booklet Maker BK5010, it enables saddle-stitch of custom size. Currently, this function is available only when connected to CREO.			
	 Symptoms Corrected: The error occurs when making one booklet with the Boolket Maker BK5010. The jam occurs when copy/print with switching the punch-hole type. This occur when we use main machine(110cpm or 135 cpm)/SR5000 with decurl unit. 			

[&]quot;Available": The firmware can be updated via RFU or SD card.



PAGE: 2/5

Reissued: 09-Nov-12

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1, Date: 11-May-06 No.: RB2340140 B-C3/C3.5/C4, DDP

	/C3.3/C4, DDF
Version	Modified Points or Symptom Corrected
2.000:61	 Specification Change Process Speed Setting (Low) on the Pro C901/C901S is supported. Z-fold staple job is supported for 8K paper size (267 × 390mm applied in China) on the RICOH Pro 907/1107/1357. Initialization behavior of the exit guide plate rollers have been changed to rotate the drive rollers to prevent the drive rollers from adhering to the driven rollers. Symptoms Corrected:
	 Jam 116 occurs when switching from proof mode to staple mode while the stapler is in the position for staple refill. With the Booklet Maker BK5010 installed the control panel remains to indicate jam status even after clearing the jam.
1.900:60	 Modified Points: Countermeasure against the machine cannot print when SC750 is occurring. Countermeasure against the machine cannot print when SC721 is occurring.
	SC750 Cause After the SR5000 send the "tray rising" command, it did not send "stop rising tray" command. The engine was waiting to receive the "stop rising tray" command; therefore, it did not start printing
	Measure When JAM and SC occurred on tray lift motor, while sending the "tray rising" command, SR5000 will also send "stop tray rising" command, in order to start printing.
	SC721 Cause After the SR5000 send the "wait" command, it did not send "wait cancel" command. The engine was waiting to receive the "wait cancel" command; therefore, it did not start printing
	Measure If the staple jogger motor is not at the home position when standby poison check occurred, "request default the position flag" will be set; however, when JAM or SC occurred on stable jogger motor, changed to "request default the position flag" will not be set.
	When checking whether there are staples, if the stapler is not at the home position," move to the home position" signal was released but, for ver. 1.900:60, when JAM or SC occurred in stapler motor, it does not sent the "move to the home position" signal.
1.820:59	Symptoms Corrected:1. The shift tray does not descend nor ascend even when the emergency stop button is pressed.



PAGE: 3/5

Reissued: 09-Nov-12

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1,	Date: 11-May-06	No.: RB234014o
B-C3/C3.5/C4, DDP		

Version	Modified Points or Symptom Corrected
	2. The machine stalls at a "printing in process" status in a jam where the paper is not exit to the shift tray. This symptom occurs only when installing the Katana-C2 and the EFI controller.
	<note> Please apply firmware V1.820 or later for a configuration consisted of the Katana-C2 and the EFI controller.</note>
1.800:58	Symptom Corrected: - Jam115 when changing from Standard size to Non-standard size. Other changes: - Moving distance of initialization has been changed to "2mm after sensor turn-
	off".
1.600	<note> Please apply Version (V1.600) onward when applying Plockmatic/GBC on the Aegis.</note>
	 Symptom Corrected: During Plockmatic connection, JAM115 occurs when operating manual stapling. During Plockmatic connection, indication of "out of staples" does not disappear even when staples are added after commanding a saddle-stitch job, in which the VICTORIA-E is powered in a "out of staples" status. During Plockmatic connection, when commanding saddle-stitch of more than 2 sheets consisted of a single print using 12x18 sheet, job completion is not correctly informed in order to start the 2nd stapling function, and results in a "still copying" status. During GBC connection, sheets that are not assigned to be punched are punched.
	Changes made: When operating saddle-stitch of more than 16 sheets at Plockmatic connection, a the width of the exit guide plate opening will be set to 5mm. b the shutting timing of the exit guide plate will be when 20mm of the leading edge goes through.



PAGE: 4/5

Reissued: 09-Nov-12

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1, Date: 11-May-06 No.: RB2340140 B-C3/C3.5/C4, DDP

B-C3	3/C3.5/C4, DDP
Version	Modified Points or Symptom Corrected
1.500	 Symptom Corrected: Operation stops and will not recover when "stop" button on VICTORIA-E_LED is pressed during stacker exit. Deactivate request cannot be cancelled at Plockmatic connection. Deactivate request cannot be cancelled at GBC connection. Under the condition of having no staples, jam occurs when staple function is released after its operation has been stopped. In Aegis-P1, paper cannot be fed when Plockmatic is connected; indicator shows "full" in shift tray. Other changes: Under staple-mode, single sheet of paper ejected to the shift tray will not be
4.400.54	 stapled. Although display differs in version-up Finisher Version (1.500:53) and SP mode Version (1.500:52), there is no problem as long as the SP mode Version is set to "1.500".
1.420:51	Changes: Support for Aegis-C1/P1.
1.400:50	Symptom Corrected: • When the SP adjustment value for the Jogger is set to +1.5mm, the Jogger gradually widens and results in misaligned sheets.
1.310:48	Symptom Corrected: 1. When a jam occurs at the GBC, the number of sheets of recovery is different. (The 1st sheet is omitted.)
	Other changes: 1. Support for Plockmatic SRA3 size.
1.160	 Symptom corrected: JAM 230 sometimes occurs, and the VICTORIA does not send its self-status to machine. Sometimes the VICTORIA cannot align the paper correctly when stapling. If GBC punch is selected during a copy job already set for 3-hole punching, the paper is punched by both the VICTORIA and the GBC punch unit.
1.140	 Symptom corrected: The machine stalls and displays "Copying" if the top sheet on the shift tray is removed after the tray is full. Note: When this occurs, copies cannot be made. The machine displays SC625 instead of a "jam" message when an exit jam occurs with stapled paper. Sometimes, the punch motor does not turn ON. The last sheet of a staple job is not stapled correctly. Conditions: 2 sheets/set, A4 LEF

Technical Bulletin

PAGE: 5/5

Reissued: 09-Nov-12

Model: **Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1,** Date: 11-May-06 No.: RB2340140 B-C3/C3.5/C4, DDP

Version	Modified Points or Symptom Corrected
	cleared.
	7. SC625 occurs after a staple jam is cleared.
	Conditions: The staple jam occurs when the operator opens the door during staple stacking.
	8. The machine displays "Copying"if the previous job used mixed-sizes and was cancelled.
	9. A error with the jogger fences occurs when using Z-fold stapling mode.
1.100	Latest Firmware Version

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 EFI		Dat	e: 23-Ja n	-09	No.: RG178031a	
Subject: Firmware Release Note: System EFI			Prepared by: A.Tajima			
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()		

This RTB is the release note for Patch File **1-10JUV3.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-10JUV3.ps	- When printing PCL data, some characters within the text overlap.

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s):

None

Patch Update Procedure

- 1. Extract R0205014.exe until you get the 1-10JUV3 file.
- 2. Download/Import the patch file "1-10JUV3.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-10JUV3".

Note 1: This patch is Exclusive, which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server **Note 2:** This patch does not update the Fiery version.

Technical Bulletin

PAGE: 1/4

Model: Aegis-P1		Dat	te: 13-Jan-09		No.: RG178032	
Subject: Rear Controller Box Removal		Prepared by: N.iida				
From: PPBG QA/	Service Planning Dept.					
Classification:		☐ Part informa		tion		n required
		☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transmi	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

SYMPTOM

SC (SC254, SC424, SC425, SC426, SC427) and machine malfunction seen after reinstalling the Rear Controller Box.

CAUSE

Harnesses were mistakenly inserted upside down after they had been pulled out when the Rear Controller Box had been removed. (It is possible to connect the upper harness to the lower section by mistake, and the lower harness to the upper section, because the upper and lower sections share the same form.)

SOLUTION

Removing the harness clamp can cause incorrect connection, so do not remove clamps when reinstalling the harnesses. Please follow the instructions in the service manual when removing the Rear Controller Box.

The Rear Controller Box can be separated without removing harness clamps.

(Reference: Service manual, page 61-65, Rear Controller Box Removal)

PAGE: 2/4

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178032

The following is the checking procedure and trouble-shooting procedure for making correct connection when the harness clamp is mistakenly removed.


Combination of the Cables

Connectors having the possibility of being inserted falsely are 3 couples of CN411⇔CN414, CN412⇔CN415, CN413⇔CN416.

Identification of upper and lower section is possible by checking whether a black band is present or not.

Harnesses to be connected in the lower section are wrapped with a black band.

Harnesses without the black band must be connected to the upper section.



Technical Bulletin

PAGE: 3/4

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178032

Trouble-shooting

Connector	Symptom		
Incorrect connection of CN413/CN416	SC254 occurs when power is switched ON.		
Incorrect connection of CN411/CN414	Operation is normal after power is switched ON. Printing operation is normal as well. SC424, S425, SC426, SC427 are counted (recorded) internally (not shown on display) when process control is executed.		
Incorrect connection of CN412/CN415	SC254 occurs when power is switched ON.		
Incorrect connection of both CN411/CN414 and CN412/CN415	SC254 occurs when power is switched ON.		
Incorrect connection of both CN411/CN414 and CN413/CN416	SC254 occurs when power is switched ON.		
Incorrect connection of both CN412/CN415 and CN413/CN416	 Operates normally after power is switched on but generates an abnormal picture (the picture is clearly abnormal). SC410 occurs when process control is executed. 		
Incorrect connection of all CN411/CN414, CN412/CN415, and CN413/CN416	 Operates normally after power is switched on but generates an abnormal picture (the picture is clearly abnormal). SC410 occurs when process control is executed. 		
Disconnection of CN410	SC161-01 appears on the display. Initial operation of the machine is normal.		
Disconnection of CN418	SC202 appears on the display.		
Disconnection of CN419	Initializing does not operate. "Please wait" appears on display and stays there.		
Disconnection of CN420	Initializing does not operate. "Please wait" appears on display and stays there.		
Disconnection of CN423	Flashing of all indicators on the operation panel.		
Bad connection between "GW Controller" and "Fiery Controller"	SC991/991 may occur.		

An abnormal picture is generated as seen below when connection of CN412 is incomplete. The result of an all-red picture is printed as seen on the left.

Example of Abnormal Picture



Example of Normal Picture






Model: Aegis-P1

Technical Bulletin

Date: 13-Jan-09 No.: RG178032

PAGE: 4/4

An abnormal picture is generated as seen below when connection of CN415 is incomplete. An abnormal picture as seen below is an example when printing an all-black picture.



Technical Bulletin

PAGE: 1/7

Model: Aegis-P1			Dat	i te : 13-Jan-09		No.: RG178033
Subject: SR5000: Exit Roller Leaves Marks When Using Coated Paper 28-Jan-09 Revised				Prepared	d by: M.K	íudoh
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
!	☐ Mechanical	☐ Electric	al		☐ Servic	e manual revision
!	☐ Paper path	☐ Transm	it/rec	eive	□ Retrof	fit information
!	☐ Product Safety	Other ()	⊠ Tier 2	

SYMPTOM

The exit roller leaves marks when using coated paper.

CAUSE

This case is limited to the Ultra Digital 80lb Gloss Test.

SOLUTION

An altered exit drive roller without the brim (**B8309533**) is available as an individual corresponding part.


NOTE

Stacking failure and paper ejection failure may occur when thin paper is used for this roller. These symptoms are presently seen when Classic White (A3 size) is used. Be sure to give due consideration to this side effect when supporting the users.


PAGE: 2/7

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178033

1. Please remove the parts indicated by the arrows (Front Door, Covers and Jogger Unit).



2. Remove the guide panel




2-1. Remove the rear-side screws


PAGE: 3/7

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178033

Remove the Rear Gear Cover



While supporting the tray with one hand, lift the middle gear to lower the tray. (Please be careful not to turn the lower gear.)




Model: Aegis-P1

Technical Bulletin

Date: 13-Jan-09 No.: RG178033

PAGE: 4/7

Remove the screw indicated by the arrow and raise the bracket connected to the motor.



Area with bracket dislocated




Then, remove the gear connected to the belt shaft. Please be careful not to drop the balance pin when removing the large lower gear. Remove the Sintering Bearing from the sideboard and remove the balance pin by pushing it through, it is difficult to remove.

Model: Aegis-P1

PAGE: 5/7 Date: 13-Jan-09 No.: RG178033

Remove the screws from the guide board.



2-2. Removal of front-side screws



Screw

2-3 Removal of guide board
Pull the guide board from the paper ejection port. Please be careful not to rip the mylar inside the machine.




PAGE: 6/7

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178033

- 3 Change the roller
- 3-1 Remove every roller shaft


Remove the E-ring gear, and with the removal of the bearing the shaft may be removed.





Remove E-ring Gear

3-2 Change the rollers on the shaft that has been removed. Change the two central rollers.



Change these

3-2-1 Removal of end rollers

In order to remove the central rollers, it is necessary to first remove the end rollers.

- (1) Remove the E-ring
- (2) Remove the roller



Technical Bulletin

PAGE: 7/7

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178033

Slide the rollers off the shaft. Be careful not to drop the balance pins, they will be removed later.



3-2-2 Removal and replacement of center rollers Remove the end rollers and the E-rings from the shaft. Again, be careful not to drop the balance pins.



Square up the balancing pin with the new roller and slide it on. Be careful of the direction the roller is placed on the shaft, and then return the E-rings.



Repeat the same procedure with the rollers on the other end. Re-assembly is the opposite of disassembly.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 Date			ate: 13-Jan-09		No.: RG178034	
Subject: Exchanging Oil Tank Filter		Prepared by: N.iida				
From: PPBG QA	Service Planning Dept.					
Classification:	☑ Troubleshooting	☐ Part informa		ation		required
	☐ Mechanical	☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM/CAUSE

As for clients that use a large amount of normal paper, filtering efficiency is lower when printing exceeds 100K, caused by paper dust and calcium carbonate contained in paper clogging the oil filter.

As a result, impurities circulating with the oil are adhered to the oil supply unit, causing uneven oil coating, eventually causing uneven brightness and glossy lines.

SOLUTION

Change of filter is under review. The change will take place around February. Details will be informed through RTB updates.

-Temporary actions to be taken in the market-For clients using *only* normal paper, the oil filter will be changed at approximately 100K.

Also, when Oil Supply Unit is exchanged at PM (400K), the Oil Tank Filter must be exchanged at the same time.

Technical Bulletin

PAGE: 1/3

Model: Aegis-P1			Dat	e: 13-Jan-	09	No.: RG178035
Subject: Firmware Update			Prepared by: N.iida			
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part informa		nation 🖂 Act		n required
		☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transmi	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

SOLUTION

Even if "A3/DLT Double Count (SP5-104-001)" is set to "1: Double count", SRA3 is not double counted. As firmware reflecting this problem has been released, please apply to all products distributed to the market. Make sure to update the firmware to a version mentioned below or higher. Update upon installation. Machines that have already been distributed to the market shall be updated upon PM & EM visits.

Mainframe

Program Name	Firmware No.	Version
Engine	G1785252D	1.108 :11
System	G1785252D	1.02
Websys	G1786093C	1.01

Notes

- Update the following firmware at the same time: Engine, System and Websys.
- See the following page for improvements made in each program.



PAGE: 2/3

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178035

Engine

Version	Modified Points or Symptoms Adjusted
1.108 :11	Malfunction has been restored involving the appearance of an alert signal indicating a spanner mark when pulling out the trays.
	 Oil Removal function made available during process control for Interrupt, JobEnd and Non-use Time Setting. Change has been made in Oil Removal manual operation method.
	 4 . Adjustments have been made for trouble occurrence of SC670 during Clearing Engine Memory (SP5-801-002). ※Use combination of System:1.02 & engine:1.108:11 to operate.

System

System	
Version	Modified Points or Symptoms Adjusted
1.02	 Adjustments have been made for SC819 caused by memory leak when returning from Energy Saving. Change in SP default value:
	SP3-309-009: Oil removal mode Select mode between paper (former) default value: 0 "ON" depending on operating environment (revised) default value: 1 "ON" at all times 3. Additions made in SP number:
	SP3-309-008: Oil removal mode Select mode at Process Control
	Oil Removal will automatically start during Process Control for Non-use Time Setting.
	SP3-309-014: Oil removal mode Interrupt ON/OFF
	Selection of yes/no of Oil Removal during Interrupt
	SP3-309-015 : Oil removal mode Interrupt Thresh
	Value of Thresh prints at Oil Removal in an Interrupt during print operation.
	SP3-309-016: Oil removal mode Job End thresh
	Value of Oil Removal Thresh prints after JobEnd.
	SP3-309-017: Oil removal mode Both Sides Counter
	Counter function for Both Sides printing. 4. Additions made in Function Setting SP for Oil Removal command manual.
	SP3-309-18 : Oil removal mode Idling Time 1
	Idling Time-1 after development of Toner Pattern for Oil Removal
	SP3-309-19 : Oil removal mode Idling Time 2
	Idling Time-2 after development of Toner Pattern for Oil Removal
	SP3-309-20 : Oil removal mode Repeat Time
	Number of Toner Pattern development for Oil Removal 5. Adjustments have been made involving problems with toner refresh not functioning. 6. Adjustments have been made involving problems with SRA3 not reading a double
	count despite "1: Double count" is set for " A3/DLT Double Count (SP5-104-001)"

Technical **B**ulletin

PAGE: 3/3

Model: Aegis-P1 Date: 13-Jan-09 No.: RG178035

WebSystem

Version	Modified Points or Symptoms Adjusted
1.01	PnP table has been replaced to enable correspondence with multi-brands.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 EFI Controller Dat			Date: 26-Jan-09		No.: RG178036	
Subject: Information on order of applying controller patch for Pro C900 Fiery			Prepared by: A. Tajima			
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	Action	required
	☐ Mechanical	Mechanical		ectrical Serv		e manual revision
	☐ Paper path ☐ Transmit/re		☐ Transmit/receive		☐ Retrof	it information
	☐ Product Safety			order)	⊠ Tier 2	

To clarify the complicated order of applying patches for the Fiery controller, we would like to inform the correct order and the prerequisite patches.

Currently, 5 patches have been released officially on the Rissn server. In the table below, you can find the recommended order of applying the patches, which is the same order as they were released on the Rissn server.

Recommended order of applying (Released order on Rissn server)	Code # of patch	Prerequisite patch
1	1-YX34D	None
2	1-ZPVPD	1-YX34D
3	1-ZX2LD	None
4	1-103CJ7	None
5	1-10JUV3	None

We were officially supposed to say that 1-YX34D is necessary for 1-ZPVPD for managing patches.

However, 1-ZPVPD actually contains 1-YX34D, and this means 1-YX34D is not necessary. (1-YX34D has not been applied to some of the mass production units.)

When 1-10JUV3 was released, we were supposed to say that 1-10JUV3 needs four previous patches.

However, EFI has confirmed that 1-10JUV3 does not need the previous four patches. For example, there will be no problem even if you apply patches in the order below, which differs from the recommended order.

Applied order	Recommended order	Code # of patch
1	1	1-YX34D
2	2	1-ZPVPD
3	5	1-10JUV3
4	3	1-ZX2LD
5	4	1-103CJ7

If you are uncertain about the order of the patch application, please apply them in the recommended order which is the same as the released order on the Rissn server.

Technical Bulletin

Model: Aegis-P1 Date			e: 29-Jan-09	No.: RG178037	
Subject: Oil gloss line			Prepared by: Nobuo.iida		
From: PPBG QA	/Service Planning Dept.				
Classification:		☐ Part info	rmati	on Action	required
	☐ Mechanical	☐ Electrica	al	☐ Service	ce manual revision
	☐ Paper path	☐ Transmit	t/rece	eive 🗌 Retrof	fit information

☐ Tier 2

SYMPTOM

Difference in glossiness occurs when printing in DLT/A3 size after printing more than 40 photo image prints in LT/A4 (SEF) size with a margin.

Other (


More than 40 prints of photo image in LT/A4 (SEF) size

☐ Product Safety



Prints in DLT/A3 size

)




High Glossiness Area


PAGE: 1/2

CAUSE

A very small amount of toner adheres to the surface of the fusing belt where the toner passes. A difference in glossiness occurs in the next image due to the difference in amount of toner adhesion on belt. Glossiness is lower in areas where a small amount of toner is adhered. Glossiness tends to be even higher in the area where toner hasn't passed, making the difference in glossiness significant especially when the belt is brand new. The difference in glossiness tends to lower as number of sheets of paper passing the belt increases.

After printing more than 40 prints of an image such as (1), a difference occurs on the surface of the fusing belt (toner adhesion), causing a difference in glossiness within the print in the next image such as (2).





High Glossiness Area



PAGE: 2/2

Model: Aegis-P1 Date: 29-Jan-09 No.: RG178037

SOLUTION

Adhering a small amount of toner evenly on the entire surface of the fusing belt by making solid black prints in DLT/A3 size solves this problem. Make 20 solid black prints (solid black on both sides). If the problem is not solved by the first 20 prints (both sides), continue with an additional 20 prints (both sides) until the problem is solved.

The procedure is as follows:

- 1. Enter the SP mode and then select SP2109-002 ("Select Pattern" < "Write Test Pattern").
- 2. Select No.20 (100% Coverage) pattern in the test pattern list, and then press "OK".
- 3. Select SP2109-004 (color select), press"0","1","2" keys and then press "OK". Status should be: "00001000"
- 4. Press the "APL Window" button on the top of the LCD
- 5. Make a test print from a PC. (Size: A3/DLT (11x17), Duplex: on, Number of Copies: 20 pages (both sides)
 - * The image for the test print must include black.
- 6. Check the image and continue with the solid black prints until the difference in glossiness is resolved.

Notes

- Solid black prints can be made after the paper size is selected on the operation panel.
 However, as this method will not allow you to set the number of copies, make a test
 print from a PC. Please ensure that you follow the above procedure when making solid
 black prints. (The Total Counter will not count these test prints, because they are
 made in SP mode.)
- If paper sizes larger than A3/DLT such as SRA3, 12x18, 13,18, etc are to be used by the client, solid black print testing is recommended in sizes as large as possible.
- No particular application software is specified for the test print from the PC. Prepare a 2-page document consisting of texts using software installed in a standard OS such as Word Pad. Set "size", "both sides printing" and "number of copies" and then print.
 Size: A3/DLT (11x17), Duplex: on, Number of Copies: 20 pages (both sides)

Example of the test print

Test Page 1	Test Page 2	

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1	EFI		Dat	e: 02-Feb	-09	No.: RG178038
Subject: Firmware			Prepared by: T. Satoh			
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for Patch File **1-10JE4A.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-10JE4A.ps	When printing certain PDF files, some areas that are supposed to be
	white print in gray

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s):

1-YX34D-1

1-ZPVPD

1-ZX2LD

1-103CJ7

1-10JUV3

Patch Update Procedure

- 1. Extract R0205027.exe until you get the 1-10JE4A file.
- 2. Download/Import the patch file "1-10JE4A.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-10JE4A".

Note 1: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server **Note 2:** This patch does not update the Fiery version.

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1 EFI Dat				e: 02 -Feb	-09	No.: RG178039
Subject: Firmware				Prepare	d by: T. S	Satoh
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electrica	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for Patch File **1-108MRT.ps** for ProC900 system version 1.01.

Patch File	Issue(s)
1-108MRT.ps	Unwanted strip of white lines print when printing certain PDF jobs with
	Text/Graphics Quality = Best and resolution = 1200dpi.

Notes: This patch is only for ProC900 system version 1.01.

Prerequisite(s):

1-YX34D-1

1-ZPVPD

1-ZX2LD

1-103CJ7

1-10JUV3

Patch Update Procedure

- 1. Extract R0205026.exe until you get the 1-108MRT file.
- 2. Download/Import the patch file "1-108MRT.ps" with Command Workstation to the "Direct" queue.
- 3. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
- 4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD.
- 5. Please wait until the Fiery comes to idle and print out the configuration page.
- 6. Verify the **Update Info** section. It should contain the patch number "1-108MRT".

Note 1: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server **Note 2:** This patch does not update the Fiery version.

Technical Bulletin


PAGE: 1/1


Model: Aegis-P1	Dat	:e: 24-Feb	-09	No.: RG178040		
Subject: Web Cleaning Unit: Near End/End Clear Error					d by: N.iid	da
From: PPBG QA/	rom: PPBG QA/Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion		required
	☐ Mechanical	☐ Electrica	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

Web Cleaning Unit: Near End/End Clear Error

Symptom

Even though clearing the PM counter for the web cleaning unit with SP7622-129 is done after a new web cleaning unit has been installed, the web near end message [A] is displayed on the operation panel or the web end message [B] is displayed on the operation panel and then machine stops operating.





Action

Follow the procedure below after the new web cleaning unit has been installed. (This must be done until the updated firmware for this problem is released.)

- 1. Replace the old web cleaning unit with a new web cleaning unit.
- 2. Clear the PM counter for the web cleaning unit with SP7622-129.
- 3. Execute SP1902-006 (Web Near End/End Clear).
- 4. Open the front door, and then close the front door.

Note: Never forget to open and close the front door. This step is important. It is because this action makes a reset signal for the web near end and web end from the BCU to the controller board.

Technical Bulletin

PAGE: 1/2

Model: Aegis-P1/C1 Date			te: 23-Feb-09		No.: RG178041	
Subject: Important notes when replacing the RCB				Prepare	d by: N.iid	da
From: PPBG QA/Service Planning Dept.						
Classification:	n: Troubleshooting Part inform		orma	tion		required
	☐ Mechanical ☐ Electrical		cal Service manual		e manual revision	
☐ Paper path ☐ Transmit/re		it/rec	eive	☐ Retrof	it information	
	☐ Product Safety	Other ()	⊠ Tier 2	

Important notes when replacing the RCB

The function of the logging SC detection is newly added to the Aegis-C1 model and P1 model which has the engine firmware released in February 2009.

However, some RCB parts which have old firmware version do not allow this function to work properly.

Action

To avoid the logging SC:

• Always update the engine firmware to the latest version after replacing the RCB. Otherwise, one of the logging SCs (SC675-04, -07, -08) may be issued.

Note: For some combinations of BCU and RCB firmware versions, engine firmware update may not be necessary. For details, refer to the "Firmware Matrix for Logging SC".

Firmware Matrix for Logging SC

Here is the firmware matrix for the logging SC. Check if the engine firmware update is necessary or not to avoid the logging SC.

- "No SC" means that the engine firmware update is not necessary.
- "Logging SC" means that the engine firmware update is necessary.

		RCB Engine Program (Aegis-P1/C1)					
	Software Part	G1787707B	G1787707C	G1787707D			
	Number						
BCU Engine	G1785252B	No SC	No SC	No SC			
Program (Aegis-	G1785252C	No SC	No SC	No SC			
	G1785252D	No SC	No SC	No SC			
P1)	G1785252E	Logging SC	Logging SC	No SC			
BCU Engine	D0165252A	Logging SC	Logging SC	No SC			
Program (Aegis-	D0165252B	Logging SC	Logging SC	No SC			
C1)							

PAGE: 2/2


Model: Aegis-P1/C1 Date: 23-Feb-09 No.: RG178041

Checking the software part number of the BCU engine program

• Enter SP mode, and then check the part number of the BCU engine program with SP7801-255 or by printing the self-diagnostic sheet with SP5990-005.

Checking the software part number of the RBC engine program

1. Check the part number printed on the RCB.



2. Find the software part number of the RCB engine program referring to the table below.

Software Number of	RCB Part Number
RCB Engine Program (Aegis-P1/C1)	
G1787707B	G1787706B
G1787707C	G1787706C
G1787707D	G1787706D

For example:

- 1. If an RCB part number on the RCB is "G1787706C" as shown above, the software number of the RCB engine program is "G1787707C".
- 2. See the "Firmware Matrix for Logging SC".
- 3. Now you know that the following software numbers cause the logging SC with "G1787707C" of the RCB engine program.
 - G1785252E/ D0165252A/ D0165252B
- 4. Update the engine firmware to the latest version if the machine which you are working on has the BCU software part numbers causing the logging SC.

or

If not, reassemble the machine.

Technical Bulletin

PAGE: 1/44

Reissued:24-Apr-09

Model: Aegis-P1	ate: 24-Mar-09		No.: RG178042a			
Subject: Aegis field modification					d by: N.iio	da
From: PPBG QA/Service Planning Dept.						
Classification:	n: Troubleshooting Part info		al		Service	n required be manual revision fit information

RTB Reissue

The items in **bold italics** were corrected or added.

Please perform these modifications on the field machines.

1. Adding a Filter to the Oil Tank

Symptom: Oil cannot be coated on the belt evenly when reaching approximately 200K.

(time limited restriction)

Cause: Due to adhesion of calcium carbonate to the oil supply unit.

Solution: By increasing the filter size, calcium carbonate is removed and prevents its

adhesion to the oil supply unit. Improvement will allow an even oil coating to

the belt.

2. Adding Fusing Knob "A"

Symptom: Jammed paper wrapped around the hot roller cannot be removed.

Cause: A method for solving this problem was not included in the design.

The attached knob will allow users to easily remove the jammed paper.

3. Adding a Mylar on the Tray 1 Exit

Symptom: Torn paper and jam occurs when using normal paper in Tray 1.

Cause: Due to damage at the paper edge caused by the second sheet of paper

directly hitting the Reverse Roller.

Solution: The newly added Mylar will prevent the second sheet of paper from directly

hitting the Reverse Roller.

4. Replacement of the Rubber Roller on the Waste Toner Plate

Symptom: In the durability test, the rubber roller was damaged. Pieces of the damaged

parts interfered with the screw and caused "SC489 Waste toner transport

motor 2 sensor error".

Cause: Durability of the rubber roller was insufficient.

Solution: Material of the roller has been changed from silicone to a more durable

urethane.

Please perform the above modifications at PM or EM.

* As for C1, modification is completed at the factory.



PAGE: 2/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Modification Item

1. MODIFICATION KIT:A (part number G1789901)

Modification for Mainframe

This modification will allow easy removal of jammed paper from the fusing unit as well as a longer life span for the oil application unit.

*Although the oil application unit was originally designed with a life span of 400K, it had turned out to be approximately 200K in practice. This modification will reflect the original design.

No.	Item	Pats No.	Parts Name	Amount	Remarks
1		D0164319	STAND:OIL TANK:UPPER	1	
2		D0164158	STOPPER:CASE	1	
3		D0164432	COVER:OIL TANK (bottom)	1	
4		D0164403	HOLDER:USED DEVELPER:OIL TANK	1	
5		D0164412	CASE:FILTER:ADHESION	1	
6		D0164400	COVER:OIL TANK (top)	1	
7		D0164266	COVER:OIL SUPPLY SUB-UNIT	1	
8		D0164452	COVER:PUMP:OIL TANK	1	
9	Oil Filter	G1787901	DECAL:WARNING	1	
10		G1785077	DECAL:E	1	
11		G1784217	DECAL:OIL:OVERFLOW:OIL TANK	1	
40			DECAL:OIL SUPPLY SUB-		
12		G1784313	UNIT:DESIGN SKETCH	1	
13		04504012N	TAPPING SCREW:4X12	2	
14		04504010N	TAPPING SCREW:4X10	1	
15		04514008N	TAPPING SCREW:4X8	1	
16		D0167924	TUBE:DIA8.5:COLLECT:MAIN	1	
17		G1781559	SUPPORTING PLATE:DOOR:LEFT	1	
18	Fuser Knob for	G1787912	DECAL:OIL SUPPLY INSTRUCTIONS	1	
19		G1781580	HOLDER:SHEET:FUSING:ASS'Y	1	
20	Mainflame	D0164032	DECAL:PICK-UP PAPER JAM:D	1	
21		G1785083	DECAL:GRIP:OPEN AND CLOSE:D4	1	
22		D0164244	KNOB:FUSING:MECHANICAL ROLLER CLUTCH	1	
23		D0164241	STAY:SHAFT:KNOB:HOT ROLLER:2HOLE	1	
24		G1784139	COVER:FUSING UNIT:FRONT:ASS'Y	1	
25	Fuser Knob for	03604008N	SCREW:M4X8	4	
26	Fuser unit	09544008N	SCREW:POLISHED ROUND/SPRING:M4X8	1	
27		05740080E	SET SCREW:M4X8	3	For Hot Roller without hole
28		D0164097	BASE KNOB:HOT ROLLER	1	For Hot Roller without hole
29		D0164092	STAY:SHAFT:KNOB:HOT ROLLER:4HOLE	1	For Hot Roller without hole
30	Tray 1Guide Sheet	G1782979	GUIDE:SHEET:FEED TRAY	1	
31	Rubber Roller of Waste Toner Duct	G1787818	ROLLER:RUBBER:TONER RECYCLING SUB-UNIT	1	
32	Fuser Exit Guide Screw	09544008N	SCREW:POLISHED ROUND/SPRING:M4X8	1	



PAGE: 3/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

2. MODIFICATION KIT:B FUSER ASSY (part number G1789902)

Modification for Fusing unit

Please apply this modification kit for the FRU Fusing Unit stored at the client site.

No.	Item	Pats No.	Parts Name	Amount	Remarks
1		D0164244	KNOB:FUSING:MECHANICAL ROLLER CLUTCH	1	
2		D0164241	STAY:SHAFT:KNOB:HOT	1	
3		G1784139	COVER:FUSING UNIT:FRONT:ASS'Y	1	
4	Cusar Knah far	03604008N	SCREW:M4X8	4	
5	Fuser Knob for Fuser unit	09544008N	SCREW:POLISHED ROUND/SPRING:M4X8	1	
6		05740080E	SET SCREW:M4X8	3	For Hot Roller without hole
7		D0164097	BASE KNOB:HOT ROLLER	1	For Hot Roller without hole
8		D0164092	STAY:SHAFT:KNOB:HOT ROLLER:4HOLE	1	For Hot Roller without hole
9	Fuser Exit Guide Screw	09544008N	SCREW:POLISHED ROUND/SPRING:M4X8	1	

3. MODIFICATION KIT: C (part number G1789903)

OIL TANK

If oil is deteriorated (white colored and unclear) please change the oil by applying the parts included in this kit.

No.	Item	Parts No.	Parts Name	Amount	Remarks
1		G1784425	OIL TANK	1	
2		G1784476	PACKING:OIL TANK	1	
3	Oil Tank	G1784337	FILTER:OIL:ASS'Y	1	
4		04504010N	TAPPING SCREW:M4X10	8	
5		A2579550	SILICONE OIL TYPE SS	2	

PAGE: 4/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Serial Numbers for Object Machines that Require Modification

NOTE: Blue indicates machines for InfoPrint.

AP: TOTAL 14

S3281100005
S3281100006
S3281100007
S3281100008
S3281100009
S3281100010
S3281100011
S3281100012
S3281200001
S3281200002
S3281200003
S3281200004
S3281200005
S3281200006

RE	T	$^{-}$	$\Gamma \Lambda I$	96
		\circ		_ 00

2 S3280800043 3 S3280800044 4 S3280800045 5 S3280800046 6 S3280800047 7 S3280800048 8 S3280800049 9 S3280800050 10 S3280900003 11 S3280900005 13 S3280900005 14 S3280900006 14 S3280900006 14 S3280900009 17 S3280900009 17 S3280900010 18 S3280900011 19 S3280900011 19 S3280900012 20 S3280900015 23 S3280900015 23 S328090015 24 S3280900015 25 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000108 27 S3281000109 28 S3281000110 29 S3281000111 30 S3281000111 30 S3281000112 31 S3281000112 31 S3281000115 34 S3281000115 35 S3281000111 30 S3281000111 30 S3281000112 31 S3281000112 32 S3281000112 33 S3281000112 34 S3281000120 39 S3281000120 39 S3281000120 39 S3281000122 41 S3281000125 44 S3281000125 44 S3281000126 45 S3281000129 48 S3281000129	1	S3280800042
3 S3280800044 4 S3280800045 5 S3280800046 6 S3280800047 7 S3280800048 8 S3280800049 9 S3280800050 10 S3280900003 11 S3280900005 13 S3280900006 14 S3280900006 14 S3280900007 15 S3280900009 17 S3280900010 18 S3280900010 18 S3280900011 19 S3280900012 20 S3280900013 21 S3280900015 23 S3280900015 24 S3280900015 25 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000107 26 S3281000108 27 S3281000109 28 S3281000110 29 S3281000111 30 S3281000111 30 S3281000111 31 S3281000111 32 S3281000111 33 S3281000111 34 S3281000111 35 S3281000111 36 S3281000112 37 S3281000111 38 S3281000112 31 S3281000112 32 S3281000112 33 S3281000115 34 S3281000115 34 S3281000120 39 S3281000121 40 S3281000122 41 S3281000122 41 S3281000125 44 S3281000125 44 S3281000127 46 S3281000129 48 S3281000129	2	
4 \$3280800045 5 \$3280800046 6 \$3280800047 7 \$3280800048 8 \$3280800049 9 \$3280800050 10 \$3280900003 11 \$3280900004 12 \$3280900005 13 \$3280900005 14 \$3280900006 14 \$3280900007 15 \$3280900008 16 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000106 25 \$3281000109 28 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000117 36 \$3281000118 37 \$3281000119 38 \$3281000119 38 \$3281000120 40 \$3281000120 41 \$3281000120 42 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000129 48 \$3281000129 48 \$3281000129 48 \$3281000129 48 \$3281000129 48 \$3281000129		
6 S3280800047 7 S3280800048 8 S3280800049 9 S3280800050 10 S3280900003 11 S3280900005 13 S3280900006 14 S3280900006 14 S3280900007 15 S3280900008 16 S3280900009 17 S3280900010 18 S3280900011 19 S3280900011 20 S3280900012 20 S3280900013 21 S3280900015 23 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000109 28 S3281000109 28 S3281000110 29 S3281000110 29 S3281000111 30 S3281000112 31 S3281000115 34 S3281000115 34 S3281000115 34 S3281000116 35 S3281000117 36 S3281000117 37 S3281000119 38 S3281000119 38 S3281000120 39 S3281000120 39 S3281000120 40 S3281000120 41 S3281000120 42 S3281000120 43 S3281000120 44 S3281000120 45 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000129		
7 S3280800048 8 S3280800049 9 S3280800050 10 S3280900003 11 S3280900004 12 S3280900006 14 S3280900006 14 S3280900008 16 S3280900009 17 S3280900010 18 S3280900010 19 S3280900012 20 S3280900013 21 S3280900014 22 S3280900015 23 S3280900015 24 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000109 28 S3281000110 29 S3281000110 29 S3281000111 30 S3281000112 31 S3281000113 32 S3281000115 34 S3281000115 34 S3281000116 35 S3281000117 36 S3281000119 37 S3281000119 38 S3281000119 38 S3281000120 39 S3281000120 40 S3281000121 40 S3281000122 41 S3281000125 44 S3281000125 44 S3281000126 45 S3281000127 46 S3281000129 48 S3281000129 48 S3281000129	5	
8 \$3280800049 9 \$3280800050 10 \$3280900003 11 \$3280900004 12 \$3280900005 13 \$3280900006 14 \$3280900006 14 \$3280900008 16 \$3280900009 17 \$3280900010 18 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900012 20 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000111 30 \$3281000112 31 \$3281000115 34 \$3281000115 35 \$3281000117 36 \$3281000116 35 \$3281000117 36 \$3281000117 36 \$3281000119 38 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000125 44 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000129 48 \$3281000129 48 \$3281000129 48 \$3281000129	6	S3280800047
8 S3280800049 9 S3280800050 10 S3280900003 11 S3280900004 12 S3280900005 13 S3280900006 14 S3280900006 14 S3280900008 16 S3280900009 17 S3280900010 18 S3280900011 19 S3280900012 20 S3280900013 21 S3280900014 22 S3280900015 23 S3280900015 23 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000109 28 S3281000110 29 S3281000111 30 S3281000111 30 S3281000112 31 S3281000115 34 S3281000115 34 S3281000115 35 S3281000117 36 S3281000116 35 S3281000117 36 S3281000119 38 S3281000119 38 S3281000120 39 S3281000120 40 S3281000121 40 S3281000122 41 S3281000125 44 S3281000125 44 S3281000126 45 S3281000127 46 S3281000129 48 S3281000129 48 S3281000129	7	S3280800048
9 \$3280800050 10 \$3280900003 11 \$3280900004 12 \$3280900005 13 \$3280900006 14 \$3280900006 14 \$3280900009 15 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900012 20 \$3280900013 21 \$3280900015 23 \$3280900015 24 \$3281000105 24 \$3281000106 25 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000111 30 \$3281000112 31 \$3281000114 33 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000117 36 \$3281000119 38 \$3281000119 38 \$3281000120 39 \$3281000120 40 \$3281000121 40 \$3281000125 44 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000129 48 \$3281000129	8	
11 \$3280900004 12 \$3280900005 13 \$3280900006 14 \$3280900008 16 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000105 24 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000125 44 \$3281000125	9	S3280800050
12 S3280900005 13 S3280900006 14 S3280900006 14 S3280900008 16 S3280900009 17 S3280900010 18 S3280900011 19 S3280900012 20 S3280900013 21 S3280900014 22 S3280900015 23 S3281000105 24 S3281000106 25 S3281000106 25 S3281000107 26 S3281000109 28 S3281000110 29 S3281000110 29 S3281000111 30 S3281000112 31 S3281000112 31 S3281000115 34 S3281000115 34 S3281000115 34 S3281000116 35 S3281000117 36 S3281000117 36 S3281000119 38 S3281000119 38 S3281000120 40 S3281000121 40 S3281000122 41 S3281000123 42 S3281000125 44 S3281000126 45 S3281000127 46 S3281000129 48 S3281000129 48 S3281000129	10	S3280900003
13 \$3280900006 14 \$3280900007 15 \$3280900008 16 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000124 43 \$3281000125 44 \$3281000126 45 \$3281000129	11	S3280900004
14 \$3280900007 15 \$3280900008 16 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000124 43 \$3281000125 44 \$3281000126 45 \$3281000129 48 \$3281000129	12	S3280900005
15 S3280900008 16 S3280900009 17 S3280900010 18 S3280900011 19 S3280900012 20 S3280900013 21 S3280900014 22 S3280900015 23 S3281000105 24 S3281000106 25 S3281000107 26 S3281000109 28 S3281000110 29 S3281000111 30 S3281000112 31 S3281000112 31 S3281000114 33 S3281000115 34 S3281000115 35 S3281000115 36 S3281000115 37 S3281000116 35 S3281000117 36 S3281000117 36 S3281000119 38 S3281000119 38 S3281000120 39 S3281000120 40 S3281000121 40 S3281000122 41 S3281000122 41 S3281000125 44 S3281000126 45 S3281000127 46 S3281000129 48 S3281000129	13	S3280900006
16 \$3280900009 17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000115 34 \$3281000117 36 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000125 44 \$3281000126 45 \$3281000129 48 \$3281000129	14	S3280900007
17 \$3280900010 18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000115 35 \$3281000117 36 \$3281000118 37 \$3281000120 39 \$3281000121 40 \$3281000121 40 \$3281000124 41 \$3281000125 44 \$3281000126 45 \$3281000129 48 \$3281000129 48 \$3281000130	15	S3280900008
18 \$3280900011 19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000118 37 \$328100012 40 \$328100012 40 \$328100012 41 \$328100012 42 \$328100012 43 \$3281000125 44 \$3281000126 45 \$3281000129 48 \$3281000130		S3280900009
19 \$3280900012 20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000115 34 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000124 43 \$3281000125 44 \$3281000127 46 \$3281000129 48 \$3281000129 48 \$3281000130		S3280900010
20 \$3280900013 21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000121 40 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		S3280900011
21 \$3280900014 22 \$3280900015 23 \$3281000105 24 \$3281000107 26 \$3281000109 27 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000117 37 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000129 48 \$3281000130		S3280900012
22 \$3280900015 23 \$3281000105 24 \$3281000107 26 \$3281000109 27 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000121 40 \$3281000124 41 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000129 48 \$3281000129 48 \$3281000130		S3280900013
23 \$3281000105 24 \$3281000106 25 \$3281000107 26 \$3281000109 27 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000129 48 \$3281000130		S3280900014
24 \$3281000106 25 \$3281000107 26 \$3281000109 27 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		S3280900015
25 S3281000107 26 S3281000108 27 S3281000109 28 S3281000110 29 S3281000111 30 S3281000112 31 S3281000113 32 S3281000114 33 S3281000115 34 S3281000115 34 S3281000116 35 S3281000117 36 S3281000119 38 S3281000120 39 S3281000120 40 S3281000121 40 S3281000121 40 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000125 44 S3281000127 46 S3281000129 48 S3281000129		S3281000105
26 \$3281000108 27 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		S3281000106
27 \$3281000109 28 \$3281000110 29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000129 48 \$3281000130		S3281000107
28 S3281000110 29 S3281000111 30 S3281000112 31 S3281000113 32 S3281000114 33 S3281000115 34 S3281000116 35 S3281000117 36 S3281000117 37 S3281000119 38 S3281000120 39 S3281000120 40 S3281000122 41 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000125 44 S3281000127 46 S3281000128 47 S3281000129 48 S3281000129		S3281000108
29 \$3281000111 30 \$3281000112 31 \$3281000113 32 \$3281000114 33 \$3281000115 34 \$3281000116 35 \$3281000117 36 \$3281000118 37 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130	27	S3281000109
30 S3281000112 31 S3281000113 32 S3281000114 33 S3281000115 34 S3281000116 35 S3281000117 36 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000123 42 S3281000123 42 S3281000124 43 S3281000125 44 S3281000125 44 S3281000127 46 S3281000127 46 S3281000129 48 S3281000130	28	S3281000110
31 S3281000113 32 S3281000114 33 S3281000115 34 S3281000116 35 S3281000117 36 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000125 44 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130	29	S3281000111
32 S3281000114 33 S3281000115 34 S3281000116 35 S3281000117 36 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000122 41 S3281000124 43 S3281000125 44 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		S3281000112
33 S3281000115 34 S3281000116 35 S3281000117 36 S3281000118 37 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000125 44 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		S3281000113
34 \$3281000116 35 \$3281000117 36 \$3281000117 37 \$3281000119 38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		S3281000114
35 S3281000117 36 S3281000118 37 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		
36 S3281000118 37 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		S3281000116
37 S3281000119 38 S3281000120 39 S3281000121 40 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		
38 \$3281000120 39 \$3281000121 40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		S3281000118
39 S3281000121 40 S3281000122 41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130	37	
40 \$3281000122 41 \$3281000123 42 \$3281000124 43 \$3281000125 44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		
41 S3281000123 42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		
42 S3281000124 43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		
43 S3281000125 44 S3281000126 45 S3281000127 46 S3281000128 47 S3281000129 48 S3281000130		
44 \$3281000126 45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		
45 \$3281000127 46 \$3281000128 47 \$3281000129 48 \$3281000130		
46 S3281000128 47 S3281000129 48 S3281000130		
47 S3281000129 48 S3281000130		
48 S3281000130		
	49	
50 S3281000132	50	53281000132

51 52 53	S3281000133 S3281000134
52	
	C2201000124
53	33201000134
	S3281000135
54	S3281000136
55	S3281000137
56	S3281000138
57	S3281000139
58	S3281000140
59	S3281000141
60	S3281000142
61	S3292500001
62	S3292500002
63	S3292500003
64	S3292500004
65	S3292500005
66	S3292500006
67	S3292500007
68	S3292500008
69	S3292500009
70	S3292500010
71	S3292500011
72	S3292500012
73	S3292500013
74	S3292500014
75	S3292500015
76	S3292500016
77	S3292500017
78	S3292500018
79	S3292500019
80	S3292500021
81	S3292500022
82	S3292500024
83	S3292500025
84	S3292500026
85	S3292500027
86	S3292500030



PAGE: 5/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

NA: TOTAL 254

10110					
1	S3280700002	51	S3281000017	101	S3281000069
2	S3280700003	52	S3281000018	102	S3281000070
3	S3280700004	53	S3281000019	103	S3281000071
4	S3280700005	54	S3281000020	104	S3281000072
5	S3280700006	55	S3281000021	105	S3281000072
6	S3280700007	56	S3281000021	106	S3281000074
7	S3280700008	57	S3281000023	107	S3281000075
8	S3280700009	58	S3281000024	108	S3281000076
9	S3280700010	59	S3281000025	109	S3281000077
10	S3280700011	60	S3281000026	110	S3281000078
11	S3280700012	61	S3281000027	111	S3281000079
12	S3280700013	62	S3281000028	112	S3281000080
13	S3280700014	63	S3281000029	113	S3281000081
14	S3280700015	64	S3281000030	114	S3281000083
15	S3280700016	65	S3281000031	115	S3281000084
16	S3280700017	66	S3281000032	116	S3281000085
17	S3280700018	67	S3281000033	117	S3281000086
18	S3280700019	68	S3281000034	118	S3281000087
19	S3280700020	69	S3281000035	119	S3281000088
20	S3280700021	70	S3281000036	120	S3281000089
21	S3280700022	71	S3281000038	121	S3281000090
22	S3280700023	72	S3281000039	122	S3281000092
23	S3280700046	73	S3281000040	123	S3281000093
24	S3280700047	74	S3281000041	124	S3281000094
25	S3280700048	75	S3281000042	125	S3281000095
26	S3280700049	76	S3281000043	126	S3281000096
27	S3280700050	77	S3281000044	127	S3281000097
28	S3280700051	78	S3281000045	128	S3281000099
29	S3280700052	79	S3281000046	129	S3281000100
30	S3280800001	80	S3281000047	130	S3281000101
31	S3280800002	81	S3281000048	131	S3281000102
32	S3280800003	82	S3281000049	132	S3281000103
33	S3280800004	83	S3281000050	133	S3281000104
34	S3280800005	84	S3281000051	134	S3281000178
35	S3280800006	85	S3281000052	135	S3281000179
36	S3281000001	86	S3281000053	136	S3286000001
37	S3281000002	87	S3281000054	137	S3286000002
38	S3281000003	88	S3281000055	138	S3286000003
39	S3281000004	89	S3281000056	139	S3286000005
40	S3281000005	90	S3281000057	140	S3286000006
41	S3281000007	91	S3281000058	141	S3286000007
42	S3281000008	92	S3281000059	142	S3286000008
43	S3281000009	93	S3281000060	143	S3286000009
44	S3281000010	94	S3281000061	144	S3286000010
45	S3281000011	95	S3281000062	145	S3286000011
46	S3281000012	96	S3281000063	146	S3286000012
47	S3281000013	97	S3281000064	147	S3286000013
48	S3281000014	98	S3281000065	148	S3286000014
49	S3281000015	99	S3281000067	149	S3286000015
50	S3281000016	100	S3281000068	150	S3286000016
				<u> </u>	

PAGE: 6/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

454	00000000047
151	S3286000017
152	S3286000018
153	S3286000019
154	S3286000020
155	S3286000021
156	S3286000022
157	S3286000023
158	S3286000024
159	S3286000025
160	S3286000026
161	S3286000027
162	S3286000028
163	S3286000029
164	S3286000030
165	S3286000031
166	S3286000032
167	S3286000033
168	S3286000034
169	S3286000035
170	S3286000036
171	S3286000037
172	S3286000038
173	S3286000039
174	S3286000040
175	S3286000041
176	S3286000042
177	S3286000043
178	S3286000044
179	S3286000045
180	S3286000046
181	S3286000047
182	S3286000048
183	S3286000049
184	S3286000050
185	S3294900001
186	S3294900002
187	S3294900003
188	S3294900004
189	S3294900005
190	S3294900006
191	S3294900007
192	S3294900007
193	S3294900009
194	S3294900010
195	S3294900010
196	S3294900011 S3294900012
197	S3294900012 S3294900013
198	S3294900013 S3294900014
199	S3294900014 S3294900015
200	S3294900015 S3294900016
200	0020 1 300010

201	S3294900017
202	S3294900018
203	S3294900019
204	S3294900020
205	S3294900021
206	S3294900022
207	S3294900023
208	S3294900024
209	S3294900025
210	S3294900026
211	S3294900027
212	S3294900028
213	S3294900029
214	S3294900030
215	S3294900031
216	S3294900032
217	S3294900032
218	S3294900034
219	S3294900035
220	S3294900036
221	S3294900037
222	S3294900038
223	S3294900039
224	S3294900040
225	S3294900041
226	S3294900042
227	S3294900043
228	S3294900044
229	S3294900045
230	S3294900046
231	S3294900047
232	S3294900048
233	S3294900049
234	S3294900049 S3294900050
235	S3294900051
236	S3294900052
237	S3294900053
238	S3294900054
239	S3294900055
240	S3294900056
241	S3294900057
242	S3294900058
243	S3294900059
244	S3294900060
245	S3294900061
246	S3294900062
247	S3294900064
248	S3294900066
249	S3294900067
250	S3294900067 S3294900068
230	33234300000

251	S3281000082
	S3281000091
253	S3281000098
254	S3281000143

Technical Bulletin

PAGE: 7/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Contents

- * Procedure for Modifying the Oil Tank Filter (p 7)
- * Procedure for Adding the Fusing Knob (p24)
- * Procedure for Adding the Fusing Knob for Units without the "Two M4 Tap Holes" on the End-face of the Hot Roller (Units that have not been modified previously.) (p 26)
- * Attaching the Tray 1 Guide Sheet (p31)
- * Replacing the Rubber Roller in the Toner Recycling Unit (p 32)

1. Procedure for Modifying the Oil Tank Filter



CAUTION

- * Wipe off immediately any silicone oil spilt outside the machine.

 Make sure to completely wipe off spillage of silicone oil on the floor to prevent a slippery surface that may cause injuries.
- * The fusing unit has a high temperature and may cause burn injuries. Make sure the fusing unit is cool when installing/de-installing.



"Nuts and Bolts"

Oil adhesion may be found in the bottom part of the fusing unit. If found, please clean off the adhered oil when installing/de-installing. Also, to prevent oil adhesion on the floor, please prepare something such as a cloth when placing the unit on the floor.

STEP 1

Removing the Fusing Unit

(1) Peel off the tapes on the front-right/front-left doors. [diag.1-1.] **Proceed to the following step if tapes have been removed in advance.**



diag. 1-1. Tapes A


(2) Open the front-right/front-left doors.

PAGE: 8/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(3) Pull out the Fusing Paper Exit Unit. [diag. 1-2.]



Fusing Paper Exit Unit diag.1-2. Fusing Paper Exit Unit

(4) Peel off the tapes on both the Fusing Paper Exit Unit and the Fusing Unit. [diag. 1-3.] **Proceed to the following step if tapes have been removed in advance.**





diag. 1-3. Tapes B

(5) Remove 1 mounting screw on the Fusing Unit. [diag. 1-4.]



diag. 1-4. Mounting Screw on Fusing Unit



PAGE: 9/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(6) Grip the handle and remove the Fusing Unit. [diag. 1-5.]



CAUTION: 2 PERSONS ARE REQUIRED FOR REMOVING THE FUSING UNIT.

Handle




Fusing Unit

diag. 1-5. Handle on Fusing Unit

STEP 2

Removing the Fusing Paper Exit Unit

(1) Remove 2 screws on the Slide Rails. [diag. 2-1.]





Slide Rail

Slide Rail

diag. 2-1. Mounting Screws on Fusing Paper Exit Unit

Technical Bulletin


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(2) Lift up and remove the Fusing Paper Exit Unit from the Slide Rails. [diag. 2-2.]



CAUTION: 2 PERSONS REQUIRED FOR REMOVING THE FUSING PAPER EXIT UNIT.









PAGE: 10/44

Hold here when removing the unit.

Front Cover

diag. 2-2. Removing the Fusing Paper Exit Unit


STEP 3

Removing the Bottom Cover of the Fusing Paper Exit Unit

(1) Remove 5 mounting screws on the Front Cover. [diag. 3-1.]



(2) Remove 3 mounting screws on the Bottom Cover of the Fusing Paper Exit Unit. [diag. 3-2.]



diag. 3-2. Mounting Screws on Bottom Cover of Fusing Paper Exit Unit

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(3) Lift up the front end of the Fusing Paper Exit Unit Bottom Cover and disconnect the Fan Connector. [diag. 3-3.]



diag. 3-3. Disconnecting the Fan Connector

Bottom Cover of Fusing Paper Exit Unit (steel plate)

* Lift up the cover slightly to avoid damage to the fan connector.

PAGE: 11/44

(4) Remove the Bottom Cover of the Fusing Paper Exit Unit.

STEP 4

Removing the Current Oil Tank

(1) Remove the Snap Ring from the top left corner of the front-left door, lift up the door, *and remove it*. [diag. 4-1.]



diag. 4-1 Snap Ring on front-left door

(2) Remove 4 mounting screws on the Oil Tank Front Cover and remove the Oil Tank Front Cover. [diag. 4-2.]

* Dispose of the Oil Tank Front Cover.



diag. 4-2. Removing the Oil Tank Front Cover




PAGE: 12/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(3) Unfasten 2 mounting screws on the Pump Cover located behind the Oil Tank, and remove the Pump Cover.

[diag. 4-3.]




diag. 4-3. Removing the Pump Cover

(4) Unfasten 2 Tube Clips from the ends of the tube, and remove the tube. [diag. 4-4.]



Nuts and Bolts: Silicone oil could spill from the tube. Please prepare paper towels before you remove the tube.



Diag. 4-4. Removing the Tube

PAGE: 13/44

Reissued:24-Apr-09


Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(5) Pull out the Oil Collecting Tube from the Oil Tank, and remove 2 Pump Connectors and the Oil End Sensor.

The tube will not be reused because a NEW tube will be applied in (9). [diag. 4-5.]



Nuts and Bolts: Silicone oil could spill from the tube. Please prepare paper towels before you remove the tube.



diag. 4-5. Removing the Oil Collecting Tube and the Connector

(6) Unfasten the harness from the clamp. [diag. 4-6.]



diag. 4-6. Unfastening the Harness

(7) Remove 1 mounting screw from the Oil Tank Box, and pull out the Oil Tank towards the front. [diag. 4-7.]



diag. 4-7. Removing the Oil Tank




IIETIN PAGE: 14/44

Reissued:24-Apr-09


Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(8) Remove 2 mounting screws from the Upper Oil Tank Stand, and pull out the Upper Oil Tank Stand towards the front. [diag. 4-8.]



diag. 4-8. Removing the Upper Oil Tank Stand

(9) Install a NEW Oil Collecting Tube (D0167924). [diag. 4-9.]



diag. 4-9. New Oil Collecting Tube

(10) If oil is deteriorated (white colored and unclear), please change the oil by applying the parts included in MODIFICATION KIT: C OIL TANK.

^{*} Do NOT use deteriorated oil, because the whitening indicates the presence of calcium carbonate.

Technical Bulletin

PAGE: 15/44

Reissued:24-Apr-09


Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

STEP 5

Attaching the Filter to the Oil Tank

(1) Remove the following parts from the current oil tank removed in the previous section. [diag.5-1.] The removed Packing, Pumps, Oil End Sensor, and Oil End Sensor Retaining Parts "A/B" will be reused to assemble the Filtered Oil Tank in the following step.

- 2 sets of Pumps ("A "in the following diag.), 2 Screws ("102" in the following diag.)
- Oil End Sensor ("13" in the following diag.) * remove by rotating
- Oil End Sensor Retaining Parts "A" ("12" in the following diag.) & "B" ("27" in the following diag.), 2 Screws ("101" & 102" in the following diag.)
- Oil Tank Upper Cover ("B" in the lower-left diag.), 7 Screws ("B" in the lower-left diag.) Setting the Packing ("C" in the following diagram).
- * Dispose of the Oil Tank Upper Cover.



diag. 5-1. Removing the current Oil Tank Upper Cover

Technical Bulletin


PAGE: 16/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(2) Install the following parts in the Oil Tank.


- Packing [diag. 5-2-a]
- * If modification is performed using the MODIFICATION KIT: C, please replace with the NEW Packing included in the kit.
- * Make sure the packing has no twists and will not drop off.



* Make sure the packing is securely attached when setting the cover.

diag. 5-2-a. Setting the Packing

- Used Developer Holder (NEW) (04504010N; tapping screw; M4x10; x2)
- Oil Tank Upper Cover (NEW) (04504010N; tapping screw; M4x10; x5) [diag. 5-2-b]



diag. 5-2-b. Attaching the Tank Cover and Holder

Used Developer Holder D0164403 (NEW)

> Cover Oil Tank D0164432 (NEW)


PAGE: 17/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a


• 2 Sets of Pumps (*Re-use*) (04504010N; tapping screw; M4x10; 1 each, x2) [diag. 5-2-c] * *Make sure that the slants on the tube-cut-offs face the front.*

Install the tubes in the oil tank so that the cut offs (45-degree angle) face the front as shown below.



Slanted Cut Offs (45-degree angle) diag. 5-2-c. Setting the Pumps

Oil End Sensor Retaining Part "A" (Re-use) (04504010N;tapping screw; M4x10; x1) [diag. 5-2-d]




Oil End Sensor Retaining Part "A" (diag. 5-1. "12") (RE-USED)

diag. 5-2-d. Attaching the Retaining Part "A"

- Oil End Sensor/Oil End Sensor Retaining Part "B" (Re-use) (04514008N: tapping screw; 4x8; x1)
- Slip the Oil End Sensor Harness through the rear.

Oil End Sensor Retaining Part "B" (diag. 5-1. "27") (RE-USED)



diag. 5-2-e. Attaching the Retaining Part "B"



PAGE: 18/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(3) Prepare a NEW Case: Filter: Adhesion (D0164412). [diag. 5-3.]



Case:Filter:Adhesion D0164412 (NEW)


diag. 5-3. NEW Filter Case

(4) Place Filter Case (NEW) and Oil Tank Cover (NEW) on the Oil Tank and fasten with 3 mounting screws.

[diag. 5-4.]

Screw for A : 04504010N; tapping screw M4x10; x1 (NEW)
 Screws for B&C : 04504012N; tapping screw 4x12; x1 each (NEW)

Oil Tank Cover D0164400 (NEW)



diag. 5-4. Assembling the new Oil Tank Filter

PAGE: 19/44 Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

STEP 6

Installing the Oil Tank

(1) Remove 1 clamp (11050488; locking wire saddle; LWS-1211Z) and 2 tapping screws (04514008N; tapping screw; 4x8) from the former Upper Oil Tank Stand and reuse them to assemble the NEW Upper Oil Tank Stand (D0164319). Do NOT fasten screws completely at this stage. [diag.6-1.]

* Dispose of the former Oil Tank Stand.

11050488 Clamp: LWS-1211Z (Re-use)





diag. 6-1. New Upper Oil Tank Stand (D0164319)

(2) Insert the new Upper Oil Tank Stand into the mainframe and fasten 1 mounting screw (04514008N; tapping screw; 4x8) Re-use the screw removed in step 4 (8) [diag. 6-2.]





diag. 6-2. Assembling the new Upper Oil Tank Stand

(3) Insert the Filtered Oil Tank into the mainframe and fasten 1 mounting screw (04514008N; tapping screw; 4x8) Re-use the screw removed in STEP4 (7) [diag. 6-3.]





diag. 6-3. Assembling the Filtered Oil Tank

Technical Bulletin

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(4) Fasten 2 screws (04514008N; tapping screw; 4x8) to the stopper that connects the Upper Tank Stand and the mainframe. Reuse 1 screw removed in step 4 (8) and 1 NEW screw included in the kit.

[diag.6-4.]



Stopper *D0164158* (*NEW*)

PAGE: 20/44

- (5) Attach the following connectors and tubes. [diag. 6-5.]
 - Insert the Pump Connectors (2 locations) and the Oil End Sensor.
 Fasten the feeder harness to the clamp attached in "STEP 6. (1)."
 - Insert the Oil Collecting Tube all the way in into the *Used Developer Holder*.
 - Attach the Oil Supplying Tubes (2 locations).
 Slip the Oil Supplying Tube behind the Oil Collecting Tube.
 Attach clips to hold the tubes to the pump.



diag. 6-5. Attaching Connector and Tube




PAGE: 21/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(6) Attach the Decal (G1787901: Warning; Electrical: Pump) (NEW) to the Pump Cover (NEW). [diag. 6-6.]



(7) Attach the Pump Cover and completely fasten the screw attached in step 6-(1)." [diag. 6-7]



diag. 6-7. Attaching the Pump Cover



PAGE: 22/44


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(8) Attach the following Decals (NEW) to Cover:OilSupplySub-Unit (NEW).. [diag. 6-8]


· G1785077 Decal: E

G1784217 Decal: Oil: Overflow: Oil Tank
 D0164266 Cover: Oil Supply Sub-Unit



diag. 6-8. Attaching Decals

(9) Fasten the Oil Tank Front Cover *(Cover:OilSuppplySub-unit)* with 4 mounting screws (04514008N; tapping screw; 4x8). *Reuse the screws removed in step 4-(2).* [diag. 6-9.]



diag. 6-9. Attaching the Oil Tank Front Cover



Model: Aegis-P1

Technical Bulletin

PAGE: 23/44 Reissued:24-Apr-09


Procedure for North American & European Machines

7. Attaching the Oil Supply Decal

Attach the Decal (G1784313: Oil Supply Sub-unit: Design Sketch) to the front of the Bottom Oil Tank Filter drawer. [diag. 7-1.]

Date: 24-Mar-09

No.: RG178042a



diag. 7-1. Attaching the Decal

8. Re-attaching the Removed Parts

Follow the steps in reverse order to re-attach removed parts.

- Door Front Left (54472681 Snap Ring: x1)
- Fusing Unit Bottom Cover (a connector is connected, 04514008N; tapping screw: 4x8; x3)
- Front Cover (04514008N; tapping screw: 4x8, x5)
- Fusing Exit Unit (G1784909; screw; Transport; x2)
- Fusing Unit (B2342390; Flanged Hexagonal Head Bolt: M4x8)
- Tapes (Front Door Left/Right x5, Fusing Paper Exit Unit x2)

This completes the installation of the Oil Tank Filter.

Technical Bulletin

Reissued:24-Apr-09


Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

2-1. Procedure for Adding the Fusing Knob


NOTE

Before moving on to the following procedure, please refer to "2.2. Procedure for Front-Left Door Modification and Decal Attachment following the Addition of Fusing Knob" because the front door must be removed in advance.

Procedure for Modifying the Fusing Unit




Remove inner front cover (3 screws)
Tapping Screw: M4 x 8 [04544008Q]
* These screws will be Re-used.




PAGE: 24/44

2 M4 tap holes on end-face of Hot Roller



Clamp Plate: Knob: Hot Roller: Apply plate by adjusting crimp hole and tap hole. No alignment relation between 2 tap holes and elongate hole/roundhole.

(elongate hole on left, round hole on right)





Fasten 2 M4 × 8 screws.
Fasten elongate hole first. (left in diagram [3])
Tapping Screws: M4 × 8
[03604008N] (2 screws newly added)




Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a







PAGE: 25/44

Insert knob to shaft and fasten screw into shaft. [09544008N] Screw: M4 x 8 (NEW)

NOTE

When modifying a fusing unit HAVING the two tap holes, the following parts in the kit will remain unused. However, as these parts could be applied when replacing the Hot Roller or the Fusing Unit, please keep them stored at the customer's site.

03604008N Screw: M4x8

05440080E Setscrew: M4x8

D0164097 Base Knob: Hot Roller

D0164092 Stay: Shaft: Knob: Hot Roller: 4 Hole


Technical Bulletin


PAGE: 26/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Modification Procedure for Units without the "Two M4 Tap Holes" on the End-face of the Hot Roller (Units that have not been modified previously.)








Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Replacing the Screws for Guide:Paper Exit Sub-unit:Upper

Remove screw M4x8 (03604008N) and exchange with screw M4x8 (0954 4008N) (NEW).





PAGE: 27/44



PAGE: 28/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a


2.2. Procedure for Front-Left Door Modification and Decal Attachment following the Addition of the Fusing Knob

STEP 1 - Modifying the Front-Left Door

(1) Remove the Snap Ring from the top left corner of the front-left door, lift up the door and remove it. [diag. 1]



(2) Remove the front-left door inner Supporting Board (screw x11), Bracket: Door Catch (metal plate x2, screw x2), Lever-Safety Switch (molded part x1, screw x1) from the front-left door. [diag. 2]



diag. 2

(3) Attach the front-left door inner Supporting Board (G1781559 **NEW**) (hole found in the center) (screw x11), Bracket: Door Catch (metal plate x2, screw x2), Lever-Safety Switch (molded part x1, screw x1) by following the reverse order of previous step.




PAGE: 29/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

(4) Attach Holder:Sheet:Fusing:Ass'y (G1781580) to the inner side of the front-left door. [diag. 3]




Guide for G1781580 Holder:Sheet: Fusing:Ass'y Attachment Position

- Vertical position: attach so that "1" contacts "2" and is aligned with the rib (0-1 mm)
- Horizontal position: attach so that "3" contacts "4" and is aligned with the side of supporting board (0-1 mm)
 - (5) Re-attach the front-left door following the reverse order of step 1- (1).

Procedure exclusively for NA and EU Machines

Attach G1787912 Decal: Oil Supply to the inner side of the front-left door. [diag. 4]






PAGE: 30/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a


STEP 2 - Attaching the Decal

(1) Attach the **NEW** Decal (D0164032) on top of Decal:Main:Pick-up Paper Jam (G1781074) as shown below. [diag. 5]



diag. 5

(2) Attach **Decal Grip: Open and Close D4 (G1785083)** onto Paper Exit Unit Release Grip: Vertical Transport (B2346424B) attached to the left-hand side. Place the decal so that it overlaps Decal:Grip:Open and Close:D3 (G1785079). [diag. 6]






PAGE: 31/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

3. Attaching the Tray 1 Guide Sheet

- 1. Apply alcohol to clean the surface of Side Plate Side (B2346667) of the Tandem LCT Unit Right DOM (B2346610).
- 2. Attach Guide:Sheet:FeedTray (G1782979) (NEW) to a position 137.5 mm from the plate edge; the crease on the sheet should correspond to the slanted edge of the Side Plate Side (B2346667).






PAGE: 32/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

- 4. Replacing the Rubber Roller in the Toner Recycling Unit
- 1. Remove 3 screws and remove the molded plate by lifting it up.




Technical Bulletin


PAGE: 33/44 Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

2. Remove 4 screws and open the rear cover.



3. Remove 3 connectors, 2 clamps, and ground wire.




Technical Bulletin

PAGE: 34/44


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

4. Remove the following 8 screws.



5. Remove 3 clamps and 2 connectors.






PAGE: 35/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

6. Open out the boards.



7. Prevent waste toner from pouring out.



Technical Bulletin

PAGE: 36/44


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

Move on to STEP 8 if a special tool (ratchet or short screw-driver) is available. Move on to STEP 18 if a special tool (ratchet or short screw-driver) is not available.

8. Remove 7 screws.





9. Remove the cover. Be careful of toner scattering.




Technical Bulletin


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

10. Release the bottom end of the spring, and remove the plate.



11. Remove the plate, and clean both plate and duct cover.





PAGE: 37/44

Technical Bulletin

PAGE: 38/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

12. Remove the rubber from the roller and replace it with *G1787818 Waste Toner Duct Rubber Roller (NEW)*.



13. Attach the spring to the plate, and reattach the plate to the duct.




PAGE: 39/44

Reissued:24-Apr-09


Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

14. Attach the spring.



* Use a spring hook or pliers.

15. Replacing the Cover *Make sure the spring is set correctly.



Technical Bulletin


PAGE: 40/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

16. Fasten the screws (x7). First, fasten the screw circled in pink.





17. REASSEMBLY

- 1. Remove the toner pour-out prevention cover.
- 2. Close the boards. [Fasten clamps (x3) and connectors (x2)]
 - * The connectors not mentioned above should be checked as well. Ensure that they are connected correctly.
- 3. Fasten screws (x8) to reattach the boards.
- 4. Set connectors (x3), clamps (x2), and ground wire.
- 5. Reattach the rear unit cover.

Technical Bulletin

PAGE: 41/44


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a


NOTE:

The following procedure is a continuation from "7". Apply only if a <u>special tool</u> is NOT available.

18. Remove the unit by removing 4 screws.



19. Remove 2 connectors and 3 screws, and remove the motor holder.




Technical Bulletin

Reissued:24-Apr-09

Model: Aegis-P1 No.: RG178042a Date: 24-Mar-09

20. Remove 7 screws and remove the duct cover.



21. Remove the plate, and clean both plate and duct cover.

Use a vacuum cleaner to get rid of waste toner.

* Be careful not to lose the spring.





PAGE: 42/44

Technical Bulletin

PAGE: 43/44

Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

22. Remove the rubber from the roller, and replace it with *G1787818 Waste Toner Duct Rubber Roller (NEW)*.



23. Reattach the plate to the duct.



* Use a spring hook or pliers.



Make sure to hook the spring.

Technical Bulletin


Reissued:24-Apr-09

Model: Aegis-P1 Date: 24-Mar-09 No.: RG178042a

24. Reattach the cover to the duct.

* Set the marked rib of the duct cover into the folded-up edge of the plate.

* Be careful not to drop and lose the spring.




PAGE: 44/44

25. Fasten the screws on the cover and attach it to the mainframe.

- Follow the disassembly steps in reverse order to reassemble the machine.
- Be careful of the following 2 locations when reassembling.
- Before reassembling, make sure the connectors that haven't been disconnected during this procedure are also connected correctly.



* harness clamp located right below the motor holder



* feet of the harness clamp

Technical Bulletin

PAGE: 1/4

Model: Aegis-P1 EFI Dat			te: 26-Mar-09		No.: RG178043	
Subject: Release note for System Software Version3.0 for Aegis-P1/C1 EFI					d by: T. S	Satoh
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part informa		tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 3.0 for ProC900(P1)/ProC900s(C1).

1.Newly Added Functions

-Support for New Peripherals

- · Ring Binder (ISHIKARI)
- Stacker (NAKGAWA)
- · GBC Punch
- Plockmatic

-Support for First Tab Indent

A function was added for Tab Stock printing, which allows the user to adjust the print position on the Tab by adjusting the gap between the top edge of the 1st Tab and the upper edge of the sheet.

Without this function, depending on the Tab Stock, the print position on the tab could be misaligned.

-Automatic Detecting Function of P1/C1

This function will allow the Fiery to automatically detect its connection to the engine; verifies P1 or C1 and will function accordingly.



PAGE: 2/4

Model: Aegis-P1 EFI Date: 26-Mar-09 No.: RG178043

2.Problem Solving (Countermeasures)

Following are the key problems that have been given countermeasures.

-Problems in the Field

-Problems in	<u>n the Field</u>				
Patch	Symptom	AegisP1 (G1.0)	AegisC1 (G2.0)	Support for AegisP1/C1 Peripherals (G3.0)	
1-YX34D-1	Even when recovering from PaperEnd status by refilling paper, print operation does not restart. Machine is stalled with display of 'Printing'.		Reflected	Reflected	
1-ZPVPD	Composite Patch	Reflected to Mass Production	Reflected	Reflected	
1-ZX2LD/ 1-ZX2LZ	ICC Profile includes the Aegis.	Reflected to Mass	Reflected	Reflected	
	HotFolder Utility cannot be installed independently.	Production			
1-103CJ7	Composite Patch Image defects when ripping PDF files. Error indicating excess of 'maximum number of displayable screens' on the LCD. Insufficient compression rate of the HAIC causes memory shortage on the Fiery, resulting in a SC911. Error occurs when opening a PS file created by 3rd vendor software on the Compose.	Reflected to Mass Production	Reflected	Reflected	
1-10JUV3	When printing PCL data, a letter is printed on top of another.	Reflected to Mass Production	Reflected	Reflected	
1-108MRT	Void-white lines appear when printing a PDF file.	Reflected to Mass Production	Reflected	Reflected	
1-10JE4A	Output problems with the Illustrator. (Faint color appears in the white background.)	Reflected to Mass Production	Reflected	Reflected	
1-110NIB	Printing a pdf file causes E900 to crash and SC991	Individual Patch	Reflected	Reflected	
1-10JUW8	When pausing a job for 1 hour, and restarting the same job, the display indicates 'printing' but does not restart.	Unreleased	Reflected		Patch exists but not announced to the field
1-113APJ	A completed job that has been archived remains on the HOLD tab on the display.	Patch	Reflected	Reflected	
1-11DDFY	In the Mac Driver and PC Driver, Substitute Color is only selectable with Graphic Arts Package, Premium Addition.		Unreflected		Patch exists but not announced to the field
1-10WZV0		Individual Patch	Unreflected	Reflected	
1-117SD8	Printed Page is not displayed correctly on OCP	Individual Patch	Unreflected	Reflected	
User Software	File missing on the User Software DVD for the Pro C900	Individual File	Individual File	Reflected	

Technical Bulletin

PAGE: 3/4

Model: Aegis-P1 EFI No.: RG178043 Date: 26-Mar-09

<u>-Specification Changes</u>
Cases to be reflected on supporting machines such as Aegis C1 (G2.0) and Aegis P1/C1 peripherals (G3.0); cases brought up from Aegis P1 spec changes.

No.	Cases	AegisC1	Support for
140.	54000	(G2.0)	AegisP1/C1
		(==:=,	Peripherals
			(G3.0)
1	When setting the Tray after indication of Warning Popup P2 on the display, Error	Reflected	Reflected
	Popup P3 appears.		
2	When specifying paper size in the PS Drv, 'Return Postcard' previously registered in	Reflected	Reflected
	the Paper Catalog does not appear in the list.	Deflected	Deflected
	After Rush Printing, the machine stops and indicates 'Printing' Color of the Rotary Beacon Light flashes incorrectly; 'green only' when paper is	Reflected	Reflected
4	refilled after the job enters a Paper End status.	Reflected	Reflected
5	After powering the machine, indication of Idle does not appear even after waiting for	Reflected	Reflected
3	10 min.	Reflected	Reflected
6	When 'Mismatch Action' is ON and a mismatch error occurs, the 'Beeper 8' could	Reflected	Reflected
	make a random alert noise.(number of beeps is not constant)		
7	Paper Catalog: Tray Names are incorrectly indicated on Paper/Tray Association	Reflected	Reflected
	differs from spec.		
8	In a staple job, when a specified feed tray has a defect and another tray has been	Reflected	Reflected
	selected to continue the job, the machine runs idle without the paper.		
	'Program error' could be indicated during installation of the Fiery controller.	Reflected	Reflected
	CWS: Correct indication does not appear on the CWS display during printing.	Reflected	Reflected
11	WORDING: Correct error message does not appear for jam occurrence during staple	Reflected	Reflected
	operation.		
12	When resetting the paper size to Standard on the Imposer after having been set to	Reflected	Reflected
	Customized on the CWS, the change is not reflected and output turns out in Standard.		
12	Some paper type is not indicated correctly on the German version of PS Drv.	Reflected	Reflected
	When printing in German language based environment, the term 'print amount' is	Unreflected	Reflected
14	incorrectly indicated on the activity window displayed on the MAC CWS.	Officilected	Reliected
15	When running a print on FreeForm and Impose, print position of the registration	Reflected	Reflected
.0	marker is misaligned.	1101100104	rtonoctou
16	Pagination does not appear on the German language version of MAC CWS.	Unreflected	Reflected
	CMYK value cannot be input in increment of 0.5 on the Spon-On UI of the	Reflected	Reflected
	ColorWiseProTools(CWPT).		
	KANJI: Error message appears in Roman on the Tab Insert screen on the CWS.	Unreflected	Reflected
	Minimum paper size indicated in Points differ from specification.	Unreflected	Reflected
20	Checkbox specified on the [MacFRS] Thin Media is falsely cleared when FRS is once	Unreflected	Reflected
	shut and rebooted.		
	Print cannot be made from the driver when the Inserter side cover is opened.	Unreflected	Reflected
22	An incorrect indication in the pop-up error message: 'any' is incorrectly appeared as	Unreflected	Reflected
	'Any' with an upper case 'A'.	l lange en en e	Deflected
23	When interrupting a Copy job with a Printer job by cancelling the Copy job, the Print	Unreflected	Reflected
24	operation stops. When printing in a German language based environment, indication of the term 'print	Unreflected	Deflected
24	amount' is incorrect on the activity window displayed on the MAC CWS.	Unitellected	Reflected
25	Pagination does not appear on the German language version of MAC CWS.	Unreflected	Reflected
20	i agination does not appear on the German language version of MAC CWS.	Jillellected	renected

-Symptoms involving PMO

-oyniptonis	IIIVOIVIII TIVIO				
Patch	Symptom	AegisP1 (G1.0)	AegisC1 (G2.0)	Support for AegisP1/C1 Peripherals (G3.0)	Remarks
1-119GYH	Job info is not displayed.	Unreflected	Unreflected	Reflected	

PAGE: 4/4

Model: Aegis-P1 EFI Date: 26-Mar-09 No.: RG178043

Note:

- It is necessary to update firmware of the mainframe when you update the System Software Version 3.0.
- It is necessary to update User Software: Printer Driver (Version3.0) when you update the System Software Version 3.0.

Latest firmware version:

Aegis-P1

	Program Name	Firmware No.	Version
New	System	G1786091E	2.03
New	Network Support (NCS)	G1786092C	7.03
New	Engine	G1785252E	2.000:12
		NA:G1785971B	
-	LCDC	EU:G1785972B	1.01
-	Language	G1785979	1.01
-	Web Support	G1786093C	1.01

Aegis-C1

	Program Name	Firmware No.	Version
New	System	D0166091C	1.03
New	Web Uapl	D0166095B	1.09
New	Engine	D0165252B	2.000:12
		NA:G1785975B	
New	LCDC	EU:G1785976B	1.04
-	Scanner	D0166097A	1.03
-	Language	G1785980	1.01
-	Web Support	D0166093A	1.00
-	Network Support (NCS)	D0166092A	7.03
-	Network DocBox (NFA)	D0166096A	1.01

Options

New	SR5000 Finisher	B8305102M	1.60
New	Cover Interposer Tray CI5010	B8355510E	02.070
New	Ring Binder RB5000	Main:D3925510D Sub:D3925520B	Main:1.280:04 Sub :1.050:01
New	High Capacity Stacker SK5000	1st:D3645620_P1 2nd:D3645620_P2	4.02:12
-	Booklet Finisher BK5000	B8365550B	2.17
-	Plockmatic	-	2.01

Technical Bulletin

PAGE: 1/3

Reissued: 28-Jul-10

Model: AG-P1/C1 STACKER NAKAGAWA(SK5000)	Date: 26-Mar-09	No.: RG178044c
--	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: STACKER		Prepared by: N. lida		
From: PPBG Ser	vice Planning Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical	☐ Part informa	tion	☐ Action required ☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

This RTB has been issued to announce the firmware release information for the **STACKER**.

1st STACKER

Version	Program No.	Effective Date
4.08 :15	D3645620C_P1	July 2010 production
4.07 :14	D3645620B_P1	December 2009 production
4.06 :13	D3645620A_P1	August 2009 production
4.02 :12	D3645620_P1	1st Mass production

2nd STACKER

Version	Program No.	Effective Date
4.08 :15	D3645620C_P2	July 2010 production
4.07 :14	D3645620B_P2	December 2009 production
4.06 :13	D3645620A_P2	August 2009 production
4.02 :12	D3645620_P2	1st Mass production

Version	Modified Points or Symptoms Corrected
4.08:15	After recovering from a jam in which the jammed sheet hasn't reached the
	Entrance Sensor of the Stacker, the last sheet correctly fed out is falsely
	reprinted due to a system communication error.
4.07:14	The following problems that occur under the configuration of "Aegis-P1(Creo) +
	STACKER + SR5000" have been fixed:
	- Jams occurring on the SR5000 is not notified to the mainframe.
	- When the STACKER is full and its door is opened and closed without
	removing the stack, the Creo Color Server's Workspace falsely indicates that
	the full stack has been cleared.
4.06:13	Symptoms Corrected:
	- False detection of SC621 (Finisher communication error) during a print
	operation
	- The fan remains operated when a jam occurs.
	- The fan motor of Stacker #2 is falsely operated while printing and feeding the sheets to Stacker #1.

PAGE: 2/3


Reissued: 28-Jul-10

Model: AG-P1/C1 STACKER NAKAGAWA(SK5000) Date: 26-Mar-09 No.: RG178044c

Modified Points or Symptoms Corrected Version Since the anomalies that occur on the peripherals downstream to the Stacker are not notified to the mainframe, system communication error causes the mainframe to stall. Stacker #1 does not detect errors occurring on Stacker #2. The Stacker and the peripherals downstream to the Stacker do not stop their operation even when a system communication error occurs in the upstream peripherals. Jams between the GBC and the Stacker cannot be cleared when operated in the following configuration: Aegis-P1(Creo)+ Cl5010+ZF4000+GBC+SK5000 #1+SK5000 #2+SR5000 4.02:12 1st Mass production.

When connecting two Stackers as in below, the only difference is the installing location of the firmware, which is specified from the mainframe, the same firmware is applied. Therefore, Stackers [1] and [2] can be connected either way. However, when they are to be connected in the opposite order, as in [2] [1], be sure to change the dip switch settings on the PCB.

1st stacker: Dip switch 2-1: Turn dip switch 2-1 to the "OFF" position. 2nd stacker: Dip switch 2-1: Turn dip switch 2-1 to the "ON" position.



- *When connecting the Stacker, please update below Firmware as indicated.
- * Please make sure that ALL versions listed below are updated concurrently.

Aeais-P1

Program Name	Program No.	Version
System	G1786091E	2.03
Network Support(NCS)	G1786092C	7.03
Engine	G1785252E	2.000:12
LCDC	NA:G1785971B	1.01
Language	G1785979	1.01
Websystem	G1786093C	1.01
Fiery Server	_	3.0

Aegis-C1

Technical Bulletin

PAGE: 3/3

Reissued: 28-Jul-10

Model: AG-P1/C1 STACKER NAKAGAWA(SK5000)	Date: 26-Mar-09	No.: RG178044c
--	-----------------	----------------

Version	Modified Points or Symptoms Corrected					
		EU:G1785976B				
	Scanner	D0166097A	1.03			
	Language	G1785980	1.01			
	Web Support	D0166093A	1.00			
	Network Support(NCS)	D0166092A	7.03			
	Network DocBox(NFA)	D0166096A	1.01			
	Fiery Server	-	3.0			

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1/C1 Da				Date: 7-Apr-09		No.: RG178045
Subject: SC35X Toner Bottle Motor Error				Prepare	d by: Mas	sahiko Kudo
From: PPBG QA	Service Planning Dept.					
Classification:		☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

SYMPTOM

SC35* occurs after exchanging the toner bottle.

SC352: Toner Bottle Motor Error: K SC353: Toner Bottle Motor Error: C SC354: Toner Bottle Motor Error: M SC355: Toner Bottle Motor Error: Y


CAUSE

When replacing with a toner bottle that has been stored for a long period of time, the toner is stiffened and causes an increase in the initial rotation torque.

*

SOLUTION

- 1) Upon machine installation and PM/EM visits, please be sure to advise the Operators to **shake** the bottle thoroughly as in the diagram below whenever installing a new toner bottle (initial machine installation, toner near-end).
- * The swinging motion should reach 90 degrees from horizontal.
- As the same symptom could occur with toner bottles installed in the machine if the machine is left unused for a long period of time, again shaking of the bottle will resolve the problem.



Technical Bulletin

PAGE: 1/1

Model: Aegis-P1/C1 Dat					9	No.: RG178046
Subject: SC524 a Long period in Lov	at Power ON when Machine is V Temp	d for	Prepare	d by: N.iid	da	
From: PPBG QA	Service Planning Dept.					
Classification:		☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
☐ Paper path ☐ Transmit/re			it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	⊠ Tier 2	

SYMPTOM

When the machine has not been used for a long period of time in a low temperature environment, SC524 (paper exit motor lock) may occur when turning on the power.

CAUSE

This symptom may occur when the Cooling Transport Belt is kept at a low temperature for a long period of time, which causes such effects as the adhesion of the belt to the roller inducing an increase in rotation load and a longer preparation time for the belt to begin its normal rotation (exceeding the roller locking detection time of 800 ms), resulting in a SC524 roller error detection.

The symptom may occur in approximately 20% of the machines if the machine was not used for 1 week in an ambient temperature of below 5 degrees Centigrade.

* The lower the temperature, and the longer the time that the machine is left unused, the higher the possibility that the symptom will occur.

Error detection will not occur if the machine power is again switched ON, as after the Cooling Transport Belt rotates, that rotation will automatically reduce its load.

TENTATIVE SOLUTION

Turn OFF the power, open the front cover, and turn the switchback paper exit unit C1 knob counterclockwise 3 times. Do the same when SC524 occurs after turning ON the machine.

PERMANENT SOLUTION

Software will be changed; the revised program will allow a longer time before detecting the paper exit motor lock.

NOTE: New firmware release is scheduled for June.


Technical Bulletin

PAGE: 1/3

Model: Aegis-P1 Date					'-09	No.: RG178052
Subject: Fusing Knob Removal Procedure					d by: N.iid	da
From: PPBG QA						
Classification:	Troubleshooting	☐ Part info	orma	tion		n required
		☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transmit/re		smit/receive [fit information
	☐ Product Safety	Other ()	☐ Tier 2	

The fusing knob is newly added to the fusing unit of the AG-C1 (D016) and P1 (G178). As a result, a new fusing unit as a replacement part has the fusing knob, but a specific modification is required to install the fusing unit with the fusing knob in the machines which do not have the new *Inner Supporting Board (G1781559) [A]* of the front left door as shown below ([B] is an old inner supporting board).

If the target machine does not have the inner supporting board [A], remove the fusing knob from a new fusing unit to install it in the target machine.



Perform the AG field modification (see the latest version of RTB 42) on any machine which does not have the fusing knob on the fusing unit.



Model: Aegis-P1 Date: 27-May-09 No.: RG178052

Fusing Knob Removal Procedure




CAUTION


- Wipe off immediately of any silicone oil spilt outside of the machine.
 Make sure to completely wipe off spillage of silicone oil on the floor to prevent slippery surface that may cause injuries.
- The fusing unit has a high temperature and may cause burn injuries. Make sure the fusing unit is cool when installing/removing.



Point

Oil adhesion can be found in the bottom part of the fusing unit. If found, please clean off the adhered oil when installing/removing. Also, to prevent oil adhesion on the floor, please prepare something such as cloths when placing the unit on the floor.






g178t534

PAGE: 2/3

- 1. Remove the fusing knob [A] from the new fusing unit (screw x 1).
- 2. Remove the fusing front cover [B] of the new fusing unit (screw x 3).




g1/8t535

- 3. Remove the fusing knob shaft [C] (screw x 2).
- 4. Remove the fusing front cover (no hole) from the old fusing unit in the machine.



PAGE: 3/3

Model: Aegis-P1 Date: 27-May-09 No.: RG178052



- 5. Attach the fusing front cover [D] without a hole (removed in step 4) to the new fusing unit (screw x 3).
- 6. Replace the old fusing unit with the new fusing unit.

		~	
K	IC	_(П

PAGE: 1/66

Model: Aegis-P1/C1 Date					09	No.: RG178053
Subject: Manua			Prepared	d by: N.iid	da	
From: PPBG QA	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	rmat	tion	☐ Action	required
		☐ Electrica	ectrical 🗵 Servi		⊠ Service	e manual revision
	☐ Paper path	☐ Transmit/red		smit/receive		fit information
	☐ Product Safety	Other ()	☐ Tier 2	

The "Troubleshooting" chapter of the service manual for the AG-C1 (D016) has been corrected in order to be updated and be used for both the copier model (D016) and printer model (G178).

- Add the following new or revised information which is shown in red text.
- On pages from 625 to 627

List of POST Codes

These are POST codes that the Fiery controller shows on the LED when the automatic diagnostics run.

Code	Test Results		Parts	to be repl	aced	
		M/B	DIMM	HDD	PSU	V/B
	(Nothing is displayed on LED.)	0	0		0	0
00h	(Normal Operation)					
C9h	Test BIOS Checksum	0	0			
11h	Initialize registers of Chipset and Super I/O	0				
28h	Autosize memory		0			
2Ah	Zero clear Base RAM1		0			
2Ch	Address line test of Base RAM		0			
2Eh	Test of Base RAM		0			
38h	Shadowing of BIOS ROM	0	0			
0Ah	Initialize CPU	0				
14h	Initialize keyboard controller	0				
69h	Initialize SMI handler	0				
49h	Initialize PCI	0				
55h	Initialize USB controller	0				
52h	Initialize keyboard	0				
4Ah	Initialize Video	0				
4Bh	Start bit map display	0				
50h	Display CPU type	0				
5Ch	Test conventional memory, display size	0	0			
60h	Test extended memory, display	0	0			

Technical Bulletin

PAGE: 2/66

Model: Aegis-P1/C1			Date: 22-Jun-09 No.: RG			No.: RG178	053
Code	Test Results			Parts	to be re	eplaced	
		M	l/B	DIMM	HDD	PSU	V/B
	size						
62h	Test extended memory address line	(0	0			
66h	Configure advanced cache registers	(0				
6Ah	Display cache memory size	(0				
84h	Initialize Super I/O	(0				
87h	Configure configurable devices of Super I/O	(0		O		O
90h	Configure IDE,ATAPI	(0		0		
98h	Initialize Option ROM	(0				
93h	Initialize APIC	(0				
9Ch	Set up Power management	(0			0	
B5h	Quit bit map display	(0				
B7h	Initialize ACPI	(0				
BDh	Display Boot Pop up menu	(0				
BFh	Display summary page	(0				
C0h	Boot with Int19h O O						
D1h	Hardware access error	Hardware access error					O
D2h	Decoder error						O
D3h	Encoder error						O
D4h	Checksum mismatch						O
D5h	Software error						O
Fxh	Fxh Fan Alarm			e Fan Aları	m list.		

O: indicates that this part needs to be replaced.

M/B: Mother Board V/B: Video Board • Note

Memory space from 0 to 4MB is called "Base RAM" and it is used by the System BIOS in POST.

On pages from 640 to 641

	en pages nem e le te e l'					
No.	Type	Details (Symptom, Possible Cause, Troubleshooting Procedures)				
240	С	LD error: Bk				
241	С	LD error: C				
242	С	LD error: M				
243	С	LD error: Y				
-	-	The IPU detects excessive current (100 mA or more) while the LDB unit				
		is firing.				
		 Poor connection between laser unit and IPU 				
		 Poor connection around PSU-G and FIB 				
		■ Worn-out LD				
		Defective LD board				

Technical Bulletin

PAGE: 3/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

No.	Type	Details (Symptom, Possible Cause, Troubleshooting Procedures)
		Check the harness connection (laser unit and IPU).
		2. Check the harness connection of PSU-G and FIB
		3. Replace the laser unit.

On pages from 647 to 648

• On pages nom 647 to 648			
No.	Type	Details (Symptom, Possible Cause, Troubleshooting Procedures)	
332	D	Toner supply error: K	
333	D	Toner supply error: C	
334	D	Toner supply error: M	
335	D	Toner supply error: Y	
-	-	The machine fails the toner filling up for a color after the toner	
		end sensor detected "Toner Empty".	
		 Toner condensation in the toner bottle 	
		 Toner stuck in the toner supply tube 	
		Bent toner supply tube	
		Defective toner pump	
		Defective toner bottle motor	
		Straighten the toner supply tube.	
		2. Replace the toner pump.	
		3. Replace the toner bottle motor, and then execute SP2-253-	
		xxx. (-001: K, -002: C, -003: M, -004: Y, -005: YMC, -006: All	
		colors)	
		When executing SP2-253-xxx, make sure of the following conditions;	
		First, turn the machine off and on after opening the front left or right door.	
		Make sure that the target color toner bottle is installed	
		and the toner hopper cover is closed.	
		Enter the SP mode, and then execute SP2-253-xxx.	

On pages from 686 to 687

No.	Туре	Details (Symptom, Possible Cause, Troubleshooting Procedures)
503	В	Tray 3 (A4 LCT) feed error (G178 only)
504	В	Tray 4 (A4 LCT) feed error (G178 only)
505	В	Tray 5 (A4 LCT) feed error (G178 only)



PAGE: 4/66 Date: 22-Jun-09 No.: RG178053

Model:	Aegis-P	1/C1	Date: 22-Jun-09	No.: RG178053
No.	Type	Details (Symptom, Possible	Cause, Troubleshooti	ng Procedures)
		One of the following conditions it LCT: The tray 3, 4 or 5 lift sensor or 5 lift motor turned on. Upper limit is not detected we during paper feed. The tray 3, 4 or 5 lift sensor in placed in the machine	s not activated for 10 sithin 10 s while the pa	s after the tray 3, 4 per tray is lifting
		 Poor connection or defective Poor connection or defective Remaining paper or another motor. Pick-up solenoid 3, 4 or 5 co Pick-up solenoid 3, 4 or 5 is Replace the tray 3, 4 or 5 lift 	tray 3, 4 or 5 lift sense obstruction has stopped nnector is loose. blocked by an obstruction motor.	or ed the tray and
		2. Replace the tray 3, 4 or 5 lift3. Check or clear obstacles are		3, 4, or 5.

On page 719

<u> </u>	age i	
No.	Type	Details (Symptom, Possible Cause, Troubleshooting Procedures)
SC601	В	Communication Error between BCU and MCU (D016 only)
		One or more of the following occurred:
		 The BCU cannot communicate with the MCU (LCT-MF) within
		100 ms after power on after 3 tries.
		 A BREAK signal was detected after connection between the
		BCU and MCU.
		 After a communication error, three tries to communicate with
		the MCU failed.
		 Poor connection between BCU and MCU
		 BCU defective
		 MCU defective
		1. Check or replace the harness between the BCU and MCU.
		2. Replace the BCU.
		3. Replace the MCU in the LCT-MF.

No.	Type	Details (Symptom, Possible Cause, Troubleshooting Procedures)
SC620	В	ADF Communication Error (D016 only)
		No reponse from the ADF to the ACK signal issued by the IPU.
		 Poor connection between the IPU and ADF
		 Electrical noise interfering with communication between
		electrical components
		 ADF cable or connector loose, broken, defective
		 ADF defective
		IPU defective



Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 5/66

- 1. Check or replace the cable between IPU and ADF.
- Replace the ADF.
 Replace the IPU.




PAGE: 6/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

On page 796

Paper Path from the LCT-MF or Optional LCT

1. Open the front left door of the LCT-MF.



g178r838


On pages from 797 to 798

Color Spots

If color spots occur on outputs, print out 150 to 200 copies of a test pattern (SP2109-002) with a full coverage image.

For Printer G178

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" with SP2109-002.
- 3. Select all colors (YMCK) with SP2-109-004 as shown below.



g178r691

"0": Not selected, "1": Selected

- [1] for "Black". Press the "3" key on the operation panel if you want to select this color.
- [2] for **"Cyan"**. Press the **"2"** key on the operation panel if you want to select this color.
- [3] for **"Magenta"**. Press the **"1"** key on the operation panel if you want to select this color.
- [4] for **"Yellow"**. Press the **"0"** key on the operation panel if you want to select this color.

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 7/66

- 4. Press the "APL Window" button to enter the copy screen.
- 5. Print a test pattern (150 to 200 sheets) from a PC.
- 6. Check the outputs if the problem is solved. If not, try this procedure again.
- 7. Exit the SP mode after the machine has completed printing.

For Copier D016

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" with SP2109-002.
- 3. Press the "APL Window" button to enter the copy screen.
- 4. Input a number of pages from 150 to 200 with the numeric keys, and then select "Full Color" mode.
- 5. Press the "Start" key on the operation panel.
- 6. Exit the SP mode after the machine has completed printing.
- After page 800, the following troubleshooting is newly added.

Vertical White Line

Vertical white line may occur due to various reasons. This section shows how to decide cause of a vertical white line and solve the vertical white line problem.

Decision Flow

Check the following points, and then see each counter measure.

- 1. A problem output is half-tone image and has a white line at 314 mm interval.
 - Yes: See "1. Countermeasure for Drum Problem" described below.
 - No: Go to next check point.
- 2. Print out a same image which has caused a white line problem again after the white line problem has occurred on outputs.
 - Problem is solved: See "2. Countermeasure for VL Error Problem" described below.
 - Problem is not solved: Go to next check point.
- 3. Print out a same image which has caused a white line problem again after the manual oil removal mode has been done with SP3-309-010.
 - Problem is solved: See "3. Countermeasure for ITB Dirty due to Fusing Oil" described below.
 - Problem is not solved: Go to next check point.
- 4. Print out a same image which has caused a white line problem again after the clear blurred image has been done with SP2-810-001.
 - Problem is solved: See "1. Countermeasure for Drum Problem" described below.
 - Problem is not solved: See "4. Countermeasure for Fusing Belt Error" described below.

1. Countermeasure for Drum Problem

Symptom

Technical Bulletin

PAGE: 8/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

- White line occurs on outputs at 314 mm interval.
- Problem point differs or problem does not occur depending on which color (YMCK) is used.

Possible Cause

Charge error due to adhered NOx on the drum surface

Countermeasure

1. Execute "Exe Oil removal" (SP3-309-010) first, and then "Clear blurred img" (SP2-810-001).

2. Countermeasure for VL Error Problem

Symptom

- White line occurred on outputs is thick.
- Problem point differs or problem does not occur depending on which color (YMCK) is used.

Possible Cause

VL value increases due to the low capacity area on the drum surface, and then this
causes low toner density on outputs. (A low capacity area on the drum surface tends to
be caused by the multiple printing (20 outputs or more) of a same image.)

Countermeasure

- 1. Do not send two jobs at the same time to the machine if a first job is the multiple printing (20 outputs or more) of a same image. Send a job causing the image problem after multiple printing job of a same image has been finished.
- 2. Insert a white image job between the multiple printing job (20 outputs or more) of a same image and the job causing an image problem.
- 3. Use "Fixed Paper Intrvl" (CPM/PPM down) to solve this problem with SP2-107-010 to 069.
 - Select an SP number corresponding with paper type and thickness to be used. (e.g. Select SP1-207-011 if a customer wants to use uncoated plain paper.)
 - Input "2" in the setting of SP1-207-xxx (-010 to -069) if the machine is located in the LL (Low temperature and Low humidity) condition (10°C/ 15%).
 Or

Input "0.5" in the setting of SP1-207-xxx (-010 to -069) if the machine is located in the condition other than LL condition (10° C/ 15°).

(Important

Select the paper setting (paper type and thickness) which has been set in step 3 when printing a problem image.

Once a paper setting is adjusted by SP1-207-xxx (-010 to -069), CPM (PPM) down is always enabled for that paper setting. Advise a customer not to select the paper setting for which "Fixed Paper Intrvl" (CPM/PPM down) has been enabled if f any images other than a problem image are to be printed.

The side effect of the "Fixed Paper Intrvl" (CPM/PPM down) is that the productivity of the machine is lowered. For details, refer to "Fixed Paper Interval: SP1207" in the chapter "Service Tables".

LL condition: Down to 40% for A3/ Down to 27% for A4 LEF Other condition: Down to 80% for A3/ Down to 68% for A4 LEF

Technical Bulletin

PAGE: 9/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

3. Countermeasure for ITB Dirty due to Fusing Oil

Symptom

- No specific occurrence pattern
- Problem appears only in the range of the paper width size in the duplex printing.

Possible Cause

 Image transferring capacity of the ITB (Image Transfer Belt) is lowered due to the adhered fusing oil on the ITB caused by the duplex printing.

Countermeasure

- 1. Execute "Exe Oil removal" with SP3-309-010.
 - This may solve this problem temporally. If this problem occurs again after a while, try another countermeasure.
- 2. Enable the interrupting oil removal mode with SP3-309-014 (1: On).
- 3. Replace the ITB cleaning blade.
- 4. Countermeasure for Fusing Belt Error

Symptom


- Uneven glossiness occurs on outputs.
- White line occurred on outputs is thick.

Possible Cause

 Uneven surface of the fusing belt caused by the multiple printing (50 outputs or more) of a same image

Countermeasure

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" test pattern for each color with SP2-109-002.
- 3. Select the following colors for printing with SP2-109-004 as shown below.



g178r691

"0": Not selected, "1": Selected


- [2] for **"Cyan"**. Press the **"2"** key on the operation panel if you want to select this color.
- [3] for **"Magenta"**. Press the **"1"** key on the operation panel if you want to select this color.
- [4] for **"Yellow"**. Press the **"0"** key on the operation panel if you want to select this color.
- 4. Press the "APL Window" button on the top of the LCD
- 5. Print a sample image 40 pages from a PC.
 - A sample page must include black color.
 - Size: A3/DLT (11x17), Duplex: on
 - Print a sample image in the largest printable size if paper sizes larger than A3/DLT such as SRA3, 12x18, 13x18, etc are to be used by a client.
- 6. Check the outputs if the problem is solved. If not, try this procedure again.



Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

PAGE: 10/66


White Scattered Dots



If a white scattered dots image as shown above occurs on the outputs, do the following countermeasures.

Before doing countermeasures

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" test pattern for each color with SP2-109-002.
 - Color select can be done with SP2-109-004 as shown below.



g178r691

"0": Not selected, "1": Selected

- [1] for "Black". Press the "3" key on the operation panel if you want to select this color.
- [2] for **"Cyan"**. Press the **"2"** key on the operation panel if you want to select this color.
- [3] for "Magenta". Press the "1" key on the operation panel if you want to select this
- [4] for **"Yellow"**. Press the **"0"** key on the operation panel if you want to select this color.
- 3. Print a sample image 40 pages from a PC.
 - A sample page must include black color.
 - Size: A3/DLT (11x17), Duplex: on
- 4. Check the output to decide a problem drum unit.
- 5. Do the following countermeasures for the problem drum unit.

Countermeasures


- 1. Remove the adhered silica dust on the drum surface.
- 2. Clean or replace the drum cleaning unit.



PAGE: 11/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

Black Spots at 125 mm Interval



If black spots at 125 mm interval appear on the outputs, these black spots may be caused by waste toner [A] adhered on the idle roller [B] against the ITB (Image Transfer Belt) cleaning brush roller. Clean the idle roller [B] against the ITB cleaning brush roller.

Low Toner Density and Uneven Toner Density Image

If the toner density of the outputs is low or toner density of the outputs is not even, use SP2-329 to change the transfer current of the PTR (paper transfer roller). Changing the transfer current can adjust the toner density for each paper type and thickness.

- 1. Check the paper type and printing mode (color or black and white) of a customer's setting.
- 2. Enter the SP mode, and then select a proper SP number.
 - If a customer has used the "Special 6/ Thick 2" setting in the full color mode, select the SP2-329-044 and -045.
- 3. Subtract 10 \(\mu \) A from the default value of the selected SP numbers.
 - If a customer has used the "Special 6/ Thick 2" setting in the full color mode, change the -70 \(\mathbb{H}\)A to -80 \(\mathbb{H}\)A with the SP2-329-044 and -045.
- 4. Check the test print with SP2-109-002.

Side Effect

These SPs affect other settings of paper thickness. For example, each paper type has six types of paper thicknesses (thin, plain, middle thick, thick 1, thick 2 and thick 3). If a problem paper setting is "Special 6/ Thick 2" and this setting is changed, other settings ("Special 6/ Thin", "Special 6/ Plain", "Special 6/ Middle Thick", "Special 6/ Thick 1" and "Special 6/ Thick 3") will be also changed.

Toner Coming Off

The toner may come off from the output paper due to the insufficient fusing temperature. Do the following procedures if this problem occurs.

Technical Bulletin

PAGE: 12/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053



The counter measure for the toner coming off differs in the located condition (low or high temperature). The threshold temperature between low and normal temperature condition is defined by SP1107-018 (default: 17°C).

Toner Coming Off in Low Temperature Condition

- 1. Enter the SP mode.
- 2. Check the paper thickness of the paper to be used, and then select the setting of the "CPM (PPM) Down Setting" with SP1201-003 to -008.
 - Thin: 60 to 75 g/m² (SP1201-003: "0" default)
 - Plain: 76 to 100 g/m² (SP1201-004: "0" default)
 - Middle Thick: 101 to 126 g/m² (SP1201-005: "0" default)
 - Thick 1: 127 to 156 g/m² (SP1201-006: "0" default)
 - Thick 2: 157 to 220 g/m² (SP1201-007: "0" default)
 - Thick 3: 221 to 300 g/m² (SP1201-008: "1" default)
- 3. Change the setting of the "CPM Down Setting" from the default setting to the next step. e.g. If the default setting is "0", change the setting to "1". If it is "1", change the setting to "2".
 - "0": No CPM (PPM) down
 - "1": 80% CPM (PPM)
 - "2": 60% CPM (PPM)
 - "3": 40% CPM (PPM)
- 4. Change the setting of the "CPM Down Setting" again if the problem cannot be recovered.

Toner Coming Off in Normal Temperature Condition

- 1. Enter the SP mode.
 - Check the paper type and thickness of the paper to be used, and then select the target SP number ("Fixed Paper Interval":SP1207-xxx) referring to the following matrix.

Fixed Paper Interval: SP1207-xxx

	Thin	Plain	Middle Thick	Thick 1	Thick 2	Thick 3
Uncoated	-010	-011	-012	-013	-014	-015
Coated 1	-016	-017	-018	-019	-020	-021
Coated 2	-022	-023	-024	-025	-026	-027
Coated 3	-028	-029	-030	-031	-032	-033
Special 1	-034	-035	-036	-037	-038	-039
Special 2	-040	-041	-042	-043	-044	-045
Special 3	-046	-047	-048	-049	-040	-051
Special 4	-052	-053	-054	-055	-056	-057
Special 5	-058	-059	-060	-061	-062	-063
Special 6	-064	-065	-066	-067	-068	-069

Thin: 60 to 75 g/m²/ Plain: 76 to 100 g/m²/ Middle Thick: 101 to 126 g/m²/ Thick 1: 127 to 156 g/m²/ Thick 2: 157 to 220 g/m²/ Thick 3: 221 to 300 g/m²

PAGE: 13/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

2. Change the setting of the "Fixed Paper Interval" to a proper setting.

Fist input "0.5" in the setting of the target SP number.

 Change the setting of the "Fixed Paper Interval" by "0.1" (46 mm interval/ 0.1) if the problem cannot be recovered.

(Important

- Select the paper setting (paper type and thickness) which has been set in the procedure above when printing a problem image.
- Once a paper setting is adjusted by SP1-207-xxx (-010 to -069), CPM (PPM) down is always enabled for that paper setting. Advise a customer not to select the paper setting for which "Fixed Paper Intrvl" (CPM/PPM down) has been enabled if f any images other than a problem image are to be printed.
- The side effect of the "Fixed Paper Intrvl" (CPM/PPM down) is that the productivity of the machine is lowered. For details, refer to "Reference Table of Productivity Change" described below.

Reference Table of Productivity Change

Paper Length Size	SP1207 Setting Value	Default CPM (PPM)	Changed CPM (PPM)	Productivity Rate
	1		39.0	43%
216 mm	2	90.4	23.2	26%
	3		16.5	18%
	1		34.9	50%
297 mm	2	70.4	21.7	31%
	3		15.7	22%
	1		32.0	53%
364 mm	2	60.2	20.6	34%
	3		15.1	25%
	1		29.6	58%
432 mm	2	51.4	19.5	38%
	3		14.6	28%
	1		27.8	60%
488 mm	2	46.2	18.7	41%
	3		14.1	31%

Fusing Problem

Here are four common problems caused by the fusing unit. Do the following countermeasures for the each fusing problem.


Paper Wrinkles/ Worm Tracks

TITLE: Sample of Worm Tracks



PAGE: 14/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053



g178t537

Countermeasure

Decrease the fusing motor speed with SP1909.

Note

If the fusing speed is decreased too much, SC524 may occur.

Blister



g178t538

Countermeasure



Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

- Decrease the fusing temperature of the target setting with SP1105 or SP1108.
- Decrease the nip width of the target setting with SP1905.

(Important

Select one of the following choices to change this setting. Do not input other setting value other than followings.

510 msec/ 330 msec/ 40 msec

Turn on the "Toner Reduction" in the printer driver.

Poor Fusing



g178t539

PAGE: 15/66

Countermeasure

- Increase the fusing temperature of the target setting with SP1105 or SP1108.
- Increase the nip width of the target setting with SP1905.

(Important

Select one of the following choices to change this setting. Do not input other setting value other than followings.

510 msec/ 330 msec/ 40 msec

- Increase the paper interval with SP1207 (Fixed Paper Interval).
- Adjust the fusing temperature control. For details, see the followings below.

Problem at first print just after power-on

If a fusing problem occurs at the first print just after power-on, extend the idle rotation after the print ready condition.

1. Change the setting of the SP1107-034 from "7 (default)" to "15".

(Important

If a print job is sent to the machine, the machine stops this idle rotation to print. To enables the idle rotation after the print ready condition, instruct a customer not to send any job until the machine completes the idle rotation.

If the interval of the idle rotation is extended, PM interval of the fusing unit may be shorter.



PAGE: 16/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

Problem on pages 5 to 10

If a fusing problem occurs on pages 5 to 10 just after power-on or recovery form the low power mode, do the followings below.

- 1. Change the setting of the SP1107-035 from "20 (default)" to "50".
 - This SP extends the interval of the additional temperature mode.
- 2. If step 1 does not solve the problem, increase the additional temperature with SP1107-xxx (for each paper thickness).



200°C or 205°C is the maximum temperature for the fusing temperature. (The maximum temperature is different depending on the engine firmware version. For the firmware released at the end of July 2009 or later, 205°C is available.) For example, 200°C is the default setting of the SP1108-074 (Thick 3: FC: SP6). Even though you change the setting of SP1107-033 from "5" to "20" and expected temperature is 220°C (200°C + 20°C), the fusing temperature of the "Thick 3/ FC/ Special 6" does not exceed 200°C or 205°C.

Problem at each edge on large size paper

If a fusing problem occurs at each edge on the large size paper, extend the waiting time for the paper feed permission before feeding paper from the paper tray.

- 1. Change the setting of the SP1107-037 from "0" to "3".
 - Selecting "3" in SP1107-037 enables the "Feed Start Extensions" SPs (SP1101-061 to -066). These SPs adjust the waiting time for the paper feed permission for each paper thickness.
- 2. Increase the setting time for each paper thickness with SP1101-xxx.

Problem after being left in stand-by mode for a long time

If a fusing problem occurs after being left in stand-by mode for a long time, do the followings below.

- 1. Change the setting of the SP1107-040 from "0 (Off)" to "1 (On)".
 - This SP can enable or disable the idle rotation during the stand-by mode.
- 2. Change the setting of the SP1107-038 from "60" to "360".
 - This SP can adjust the interval of the idle rotation during the stand-by mode.

(Important

If the interval of the idle rotation is extended, PM interval of the fusing unit may be shorter.

Problem for all conditions

To improve the fusing capacity for all conditions, increase the fusing temperature in the stand-by mode with the following SPs.

- Normal temperature condition (17°C to 27°C): SP1105-031
- Low temperature condition (less than 17°C): SP1105-032
- High temperature condition (more than 27°C): SP1105-033

22	Note	4

The threshold temperature between each temperature condition can be adjusted with SP1107-018 and -019.



Model: Aegis-P1/C1 No.: RG178053 Date: 22-Jun-09

PAGE: 17/66

Scratched Lines/ Rib Marks



g178t540

- Check if the setting of the SP1-805-001 is set to "1592.9 (rpm)". If not, change the setting value to "1592.9 (rpm)".
- Decrease the fusing motor speed with SP1909.

Note

If the fusing speed is decreased too much, SC524 may occur.

Adjustment SPs for Paper Type and Thickness Settings

Here are SP tables for the paper type and thickness settings.

Uncoated

TITLE: Uncoated: Thin Paper

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-042	160°C (NA)/ 165°C (EU)
Fusing Temp.	Simplex: FC	SP1105-043	160°C (NA)/ 165°C (EU)
rusing remp.	Duplex: B/W	SP1105-054	160°C (NA)/ 165°C (EU)
	Duplex: FC	SP1105-055	160°C (NA)/ 165°C (EU)
Fusing Motor Speed Correction	_	SP1909-020	-2% (NA)/ 0% (EU)
Nip Width Setting	Low Temp.	SP1905-011	510 msec. (NA/ EU)
Mip Width Setting	Over Low Temp.	SP1905-077	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-001	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-010	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-006	50 HA (NA/ EU)
Bias Setting	B/W: Back	SP2329-007	50 ^μ A (NA/ EU)
	FC: Front	SP2329-008	70 ^µ A (NA/ EU)



PAGE: 18/66

Model: Aegis-P1/C1	1		Date:	22-Jun-09	No.: RG178	3053
Adjustable SP	Mode	SP N	0.	Defau	ılt	
_	FC: Back	SP2329-0	009	70 HA (NA/ EL	J)	
PTR: Leading Edge	B/W: Front	SP2426-0	001	170% (NA/ EU)	
Bias Correction	B/W: Back	SP2426-0	007	170% (NA/ EU)	
Setting	FC: Front	SP2426-0	012	170% (NA/ EU)	
Setting	FC: Back	SP2426-0	018	170% (NA/ EU)	
PTR: Trailing Edge	B/W: Front	SP2428-0	001	100% (NA/ EU)	
Bias Correction	B/W: Back	SP2428-0		100% (NA/ EU)	
Setting	FC: Front	SP2428-0	003	100% (NA/ EU		
Cetting	FC: Back	SP2428-0	004	100% (NA/ EU)	
TITLE: Uncoated: Pl						
Adjustable SP	Mode	SP N	0.	Defau		
	Simplex: B/W	SP1105-0	040	175°C (NA)/ 18	` '	
Fusing Temp.	Simplex: FC	SP1105-0		175°C (NA)/ 18		
i dailig remp.	Duplex: B/W	SP1105-0	052	175°C (NA)/ 18	. ,	
	Duplex: FC	SP1105-0	053	175°C (NA)/ 18	80°C (EU)	
Fusing Motor Speed Correction	-	SP1909-0	021	0% (NA)/ -3%	(EU)	
Nin Width Cotting	Low Temp.	SP1905-0	012	510 msec. (NA	V EU)	
Nip Width Setting	Over Low Temp.	SP1905-0	078	510 msec. (NA	v EÚ)	
Jam 38 Detection Timing Setting	-	SP1160-0	002	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	-	SP1207-0	011	0 (NA/ EU)		
_	B/W: Front	SP2329-0	006	50 HA (NA/ EL	J)	
PTR: Standard	B/W: Back	SP2329-0	007	50 HA (NA/ EL	J)	
Bias Setting	FC: Front	SP2329-0	800	70 HA (NA/ EL	J)	
	FC: Back	SP2329-0	009	70 μA (NA/ EL	J)	
PTR: Leading Edge	B/W: Front	SP2426-0	002	170% (NA/ EU)	
Bias Correction	B/W: Back	SP2426-0	800	170% (NA/ EU)	
Setting	FC: Front	SP2426-0		170% (NA/ EU		
Setting	FC: Back	SP2426-0	019	170% (NA/ EU)	
PTR: Trailing Edge	B/W: Front	SP2428-0	001	100% (NA/ EU	•	
Bias Correction	B/W: Back	SP2428-0	002	100% (NA/ EU)	
Setting	FC: Front	SP2428-0		100% (NA/ EU		
Octung	FC: Back	SP2428-0	004	100% (NA/ EU)	
TITLE: Uncoated: Mi	iddle Thick					
Adjustable SP	Mode	SP N		Defau		
	Simplex: B/W	SP1105-0		175°C (NA/ EL	,	
Fusing Temp.	Simplex: FC	SP1105-0		175°C (NA/ EU	,	
i doing romp.	Duplex: B/W	SP1105-0		175°C (NA/ EU		
	Duplex: FC	SP1105-0	057	175°C (NA/ EL	J)	
Fusing Motor Speed Correction	-	SP1909-0	022	0% (NA)/ -1%	(EU)	
Nip Width Setting	Low Temp.	SP1905-0	013	330 msec. (NA	V EU)	
TAID ANIGHT SERING	Over Low Temp.	SP1905-0	79	330 msec. (NA	V EU)	



PAGE: 19/66 No.: RG178053

Model: Aegis-P1/C1	1	Date	: 22-Jun-09	No.: RG178053
Adjustable SP	Mode	SP No.	Defau	ılt
Jam 38 Detection		SP1160-003	30 mm (NA/ E	LIN
Timing Setting		01 1100-000	00 mm (1474 L	0)
Fixed Paper	_	SP1207-012	0 (NA/ EU)	
Interval Setting	B/W: Front	SP2329-006	50 HA (NA/ EU	1)
PTR: Standard	B/W: Flork	SP2329-007	50 MA (NA/ EU	,
Bias Setting	FC: Front	SP2329-008	70 PA (NA/ EU	
	FC: Back	SP2329-009	70 PA (NA/ EU	/
<u> </u>	B/W: Front	SP2426-003	170% (NA/ EL	,
PTR: Leading Edge	B/W: Back	SP2426-009	170% (NA/ EU	,
Bias Correction	FC: Front	SP2426-014	170% (NA/ EL	
Setting	FC: Back	SP2426-020	170% (NA/ EL	/
	B/W: Front	SP2428-001	100% (NA/ EU	/
PTR: Trailing Edge	B/W: Flork	SP2428-002	100% (NA/ EU	
Bias Correction	FC: Front	SP2428-003	100% (NA/ EU	
Setting	FC: Back	SP2428-004	100% (NA/ EU	,
TITLE: Uncoated: Th		01 2420-004	10070 (1474) EC	')
Adjustable SP	Mode	SP No.	Defau	ılt
rajuotable of	Simplex: B/W	SP1105-046	185°C (NA/ El	
	Simplex: FC	SP1105-047	185°C (NA/ El	/
Fusing Temp.	Duplex: B/W	SP1105-058	185°C (NA/ El	,
	Duplex: FC	SP1105-059	185°C (NA/ El	,
Fusing Motor Speed Correction	-	SP1909-023	-2% (NA)/ 0%	,
•	Low Temp.	SP1905-014	330 msec. (NA	V EU)
Nip Width Setting	Over Low Temp.	SP1905-080	330 msec. (NA	
Jam 38 Detection Timing Setting	-	SP1160-004	30 mm (NA/ E	
Fixed Paper				
Interval Setting	-	SP1207-013	0 (NA/ EU)	
	B/W: Front	SP2329-006	50 HA (NA/ EU	
PTR: Standard	B/W: Back	SP2329-007	50 HA (NA/ EU	J)
Bias Setting	FC: Front	SP2329-008	70 HA (NA/ EU	J)
	FC: Back	SP2329-009	70 HA (NA/ EU	J)
DTD: Loading Edge	B/W: Front	SP2426-004	170% (NA/ EL	J)
PTR: Leading Edge	B/W: Back	SP2426-010	170% (NA/ EL	J)
Bias Correction Setting	FC: Front	SP2426-015	170% (NA/ EL	J)
	FC: Back	SP2426-021	170% (NA/ EL	J)
DTD TANK 51	B/W: Front	SP2428-001	100% (NA/ EL	J)
PTR: Trailing Edge	B/W: Back	SP2428-002	100% (NA/ EL	J)
Bias Correction	FC: Front	SP2428-003	100% (NA/ EL	
Setting	FC: Back	SP2428-004	100% (NA/ EL	,
TITLE: Uncoated: Th	nick 2		·	
Adjustable SP	Mode	SP No.	Defau	ılt
Fusing Temp.	Simplex: B/W	SP1105-048	190°C (NA/ El	
· · ·		*	•	-



Model: Aegis-P1/C1

Technical Bulletin

 Ulletin
 PAGE: 20/66

 Date: 22-Jun-09
 No.: RG178053

U			
Adjustable SP	Mode	SP No.	Default
	Simplex: FC	SP1105-049	190°C (NA/ EU)
	Duplex: B/W	SP1105-060	190°C (NA/ EU)
	Duplex: FC	SP1105-061	190°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-024	0% (NA)/ -2% (EU)
Nin Width Cotting	Low Temp.	SP1905-015	330 msec. (NA)/ 40 msec. (EU)
Nip Width Setting	Over Low Temp.	SP1905-081	330 msec. (NA)/ 40 msec. (EU)
Jam 38 Detection Timing Setting	_	SP1160-005	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-014	0 (NA/ EU)
	B/W: Front	SP2329-006	50 \(\text{PA} \) (NA/ EU)
PTR: Standard	B/W: Back	SP2329-007	50 \textsup A (NA/ EU)
Bias Setting	FC: Front	SP2329-008	70 HA (NA/ EU)
	FC: Back	SP2329-009	70 \textsquare (NA/ EU)
DTD: Loading Edge	B/W: Front	SP2426-005	250% (NA/ EU)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-011	250% (NA/ EU)
Setting	FC: Front	SP2426-016	250% (NA/ EU)
	FC: Back	SP2426-022	250% (NA/ EU)
DTD: Trailing Edge	B/W: Front	SP2428-001	100% (NA/ EU)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-002	100% (NA/ EU)
Setting	FC: Front	SP2428-003	100% (NA/ EU)
Setting	FC: Back	SP2428-004	100% (NA/ EU)

TITLE: Uncoated: Thick 3

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1105-050	195°C (NA/ EU)
rusing remp.	Simplex: FC	SP1105-051	195°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-025	-2% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-016	40 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-082	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-006	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-015	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-006	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-008	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-006	125% (NA)/ 250% (EU)
Bias Correction Setting	FC: Front	SP2426-017	125% (NA)/ 250% (EU)
PTR: Trailing Edge	B/W: Front	SP2428-001	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-003	100% (NA/ EU)
Paper Thickness	_	SP2368-006	125% (NA)

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 21/66

Adjustable SP	Mode	SP No.	Default
Correction		(NA only)	

Special 4 (uncoated)

Model: Aegis-P1/C1

TITLE: \$	Special	. 4: Th	in Pa	per
-----------	---------	---------	-------	-----

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1108-009	160°C (NA)/ 165°C (EU)
Fusing Temp.	Simplex: FC	SP1108-010	160°C (NA)/ 165°C (EU)
rusing remp.	Duplex: B/W	SP1108-021	160°C (NA)/ 165°C (EU)
	Duplex: FC	SP1108-022	160°C (NA)/ 165°C (EU)
Fusing Motor Speed Correction	-	SP1909-062	0% (NA)/ -3% (EU)
Nin Width Cotting	Low Temp.	SP1905-053	510 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-119	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-043	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-052	0 (NA/ EU)
	B/W: Front	SP2329-034	50 ^μ A (NA/ EU)
PTR: Standard	B/W: Back	SP2329-035	50 ^μ A (NA/ EU)
Bias Setting	FC: Front	SP2329-036	70 μA (NA/ EU)
	FC: Back	SP2329-037	70 μA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-155	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-161	170% (NA/ EU)
Setting	FC: Front	SP2426-166	170% (NA/ EU)
	FC: Back	SP2426-172	170% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-029	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-030	100% (NA/ EU)
Setting	FC: Front	SP2428-031	100% (NA/ EU)
	FC: Back	SP2428-032	100% (NA/ EU)

TITLE: Special 4: Plain

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1108-007	180°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1108-008	180°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1108-019	180°C (NA/ EU)
	Duplex: FC	SP1108-020	180°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-063	-3% (NA)/ 0% (EU)
Nin Width Cotting	Low Temp.	SP1905-054	510 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-120	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-044	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-053	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-034	50 HA (NA/ EU)
Bias Setting	B/W: Back	SP2329-035	50 HA (NA/ EU)



PAGE: 22/66

Model: Aegis-P1/C1			Date:	22-Jun-09	No.: RG1780	53
Adjustable SP	Mode	SP N	0.	Defau	ilt	
_	FC: Front	SP2329-0	036	70 HA (NA/ EL	J)	
	FC: Back	SP2329-0	037	70 HA (NA/ EL	J)	
DTD: Loading Edge	B/W: Front	SP2426-	156	170% (NA/ EU)	
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-	162	170% (NA/ EU)	
Setting	FC: Front	SP2426-	167	170% (NA/ EU)	
Setting	FC: Back	SP2426-	173	170% (NA/ EU)	
PTR: Trailing Edge	B/W: Front	SP2428-0	029	100% (NA/ EU		
Bias Correction	B/W: Back	SP2428-0	030	100% (NA/ EU)	
Setting	FC: Front	SP2428-0	031	100% (NA/ EU)	
Setting	FC: Back	SP2428-0	032	100% (NA/ EU)	
TITLE: Special 4: Mi	ddle Thick					
Adjustable SP	Mode	SP N		Defau		
	Simplex: B/W	SP1108-0	011	180°C (NA)/ 18	85°C (EU)	
Fusing Temp.	Simplex: FC	SP1108-0	012	180°C (NA)/ 18	85°C (EU)	
rusing remp.	Duplex: B/W	SP1108-0	023	180°C (NA)/ 18	85°C (EU)	
	Duplex: FC	SP1108-0	024	180°C (NA)/ 18	85°C (EU)	
Fusing Motor Speed Correction	-	SP1909-0	064	-2% (NA)/ 0%	(EU)	
	Low Temp.	SP1905-0	055	330 msec. (NA msec.(EU)	x)/ 510	
Nip Width Setting	Over Low Temp.	SP1905-1	121	330 msec. (NA msec.(EU)	x)/ 510	
Jam 38 Detection Timing Setting	-	SP1160-0	045	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	-	SP1207-0	054	0 (NA/ EU)		
	B/W: Front	SP2329-0	034	50 HA (NA/ EL	J)	
PTR: Standard	B/W: Back	SP2329-0		50 HA (NA/ EL		
Bias Setting	FC: Front	SP2329-0		70 HA (NA/ EL	/	
Ŭ	FC: Back	SP2329-0		70 HA (NA/ EL		
DTD	B/W: Front	SP2426-		170% (NA/ EU		
PTR: Leading Edge	B/W: Back	SP2426-		170% (NA/ EU		
Bias Correction	FC: Front	SP2426-		170% (NA/ EU	,	
Setting	FC: Back	SP2426-		170% (NA/ EU	,	
DTD Torres Educ	B/W: Front	SP2428-0	029	100% (NA/ EU	•	
PTR: Trailing Edge	B/W: Back	SP2428-0	030	100% (NA/ EU)	
Bias Correction	FC: Front	SP2428-0	031	100% (NA/ EU)	
Setting	FC: Back	SP2428-0	032	100% (NA/ EU		
TITLE: Special 4: Th	ick 1	'			•	
Adjustable SP	Mode	SP N	0.	Defau	ılt	
	Simplex: B/W	SP1108-0	013	175°C (NA/ EU	J)	
Fueing Tomp	Simplex: FC	SP1108-0	014	175°C (NA/ EU	J)	
Fusing Temp.	Duplex: B/W	SP1108-0	025	175°C (NA/ EU	J)	
	Duplex: FC	SP1108-0	026	175°C (NA/ EU	J)	
Fusing Motor	_	SP1909-0	065	-3% (NA/ EU)		



Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 23/66

Adjustable SP	Mode	SP No.	Default
Speed Correction			
Nip Width Setting	Low Temp.	SP1905-056	510 msec. (NA)/ 330 msec. (EU)
inp widin setting	Over Low Temp.	SP1905-122	510 msec. (NA)/ 330 msec. (EU)
Jam 38 Detection Timing Setting	-	SP1160-046	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-055	0 (NA/ EU)
	B/W: Front	SP2329-034	50 ¼A (NA/ EU)
PTR: Standard	B/W: Back	SP2329-035	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-036	70 HA (NA/ EU)
	FC: Back	SP2329-037	70 HA (NA/ EU)
DTD: Loading Edge	B/W: Front	SP2426-158	170% (NA/ EU)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-164	170% (NA/ EU)
Setting	FC: Front	SP2426-169	170% (NA/ EU)
Setting	FC: Back	SP2426-175	170% (NA/ EU)
PTR: Trailing Edge Bias Correction	B/W: Front	SP2428-029	100% (NA/ EU)
	B/W: Back	SP2428-030	100% (NA/ EU)
	FC: Front	SP2428-031	100% (NA/ EU)
Setting	FC: Back	SP2428-032	100% (NA/ EU)

TITLE: Special 4: Thick 2

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1108-015	185°C (NA)/ 195°C (EU)
Fusing Temp.	Simplex: FC	SP1108-016	185°C (NA)/ 195°C (EU)
rusing remp.	Duplex: B/W	SP1108-027	185°C (NA)/ 195°C (EU)
	Duplex: FC	SP1108-028	185°C (NA)/ 195°C (EU)
Fusing Motor Speed Correction	-	SP1909-066	-2% (NA/ EU)
Nin Width Sotting	Low Temp.	SP1905-057	40 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-123	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-047	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-056	0 (NA/ EU)
	B/W: Front	SP2329-034	50 μA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-035	50 μA (NA/ EU)
Bias Setting	FC: Front	SP2329-036	70 μA (NA/ EU)
	FC: Back	SP2329-037	70 μA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-159	250% (NA/ EU)
Bias Correction Setting	B/W: Back	SP2426-165	250% (NA/ EU)
	FC: Front	SP2426-170	250% (NA/ EU)
Setting	FC: Back	SP2426-176	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-029	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-030	100% (NA/ EU)

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09	No.: RG178053

PAGE: 24/66

Adjustable SP	Mode	SP No.	Default		
Setting	FC: Front	SP2428-031	100% (NA/ EU)		
	FC: Back	SP2428-032	100% (NA/ EU)		
TITLE: Special 4: Thick 3					

THEE. Special 4. Thick 5				
Adjustable SP	Mode	SP No.	Default	
Fusing Temp.	Simplex: B/W	SP1108-017	195°C (NA/ EU)	
rusing remp.	Simplex: FC	SP1108-018	195°C (NA/ EU)	
Fusing Motor Speed Correction	-	SP1909-067	-3% (NA/ EU)	
Nip Width Setting	Low Temp.	SP1905-058	40 msec. (NA/ EU)	
Mp Width Setting	Over Low Temp.	SP1905-124	40 msec. (NA/ EU)	
Jam 38 Detection Timing Setting	-	SP1160-048	30 mm (NA/ EU)	
Fixed Paper Interval Setting	-	SP1207-057	0 (NA/ EU)	
PTR: Standard	B/W: Front	SP2329-034	50 HA (NA/ EU)	
Bias Setting	FC: Front	SP2329-036	70 HA (NA/ EU)	
PTR: Leading Edge	B/W: Front	SP2426-160	250% (NA/ EU)	
Bias Correction Setting	FC: Front	SP2426-171	250% (NA/ EU)	
PTR: Trailing Edge	B/W: Front	SP2428-029	100% (NA/ EU)	
Bias Correction Setting	FC: Front	SP2428-031	100% (NA/ EU)	

Special 5 (uncoated)

TITLE: Special 5: Thin Paper

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1108-037	165°C (NA)/ 175°C (EU)
Fusing Temp.	Simplex: FC	SP1108-038	165°C (NA)/ 175°C (EU)
rusing remp.	Duplex: B/W	SP1108-049	165°C (NA)/ 175°C (EU)
	Duplex: FC	SP1108-050	165°C (NA)/ 175°C (EU)
Fusing Motor Speed Correction	-	SP1909-068	0% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-059	510 msec. (NA/ EU)
inp widin setting	Over Low Temp.	SP1905-125	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-049	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-058	0 (NA/ EU)
_	B/W: Front	SP2329-038	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-039	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-040	70 HA (NA/ EU)
	FC: Back	SP2329-041	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-177	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-183	170% (NA/ EU)
Setting	FC: Front	SP2426-188	170% (NA/ EU)



Technical Bulletin PAGE: 25/66

Model: Aegis-P1/C	el: Aegis-P1/C1 Date: 22-Jun-09 No.: F			No.: RG178053
Adjustable SP	Mode	SP No.	Defau	ult
	FC: Back	SP2426-194	170% (NA/ EL	
PTR: Trailing Edge	B/W: Front	SP2428-033	100% (NA/ EL	
Bias Correction	B/W: Back	SP2428-034	100% (NA/ EU	J)
Setting	FC: Front	SP2428-035	100% (NA/ EL	J)
Setting	FC: Back	SP2428-036	100% (NA/ EL	J)
TITLE: Special 5: Pla	ain			
Adjustable SP	Mode	SP No.	Defau	ult
	Simplex: B/W	SP1108-035	170°C (NA/ El	,
Fusing Temp.	Simplex: FC	SP1108-036	170°C (NA/ El	J)
rusing remp.	Duplex: B/W	SP1108-047	170°C (NA/ El	J)
	Duplex: FC	SP1108-048	170°C (NA/ EI	J)
Fusing Motor Speed Correction	-	SP1909-069	-2% (NA)/ 0%	(EU)
•	Low Temp.	SP1905-060	510 msec. (NA	√ EU)
Nip Width Setting	Over Low Temp.	SP1905-126	510 msec. (NA	
Jam 38 Detection Timing Setting	_	SP1160-050	30 mm (NA/ E	U)
Fixed Paper Interval Setting	_	SP1207-059	0 (NA/ EU)	
	B/W: Front	SP2329-038	50 HA (NA/ EU	J)
PTR: Standard	B/W: Back	SP2329-039	50 HA (NA/ El	J)
Bias Setting	FC: Front	SP2329-040	70 HA (NA/ EU	
	FC: Back	SP2329-041	70 HA (NA/ El	J)
DTD: Loading Edge	B/W: Front	SP2426-178	170% (NA/ EL	J)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-184	170% (NA/ EL	J)
	FC: Front	SP2426-189	170% (NA/ EL	J)
Setting	FC: Back	SP2426-195	170% (NA/ EL	J)
DTD T ''' E !	B/W: Front	SP2428-033	100% (NA/ EL	J)
PTR: Trailing Edge	B/W: Back	SP2428-034	100% (NA/ EL	,
Bias Correction	FC: Front	SP2428-035	100% (NA/ EU	,
Setting	FC: Back	SP2428-036	100% (NA/ EU	
TITLE: Special 5: Mi		101 - 1-0 000	1.00.00	,
Adjustable SP	Mode	SP No.	Defau	ult
	Simplex: B/W	SP1108-039	185°C (NA/ El	
	Simplex: FC	SP1108-040	185°C (NA/ EI	,
Fusing Temp.	Duplex: B/W	SP1108-051	185°C (NA/ EI	
	Duplex: FC	SP1108-052	185°C (NA/ EI	
Fusing Motor Speed Correction	-	SP1909-070	-1% (NA)/ -3%	,
	Low Temp.	SP1905-061	330 msec. (NA	A/ EU)
Nip Width Setting	Over Low Temp.	SP1905-127	330 msec. (NA	,
Jam 38 Detection Timing Setting	-	SP1160-051	30 mm (NA/ E	ŕ
Fixed Paper Interval Setting	-	SP1207-060	0 (NA/ EU)	



PAGE: 26/66

Adjustable SP	Model: Aegis-P1/C1	1		Date:	22-Jun-09	No.: RG178053
PTR: Standard Biw: Back SP2329-039 50 µA (NA/ EU) FC: Front SP2329-040 70 µA (NA/ EU) FC: Back SP2329-041 70 µA (NA/ EU) FC: Back SP2329-041 70 µA (NA/ EU) FC: Back SP2426-179 170% (NA/ EU) FC: Front SP2426-196 170% (NA/ EU) FC: Front SP2426-196 170% (NA/ EU) FC: Back SP2426-196 170% (NA/ EU) FC: Back SP2426-196 170% (NA/ EU) FC: Back SP2428-033 100% (NA/ EU) FC: Front SP2428-033 100% (NA/ EU) FC: Front SP2428-033 100% (NA/ EU) FC: Front SP2428-035 100% (NA/ EU) FC: Front SP2428-036 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) FC: Front SP2428-036 175°C (NA)/ 180°C (EU) FC: Front SP2428-036 175°C (NA)/ 180°C (EU) FC: Front SP2428-036 175°C (NA)/ 180°C (EU) FC: Front SP2428-036 175°C (NA/ EU) FC: Front SP2428-036 100% (NA/ EU) FC: Front SP2329-040 70 µA (NA/ EU) FC: Front SP2329-040 70 µA (NA/ EU) FC: Front SP2329-040 70 µA (NA/ EU) FC: Back SP2426-191 70% (NA/ EU) FC: Back SP2426-191 70% (NA/ EU) FC: Back SP2428-033 100% (NA/ EU) FC: Front SP2428-033 100% (NA/ EU) FC: Fro	Adjustable SP					
Bias Setting			SP2329-0			
PTR: Leading Edge Bias Correction						
PTR: Leading Edge Bias Correction Setting SP2426-179 170% (NA/ EU) SP2426-185 170% (NA/ EU) FC: Front SP2426-190 170% (NA/ EU) FC: Back SP2426-190 170% (NA/ EU) SP2428-196	Bias Setting				•	,
PTR: Leading Edge Bias Correction Setting FC: Front SP2426-196 170% (NA/ EU) FC: Back SP2426-196 170% (NA/ EU) FC: Back SP2428-033 100% (NA/ EU) FC: Front SP2428-033 100% (NA/ EU) FC: Front SP2428-035 100% (NA/ EU) FC: Front SP2428-036 100% (NA/ EU) FC: Front SP2428-037 170% (NA						
Bias Correction Setting FC: Front SP2426-196 170% (NA/ EU) FC: Back SP2426-196 170% (NA/ EU) FC: Back SP2426-196 170% (NA/ EU) SP2428-033 100% (NA/ EU) SP2428-035 100% (NA/ EU) SP2428-035 100% (NA/ EU) SP2428-035 100% (NA/ EU) FC: Back SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) SImplex: FC SP1108-041 175°C (NA)/ 180°C (EU) Simplex: FC SP1108-042 175°C (NA)/ 180°C (EU) Simplex: FC SP1108-053 175°C (NA)/ 180°C (EU) SP108-053 175°C (NA)/ 180°C (EU) SP108-054 175°C (NA)/ 180°C (EU) SP109-071 2% (NA)/ 0% (EU) SP109-072 330 msec. (NA/ EU) SP1108-054 175°C (NA)/ 180°C (EU) SP109-072 330 msec. (NA/ EU) SP1108-052 30 mm (NA/ EU) SP1108-052 30 mm (NA/ EU) SP1108-052 30 mm (NA/ EU) SP1229-040 30 mm (NA/ EU) SP2229-041 30 mm (NA/ EU)	PTR: Leading Edge				,	,
Setting					`	•
PTR: Trailing Edge Bias Correction SP2428-034 100% (NA/ EU) BW: Back SP2428-034 100% (NA/ EU) FC: Back SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) STITLE: Special 5: Thick 1					•	,
Bias Correction B/W: Back SP2428-034 100% (NA/ EU) FC: Front SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) FC: Back SP108-041 175°C (NA)/ 180°C (EU) Simplex: FC SP1108-042 175°C (NA)/ 180°C (EU) Simplex: FC SP1108-054 175°C (NA)/ 180°C (EU) SP108-054 175°C (NA)/ 180°C (EU) SP109-071 -2% (NA)/ 0% (EU) SP109-072 330 msec. (NA/ EU) SP1160-052 30 mm (NA/ EU) SP1160-052 SP1108-040 SP1207-061 O (NA/ EU) SP1160-052 SP1108-040 SP1207-061 O (NA/ EU) SP1160-052 SP1160-0						
Bias Correction Setting FC: Front SP2428-035 100% (NA/ EU)	PTR: Trailing Edge		+		`	/
Setting						
TITLE: Special 5: Thick 1						
Adjustable SP			SP2428-0	36	100% (NA/ EU)
Simplex: B/W SP1108-041 175°C (NA)/ 180°C (EU) Simplex: FC SP1108-042 175°C (NA)/ 180°C (EU) Duplex: B/W SP1108-053 175°C (NA)/ 180°C (EU) Duplex: FC SP1108-054 175°C (NA)/ 180°C (EU) Duplex: FC SP1108-054 175°C (NA)/ 180°C (EU) SP108-054 175°C (NA)/ 180°C (EU) SP109-071 -2% (NA)/ 0% (EU) SP109-072 330 msec. (NA/ EU) SP109-072 330 msec. (NA/ EU) SP1160-052 30 mm (NA/ EU) SP1160-054 30 mm (NA/ EU) SP1160-055 30 mm (NA/ EU) SP1160-056 30 mm (NA/						
Fusing Temp. Simplex: FC SP1108-042 175°C (NA)/ 180°C (EU)	Adjustable SP					
Duplex: B/W Duplex: B/W Duplex: B/W Duplex: FC SP1108-053 175°C (NA)/ 180°C (EU)					` '	\ /
Duplex: B/W Duplex: FC SP1108-053 175°C (NA)/ 180°C (EU)	Fusing Temp	•			` '	· /
Fusing Motor Speed Correction Speed Correctio	r doing romp.	•			, ,	,
Speed Correction Nip Width Setting Low Temp. SP1905-062 330 msec. (NA/ EU)		Duplex: FC	SP1108-0	54	175°C (NA)/ 18	30°C (EU)
Number Setting Over Low Temp. SP1905-128 330 msec. (NA/ EU)		-	SP1909-0	71	-2% (NA)/ 0%	(EU)
Jam 38 Detection	Nin Width Cotting	Low Temp.	SP1905-0	62	330 msec. (NA	√EU)
Timing Setting Fixed Paper Interval Setting B/W: Front B/W: Back FC: Front FC: Back Bias Correction Setting PTR: Trailing Edge Bias Correction Setting PTR: Trailing Edge Bias Correction Setting FC: Front FC: Back FC: Front FC: Front FC: Back FC: Front	inip width Setting	Over Low Temp.	SP1905-1	28	330 msec. (NA	√ EU)
SP1207-061 O (NA/ EU)		-	SP1160-0	52	30 mm (NA/ E	U)
B/W: Front	Fixed Paper	-	SP1207-0	61	0 (NA/ EU)	
PTR: Standard Bias Setting FC: Front FC: Back SP2329-040 FC: Back SP2329-041 FC: Back SP2426-180 FC: Front SP2426-180 FC: Front SP2426-191 FC: Back SP2426-191 FC: Back SP2426-197 FC: Back SP2428-033 FC: Front SP2428-033 FC: Front SP2428-034 FC: Front SP2428-035 FC: Front SP2428-035 FC: Front SP2428-036 FC: Front SP2	<u> </u>	B/W: Front	SP2329-0	38	50 HA (NA/ EL	J)
FC: Front	PTR: Standard					
FC: Back	Bias Setting	FC: Front	SP2329-0			
PTR: Leading Edge B/W: Front SP2426-180 170% (NA/ EU) Bias Correction Setting FC: Front SP2426-186 170% (NA/ EU) PTR: Trailing Edge Bias Correction Setting B/W: Front SP2428-033 100% (NA/ EU) B/W: Back SP2428-034 100% (NA/ EU) B/W: Back SP2428-034 100% (NA/ EU) B/W: Back SP2428-035 100% (NA/ EU) FC: Front SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) TITLE: Special 5: Thick 2 Adjustable SP Mode SP No. Default Simplex: B/W SP1108-043 190°C (NA)/ 195°C (EU) Simplex: FC SP1108-055 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)			SP2329-0	41	· · · · · · · · · · · · · · · · · · ·	
Bias Correction Setting FC: Front SP2426-191 170% (NA/ EU)	DTD: Loading Edge	B/W: Front	SP2426-1	80	170% (NA/ EU)
Setting		B/W: Back	SP2426-1	86	170% (NA/ EU)
PTR: Trailing Edge Bias Correction Setting B/W: Front B/W: Back SP2428-033 100% (NA/ EU) B/W: Back FC: Front SP2428-034 100% (NA/ EU) FC: Front SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) TITLE: Special 5: Thick 2 Adjustable SP Mode SP No. Default Simplex: B/W SP1108-043 190°C (NA)/ 195°C (EU) Simplex: FC Duplex: B/W SP1108-044 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)		FC: Front	SP2426-1	91	170% (NA/ EU)
Bias Correction Setting B/W: Back SP2428-034 100% (NA/ EU)	Setting	FC: Back	SP2426-1	97	170% (NA/ EU)
Bias Correction Setting FC: Front SP2428-035 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) FC: Back SP2428-036 100% (NA/ EU) TITLE: Special 5: Thick 2 Adjustable SP Mode SP No. Default Simplex: B/W SP1108-043 190°C (NA)/ 195°C (EU) Simplex: FC SP1108-044 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)	DTD: Trailing Edge	B/W: Front	SP2428-0	33	100% (NA/ EU)
Setting FC: Front FC: Back SP2428-035		B/W: Back	SP2428-0	34	100% (NA/ EU)
TITLE: Special 5: Thick 2 Adjustable SP		FC: Front	SP2428-0	35	100% (NA/ EU)
Adjustable SP Mode SP No. Default Fusing Temp. Simplex: B/W SP1108-043 190°C (NA)/ 195°C (EU) Simplex: FC SP1108-044 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)	Setting	FC: Back	SP2428-0	36	100% (NA/ EU)
Adjustable SP Mode SP No. Default Fusing Temp. Simplex: B/W SP1108-043 190°C (NA)/ 195°C (EU) Simplex: FC SP1108-044 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)	TITLE: Special 5: Th	ick 2				
Fusing Temp. Simplex: FC SP1108-044 190°C (NA)/ 195°C (EU) Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)			SP No).		
Duplex: B/W SP1108-055 190°C (NA)/ 195°C (EU) Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)					190°C (NA)/ 19	95°C (EU)
Duplex: FC SP1108-056 190°C (NA)/ 195°C (EU)	Fusing Temp	Simplex: FC	SP1108-0	44	190°C (NA)/ 19	95°C (EU)
	i using remp.	Duplex: B/W	SP1108-0	55	190°C (NA)/ 19	95°C (EU)
		Duplex: FC			` '	· /
Fusing Motor - SP1909-072 -2% (NA)/ -3% (EU)	Fusing Motor	-	SP1909-0	72	-2% (NA)/ -3 <mark>%</mark>	(EU)

Technical Bulletin

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

PAGE: 27/66

Adjustable SP	Mode	SP No.	Default
Speed Correction			
Nip Width Setting	Low Temp.	SP1905-063	40 msec. (NA/ EU)
Mp Width Setting	Over Low Temp.	SP1905-129	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-053	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-062	0 (NA/ EU)
	B/W: Front	SP2329-038	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-039	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-040	70 HA (NA/ EU)
	FC: Back	SP2329-041	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-181	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-187	250% (NA/ EU)
Setting	FC: Front	SP2426-192	250% (NA/ EU)
Setting	FC: Back	SP2426-198	250% (NA/ EU)
IDTB: Trailing Edge	B/W: Front	SP2428-033	100% (NA/ EU)
	B/W: Back	SP2428-034	100% (NA/ EU)
Setting	FC: Front	SP2428-035	100% (NA/ EU)
Setting	FC: Back	SP2428-036	100% (NA/ EU)

TITLE: Special 5: Thick 3

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1108-045	200°C (NA/ EU)
r using remp.	Simplex: FC	SP1108-046	200°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-073	-2% (NA)/ -3% (EU)
Nip Width Setting	Low Temp.	SP1905-064	40 msec. (NA/ EU)
Mp Width Setting	Over Low Temp.	SP1905-130	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-054	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-063	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-038	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-040	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-182	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-193	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-033	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-035	100% (NA/ EU)

Special 6 (uncoated)

TITLE: Special 6: Thin Paper

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1108-065	170°C (NA)/ 175°C (EU)
	Simplex: FC	SP1108-066	170°C (NA)/ 175°C (EU)



Model: Aegis-P1/C1

Technical Bulletin

 Cal Bulletin
 PAGE: 28/66

 Date: 22-Jun-09
 No.: RG178053

Adjustable SP	Mode	SP No.	Default
	Duplex: B/W	SP1108-077	170°C (NA)/ 175°C (EU)
	Duplex: FC	SP1108-078	170°C (NA)/ 175°C (EU)
Fusing Motor Speed Correction	_	SP1909-074	0% (NA)/ -3% (EU)
Nip Width Setting	Low Temp.	SP1905-065	510 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-131	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-055	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-064	0 (NA/ EU)
	B/W: Front	SP2329-042	50 μA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-043	50 μA (NA/ EU)
Bias Setting	FC: Front	SP2329-044	70 HA (NA/ EU)
	FC: Back	SP2329-045	70 HA (NA/ EU)
DTD: Loading Edge	B/W: Front	SP2426-199	170% (NA/ EU)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-205	170% (NA/ EU)
Setting	FC: Front	SP2426-210	170% (NA/ EU)
Setting	FC: Back	SP2426-216	170% (NA/ EU)
DTD: Trailing Edge	B/W: Front	SP2428-037	100% (NA/ EU)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-038	100% (NA/ EU)
Setting	FC: Front	SP2428-039	100% (NA/ EU)
Setting	FC: Back	SP2428-040	100% (NA/ EU)
TITLE, Cassial C. Dla	•		

TITLE: Special 6: Plain

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1108-063	170°C (NA/ EU)
Fusing Tomp	Simplex: FC	SP1108-064	170°C (NA/ EU)
Fusing Temp.	Duplex: B/W	SP1108-075	170°C (NA/ EU)
	Duplex: FC	SP1108-076	170°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-075	-3% (NA/ EU)
Nin Width Cotting	Low Temp.	SP1905-066	510 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-132	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-056	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-065	0 (NA/ EU)
	B/W: Front	SP2329-042	50 μA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-043	50 μA (NA/ EU)
Bias Setting	FC: Front	SP2329-044	70 HA (NA/ EU)
	FC: Back	SP2329-045	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-200	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-206	170% (NA/ EU)
Setting	FC: Front	SP2426-211	170% (NA/ EU)
Setting	FC: Back	SP2426-217	170% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-037	100% (NA/ EU)



PAGE: 29/66 Date: 22-Jun-09 No.: RG178053

Model: Aegis-P1/C1		Date	e: 22-Jun-09	No.: RG178053
Adjustable SP	Mode	SP No.	Defau	
Bias Correction	B/W: Back	SP2428-038	100% (NA/ EU	
Setting	FC: Front	SP2428-039	100% (NA/ EU	,
Cetting	FC: Back	SP2428-040	100% (NA/ EU	
TITLE: Special 6: Mi	I.	01 2420-040	10070 (1477 EC	')
Adjustable SP	Mode	SP No.	Defau	ılt
Aujustable of	Simplex: B/W	SP1108-067	185°C (NA)/ 1	
		SP1108-068	185°C (NA)/ 1	· · · · · ·
Fusing Temp.	Simplex: FC		. ,	
	Duplex: B/W	SP1108-079	185°C (NA)/ 1	
Fusing Motor	Duplex: FC	SP1108-080	185°C (NA)/ 1	50°C (EU)
Fusing Motor Speed Correction	-	SP1909-076	0% (NA)/ -3%	(EU)
opeed Correction	Low Temp.	SP1905-067	330 msec. (NA	\/ E II\
Nip Width Setting	Over Low Temp.	SP1905-007	330 msec. (NA	
Jam 38 Detection	Over Low Tellip.	SF 1805-155	SSU IIISEC. (INF	V EU)
	-	SP1160-057	30 mm (NA/ E	U)
Timing Setting				
Fixed Paper Interval Setting	-	SP1207-066	0 (NA/ EU)	
interval octarig	B/W: Front	SP2329-042	50 μA (NA/ EU	1)
PTR: Standard	B/W: Back	SP2329-043	50 PA (NA/ EU	,
	FC: Front	SP2329-044	70 HA (NA/ EU	
	FC: Back	SP2329-045	70 HA (NA/ EU	,
			,	,
PTR: Leading Edge	B/W: Front	SP2426-201	170% (NA/ EU	,
Bias Correction	B/W: Back	SP2426-207	170% (NA/ EU	/
Setting	FC: Front	SP2426-212	170% (NA/ EU	
_	FC: Back	SP2426-218	170% (NA/ EU	,
PTR: Trailing Edge	B/W: Front	SP2428-037	100% (NA/ EU	
Bias Correction	B/W: Back	SP2428-038	100% (NA/ EU	,
Setting	FC: Front	SP2428-039	100% (NA/ EU	,
	FC: Back	SP2428-040	100% (NA/ EU)
TITLE: Special 6: Th				
Adjustable SP	Mode	SP No.	Defau	
	Simplex: B/W	SP1108-069	180°C (NA)/ 1	
Fusing Temp.	Simplex: FC	SP1108-070	180°C (NA)/ 1	
r doing romp.	Duplex: B/W	SP1108-081	180°C (NA)/ 1	
	Duplex: FC	SP1108-082	180°C (NA)/ 1	90°C (EU)
Fusing Motor Speed Correction	_	SP1909-077	0% (NA/ EU)	
Nin Width Cotting	Low Temp.	SP1905-068	330 msec. (NA	√EU)
Nip Width Setting	Over Low Temp.	SP1905-134	330 msec. (NA	√ EU)
Jam 38 Detection		CD1160 050	,	,
Timing Setting	_	SP1160-058	30 mm (NA/ E	0)
Fixed Paper		SP1207-067	0 (NA/ EU)	
Interval Setting		01 1201-001	O (INALO)	
PTR: Standard	B/W: Front	SP2329-042	50 HA (NA/ EL	
Bias Setting	B/W: Back	SP2329-043	50 HA (NA/ EU	J)



PAGE: 30/66 Date: 22-Jun-09 No.: RG178053

Model: Aegis-P1/C	1	Date: 22-Jun-09 No.: F			
Adjustable SP	Mode	SP No.	Defa	ult	
	FC: Front	SP2329-044	70 HA (NA/ EU	J)	
	FC: Back	SP2329-045	70 HA (NA/ EU	J)	
DTD: Looding Edge	B/W: Front	SP2426-202	170% (NA/ EU	J)	
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-208	170% (NA/ EU	١)	
Setting	FC: Front	SP2426-213	170% (NA/ EU	J)	
Setting	FC: Back	SP2426-219	· · · · · · · · · · · · · · · · · · ·		
PTR: Trailing Edge	B/W: Front	SP2428-037	<u> </u>		
Bias Correction	B/W: Back	SP2428-038	` `		
Setting	FC: Front	SP2428-039	· · · · · · · · · · · · · · · · · · ·	•	
Octung	FC: Back	SP2428-040	100% (NA/ EU	J)	
TITLE: Special 6: Th	ick 2				
Adjustable SP	Mode	SP No.	Defa		
	Simplex: B/W	SP1108-071		, ,	
Fusing Temp.	Simplex: FC	SP1108-072			
r daing remp.	Duplex: B/W	SP1108-083	, ,	, ,	
	Duplex: FC	SP1108-084	190°C (NA)/ 2	00°C (EU)	
Fusing Motor Speed Correction	_	SP1909-078	-3% (NA)/ -2%	6 (EU)	
Nin Midth Catting	Low Temp.	SP1905-069	40 msec. (NA	/ EU)	
Nip Width Setting	Over Low Temp.	SP1905-135		,	
Jam 38 Detection	•	SP1160-059	20 mm /NA/ E		
Timing Setting		SP 1160-059	30 mm (NA/ E	:0)	
Fixed Paper Interval Setting	_	SP1207-068	0 (NA/ EU)		
	B/W: Front	SP2329-042	50 HA (NA/ EU	J)	
PTR: Standard	B/W: Back	SP2329-043	50 HA (NA/ EI	J)	
Bias Setting	FC: Front	SP2329-044	70 HA (NA/ EU	J)	
	FC: Back	SP2329-045	70 HA (NA/ EU	J)	
DTD: Loading Edge	B/W: Front	SP2426-203	250% (NA/ EU	J)	
PTR: Leading Edge	B/W: Back	SP2426-209	•	•	
Bias Correction	FC: Front	SP2426-214	250% (NA/ EU	J)	
Setting	FC: Back	SP2426-220	250% (NA/ EU	J)	
DTD T ''' E !	B/W: Front	SP2428-037	100% (NA/ EU	J)	
PTR: Trailing Edge	B/W: Back	SP2428-038		•	
Bias Correction	FC: Front	SP2428-039	<u> </u>	,	
Setting	FC: Back	SP2428-040	,		
TITLE: Special 6: Th	TITLE: Special 6: Thick 3				
Adjustable SP	Mode	SP No.	Defai	ult	
,	Simplex: B/W	SP1108-073			
Fusing Temp.	Simplex: FC	SP1108-074	,	,	
Fusing Motor Speed Correction	-	SP1909-079		6 (EU)	
	Low Temp.	SP1905-070	40 msec. (NA	/ EU)	
Nip Width Setting	Over Low Temp.	SP1905-136		,	
Jam 38 Detection	-	SP1160-060	,	,	

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 31/66

Adjustable SP	Mode	SP No.	Default
Timing Setting			
Fixed Paper Interval Setting	_	SP1207-069	0 (NA/ EU)
PTR: Standard	B/W: Front		50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-044	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-204	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-215	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-037	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-039	100% (NA/ EU)

Coat 1

TITLE: Coat 1: Thin Paper

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-070	165°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-071	165°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1105-082	165°C (NA/ EU)
	Duplex: FC	SP1105-083	165°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-026	0% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-017	510 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-083	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-007	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-016	0 (NA/ EU)
	B/W: Front	SP2329-010	50 \(\text{NA} \) (NA/ EU)
PTR: Standard	B/W: Back	SP2329-011	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-012	70 HA (NA/ EU)
	FC: Back	SP2329-013	70 \textsquare (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-023	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-029	170% (NA/ EU)
Setting	FC: Front	SP2426-034	170% (NA/ EU)
Cotting	FC: Back	SP2426-040	170% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-005	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-006	180% (NA/ EU)
Setting	FC: Front	SP2428-007	100% (NA/ EU)
Cotting	FC: Back	SP2428-008	180% (NA/ EU)

TITLE: Coat 1: Plain

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-068	175°C (NA/ EU)
Fusing Tomp	Simplex: FC	SP1105-069	175°C (NA/ EU)
	Duplex: B/W	SP1105-080	175°C (NA/ EU)
	Duplex: FC	SP1105-081	175°C (NA/ EU)



 Ulletin
 PAGE: 32/66

 Date: 22-Jun-09
 No.: RG178053

Model: Aegis-P1/C	1		Date:	22-Jun-09	No.: RG178
Adjustable SP	Mode	SP N	0.	Defau	lt
Fusing Motor Speed Correction	-	SP1909-0)27	0% (NA/ EU)	
Nip Width Setting	Low Temp. Over Low Temp.	SP1905-0 SP1905-0		510 msec. (NA 510 msec. (NA	,
Jam 38 Detection Timing Setting	-	SP1160-0		30 mm (NA/ E	ŕ
Fixed Paper Interval Setting	-	SP1207-0	017	0 (NA/ EU)	
PTR: Standard Bias Setting	B/W: Front B/W: Back FC: Front FC: Back	SP2329-0 SP2329-0 SP2329-0 SP2329-0)11)12	50 HA (NA/ EL 50 HA (NA/ EL 70 HA (NA/ EL 70 HA (NA/ EL	J) J)
PTR: Leading Edge Bias Correction Setting	B/W: Front B/W: Back FC: Front FC: Back	SP2426-0 SP2426-0 SP2426-0 SP2426-0)30)35	170% (NA/ EU 170% (NA/ EU 170% (NA/ EU 170% (NA/ EU))
PTR: Trailing Edge Bias Correction Setting	B/W: Front B/W: Back FC: Front FC: Back	SP2428-0 SP2428-0 SP2428-0 SP2428-0	006 007	100% (NA/ EU 180% (NA/ EU 100% (NA/ EU 180% (NA/ EU)

TITLE: Coat 1: Middle Thick

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-072	180°C (NA)/ 185°C (EU)
Fusing Temp.	Simplex: FC	SP1105-073	180°C (NA)/ 185°C (EU)
rusing remp.	Duplex: B/W	SP1105-084	180°C (NA)/ 185°C (EU)
	Duplex: FC	SP1105-085	180°C (NA)/ 185°C (EU)
Fusing Motor		SP1909-028	0% (NA)/ -3% (EU)
Speed Correction		31 1909-020	0 % (NA)/ -3 % (LO)
Nip Width Setting	Low Temp.	SP1905-019	330 msec. (NA/ EU)
	Over Low Temp.	SP1905-085	330 msec. (NA/ EU)
Jam 38 Detection	_	SP1160-009	30 mm (NA/ EU)
Timing Setting		J. 1100 000	(2 = 5)
Fixed Paper	_	SP1207-018	0 (NA/ EU)
Interval Setting			` '
	B/W: Front	SP2329-010	50 PA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-011	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-012	70 HA (NA/ EU)
	FC: Back	SP2329-013	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-025	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-031	170% (NA/ EU)
Setting	FC: Front	SP2426-036	170% (NA/ EU)
Octung	FC: Back	SP2426-042	170% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-005	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-006	180% (NA/ EU)
Setting	FC: Front	SP2428-007	100% (NA/ EU)



Technical Bulletin **PAGE: 33/66**

Model: Aegis-P1/C	1	Date: 22-Jun-09 No.: RG1780			
Adjustable SP	Mode	SP No.	Defau	ult	
	FC: Back	SP2428-008	180% (NA/ EU	J)	
TITLE: Coat 1: Thick					
Adjustable SP	Mode	SP No.	Defa		
	Simplex: B/W	SP1105-074	180°C (NA)/ 1	· /	
Fusing Temp.	Simplex: FC	SP1105-075	180°C (NA)/ 1		
r doing romp.	Duplex: B/W	SP1105-086	180°C (NA)/ 1		
	Duplex: FC	SP1105-087	180°C (NA)/ 1	90°C (EU)	
Fusing Motor Speed Correction	-	SP1909-029	-1% (NA)/ 0%	(EU)	
Nip Width Setting	Low Temp.	SP1905-020	330 msec. (NA	¥/ EU)	
	Over Low Temp.	SP1905-086	330 msec. (NA	√EU)	
Jam 38 Detection Timing Setting	-	SP1160-010	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	_	SP1207-019	0 (NA/ EU)		
	B/W: Front	SP2329-010	50 HA (NA/ EU		
PTR: Standard	B/W: Back	SP2329-011	50 HA (NA/ EU	/	
Bias Setting	FC: Front	SP2329-012	70 HA (NA/ EU		
	FC: Back	SP2329-013	70 HA (NA/ EU	/	
PTR: Leading Edge	B/W: Front	SP2426-026	250% (NA/ EU	/	
Bias Correction	B/W: Back	SP2426-032	250% (NA/ EU	,	
Setting	FC: Front	SP2426-037	250% (NA/ EU	/	
5	FC: Back	SP2426-043	250% (NA/ EU	,	
PTR: Trailing Edge	B/W: Front	SP2428-005	100% (NA/ EU	•	
Bias Correction	B/W: Back	SP2428-006	180% (NA/ EU	,	
Setting	FC: Front	SP2428-007	100% (NA/ EU	<i>'</i>	
	FC: Back	SP2428-008	180% (NA/ EU	J)	
TITLE: Coat 1: Thick		OD Na	Defe	.14	
Adjustable SP	Mode	SP No.	Defau		
	Simplex: B/W	SP1105-076	190°C (NA/ El		
Fusing Temp.	Simplex: FC	SP1105-077	190°C (NA/ El	,	
	Duplex: B/W	SP1105-088	190°C (NA/ El	,	
Fusing Motor	Duplex: FC	SP1105-089	190°C (IVA/ EI	J)	
Fusing Motor Speed Correction	_	SP1909-030	-1% (NA)/ 0%		
Nip Width Setting	Low Temp.	SP1905-021	40 msec. (NA		
	Over Low Temp.	SP1905-087	40 msec. (NA	'EU)	
Jam 38 Detection Timing Setting	-	SP1160-011	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	_	SP1207-020	0 (NA/ EU)		
	B/W: Front	SP2329-010	50 HA (NA/ EU		
PTR: Standard	B/W: Back	SP2329-011	50 HA (NA/ El	,	
Bias Setting	FC: Front	SP2329-012	70 HA (NA/ EU		
	FC: Back	SP2329-013	70 HA (NA/ EU	J)	

Technical Bulletin

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

PAGE: 34/66

Adjustable SP	Mode	SP No.	Default
IDID: Looding Edge		SP2426-027	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-033	250% (NA/ EU)
Setting	FC: Front	SP2426-038	250% (NA/ EU)
Setting			250% (NA/ EU)
PTR: Trailing Edge Bias Correction Setting	B/W: Front		100% (NA/ EU)
	B/W: Back	SP2428-006	180% (NA/ EU)
	FC: Front	SP2428-007	100% (NA/ EU)
Setting	FC: Back	SP2428-008	180% (NA/ EU)

TITLE: Coat 1: Thick 3

IIILL. Coat 1. Thick	. 0		
Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1105-078	195°C (NA)/ 200°C (EU)
rusing remp.	Simplex: FC	SP1105-079	195°C (NA)/ 200°C (EU)
Fusing Motor		SP1909-031	0% (NA)/ -2% (EU)
Speed Correction		01 1909-001	0 % (IVA)/ -2 % (EO)
Nip Width Setting	Low Temp.	SP1905-022	40 msec. (NA/ EU)
TAID ANIGHT SETTING	Over Low Temp.	SP1905-088	40 msec. (NA/ EU)
Jam 38 Detection		SP1160-012	30 mm (NA/ EU)
Timing Setting		01 1100-012	30 mm (NA/ EO)
Fixed Paper		SP1207-021	0 (NA/ EU)
Interval Setting		01 1207-021	O (NA) LO)
PTR: Standard	B/W: Front	SP2329-010	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-012	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-028	250% (NA/ EU)
Bias Correction	FC: Front	SP2426-039	250% (NA/ EU)
Setting			,
PTR: Trailing Edge	B/W: Front	SP2428-005	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-007	100% (NA/ EU)

Coat 2

TITLE: Coat 2: Thin Paper

	r r apor		
Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-098	165°C (NA/ EU)
Fusing Tomp	Simplex: FC	SP1105-099	165°C (NA/ EU)
Fusing Temp.	Duplex: B/W	SP1105-110	165°C (NA/ EU)
	Duplex: FC	SP1105-111	165°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-032	-3% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-023	510 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-089	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-013	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-022	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-014	50 μA (NA/ EU)



Technical Bulletin PAGE: 35/66

Model: Aegis-P1/C1		Da	te: 22-Jun-09	No.: RG1780
Adjustable SP	Mode	SP No.	Defau	ılt
Bias Setting	B/W: Back	SP2329-015	50 μA (NA/ EU	J)
•	FC: Front	SP2329-016	70 HA (NA/ EU	J)
	FC: Back	SP2329-017	70 HA (NA/ EU	J)
OTD 1 1 51	B/W: Front	SP2426-045	170% (NA/ EL	J)
PTR: Leading Edge	B/W: Back	SP2426-051	170% (NA/ EL	
Bias Correction	FC: Front	SP2426-056	170% (NA/ EL	,
Setting	FC: Back	SP2426-062	170% (NA/ EL	,
	B/W: Front	SP2428-009	100% (NA/ EL	,
PTR: Trailing Edge	B/W: Back	SP2428-010	180% (NA/ EL	
Bias Correction	FC: Front	SP2428-011	100% (NA/ EL	,
Setting	FC: Back	SP2428-012	180% (NA/ EU	_
TITLE: Coat 2: Plain	O. Dack	01 2420-012	10070 (1474) EC	')
Adjustable SP	Mode	SP No.	Defau	ılt
Adjustable of	Simplex: B/W	SP1105-096	180°C (NA/ El	
	Simplex: FC	SP1105-090	180°C (NA/ EU	
Fusing Temp.	<u> </u>			
	Duplex: B/W	SP1105-108	180°C (NA/ EL	,
	Duplex: FC	SP1105-109	180°C (NA/ El	J)
Fusing Motor Speed Correction	_	SP1909-033	0% (NA/ EU)	
Nip Width Setting	Low Temp.	SP1905-024	510 msec. (NA	√EU)
NIP WIGHT Setting	Over Low Temp.	SP1905-090	510 msec. (NA	√EU)
Jam 38 Detection Fiming Setting	-	SP1160-014	30 mm (NA/ E	U)
Fixed Paper nterval Setting	-	SP1207-023	0 (NA/ EU)	
	B/W: Front	SP2329-014	50 HA (NA/ EU	J)
PTR: Standard	B/W: Back	SP2329-015	50 HA (NA/ EU	
Bias Setting	FC: Front	SP2329-016	70 HA (NA/ EU	,
Ŭ	FC: Back	SP2329-017	70 HA (NA/ EU	,
	B/W: Front	SP2426-046	170% (NA/ EL	,
PTR: Leading Edge	B/W: Back	SP2426-052	170% (NA/ EU	
Bias Correction	FC: Front	SP2426-057	170% (NA/ EU	/
Setting	FC: Back	SP2426-063	170% (NA/ EU	/
	B/W: Front	SP2428-009	100% (NA/ EU	,
PTR: Trailing Edge			`	•
Bias Correction	B/W: Back	SP2428-010	180% (NA/ EL	,
Setting	FC: Front	SP2428-011	100% (NA/ EL	
- O	FC: Back	SP2428-012	180% (NA/ EL	')
FITLE: Coat 2: Middl		ODA	Def	.14
Adjustable SP	Mode	SP No.	Defau	
	Simplex: B/W	SP1105-100	185°C (NA)/ 1	· · · · ·
Fusing Temp.	Simplex: FC	SP1105-101	185°C (NA)/ 1	
acing romp.	Duplex: B/W	SP1105-112	185°C (NA)/ 1	
	Duplex: FC	SP1105-113	185°C (NA)/ 1	75°C (EU)
Fusing Motor Speed Correction	-	SP1909-034	0% (NA/ EU)	



 Ulletin
 PAGE: 36/66

 Date: 22-Jun-09
 No.: RG178053

Model: Aegis-P1/C1	1		Date:	22-Jun-09	No.: RG178
Adjustable SP	Mode	SP N	0.	Defau	ılt
Nip Width Setting	Low Temp.	SP1905-0	025	330 msec. (NA	\/ EU)
Mp Width Setting	Over Low Temp.	SP1905-0	091	330 msec. (NA	\/ EU)
Jam 38 Detection Timing Setting	-	SP1160-0	015	30 mm (NA/ E	U)
Fixed Paper Interval Setting	-	SP1207-0)24	0 (NA/ EU)	
	B/W: Front	SP2329-0	014	50 ¼A (NA/ EU	J)
PTR: Standard	B/W: Back	SP2329-0	015	50 HA (NA/ EL	J)
Bias Setting	FC: Front	SP2329-0	016	70 HA (NA/ EL	J)
	FC: Back	SP2329-0	017	70 HA (NA/ EU	J)
PTR: Leading Edge	B/W: Front	SP2426-0	047	170% (NA/ EL	J)
Bias Correction	B/W: Back	SP2426-0	053	170% (NA/ EL	J)
	FC: Front	SP2426-0	058	170% (NA/ EU	J)
Setting	FC: Back	SP2426-0	064	170% (NA/ EU	J)
DTD: Trailing Edge	B/W: Front	SP2428-0	009	100% (NA/ EL	J)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-0	010	180% (NA/ EL	J)
Setting	FC: Front	SP2428-0	011	100% (NA/ EL	J)
Setting	FC: Back	SP2428-0	012	180% (NA/ EL	J)

TITLE: Coat 2: Thick 1

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-102	185°C (NA)/ 195°C (EU)
Eucina Tomp	Simplex: FC	SP1105-103	185°C (NA)/ 195°C (EU)
Fusing Temp.	Duplex: B/W	SP1105-114	185°C (NA)/ 195°C (EU)
	Duplex: FC	SP1105-115	185°C (NA)/ 195°C (EU)
Fusing Motor Speed Correction	_	SP1909-035	0% (NA)/ -2% (EU)
Nip Width Setting	Low Temp.	SP1905-026	330 msec. (NA)/ 40 msec. (EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-092	330 msec. (NA)/ 40 msec. (EU)
Jam 38 Detection Timing Setting	_	SP1160-016	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-025	0 (NA/ EU)
	B/W: Front	SP2329-014	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-015	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-016	70 HA (NA/ EU)
	FC: Back	SP2329-017	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-048	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-054	250% (NA/ EU)
Setting	FC: Front	SP2426-059	250% (NA/ EU)
Setting	FC: Back	SP2426-065	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-009	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-010	180% (NA/ EU)
Setting	FC: Front	SP2428-011	100% (NA/ EU)



PAGE: 37/66

Model: Aegis-P1/C1	Madely Apric D1/C	1		Deter	00 1 00	No : 00476	2050
FC: Back	Model: Aegis-P1/C	I		Date. 22-Jun-09		NO.: RG178	3053
Mode	Adjustable SP		SP N	lo.			Ì
Adjustable SP		1	SP2428-	012	180% (NA/ EU	J)	l
Simplex: B/W SP1105-104 195°C (NA)/ 190°C (EU)							
Fusing Temp. Simplex: FC Duplex: BWW SP1105-105 195°C (NA)/ 190°C (EU) Duplex: BWW SP1105-116 195°C (NA)/ 190°C (EU) Duplex: FC SP1105-117 195°C (NA)/ 190°C (EU) SP1909-036 -1% (NA/ EU) SP1909-036 -1% (NA/ EU) SP1909-036 -1% (NA/ EU) SP1905-093 40 msec. (NA/ EU) SP1905-093 40 msec. (NA/ EU) SP1106-017 30 mm (NA/ EU) SP1106-017 30 mm (NA/ EU) SP1106-017 30 mm (NA/ EU) SP1106-017 SP1207-026 O(NA/ EU) SP2239-015 SO IPA (NA/ EU) SP239-016 SO IPA (NA/ EU) SP2428-049 250% (NA/ EU) SP2428-049 250% (NA/ EU) SP2428-055 SO IPA (NA/ EU) SP2428-066 SO IPA (NA/ EU) SP2428-011 SO IPA (NA/ EU) SIMPLEX: FOR SP1105-106 SP3428-011 SO IPA (NA/ EU) SIMPLEX: FOR SP1105-106 SP3428-011 SO IPA (NA/ EU) SIMPLEX: FOR SP1105-106 SP36°C (NA)/ 200°C (EU) SIMPLEX: FOR SP1105-107 SP3428-012 SO IPA (NA/ EU) SIMPLEX: FOR SP1105-107 SP3428-019 SIMPLEX: FOR SP1105-107 SP3428-019 SIMPLEX: FOR SP1105-107 SP3428-019 SIMPLEX: FOR SP1105-106 SP3428-019 SP	Adjustable SP	Mode	SP N	lo.			Ì
Duplex: B/W Duplex: B/W Duplex: B/W Duplex: FC SP1105-116 195°C (NA)/ 190°C (EU)		Simplex: B/W	SP1105-	104	195°C (NA)/ 1	90°C (EU)	Ì
Duplex: B/W SP1105-116 195°C (NA)/ 190°C (EU)	Fusing Temp	Simplex: FC	SP1105-	105	195°C (NA)/ 1	90°C (EU)	Ì
Fusing Motor Speed Correction Speed Correctio	i using remp.	Duplex: B/W	SP1105-	116	195°C (NA)/ 19	90°C (EU)	Ì
Speed Correction		Duplex: FC	SP1105-	117	195°C (NA)/ 1	90°C (EU)	Ì
Name		-	SP1909-	036	-1% (NA/ EU)		
Setting	Nin Width Setting	Low Temp.	SP1905-	027	40 msec. (NA/	EU)	Ì
Timing Setting Fixed Paper Interval Setting Fixed Paper Interval Setting B/W: Front SP2329-014 S0 MA (NA/ EU) PTR: Standard Bias Setting FC: Front FC: Back SP2329-015 S0 MA (NA/ EU) FC: Back SP2329-016 FC: Front FC: Back SP2329-017 FC: Back SP2426-049 SP426-049 SP426-055 SP50% (NA/ EU) FC: Back SP2426-060 SP2426-060 SP0% FC: Front SP2426-060 SP2426-060 SP0% SP428-010 SP2428-010 SP2428-010 SP2428-011 SP2428-011 SP2428-011 SP2428-011 SP2428-012	Mip Width Setting	Over Low Temp.	SP1905-	093	40 msec. (NA/	EU)	Ì
Interval Setting		_	SP1160-	017	30 mm (NA/ E	U)	
Setting			SP1207-	026	O (NA/ ELI)		Ì
PTR: Standard B.W: Back SP2329-015 50 \(\text{PA} \) (NA/ EU) FC: Front SP2329-016 70 \(\text{PA} \) (NA/ EU) FC: Back SP2329-017 70 \(\text{PA} \) (NA/ EU) PTR: Leading Edge Bias Correction Setting B.W: Front SP2426-049 250% (NA/ EU) B.W: Back SP2426-055 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2428-009 100% (NA/ EU) FC: Back SP2428-009 100% (NA/ EU) FC: Back SP2428-010 180% (NA/ EU) FC: Back SP2428-011 100% (NA/ EU) FC: Back SP2428-012 180% (NA/ EU) FC:	Interval Setting				, ,		Ì
Bias Setting					\		Ì
FC: Back SP2329-017 70 HA (NA/ EU)			_				Ì
B/W: Front SP2426-049 250% (NA/ EU)	Bias Setting				` ,		Ì
Bias Correction Bias Correction Setting Bias Correction FC: Front SP2426-055 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2428-009 100% (NA/ EU) Bias Correction Setting Bias Correction Setting Bias Correction Setting Bias Correction SP2428-010 180% (NA/ EU) FC: Back SP2428-011 100% (NA/ EU) FC: Back SP2428-012 180% (NA/ EU) FC: Back SP1105-106 195°C (NA)/ 200°C (EU) Simplex: FC SP1105-107 195°C (NA)/ 200°C (EU) Fusing Motor SP1909-037 -2% (NA)/ -3% (EU) SP1909-037 -2% (NA/ EU) SP1905-028 40 msec. (NA/ EU) SP1905-094 40 msec. (NA/ EU) SP1160-018 30 mm (NA/ EU) SP1160-018 30 mm (NA/ EU) SP1160-018 SP1207-027 0 (NA/ EU) SP1207-027 0 (NA/ EU) SP1207-027 0 (NA/ EU) SP1207-027 50 PA (NA/ EU) SP1207-027			_		`	,	Ì
Bias Correction Setting FC: Front SP2426-060 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2426-066 250% (NA/ EU) FC: Back SP2428-009 100% (NA/ EU) FC: Back SP2428-010 180% (NA/ EU) FC: Front SP2428-010 180% (NA/ EU) FC: Back SP2428-011 100% (NA/ EU) FC: Back SP2428-012 180% (NA/ EU) FC:	PTR: Leading Edge				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	,	Ì
FC: Front SP2426-060 250% (NA/ EU)	Bias Correction				\\	,	Ì
PTR: Trailing Edge Bias Correction Setting B/W: Front SP2428-009 100% (NA/ EU)			SP2426-	060	`	,	Ì
Bias Correction					`	,	Ì
Bias Correction Setting	PTR: Trailing Edge		_		•		Ì
Setting			_		<u> </u>		Ì
TITLE: Coat 2: Thick 3					<u> </u>		Ì
Adjustable SP Mode SP No. Default Fusing Temp. Simplex: B/W SP1105-106 195°C (NA)/ 200°C (EU) Fusing Motor Speed Correction - SP1909-037 -2% (NA)/ -3% (EU) Nip Width Setting Low Temp. Details and setting Details are setting SP1905-028 SP1905-028 SP1905-094 SP1	Octung	FC: Back	SP2428-	012	180% (NA/ EU	J)	
Fusing Temp. Simplex: B/W SP1105-106 195°C (NA)/ 200°C (EU) Simplex: FC SP1105-107 195°C (NA)/ 200°C (EU) Fusing Motor Speed Correction - SP1909-037 -2% (NA)/ -3% (EU) Nip Width Setting Low Temp. SP1905-028 40 msec. (NA/ EU) Jam 38 Detection SP1905-094 40 msec. (NA/ EU) Jam 38 Detection SP1160-018 30 mm (NA/ EU) Fixed Paper SP1207-027 0 (NA/ EU) Fixed Paper SP1207-027 0 (NA/ EU) PTR: Standard B/W: Front SP2329-014 50 \(\text{PA} \) (NA/ EU) Bias Setting FC: Front SP2329-016 70 \(\text{PA} \) (NA/ EU) PTR: Leading Edge B/W: Front SP2426-050 250% (NA/ EU) FC: Front SP2426-061 250% (NA/ EU)		x 3					
Fusing Temp. Simplex: FC SP1105-107 195°C (NA)/ 200°C (EU)	Adjustable SP						Ì
Fusing Motor Speed Correction Nip Width Setting Low Temp. Over Low Temp. SP1905-028 SP1905-094 Fixed Paper Interval Setting PTR: Standard Bias Setting FC: Front SP2329-014 SP2426-050 SP250% (NA/ EU) SP1905-027 SP1905-028 FO: NA/ EU) FO: NA/ EU) FO: Front SP2426-061 FO: Front SP2426-061 FO: NA/ EU)	Fusing Temp	Simplex: B/W	SP1105-	106	195°C (NA)/ 20	00°C (EU)	Ì
Speed Correction	r dailig remp.	Simplex: FC	SP1105-	107	195°C (NA)/ 20	00°C (EU)	Ì
Over Low Temp. SP1905-094 40 msec. (NA/ EU) Jam 38 Detection Timing Setting Fixed Paper Interval Setting PTR: Standard Bias Setting FC: Front SP2329-014 SP2426-050 SP2426-061 SP2426-061 SP2426-061 SP250% (NA/ EU) SP2426-061 SP2426-061 SP2426-061 SP2426-061	_	-	SP1909-	037	-2% (NA)/ -3%	(EU)	
Jam 38 Detection Timing Setting Fixed Paper Interval Setting PTR: Standard Bias Setting FC: Front SP1905-094 40 msec. (NA/ EU) 30 mm (NA/ EU) 0 (NA/ EU) PTR: Standard SP2329-014 SP2329-014 SP2329-016 FC: Front SP2426-050 SP2426-050 SP2426-061 SP2426-061 SP2426-061 SP2426-061	Nin Width Setting	Low Temp.	SP1905-	028	40 msec. (NA/	EU)	Ì
Timing Setting SP1160-018 30 mm (NA/ EU) Fixed Paper Interval Setting SP1207-027 0 (NA/ EU) PTR: Standard B/W: Front SP2329-014 50 \(\text{PA} \) (NA/ EU) Bias Setting FC: Front SP2329-016 70 \(\text{PA} \) (NA/ EU) PTR: Leading Edge B/W: Front SP2426-050 250% (NA/ EU) Bias Correction Setting FC: Front SP2426-061 250% (NA/ EU)	Mip Width Setting	Over Low Temp.	SP1905-	094	40 msec. (NA/	EU)	Ì
Interval Setting		-	SP1160-	018	30 mm (NA/ E	U)	
Bias Setting FC: Front SP2329-016 70 \(\text{PA} \) (NA/ EU) PTR: Leading Edge B/W: Front SP2426-050 250% (NA/ EU) Bias Correction Setting SP2426-061 250% (NA/ EU)		_	SP1207-	027	0 (NA/ EU)		
PTR: Leading Edge B/W: Front SP2426-050 250% (NA/ EU) Bias Correction FC: Front SP2426-061 250% (NA/ EU)			SP2329-	014	50 HA (NA/ EL	J)	i
PTR: Leading Edge B/W: Front SP2426-050 250% (NA/ EU) Bias Correction FC: Front SP2426-061 250% (NA/ EU)	Bias Setting	FC: Front	SP2329-	016	70 HA (NA/ EL	J)	i
Setting FC: Front SP2426-061 250% (NA/ EU)	PTR: Leading Edge		SP2426-	050	250% (NA/ EU	J)	i
	Bias Correction	FC: Front	SP2426-	061	250% (NA/ EU	J)	
		B/W: Front	SP2428-	009	100% (NA/ EU	J)	İ



Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 38/66

Adjustable SP	Mode	SP No.	Default
Bias Correction Setting	FC: Front	SP2428-011	100% (NA/ EU)

Coat 3

TITLE: Coat 3: Thin Adjustable SP	Mode	SP No.	Default
/ tajaotable el	Simplex: B/W	SP1105-126	170°C (NA/ EU)
	Simplex: FC	SP1105-127	170°C (NA/ EU)
Fusing Temp.	Duplex: B/W	SP1105-138	170°C (NA/ EU)
	Duplex: FC	SP1105-139	170°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-038	0% (NA/ EU)
Vin Width Catting	Low Temp.	SP1905-029	510 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-095	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-019	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-028	0 (NA/ EU)
	B/W: Front	SP2329-018	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-019	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-020	70 HA (NA/ EU)
	FC: Back	SP2329-021	70 HA (NA/ EU)
DTD: Looding Edge	B/W: Front	SP2426-067	170% (NA/ EU)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-073	170% (NA/ EU)
Setting	FC: Front	SP2426-078	170% (NA/ EU)
Setting	FC: Back	SP2426-084	170% (NA/ EU)
DTD: Trailing Edge	B/W: Front	SP2428-013	100% (NA/ EU)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-014	180% (NA/ EU)
Setting	FC: Front	SP2428-015	100% (NA/ EU)
Octurig	FC: Back	SP2428-016	180% (NA/ EU)

TITLE: Coat 3: Plain

Adjustable SP	Mode	SP No.	Default
_	Simplex: B/W	SP1105-124	175°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-125	175°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1105-136	175°C (NA/ EU)
	Duplex: FC	SP1105-137	175°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-039	0% (NA)/ -3% (EU)
Nip Width Setting	Low Temp.	SP1905-030	330 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-096	330 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-020	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-029	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-018	50 HA (NA/ EU)



PAGE: 39/66

Model: Aegis-P1/C1	P1/C1 Date: 22-Jun-09 No.: RG17805			
Adjustable SP	Mode	SP No.	Defau	ult
Bias Setting	B/W: Back	SP2329-019	50 μA (NA/ El	J)
	FC: Front	SP2329-020	70 HA (NA/ EU	J)
	FC: Back	SP2329-021	70 HA (NA/ EU	J)
PTR: Leading Edge	B/W: Front	SP2426-068	170% (NA/ EU	
Bias Correction	B/W: Back	SP2426-074	170% (NA/ EU	,
Setting	FC: Front	SP2426-079	170% (NA/ EU	J)
Setting	FC: Back	SP2426-085	170% (NA/ EU	J)
DTD: Trailing Edge	B/W: Front	SP2428-013	100% (NA/ EL	
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-014	180% (NA/ EL	J)
Setting	FC: Front	SP2428-015	100% (NA/ EL	J)
Octing	FC: Back	SP2428-016	180% (NA/ EU	J)
TITLE: Coat 3: Midd				
Adjustable SP	Mode	SP No.	Defau	
	Simplex: B/W	SP1105-128	190°C (NA)/ 1	85°C (EU)
Fusing Temp.	Simplex: FC	SP1105-129	190°C (NA)/ 1	85°C (EU)
daing remp.	Duplex: B/W	SP1105-140	190°C (NA)/ 1	, ,
	Duplex: FC	SP1105-141	190°C (NA)/ 1	85°C (EU)
Fusing Motor Speed Correction	-	SP1909-040	-3% (NA)/ 0%	(EU)
Nin Width Sotting	Low Temp.	SP1905-031	330 msec. (NA	¥/ EU)
Nip Width Setting	Over Low Temp.	SP1905-097	330 msec. (NA	¥/ EU)
Jam 38 Detection Timing Setting	-	SP1160-021	30 mm (NA/ E	U)
Fixed Paper Interval Setting	_	SP1207-030	0 (NA/ EU)	
	B/W: Front	SP2329-018	50 HA (NA/ EU	
PTR: Standard	B/W: Back	SP2329-019	50 HA (NA/ EU	J)
Bias Setting	FC: Front	SP2329-020	70 HA (NA/ EU	J)
	FC: Back	SP2329-021	70 HA (NA/ EU	J)
PTR: Leading Edge	B/W: Front	SP2426-069	170% (NA/ EL	
Bias Correction	B/W: Back	SP2426-075	170% (NA/ EL	J)
Setting	FC: Front	SP2426-080	170% (NA/ EL	J)
	FC: Back	SP2426-086	170% (NA/ EL	/
PTR: Trailing Edge	B/W: Front	SP2428-013	100% (NA/ EU	J)
Bias Correction	B/W: Back	SP2428-014	180% (NA/ EU	J)
Setting	FC: Front	SP2428-015	100% (NA/ EL	J)
	FC: Back	SP2428-016	180% (NA/ EL	J)
TITLE: Coat 3: Thick			1	
Adjustable SP	Mode	SP No.	Defau	
	Simplex: B/W	SP1105-130	190°C (NA)/ 1	
Fusing Temp.	Simplex: FC	SP1105-131	190°C (NA)/ 1	
. admig Tomp.	Duplex: B/W	SP1105-142	190°C (NA)/ 1	
	Duplex: FC	SP1105-143	190°C (NA)/ 1	95°C (EU)
Fusing Motor	_	SP1909-041	-1% (NA)/ 0%	(FU)
Speed Correction		5. 1000 0 4 1	1 /0 (14/1)/ 0 /0	(-0)



180% (NA/ EU)

100% (NA/ EU)

180% (NA/ EU)

PAGE: 40/66 No.: RG178053

Model: Aegis-P1/C1			Date:	No.: RG178	
Adjustable SP	Mode	SP N	lo.	Defau	ılt
Nip Width Setting	Low Temp.	SP1905-	032	330 msec. (NA msec. (EU)	A)/ 40
Nip Width Setting	Over Low Temp.	SP1905-0	098	330 msec. (NA)/ 40 msec. (EU)	
Jam 38 Detection Timing Setting	-	SP1160-	022	30 mm (NA/ E	U)
Fixed Paper Interval Setting	-	SP1207-0	031	0 (NA/ EU)	
	B/W: Front	SP2329-0	018	50 HA (NA/ EU	_
PTR: Standard	B/W: Back	SP2329-0	019	50 μA (NA/ EU	J)
Bias Setting	FC: Front	SP2329-0	020	70 μA (NA/ EU	J)
	FC: Back	SP2329-0	021	70 HA (NA/ EL	J)
DTD: Loading Edge	B/W: Front	SP2426-0	070	250% (NA/ EU	J)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-0	076	250% (NA/ EL	J)
Setting	FC: Front	SP2426-0	081	250% (NA/ EU	J)
Setting	FC: Back	SP2426-0	087	250% (NA/ EU	J)
DTD: Trailing Edge	B/W: Front	SP2428-0	013	100% (NA/ EL	J)
PTR: Trailing Edge	B/W· Back	SP2428-	014	180% (NA/ FL	J)

SP2428-014

SP2428-015

SP2428-016

TITLE: Coat 3: Thick 2

Bias Correction

Setting

B/W: Back

FC: Front

FC: Back

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-132	195°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-133	195°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1105-144	195°C (NA/ EU)
	Duplex: FC	SP1105-145	195°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-042	-3% (NA)/ 0% (EU)
•	Low Temp.	SP1905-033	40 msec. (NA/ EU)
Nip Width Setting	Over Low Temp.	SP1905-099	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-023	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-032	0 (NA/ EU)
	B/W: Front	SP2329-018	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-019	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-020	70 HA (NA/ EU)
	FC: Back	SP2329-021	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-071	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-077	250% (NA/ EU)
Setting	FC: Front	SP2426-082	250% (NA/ EU)
Setting	FC: Back	SP2426-088	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-013	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-014	180% (NA/ EU)
Setting	FC: Front	SP2428-015	100% (NA/ EU)

RICOH

Technical Bulletin

No.: RG178053

PAGE: 41/66

Model: Aegis-P1/C1	Date: 22-Jun-09			No.: RG178	
Adjustable SP	Mode	SP N	0.	Defau	lt
	FC: Back	SP2428-0	016	180% (NA/ EU)
TITLE: Coat 3: Thick	3				
Adjustable SP	Mode	SP N	0.	Defau	lt
Fusing Temp.	Simplex: B/W	SP1105-	134	200°C (NA)/ 19	95°C (EU)
r daing remp.	Simplex: FC	SP1105-	135	200°C (NA)/ 19	95°C (EU)
Fusing Motor Speed Correction	-	SP1909-0	043	0% (NA/ EU)	
Nip Width Setting	Low Temp.	SP1905-0	034	40 msec. (NA/	EU)
Mp Width Setting	Over Low Temp.	SP1905-1	100	40 msec. (NA/	EU)
Jam 38 Detection Timing Setting	-	SP1160-0	024	30 mm (NA/ E	U)
Fixed Paper Interval Setting	-	SP1207-0	033	0 (NA/ EU)	
PTR: Standard	B/W: Front	SP2329-0	018	50 MA (NA/ EL	J)
Bias Setting	FC: Front	SP2329-0	020	70 HA (NA/ EL	J)
PTR: Leading Edge	B/W: Front	SP2426-0	072	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-0	083	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-0	013	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-0	015	100% (NA/ EU)

Special 1 (coated)

_		_	\sim	Special	1 1		\mathbf{m}		n	
	 1 6		•	macia			3 11	าาท	PG	nar
	 		L	pecia.	ιл	•	11	LLLL .	LC	aper

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-154	170°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-155	170°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1105-166	170°C (NA/ EU)
	Duplex: FC	SP1105-167	170°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-044	-3% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-035	510 msec. (NA/ EU)
inp widin setting	Over Low Temp.	SP1905-101	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	_	SP1160-025	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-034	0 (NA/ EU)
	B/W: Front	SP2329-022	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-023	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-024	70 HA (NA/ EU)
	FC: Back	SP2329-025	70 HA (NA/ EU)
DTD: Loading Edge	B/W: Front	SP2426-089	170% (NA/ EU)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-095	170% (NA/ EU)
Setting	FC: Front	SP2426-100	170% (NA/ EU)
Setting	FC: Back	SP2426-106	170% (NA/ EU)



PAGE: 42/66

Model: Aegis-P1/C1	1	Date:	Date: 22-Jun-09 No.: R			
Adjustable SP	Mode	SP N	0.	Defau	lt	
DTD: Trailing Edge	B/W: Front	SP2428-0	017	100% (NA/ EU)	
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-0	018	180% (NA/ EU)		
Setting	FC: Front	SP2428-0	019	100% (NA/ EU)	
Setting	FC: Back	SP2428-0	020	180% (NA/ EU)	
TITLE: Special 1: Pla	ain					
Adjustable SP	Mode	SP N		Defau		
	Simplex: B/W	SP1105-	152	185°C (NA)/ 18	30°C (EU)	
Fusing Temp.	Simplex: FC	SP1105-	153	185°C (NA)/ 18	30°C (EU)	
rusing remp.	Duplex: B/W	SP1105-	164	185°C (NA)/ 18	30°C (EU)	
	Duplex: FC	SP1105-	165	185°C (NA)/ 18	30°C (EU)	
Fusing Motor	_	SP1909-	045	-1% (NA)/ 0%	(EU)	
Speed Correction	Law Taren	CD4005 /	226	220 (NIA	/ F II)	
Nip Width Setting	Low Temp.	SP1905-0		330 msec. (NA		
Iom 20 Detection	Over Low Temp.	SP1905-	102	330 msec. (NA	V EU)	
Jam 38 Detection Timing Setting	-	SP1160-	026	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	-	SP1207-0	035	0 (NA/ EU)		
interval cetting	B/W: Front	SP2329-0	122	50 μA (NA/ EL	I)	
PTR: Standard	B/W: Back	SP2329-0		50 PA (NA/ EU)		
Bias Setting	FC: Front	SP2329-0		70 PA (NA/ EL		
Dias octaing	FC: Back	SP2329-		70 PA (NA/ EL	/	
	B/W: Front	SP2426-0		170% (NA/ EU		
PTR: Leading Edge	B/W: Back	SP2426-0		170% (NA/ EU		
Bias Correction	FC: Front	SP2426-		170% (NA/ EU		
Setting	FC: Back	SP2426-		170% (NA/ EU		
	B/W: Front	SP2428-0		100% (NA/ EU		
PTR: Trailing Edge	B/W: Back	SP2428-0		180% (NA/ EU	,	
Bias Correction	FC: Front	SP2428-0		100% (NA/ EU	,	
Setting	FC: Back	SP2428-0		180% (NA/ EU	_	
TITLE: Special 1: Mi	I .	0	<u></u>	1.0070 (1.1.1.2.20		
Adjustable SP	Mode	SP N	0.	Defau	lt	
- ragaretamene	Simplex: B/W	SP1105-		185°C (NA/ EU		
	Simplex: FC	SP1105-		185°C (NA/ EU	,	
Fusing Temp.	Duplex: B/W	SP1105-		185°C (NA/ EU		
	Duplex: FC	SP1105-		185°C (NA/ EU		
Fusing Motor Speed Correction	-	SP1909-0		-3% (NA)/ -1%	,	
•	Low Temp.	SP1905-0	าว7	330 msec. (NA	/ FII)	
Nip Width Setting	Over Low Temp.	SP1905-		330 msec. (NA		
Jam 38 Detection		SP1160-027		30 mm /NA/ E	(1)	
Timing Setting		37 100-1	JZ1	30 mm (NA/ E	U)	
Fixed Paper	_	SP1207-	036	0 (NA/ EU)		
Interval Setting PTR: Standard	B/W: Front	SP2329-0		50 μA (NA/ EL	J)	
i iiv. Otandaru	PIVV. I TOTIL	01 2029-	<i></i>	OUT A LIVA LC	' /	



PAGE: 43/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG			No.: RG1780	53	
Adjustable SP	Mode	SP No.	Defa	ult	
Bias Setting	B/W: Back	SP2329-023	50 HA (NA/ E	U)	
	FC: Front	SP2329-024	70 HA (NA/ E	U)	
	FC: Back	SP2329-025	70 HA (NA/ E	U)	
PTR: Leading Edge	B/W: Front	SP2426-091	170% (NA/ El		
Bias Correction	B/W: Back	SP2426-097	170% (NA/ EU	,	
Setting	FC: Front	SP2426-102	170% (NA/ El		
	FC: Back	SP2426-108	170% (NA/ EU	•	
PTR: Trailing Edge	B/W: Front	SP2428-017	100% (NA/ EU	_	
Bias Correction	B/W: Back	SP2428-018	180% (NA/ EU		
Setting	FC: Front	SP2428-019	100% (NA/ EU		
	FC: Back	SP2428-020	180% (NA/ El	J)	
TITLE: Special 1: Th		00.11		14	
Adjustable SP	Mode	SP No.	Defa		
	Simplex: B/W	SP1105-158	195°C (NA/ E		
Fusing Temp.	Simplex: FC	SP1105-159	195°C (NA/ E	,	
	Duplex: B/W	SP1105-170	195°C (NA/ E	,	
Euripe Mater	Duplex: FC	SP1105-171	195°C (NA/ E	0)	
Fusing Motor Speed Correction	_	SP1909-047	-2% (NA)/ 0%	(EU)	
Nip Width Setting	Low Temp.	SP1905-038	40 msec. (NA msec. (EU))/ 330	
Nip Width Setting	Over Low Temp.	SP1905-104	40 msec. (NA msec. (EU))/ 330	
Jam 38 Detection Timing Setting	-	SP1160-028	30 mm (NÁ)/ (NA/ EU)	15 mm	
Fixed Paper Interval Setting	-	SP1207-037	0 (NA/ EU)		
	B/W: Front	SP2329-022	50 HA (NA/ E	U)	
PTR: Standard	B/W: Back	SP2329-023	50 HA (NA/ E	U)	
Bias Setting	FC: Front	SP2329-024	70 HA (NA/ E	U)	
	FC: Back	SP2329-025	70 HA (NA/ E	U)	
PTR: Leading Edge	B/W: Front	SP2426-092	250% (NA/ El	J)	
Bias Correction	B/W: Back	SP2426-098	250% (NA/ El	J)	
Setting	FC: Front	SP2426-103	250% (NA/ El		
Cetting	FC: Back	SP2426-109	250% (NA/ El	,	
PTR: Trailing Edge	B/W: Front	SP2428-017	100% (NA/ El		
Bias Correction	B/W: Back	SP2428-018	180% (NA/ EU	,	
Setting	FC: Front	SP2428-019	100% (NA/ EU	•	
	FC: Back	SP2428-020	180% (NA/ El	J)	
TITLE: Special 1: Th					
Adjustable SP	Mode	SP No.	Defa		
	Simplex: B/W	SP1105-160	200°C (NA)/ 1	· /	
Fusing Temp.	Simplex: FC	SP1105-161	200°C (NA)/ 1	` /	
1 2 1 3 1 2 1 1 P	Duplex: B/W	SP1105-172	200°C (NA)/ 1		
	Duplex: FC	SP1105-173	200°C (NA)/ 1	95°C (EU)	

RICOH

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 44/66

Adjustable SP	Mode	SP No.	Default
Fusing Motor Speed Correction	-	SP1909-048	0% (NA)/ -2% (EU)
Nip Width Setting	Low Temp.	SP1905-039	40 msec. (NA/ EU)
pg	Over Low Temp.	SP1905-105	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-029	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-038	0 (NA/ EU)
	B/W: Front	SP2329-022	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-023	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-024	70 HA (NA/ EU)
	FC: Back	SP2329-025	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-093	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-099	250% (NA/ EU)
Setting	FC: Front	SP2426-104	250% (NA/ EU)
Setting	FC: Back	SP2426-110	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-017	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-018	180% (NA/ EU)
Setting	FC: Front	SP2428-019	100% (NA/ EU)
Cotting	FC: Back	SP2428-020	180% (NA/ EU)

TITLE: Special 1: Thick 3

Adjustable SP	Mode	SP No.	Default
Fusing Tomp	Simplex: B/W	SP1105-162	195°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-163	195°C (NA/ EU)
Fusing Motor Speed Correction	-	SP1909-049	-3% (NA)/ -2% (EU)
Nip Width Setting	Low Temp.	SP1905-040	40 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-106	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-030	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-039	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-022	50 MA (NA/ EU)
Bias Setting	FC: Front	SP2329-024	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-094	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-105	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-017	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-019	100% (NA/ EU)

Special 2 (coated)

TITLE.	امندمدا	1 0. Th:-	. Da
	pecia	l 2: Thir	ı Paper

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1105-182	175°C (NA/ EU)



Technical Bulletin PAGE: 45/66

Model: Aegis-P1/C	lodel: Aegis-P1/C1 Date: 22-Jun-09			No.: RG178		
Adjustable SP	Mode	SP No	0.		Defau	ılt
	Simplex: FC	SP1105-1	83	175°C	(NA/ EL	J)
	Duplex: B/W	SP1105-1	94	175°C	(NA/ EU	J)
	Duplex: FC	SP1105-1	95	175°C	(NA/ EL	J)
Fusing Motor Speed Correction	-	SP1909-0	50 -	-3% (N	A/ EU)	
•	Low Temp.	SP1905-0)41	510 ms	ec. (NA	V EU)
Nip Width Setting	Over Low Temp.	SP1905-1			ec. (NA	
Jam 38 Detection Timing Setting	-	SP1160-0)31	30 mm	(NA/ E	U)
Fixed Paper Interval Setting	_	SP1207-0)40	O (NA/	EU)	
<u> </u>	B/W: Front	SP2329-0	26	50 μ _A ((NA/ EL	J)
PTR: Standard	B/W: Back	SP2329-0)27	50 μA (NA/ EL	J)
Bias Setting	FC: Front	SP2329-0			NA/ EL	
	FC: Back	SP2329-0	29	70 HA (NA/ EL	J)
DTD: Loading Edge	B/W: Front	SP2426-1	11	170% (NA/ EU	l)
PTR: Leading Edge Bias Correction	B/W: Back	SP2426-1	17	170% (NA/ EU)
Setting	FC: Front	SP2426-1	22	170% (NA/ EU)
Setting	FC: Back	SP2426-1			NA/ EU	
DTD: Trailing Edge	B/W: Front	SP2428-0)21	100% (NA/ EU)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-0)22	180% (NA/ EU)
Setting	FC: Front	SP2428-0)23	100% (NA/ EU)
Setting	FC: Back	SP2428-0)24	180% (NA/ EU)
TITLE: Special 2: Pla	ain					
Adjustable SP	Mode	SP No	0.		Defau	ilt
	Simplex: B/W	SP1105-1			(NA/ EL	,
Fusing Temp.	Simplex: FC	SP1105-1			(NA/ EL	,
rusing remp.	Duplex: B/W	SP1105-1	92	180°C	(NA/ EL	J)
	Duplex: FC	SP1105-1	93	180°C	(NA/ EL	J)
Fusing Motor Speed Correction	_	SP1909-0)51 -	-3% (N	A)/ -1%	(EU)
•	Low Temp.	SP1905-0)42	330 ms	ec. (NA	v EU)
Nip Width Setting	Over Low Temp.	SP1905-1			ec. (NA	
Jam 38 Detection Timing Setting	_	SP1160-0	32	30 mm	(NA/ E	U)
Fixed Paper Interval Setting	_	SP1207-0)41 () (NA/	EU)	
	B/W: Front	SP2329-0	26	50 HA ((NA/ EL	J)
PTR: Standard	B/W: Back	SP2329-0)27	50 μ _A (NA/ EL	J)
Bias Setting	FC: Front	SP2329-0	28	70 HA (NA/ EL	J)
	FC: Back	SP2329-0			NA/ EL	
DTD: Landing Ed	B/W: Front	SP2426-1			NA/ EU	_
PTR: Leading Edge	B/W: Back	SP2426-1		•	NA/ EU	•
Bias Correction	FC: Front	SP2426-1			NA/ EU	,
Setting	FC: Back	SP2426-1			NA/ EU	,



PAGE: 46/66

Model: Aegis-P1/C1			e: 22-Jun-09	No.: RG17805
Adjustable SP	Mode	SP No.	Defau	
DTD: Trailing Edge	B/W: Front	SP2428-021	100% (NA/ EU	l)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-022	180% (NA/ EU	1)
	FC: Front	SP2428-023	100% (NA/ EU	l)
Setting	FC: Back	SP2428-024	180% (NA/ EU	J)
TITLE: Special 2: Mi	ddle Thick			
Adjustable SP	Mode	SP No.	Defau	ılt
,	Simplex: B/W	SP1105-184	190°C (NA/ EU	J)
Fraince Towns	Simplex: FC	SP1105-185	190°C (NA/ EU	J)
Fusing Temp.	Duplex: B/W	SP1105-196	190°C (NA/ EU	
	Duplex: FC	SP1105-197	190°C (NA/ EU	J)
Fusing Motor	•		,	,
Speed Correction	-	SP1909-052	0% (NA/ EU)	
Nin Width Catting	Low Temp.	SP1905-043	40 msec. (NA/	EU)
Nip Width Setting	Over Low Temp.	SP1905-109	40 msec. (NA/	EU)
Jam 38 Detection Timing Setting	-	SP1160-033	30 mm (NA/ E	U)
Fixed Paper Interval Setting	-	SP1207-042	0 (NA/ EU)	
intorvar couring	B/W: Front	SP2329-026	50 μA (NA/ EU	1)
PTR: Standard	B/W: Florit	SP2329-027	50 HA (NA/ EU	,
Bias Setting	FC: Front	SP2329-028	70 HA (NA/ EU	,
Dias Setting	FC: Back	SP2329-029	70 HA (NA/ EU	/
	B/W: Front	SP2426-113	170% (NA/ EU	
PTR: Leading Edge	B/W: Back	<u> </u>	`	,
Bias Correction		SP2426-119	170% (NA/ EU	
Setting	FC: Front	SP2426-124	170% (NA/ EU	
	FC: Back	SP2426-130	170% (NA/ EU	
PTR: Trailing Edge	B/W: Front	SP2428-021	100% (NA/ EU	,
Bias Correction	B/W: Back	SP2428-022	180% (NA/ EU	,
Setting	FC: Front	SP2428-023	100% (NA/ EU	/
	FC: Back	SP2428-024	180% (NA/ EU)
TITLE: Special 2: Th				
Adjustable SP	Mode	SP No.	Defau	
	Simplex: B/W	SP1105-186	200°C (NA/ EU	,
Fusing Temp.	Simplex: FC	SP1105-187	200°C (NA/ EU	J)
rusing remp.	Duplex: B/W	SP1105-198	200°C (NA/ EU	J)
	Duplex: FC	SP1105-199	200°C (NA/ EU	J)
Fusing Motor Speed Correction	-	SP1909-053	0% (NA/ EU)	
	Low Temp.	SP1905-044	40 msec. (NA) msec. (EU)	/ 330
Nip Width Setting	Over Low Temp.	SP1905-110	40 msec. (NA) msec. (EU)	/ 330
Jam 38 Detection Timing Setting	_	SP1160-034	30 mm (NA/ E	U)
Fixed Paper	_	SP1207-043	0 (NA/ EU)	
i woa i apoi	İ	JI 1201 UTU		



Model: Aegis-P1/C1			Oate: 22-Jun-09	No.: RG17805
Adjustable SP	Mode	SP No.	Defa	ult
nterval Setting				
	B/W: Front	SP2329-02	6 50 HA (NA/ EI	J)
PTR: Standard	B/W: Back	SP2329-02		
Bias Setting	FC: Front	SP2329-02	8 70 HA (NA/ EI	J)
· ·	FC: Back	SP2329-02	<u> </u>	
TD	B/W: Front	SP2426-11	4 250% (NA/ EU	J)
TR: Leading Edge	B/W: Back	SP2426-12	,	•
Bias Correction Setting	FC: Front	SP2426-12	· · · · · · · · · · · · · · · · · · ·	,
	FC: Back	SP2426-13	`	_
OTD TARREST ENGLISH	B/W: Front	SP2428-02	1 100% (NA/ EU	J)
PTR: Trailing Edge	B/W: Back	SP2428-02	<u> </u>	
Bias Correction	FC: Front	SP2428-02		,
Setting	FC: Back	SP2428-02	\	J)
TITLE: Special 2: Th	ick 2	<u>'</u>		
Adjustable SP	Mode	SP No.	Defa	ult
,	Simplex: B/W	SP1105-18		
· -	Simplex: FC	SP1105-18	` '	
Fusing Temp.	Duplex: B/W	SP1105-20	, ,	. ,
	Duplex: FC	SP1105-20	` '	
using Motor	,			` '
Speed Correction	_	SP1909-05	0% (NA)/ -3%	(EU)
lin Midth Catting	Low Temp.	SP1905-04	5 40 msec. (NA	/ EU)
lip Width Setting	Over Low Temp.	SP1905-11	1 40 msec. (NA	/ EU)
am 38 Detection		SP1160-03	E 20 mm /NA / E	7.11
iming Setting	_	SP 1100-03	30 mm (NA/ E	:0)
ixed Paper		SP1207-04	4 0 (NA / ELI)	
nterval Setting	_	SP 1207-04	4 0 (NA/ EU)	
	B/W: Front	SP2329-02	6 50 HA (NA/ EI	J)
PTR: Standard	B/W: Back	SP2329-02	7 50 ^H A (NA/ EI	J)
Bias Setting	FC: Front	SP2329-02	8 70 HA (NA/ EI	J)
	FC: Back	SP2329-02	9 70 HA (NA/ EI	J)
TD: Looding Edge	B/W: Front	SP2426-11	5 250% (NA/ EU	J)
PTR: Leading Edge	B/W: Back	SP2426-12	1 250% (NA/ EU	J)
Bias Correction Setting	FC: Front	SP2426-12	6 250% (NA/ EL	J)
betting	FC: Back	SP2426-13	2 250% (NA/ EU	J)
OTD: Trailing Edge	B/W: Front	SP2428-02	1 100% (NA/ EL	J)
PTR: Trailing Edge	B/W: Back	SP2428-02	2 180% (NA/ EL	J)
sias Correction	FC: Front	SP2428-02	3 100% (NA/ EL	J)
Setting	FC: Back	SP2428-02	4 180% (NA/ EL	J)
TITLE: Special 2: Th	ick 3		,	,
Adjustable SP	Mode	SP No.	Defa	ult
	Simplex: B/W	SP1105-19		
Fusing Temp.	Simplex: FC	SP1105-19		
using Motor				
_	-	SP1909-05	55 -2% (NA)/ -3%	n (I=U)

RICOH

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 48/66

Adjustable SP	Mode	SP No.	Default
Nip Width Setting	Low Temp.	SP1905-046	40 msec. (NA/ EU)
INIP WIGHT Setting	Over Low Temp.	SP1905-112	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-036	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-045	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-026	50 \(\text{PA} \) (NA/ EU)
Bias Setting	FC: Front	SP2329-028	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-116	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-127	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-021	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-023	100% (NA/ EU)

Special 3 (coated)

Ш	ILE:	S	pecial	3:	Th1	n P	'ap	er

Adjustable SP	Mode	SP No.	Default
	Simplex: B/W	SP1105-210	180°C (NA/ EU)
Fusing Temp.	Simplex: FC	SP1105-211	180°C (NA/ EU)
rusing remp.	Duplex: B/W	SP1105-222	180°C (NA/ EU)
	Duplex: FC	SP1105-223	180°C (NA/ EU)
Fusing Motor Speed Correction	_	SP1909-056	-3% (NA/ EU)
Nip Width Setting	Low Temp.	SP1905-047	510 msec. (NA/ EU)
inp widin setting	Over Low Temp.	SP1905-113	510 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-037	30 mm (NA/ EU)
Fixed Paper Interval Setting	_	SP1207-046	0 (NA/ EU)
	B/W: Front	SP2329-030	50 HA (NA/ EU)
PTR: Standard	B/W: Back	SP2329-031	50 HA (NA/ EU)
Bias Setting	FC: Front	SP2329-032	70 HA (NA/ EU)
	FC: Back	SP2329-033	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-133	170% (NA/ EU)
Bias Correction	B/W: Back	SP2426-139	170% (NA/ EU)
Setting	FC: Front	SP2426-144	170% (NA/ EU)
Cetting	FC: Back	SP2426-150	170% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-025	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-026	180% (NA/ EU)
Setting	FC: Front	SP2428-027	100% (NA/ EU)
Setting	FC: Back	SP2428-028	180% (NA/ EU)

TITLE: Special 3: Plain

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1105-208	190°C (NA)/ 180°C (EU)



Technical Bulletin PAGE: 49/66

Model: Aegis-P1/C1		1	Date: 22-Jun-09 No.:		No.: RG17	805
Adjustable SP	Mode	SP No).	Defau	lt	
	Simplex: FC	SP1105-20		190°C (NA)/ 18		
	Duplex: B/W	SP1105-22	20	190°C (NA)/ 18	30°C (EU)	
	Duplex: FC	SP1105-22	21 ′	190°C (NA)/ 18	30°C (EU)	
Fusing Motor Speed Correction	-	SP1909-0	57 (0% (NA)/ -3%	(EU)	
Nip Width Setting	Low Temp.	SP1905-04		330 msec. (NA		
Mip Width Setting	Over Low Temp.	SP1905-1	14	330 msec. (NA	√EU)	
Jam 38 Detection Timing Setting	-	SP1160-03	38	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	-	SP1207-04	47 (0 (NA/ EU)		
	B/W: Front	SP2329-03		50 ^µ A (NA/ EL		
PTR: Standard	B/W: Back	SP2329-03	31	50 HA (NA/ EL	J)	
Bias Setting	FC: Front	SP2329-03	32	70 HA (NA/ EL	J)	
	FC: Back	SP2329-03		70 HA (NA/ EL	,	
DTD: Leading Ed	B/W: Front	SP2426-13		170% (NA/ EU	,	
PTR: Leading Edge	B/W: Back	SP2426-14		170% (NA/ EU))	
Bias Correction	FC: Front	SP2426-14		170% (NA/ EU	,	
Setting	FC: Back	SP2426-1		170% (NA/ EU		
	B/W: Front	SP2428-02		100% (NA/ EU		
PTR: Trailing Edge	B/W: Back	SP2428-02		180% (NA/ EU	•	
Bias Correction	FC: Front	SP2428-02		100% (NA/ EU		ŀ
Setting	FC: Back	SP2428-02		180% (NA/ EU		
TITLE: Special 3: Mi		01 2420 02	20	10070 (1471) EO)]
Adjustable SP	Mode	SP No)	Defau	lt	
7 tajaotabio Ci	Simplex: B/W	SP1105-2		190°C (NA/ EU		•
	Simplex: FC	SP1105-2		190°C (NA/ EU	•	
Fusing Temp.	Duplex: B/W	SP1105-22		190°C (NA/ EU	<u> </u>	
	Duplex: FC	SP1105-22		190°C (NA/ EU	/	
Eucina Motor	Duhley. I.C	SF 1100-24	20	190 C (INAV EC	(1	
Fusing Motor Speed Correction	-	SP1909-0		-2% (NA/ EU)		
Nip Width Setting	Low Temp.	SP1905-04		40 msec. (NA/		
	Over Low Temp.	SP1905-1	15	40 msec. (NA/	EU)	
Jam 38 Detection Timing Setting	-	SP1160-03	39	30 mm (NA/ E	U)	
Fixed Paper Interval Setting	-	SP1207-04	48 (0 (NA/ EU)		
	B/W: Front	SP2329-03	30	50 HA (NA/ EL	J)	
PTR: Standard	B/W: Back	SP2329-03		50 HA (NA/ EL	/	
Bias Setting	FC: Front	SP2329-03		70 HA (NA/ EL	,	
	FC: Back	SP2329-03		70 PA (NA/ EL		
	B/W: Front	SP2426-13		170% (NA/ EU	•	
PTR: Leading Edge	B/W: Florit	SP2426-14		170% (NA/ EU	•	1
Bias Correction	FC: Front	SP2426-14		170% (NA/ EU	<u>′ </u>	
Setting	FC: Back	SP2426-1		170% (NA/ EU		
1	, J. Duon	O1 2720 1	~ <u>~</u>	0 /0 (1 1/ // LO	,	ı



PAGE: 50/66

Model: Aegis-P1/C1			Date:	22-Jun-09	No.: RG178053
Adjustable SP	Mode	SP N	0.	Defau	ılt
PTR: Trailing Edge	B/W: Front	SP2428-0	025	100% (NA/ EU)
Bias Correction	B/W: Back	SP2428-0		180% (NA/ EU	
Setting	FC: Front	SP2428-0	027	100% (NA/ EU)
Octung	FC: Back	SP2428-0	028	180% (NA/ EU)
TITLE: Special 3: Th	ick 1				
Adjustable SP	Mode	SP N		Defau	
	Simplex: B/W	SP1105-2		200°C (NA/ EU	/
Fusing Temp.	Simplex: FC	SP1105-2	215	200°C (NA/ EU	
r doing romp.	Duplex: B/W	SP1105-2		200°C (NA/ EU	/
	Duplex: FC	SP1105-2	227	200°C (NA/ EU	J)
Fusing Motor	_	SP1909-0)59	-2% (NA/ EU)	
Speed Correction				, ,	
Nip Width Setting	Low Temp.	SP1905-0		40 msec. (NA/	
	Over Low Temp.	SP1905-	116	40 msec. (NA/	EU)
Jam 38 Detection Timing Setting	-	SP1160-0	040	30 mm (NA/ E	U)
Fixed Paper Interval Setting	-	SP1207-0	049	0 (NA/ EU)	
	B/W: Front	SP2329-0	030	50 μA (NA/ EL	J)
PTR: Standard	B/W: Back	SP2329-0	031	50 HA (NA/ EL	J)
Bias Setting	FC: Front	SP2329-0	032	70 HA (NA/ EL	J)
	FC: Back	SP2329-0	033	70 HA (NA/ EL	J)
PTR: Leading Edge	B/W: Front	SP2426-	136	250% (NA/ EU)
Bias Correction	B/W: Back	SP2426-	142	250% (NA/ EU)
Setting	FC: Front	SP2426-	147	250% (NA/ EU)
Octung	FC: Back	SP2426-	153	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-0	025	100% (NA/ EU	,
Bias Correction	B/W: Back	SP2428-0	026	180% (NA/ EU	
Setting	FC: Front	SP2428-0	027	100% (NA/ EU)
	FC: Back	SP2428-0	028	180% (NA/ EU)
TITLE: Special 3: Th					
Adjustable SP	Mode	SP N		Defau	
	Simplex: B/W	SP1105-2		200°C (NA/ EU	,
Fusing Temp.	Simplex: FC	SP1105-2	217	200°C (NA/ EU	,
r doing remp.	Duplex: B/W	SP1105-2		200°C (NA/ EU	
	Duplex: FC	SP1105-2	229	200°C (NA/ EU	J)
Fusing Motor Speed Correction	_	SP1909-0	060	-3% (NA)/ -2%	(EU)
Nip Width Setting	Low Temp.	SP1905-0	051	40 msec. (NA/	EU)
INP WIGHT SELLING	Over Low Temp.	SP1905-	117	40 msec. (NA/	EU)
Jam 38 Detection Timing Setting	_	SP1160-0	041	30 mm (NA/ E	U)
Fixed Paper		CD4007 (250	0 (NIA / ELL)	
Interval Setting		SP1207-0	JOU	0 (NA/ EU)	
PTR: Standard	B/W: Front	SP2329-0	030	50 HA (NA/ EL	J)



PAGE: 51/66 Date: 22-Jun-09 No.: RG178053

Model: Aegis-P1/C1			Date:	22-Jun-09	No.: RG178
Adjustable SP	Mode	SP N	lo.	Defau	ılt
Bias Setting	B/W: Back	SP2329-0	031	50 μA (NA/ EL	J)
	FC: Front	SP2329-0	032	70 HA (NA/ EL	J)
	FC: Back	SP2329-0	033	70 HA (NA/ EL	J)
PTR: Leading Edge Bias Correction	B/W: Front	SP2426-	137	250% (NA/ EU	J)
	B/W: Back	SP2426-	143	250% (NA/ EU	J)
	FC: Front	SP2426-	148	250% (NA/ EU	J)
Setting	FC: Back	SP2426-	154	250% (NA/ EU	J)
DTD: Trailing Edge	B/W: Front	SP2428-0	025	100% (NA/ EU	J)
PTR: Trailing Edge Bias Correction	B/W: Back	SP2428-0	026	180% (NA/ EU	J)
Setting	FC: Front	SP2428-0	027	100% (NA/ EU	J)
	FC: Back	SP2428-0	028	180% (NA/ EU	J)
FITLE: Special 3: Thick 3					

Adjustable SP	Mode	SP No.	Default
Fusing Temp.	Simplex: B/W	SP1105-218	200°C (NA)/ 195°C (EU)
r using remp.	Simplex: FC	SP1105-219	200°C (NA)/ 195°C (EU)
Fusing Motor Speed Correction	-	SP1909-061	-3% (NA)/ 0% (EU)
Nip Width Setting	Low Temp.	SP1905-052	40 msec. (NA/ EU)
Mp Width Setting	Over Low Temp.	SP1905-118	40 msec. (NA/ EU)
Jam 38 Detection Timing Setting	-	SP1160-042	30 mm (NA/ EU)
Fixed Paper Interval Setting	-	SP1207-051	0 (NA/ EU)
PTR: Standard	B/W: Front	SP2329-030	50 ¼A (NA/ EU)
Bias Setting	FC: Front	SP2329-032	70 HA (NA/ EU)
PTR: Leading Edge	B/W: Front	SP2426-138	250% (NA/ EU)
Bias Correction Setting	FC: Front	SP2426-149	250% (NA/ EU)
PTR: Trailing Edge	B/W: Front	SP2428-025	100% (NA/ EU)
Bias Correction Setting	FC: Front	SP2428-027	100% (NA/ EU)



PAGE: 52/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

• After **page 812**, the "Jam Detection" section is newly added. This section is newly added. Therefore, red text is not used.

Jam Detection

Paper Jam Display

{ XE "Jam Detection:Jam" \z "0:0" $\$ MERGEFORMAT }SP7-507 shows the paper jam history.

CODE :011 SIZE :05h TOTAL:000034

DATE: Fri Feb 20 11:44:50 2009

d016t503

- CODE: Indicates the jam code.
- SIZE: Indicates the paper Size Code.
- TOTAL: Indicates the total counter (SP7-502-001).
- DATE: indicates the date when the jam occurred.

Paper Size Code

Size Code	Paper Size	Size Code	Paper Size
05	A4 LEF	141	B4 SEF
06	A5 LEF	142	B5 SEF
14	B5 LEF	160	DLT SEF
38	LT LEF	164	LG SEF
44	HLT LEF	166	LT SEF
132	A3 SEF	172	HLT SEF
133	A4 SEF	255	Others
134	A5 SEF	-	-

Jam Codes and Display Codes

SP7-504 and SP7-509 show how many jams occurred at each location. Jam codes from 001 to 255 correspond with the suffix number of SP7-504 (e.g. Jam code 001 corresponds with SP7-504-001) and Jam codes from 256 to 396 correspond with the suffix number of SP7-509 by the following formula.

Suffix number of SP7-509 = Jam code (256 to 396) - 255 (e.g. Jam code 256 corresponds with SP7-509-001)

The following jam code and display code table is used for the printer model (G178) and copier model (D016).



PAGE: 53/66

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178053

Note

"P only" denotes that its jam code is used only for the printer model (G178).

Mainframe

Jam	Display	Description	LCD
Code -001	At power on	Initial paper jam	Display
-001	Paper feed sensor 1:	Paper is not fed from tray 1.	-
	Late	·	A3
-004	Paper feed sensor 2: Late	Paper is not fed from tray 2.	A2
-006 (P only)	Paper feed sensor 3 (A4 LCT): Late	Paper is not fed from the upper tray of the A4 LCT.	U2
-007	Paper feed sensor 4 (A4 LCT): Late	Paper is not fed from the middle tray of the A4 LCT.	U4
-008	Paper feed sensor 5 (A4	Paper is not fed from the lower tray of the A4 LCT.	U5
-009	Paper feed sensor (By- pass): Late	Paper is not fed from the bypass tray.	V
-010	Paper feed sensor upper (A3 LCT1): Late	Paper is not fed from the upper tray of the A3 LCT or LCT-MF.	U2
-011	Paper feed sensor lower (A3 LCT1): Late	Paper is not fed from the lower tray of the A3 LCT or LCT-MF.	U4
-012	Paper feed sensor upper (A3 LCT2): Late	Paper is not fed from the upper tray of the A3 LCT.	U2
-013	Paper feed sensor lower (A3 LCT2): Late	Paper is not fed from the lower tray of the A3 LCT.	U4
-014	Vertical Transport Sensor 1: Late	Vertical transport sensor 1 does not detect paper from tray 1.	Α
-015	Vertical Transport Sensor 2: Late	Vertical transport sensor 1 does not detect paper from tray 2.	Α
-017 (P only)	Grip Sensor 1: Late	Registration sensor does not detect paper.	В
-0118 (P only)	Grip Sensor 2: Late	Fusing entrance sensor does not detect paper.	В
-019 (P only)	Grip Sensor 3: Late	Fusing exit sensor does not detect paper.	В
-020	Relay sensor (By-pass): Late	-	V
-021	LCT Grip Sensor 1 (A3 LCT1): Late	LCT grip sensor 1 (A3 LCT1) does not detect paper.	U, U2
-022	LCT Grip Sensor 2 (A3 LCT1): Late	LCT grip sensor 2 (A3 LCT1) does not detect paper.	U, U4
-023	LCT Grip Sensor 1 (A3 LCT2): Late	LCT grip sensor 1 (A3 LCT2) does not detect paper.	U, U2



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 54/66

Jam Code	Display	Description	LCD Display
-024	LCT Grip Sensor 2 (A3 LCT2): Late	LCT grip sensor 2 (A3 LCT2) does not detect paper.	U, U4
-025 (P only)	Relay sensor (A4 LCT): Late	-	U
-026	LCT vertical transport sensor 3 (A3 LCT1): Late	LCT vertical transport sensor 3 (A3 LCT1) does not detect paper.	U
-027	LCT vertical transport sensor 1 (A3 LCT1): Late	LCT vertical transport sensor 1 (A3 LCT1) does not detect paper.	C
-028	LCT vertical transport sensor 2 (A3 LCT1): Late	LCT vertical transport sensor 2 (A3 LCT1) does not detect paper.	U
-029	LCT vertical transport sensor 1 (A3 LCT2): Late	LCT vertical transport sensor 1 (A3 LCT2) does not detect paper.	U
-030	LCT vertical transport sensor 2 (A3 LCT2): Late	LCT vertical transport sensor 2 (A3 LCT2) does not detect paper.	U
-031 (P only)	LCT exit sensor (A4 LCT): Late	LCT exit sensor (A4 LCT) does not detect paper.	U
-033	Registration entrance sensor: Late	Registration entrance sensor does not detect paper.	B4
-034	LCT entrance sensor: Late	LCT entrance sensor does not detect paper.	B5
-035	Registration timing sensor: Late	Registration timing sensor does not detect paper.	В6
-036	PTR timing sensor: Late	PTR timing sensor does not detect paper.	В6
-037	PTB jam sensor: Late	PTB jam sensor does not detect paper.	С
-038	Fusing exit sensor: Late	Fusing exit sensor does not detect paper.	D1
-039	Exit junction timing sensor: Late	Exit junction timing sensor does not detect paper.	D2
-040	Paper exit sensor: Late	Paper exit sensor does not detect paper.	D2
-041	Switchback sensor: Late	Switchback sensor does not detect paper.	D3
-042	Duplex transport sensor 1: Late	Duplex transport sensor 1 does not detect paper.	Z1
-043	Duplex transport sensor 2: Late	Duplex transport sensor 2 does not detect paper.	Z1
-044	Duplex transport sensor 3: Late	Duplex transport sensor 3 does not detect paper.	Z4



Technical Bulletin

 Ulletin
 PAGE: 55/66

 Date: 22-Jun-09
 No.: RG178053

	,	_ 0.00 00 00	
Jam Code	Display	Description	LCD Display
-045	Duplex transport sensor 4: Late	Duplex entrance sensor 4 does not detect paper.	Z4
-053	Paper feed sensor 1: Stay on	Paper feed sensor 1 does not turn off.	A3
-054	Paper feed sensor 2: Stay on	Paper feed sensor 2 does not turn off.	A2
-056 (P only)	Paper feed sensor upper (A4 LCT): Stay on	Paper feed sensor upper (A4 LCT) does not turn off.	U2
-057 (P only)	Paper feed sensor middle (A4 LCT): Stay on	Paper feed sensor middle (A4 LCT) does not turn off.	U4
-058 (P only)	Paper feed sensor lower (A4 LCT): Stay on	Paper feed sensor lower (A4 LCT) does not turn off.	U5
-059	Paper feed sensor (Bypass): Stay on	Paper feed sensor (By-pass) does not turn off.	V
-060	Paper feed sensor upper (A3 LCT1): Stay on	Paper feed sensor upper (A3 LCT1) does not turn off.	U2
-061	Paper feed sensor lower (A3 LCT1): Stay on	Paper feed sensor lower (A3 LCT1) does not turn off.	U4
-062	Paper feed sensor upper (A3 LCT2): Stay on	Paper feed sensor upper (A3 LCT2) does not turn off.	U2
-063	Paper feed sensor lower (A3 LCT2): Stay on	Paper feed sensor lower (A3 LCT2) does not turn off.	U4
-064	Vertical Transport Sensor 1: Stay on	Vertical transport sensor 1 does not turn off.	А
-065	Vertical Transport Sensor 2: Stay on	Vertical transport sensor 2 does not turn off.	Α
-067 (P only)	4th transport sensor (A4 LCT): Stay on	4th transport sensor (A4 LCT) does not turn off.	U2
-068 (P only)	5th transport sensor (A4 LCT): Stay on	5th transport sensor (A4 LCT) does not turn off.	U4
-069 (P only)	6th transport sensor (A4 LCT): Stay on	6th transport sensor (A4 LCT) does not turn off.	U5
-070	Relay sensor (By-pass): Stay on	Relay sensor (By-pass) does not turn off.	U
-071	LCT Grip Sensor 1 (A3 LCT1): Stay on	LCT Grip Sensor 1 (A3 LCT1) does not turn off.	U, U2
-072	LCT Grip Sensor 2 (A3 LCT1): Stay on	LCT Grip Sensor 2 (A3 LCT1) does not turn off.	U, U2
-073	LCT Grip Sensor 1 (A3 LCT2): Stay on	LCT Grip Sensor 1 (A3 LCT2) does not turn off.	U, U2
-074	LCT Grip Sensor 2 (A3 LCT2): Stay on	LCT Grip Sensor 2 (A3 LCT2) does not turn off.	U, U2



Technical Bulletin

 Ulletin
 PAGE: 56/66

 Date: 22-Jun-09
 No.: RG178053

Jam Code	Display	Description	LCD Display
-075 (P only)	Relay sensor (A4 LCT): Stay on	Relay sensor (A4 LCT) does not turn off.	U
-076	LCT vertical transport sensor 3 (A3 LCT1): Stay on	LCT vertical transport sensor 3 (A3 LCT1) does not turn off.	U
-077	LCT vertical transport sensor 1 (A3 LCT1): Stay on	LCT vertical transport sensor 1 (A3 LCT1) does not turn off.	U
-078	LCT vertical transport sensor 2 (A3 LCT1): Stay on	LCT vertical transport sensor 2 (A3 LCT1) does not turn off.	U
-079	LCT vertical transport sensor 1 (A3 LCT2): Stay on	LCT vertical transport sensor 1 (A3 LCT2) does not turn off.	U
-080	LCT vertical transport sensor 2 (A3 LCT2): Stay on	LCT vertical transport sensor 2 (A3 LCT2) does not turn off.	U
-081 (P only)	LCT exit sensor (A4 LCT): Stay on	LCT exit sensor (A4 LCT) does not turn off.	U
-083	Registration entrance sensor: Stay on	Registration entrance sensor does not turn off.	B4
-084	LCT entrance sensor: Stay on	LCT entrance sensor does not turn off.	B5
-085	Registration timing sensor: Stay on	Registration timing sensor does not turn off.	В6
-086	PTR timing sensor: Stay on	PTR timing sensor does not turn off.	В6
-087	PTB jam sensor: Stay on	PTR jam sensor does not turn off.	С
-088	Fusing exit sensor: Stay on	Fusing exit sensor does not turn off.	D1
-089	Exit junction timing sensor: Stay on	Exit junction timing sensor does not turn off.	D2
-090	Paper exit sensor: Stay on	Paper exit sensor does not turn off.	D2
-091	Switchback sensor: Stay on	Switchback sensor does not turn off.	D3
-092	Duplex transport sensor 1: Stay on	Duplex transport sensor 1 does not turn off.	Z1
-093	Duplex transport sensor 2: Stay on	Duplex transport sensor 2 does not turn off.	Z1
-094	Duplex transport sensor 3: Stay on	Duplex transport sensor 3 does not turn off.	Z4
-095	Duplex transport sensor 4: Stay on	Duplex transport sensor 4 does not turn off.	Z4



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 57/66

Jam Code	Display	Description	LCD Display
-097	Switchback Sensor	Switchback lower sensor does not turn off.	E
-098	CIS: Skew Detection	CIS does not turn off.	B6
-099	Double-feed Sensor	Double-feed Sensor does not turn off.	В6

Finisher SR5000 (B830)

Jam Code	Display	Description	LCD Display
-101	Entrance Sensor - Fin.: Paper late error	Entrance sensor does not detect paper.	R1 to R3
-102	Entrance Sensor - Fin. (Stay On): Paper lag error	Entrance sensor does not turn off.	R1 to R3
-103	Upper Tray Exit Sensor - Fin: Paper late error	Upper tray exit sensor does not detect paper.	R1 to R3
-104	Upper Tray Exit Sensor - Fin (Stay On): Paper lag error	Upper tray exit sensor does not turn off.	R1 to R3
-105	Shift Tray Exit Sensor - Fin: Paper late error	Shift tray exit sensor does not detect paper.	R1 to R3
-106	Shift Tray Exit Sensor - Fin (Stay On): Paper lag error	Shift tray exit sensor does not turn off.	R1 to R3
-107	Staple Tray Exit Sensor - Fin: Paper late error	Staple tray exit sensor does not detect paper.	R4 to R8
-108	Staple Tray Exit Sensor - Fin (Stay On): Paper lag error	Staple tray exit sensor does not turn off.	R4 to R8
-109	Staple Tray Paper Sensor - Fin: Paper late error	Staple tray paper sensor does not detect paper.	R4 to R8
-110	Staple Tray Paper Sensor - Fin (Stay On): Paper lag error	Staple tray paper sensor does not turn off.	R4 to R8
-111	Stack Feed-Out Belt HP Sensor	Stack feed-out belt HP sensor does not turn off.	R4 to R8
-112	Transport Motors	The machine detects a lock signal from the transport motors.	R1 to R3
-113	Shift Tray Lift Motor	The machine detects a lock signal from the shift tray lift motor.	R1 to R3



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 58/66

Jam Code	Display	Description	LCD Display
-114	Jogger Motor	The machine detects a lock	R4 to
		signal from the jogger motor.	R8
-115	Shift Motor	The machine detects a lock	R1 to
		signal from the shift motor.	R3
-116	Staple Motor	The machine detects a lock	R4 to
	-	signal from the staple motor.	R8
-117	Stack Feed-Out Belt Motor	The machine detects a lock signal from the stack feed-out belt motor.	R4 to R8
-118	Punch Motor	The machine detects a lock signal from the punch motor.	R1 to R3
-119	Z-Fold Jam - Fin	The machine detects a lock signal from the Z-hold jam motor.	R4 to R8
-120	Pre-Stack Transport Motor	The machine detects a lock signal from the pre-stack transport jam motor.	R4 to R8
-121	Abnormal Signal - Fin	The machine detects the job data error.	R1 to R3
-122	Upper Stopper Motor Lock	The machine detects the jam signal from the Plockmatic unit.	Ploc

Cover Interposer Tray CI5010 (B835)

Jam Code	Display	Description	LCD Display
-130	1st Paper Feed Sensor - Late	1st paper feed sensor does not detect paper.	Q1
-131	1st Paper Feed Sensor - Lag	1st paper feed sensor does not turn off.	Q1
-132	2nd Paper Feed Sensor - Late	2nd paper feed sensor does not detect paper.	Q2
-133	2nd Paper Feed Sensor - Lag	2nd paper feed sensor does not turn off.	Q2
-134	1st Transport Sensor - Late	1st transport sensor does not detect paper.	Q3 to Q4
-135	1st Transport Sensor - Lag	1st transport sensor does not turn off.	Q3 to Q4
-136	2nd Transport Sensor - Late	2nd transport sensor does not detect paper.	Q3 to Q4
-137	2nd Transport Sensor - Lag	2nd transport sensor does not turn off.	Q3 to Q4
-138	1st Vertical Transport Sensor - Late	1st vertical transport sensor does not detect paper.	Q3 to Q4



Date: 22-Jun-09 No.: RG178053

PAGE: 59/66

Model: Aeg	jis-P1/C1	Date: 22-Jun-09	No.: RG1780
Jam Code	Display	Description	LCD Display
-139	1st Vertical Transport Sensor - Lag	1st vertical transport sensor does not turn off.	Q3 to Q4
-140	2nd Vertical Transport Sensor - Late	2nd vertical transport sensor does not detect paper.	Q3 to Q4
-141	2nd Vertical Transport Sensor - Lag	2nd vertical transport sensor does not turn off.	Q3 to Q4
-142		Vertical exit sensor does not detect paper.	Q3 to Q4
-143	Vertical Exit Sensor - Lag	Vertical exit sensor does not turn off.	Q3 to Q4
-144	Entrance Sensor - Late	Entrance sensor does not detect paper.	Q3 to Q4
-145	Entrance Sensor - Lag	Entrance sensor does not turn off.	Q3 to Q4
-146	Exit Sensor - Late	Exit sensor does not detect paper.	Q3 to Q4
-147	Exit Sensor - Lag	Exit sensor does not turn off.	Q3 to Q4
-148	1st Lift Motor	The machine detects a lock signal from the 1st lift motor.	Q1
-149	2nd Lift Motor	The machine detects a lock signal from the 2nd lift motor	Q2
-150	1st Pick-Up Motor	The machine detects a lock signal from the 1st pick-up motor.	Q1
-151	2nd Pick-Up Motor	The machine detects a lock signal from the 2nd pick-up motor	Q2

Cover Interposer Tray CI5010 (B835)

Jam Code	Display	Description	LCD Display
-160	Entrance Sensor - Late	Entrance sensor does not detect paper.	M1 to M3
-161	Entrance Sensor - Lag	Entrance sensor does not turn off.	M1 to M3
-162	Stapling Tray Paper Sensor - Late	Stapling tray paper sensor does not detect paper.	M7 to M11
-163	Stapling Tray Paper Sensor - Lag	Stapling tray paper sensor does not turn off.	M7 to M11
-164	Stack Present Sensor - Late	Stack present sensor does not detect paper.	M4 to M6
-165	Stack Present Sensor - Lag	Stack present sensor does not turn off.	M4 to M6



Date: 22-Jun-09 No.: RG178053

PAGE: 60/66

Model: Aeg	is-P1/C1	Date: 22-Jun-09	No.: RG178
Jam Code	Display	Description	LCD Display
-166	Fold Unit Entrance Sensor - Late	Fold unit entrance sensor does not detect paper.	M7 to M11
-167	Fold Unit Entrance Sensor - Lag	Fold unit entrance sensor does not turn off.	M7 to M11
-168	Fold Unit Exit Sensor - Late	Fold unit exit sensor does not detect paper.	M7 to M11
-169	Fold Unit Exit Sensor - Lag	Fold unit exit sensor does not turn off.	M7 to M11
-170	Exit Sensor - Late	Exit sensor does not detect paper.	M4 to M6
-171	Exit Sensor - Lag	Exit sensor does not turn off.	M4 to M6
-174	Jogger Fence	The machine detects a lock signal from the jogger fence motor.	M7 to M11
-175	Stack Feed-Out Belt	The machine detects a lock signal from the stack feed-out belt motor.	M7 to M11
-176	Booklet Stapler - Front	The machine detects a lock signal from the booklet stapler - front motor.	M4 to M6
-177	Booklet Stapler - Rear	The machine detects a lock signal from the booklet stapler - rear motor.	M4 to M6
-178	Stack Junction Gate Motor	The machine detects a lock signal from the stack junction gate motor.	M7 to M11
-179	Clamp Roller Retraction Motor	The machine detects a lock signal from the clamp roller retraction motor	M7 to M11
-180	Bottom Fence Lift Motor	The machine detects a lock signal from the bottom fence lift motor.	M7 to M11
-181	Fold Plate Motor	The machine detects a lock signal from the fold plate motor.	M7 to M11
-182	Bind: Job data Err	The machine detects the job data error.	M7 to M11

Z-folding Unit ZF4000 (B660)

Jam Code	Display	Description	LCD Display
-200	Feed Sensor - Late	Feed sensor does not detect paper.	N1
-201	Feed Sensor - Lag	Feed sensor does not turn off.	N1



Date: 22-Jun-09 No.: RG178053

PAGE: 61/66

Model: Aeg	is-P1/C1	Date: 22-Jun-09	No.: RG1780
Jam Code	Display	Description	LCD Display
-202	Fold Timing Sensor - Late	Fold timing sensor does not detect paper.	N2, N3
-203	Fold Timing Sensor - Lag	Fold timing sensor does not turn off.	N2, N3
-204	Leading Edge Sensor - Late	Leading edge sensor does not detect paper.	N2, N3
-205	Leading Edge Sensor - Lag	Leading edge sensor does not turn off.	N2, N3
-206	Upper Stopper HP Sensor - Late	Upper stopper HP sensor does not detect paper.	N2, N3
-207	Upper Stopper HP Sensor - Lag	Upper stopper HP sensor does not turn off.	N2, N3
-208	Upper Exit Sensor 1 - Late	Upper exit sensor 1 does not detect paper.	N1
-209	Upper Exit Sensor 1 - Lag	Upper exit sensor 1 does not turn off.	N1
-212	Lower Exit Sensor 2 - Late	Lower exit sensor 2 does not detect paper.	N2, N3
-213	Lower Exit Sensor 2 - Lag	Lower exit sensor 2 does not turn off.	N2, N3
-214	Feed Motor	The machine detects a lock signal from the feed motor.	N1
-215	Lower Stopper Motor	The machine detects a lock signal from the lower stopper motor.	N2, N3
-216	Upper Stopper Motor	The machine detects a lock signal from the upper stopper motor.	N2, N3

High Capacity Stacker SK5000 (D364)

Jam Code	Display	Description	LCD Display
-250	Stacker1:Entrance Sn:Late	Entrance sensor (stacker 1) does not detect paper.	L1
-251	Stacker1:Ex-Tray:P Exit Sn:Late	Proof tray exit sensor (stacker 1) does not detect paper.	L2
-252	Stacker1:Ex-Tray:P Exit Sn:Stay on	Proof tray exit sensor (stacker 1) does not turn off.	L2
-253	Stacker1:S-Tray:P Exit Sn:Late	Tray exit sensor (stacker 1) does not detect paper.	L
-254	Stacker1:S-Tray:P Exit Sn:Lag	Tray exit sensor (stacker 1) does not turn off.	L
-255	Stacker1:Bridge Path Jam	Relay sensor (stacker 1) does not detect paper.	L3 to L5



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 62/66

9			
Jam Code	Display	Description	LCD Display
-256	Stacker1:Br-Path Exit Sn:Late	Exit sensor (stacker 1) does not detect paper.	L3 to L5
-257	Stacker1:Br-Path Exit Sn:Stay on	Exit sensor (stacker 1) does not turn off.	L3 to L5
-258	Stacker1:Off-set Unit Error	The machine detects a lock signal from the tray exit roller motor (stacker 1).	L
-259	Stacker1:Side Jogger Error	The machine detects a lock signal from the jogger motors (stacker 1).	L
-260	Stacker1:L-Edge Jogger Error	The machine detects a lock signal from the leading edge jogger motor (stacker 1).	L
-261	Stacker1:Stack Tray Error	The machine detects the stack tray error (stacker 1).	L
-262	Stacker1:Job Data Error	The machine detects the job data error (stacker 1).	L
-270	Stacker2:Entrance Sn:Late	Entrance sensor (stacker 2) does not detect paper.	L1
-271	Stacker2:Ex-Tray:P Exit Sn:Late	Proof tray exit sensor (stacker 2) does not detect paper.	L2
-272	Stacker2:Ex-Tray:P Exit Sn:Stay on	Proof tray exit sensor (stacker 2) does not turn off.	L2
-273	Stacker2:S-Tray:P Exit Sn:Late	Tray exit sensor (stacker 2) does not detect paper.	L
-274	Stacker2:S-Tray:P Exit Sn:Lag	Tray exit sensor (stacker 2) does not turn off.	L
-275	Stacker2:Bridge Path Jam	Relay sensor (stacker 2) does not detect paper.	L3 to L5
-276	Stacker2:Br-Path Exit Sn:Late	Exit sensor (stacker 2) does not detect paper.	L3 to L5
-277	Stacker2:Br-Path Exit Sn:Stay on	Exit sensor (stacker 2) does not turn off.	L3 to L5
-278	Stacker2:Off-set Unit Error	The machine detects a lock signal from the tray exit roller motor (stacker 2).	L
-279	Stacker2:Side Jogger Error	The machine detects a lock signal from the jogger motors (stacker 2).	L
-280	Stacker2:L-Edge Jogger Error	The machine detects a lock signal from the leading edge jogger motor (stacker 2).	L
-281	Stacker2:Stack Tray Error	The machine detects the stack tray error (stacker 2).	L



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 63/66

Jam Code	Display	Description	LCD Display
-282	Stacker2:Job Data Error	The machine detects the job	ı
		data error (stacker 2).	L .

Ring Binder RB5000 (D392)

Jam Code	Display	Description	LCD Display
-350	R-Binder:Entrance	Entrance sensor does not	Mc1,
	Sn:Late	detect paper.	Mc2
-351	R-Binder:Entrance	Entrance sensor does not turn	Mc1,
	Sn:Stay on	off.	Mc2
-352	R-Binder:Transport	Transport sensor does not	Mc3,
	Sn:Late	detect paper.	Mc4
-353	R-Binder:Transport	Transport sensor does not turn	Mc3,
	Sn:Stay on	off.	Mc4
-354	R-Binder:Exit Sn:Late	Exit sensor does not detect	Mc3,
		paper.	Mc4
-355	R-Binder:Exit Sn:Stay	Exit sensor does not turn off.	Mc3,
	on		Mc4
-356	R-Binder:Pre-punch	Pre-punch jogger trigger sensor	Mc5,
	Jam	does not turn off.	Mc6
-357	R-Binder:After-Punch	Binder delivery sensor does not	Mc5,
	Jam	turn off.	Mc6
-358	R-Binder:P TE Detect	Paper LE detect sensor does	Mc7,
	Sn Jam	not turn off.	Mc8
-359	R-Binder:P LE Detect	Paper LE detect sensor does	Mc7,
	Sn Jam	not detect paper.	Mc8
-360	R-Binder:Ring Error	The machine detects a ring	Mc7,
	Jam	error.	Mc8
-361	R-Binder:Binder Unit	The machine cannot detect the	Mc7,
	Set Jam	binder unit.	Mc8
-362	R-Binder:Output Belt 1 Jam	Output belt 1 HP sensor does not turn off.	Mc9
-363	R-Binder:Output Belt 2 Jam	Output belt 2 HP sensor does not turn off.	Мс9
-364	R-Binder:Stacker Jam	The machine detects an error at the stacker unit.	Mc10
-365	R-Binder:Punch Motor	The machine detects a lock	Mc5,
	Error	signal from the punch motor.	Mc6
-366	R-Binder:Shutter Motor	The machine detects a lock	Mc7,
	Error	signal from the shutter motor.	Mc8
-367			MeZ
	Error	signal from the alignment pin	Mc7, Mc8
		motor.	IVICO



Date: 22-Jun-09 No.: RG178053

PAGE: 64/66

Model: Aeg	is-P1/C1		Date: 22-Jun-09	No.: RG178
Jam Code	Display	Description	า	LCD Display
-368	R-Binder:Paper Jog Error		ne detects an error n the pre-punch	Mc5, Mc6
-369	R-Binder:Line-up Pin Error	The machine detects an error signal from the pre-bind jogger unit.		Mc7, Mc8
-370	R-Binder:Clamp Motor Error		ne detects a lock the clamp motor.	Mc7, Mc8
-371	R-Binder:50/100 Adj. M Error	The machine detects a lock signal from the 50/100 clamp adjust motor.		Mc7, Mc8
-372	R-Binder:Out-Belt Rot. M Error	The machine detects a lock signal from the output belt rotation motor.		Мс9
-373	R-Binder:Job Data Error	The machi data error.	ne detects the job	Мс

Buffer Pass Unit (M379)

Jam Code	Display	Description	LCD Display
-380	Buffer Pass Unit: Relay Sensor 1: Late	Transport sensor 1 does not detect paper.	Kc1
-381	Buffer Pass Unit: Relay Sensor 1: Stay on	Transport sensor 1 does not turn off.	Kc1
-382	Buffer Pass Unit: Relay Sensor 2: Late	Transport sensor 2 does not detect paper.	Kc2
-383	Buffer Pass Unit: Relay Sensor 2: Stay on	Transport sensor 2 does not turn off.	Kc2
-384	Buffer Pass Unit: Relay Sensor 3: Late	Transport sensor 3 does not detect paper.	Kc3
-385	Buffer Pass Unit: Relay Sensor 3: Stay on	Transport sensor 3 does not turn off.	Kc3
-386	Buffer Pass Unit: Relay Sensor 4: Late	Transport sensor 4 does not detect paper.	Kc4
-387	Buffer Pass Unit: Relay Sensor 4: Stay on	Transport sensor 4 does not turn off.	Kc4
-388	Buffer Pass Unit: Relay Sensor 5: Late	Transport sensor 5 does not detect paper.	Kc5
-389	Buffer Pass Unit: Relay Sensor 5: Stay on	Transport sensor 5 does not turn off.	Kc5
-390	Buffer Pass Unit: Relay Sensor 6: Late	Transport sensor 6 does not detect paper.	Kc6
-391	Buffer Pass Unit: Relay Sensor 6: Stay on	Transport sensor 6 does not turn off.	Kc6



Date: 22-Jun-09 No.: RG178053

PAGE: 65/66

Model: Aeg	is-P1/C1		Date: 22-Jun-09	No.: RG178
Jam Code	Display	Description	Description	
-392	Buffer Pass Unit: Relay Sensor 7: Late	Transport : detect pap	sensor 7 does not er.	Kc7
-393	Buffer Pass Unit: Relay Sensor 7: Stay on	Transport sensor 7 does not turn off.		Kc7
-394	Buffer Pass Unit: Relay Sensor 8: Late	Transport sensor 8 does not detect paper.		Kc8
-395	Buffer Pass Unit: Relay Sensor 8: Stay on	Transport sensor 8 does not turn off.		Kc8
-396	Buffer Pass Unit: Job Data Error	The machi data error.	ne detects the job	Kc9

LCT-MF or LCIT RT5020 (D355)

Jam Code	Display	Description	LCD Display
-400	A3 LCT1:Exit Sn:Late	Exit sensor (LCT1 or LCT-MF) does not detect paper.	U
-401	A3 LCT1:Entrance Sn:Late	Entrance sensor (LCT1 or LCT-MF) does not detect paper.	U8
-402	A3 LCT1:Right Ver. Sn:Late	LCT right vertical sensor (LCT1 or LCT-MF) does not detect paper.	U8
-403	A3 LCT1:H-Trans. Ent. Sn:Late	LCT horizontal transport entrance sensor (LCT1 or LCT- MF) does not detect paper.	U8
-404	A3 LCT1:H-Trans. Exit Sn:Late	LCT horizontal transport exit sensor (LCT1 or LCT-MF) does not detect paper.	U
-405	A3 LCT1:V-Trans. Ent. Sn:Late	LCT vertical transport entrance sensor (LCT1 or LCT-MF) does not detect paper.	U
-406	A3 LCT2:Exit Sn:Late	Exit sensor (LCT2) does not detect paper.	U
-451	A3 LCT1:Entrance Sn:Stay on	Entrance sensor (LCT1 or LCT-MF) does not turn off.	U8
-452	A3 LCT1:Right Ver. Sn:Stay on	LCT right vertical sensor (LCT1 or LCT-MF) does not turn off.	U8
-453	A3 LCT1:H-Trans. Ent. Sn:Stay on	LCT horizontal transport entrance sensor (LCT1 or LCT- MF) does not turn off.	U8
-454	A3 LCT1:H-Trans. Exit Sn:Stay on	LCT horizontal transport exit sensor (LCT1 or LCT-MF) does not turn off.	U



Technical Bulletin

Date: 22-Jun-09 No.: RG178053

PAGE: 66/66

Jam Code	Display	Description	LCD Display
-455	A3 LCT1:V-Trans. Ent. Sn:Stay on	LCT vertical transport entrance sensor (LCT1 or LCT-MF) does not turn off.	U
-456	A3 LCT2:Exit Sn:Stay on	Exit sensor (LCT2) does not turn off.	U

RICOH

Technical Bulletin

PAGE: 1/93

Model: Aegis-P1/C1			Dat	:e: 22-Jun-	09	No.: RG178054
Subject: Manual Corrections			Prepared by: N.iida			
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	n required
		☐ Electric	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

The "Service Tables" section of the service manual for the AG-C1 (D016) has been corrected in order to be updated and be used for both the copier model (D016) and printer model (G178).

- Add the following new information which is described in red text.
- On page 819

Abbreviations for AG-P1/C1 SP Service Tables

The SP titles are abbreviated so they can be used in smaller the 2-line displays of future printer models. Refer to this list if you do not understand the meaning of an abbreviation.

On pages from 825 to 838

1105*	Fusing Temp Control 1
029	Htg Roll: Reload
	Adjusts the reload temperature of the heating roller.
	[150 to 200 / 175 / 1°C]
03	Htg Roll: Rotation after Reload
	Adjusts the threshold temperature for the idle rotation of the heating
	roller after reload.
	[150 to 200 / 175 / 1°C]
03	Htg Roll: Stand-by: Normal Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for normal temperature.
	[150 to 200 / 175 / 1°C]
03	Poll: Stand-by:Low Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for low temperature.
	[<mark>150</mark> to <mark>200</mark> / 185 / 1°C]
03	Htg Roll: Stand-by:High Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for high temperature.
	[150 to 200 / 175 / 1°C]
04	Plain: BW: Uncoated
	[130 to 200 / 170 / 1°C]
04	Plain: FC: Uncoated

PAGE: 2/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 170 / 1°C]		
042	Thin: BW: Uncoated		
	[130 to 200 / 155 / 1°C]		
043	Thin: FC: Uncoated		
	[130 to 200 / 155 / 1°C]		
044	Middle Thick: BW: Uncoated		
	[130 to 200 / 180 / 1°C]		
045	Middle Thick: FC: Uncoated		
	[130 to 200 / 180 / 1°C]		
046	Thick 1: BW: Uncoated		
	[130 to 200 / 185 / 1°C]		
047	Thick 1: FC: Uncoated		
	[130 to 200 / 185 / 1°C]		
048	Thick 2: BW: Uncoated		
	[130 to 200 / 190 / 1°C]		
049	Thick 2: FC: Uncoated		
0.50	[130 to 200 / 190 / 1°C]		
050	Thick 3: BW: Uncoated		
054	[130 to 200 / 200 / 1°C]		
051	Thick 3: FC: Uncoated		
052	[130 to 200 / 200 / 1°C]		
052	Plain: Duplex BW: Uncoated [130 to 200 / 170 / 1°C]		
053	Plain: Duplex FC: Uncoated		
000	[130 to 200 / 170 / 1°C]		
054	Thin: Duplex BW: Uncoated		
	[130 to 200 / 155 / 1°C]		
055	Thin: Duplex FC: Uncoated		
	[130 to 200 / 155 / 1°C]		
056	Middle Thick: DUPLEX BW: Uncoated		
	[130 to 200 / 180 / 1°C]		
057	Middle Thick: DUPLEX FC: Uncoated		
	[130 to 200 / 180 / 1°C]		
058	Thick 1: DUPLEX BW: Uncoated		
	[130 to 200 / 185 / 1°C]		
059	Thick 1: FC: DUPLEX Uncoated		
	[130 to 200 / 185 / 1°C]		
060	Thick 2: DUPLEX BW: Uncoated		
	[130 to 200 / 190 / 1°C]		
061	Thick 2: DUPLEX FC: Uncoated		
200	[130 to 200 / 190 / 1°C]		
068	Plain: BW: Coated P1		
200	[130 to 200 / 175 / 1°C]		
069	Plain: FC: Coated P1		
070	[130 to 200 / 175 / 1°C]		
070	Thin: BW: Coated P1		

PAGE: 3/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 165 / 1°C]		
071	Thin: FC: Coated P1		
	[130 to 200 / 165 / 1°C]		
072	Middle Thick: BW: Coated P1		
	[130 to 200 / 180: NA, 185: EU / 1°C]		
073	Middle Thick: FC: Coated P1		
	[130 to 200 / 180: NA, 185: EU / 1°C]		
074	Thick 1: BW: Coated P1		
	[130 to 200 / 185 / 1°C]		
075	Thick 1: FC: Coated P1		
	[130 to 200 / 185 / 1°C]		
076	Thick 2: BW: Coated P1		
	[130 to 200 / 190 / 1°C]		
077	Thick 2: FC: Coated P1		
	[130 to 200 / 190 / 1°C]		
078	Thick 3: BW: Coated P1		
070	[130 to 200 / 195 / 1°C]		
079	Thick 3: FC: Coated P1		
000	[130 to 200 / 195 / 1°C]		
080	Plain: Duplex BW: Coated P1 [130 to 200 / 175 / 1°C]		
091	Plain: Duplex FC: Coated P1		
001	[130 to 200 / 175 / 1°C]		
082	Thin: Duplex BW: Coated P1		
002	[130 to 200 / 160 / 1°C]		
083	Thin: Duplex FC: Coated P1		
	[130 to 200 / 160 / 1°C]		
084	Middle Thick: DUPLEX BW: Coated P1		
	[130 to 200 / 180: NA, 185: EU / 1°C]		
085	Middle Thick: DUPLEX FC: Coated P1		
	[130 to 200 / 180: NA, 185: EU / 1°C]		
086	Thick 1: DUPLEX BW: Coated P1		
	[130 to 200 / 185 / 1°C]		
087	Thick 1: FC: DUPLEX Coated P1		
	[130 to 200 / 185 / 1°C]		
088	Thick 2: DUPLEX BW: Coated P1		
	[130 to 200 / 190 / 1°C]		
	Thick 2: DUPLEX FC: Coated P1		
	[130 to 200 / 190 / 1°C]		
096	Plain: BW: Coated P2		
225	[130 to 200 / 180 / 1°C]		
097	Plain: FC: Coated P2		
200	[130 to 200 / 180 / 1°C]		
098	Thin: BW: Coated P2		
000	[130 to 200 / 165 / 1°C]		
099	Thin: FC: Coated P2		

PAGE: 4/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 165 / 1°C]		
100	Middle Thick: BW: Coated P2		
	[130 to 200 / 185: NA, 175: EU / 1°C]		
101	Middle Thick: FC: Coated P2		
	[130 to 200 / 185: NA, 175: EU / 1°C]		
102	Thick 1: BW: Coated P2		
	[130 to 200 / 185: NA, 175: EU / 1°C]		
103	Thick 1: FC: Coated P2		
	[130 to 200 / 185: NA, 195: EU / 1°C]		
104	Thick 2: BW: Coated P2		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
105	Thick 2: FC: Coated P2		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
106	Thick 3: BW: Coated P2		
	[130 to 200 / 195: NA, 200: EU / 1°C]		
107	Thick 3: FC: Coated P2		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
108	Plain: Duplex BW: Coated P2		
	[130 to 200 / 180 / 1°C]		
	Plain: Duplex FC: Coated P2		
	[130 to 200 / 180 / 1°C]		
110	Thin: Duplex BW: Coated P2		
444	[130 to 200 / 165 / 1°C]		
111	Thin: Duplex FC: Coated P2		
110	[130 to 200 / 165 / 1°C]	1	
112	Middle Thick: DUPLEX BW: Coated P2 [130 to 200 / 185: NA, 175: EU / 1°C]	<u>′</u>	
112	Middle Thick: DUPLEX FC: Coated P2		
113	[130 to 200 / 185: NA, 175: EU / 1°C]		
11/	Thick 1: DUPLEX BW: Coated P2		
114	[130 to 200 / 185: NA, 195: EU / 1°C]		
115	Thick 1: FC: DUPLEX Coated P2		
113	[130 to 200 / 185: NA, 195: EU / 1°C]		
116	Thick 2: DUPLEX BW: Coated P2		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
117	Thick 2: DUPLEX FC: Coated P2		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
	Plain: BW: Coated P3		
	[130 to 200 / 175 / 1°C]		
	Plain: FC: Coated P3		
	[130 to 200 / 175 / 1°C]		
126	Thin: BW: Coated P3		
	[130 to 200 / 170 / 1°C]		
127	Thin: FC: Coated P3		
	[130 to 200 / 170 / 1°C]		
128	Middle Thick: BW: Coated P3		

PAGE: 5/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 185 / 1°C]		
	Middle Thick: FC: Coated P3		
	[130 to 200 / 185 / 1°C]		
130	Thick 1: BW: Coated P3		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
131	Thick 1: FC: Coated P3		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
132	Thick 2: BW: Coated P3		
	[130 to 200 / 195 / 1°C]		
133	Thick 2: FC: Coated P3		
	[130 to 200 / 195 / 1°C]		
134	Thick 3: BW: Coated P3		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
	Thick 3: FC: Coated P3		
	[130 to 200 / 200 : NA , 195 : EU / 1°C]		
136	Plain: Duplex BW: Coated P3		
	[130 to 200 / 175 / 1°C]		
137	Plain: Duplex FC: Coated P3		
	[130 to 200 / 175 / 1°C]		
	Thin: Duplex BW: Coated P3		
	[130 to 200 / 170 / 1°C]		
139	Thin: Duplex FC: Coated P3		
	[130 to 200 / 170 / 1°C]		
140	Middle Thick: DUPLEX BW: Coated P3		
	[130 to 200 / 190: NA, 185: EU / 1°C]		
141	Middle Thick: DUPLEX FC: Coated P3		
	[130 to 200 / 190 : NA , 185 : EU / 1°C]		
142	Thick 1: DUPLEX BW: Coated P3		
1.10	[130 to 200 / 190: NA, 195: EU / 1°C]		
143	Thick 1: FC: DUPLEX Coated P3		
444	[130 to 200 / 190: NA, 195: EU / 1°C]		
	Thick 2: DUPLEX BW: Coated P3		
	[130 to 200 / 195 / 1°C]		
145	Thick 2: DUPLEX FC: Coated P3		
150	[130 to 200 / 195 / 1°C]		
152	Plain: BW: SP1 [130 to 200 / 185: NA, 180: EU / 1°C]		
152	Plain: FC: SP1		
	[130 to 200 / 185: NA, 180: EU / 1°C]		
	Thin: BW: SP1		
154	[130 to 200 / <mark>170</mark> / 1°C]		
155	Thin: FC: SP1		
155	[130 to 200 / <mark>170</mark> / 1°C]		
156	Middle Thick: BW: SP1		
150	[130 to 200 / 185 / 1°C]		
157	Middle Thick: FC: SP1		
137	iviladic Tillon. FO. Of T		

PAGE: 6/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 185 / 1°C]		
158	Thick 1: BW: SP1		
	[130 to 200 / 195: NA, 180: EU / 1°C]		
159	Thick 1: FC: SP1		
	[130 to 200 / 195: NA, 180: EU / 1°C]		
160	Thick 2: BW: SP1		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
161	Thick 2: FC: SP1		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
162	Thick 3: BW: SP1		
	[130 to 200 / 195 / 1°C]		
163	Thick 3: FC: SP1		
	[130 to 200 / 195 / 1°C]		
	Plain: Duplex BW: SP1		
	[130 to 200 / 185 : NA , 180 : EU / 1°C]		
165	Plain: Duplex FC: SP1		
100	[130 to 200 / 185 : NA , 180 : EU / 1°C]		
166	Thin: Duplex BW: SP1		
107	[130 to 200 / 170 / 1°C]		
	Thin: Duplex FC: SP1		
	[130 to 200 / 170 / 1°C]		
168	Middle Thick: DUPLEX BW: SP1		
160	[130 to 200 / 185 / 1°C] Middle Thick: DUPLEX FC: SP1		
109	[130 to 200 / 185 / 1°C]		
170	Thick 1: DUPLEX BW: SP1		
170	[130 to 200 / 195: NA, 190: EU / 1°C]		
171	Thick 1: FC: DUPLEX SP1		
	[130 to 200 / 195: NA, 190: EU / 1°C]		
172	Thick 2: DUPLEX BW: SP1		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
173	Thick 2: DUPLEX FC: SP1		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
180	Plain: BW: SP2		
	[130 to 200 / <mark>180</mark> / 1°C]		
181	Plain: FC: SP2		
	[130 to 200 / 180 / 1°C]		
	Thin: BW: SP2		
	[130 to 200 / 175 / 1°C]		
183	Thin: FC: SP2		
	[130 to 200 / 175 / 1°C]		
184	Middle Thick: BW: SP2		
	[130 to 200 / 190 / 1°C]		
185	Middle Thick: FC: SP2		
	[130 to 200 / 190 / 1°C]		
186	Thick 1: BW: SP2		

PAGE: 7/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG ²	178054
[130 to 200 / 200 / 1°C]	
187 Thick 1: FC: SP2	
[130 to 200 / 200 / 1°C]	
188 Thick 2: BW: SP2	
[130 to 200 / 190: NA, 195: EU / 1°C]	
189 Thick 2: FC: SP2	
[130 to 200 / 190: NA, 195: EU / 1°C]	
190 Thick 3: BW: SP2	
[130 to 200 / 200: NA, 195: EU / 1°C]	
191 Thick 3: FC: SP2	
[130 to 200 / 200: NA, 195: EU / 1°C]	
192 Plain: Duplex BW: SP2	
[130 to 200 / 180 / 1°C]	
193 Plain: Duplex FC: SP2	
[130 to 200 / 180 / 1°C]	
194 Thin: Duplex BW: SP2	
[130 to 200 / 175 / 1°C]	
195 Thin: Duplex FC: SP2	
[130 to 200 / 175 / 1°C]	
196 Middle Thick: DUPLEX BW: SP2	
[130 to 200 / 190 / 1°C]	
197 Middle Thick: DUPLEX FC: SP2	
[130 to 200 / 190 / 1°C] 198 Thick 1: DUPLEX BW: SP2	
[130 to 200 / 200 / 1°C]	
199 Thick 1: FC: DUPLEX SP2	
[130 to 200 / 200 / 1°C]	
200 Thick 2: DUPLEX BW: SP2	
[130 to 200 / 190: NA, 195: EU / 1°C]	
201 Thick 2: DUPLEX FC: SP2	
[130 to 200 / 190: NA, 195: EU / 1°C]	
208 Plain: BW: SP3	
[130 to 200 / 190: NA, 180: EU / 1°C]	
209 Plain: FC: SP3	
[130 to 200 / 190: NA, 180: EU / 1°C]	
210 Thin: BW: SP3	
[130 to 200 / 180 / 1°C]	
211 Thin: FC: SP3	
[130 to 200 / 180 / 1°C]	
212 Middle Thick: BW: SP3	
[130 to 200 / 190 / 1°C]	
213 Middle Thick: FC: SP3	
[130 to 200 / 190 / 1°C]	
214 Thick 1: BW: SP3	
[130 to 200 / 200 / 1°C]	
215 Thick 1: FC: SP3	

RICOH

Technical Bulletin

PAGE: 8/93

Model: Aeg	is-P1/C1	Date: 22-Jun-09	No.: RG178054
	[130 to 200 / 200 / 1°C]		
	Thick 2: BW: SP3		
	[130 to 200 / 200 / 1°C]		
217	Thick 2: FC: SP3		
	[130 to 200 / 200 / 1°C]		
	Thick 3: BW: SP3		
	[130 to 200 / 200 / 1°C]		
	Thick 3: FC: SP3		
	[130 to 200 / 200 / 1°C]		
	Plain: Duplex BW: SP3		
	[130 to 200 / 190: NA, 180: EU / 1°C]		
	Plain: Duplex FC: SP3		
	[130 to 200 / 190: NA, 180: EU / 1°C]		
	Thin: Duplex BW: SP3		
	[130 to 200 / 180 / 1°C]		
	Thin: Duplex FC: SP3		
	[130 to 200 / 180 / 1°C]		
I	Middle Thick: DUPLEX BW: SP3		
	[130 to 200 / 190 / 1°C]		
	Middle Thick: DUPLEX FC: SP3		
	[130 to 200 / 190 / 1°C]		
	Thick 1: DUPLEX BW: SP3		
	[130 to 200 / 200 / 1°C]		
I	Thick 1: FC: DUPLEX SP3		
	[130 to 200 / 200 / 1°C]		
l l	Thick 2: DUPLEX BW: SP3		
	[130 to 200 / 200 / 1°C]		
l l	Thick 2: DUPLEX FC: SP3		
	[130 to 200 / <mark>200</mark> / 1°C]		

On pages from 838 to 851

1107*	Mode Shift Setting
009	Stand-by Idle Rotate:Interval
	Adjusts the interval of the fusing idle rotation in stand-by mode.
	[0 to 360 / 30 / 1 min]
010	Stand-by Idle Rotate:Time
	Adjusts the time of the fusing idle rotation in stand-by mode.
	[0 to 360 / 5 / 1 min]
017	Stand-by Mode Interval
	[1 to 255 / 168 / 1 hour]
018	Low Temp On/Off
	Adjusts the threshold temperature for the low temperature
	condition.
	[10 to 23 / 17 / 1°C]
019	High Temp On/Off

PAGE: 9/93

KICO	Technical	Juneum	PAGE: 9/
Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	Adjusts the threshold temperature for	or the high temperature	
	condition.		
	[24 to 40 / 28 / 1°C]		
020	Low Temp:Reload		
	Adjusts the temperature to be added	to the reload tempera	ture in
	the low temperature condition.		
	[0 to 15 / 5 / 1°C]		
021	High Temp:Reload		
	Adjusts the temperature to be subtra		
	temperature in the high temperature	condition.	
000	[0 to 15 / 0 / 1°C]		
022	Low Temp:Feed		
000	[0 to 15 / 15 / 1°C]		
023	High Temp:Feed		
024	[0 to 15 / 5 / 1°C]		
024	L-Limit:Htg Roll:Feed Plain [0 to 50 / 5 / 1°C]		
025	1		
025	[0 to 100 / 40 / 1°C]		
026	H-Limit:Htg Roll:Feed Plain		
020	[0 to 20 / 6 / 1°C]		
027	H-Limit:Press Roll:Feed Plain		
021	[0 to 128 / 50 / 1°C]		
028	Additional Temp:Plain		
	[0 to 20 / 0 / 1°C]		
029	Additional Temp:Thin		
	[0 to 20 / 0 / 1°C]		
030	Additional Temp:Mid Thk		
	[0 to 20 / 5 / 1°C]		
031	Additional Temp:Thk1		
	[0 to 20 / 5 / 1°C]		
032	Additional Temp:Thk2		
	[0 to 20 / 5 / 1°C]		
033	Additional Temp:Thk3		
	[0 to 20 / 5 / 1°C]		
034	Idle Time:After Reload		
205	[0 to 15 / 7 / 1 min]		
035	Additional Temp:Time		
000	[0 to 50 / 20 / 1 sec]		
036	Reload Extension: Low Temp		
027	[0 to 255 / 150 / 1 sec]		
037	Feed Start Extension		
020	[0 to 3 / 0 / 1]		
038	Idle Rotation: Standby:Interval [0 to 360 / 60 / 1 sec]		
039	Idle Rotation:Standby:Time		
039	idie Notation.Standby.Time		

Technical Bulletin

No.: RG178054

PAGE: 10/93

11100	• • • • • • • • • • • • • • • • • • •		FAC
Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG1
	[0 to 360 / 10 / 1 sec]		
040	Idle Rotation:Standby:ON/OFF		
	[0 : OFF, 1: ON]		
041	L-Limit:Htg Roll:Feed Thin		
	[0 to 20 / 0 / 1°C]		
042	L-Limit:Press Roll:Feed Thin		
	[0 to 100 / 40 / 1°C]		
043	H-Limit:Htg Roll:Feed Thin		
	[0 to 20 / 11 / 1°C]		
044			
	[0 to <mark>128</mark> / 50 / 1°C]		
045			
	[0 to 20 / 5 / 1°C]		
046	L-Limit:Press Roll:Feed Mid Thk		
0.17	[0 to 100 / 40 / 1°C]		
047	_		
040	[0 to 20 / 15 / 1°C]		
048			
040	[0 to 128 / 128 / 1°C]		
049	L-Limit:Htg Roll:Feed Thk1 [0 to 20 / 5 / 1°C]		
050	-		
030	[0 to 100 / 40 / 1°C]		
051	 		
031	[0 to 20 / 15 / 1°C]		
052	H-Limit:Press Roll:Feed Thk1		
002	[0 to 128 / 50 / 1°C]		
053			
	[0 to 20 / 0 / 1°C]		
054	L-Limit:Press Roll:Feed Thk2		
	[0 to 100 / 40 / 1°C]		
055	H-Limit:Htg Roll:Feed Thk2		
	[0 to 20 / 10 / 1°C]		
056	H-Limit:Press Roll:Feed Thk2		
	[0 to <mark>128</mark> / 50 / 1°C]		
057	L-Limit:Htg Roll:Feed Thk3		
	[0 to 20 / 0 / 1°C]		
058	L-Limit:Press Roll:Feed Thk3		
	[0 to 100 / 40 / 1°C]		
059	H-Limit:Htg Roll:Feed Thk3		
	[0 to 20 / 10 / 1°C]		
060	H-Limit:Press Roll:Feed Thk3		
	[0 to 128 / 50 / 1°C]		
061	Feed Start Extension:Plain	-1	
000	[1000 to 300,000 / 1000 / 1000 mse	ec]	
062	Feed Start Extension:Thin		

No.: RG178054 Date: 22-Jun-09

PAGE: 11/93

[1000 to 300,000 / 1000 / 1000 msec] 63 Feed Start Extension:Mid Thk [1000 to 300,000 / 1000 / 1000 msec] 64 Feed Start Extension:Thk1 [1000 to 300,000 / 5000 / 1000 msec] 65 Feed Start Extension:Thk2 [1000 to 300,000 / 10,000 / 1000 msec] 66 Feed Start Extension:Thk3 [1000 to 300,000 / 10,000 / 1000 msec] 67 Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] 68 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 69 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 71 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 72 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 73 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 74 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 75 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 76 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 77 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 78 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 79 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 77 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 78 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 79 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 79 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 80 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 81 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 82 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 83 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] 84 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] 85 Htg Roll:Feed:H-Limit:2-S Thk2	Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG1
063 Feed Start Extension:Mid Thk [1000 to 300,000 / 1000 / 1000 msec] 064 Feed Start Extension:Thk1 [1000 to 300,000 / 5000 / 1000 msec] 065 Feed Start Extension:Thk2 [1000 to 300,000 / 10,000 / 1000 msec] 066 Feed Start Extension:Thk3 [1000 to 300,000 / 10,000 / 1000 msec] 067 Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] 068 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 070 Press Roll:Feed:H-Limit:2-S Plain [0 to 123 / 50 / 1°C] 071 Htg Roll:Feed:H-Limit:2-S Thin [0 to 100 / 40 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 1 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 1 / 1°C] 075 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 128 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 079 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 081 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 10 / 1°C]				
[1000 to 300,000 / 1000 / 1000 msec] 644 Feed Start Extension:Thk1 [1000 to 300,000 / 5000 / 1000 msec] 655 Feed Start Extension:Thk2 [1000 to 300,000 / 10,000 / 1000 msec] 666 Feed Start Extension:Thk3 [1000 to 300,000 / 10,000 / 1000 msec] 676 Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] 688 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 699 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 700 Press Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 701 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 702 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 703 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 704 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 5 / 1°C] 705 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 706 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 707 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 708 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 708 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 709 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 700 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 700 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 700 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	063			
Ged Feed Start Extension:Thk1				
[1000 to 300,000 / 5000 / 1000 msec] Feed Start Extension:Thk2 [1000 to 300,000 / 10,000 / 1000 msec] Feed Start Extension:Thk3 [1000 to 300,000 / 10,000 / 1000 msec] Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] 68 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 69 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 71 Htg Roll:Feed:H-Limit:2-S Thin [0 to 100 / 40 / 1°C] 72 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 73 Htg Roll:Feed:H-Limit:2-S Thin [0 to 100 / 40 / 1°C] 74 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 75 Htg Roll:Feed:H-Limit:2-S Thin [0 to 100 / 40 / 1°C] 76 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 77 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 78 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 79 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 70 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 77 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 78 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 79 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 70 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C]	064			
Teed Start Extension:Thk2				
[1000 to 300,000 / 10,000 / 1000 msec] Feed Start Extension:Thk3 [1000 to 300,000 / 10,000 / 1000 msec] 067 Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] 068 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 069 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 070 Press Roll:Feed:H-Limit:2-S Plain [0 to 128 / 50 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 075 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 080 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 087 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 088 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 089 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 080 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	065	<u> </u>		
[1000 to 300,000 / 10,000 / 1000 msec] Of7 Htg Roll:Feed:L-Limit:2-S Plain [0 to 20 / 5 / 1°C] Of8 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] Of9 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] Of0 Press Roll:Feed:H-Limit:2-S Plain [0 to 128 / 50 / 1°C] Of1 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 0 / 1°C] Of2 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] Of3 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] Of4 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] Of5 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] Of6 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] Of7 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] Of8 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] Of9 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] Of9 Press Roll:Feed:H-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] Of9 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]		[1000 to 300,000 / 10,000 / 1000 mse	ec]	
1	066	Feed Start Extension:Thk3	•	
[0 to 20 / 5 / 1°C] 068 Press Roll:Feed:L-Limit:2-S Plain		[1000 to 300,000 / 10,000 / 1000 mse	ec]	
068 Press Roll:Feed:L-Limit:2-S Plain [0 to 100 / 40 / 1°C] 069 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 070 Press Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 075 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 085 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] 086 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] 087 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C] 088 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	067	Htg Roll:Feed:L-Limit:2-S Plain		
[0 to 100 / 40 / 1°C] 069 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 070 Press Roll:Feed:H-Limit:2-S Plain [0 to 128 / 50 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 085 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C]				
069 Htg Roll:Feed:H-Limit:2-S Plain [0 to 20 / 6 / 1°C] 070 Press Roll:Feed:H-Limit:2-S Plain [0 to 128 / 50 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	068	Press Roll:Feed:L-Limit:2-S Plain		
[0 to 20 / 6 / 1°C] 070				
070 Press Roll:Feed:H-Limit:2-S Plain [0 to 128 / 50 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C]	069	•		
[0 to 128 / 50 / 1°C] 071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2				
071 Htg Roll:Feed:L-Limit:2-S Thin [0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C]	070			
[0 to 20 / 0 / 1°C] 072 Press Roll:Feed:L-Limit:2-S Thin [0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]		<u> </u>		
072	071	· ·		
[0 to 100 / 40 / 1°C] 073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]				
073 Htg Roll:Feed:H-Limit:2-S Thin [0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:H-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	072			
[0 to 20 / 11 / 1°C] 074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	070			
074 Press Roll:Feed:H-Limit:2-S Thin [0 to 128 / 50 / 1°C] 075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	073	•		
[0 to 128 / 50 / 1°C] 1075 Htg Roll:Feed:L-Limit:2-S Mid Thk [0 to 20 / 5 / 1°C] 1076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 1077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 1078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 1079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 1080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 1081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 1082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 1083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 1084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	074			
O75	074			
[0 to 20 / 5 / 1°C] 076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	075	-		
076 Press Roll:Feed:L-Limit:2-S Mid Thk [0 to 100 / 40 / 1°C] 077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	075			
[0 to 100 / 40 / 1°C] O77 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] O78 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] O79 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] O80 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] O81 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] O82 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] O83 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] O84 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	076	-		
077 Htg Roll:Feed:H-Limit:2-S Mid Thk [0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	070			
[0 to 20 / 15 / 1°C] 078 Press Roll:Feed:H-Limit:2-S Mid Thk [0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	077	1		
078	011			
[0 to 128 / 128 / 1°C] 079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	078			
079 Htg Roll:Feed:L-Limit:2-S Thk1 [0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	0.0			
[0 to 20 / 5 / 1°C] 080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	079	4		
080 Press Roll:Feed:L-Limit:2-S Thk1 [0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]				
[0 to 100 / 40 / 1°C] 081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	080	1		
081 Htg Roll:Feed:H-Limit:2-S Thk1 [0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]				
[0 to 20 / 15 / 1°C] 082 Press Roll:Feed:H-Limit:2-S Thk1 [0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	081	-		
[0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]				
[0 to 128 / 50 / 1°C] 083 Htg Roll:Feed:L-Limit:2-S Thk2 [0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	082	Press Roll:Feed:H-Limit:2-S Thk1		
[0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]				
[0 to 20 / 0 / 1°C] 084 Press Roll:Feed:L-Limit:2-S Thk2 [0 to 100 / 40 / 1°C]	083	Htg Roll:Feed:L-Limit:2-S Thk2		
[0 to 100 / 40 / 1°C]		•		
	084	Press Roll:Feed:L-Limit:2-S Thk2		
085 Htg Roll:Feed:H-Limit:2-S Thk2		<u> </u>		
	085	Htg Roll:Feed:H-Limit:2-S Thk2		

No.: RG178054 Date: 22-Jun-09

PAGE: 12/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG
	[0 to 20 / 10 / 1°C]	<u> </u>	
086	Press Roll:Feed:H-Limit:2-S Thk2		
	[0 to 128 / 50 / 1°C]		
087	Lamp OFF Timing:Plain Low Temp		
	[-483 to 483 / 0 / 1 mm]		
088	Lamp OFF Timing:Plain Normal Tem	р	
	[-483 to 483 / 0 / 1 mm]		
089	Lamp OFF Timing:Plain High Temp		
	[–483 to 483 / 0 / 1 mm]		
090	Lamp OFF Timing:Thin Low Temp		
	[–483 to 483 / 0 / 1 mm]		
091	Lamp OFF Timing:Thin Normal Temp	0	
	[-483 to 483 / 0 / 1 mm]		
092			
	[-483 to 483 / 0 / 1 mm]		
093	Lamp OFF Timing:Mid Thk Low Tem	р	
00.4	[-483 to 483 / 0 / 1 mm]	,	
094	Lamp OFF Timing:Mid Thk Normal T	emp	
005	[-483 to 483 / 0 / 1 mm]		
095	Lamp OFF Timing:Mid Thk High Tem	<u>1p</u>	
006	[-483 to 483 / 0 / 1 mm]		
096	Lamp OFF Timing:Thk1 Low Temp		
097	[–483 to 483 / 0 / 1 mm] Lamp OFF Timing:Thk1 Normal Tem	n	
097	[-483 to 483 / 0 / 1 mm]	ıμ	
098	Lamp OFF Timing:Thk1 High Temp		
030	[–483 to 483 / 0 / 1 mm]		
099	Lamp OFF Timing:Thk2 Low Temp		
	[-483 to 483 / 0 / 1 mm]		
100	Lamp OFF Timing:Thk2 Normal Tem	מו	
	[–483 to 483 / 0 / 1 mm]	<u>r</u>	
101	Lamp OFF Timing:Thk2 High Temp		
	[–483 to 483 / 0 / 1 mm]		
102	Lamp OFF Timing:Thk3 Low Temp		
	[-483 to 483 / 0 / 1 mm]		
103	Lamp OFF Timing:Thk3 Normal Tem	ip	
	[-483 to 483 / 0 / 1 mm]		
104	Lamp OFF Timing:Thk3 High Temp		
	[-483 to 483 / 0 / 1 mm]		
141	Idle Rotation after Feed:Time		
	[0 to 60 / 10 / 1 sec]		
142	Idle Rotation after Feed:Extend Time)	
	[0 to 250 / 60 / 1 sec]		
143	Low Temp Coeff:Htg Roll:Feed		
	[0 to 3 / 1 / 0.1]		
144	High Temp Coeff:Htg Roll:Feed		

Date: 22-Jun-09 No.: RG178054

PAGE: 13/93

	1 3 3 1 1 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1		
Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG1
	[0 to 3 / 1 / 0.1]		
145	Low Temp Coeff:Press Roll:Feed		
	[0 to 3 / 1 / 0.1]		
146	High Temp Coeff:Press Roll:Feed		
	[0 to 3 / 1 / 0.1]		
150	Uncoated:Thin:P-Roll Temp		
	[-20 to 20 / 3 / 1 deg]		
151	Uncoated:Plain:P-Roll Temp		
151	[-20 to 20 / 0 / 1 deg]		
152	Uncoated:Mid Thk:P-Roll Temp		
152	[-20 to 20 / 0 / 1 deg]		
153	Uncoated:Thk1:P-Roll Temp		
153	[-20 to 20 / -2 / 1 deg]		
154	Uncoated:Thk2:P-Roll Temp		
154	[-20 to 20 / -7 / 1 deg]		
155	Uncoated:Thk3:P-Roll Temp		
155	[-20 to 20 / -7 / 1 deg]		
156	Coated1:Thin:P-Roll Temp		
156	[-20 to 20 / 5 / 1 deg]		
157	Coated1:Thin:P-Roll Temp		
157	[-20 to 20 / 3 / 1 deg]		
150	Coated1:Mid Thk:P-Roll Temp		
158	[-20 to 20 / 0 : NA , -2 : EU / 1 deg]		
150	Coated1:Thk1:P-Roll Temp		
159	[-20 to 20 / 0 : NA , -7 : EU / 1 deg]		
160	Coated1:Thk2:P-Roll Temp		
160	[-20 to 20 / -7 / 1 deg]		
161	Coated1:Thk3:P-Roll Temp		
161	[-20 to 20 / -7 / 1 deg]		
400	Coated2:Thin:P-Roll Temp		
162	[-20 to 20 / 5 / 1 deg]		
162	Coated2:Plain:P-Roll Temp		
163	[-20 to 20 / 0 / 1 deg]		
164	Coated2:Mid Thk:P-Roll Temp		
164	[-20 to 20 / -2: NA, 3: EU / 1 deg]		
165	Coated2:Thk1:P-Roll Temp		
165	[-20 to 20 / -2: NA, -7 EU / 1 deg]		
166	Coated2:Thk2:P-Roll Temp		
166	[-20 to 20 / -7 / 1 deg]		
167	Coated2:Thk3:P-Roll Temp		
167	[-20 to 20 / -7 / 1 deg]		
400	Coated3:Thin:P-Roll Temp		
168	[-20 to 20 / 3 / 1 deg]		
400	Coated3:Plain:P-Roll Temp		
169	[-20 to 20 / 3 / 1 deg]		
170	Coated3:Mid Thk:P-Roll Temp		

Technical **B**ulletin

No.: RG178054 Date: 22-Jun-09

PAGE: 14/93

	• Oommoan		FAC
Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG1
	[-20 to 20 / -2 / 1 deg]		
474	Coated3:Thk1:P-Roll Temp		
171	[-20 to 20 / -7 / 1 deg]		
170	Coated3:Thk2:P-Roll Temp		
172	[-20 to 20 / -7 / 1 deg]		
173	Coated3:Thk3:P-Roll Temp		
173	[-20 to 20 / -7 / 1 deg]		
174	Special1:Thin:P-Roll Temp		
174	[-20 to 20 / 3 / 1 deg]		
175	Special1:Plain:P-Roll Temp		
175	[-20 to 20 / -2: NA, 0: EU / 1 deg]		
176	Special1:Mid Thk:P-Roll Temp		
170	[-20 to 20 / -2 / 1 deg]		
177	Special1:Thk1:P-Roll Temp		
177	[-20 to 20 / -7 / 1 deg]		
178	Special1:Thk2:P-Roll Temp		
170	[-20 to 20 / -7 / 1 deg]		
179	Special1:Thk3:P-Roll Temp		
173	[-20 to 20 / -7 / 1 deg]		
180	Special2:Thin:P-Roll Temp		
100	[-20 to 20 / 3 / 1 deg]		
181	Special2:Plain:P-Roll Temp		
101	[-20 to 20 / 0 / 1 deg]		
182	Special2:Mid Thk:P-Roll Temp		
.02	[-20 to 20 / -7 / 1 deg]		
183	Special2:Thk1:P-Roll Temp		
	[-20 to 20 / - 7 / 1 deg]		
184	Special2:Thk2:P-Roll Temp		
_	[-20 to 20 / -7 / 1 deg]		
185	Special2:Thk3:P-Roll Temp		
	[-20 to 20 / - 7 / 1 deg]		
186	Special3:Thin:P-Roll Temp		
	[-20 to 20 / 0 / 1 deg]		
187	Special3:Plain:P-Roll Temp		
	[-20 to 20 / -7: NA, 0 EU / 1 deg]		
188	Special3:Mid Thk:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		
189	Special3:Thk1:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		
190	Special3:Thk2:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		
191	Special3:Thk3:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		
192	Special4:Thin:P-Roll Temp		
102	[-20 to 20 / 3 / 1 deg]		
193	Special4:Plain:P-Roll Temp		

Technical Bulletin

No.: RG178054

PAGE: 15/93

1100	• • • • • • • • • • • • • • • • • • •		FAC
Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG1
	[-20 to 20 / 0 / 1 deg]		
194	Special4:Mid Thk:P-Roll Temp		
194	[-20 to 20 / 0: NA, -2 EU / 1 deg]		
195	Special4:Thk1:P-Roll Temp		
195	[-20 to 20 / 0 / 1 deg]		
196	Special4:Thk2:P-Roll Temp		
190	[-20 to 20 / -2: NA, -7: EU / 1 deg]		
197	Special4:Thk3:P-Roll Temp		
107	[-20 to 20 / -7 / 1 deg]		
198	Special5:Thin:P-Roll Temp		
100	[-20 to 20 / 3: NA, 0: EU / 1 deg]		
199	Special5:Plain:P-Roll Temp		
	[-20 to 20 / 3 / 1 deg]		
200	Special5:Mid Thk:P-Roll Temp		
	[-20 to 20 / -2 / 1 deg]		
201	Special5:Thk1:P-Roll Temp		
	[-20 to 20 / 0 / 1 deg]		
202	Special5:Thk2:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		
203	Special5:Thk3:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg] Special6:Thin:P-Roll Temp		
204	[-20 to 20 / 3: NA, 0: EU / 1 deg]		
	Special6:Plain:P-Roll Temp		
205	[-20 to 20 / 3 / 1 deg]		
	Special6:Mid Thk:P-Roll Temp		
206	[-20 to 20 / -2: NA, 0: EU / 1 deg]		
	Special6:Thk1:P-Roll Temp		
207	[-20 to 20 / 0 : NA , - 7 : EU / 1 deg]		
	Special6:Thk2:P-Roll Temp		
208	[-20 to 20 / -7 / 1 deg]		
000	Special6:Thk3:P-Roll Temp		
209	[-20 to 20 / -7 / 1 deg]		
040	Envelope:Thin:P-Roll Temp		
210	[-20 to 20 / 5 / 1 deg]		
211	Envelope:Plain:P-Roll Temp		
211	[-20 to 20 / 3 / 1 deg]		
212	Envelope:Md Thk:P-Roll Temp		
212	[-20 to 20 / 0 / 1 deg]		
213	Envelope:Thk1:P-Roll Temp		
213	[-20 to 20 / -2 / 1 deg]		
214	Envelope:Thk2:P-Roll Temp		
217	[-20 to 20 / -7 / 1 deg]		
215	Envelope:Thk3:P-Roll Temp		
	[-20 to 20 / -7 / 1 deg]		

Technical Bulletin

PAGE: 16/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09

 On 	page	es from 852 to 860
1108*		Fusing Temp Control 3
	007	Plain:BW:SP4
		[130 to 200 / 180 / 1°C]
	800	Plain:FC:SP4
		[130 to 200 / 180 / 1°C]
	009	Thin:BW:SP4
		[130 to 200 / 160: NA, 165: EU / 1°C]
	010	Thin:FC:SP4
		[130 to 200 / 160: NA, 165: EU / 1°C]
	011	Mid Thk:BW:SP4
		[130 to 200 / 180: NA, 185: EU / 1°C]
	012	Mid Thk:FC:SP4
		[130 to 200 / 180: NA, 185: EU / 1°C]
	013	Thk1:BW:SP4
		[130 to 200 / 175 / 1°C]
		Thk1:FC:SP4
		[130 to 200 / 175 / 1°C]
	015	Thk2:BW:SP4
		[130 to 200 / 185: NA, 195: EU / 1°C]
		Thk2:FC:SP4
		[130 to 200 / 185: NA, 195: EU / 1°C]
	017	Thk3:BW:SP4
		[130 to 200 / 195 / 1°C]
		Thk3:FC:SP4
		[130 to 200 / 195 / 1°C]
		2-S Plain:BW:SP4
		[130 to 200 / 180 / 1°C]
	020	2-S Plain:FC:SP4
		[130 to 200 / 180 / 1°C]
		2-S Thin:BW:SP4
		[130 to 200 / 160: NA, 165: EU / 1°C]
	022	2-S Thin:FC:SP4
		[130 to 200 / 160: NA, 165: EU / 1°C]
		2-S Mid Thk:BW:SP4
		[130 to 200 / 180: NA, 185: EU / 1°C]
	024	2-S Mid Thk:FC:SP4
		[130 to 200 / 180: NA, 185: EU / 1°C]
	025	2-S Thk1:BW:SP4
		[130 to 200 / 175 / 1°C]
]	026	2-S Thk1:FC:SP4
		[130 to 200 / 175 / 1°C]
		2-S Thk2:BW:SP4
		[130 to 200 / 185: NA, 195: EU / 1°C]
	028	2-S Thk2:FC:SP4
· · · · · · · · · · · · · · · · · · ·	_	

No.: RG178054

PAGE: 17/93

	i dominat E	diretiri	FAG
Model: Aeg	is-P1/C1	Date: 22-Jun-09	No.: RG1
	[130 to 200 / 185: NA, 195: EU / 1°C]		
035	Plain:BW:SP5		
	[130 to 200 / 170 / 1°C]		
036	Plain:FC:SP5		
Ī	130 to 200 / 170 / 1°C]		
037	Thin:BW:SP5		
	130 to 200 / 165: NA, 175: EU / 1°C]		
038	Thin:FC:SP5		
Ī	130 to 200 / 165: NA, 175: EU / 1°C]		
039	Mid Thk:BW:SP5		
	130 to 200 / 185 / 1°C]		
040	Mid Thk:FC:SP5		
Ī	130 to 200 / 185 / 1°C]		
	Thk1:BW:SP5		
	[130 to 200 / 175: NA, 180: EU / 1°C]		
	Thk1:FC:SP5		
Ī	[130 to 200 / 175: NA, 180: EU / 1°C]		
-	Thk2:BW:SP5		
Ī	130 to 200 / 190: NA, 195: EU / 1°C]		
	Thk2:FC:SP5		
 	130 to 200 / 190: NA, 195: EU / 1°C]		
	Thk3:BW:SP5		
l ==	130 to 200 / 200 / 1°C]		
	Thk3:FC:SP5		
-	130 to 200 / 200 / 1°C]		
	2-S Plain:BW:SP5		
L	[130 to 200 / 170 / 1°C]		
	2-S Plain:FC:SP5		
L	[130 to 200 / 170 / 1°C]		
	2-S Thin:BW:SP5		
	130 to 200 / 165: NA, 175: EU / 1°C]		
	2-S Thin:FC:SP5		
<u> </u>	130 to 200 / 165: NA, 175: EU / 1°C]		
051	2-S Mid Thk:BW:SP5		
L	130 to 200 / 185 / 1°C]		
	2-S Mid Thk:FC:SP5		
	130 to 200 / 185 / 1°C]		
	2-S Thk1:BW:SP5		
I	130 to 200 / 175: NA, 180: EU / 1°C]		
	2-S Thk1:FC:SP5		
E	130 to 200 / 175: NA, 180: EU / 1°C]		
	2-S Thk2:BW:SP5		
I	130 to 200 / 190: NA, 195: EU / 1°C]		
	2-S Thk2:FC:SP5		
l <u>-</u>	[130 to 200 / 190: NA, 195: EU / 1°C]		
	Plain:BW:SP6		

Date: 22-Jun-09 No.: RG178054

PAGE: 18/93

11100	I dominal E	Janothi	FAG
Model: Aeg	is-P1/C1	Date: 22-Jun-09	No.: RG1
	130 to 200 / 170 / 1°C]		
064	Plain:FC:SP6		
[130 to 200 / <mark>170</mark> / 1°C]		
	Γhin:BW:SP6		
	130 to 200 / 170 : NA , 175 : EU / 1°C]		
066	Γhin:FC:SP6		
	130 to 200 / 170: NA, 175: EU / 1°C]		
L	Mid Thk:BW:SP6		
	130 to 200 / 185: NA, 180: EU / 1°C]		
L	Mid Thk:FC:SP6		
	130 to 200 / 185: NA, 180: EU / 1°C]		
_	Γhk1:BW:SP6		
	130 to 200 / 180: NA, 190: EU / 1°C]		
L L	Γhk1:FC:SP6		
	130 to 200 / 180: NA, 190: EU / 1°C]		
<u> </u>	Γhk2:BW:SP6		
	130 to 200 / 190: NA, 200: EU / 1°C]		
<u> </u>	Γhk2:FC:SP6		
ļ	130 to 200 / 190: NA, 200: EU / 1°C]		
I	Thk3:BW:SP6		
	130 to 200 / 200 / 1°C]		
	Γhk3:FC:SP6		
	130 to 200 / 200 / 1°C]		
	2-S Plain:BW:SP6		
	130 to 200 / 170 / 1°C]		
<u> </u>	2-S Plain:FC:SP6		
	130 to 200 / 170 / 1°C]		
	2-S Thin:BW:SP6		
	130 to 200 / 170 : NA , 175 : EU / 1°C]		
	2-S Thin:FC:SP6		
	130 to 200 / 170: NA, 175: EU / 1°C]		
<u> </u>	2-S Mid Thk:BW:SP6		
ļ	130 to 200 / 185 : NA , 180 : EU / 1°C]		
-	2-S Mid Thk:FC:SP6		
	130 to 200 / 185 : NA , 180 : EU / 1°C]		
	2-S Thk1:BW:SP6		
ļ-	130 to 200 / 180: NA, 190: EU / 1°C]		
	2-S Thk1:FC:SP6		
	130 to 200 / 180: NA, 190: EU / 1°C]		
I	2-S Thk2:BW:SP6		
	130 to 200 / 190: NA, 200: EU / 1°C]		
	2-S Thk2:FC:SP6		
	130 to 200 / 190: NA, 200: EU / 1°C]		
	Plain:BW:Envelope		
	130 to 200 / 170 / 1°C]		
U92	Plain:FC:Envelope		

Date: 22-Jun-09 No.: RG178054

PAGE: 19/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG1
	[130 to 200 / 170 / 1°C]		
093	Thin:BW:Envelope		
	[130 to 200 / 160 / 1°C]		
094	Thin:FC:Envelope		
	[130 to 200 / 160 / 1°C]		
095	Mid Thk:BW:Envelope		
	[130 to 200 / 180 / 1°C]		
096	Mid Thk:FC:Envelope		
	[130 to 200 / 180 / 1°C]		
097	Thk1:BW:Envelope		
	[130 to 200 / 185 / 1°C]		
098	Thk1:FC:Envelope		
	[130 to 200 / 185 / 1°C]		
099	Thk2:BW:Envelope		
	[130 to 200 / 190 / 1°C]		
100	Thk2:FC:Envelope		
	[130 to 200 / 190 / 1°C]		
101	Thk3:BW:Envelope		
	[130 to 200 / 190 / 1°C]		
102	Thk3:FC:Envelope		
	[130 to 200 / 190 / 1°C]		
103	Press Roll Ctr:Reload		
	[110 to 160 / 150 / 1°C]		
104	Press Roll Ctr:Idle:Reload		
	[110 to 160 / 150 / 1°C]		
105	Press Roll Ctr:Standby:Normal Temp)	
	[110 to 160 / 125 / 1°C]		
106	Press Roll Ctr:Standby:Low Temp		
	[110 to 160 / 135 / 1°C]		
107	Press Roll Ctr:Standby:High Temp		
	[110 to 160 / 125 / 1°C]		
170	Thin:plain		
4=4	[-80 to -20 / -40 : NA , -45 EU / 1 deg]		
1/1	Thin:coat1		
470	[-80 to -20 / -45 / 1 deg]		
1/2	Thin:Coat2		
470	[-80 to -20 / -45 / 1 deg]		
1/3	Thin:Coat3		
474	[-80 to -20 / -50 / 1 deg]		
1/4	Thin:Special1		
175	[-80 to -20 / -50 / 1 deg]		
1/5	Thin:Special2		
170	[-80 to -20 / -55 / 1 deg]		
1/6	Thin:Special3		
477	[-80 to -20 / -60 / 1 deg]		
1//	Thin:Special4		

PAGE: 20/93 78054

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG1
[-80 to -20 / -40: NA	, -45 EU / 1 deg]		
178 Thin:Special5	· · · · · · · · · · · · · · · · · · ·		
[-80 to -20 / -45: NA	., -55 EU / 1 deg]		
179 Thin:Special6			
[-80 to -20 / -50: NA	., -55: EU / 1 deg]		
180 Thin:Envelope			
[-80 to -20 / -40 / 1 c	deg]		
181 Normal:plain			
[-80 to -20 / -55: NA	., -60: EU / 1 deg]		
182 Normal:coat1			
[-80 to -20 / -55 / 1 (deg]		
183 Normal:Coat2			
[-80 to -20 / -60 / 1 c	deg]		
184 Normal:Coat3			
[-80 to -20 / -55 / 1 c	deg]		
185 Normal:Special1			
[-80 to -20 / -65: NA	., -60: EU / 1 deg]		
186 Normal:Special2			
[-80 to -20 / -60 / 1 c	deg]		
187 Normal:Special3			
[-80 to -20 / -70: NA	., -60: EU / 1 deg]		
188 Normal:Special4			
[-80 to -20 / -60 / 1 c	deg]		
189 Normal:Special5			
[-80 to -20 / -50 / 1 c	deg]		
190 Normal:Special6			
[-80 to -20 / -50 / 1 c	deg]		
191 Normal:Envelope			
[-80 to -20 / -50: NA	., -60 : EU / 1 deg]		

On pages from 862 to 865 Usage of SP 1160

These SPs can adjust the threshold of the "fusing exit sensor: late jam (Jam 38)" for the each paper type. The default value for all paper types is "30" mm. This means that the mainframe determines the fusing exit sensor: late jam if the fusing exit sensor does not detect the leading edge of the next sheet of paper while the paper is being transported 30 mm from the normal detection point.

If the fusing belt has been damaged or scratched due to the paper jam at the fusing unit, do the following adjustment.

- 1. Enter the SP mode, and then select SP1160.
- 2. Select the suffix number of SP1160 to be adjusted.
- 3. Change the setting value from "30" (default) to "5".
- 4. Exit the SP mode.
- 5. Turn off the mainframe, and then turn on the mainframe.

These SPs are not designed to prevent the fusing exit sensor: late jam (Jam38).

Technical Bulletin

PAGE: 21/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

These SPs can only change the jam detection timing earlier.

1160*	Jam38 Detect Correct
	Adjusts the threshold for the Jam 38 detection.
	[5 to 30 / 30 / 1 mm]

On page 867

	1201*		CPM Down Setting
ſ		017	L Temp:CPM Down:Thk3
			[0 to 3 / 2 / 1]
			0: No CPM Down, 1: CPM Down 1, 2: CPM Down 2, 3: CPM Down
			3

On pages from 872 to 873

	25 110111 072 10 073
	Image Pos:Sub (Image Position Adjustment: Sub Scan)
001	Back Main U Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from tray 1 (mainframe; upper tray).
	[-3 to 3 / 0 / 0.1 mm]
	Back Main L Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from tray 2 (mainframe; lower tray).
	[-3 to 3 / 0 / 0.1 mm]
004	Back A4LCT U Tray (G178 only)
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the upper tray of the A4 LCT (B832
	option).
	[-3 to 3 / 0 / 0.1 mm]
005	Back A4LCT M Tray (G178 only)
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the middle tray of the A4 LCT (B832
	option).
	[-3 to 3 / 0 / 0.1 mm]
006	Back A4LCT L Tray (G178 only)
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the lower tray of the A4 LCT (B832
	option).
	[-3 to 3 / 0 / 0.1 mm]
007	Back By-Pass Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the by-pass tray (B833 option).
	[-3 to 3 / 0 / 0.1 mm]
800	Back A3LCT1 U Tray
	Adjusts the laser scanning timing in the sub scan direction for the
	back side of paper fed from the upper tray of the LCT MF

Technical Bulletin

PAGE: 22/93

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG178054
	(mainframe; tray 3) or A3 LCT (D355 o	ption).	
	[-3 to 3 / 0 / 0.1 mm]		
009	Back A3LCT1 L Tray		
	Adjusts the laser scanning timing in the		or the
	back side of paper fed from the lower to		
	(mainframe; tray 4) or A3 LCT (D355 o	ption).	
	[-3 to 3 / 0 / 0.1 mm]		
010	Sub Back A3LCT2 U Tray		
	Adjusts the laser scanning timing in the	sub scan direction for	or the
	back side of paper fed from the upper t	ray of the A3 LCT (D3	355
	option).		
	[-3 to 3 / 0 / 0.1 mm]		
011	Sub Back A3LCT2 L Tray		
	Adjusts the laser scanning timing in the	sub scan direction for	or the
	back side of paper fed from the lower to	ray of the A3 LCT (D3	355
	option).		
	[-3 to 3 / 0 / 0.1 mm]		

On pages from 873 to 874

1721*	Image Pos:Main (Image Position Adjustment: Main Scan)
001	Back Main U Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from tray 1 (mainframe; upper tray).
	[-3 to 3 / 0 / 0.1 mm]
002	Back Main L Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from tray 2 (mainframe; lower tray).
	[-3 to 3 / 0 / 0.1 mm]
004	Back A4LCT U Tray (G178 only)
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the upper tray of the A4 LCT (B832
	option).
	[-3 to 3 / 0 / 0.1 mm]
005	Back A4LCT M Tray (G178 only)
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the middle tray of the A4 LCT (B832
	option).
	[-3 to 3 / 0 / 0.1 mm]
006	Back A4LCT L Tray (G178 only)
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the lower tray of the A4 LCT (B832
	option).
007	[-3 to 3 / 0 / 0.1 mm]
007	Back By-Pass Tray
	Adjusts the laser scanning timing in the main scan direction for the
	back side of paper fed from the by-pass tray (B833 option).

Technical Bulletin

PAGE: 23/93

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG178054
	[-3 to 3 / 0 / 0.1 mm]		
800	Back A3LCT1 U Tray		
	Adjusts the laser scanning timing in the		for the
	back side of paper fed from the upper t	•	
	(mainframe; tray 3) or A3 LCT (D355 o	ption).	
	[-3 to 3 / 0 / 0.1 mm]		
009	Back A3LCT1 L Tray		
	Adjusts the laser scanning timing in the		for the
	back side of paper fed from the lower to	•	
	(mainframe; tray 4) or A3 LCT (D355 or	ption).	
040	[-3 to 3 / 0 / 0.1 mm]		
010	Sub Back A3LCT2 U Tray		for the o
	Adjusts the laser scanning timing in the		
	back side of paper fed from the upper t option).	ray of the A3 LCT (D	333
	[-3 to 3 / 0 / 0.1 mm]		
011	Sub Back A3LCT2 L Tray		
	Adjusts the laser scanning timing in the	main scan direction	for the
	back side of paper fed from the lower to		
	option).	a, c. 110 / 10 Lo 1 (De	,55
	[-3 to 3 / 0 / 0.1 mm]		

On pages from 874 to 875

1730*	Skew Detect Disable (Skew Detection Disable)
001	Main U Tray
	Enables or disables the skew detection for paper fed from tray 1
	(mainframe; upper tray).
	[0 or 1 / 0 / -]
	0: Skew detection ON (enabled)
	1: Skew detection OFF (disabled)
002	Main L Tray
	Enables or disables the skew detection for paper fed from tray 2
	(mainframe; lower tray).
	[0 or 1 / 0 / -]
	0: Skew detection ON (enabled)
	1: Skew detection OFF (disabled)
004	Back A4LCT U Tray (G178 only)
	Enables or disables the skew detection for paper fed from the upper
	tray of the A4 LCT (B832 option).
	[0 or 1 / 0 / -]
	0: Skew detection ON (enabled)
	1: Skew detection OFF (disabled)
005	Back A4LCT M Tray (G178 only)
	Enables or disables the skew detection for paper fed from the
	middle tray of the A4 LCT (B832 option).
	[0 or 1 / 0 / -]

Technical Bulletin

PAGE: 24/93

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG178054
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
006 Back A4LCT L Tray (G178 only)		
Enables or disables the skew detection	on for paper fed from th	ie lower
tray of the A4 LCT (B832 option).		
[0 or 1 / 0 / -]		
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
007 By-Pass Tray		
Enables or disables the skew detection	on for paper fed from th	ie by-
pass tray (B833 option).		
[0 or 1 / 0 / -]		
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
008 A3 LCT1 U Tray	on for nanor fod from t	ho uppor
Enables or disables the skew detecti tray of the LCT MF (mainframe; tray 3		
[0 or 1 / 0 / -]	b) of A3 LCT (D333 opt	.1011).
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
009 A3 LCT1 L Tray		
Enables or disables the skew detecti	on for paper fed from t	he lower
tray of the LCT MF (mainframe; tray 4		
[0 or 1 / 0 / -]	(_ 000 0	
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
010 A3 LCT2 U Tray		
Enables or disables the skew detecti	on for paper fed from t	he upper
tray of the A3 LCT (D355 option).		
[0 or 1 / 0 / -]		
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		
011 A3 LCT2 L Tray		
Enables or disables the skew detecti	on for paper fed from t	the lower
tray of the A3 LCT (D355 option).		
[0 or 1 / 0 / -]		
0: Skew detection ON (enabled)		
1: Skew detection OFF (disabled)		

On pages from 875 to 877

1761*	Side-to-Side Reg Disable (Side-to-Side Registration Disable)
001	Main U Tray

Technical Bulletin

PAGE: 25/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09 Enables or disables the side-to-side registration adjustment for paper fed from tray 1 (mainframe; upper tray). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 002 Main L Tray Enables or disables the side-to-side registration adjustment for paper fed from tray 2 (mainframe; lower tray). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 004 A4LCT U Tray (G178 only) Enables or disables the side-to-side registration adjustment for paper fed from the upper tray of the A4 LCT (B832 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 005 A4LCT M Tray (**G178 only**) Enables or disables the side-to-side registration adjustment for paper fed from the middle tray of the A4 LCT (B832 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 006 A4LCT L Tray (G178 only) Enables or disables the side-to-side registration adjustment for paper fed from the lower tray of the A4 LCT (B832 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 007 By-Pass Trav Enables or disables the side-to-side registration adjustment for paper fed from the by-pass tray (B833 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 008 A3 LCT1 U Tray Enables or disables the side-to-side registration adjustment for paper fed from the upper tray of the LCT MF (mainframe; tray 3) or A3 LCT (D355 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 009 A3 LCT1 L Tray Enables or disables the side-to-side registration adjustment for paper fed from the lower tray of the LCT MF (mainframe; tray 4) or A3 LCT (D355 option). [0 or 1 / **0** / -]

Technical Bulletin

PAGE: 26/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 010 A3 LCT2 U Tray Enables or disables the side-to-side registration adjustment for paper fed from the upper tray of the A3 LCT (D355 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled) 011 A3 LCT2 L Tray Enables or disables the side-to-side registration adjustment for paper fed from the lower tray of the A3 LCT (D355 option). [0 or 1 / **0** / -] 0: Side-to-side registration adjustment ON (enabled) 1: Side-to-side registration adjustment OFF (disabled)

After SP1805 on page 878

These SPs are newly added.

	· · · · · · · · · · · · · · · · · · ·	
1806*	Rotation Speed DFU	
001	Feed Motor 1	
	Adjusts the rotation speed of the drive motor right in the buffer pass unit (M379). [1000 to 2500 / 1232.5 / 0.1 rpm]	
002	Feed Motor 2	
	Adjusts the rotation speed of the drive motor left in the buffer pass unit (M379). [1000 to 2500 / 1232.5 / 0.1 rpm]	

On page 879

1902*		Cleaning Web Setting
	004	Web Near End Setting
		[0 to 100 / <mark>81</mark> / 1 %]

1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
015	Uncoated:Thk2:L-Temp
	Adjusts the pressure roller position for uncoated thick 2 paper in
	low temperature mode.
	[40 to 2000 / 330: NA, 40: EU / 10 msec/step]

Technical Bulletin

PAGE: 27/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

On page 899

1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
021	Coated1:Thk2:L-Temp
	Adjusts the pressure roller position for coated 1 and thick 2 paper in
	low temperature mode.
	[40 to 2000 / 40 / 10 msec/step]

On page 900

on page tot	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
026	Coated2:Thk1:L-Temp
	Adjusts the pressure roller position for coated 2 and thick 1 paper in
	low temperature mode.
	[40 to 2000 / 330: NA, 40: EU / 10 msec/step]
032	Coated3:Thk1:L-Temp
	Adjusts the pressure roller position for coated 3 and thick 1 paper in
	low temperature mode.
	[40 to 2000 / 330: NA, 40: EU / 10 msec/step]

On page 901

on page our	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the pressure roller lift motor. If you set a longer time than before, the nip width between the fusing belt and pressure roller will be wider.
038	Special1:Thk1:L-Temp
	Adjusts the pressure roller position for special 1 and thick 1 paper in low temperature mode. [40 to 2000 / 40: NA, 330: EU / 10 msec/step]

On page 004	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
055	Special4:Mid Thk:L-Temp
	Adjusts the pressure roller position for special 4 and middle thick
	paper in low temperature mode.
	[40 to 2000 / 330 : NA , 510 : EU / 10 msec/step]

Technical Bulletin

PAGE: 28/93

Model: Aegis-P1/C1

Date: 22-Jun-09

No.: RG178054

Special4:Thk1:L-Temp

Adjusts the pressure roller position for special 4 and thick 1 paper in low temperature mode.

[40 to 2000 / 510: NA, 330: EU / 10 msec/step]

On page 907

on page ser	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
081	Uncoated:Thk2:Over L-Temp
	Adjusts the pressure roller position for uncoated thick 2 paper at a
	higher temperature than low temperature mode.
	[40 to 2000 / 330: NA, 40: EU / 10 msec/step]

On page 908

en page eee	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
087	Coated1:Thk2:Over L-Temp
	Adjusts the pressure roller position for coated 1 and thick 2 paper at
	a higher temperature than low temperature mode.
	[40 to 2000 / 40/ 10 msec/step]

On page 909

1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
092	Coated2:Thk1:Over L-Temp
	Adjusts the pressure roller position for coated 2 and thick 1 paper at
	a higher temperature than low temperature mode.
	[40 to 2000 / 330: NA, 40: EU / 10 msec/step]

1905*		Nip Width Setting
		These SPs adjust the pressure roller position by controlling the
		pressure roller lift motor. If you set a longer time than before, the
		nip width between the fusing belt and pressure roller will be wider.
0	98	Coated3:Thk1:Over L-Temp

Technical Bulletin

PAGE: 29/93

Model: Aegis-P1/C1

Adjusts the pressure roller position for coated 3 and thick 1 paper at a higher temperature than low temperature mode.

[40 to 2000 / 330: NA, 40: EU / 10 msec/step]

On page 911

1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
104	Special1:Thk1:Over L-Temp
	Adjusts the pressure roller position for special 1 and thick 1 paper
	at a higher temperature than low temperature mode.
	[40 to 2000 / 40: NA, 330: EU / 10 msec/step]

On page 913

en page 010	
1905*	Nip Width Setting
	These SPs adjust the pressure roller position by controlling the
	pressure roller lift motor. If you set a longer time than before, the
	nip width between the fusing belt and pressure roller will be wider.
121	Special4:Mid Thk:Over L-Temp
	Adjusts the pressure roller position for special 4 and middle thick
	paper at a higher temperature than low temperature mode.
	[40 to 2000 / 330: NA, 510: EU / 10 msec/step]
122	Special4:Thk1:Over L-Temp
	Adjusts the pressure roller position for special 4 and thick 1 paper
	at a higher temperature than low temperature mode.
	[40 to 2000 / 510: NA, 330: EU / 10 msec/step]

1906*		De-curler Setting
	001	Paper Path Selection
		Adjusts the home position of the de-curler unit.
		[0 to 5 / 3 / 1 /step]
		0: Face curl correction = Lower path, Deculer nip: 0.3 mm
		1: Face curl correction (weak) = Lower path, Deculer nip: 1.5 mm
		2: Face curl correction (strong) = Lower path, Deculer nip: 2.1 mm
		3: Back curl correction = Upper path, Deculer nip: 0.3 mm
		4: Back curl correction (weak) = Upper path, Deculer nip: 1.5 mm
		5: Back curl correction (strong) = Upper path, Deculer nip: 2.1 mm
	005	Line Speed Adjust:Pos.1
		[–2.5 to 12.5 / 2 / 0.5%]
	006	Line Speed Adjust:Pos.2
		[–2.5 to 12.5 / <mark>3</mark> / 0.5%]

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 30/93

1907*	Fusin Motor Rotation
001	Fusing Motor Rotation Control
	[678.8 to 1584 / 1196.9 / 0.1 rpm]

On pages from 920 to 925

 On pages from 920 to 925 		
1909*	Fusing Mtr Rotation Correct	
	These SPs correct the rotation of the fusing motor for each paper	
	type.	
020	Uncoated:Thin	
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]	
021	Uncoated:Plain	
	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]	
022	Uncoated:Mid Thk	
	[-10 to 10 / 0: NA, -1:EU / 0.1% /step]	
023	Uncoated:Thk1	
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]	
024	Uncoated:Thk2	
	[-10 to 10 / 0: NA, -2:EU / 0.1% /step]	
025	Uncoated:Thk3	
	[-10 to 10 / -2 / 0.1% /step]	
026	Coated1:Thin	
	[-10 to 10 / 0 / 0.1% /step]	
027	Coated1:Plain	
	[-10 to 10 / 0 / 0.1% /step]	
028	Coated1:Mid Thk	
	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]	
029	Coated1:Thk1	
	[-10 to 10 / -1: NA, 0:EU / 0.1% /step]	
030	Coated1:Thk2	
	[-10 to 10 / -1: NA, 0:EU / 0.1% /step]	
031	Coated1:Thk3	
	[-10 to 10 / 0: NA, -2:EU / 0.1% /step]	
032	Coated2:Thin	
	[-10 to 10 / -3 / 0.1% /step]	
033	Coated2:Plain	
	[-10 to 10 / 0 / 0.1% /step]	
034	Coated2:Mid Thk	
	[-10 to 10 / 0 / 0.1% /step]	
035	Coated2:Thk1	
	[-10 to 10 / 0: NA, -2:EU / 0.1% /step]	
036	Coated2:Thk2	
	[-10 to 10 / -1 / 0.1% /step]	
037	Coated2:Thk3	
	[-10 to 10 / -2: NA, -3:EU / 0.1% /step]	
038	Coated3:Thin	

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 31/93

	1 0 0 11111 0 0 11		IAC
Model: A	egis-P1/C1	Date: 22-Jun-09	No.: RG1
	[-10 to 10 / 0 / 0.1% /step]		
039	Coated3:Plain		
	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]		
040	Coated3:Mid Thk		
	[-10 to 10 / -3: NA, 0:EU / 0.1% /step]		
041	Coated3:Thk1		
	[-10 to 10 / -1: NA, 0:EU / 0.1% /step]		
042	Coated3:Thk2		
	[-10 to 10 / -3: NA, 0:EU / 0.1% /step]		
043	Coated3:Thk3		
	[-10 to 10 / 0 / 0.1% /step]		
044	Special1:Thin		
	[-10 to 10 / -3 / 0.1% /step]		
045	Special1:Plain		
	[-10 to 10 / -1: NA, 0:EU / 0.1% /step]		
046	Special1:Mid Thk		
	[-10 to 10 / -3: NA, -1:EU / 0.1% /step]		
047	Special1:Thk1		
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]		
048	Special1:Thk2		
0.10	[-10 to 10 / 0: NA, -2:EU / 0.1% /step]		
049	Special1:Thk3		
050	[-10 to 10 / -3: NA, -2:EU / 0.1% /step]		
050	Special2:Thin		
054	[-10 to 10 / -3 / 0.1% /step]		
051	Special2:Plain		
052	[-10 to 10 / -3: NA, -1:EU / 0.1% /step] Special2:Mid Thk		
052	[-10 to 10 / 0 / 0.1% /step]		
053	Special2:Thk1		
033	[-10 to 10 / 0 / 0.1% /step]		
054	Special2:Thk2		
004	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]		
055	Special2:Thk3		
	[-10 to 10 / -2: NA, -3:EU / 0.1% /step]		
056	Special3:Thin		
	[-10 to 10 / -3 / 0.1% /step]		
057	Special3:Plain		
	[-10 to 10 / 0 : NA , - 3 : EU / 0.1% /step]		
058	Special3:Mid Thk		
	[-10 to 10 / -2 / 0.1% /step]		
059	Special3:Thk1		
	[-10 to 10 / -2 / 0.1% /step]		
060	Special3:Thk2		
	[-10 to 10 / -3: NA, -2:EU / 0.1% /step]		
061	Special3:Thk3		
-	•		

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 32/93

	1 0 0 11111 0 0 1 1		IA
Model: A	egis-P1/C1	Date: 22-Jun-09	No.: RG1
	[-10 to 10 / -3: NA, 0:EU / 0.1% /step]		
062	Special4:Thin		
	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]		
063	Special4:Plain		
	[-10 to 10 / -3: NA, 0:EU / 0.1% /step]		
064	Special4:Mid Thk		
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]		
065	Special4:Thk1		
	[-10 to 10 / -3 / 0.1% /step]		
066	Special4:Thk2		
	[-10 to 10 / -2 / 0.1% /step]		
067	Special4:Thk3		
	[-10 to 10 / -3 / 0.1% /step]		
068	Special5:Thin		
	[-10 to 10 / 0 / 0.1% /step]		
069	Special5:Plain		
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]		
070	Special5:Mid Thk		
	[-10 to 10 / -1: NA, -3:EU / 0.1% /step]		
071	Special5:Thk1		
	[-10 to 10 / -2: NA, 0:EU / 0.1% /step]		
072	Special5:Thk2		
	[-10 to 10 / -2: NA, -3:EU / 0.1% /step]		
073	Special5:Thk3		
	[-10 to 10 / -2: NA, -3:EU / 0.1% /step]		
074	Special6:Thin		
	[-10 to 10 / -0: NA, -3:EU / 0.1% /step]		
075	Special6:Plain		
070	[-10 to 10 / -3 / 0.1% /step]		
076	Special6:Mid Thk		
077	[-10 to 10 / 0: NA, -3:EU / 0.1% /step]		
077	Special6:Thk1		
070	[-10 to 10 / 0 / 0.1% /step] Special6:Thk2		
078	[-10 to 10 / -3: NA, -2:EU / 0.1% /step]		
079	Special6:Thk3		
019	[-10 to 10 / -3: NA, -2:EU / 0.1% /step]		
080	Envelope:Thin		
000	[-10 to 10 / 0 / 0.1% /step]		
081	Envelope:Plain		
001	[-10 to 10 / 0 / 0.1% /step]		
082	Envelope:Mid Thk		
002	[-10 to 10 / 0 / 0.1% /step]		
083	Envelope:Thk1		
003	[-10 to 10 / 0 / 0.1% /step]		
084	Envelope:Thk2		
004	LITYCIOPC. ITINZ		

Technical Bulletin

PAGE: 33/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

	[-10 to 10 / 0 / 0.1% /step]
085	Envelope:Thk3
	[-10 to 10 / 0 / 0.1% /step]

On pages from 925 to 926

On pages from 925 to 926	
1910*	Dbl-Feed Detect:Disable (Double Feed Detection: Disable)
001	Main U Tray
	Enables or disables the double feed detection for paper fed from
	tray 1 (mainframe; upper tray).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
	Main L Tray
	Enables or disables the double feed detection for paper fed from
	tray 2 (mainframe; lower tray).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
004	A4 LCT1 U Tray (G178 only)
	Enables or disables the double feed detection for paper fed from the
	upper tray of the A3 LCT (B832 option).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
005	A4 LCT1 M Tray (G178 only)
	Enables or disables the double feed detection for paper fed from the
	middle tray of the A3 LCT (B832 option).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
	1: Double feed detection OFF (disabled)
006	A4 LCT1 L Tray (G178 only)
	Enables or disables the double feed detection for paper fed from the
	lower tray of the A3 LCT (B832 option).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
007	1: Double feed detection OFF (disabled)
007	By-Pass Tray
	Enables or disables the double feed detection for paper fed from the
	by-pass tray (B833 option).
	[0 or 1 / 0 / -]
	0: Double feed detection ON (enabled)
000	1: Double feed detection OFF (disabled)
800	A3 LCT1 U Tray
	Enables or disables the double feed detection for paper fed from the
	upper tray of the LCT MF (mainframe; tray 3) or A3 LCT (D355
	option).

Technical Bulletin

PAGE: 34/93

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG178054
[0 or 1 / 0 / -] 0: Double feed detection ON (enabled 1: Double feed detection OFF (disable	•	
009 A3 LCT1 L Tray		
Enables or disables the double feed double feed double tray of the LCT MF (mainframe; option).	• •	
[0 or 1 / 0 / -]		
0: Double feed detection ON (enabled 1: Double feed detection OFF (disable		
010 A3 LCT2 U Tray		
Enables or disables the double feed double feed double tray of the A3 LCT (D355 option [0 or 1 / 0 / -]	• •	from the
0: Double feed detection ON (enabled 1: Double feed detection OFF (disable		
011 A3 LCT2 L Tray		
Enables or disables the double feed double feed double tray of the A3 LCT (D355 option [0 or 1 / 0 / -]		from the
0: Double feed detection ON (enabled 1: Double feed detection OFF (disable	•	

After SP1914-018 on page 929
 These SPs are not described in Service Manual for AG-C1.

1914*		CIS P Pass Pixel Display
	018	Main L Tray:TShift3
		[0 to 1216 / 0 / 1 dot]
	019	A4LCT U Tray:LEdge1 (G178 only)
		[0 to 1216 / 0 / 1 dot]
	020	A4LCT U Tray:LEdge2 (G178 only)
		[0 to 1216 / 0 / 1 dot]
	021	A4LCT U Tray:LEdge3 (G178 only)
		[0 to 1216 / 0 / 1 dot]
	022	A4LCT U Tray:LShift1 (G178 only)
		[0 to 1216 / 0 / 1 dot]
	023	A4LCT U Tray:LShift2 (G178 only)
		[0 to 1216 / 0 / 1 dot]
		A4LCT U Tray:LShift3 (G178 only)
		[0 to 1216 / 0 / 1 dot]
		A4LCT U Tray:TShift1 (G178 only)
		[0 to 1216 / 0 / 1 dot]
		A4LCT U Tray:TShift2 (G178 only)
		[0 to 1216 / 0 / 1 dot]
		A4LCT U Tray:TShift3 (G178 only)
		[0 to 1216 / 0 / 1 dot]

Technical Bulletin PAGE: 35/93

Date: 22-Jun-09 No.: RG178054

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG1
028 A4LCT M Tray:LEdge1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
029 A4LCT M Tray:LEdge2 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
030 A4LCT M Tray:LEdge3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
031 A4LCT M Tray:LShift1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
032 A4LCT M Tray:LShift2 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
033 A4LCT M Tray:LShift3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
034 A4LCT M Tray:TShift1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
035 A4LCT M Tray:TShift2 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
036 A4LCT M Tray:TShift3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
037 A4LCT L Tray:LEdge1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
038 A4LCT L Tray:LEdge2 (G178 only) [0 to 1216 / 0 / 1 dot]		
039 A4LCT L Tray:LEdge3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
040 A4LCT L Tray:LShift1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
041 A4LCT L Tray:LShift2 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
042 A4LCT L Tray:LShift3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
043 A4LCT L Tray:TShift1 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
044 A4LCT L Tray:TShift2 (G178 only)		
[0 to 1216 / 0 / 1 dot]		
045 A4LCT L Tray:TShift3 (G178 only)		
[0 to 1216 / 0 / 1 dot]		

On page 935

•	page 555	
1916*	CIS LED Power Magnification	
	001 Variable Magnification	
	[1 to 5 / 1.61 / 0.01]	

1918*	Double-feed Detect

Technical Bulletin

PAGE: 36/93

Model: Ae	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	Thresh Adj:M1 [0 to 100 / 30 / 1%]		
	Thresh Adj:M2		
	[0 to 100 / 30 / 1%]		
003	Thresh Adj:M3		
	[0 to 100 / 5 / 1%]		

On pages from 939 to 940

On pages from 940 to 941

	C3 110111 0+0 t0 0+1
1941*	Stand-by:Execute Setting
001	Fusing Fan 5-6
	[0 or 1 / 0 / 1]
	0: OFF, 1: ON
002	Fusing Fan 1-3
	[0 or 1 / 0 / 1]
	0: OFF, 1: ON
003	Ozone Fan:YMCK
	[0 or 1 / 0 / 1]
	0: OFF, 1: ON
004	Development Fan:YMCK
	[0 or 1 / 0 / 1]
	0: OFF, 1: ON
005	Black PCDU Fan
	[0 or 1 / 0 / 1]
	0: OFF, 1: ON
006	Fusing Fan 5-6:Half Speed

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 37/93

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG1
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		
007 Fusing Exhaust Fan 1-3:Half Speed		
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		
008 Fusing Fan 4		
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		
009 Fusing Exhaust Fan 1-3		
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		
010 Fusing Fan 4:Half Speed		
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		
011 Fusing Exhaust Fan 1-3:Half Speed		
[0 or 1 / 0 / 1]		
0: OFF, 1: ON		

On pages from 954 to 955

<u> </u>	100 Hom 00+ to 000
2113*	Side-to-Side Regist Adj
00	1 Main U Tray
	[–10 to 10 / 0 / 0.1 mm]
00	2 Main L Tray
	[–10 to 10 / 0 / 0.1 mm]
00	4 A4 LCT1 Upper Tray (G178 only)
	[-10 to 10 / 0 / 0.1 mm]
00	5 A4 LCT1 Middle Tray (G178 only)
	[-10 to 10 / 0 / 0.1 mm]
00	6 A4 LCT1 Lower Tray (G178 only)
	[–10 to 10 / 0 / 0.1 mm]
00	7 Bypass Tray
	[–10 to 10 / 0 / 0.1 mm]
00	B A3 LCT1 Upper Tray
	[–10 to 10 / 0 / 0.1 mm]
00	9 A3 LCT1 Lower Tray
	[–10 to 10 / 0 / 0.1 mm]
01	A3 LCT2 Upper Tray
	[–10 to 10 / 0 / 0.1 mm]
01	1 A3 LCT2 Lower Tray
	[–10 to 10 / 0 / 0.1 mm]

2	2186*	2-Point Synchronizing	
	0	Selection	

Technical Bulletin

PAGE: 38/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG			178054	
	Enables or disables the 2-point synchro [0 or 1 / 1 / 1] 0: Disable, 1: Enable	onizing.		
002	Paper Interval Specifies the interval for the 2-point syl [0 to 999 / 1 / 1 sec]	nchronizing during job).	
003	Paper Interval Corr: ON/ OFF Selects the method of the 2-point sync [0 or 1 / 0 / 1] 0: D-Phase correction, 1: PLL, D-Phas			

On page 982

2251*		Force Tnr Supply
	009	Manual Execute:Repeat Times
		[1 to 10 / 8 / 1 time]

On page 983

Toner Fill When executing SP2-253-001 to -006, make sure the following conditions 1. Fist, turn off and on the machine after opening the front left or right doc 2. Make sure that the target color toner bottle is installed and the toner hopper cover is close. 3. Enter the SP mode, and then execute SP2-253-xxx. 001 Manual Execute:K [0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M		
 Fist, turn off and on the machine after opening the front left or right dod Make sure that the target color toner bottle is installed and the toner hopper cover is close. Enter the SP mode, and then execute SP2-253-xxx. Manual Execute:K or 1 / 0 / -] Manual Execute:C or 1 / 0 / -] Manual Execute:M 		
2. Make sure that the target color toner bottle is installed and the toner hopper cover is close. 3. Enter the SP mode, and then execute SP2-253-xxx. 001 Manual Execute:K [0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M		
hopper cover is close. 3. Enter the SP mode, and then execute SP2-253-xxx. 001 Manual Execute:K [0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M	1.	Fist, turn off and on the machine after opening the front left or right door.
3. Enter the SP mode, and then execute SP2-253-xxx. 001 Manual Execute:K [0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M	2.	
001 Manual Execute:K [0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M		
[0 or 1 / 0 / -] 002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M		
002 Manual Execute:C [0 or 1 / 0 / -] 003 Manual Execute:M	001 <u>M</u> :	anual Execute:K
[0 or 1 / 0 / -] 003 Manual Execute:M	[0]	or 1 / 0 / -]
003 Manual Execute:M	002 M	anual Execute:C
	[0]	or 1 / 0 / -]
[0 or 1 / 0 /]	003 M	anual Execute:M
[0 01 1 7 0 7 -]	[0]	or 1 / 0 / -]
004 Manual Execute:Y	004 M	anual Execute:Y
[0 or 1 / 0 / -]	[0]	or 1 / 0 / -]
005 Manual Execute:Col	005 M	anual Execute:Col
[0 or 1 / 0 / -]	[0]	or 1 / 0 / -]
006 Manual Execute:All Col	006 M	anual Execute:All Col
[0 or 1 / 0 / -]	[0]	or 1 / 0 / -]
007* Fill Time:K	007* Fi	II Time:K
Specifies the time for the manual toner filling for black (SP2253-001).	Sr	pecifies the time for the manual toner filling for black (SP2253-001).
[0 to 200 / 120 / 1 sec]	[0]	to 200 / 120 / 1 sec]
008* Fill Time:Col	008* Fi	Il Time:Col
Specifies the time for the manual toner filling for color (SP2253-002 to -00	Sr	pecifies the time for the manual toner filling for color (SP2253-002 to -006).
[0 to 200 / 120 / 1 sec]	LU.	to 200 / 120 / 1 sec]

■ Before SP2231 on **page 986**These SPs are not described in Service Manual for AG-C1.

Technical Bulletin

PAGE: 39/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

	5
2260	Pot.Sn Check Execute
001	All Col
	Execute the potential sensor check for the all drums (YMCK).
	 The result of this check can be confirmed with SP2261.
002	Execute:K
	Execute the potential sensor check for the black drum.
	 The result of this check can be confirmed with SP2261-001.
003	Execute:C
	Execute the potential sensor check for the cyan drum.
	 The result of this check can be confirmed with SP2261-002.
004	Execute:M
	Execute the potential sensor check for the magenta drum.
	 The result of this check can be confirmed with SP2261-003.
005	Execute:Y
	Execute the potential sensor check for the yellow drum.
	 The result of this check can be confirmed with SP2261-004.

On page 1006

2362*	Resist Coeff R Level:R-2 DFU	
042	Special1 Size2:Front:PTR	
	[50 to 200 / 124 / 1%]	
043	Special1 Size3:Front:PTR	
	[50 to 200 / 140 / 1%]	
044	Special1 Size4:Front:PTR	
	[50 to 200 / 157 / 1%]	

On page 1006

2368*	Paper Thickness Correct Coeff DFU
018	Coated2 Thick3:PTR
	[50 to 200 / 125 / 1%]

On page 1048

2368*	Paper Thickness Correct Coeff DFU
058	Special6 Thick1:PTR
	[50 to 200 / 108 / 1%]

On pages from 1072 to 1073

OII	pugu	5 110111 1072 to 1070
2402*		PTR Bias Display
00		Main U Tray:Front
	001	[–300 to 0 / 0 / 1 μA]
	002	Main U Tray:Back
	002	[–300 to 0 / 0 / 1 μA]
	003	Main L Tray:Front

Technical Bulletin

PAGE: 40/93

Model: Aeg	gis-P1/C1	Date: 22-Jun-09	No.: RG178054
	[–300 to 0 / 0 / 1 μA]		
004	Main L Tray:Back		
004	[–300 to 0 / 0 / 1 μA]		
007	A4 LCT U Tray:Front (G178 only)		
007	[–300 to 0 / - / 1 μA]		
008	A4 LCT U Tray:Back (G178 only)		
	[–300 to 0 / - / 1 μA]		
009	A4 LCT M Tray:Front (G178 only)		
	[-300 to 0 / - / 1 μA]		
010	A4 LCT M Tray:Back (G178 only)		
	[-300 to 0 / - / 1 μA]		
011	A4 LCT L Tray:Front (G178 only)		
	[-300 to 0 / - / 1 µA]		
012	A4 LCT L Tray:Back (G178 only) [–300 to 0 / - / 1 μΑ]		
	Bypass Tray:Front		
013	[–300 to 0 / 0 / 1 μA]		
0.1.1	Rypage Tray: Back		
014	[-300 to 0 / 0 / 1 µA]		
015	A3 LCT1 U Tray:Front		
015	[–300 to 0 / 0 - / 1 μA]		
016	A3 LCT1 U Tray:Back		
	[–300 to 0 / 0 / 1 μA]		
017	A3 LCT1 L Tray:Front		
	[–300 to 0 / 0 / 1 μA]		
018	A3 LCT1 L Tray:Back		
0.0	[–300 to 0 / 0 / 1 μA]		
019	A3 LCT2 U Tray:Front		
	[–300 to 0 / 0 / 1 μA]		
020	A3 LCT2 U Tray:Back		
	[–300 to 0 / 0 / 1 μA]		
021	A3 LCT2 L Tray:Front		
	[–300 to 0 / 0 / 1 μA]		
022	A3 LCT2 L Tray:Back [–300 to 0 / 0 / 1 μA]		

On page 1082

	on page 100=	
2426*	LEdge Cor DFU	
006	Uncoated Thick3 Front:Bk:PTR	
	[0 to 300 / 100 : NA , 250 : EU / 1%]	

en page 1000		
2426*	LEdge Cor DFU	

Technical Bulletin

PAGE: 41/93

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG178054
017 Uncoated Thick3 Front FC PTR		

017	Uncoated Thick3 Front:FC:PTR
	[0 to 300 / 100: NA, 250: EU / 1%]

On page 1093

2426*	LEdge Cor DFU
141 <mark>140</mark>	Special3 Plain Back:Bk:PTR
141 140	[0 to 300 / 170 / 1%]

On page 1094

on page 1004	
LEdge Cor DFU	
Special3 Thin Back:FC:PTR	
[0 to 300 / 170 / 1%]	
-	
Special4 Thick1 Front:Bk:PTR	
[0 to 300 / 170 / 1%]	
-	
Special4 Thick3 Front:Bk:PTR	
[0 to 300 / 250 / 1%]	

On page 1095

<u> </u>	
2426*	LEdge Cor DFU
164	Special4 Thick1 Back:Bk:PTR
104	[0 to 300 / 170 / 1%]

On page 1097

2426*	LEdge Cor DFU
191 190	Special5 MidThk Front:FC:PTR
191 190	[0 to 300 / 170 / 1%]

On page 1107

2428*	TEdge Cor DFU
211	Uncoated Thick3 Front:Bk:PTR
	[0 to 250 / NA: 80, EU: 100 / 1%]
212	Uncoated Thick3 Front:FC:PTR
213	[0 to 250 / NA: 80, EU: 100 / 1%]

On page	on page 1110	
2429*	TEdge SWT DFU	
041	ON:Envelope:Bk:PTR	
	[0 to 100 / 20 / 1 mm]	
043	ON:Envelope:FC:PTR	

Technical Bulletin

PAGE: 42/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

On page 1157

2810		Clear blurred img
	002	select clear blurred img mode
		Selects the execution condition for the clear blurred image mode.
		[0 to 2 / 0 / 1]
		0: Always off
		1: On at process control
		2: Always on

After SP2810 on page 1157

These SPs are newly added.

111030 01 3	are newly added.
2812*	Job Divide mode
001	Continuous Printing
	Specifies the threshold pages for the job divide mode.
	The machine will stop operation for 120 seconds (adjustable with
	SP2812-004) after the threshold pages are printed.
	[0 to 9999 / 2000 / 1 page]
002	Operating Environment
	Selects the execution condition for the job divide mode
	[0 to 2 / 0 / 1]
	0: Always off
	1: On in LLL or LL condition
	2: Always on
003	Toner Coverage
	Specifies the threshold coverage for the job divide mode.
	[0 to 100 / 20 / 1 %]
004	Waiting Time
	Specifies the waiting time for the job divide mode.
	[0 to 999 / 120 / 1 sec]
	-

• After SP2901 on page 1158

These SPs are not described in Service Manual for AG-C1.

2902		SBU Test Pattern (D016 only)
	004	Select Test Pattern
		Selects the test pattern of SBU.
		[0 to 4 / 0 / 1]
		0: Normal Scanner output
		1: Fixed Value Output (adjustable with SP2902-005)
		2: Main Scan Grayscale Output
		3: Sub Scan Grayscale Output
		4: Grid Output
	005	Set Output Level

Technical Bulletin

PAGE: 43/93

Model: Aegis-P1/C1

Specifies the output level for the SBU test pattern.
This can be activated only when the setting of SP2902-004 is set to "1".
[0 to 1023 / 512 / 1]

• After SP2904 on page 1158

These SPs are not described in Service Manual for AG-C1.

2905*		Waste Toner Full Sn SSP
	001	Toner Volume
		Specifies the maximum toner amount for the machine operating after the waste tone full sensor has detected the full condition of the waste toner bottle. [0 to 1000 / 0 / 10 g]
	002	N Pgs
		Specifies the maximum number of pages for the machine operating after the waste tone full sensor has detected the full condition of the waste toner bottle. [0 to 1000 / 0 / 10 pages]

• After SP2915 on page 1161

This SP is not described in Service Manual for AG-C1.

2916*		ITB Cleaning Motor Setting
	001	Motor Rotation
		Specifies the rotation times of the ITB cleaning motor.
		[500 to 2000 / 1015.4 / 0.1 rpm]

- On page 1102		
2920*	Belt Centering Roller	
001	Current Position	
	[–100 to 100 / 0 / 1 step]	
002	Roller Position Detection	
002	Execute the ITB centering for each mode.	
	Roller Pos.: No-contact	
003	Displays the position of the belt centering roller when the ITB is away	
003	from the drums.	
	[-100 to 100 / 0 / 1step]	
	Roller Position: Bk	
004	Displays the position of the belt centering roller at the B/W printing	
004	mode.	
	[-100 to 100 / 0 / 1step]	
	Roller Position: Color	
005	Displays the position of the belt centering roller at the color printing	
003	mode.	
	[-100 to 100 / 0 / 1step]	

Technical **B**ulletin

PAGE: 44/93

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG178054
006	Roller Holding Setting Holds or does not hold the position of the ITB moves to the drums or away f [0 or 1 / 0 / 1] 0: Hold (5 seconds)		er when
	1. Does not hold		

On page 1175

3253*	Toner Pump Fill Amt DFU
012	M:Remain Level3
	[0 to 5 / 1.6 / 0.01g/s]

• After SP3306 on **pages from 1178 to 1180** These SPs are newly added.

3308*	Interval mode
-	
001	Execute page
	Specifies the threshold pages for the interval mode.
	This SP can be activated only when the setting of the idling time
	(SP3308-002) is set to a value more than "0".
	[0 to 2000 / 0 / 1 page]
	Use this SP to prevent the vertical white line problem caused by
	multiple printing.
002	Idling time
	Specifies the idling time for the interval mode.
	This SP can be activated only when the setting of the execute page
	(SP3308-001) is set to a value more than "0".
	[0 to 1000 / 0 / 1 sec.]

Technical Bulletin

PAGE: 45/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

On pages from 1180 to 1181

	es from 1180 to 1181
3309*	Oil removal mode DFU
800	Select mode at Process control
	[0 to 2 / 0 / 1]
	0: Always ON
	1: Auto ON by environment
	2: OFF
009	
	[0 or 1 / 1 / 1]
	0: Auto ON by environment
	1: Always ON
010	
	Executes the oil removal mode.
012	Pat. sub-scanning length: B/W
	[0 to 40 / 30 / 1mm]
013	Pat. sub-scanning length: FC
	[0 to 10 / 10 / 1mm]
014	Interrupt ON/OFF
	Turns on or off the interrupting oil removal mode.
	[0 or 1 / <mark>0</mark> / 1]
	0: On, 1: Off
015	Interrupt Thresh
	[0 to 9999 / 1000 / 1 sheet]
016	Job End thresh
	[0 to 9999 / 750 / 1 sheet]
017	
	[0 to 9999 / 0 / 1 sheet]
018	Idling Time 1
	[0 to 250 / 0 / 1 second]
019	Idling Time 2
	[0 to 250 / 25 / 1 second]
020	Repeat Time
	[0 to 10 / 1 / 1]

• After SP3554 on pages from 1192 to 1193

These SPs are newly added.

mees er e are nem jaaueur	
3555*	Before Job Procon
	These SPs are designed to correct the change of the toner density
	between the executions of the normal process control.
001	Short Idle Time ON/ OFF
	Turns on or off the process control for a short idle time.
	The idle time (threshold for the process control) of the machine can be adjusted with SP3555-002.
	[0 or 1 / 0 / 1]
	0: On, 1: Off
002	Idling Time

Technical Bulletin

PAGE: 46/93

Model: A	Aegis-P1/C1	Date: 22-Jun-09	No.: RG17805
Specifies the threshold time of the process control for a short idle time. [0 to 999 / 20 / 1 min]			ort idle
00	Temperature Range ON/ OFF Turns on or off the process control for the temperature change inside the machine. The temperature change (threshold for the process control) of the machine can be adjusted with SP3555-004. [0 or 1 / 0 / 1] 0: On, 1: Off		
Temperature Range Specifies the threshold temperature of the process control for the temperature change inside the machine [0 to 99 / 2 / 1°C]			or the

On page 1209

System SP4-xxx: 1 (D016 only)

SP4-xxx Scanner

On page 1230

O 11 P	age 1200
4904	Test Scan IPU
001	Test 1
	Performs write and read test for the CPU on the IPU by conducting a compare check that reads and writes to each register of the ASIC. [0 to 65535 / 0 / 1]
002	Test 2
	Performs a check of the image paths and connections and displays the location of an error is detected. [0 to 65535 / 0 / 1]

4905	Select Gradation Level	
001	Changes the threshold parameters of error diffusion.	
	[0 to 255 / 0 / 1]	

4954	Read/Restore Std	
001	Read New Chart	Reads the "Standard Color Test Chart" to calibrate the scanner gamma curve.
002	Recall Prev Chart	Restores the scanner gamma to the previous value (not the factory setting).

Technical **B**ulletin

PAGE: 47/93

Model: Aegis-P1/C1			e: 22-Jun-09	No.: RG178054
004	Set Std Chart	Overwrite the standard of gamma.	data of the scanr	ner

4991	IPU Image Pass Selection	
001	Selects the image path of the IPU.	
	[0 to 11 / 2 / 1]	
	0: Scanned RGB image	
	1: RGB image in scanner I/F	
	2: RGB image after shading correction (default)	
	3: RGB image after shading correction	
	4: Test pattern data (grayscale)	
	5: RGB image after line interval correction	
	6: RGB image after digital AE correction	
	7: RGB image after vertical line correction	
	8: RGB image after scanner gamma correction	
	9: RGB image after filtering with MTF	
	10: RGB image after ADS	
	11: RGB image after color processing	

After SP5062 on page 1231
 This SP is not described in Service Manual for AG-C1

5104	A3/DLT Double Count SSP		
	Specifies whether the counter is double clicked for A3/DLT size prints.		
	When you have to change this SP, ask your supervisor.		
001	A3 Double Count	*CTL	[0 to 2 / 0 / 1 /step]
			0: NO (Normal count)
			1: YES (Double count)
			2: YES except By-pass (Normal count
			for unknown size)

On page 1235

- · · · ·	-g- :		
5126*	Set F-size Document (D016 only)		
001	01 Selects the size for F-size document detection.		
	[0 to 2 / 0 / 1]		
	0: Foolscap (8 1/2 x 13)		
	1: Folio (8 1/4 x 13)		
	2: F (8 x 13)		

5127	APS OFF Mode (D016 only)	
	This SP can be used to switch APS (Auto Paper Select) off when a coin	
	lock or pre-paid key card device is connected to the machine.	
	[0 to 1 / 0 / -]	
0: On, 1: Off		

Technical Bulletin

PAGE: 48/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

5131*	Paper Size Type Selection		
001	Selects the paper size type (for originals and copy paper).		
	[0 to 2 / 1: NA, 2: EU / 1]		
	0: Japan, 1: NA, 2: EU		
	After changing the value, turn the main power switch off and on.		

5148	Size Detection OFF		
	Turns on or off the automatic paper size detection.		
004	Tray 3	*CTL	[0 or 1 / 0 / -]
005	Tray 4	*CTL	0: On, 1: Off
006	Tray 5	*CTL	

On page 1237

5182	HDD Pages Mgmt (D016 only)		
	Selects the LS area for the page management on the HDD.		
002	Change Pages/ Doc	*CTL	[0 or 1 / 0 / -]
			0: Standard. 1: Extension

• After SP5187 on page 1237

This SP is not described in Service Manual for AG-C1.

5188	Copy NV Version (D016 only)		
001	*(CTL	Displays the version number of the
			NVRAM on the controller board.

	900.
5193	External Controller Info. Settings (Not used for D016 and G178)
001	- *CTL [0 to 10 / 0 / 1/step]
	Sets the external controller type. This setting is appropriately adjusted if
	an external controller is installed in the machine.
	0: No external controller installed
	1: EFI controller
	2: Ratio controller
	3: Egret controller
	4: GJ
	5: Creo
	6: QX-100
	7 to 10: Reserved

5195	Limitless SW DFU		
001		*CTL	[0 or 1 / 1 / -]
			0: Productivity priority
			1: Tray priority

Technical Bulletin

PAGE: 49/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

Selects the paper feed mode.

Productivity priority:

This changes the feeding tray as soon as the machine detects the priority tray even the paper still remains in the feeding tray.

Tray priority:

This changes the feeding tray after the paper in the tray where the machine has been feeding paper has been run out of.

This SP is activated only when a customer selects the "Auto Paper Select".

After SP5195 on page 1237

These SPs are not described in Service Manual for AG-C1.

5212	Page Numbering (D016 only)			
	This program adjusts the position of the second side page numbers.			
	A "- value" moves the page number positions to the left edge or leading			
	edge (high position). A "+ value" moves the page number positions to the			
	right edge or trailing edge (low position).			
003	Duplex Printout	*CTL	[-10 to 10 / 0 / 1 mm/step]	
	Right/Left Position			
004	Duplex Printout High/Low	*CTL	[-10 to 10 / 0 / 1 mm/step]	
	Position			

On page 1243

This SP is not described in Service Manual for AG-C1.

	The or le het decembed in certice manda in the term		
5507	Supply Alarm	*CTL -	
006	Waste Toner Bottle	0: Off, 1 : On	
	Supply Alarm		

5513	Parts Alarm Level Count	
001	Normal	[1 to 9999 / 300 / 1K]
	Sets the parts replacement alarm counter for the number of paper.	
002	DF	[1 to 9999 / 300 / 1K]
	Sets the parts replacement alarm counter for the number of scanned	
	originals.	

5514	Parts Alarm	
001	Normal	[0 or 1 / 1 / -]
		0: OFF, 1: ON
	Turns on or off the	parts replacement alarm for the number of paper.
002	DF	[0 or 1 / 0 / -]
		0: OFF, 1: ON

Model: Aegis-P1/C1

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 50/93

Turns on or off the parts replacement alarm for the number of scanned originals.

On page 1245

	- 0	
5610	Base Gamma Ctrl Pt:Execute (D016 only)	
004	Get Factory Default	
005	Set Factory Default	
006	Restore Orginal Value	

5611	Toner Color in 2C (D016 only)	
001	B-C	[0 TO 128 / 100 / 1]
002	B-M	[0 TO 128 / 100 / 1]
003	G-C	[0 TO 128 / 100 / 1]
004	G-Y	[0 TO 128 / 100 / 1]
005	R-M	[0 TO 128 / 100 / 1]
006	R-Y	[0 TO 128 / 100 / 1]

5618	Color Mode Display Selection (D016 only)
	This SP switches the color display for the operation panel LCD.
	[0 or 1 / 1 / -]
	0: Domestic Japan
	1: Overseas (Outside Japan)

On page 1253

	3	
5816	[Remote Service]	*CTL -
089	CERT: ID2 Code	Displays ID2 for the @Remote certification. Spaces are displayed as underscores (_). Asteriskes (***) indicate that no @Remote certification exists.
		"000000" indicates "Common certification".

On page 1254

5816	[Remote Service]	*CTL	-
090	CERT: Subject	certification	

on page 1200			
5816	[Remote Service]	*CTL	-
208	Error Code		

Technical Bulletin

PAGE: 51/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

		· · · · · · · · · · · · · · · · · · ·
Displays a number that des either SP5816-204 or SP58		ror code that was issued when executed.
Cause	Code	Meaning
Illegal Modem Parameter	-11001	Chat parameter error
	-11002	Chat execution error
	-11003	Unexpected error
Operation Error, Incorrect Setting	-12002	Inquiry, registration attempted without acquiring device status.
	-12003	Attempted registration without execution of an inquiry and no previous registration.
	-12004	Attempted setting with illegal entries for certification and ID2.
	-12005	@Remote communication is prohibited. The device has an Embedded RC gate-related problem.
	-12006	A confirmation request was made after the confirmation had been already completed.
	-12007	The request number used at registration was different from the one used at confirmation.
	-12008	Update certification failed because mainframe was in use.

■ After SP5832 on **page 1261**These SPs are not described in Service Manual for AG-C1.

5836	Capture Settings (D016 only)	*CTL	
001	Capture Function (0:Off 1:On)	0: Disable, 1: Enable	
	With this function disabled, the settings related to the capture feature		
	cannot be initialized, displayed,	or selected.	
002	Panel Setting	0: Displayed, 1: Not displayed	
	Displays or does not display the	capture function buttons.	
	5836-71 to 5836-76, Copier and Printer Document Reduction		
	The following 6 SP modes set the default reduction for stored		
	documents sent to the document management server via the MLB.		
	Enabled only when optional MLB (Media Link Board) is installed.		
071	Reduction for Copy Color	0: 1to-1, 1: 1/2, 2: 1/3 , 3: 1/4	
072	Reduction for Copy B&W Text	0: 1to-1 , 1: 1/2, 2: 1/3, 3: 1/4, 6: 2/3	
073	Reduction for Copy B&W	0: 1to-1 , 1: 1/2, 2: 1/3, 3: 1/4, 6: 2/3	
	Other		
074	Reduction for Printer Color	0: 1to-1, 1: 1/2, 2: 1/3 , 3: 1/4	
075	Reduction for Printer B&W	0: 1to-1 , 1: 1/2, 2: 1/3, 3: 1/4, 6: 2/3	
076	Reduction for Printer B&W HQ	0: 1to-1 , 1: 1/2, 2: 1/3, 3: 1/4	

Technical Bulletin

PAGE: 52/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09 **Reduction for Printer Color** 1: 1/2, 3: 1/4, **4: 1/6**, 5: 1/8 1200 dpi Reduction for Printer B&W **1: 1/2**, 3: 1/4, 4: 1/6, 5: 1/8 078 1200 dpi 5836-81 to 5836-86, Stored document format The following 6 SP modes set Sets the default format for stored documents sent to the document management server via the MLB. Enabled only when optional MLB (Media Link Board) is installed. Format for Copy Color 0: JFIF/JPEG, 1: TIFF/MMR, 081 2: TIFF/MH, 3: TIFF/MR Format for Copy B&W Text 0: JFIF/JPEG, 1: TIFF/MMR, 082 2: TIFF/MH, 3: TIFF/MR Format for Copy B&W Other 083 0: JFIF/JPEG, 1: TIFF/MMR, 2: TIFF/MH, 3: TIFF/MR 0: JFIF/JPEG, 1: TIFF/MMR, Format for Printer Color 084 2: TIFF/MH, 3: TIFF/MR Format for Printer B&W 0: JFIF/JPEG, 1: TIFF/MMR, 085 2: TIFF/MH, 3: TIFF/MR Format for Printer B&W HQ 0: JFIF/JPEG, 1: TIFF/MMR, 086 2: TIFF/MH, 3: TIFF/MR [5 to 95 / **50** / 1 /step] Default for JPEG 091 Sets the JPEG format default for documents sent to the document management server via the MLB with JPEG selected as the format. Enabled only when optional MLB (Media Link Board) is installed.

After SP5841on pages from 1261 to 1262

These SPs are not described in Service Manual for AG-C1.

5842	GWWS Analysis Mode (D0	16 only:	DFU)
001	Setting 1	*CTL	Default: 0000000 – do not change Netfiles: Jobs to be printed from the document server using a PC and the DeskTopBinder software
002	Setting 2	*CTL	Adjusts the debug program modesetting. Bit7: 5682 mmseg-log setting 0: Date/Hour/Minute/Second 1: Minute/Second/Msec. 0 to 6: Not used

On pages from 1262 to 1263

5845	Delivery Server Setting	*CTL	
	(D016 only)		-
	Provides items for delivery se	erver sett	tings.

Technical Bulletin

PAGE: 53/93

Model: Ae	egis-P1/C1		Date: 22-Jun-09	No.: RG17805	
001	FTP Port No.	[0 to 655	35 / 3670 / 1 /step]		
	Sets the FTP port number us Server.	ed when i	mage files to the Scar	n Router	
002	IP Address (Primary)	Range: 0 255.255.	00.000.000.000 to 255.255		
	Use this SP to set the Scan F				
000	under the transfer tab can be referenced by the initial system setting.				
006	Delivery Error Display Time	_			
	Use this setting to determine displayed when a test error o NetFile application and an ex	ccurs duri	ng document transfer		
800	IP Address (Secondary)	Range: 0 255.255.	00.000.000.000 to 255.255		
	Specifies the IP address assi				
	function as the secondary de	•			
	allows only the setting of the setting.	iP address	s without reference to	the DNS	
009	Delivery Server Model	[0 to 4/ 0	/ 1 /step]		
	Allows changing the model of	•		ov the I/O	
	device.		,	,	
	0: Unknown				
	1: SG1 Provided				
	2: SG1 Package				
	3: SG2 Provided				
	4: SG2 Package				
O10 Delivery Svr Capability [0 to 255 / 0 / 1 /step] Changes the capability of the registered that the I/O dev					
			d that the I/O device r	egistered.	
	Bit7 = 1 Comment information				
	Bit6 = 1 Direct specification o		•		
	Bit5 = 1 Mail RX confirmation setting possible				
	Bit4 = 1 Address book automatic update function exists				
	Bit3 = 1 Fax RX delivery function exists				
	Bit2 = 1 Sender password fur				
	Bit1 = 1 Function to link MK-1			to "O")	
011	Bit0 = 1 Sender specification			(O U)	
011	Delivery Svr Capability (Ext)		/ 0 / 1 /step]		
	Changes the capability of the			_	
	Bit7 = 1 Address book usage	limitation	(Limitation for each a	uthorized	
	user)	ale.			
	Bit6 = 1 RDH authorization lir Bit5 to 0: Not used	IK			
012	Server Scheme (Primary) DF	11			
013	This is used for the scan rout		n		
	This is used for the scall foul	ei piogiai	H.		

021

Technical Bulletin

PAGE: 54/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09 Server Port Number (Primary) [1 to 65535 / **80** / 1 /step] This is used for the scan router program. 015 | Server URL Path (Primary) **DFU** This is used for the scan router program. Server Scheme (Secondary) DFU 016 This is used for the scan router program. Server Port Number (Secondary) [1 to 65535 / **80** / 1 /step] 017 **DFU** This is used for the scan router program. 018 Server URL Path (Secondary) DFU This is used for the scan router program. Capture Server Scheme **DFU** 019 Capture Server Port Number **DFU** 020

Enables or disables the prevention function for the continuous data

On pages from 1263 to 1265

022 | Rapid Sending Control

0: Disable, 1: Enable

sending error.
[0 to 1 / **0** / -]

Capture Server URL Path **DFU**

5846	UCS Settings *CTL	-	
001	Machine ID (For Delivery Server)		Displays ID
	(D016 only)		
	Displays the unique device ID i	•	
	The value is only displayed and		•
	from the NIC MAC or IEEE 139	4 EUI. The	ID is displayed as either 6-
	byle or 8-byte binary.	_	
002	Machine ID Clear (For Delivery	Server)	Clears ID
	(D016 only)		
	Clears the unique ID of the device used as the name in the file transfer		
	directory. Execute this SP if the connection of the device to the delivery		
	server is unstable. After clearing the ID, the ID will be established again		
	automatically by cycling the machine off and on.		
003	Maximum Entries (D016 only) [2000 to 20000/ 2000 /1 /step]		
	Changes the maximum number of entries that UCS can handle.		
	If a value smaller than the present value is set, the UCS managed data		
	is cleared, and the data (exclud	ling user co	de information) is displayed.

Technical Bulletin

PAGE: 55/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09 [0 to 255 / **0** / 1 /step] **Delivery Server Retry Timer** (D016 only) Sets the interval for retry attempts when the delivery server fails to acquire the delivery server address book. **Delivery Server Retry Times** [0 to 255 / **0** / 1 /step] (D016 only) Sets the number of retry attempts when the delivery server fails to acquire the delivery server address book. [2000 to 50000 / 2000 / 1/step] **Delivery Server Maximum Entries** 800 (D016 only) Sets the maximum number account entries of the delivery server user information managed by UCS. **LDAP Search Timeout** [1 to 255 / 60 / 1 /step] 010 Sets the length of the timeout for the search of the LDAP server. 041 Fill Addr Acl Info. This SP must be executed immediately after installation of an HDD unit in a basic machine that previously had no HDD. The first time the machine is powered on with the new HDD installed, the system automatically takes the address book from the NVRAM and writes it onto the new HDD. However, the new address book on the HDD can be accessed only by the system administrator at this stage. Executing this SP by the service technician immediately after power on grants full address book access to all users. Procedure 1. Turn the machine off. 2. Install a new HDD. 3. Turn the machine on. 4. The address book and its initial data are created on the HDD automatically. 5. However, at this point the address book can be accessed by only the system administrator or key operator. 6. Enter the SP mode and do SP5846-041. After this SP executes successfully, any user can access the address book. 043 Addr Book Media Displays the slot number where an address book data is in. [0 to 30 / - /1] 0: Unconfirmed 1: SD Slot 1 2: SD Slot 2 4: USB Flash ROM 20: HDD 30: Nothing Initialize Local Addr Clears the local address book information. 047 Book including the user code. **Initialize Delivery Addr** Clears the distribution address book 048 Book (D016 only) information, except the user code.

Technical Bulletin

PAGE: 56/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

	<u> </u>		
049	Initialize LDAP Addr Book	Clears the LDAP address book information, except the user code.	
050	Initialize All Addr Book	Clears all directory information managed by UCS, including all user codes.	
051	Backup All Addr Book	Uploads all directory information to the SD card.	
052	Restore All Addr Book	Downloads all directory information from the SD card.	
053	Clear Backup Info	Deletes the address book data from the SD card in the service slot. Deletes only the files that were uploaded from this machine. This feature does not work if the card is write-protected. Note After you do this SP, go out of the SP mode, and then turn the power off. Do not remove the SD card until the Power LED stops flashing.	
060	Search Option	p one: otopo nacimig.	
	This SP uses bit switches to set up the fuzzy search options for the UCS local address book. Bit: Meaning 0: Checks both upper/lower case characters 1: Japan Only 2: Japan Only 3: Japan Only 4 to 7: Not Used		
062	Complexity Option 1		
	Use this SP to set the conditions for password entry to access the local address book. Specifically, this SP limits the password entry to upper case and sets the length of the password. [0 to 32 / 0 / 1 /step] Note This SP does not normally require adjustment. This SP is enabled only after the system administrator has set up a group password policy to control access to the address book.		
063	Complexity Option 2 DFU		
064	Complexity Option 3 DFU		
065	Complexity Option 4 DFU		
091	FTP Auth Port Setting (D016 only)	Specifies the FTP port for getting a distribution server address book that is used in the identification mode. [0 to 65535 / 3671 / 1 /step]	
094	Encryption Stat	Shows the status of the encryption function for the address book data.	



Technical Bulletin

PAGE: 57/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09

After SP5846on pages from 1263 to 1265
 These SPs are not described in Service Manual for AG-C1.

	Des Described in Service Ma		A0-01.
5847	Rep Resolution Reduction	*CTL	-
	(D016 only)		
	SP5847-1 through SP5847-3 changes the default settings of image		
	data transferred externally by the	ne Net F	ile page reference function.
	[0 to 5 / 2 / 1 /step]		
	SP5847-21 sets the default for	JPEG in	nage quality of image files
	handled by NetFile.		
	"Net files" are jobs to be printed	I from th	e document server using a PC
	and the DeskTopBinder softwar	e.	_
001	Rate for Copy Color		0: 1x, 1: 1/2x, 2: 1/3x , 3: 1/4x,
			4: 1/6x, 5: 1/8x
002	Rate for Copy B&W Text		0: 1x, 1: 1/2x, 2: 1/3x , 3: 1/4x,
			4: 1/6x, 5: 1/8x
003	Rate for Copy B&W Other		0: 1x, 1: 1/2x, 2: 1/3x , 3: 1/4x,
			4: 1/6x, 5: 1/8x
004	Rate for Printer Color		0: 1x, 1: 1/2x, 2: 1/3x , 3: 1/4x,
			4: 1/6x, 5: 1/8x
005	Rate for Printer B&W		0: 1x , 1: 1/2x, 2: 1/3x, 3: 1/4x,
			4: 1/6x, 5: 1/8x
006	Rate for Printer Color 1200 dpi		0: 1x, 1: 1/2x, 2: 1/3x, 3: 1/4x,
	·		4: 1/6x , 5: 1/8x
007	Rate for Printer B&W 1200 dpi		0: 1x, 1: 1/2x , 2: 1/3x, 3: 1/4x,
	·		4: 1/6x, 5: 1/8x
021	Network Quality Default for JPE	EG	
	Sets the default value for the qu	uality of	JPEG images sent as NetFile
			ith the MLB (Media Link Board)
	option installed.	•	· ·
	[5 to 95 / 50 / 1 /step]		
	1 2		

5848	Web Service (D016 only)	*CTL	-		
	SP5848-2 sets the 4-bit switch assignment for the access control setting. Setting of 0001 has no effect on access and delivery from Router.				
	SP 5848-100 sets the max The default is equal to 1 gi	the maximum size allowed for downloaded images. all to 1 gigabyte.			
002	Access Ctrl: Repository (only Lower 4 bits)	0001:	No access control Denies access to DeskTop Binder. No writing control		
003	Access Ctrl: Doc. Svr. Print (Lower 4 bits)	Switch	es access control on and off.		

Technical Bulletin

PAGE: 58/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

	_	
004	Access Ctrl: udirectory (only Lower 4 bits)	0000 : No access control 0001: Denies access to DeskTop Binder.
009	Access Ctrl: Job Ctrl (Lower 4 bits)	
011	Access Ctrl: Device management (Lower 4 bits)	
021	Access Ctrl: Delivery (Lower 4 bits)	
022	Access Ctrl: uadministration (Lower 4bits)	
099	Repository: Download Image Setting	DFU
100	Repository: Download Image Max. Size	Specifies the max size of the image data that the machine can download. [1 to 1024 / 1024 / 1 MB /step]

On pages from 1269 to 1270

5873	SD Card Appli Move	
001	Move Exec	This SP copies the application programs from the original SD card in SD card slot 2 to an SD card in SD card slot 1.
002	Undo Exec	This SP copies back the application programs from an SD card in SD Card Slot 1 to the original SD card in SD card slot 2. Use this menu when you have mistakenly copied some programs by using "Move Exec" (SP5873-1).

On page 1271

○ F	, a.g. · _ · ·
5887	SD Get Counter
	This SP sends a text file to an SD card inserted in SD card Slot 2 (upper slot). The operation stores. The file is stored in a folder created in the root directory of the SD card called SD_COUNTER. The file is saved as a text file (*.txt) prefixed with the number of the machine.
	 4. Insert the SD card in SD card Slot 2 (upper slot). 5. Select SP5887 then touch [EXECUTE]. 6. Touch [Execute] in the message when you are prompted.

After SP5907on page 1271

This SP is not described in Service Manual for AG-C1.

5913

Technical Bulletin

PAGE: 59/93

Model: Aegis-P1/C1

Date: 22-Jun-09

No.: RG178054

Print Application Timer

*CTL [3 to 30 / 3 / 1 second /step]

Sets the amount of time to elapse while the machine is in standby mode (and the operation panel keys have not been used) before another application can gain control of the display.

• After SP5919 on page 1271

This SP is not described in Service Manual for AG-C1.

5967	Copy Server Set Function	*CTL	0 : ON, 1: OFF
	(D016 only)		
001	Enables and disables the document server. This is a security measure		
	that prevents image data from being left in the temporary area of the		
	HDD. After changing this setting, you must switch the main switch off and		
	on to enable the new setting.		

	.			
6006*	DF Registration Adjustment (D016 only)			
001	Side-to-Side Regist:Front	Adjusts the side-to-side registration of		
002	Side-to-Side Regist:Rear	originals with the ADF.		
	_	[-3 to 3 / 0 / 0.1 mm]		
003	LeadingEdge(ThinOriginal)	Adjusts the amount of paper buckle to		
		correct original skew.		
		[-10 to 10 / 0 / 0.1 step]		
005	LeadingEdge(Duplex-1st)	Adjusts the amount of paper buckle to		
006	LeadingEdge(Duplex-2nd)	correct original skew for the front and rear		
		sides.		
		[-29 to 29 / 0 / 0.1 step]		

6007	ADF Input Check (D016 only)
	(ADF Input Check: SP6007)

6008	ADF Output Check (D016 only)
	(ADF Output Check: SP6008)

6009	DFFreeRun (D016 only)	
002	[0 or 1 / 0 / -]	This SP does an ADF free run in duplex
		original mode.

6015*	ADF Scale Seting (D016 only)
001	Selects the ADF scale setting.
	[0 or 1 / <mark>0</mark> / -]
	0: 7 mm buckle for all original sizes
	1: 5 mm buckle for A5 SEF or lees, 7 mm buckle for B5 SEF or more

6019* ADF Motor Speed Auto Adjustment (D016 only)	
---	--

Technical Bulletin

PAGE: 60/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

001 Turns on or off the automatic speed adjustment of the ADF motor.

Turns on or off the automatic speed adjustment of the ADF motor.

[0 or 1 / **0** / -]

0: On, 1: Off

• After SP6770 on page 1286

This SP is not described in Service Manual for AG-C1.

6800	Sheet Conversion (Thick Paper) DFU
001	Permits punching, including tab sheets.
	[1 to 3 / 3 /1 sheet]
	1: 1 Sheet
	2: 2 Sheets
	3: 3 Sheets

6890	Punch Function Enabled (Z-Fold)
001	Permission for punching thick (tab) paper is forbidden and it is up to the
	service technician to pass this on to the customer.
	[0 or 1/ 0 / -]
	0: Simultaneous use forbidden
	1: Simultaneous use allowed

Technical Bulletin

PAGE: 61/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09

After SP7502 on page 1288
 This SP is not described in Service Manual for AG-C1.

7503	[Total Original Jam Counter] (D016 only)		
	Displays the total number of original jams detected.		
001	Total Jam	* CTL	[0 to 9999 / 0 / 1 sheet/step]

On page 1288

<u> </u>			
7504	[Paper Jam Location]		
	Displays the number of jams according to the location where jams		าร
	were detected.	_	
006	Paper feed sensor upper (A4 LCT): Late (G178 only)	*CTL	
007	Paper feed sensor middle (A4 LCT): Late (G178 only)	*CTL	
800	Paper feed sensor lower (A4 LCT): Late (G178 only)	*CTL	
017	4th transport sensor (A4 LCT): Late (G178 only)	*CTL	
018	5th transport sensor (A4 LCT): Late (G178 only)	*CTL	
019	6th transport sensor (A4 LCT): Late (G178 only)	*CTL	

On page 1289

7504	[Paper Jam Location]	
	Displays the number of jams according to the location	where jams
	were detected.	
025	Relay sensor (A4 LCT): Late (G178 only)	*CTL
026	LCT vertical transport sensor 3 (A3 LCT1): Late	*CTL
027	LCT vertical transport sensor 1 (A3 LCT1): Late	*CTL
028	LCT vertical transport sensor 2 (A3 LCT1): Late	*CTL
029	LCT vertical transport sensor 1 (A3 LCT2): Late	*CTL
030	LCT vertical transport sensor 2 (A3 LCT2): Late	*CTL
031	LCT exit sensor (A4 LCT): Late (G178 only)	*CTL
056	Paper feed sensor upper (A4 LCT): Stay on	*CTL
	(G178 only)	
057	Paper feed sensor middle (A4 LCT): Stay on	*CTL
	(G178 only)	
058	Paper feed sensor lower (A4 LCT): Stay on	*CTL
	(G178 only)	

7504	[Paper Jam Location]	
	Displays the number of jams according to the location was were detected.	here jams
067	4th transport sensor (A4 LCT): Stay on (G178 only)	*CTL
068	5th transport sensor (A4 LCT): Stay on (G178 only)	*CTL
069	6th transport sensor (A4 LCT): Stay on (G178 only)	*CTL
075	Relay sensor (A4 LCT): Stay on (G178 only)	*CTL

Technical Bulletin

PAGE: 62/93

 Model: Aegis-P1/C1
 Date: 22-Jun-09
 No.: RG178054

 081 LCT exit sensor (A4 LCT): Stay on (G178 only)
 *CTL

On page 1297

<u> </u>	y		
7508	[Original Jam History] (D01	6 only)	
	Displays the 10 most recer	ntly dete	cted paper jams.
001	Latest	*CTL	-
002	Latest 1		
003	Latest 2		
004	Latest 3		
005	Latest 4		
006	Latest 5		
007	Latest 6		
800	Latest 7		
009	Latest 8		
010	Latest 9		

On pages from 1298 to 1301

7509	[Paper Jam Loc]		
	Displays the number of jar	ns accor	ding to the location where jams were
	detected.		
001	Stacker1: Br-Path E	*CTL	Stacker 1 (D364)
002	Stacker1: Br-Path E	*CTL	
003	Stacker1: Off-set U	*CTL	
004	Stacker1: Side Jogg	*CTL	
005	Stacker1: L-Edge Jo	*CTL	
006	Stacker1: Stack Tra	*CTL	
007	Stacker1: Job Data	*CTL	
015	Stacker2: Entrance	*CTL	Stacker 2 (D364)
016	Stacker2: Ex-Tray: P	*CTL	
017	Stacker2: Ex-Tray: P	*CTL	
018	Stacker2: S-Tray: P	*CTL	
019	Stacker2: S-Tray: P	*CTL	
020	Stacker2: Bridge Pa	*CTL	
021	Stacker2: Br-Path E	*CTL	
022	Stacker2: Br-Path E	*CTL	
023	Stacker2: Off-set U	*CTL	
024	Stacker2: Side Jogg	*CTL	
025	Stacker2: L-Edge Jo	*CTL	
026	Stacker2: Stack Tra	*CTL	
027	Stacker2: Job Data	*CTL	
045	P-Binder: Job Data	*CTL	For future use
046	U	*CTL	
047	P-Binder: S-Through	*CTL	
048	P-Binder: Cover Reg	*CTL	

Technical Bulletin

PAGE: 63/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054 049 P-Binder: Cover Reg *CTL 050 | P-Binder: Cover H-R *CTL 051 | P-Binder: Cover H-R *CTL 052 P-Binder: Cover H-R *CTL 053 P-Binder: Cover H-R *CTL 054 P-Binder: Entrance *CTL 055 P-Binder: Entrance *CTL 056 | P-Binder: Sign. Pat *CTL 057 P-Binder: Sign. Pat *CTL 058 P-Binder: Sign. Pat *CTL *CTL 059 P-Binder: Sign. Pat 060 | P-Binder: Timing Sn *CTL For future use 061 P-Binder: Timing Sn *CTL 062 P-Binder: Stack Tray *CTL 063 P-Binder: Stack Tray *CTL 064 | P-Binder: SG Paper *CTL 065 P-Binder: Cover Pat *CTL 066 P-Binder: Cover Pat *CTL 067 | P-Binder: Cover Pat *CTL 068 P-Binder: Cover Pat *CTL *CTL 069 P-Binder: Cover Reg 070 | P-Binder: Cover Reg *CTL 071 P-B/Inserter: Com. *CTL For future use 072 P-B/Inserter: Com. *CTL 073 P-B/Inserter: U-Tra *CTL 074 P-B/Inserter: U-Tra *CTL 075 P-B/Inserter: L-Tra *CTL 076 P-B/Inserter: L-Tra *CTL *CTL 077 | P-B/Inserter: Trans 078 P-B/Inserter: Trans *CTL 079 | P-B/Inserter: Trans *CTL 080 | P-B/Inserter: Trans *CTL 081 P-B/Relay: Transport *CTL 082 P-B/Relay: Transport *CTL 095 R-Binder: Entrance *CTL Ring Binder (D392) 096 R-Binder: Entrance *CTL 097 R-Binder: Transport *CTL 098 | R-Binder: Transport *CTL 099 R-Binder: Exit Sn: L *CTL 100 R-Binder: Exit Sn: S *CTL 101 R-Binder: Pre-punch *CTL 102 | R-Binder: After-pun *CTL *CTL 103 R-Binder: P TE Data 104 R-Binder: P LE Data *CTL 105 | R-Binder: Ring Erro *CTL 106 R-Binder: Binder Un *CTL

Technical Bulletin

letin PAGE: 64/93

107 R-Binder: Output Be	Model: A	egis-P1/C1		Date: 22-Jun-09	No.: RG1780
109 R-Binder: Stacker J *CTL 110 R-Binder: Punch Mot *CTL 111 R-Binder: Shutter M *CTL 112 R-Binder: Line-up P *CTL 113 R-Binder: Line-up P *CTL 114 R-Binder: Line-up P *CTL 115 R-Binder: Clamp Mot *CTL 116 R-Binder: Clamp Mot *CTL 117 R-Binder: Out-Belt *CTL 118 R-Binder: Job Data *CTL 119 R-Binder: Job Data *CTL 111 R-Binder: Job Data *CTL 112 Buffer Pass Unit: Relay Sensor 1: Late *CTL 126 Buffer Pass Unit: Relay *CTL 127 Buffer Pass Unit: Relay *CTL 128 Buffer Pass Unit: Relay *CTL 129 Buffer Pass Unit: Relay *CTL 120 Sensor 3: Late *CTL 130 Buffer Pass Unit: Relay *CTL 131 Buffer Pass Unit: Relay *CTL 132 Buffer Pass Unit: Relay *CTL 133 Buffer Pass Unit: Relay *CTL 134 Buffer Pass Unit: Relay *CTL 135 Sensor 4: Late *CTL 136 Buffer Pass Unit: Relay *CTL 137 Sensor 6: Late *CTL 138 Buffer Pass Unit: Relay *CTL 139 Buffer Pass Unit: Relay *CTL 130 Buffer Pass Unit: Relay *CTL 131 Sensor 6: Stay on *CTL 132 Buffer Pass Unit: Relay *CTL 133 Buffer Pass Unit: Relay *CTL 134 Buffer Pass Unit: Relay *CTL 135 Sensor 6: Stay on *CTL 136 Buffer Pass Unit: Relay *CTL 137 Sensor 7: Stay on *CTL 138 Buffer Pass Unit: Relay *CTL 139 Buffer Pass Unit: Relay *CTL 130 Buffer Pass Unit: Relay *CTL 131 Sensor 7: Stay on *CTL 132 Sensor 8: Stay on *CTL 134 Buffer Pass Unit: Relay *CTL 135 Sensor 8: Stay on *CTL 136 Suffer Pass Unit: Relay *CTL 137 Sensor 8: Stay on *CTL 138 Suffer Pass Unit: Relay *CTL 139 Sensor 8: Stay on *CTL 140 Buffer Pass Unit: Job *CTL 141 Buffer Pass Unit: Job *CTL 142 Buffer Pass Unit: Job *CTL 144 Buffer Pass Unit: Job *CTL 145 Sensor 8: Stay on *CTL 146 Suffer Pass Unit: Job *CTL	107	R-Binder: Output Be	*CTL	Ring Binder (D392)	
110 R-Binder: Punch Mot	108	R-Binder: Output Be	*CTL]	
111 R-Binder: Shutter M	109	R-Binder: Stacker J	*CTL		
112 R-Binder: Line-up P *CTL 113 R-Binder: Paper Jog *CTL 114 R-Binder: Line-up P *CTL 115 R-Binder: Clamp Mot *CTL 116 R-Binder: S0/100 ad *CTL 117 R-Binder: S0/100 ad *CTL 118 R-Binder: Job Data *CTL 118 R-Binder: Job Data *CTL 128 Buffer Pass Unit: Relay Sensor 1: Late 129 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay *CTL Sensor 3: Late *CTL 129 Buffer Pass Unit: Relay *CTL Sensor 3: Late *CTL 130 Buffer Pass Unit: Relay *CTL Sensor 3: Stay on 131 Buffer Pass Unit: Relay *CTL Sensor 4: Late *CTL 132 Buffer Pass Unit: Relay *CTL Sensor 4: Stay on 133 Buffer Pass Unit: Relay *CTL Sensor 5: Stay on 134 Buffer Pass Unit: Relay *CTL Sensor 6: Late *CTL 136 Buffer Pass Unit: Relay *CTL Sensor 6: Stay on 137 Buffer Pass Unit: Relay *CTL Sensor 7: Stay on 138 Buffer Pass Unit: Relay *CTL Sensor 7: Stay on 139 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job *CTL Data Error	110	R-Binder: Punch Mot	*CTL		
113 R-Binder: Paper Jog *CTL 114 R-Binder: Line-up P *CTL 115 R-Binder: Clamp Mot *CTL 116 R-Binder: G0/100 ad *CTL 117 R-Binder: Out-Belt *CTL 118 R-Binder: Out-Belt *CTL 119 Buffer Pass Unit: Relay *CTL 120 Buffer Pass Unit: Relay *CTL 121 Buffer Pass Unit: Relay *CTL 122 Buffer Pass Unit: Relay *CTL 123 Buffer Pass Unit: Relay *CTL 124 Buffer Pass Unit: Relay *CTL 125 Buffer Pass Unit: Relay *CTL 126 Buffer Pass Unit: Relay *CTL 127 Buffer Pass Unit: Relay *CTL 128 Buffer Pass Unit: Relay *CTL 129 Buffer Pass Unit: Relay *CTL 130 Buffer Pass Unit: Relay *CTL 131 Buffer Pass Unit: Relay *CTL 132 Buffer Pass Unit: Relay *CTL 133 Buffer Pass Unit: Relay *CTL 134 Buffer Pass Unit: Relay *CTL 135 Buffer Pass Unit: Relay *CTL 136 Buffer Pass Unit: Relay *CTL 137 Buffer Pass Unit: Relay *CTL 138 Buffer Pass Unit: Relay *CTL 139 Buffer Pass Unit: Relay *CTL 140 Buffer Pass Unit: Relay *CTL 141 Buffer Pass Unit: Relay *CTL 142 Buffer Pass Unit: Relay *CTL 143 Buffer Pass Unit: Relay *CTL 144 Buffer Pass Unit: Relay *CTL 145 Buffer Pass Unit: Relay *CTL 146 Buffer Pass Unit: Relay *CTL 147 Buffer Pass Unit: Relay *CTL 148 Buffer Pass Unit: Relay *CTL 149 Buffer Pass Unit: Relay *CTL 140 Buffer Pass Unit: Relay *CTL 141 Buffer Pass Unit: Job *CTL 142 Buffer Pass Unit: Job *CTL 144 Buffer Pass Unit: Job *CTL 145 Buffer Pass Unit: Job *CTL 146 Buffer Pass Unit: Job *CTL 147 Buffer Pass Unit: Job *CTL 148 Buffer Pass Unit: Job *CTL 149 Buffer Pass Unit: Job *CTL 140 Buffer Pass Unit: Job *CTL 141 Buffer Pass Unit: Job *CTL 142 Buffer Pass Unit: Job *CTL 144 Buffer Pass Unit: Job *CTL 145 Buffer Pass Unit: Job *CTL 146	111	R-Binder: Shutter M	*CTL		
114 R-Binder: Line-up P *CTL 115 R-Binder: Clamp Mot *CTL 116 R-Binder: Out-Belt *CTL 117 R-Binder: Out-Belt *CTL 118 R-Binder: Job Data *CTL 119 R-Binder: Job Data *CTL 119 Buffer Pass Unit: Relay *CTL 25 Buffer Pass Unit: Relay *CTL 26 Buffer Pass Unit: Relay *CTL 27 Buffer Pass Unit: Relay *CTL 28 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 29 Buffer Pass Unit: Relay *CTL 20 Buffer Pass Unit: Belay *CTL 20 Buffer Pass Unit	112	R-Binder: Line-up P	*CTL		
115 R-Binder: Clamp Mot *CTL 116 R-Binder: 50/100 ad *CTL 117 R-Binder: Out-Belt *CTL 118 R-Binder: Job Data *CTL 118 R-Binder: Job Data *CTL 125 Buffer Pass Unit: Relay Sensor 1: Late 126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Late 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Late 130 Buffer Pass Unit: Relay Sensor 7: Stay on 131 Buffer Pass Unit: Relay Sensor 7: Stay on 132 Buffer Pass Unit: Relay Sensor 7: Stay on 133 Buffer Pass Unit: Relay Sensor 7: Stay on 134 Buffer Pass Unit: Relay Sensor 7: Stay on 135 Buffer Pass Unit: Relay Sensor 7: Stay on 136 Buffer Pass Unit: Relay Sensor 8: Stay on 137 Buffer Pass Unit: Relay Sensor 8: Stay on 138 Buffer Pass Unit: Relay Sensor 8: Stay on 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	113	R-Binder: Paper Jog	*CTL		
116 R-Binder: 50/100 ad *CTL 117 R-Binder: Out-Belt *CTL 118 R-Binder: Job Data *CTL 125 Buffer Pass Unit: Relay Sensor 1: Late 126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay *CTL Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Stay on 130 Buffer Pass Unit: Relay Sensor 8: Stay on 131 Buffer Pass Unit: Relay Sensor 8: Stay on 132 Buffer Pass Unit: Relay Sensor 8: Stay on 134 Buffer Pass Unit: Relay Sensor 8: Stay on 135 Buffer Pass Unit: Relay Sensor 8: Stay on 136 Buffer Pass Unit: Relay Sensor 8: Stay on 137 Buffer Pass Unit: Relay Sensor 8: Stay on 138 Buffer Pass Unit: Relay Sensor 8: Stay on 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	114	R-Binder: Line-up P			
117 R-Binder: Out-Belt *CTL 118 R-Binder: Job Data *CTL 125 Buffer Pass Unit: Relay Sensor 1: Late 126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Late 129 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Late 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 6: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Late 130 Buffer Pass Unit: Relay Sensor 7: Stay on 131 Buffer Pass Unit: Relay Sensor 7: Stay on 132 Buffer Pass Unit: Relay Sensor 7: Stay on 133 Buffer Pass Unit: Relay Sensor 7: Stay on 134 Buffer Pass Unit: Relay Sensor 7: Stay on 135 Buffer Pass Unit: Relay Sensor 8: Stay on 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	115	R-Binder: Clamp Mot	*CTL		
118 R-Binder: Job Data	116	R-Binder: 50/100 ad	*CTL		
Buffer Pass Unit: Relay Sensor 1: Late 126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Late 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Late 131 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 6: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 6: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Late 130 Buffer Pass Unit: Relay Sensor 7: Stay on 131 Buffer Pass Unit: Relay Sensor 7: Stay on 132 Buffer Pass Unit: Relay Sensor 7: Stay on 133 Buffer Pass Unit: Relay Sensor 7: Stay on 134 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	117	R-Binder: Out-Belt	*CTL		
Sensor 1: Late 126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	118	R-Binder: Job Data	*CTL		
126 Buffer Pass Unit: Relay Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 6: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 6: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Stay on 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL *CT	125	Buffer Pass Unit: Relay	*CTL	Buffer Pass Unit (M379)	
Sensor 1: Stay on 127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Late 133 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 5: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Late 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Late 130 Buffer Pass Unit: Relay Sensor 7: Stay on 131 Buffer Pass Unit: Relay Sensor 7: Stay on 132 Buffer Pass Unit: Relay Sensor 7: Stay on 133 Buffer Pass Unit: Relay Sensor 7: Stay on 134 Buffer Pass Unit: Relay Sensor 7: Stay on 135 Buffer Pass Unit: Relay Sensor 7: Stay on 136 Buffer Pass Unit: Relay Sensor 8: Late 147 Buffer Pass Unit: Relay Sensor 8: Stay on 148 Buffer Pass Unit: Relay Sensor 8: Stay on 149 Buffer Pass Unit: Job Data Error					
127 Buffer Pass Unit: Relay Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Late 133 Buffer Pass Unit: Relay Sensor 4: Stay on 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 5: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	126	Buffer Pass Unit: Relay	*CTL		
Sensor 2: Late 128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 4: Stay on 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 5: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Late 137 Buffer Pass Unit: Relay Sensor 6: Late 138 Buffer Pass Unit: Relay Sensor 6: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error					
128 Buffer Pass Unit: Relay Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 4: Stay on 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 5: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Late 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	127	_	*CTL		
Sensor 2: Stay on 129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 4: Stay on 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 5: Stay on 136 Buffer Pass Unit: Relay Sensor 6: Late 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error					
129 Buffer Pass Unit: Relay Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Late 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error	128	•	*CTL		
Sensor 3: Late 130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Late 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 130 Buffer Pass Unit: Relay Sensor 7: Stay on 131 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL *C					
130 Buffer Pass Unit: Relay Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Late 141 Buffer Pass Unit: Job Data Error *CTL 129	_	*CTL			
Sensor 3: Stay on 131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error				_	
131 Buffer Pass Unit: Relay Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	130		*CTL		
Sensor 4: Late 132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL Data Error *CTL	404		*071	4	
132 Buffer Pass Unit: Relay Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 6: Stay on 138 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	131		*CIL		
Sensor 4: Stay on 133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	400		*OTI	-	
133 Buffer Pass Unit: Relay Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL Buffer Pass Unit: M379) *CTL Buffer Pass Unit (M379) *CTL Sensor 6: Stay on *CTL Sensor 7: Stay on *CTL Sensor 8: Stay on *CTL	132	_	CIL		
Sensor 5: Late 134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	400		*CTI	Duffer Deep Unit (M270)	
134 Buffer Pass Unit: Relay Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	133		CIL	Bullet Pass Unit (M379)	
Sensor 5: Stay on 135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL Sensor 8: CTL Sensor 8: Stay on *CTL Sensor 8: Stay on *CTL Data Error	13/	Ruffer Pass Unit: Pelay	*CTI	4	
135 Buffer Pass Unit: Relay Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	104		CIL		
Sensor 6: Late 136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay *CTL Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job TCTL Sensor 8: Stay on 141 Buffer Pass Unit: Job TCTL Sensor 8: Stay on 141 Buffer Pass Unit: Job TCTL Sensor 8: Stay on	135		*CTI	1	
136 Buffer Pass Unit: Relay Sensor 6: Stay on 137 Buffer Pass Unit: Relay *CTL Sensor 7: Late 138 Buffer Pass Unit: Relay *CTL Sensor 7: Stay on 139 Buffer Pass Unit: Relay *CTL Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Total Error *CTL Sensor 8: Stay on *CTL Sensor 8: Stay on *CTL Sensor 8: Stay on	100	,	OIL		
Sensor 6: Stay on 137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL	136		*CTI	1	
137 Buffer Pass Unit: Relay Sensor 7: Late 138 Buffer Pass Unit: Relay *CTL Sensor 7: Stay on 139 Buffer Pass Unit: Relay *CTL Sensor 8: Late 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job Total Pass Unit: Job Data Error	100	-	012		
Sensor 7: Late 138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay Sensor 8: Stay on 141 Buffer Pass Unit: Job Total Sensor 8: Stay on 141 Buffer Pass Unit: Job Total Sensor 8: Stay on 142 Buffer Pass Unit: Job Total Sensor 8: Stay on 143 Buffer Pass Unit: Job Total Sensor 8: Stay on 144 Buffer Pass Unit: Job Total Sensor 8: Stay on 145 Buffer Pass Unit: Job Total Sensor 8: Stay on 146 Buffer Pass Unit: Job Total Sensor 8: Stay on	137		*CTL		
138 Buffer Pass Unit: Relay Sensor 7: Stay on 139 Buffer Pass Unit: Relay *CTL Sensor 8: Late 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job Total Sensor 8: CTL Data Error					
Sensor 7: Stay on 139 Buffer Pass Unit: Relay *CTL Sensor 8: Late 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL Data Error	138		*CTL	1	
139 Buffer Pass Unit: Relay Sensor 8: Late 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job *CTL Data Error					
Sensor 8: Late 140 Buffer Pass Unit: Relay *CTL Sensor 8: Stay on 141 Buffer Pass Unit: Job Data Error *CTL Data Error	139		*CTL	1	
Sensor 8: Stay on 141 Buffer Pass Unit: Job *CTL Data Error					
Sensor 8: Stay on 141 Buffer Pass Unit: Job *CTL Data Error	140	Buffer Pass Unit: Relay	*CTL	1	
141 Buffer Pass Unit: Job *CTL Data Error					
	141		*CTL]	
145 A3 LCT1: Exit Sn:La *CTL LCT-MF or LCT (D355)		Data Error			
TIG THE EST I. EXILORIZE SIL EST IVII OF EST (DOSS)	145	A3 LCT1: Exit Sn:La	*CTL	LCT-MF or LCT (D355)	

Technical Bulletin

PAGE: 65/93

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG178054		
146	A3 LCT1: Entrance S	*CTL			
147	A3 LCT1: Right Ver.	*CTL			
148	A3 LCT1: H-Trans. E	*CTL			
148	A3 LCT1: H-Trans. E	*CTL			
150	A3 LCT1: V-Trans. E	*CTL			
151	A3 LCT1: Exit Sn: La	*CTL	LCT	Γ-MF or LCT (D355)	
196	A3 LCT1: Entrance S	*CTL			
197	A3 LCT1: Right Ver.	*CTL			
198	A3 LCT1: H-Trans. E	*CTL			
199	A3 LCT1: H-Trans. E	*CTL			
200	A3 LCT1: V-Trans. E	*CTL			
201	A3 LCT2: Exit Sn:	*CTL	LC1	Γ (D355)	

On page 1301

7617	7617 PM Parts Counter	
	Displays the each counter for PM parts.	
001	Normal (Paper Feed Counter)	
002	Df (Original Feed Counter)	

7618	PM Parts Counter Reset	
	Clears the each counter for PM parts alarm.	
001	Normal (Paper Feed Counter)	
002	Df (Original Feed Counter)	

After SP7621-156 on page 1305
 These SPs are not described in Service Manual for AG-C1.

7621	PM Counter
	Displays the total counter for each PM parts.
157	Pickup:A4LCT Upper (G178 only)
158	Feed:A4LCT Upper (G178 only)
159	Separate:A4LCT Upper (G178 only)
160	Pickup:A4LCT Middle (G178 only)
161	Feed:A4LCT Middle (G178 only)
162	Separate:A4LCT Middle (G178 only)
163	Pickup:A4LCT Lower (G178 only)
164	Feed:A4LCT Lower (G178 only)
165	Separate:A4LCT Lower (G178 only)

	V	
7621	PM Counter	
	Displays the total counter for each PM parts.	
178	ADF Transport Belt (D016 only)	
179	ADF Reverse Roller (D016 only)	

Technical Bulletin

PAGE: 66/93

On page 1306

7621		PM Counter
		Displays the total counter for each PM parts.
	180	ADF Feed Belt # (D016 only)
	181	ADF Separation (D016 only)
	185	Contact Glass (Exposure Glass) (D016 only)
	212	Torque Limiter : Perfect Binder : Lower-Tray

On pages from 1307 to 1308

 On pag 	jes from 1307 to 1308
7801	ROM No./Firmware Version
	Displays the serial number and the ROM version for each unit or
	peripheral.
002	Engine
005	ADF (D016 only)
007	FNS1 (3000-sheet Finisher: B830)
	FNS2 (Booklet Finisher: B836)
010	LCT1 (A4 LCT B832 or 1st A3 LCT: D355)
	Cover Interposer (B835)
025	Folding Unit (Z-Folding Unit ZF4000: B660)
	LCT 2: Board Serial No. (2nd A3 LCT: D355)
	Ring Binder: Board1 Serial No. (D392)
030	Ring Binder:Board2 Serial No (D392)
031	Perfect Binder: Board1 Serial No. (D391) for future use
032	Perfect Binder: Board2 Serial No. (D391) for future use
033	Perfect Binder: Board3 Serial No. (D391) for future use
	Perfect Binder: Board4 Serial No. (D391) for future use
035	Perfect Binder: Board5 Serial No. (D391) for future use
036	Stacker 1: Board Serial No. (D364)
037	Stacker 2: Board Serial No. (D364)
038	Engine2
	Buffer Pass Unit (M379)
102	Engine
107	FNS1
108	FNS2
110	LCT1
120	Cover Interposer
	Folding Unit
128	LCT 2:Version No.
129	Ring Binder:Board1 Version No.
130	Ring Binder:Board2 Version No.
131	Perfect Binder:Board1 Version No. for future use
132	Perfect Binder:Board2 Version No. for future use
· ·	

Technical Bulletin

PAGE: 67/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09

133	Perfect Binder:Board3 Version No. for future use
134	Perfect Binder:Board4 Version No. for future use
135	Perfect Binder:Board5 Version No. for future use
136	Stacker 1:Version No.
137	Stacker 2:Version No.
138	Engine2
139	Buffer Pass Unit (M379)
255	Rom Version

After SP7801 on pages from 1307 to 1308

These SPs are not described in Service Manual for AG-C1.

7803	PM Counter Display		
001	-	CTL*	Displays the PM count since the
			last PM.

7804	PM Counter Reset		
001	-	CTL*	Clears the PM count.

• After SP7832 on page1309

These SPs are not described in Service Manual for AG-C1.

7835	ACC Counter (D016 only)		
001	Copy ACC	*CTL	Displays the ACC execution
			times for each mode.

On pay	ye i o i t
7940*	Drive Distance:End Std Value
	Displays the standard value (motor rotation count) of PM end for each
	PM part.
001	Y PCU Developer [0 to 99999999 / 368602 / 1 m]
002	M PCU Developer [0 to 99999999 / 368602 / 1 m]
003	C PCU Developer [0 to 99999999 / 368602 / 1 m]
004	Bk PCU Developer [0 to 99999999 / 349125 / 1 m]
005	Y PCU Drum [0 to 99999999 / 993571 / 1 m]
006	M PCU Drum [0 to 99999999 / 993571 / 1 m]
007	C PCU Drum [0 to 99999999 / 993571 / 1 m]
800	Bk PCU Drum [0 to 99999999 / 595582 / 1 m]
009	Used Toner Bottle [0 to 99999999 / 99999999 / 1 m]
010	Dust Filter:K [0 to 99999999 / 188528 / 1 m]
011	Dust Filter:YCM [0 to 99999999 / 188528 / 1 m]
012	Ozone Filter [0 to 99999999 / 565582 / 1 m]

Technical Bulletin

PAGE: 68/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

On page1316

7940*	Drive Distance:End Std Value
	Displays the standard value (motor rotation count) of PM end for each
	PM part.
096	ITB [0 to 99999999 / 722582 / 1 m]
112	Brush Roller Gear [0 to 99999999 / 99999999 / 1 m]
116	Hot Roller Gear [0 to 99999999 / 1261580 / 1 m]
117	Hot Roller [0 to 99999999 / 420527 / 1 m]
120	Separation Claw [0 to 99999999 / 420527 / 1 m]
125	Heating Roller Thermistor [0 to 99999999 / 841053 / 1 m]

On page1317

7940*	Drive Distance:End Std Value				
	Displays the standard value (motor rotation count) of PM end for each				
	PM part.				
126	Pressure Roller Thermistor [0 to 99999999 / 841053 / 1 m]				

7941*	Drive Distance:N-End Std Value			
	Displays the standard value (motor rotation count) of PM near-end for			
	each PM part.			
001	Y PCU Developer [0 to 99999999 / 331742 / 1 m]			
002	M PCU Developer [0 to 99999999 / 331742 / 1 m]			
003	C PCU Developer [0 to 99999999 / 331742 / 1 m]			
004	Bk PCU Developer [0 to 99999999 / 324146 / 1 m]			
005	Y PCU Drum [0 to 99999999 / 894214 / 1 m]			
006	M PCU Drum [0 to 99999999 / 894214 / 1 m]			
007	C PCU Drum [0 to 99999999 / 894214 / 1 m]			
800	Bk PCU Drum [0 to 99999999 / 509024 / 1 m]			

On page1318

7951*	Page Counter:End Std Value
	Displays the standard value (page count) of PM end for each PM part.
001	Y PCU Developer [0 to 99999999 / 800000 / 1 page]
002	M PCU Developer [0 to 99999999 / 800000 / 1 page]
003	C PCU Developer [0 to 99999999 / 800000 / 1 page]

7951*	Page Counter:End Std Value
	Displays the standard value (page count) of PM end for each PM part.
00	Bk PCU Developer [0 to 99999999 / 800000 / 1 page]

Technical Bulletin

No.: RG178054 Date: 22-Jun-09

PAGE: 69/93

Model: A	egis-P1/C1	Date: 22-Jun-09	No.: RG178
005	Y PCU Drum [0 to 99999999 / 2000000 /	/ 1 page]	
006	M PCU Drum [0 to 99999999 / 2000000	/ 1 page]	
007	C PCU Drum [0 to 99999999 / 2000000 /	/ 1 page]	
008	Bk PCU Drum [0 to 99999999 / 1200000	/ 1 page]	
009	Used Toner Bottle [0 to 99999999 / 2300	000 / 1 page]	
010	Dust Filter:K [0 to 99999999 / 400000 / 1	page]	
011	Dust Filter:YCM [0 to 99999999 / 400000) / 1 page]	
012	Ozone Filter [0 to 99999999 / 1200000/	1 page]	

On page1320

	9			
7951*	Page Counter:End Std Value			
	Displays the standard value (page count) of PM end for each PM part.			
092	Image Transfer Roller:Y [0 to 99999999 / 800000/ 1 page]			
093	Image Transfer Roller:M [0 to 99999999 / 800000/ 1 page]			
094	Image Transfer Roller:C [0 to 99999999 / 800000/ 1 page]			
095	Image Transfer Roller:K [0 to 99999999 / 800000/ 1 page]			
096	ITB [0 to 99999999 / 1600000 / 1 page]			

On page1321

O., P.,	9
7951*	Page Counter:End Std Value
	Displays the standard value (page count) of PM end for each PM part.
112	Brush Roller Gear [0 to 99999999 / 99999999/ 1 page]
115	Fusing Unit [0 to 99999999 / 400000 / 1 page]
116	Hot Roller Gear [0 to 99999999 / 2400000 / 1 page]
117	Hot Roller [0 to 99999999 / 800000 / 1 page]
118	Fusing Belt [0 to 99999999 / 400000 / 1 page]
119	Pressure Roller [0 to 99999999 / 400000 / 1 page]
120	Separation Claw [0 to 99999999 / 800000/ 1 page]
121	Oil Supply Unit [0 to 99999999 / 400000 / 1 page]
122	Blade Holder [0 to 99999999 / 400000 / 1 page]
123	Oil Pad L [0 to 99999999 / 400000 / 1 page]
124	Fusing Belt Tension Roller [0 to 99999999 / 400000 / 1 page]
125	Heating Roller Thermistor [0 to 99999999 / 1600000 / 1 page]
126	Pressure Roller Thermistor [0 to 99999999 / 1600000 / 1 page]

J D J.;	<u> </u>
7952*	Page Counter:End Std Value
	Displays the standard value (sheet count) of PM end for each PM part.
157	Pickup:A4LCT Upper [0 to 99999999 / 1000000 / 1 sheet] (G178 only)
	Feed:A4LCT Upper [0 to 99999999 / 1000000 / 1 sheet] (G178 only)
159	Separate:A4LCT Upper [0 to 99999999 / 1000000 / 1 sheet]
	(G178 only)
160	Pickup:A4LCT Middle [0 to 99999999 / 1000000 / 1 sheet] (G178 only)

Technical Bulletin

No.: RG178054

PAGE: 70/93

Model: A	egis-P1/C1	Date: 22-Jun-09	No.: RG178
161	Feed:A4LCT Middle [0 to 99999999 / 10	00000 / 1 sheet] (G17	'8 only)
	Separate:A4LCT Middle [0 to 99999999	/ 1000000 / 1 sheet]	
	(G178 only)		
163	Pickup:A4LCT Lower [0 to 99999999 / 10	000000 / 1 sheet] (G1	78 only)
164	Feed:A4LCT Lower [0 to 99999999 / 100	00000 / 1 sheet] (G17	8 only)
165	Separate:A4LCT Lower [0 to 99999999 /	1000000 / 1 sheet]	
	(G178 only)		

On page1323

٠٠. ٢ ٨,	gc 1020			
7952*	Page Counter:End Std Value			
	Displays the standard value (sheet count) of PM end for each PM part.			
185	Contact Glass [0 to 99999999 / 1000000 / 1 sheet] (D016 only)			
186	Feed Belt:U-Tray [0 to 99999999 / 600000 / 1 sheet]			
187	Separation Roller:U-Tray [0 to 99999999 / 600000 / 1 sheet]			
188	Pick-up Roller:U-Tray [0 to 99999999 / 600000 / 1 sheet]			
190	Feed Belt:L-Tray [0 to 99999999 / 600000 / 1 sheet]			
191	Separation Roller:L-Tray [0 to 99999999 / 600000 / 1 sheet]			
198	Perfect Binder:Blade [0 to 99999999 / 100000 / 1 sheet]			
199	Trimmings Catcher Unit : Perfect Binder			
	[0 to 99999999 / 100000 / 1 sheet]			

7952*	Page Counter:End Std Value		
	Displays the standard value (sheet count) of PM end for each PM part.		
212	Torque Limiter : Perfect Binder : Lower-Tray		
	[0 to 99999999 / 1000000 / 1 sheet]		

7953*	Page Counter:N-End Std Value			
	Displays the standard value (page count) of PM near-end for each PM			
	part.			
001	Y PCU Developer [0 to 99999999 / 720000 / 1 page]			
002	M PCU Developer [0 to 99999999 / 720000 / 1 page]			
003	C PCU Developer [0 to 99999999 / 720000 / 1 page]			
004	Bk PCU Developer [0 to 99999999 / 720000 / 1 page]			
005	Y PCU Drum [0 to 99999999 / 1800000 / 1 page]			
006	M PCU Drum [0 to 99999999 / 1800000 / 1 page]			
007	C PCU Drum [0 to 99999999 / 1800000 / 1 page]			
800	Bk PCU Drum [0 to 99999999 / 1080000 / 1 page]			
009	Used Toner Bottle [0 to 99999999 / 180000 / 1 page]			
016	Charge Corona Unit:Y [0 to 99999999 / 360000 / 1 page]			
022	Charge Corona Unit:M [0 to 99999999 / 360000 / 1 page]			
028	Charge Corona Unit:C [0 to 99999999 / 360000 / 1 page]			
034	Charge Corona Unit:K [0 to 99999999 / 360000 / 1 page]			

Technical Bulletin

PAGE: 71/93

 Model: Aegis-P1/C1
 Date: 22-Jun-09
 No.: RG178054

 040 Drum Cleaning Unit:Y [0 to 99999999 / 360000 / 1 page]
 053 Drum Cleaning Unit:M [0 to 99999999 / 360000 / 1 page]

 066 Drum Cleaning Unit:C [0 to 99999999 / 360000 / 1 page]
 079 Drum Cleaning Unit:K [0 to 99999999 / 360000 / 1 page]

 098 ITB Cleaning Unit [0 to 99999999 / 360000 / 1 page]
 105 PTR Unit [0 to 99999999 / 360000 / 1 page]

 115 Fusing Unit [0 to 99999999 / 360000 / 1 page]

After SP8006 on page1332

These SPs are not described in Service Manual for AG-C1.

8 011	T:Jobs/LS	*CTL	These SPs count the number of jobs stored		
8 012	C:Jobs/LS	*CTL	to the document server by each application,		
8 014	P:Jobs/LS	*CTL	to reveal how local storage is being used for		
8 015	S:Jobs/LS	*CTL	input.		
8 016	L:Jobs/LS	*CTL	[0 to 9999999/ 0 / 1]		
8 017	O:Jobs/LS	*CTL	The L: counter counts the number of jobs stored from within the document server mode screen at the operation panel.		

- When a scan job is sent to the document server, the S: counter increments. When you enter document server mode and then scan an original, the L: counter increments.
- When a print job is sent to the document server, the P: counter increments.
- When a network application sends data to the document server, the O: counter increments.
- When an image from Palm 2 is stored on the document server, the O: counter increments.
- When a fax is sent to the document server, the F: counter increments.

After SP8037 on page1333

These SPs are not described in Service Manual for AG-C1.

8 041	T:TX Jobs/LS	*CTL	These SPs count the applications that
8 042	C:TX Jobs/LS	*CTL	stored files on the document server that
8 044	P:TX Jobs/LS	*CTL	were later accessed for transmission over
8 045	S:TX Jobs/LS	*CTL	the telephone line or over a network
8 046	L:TX Jobs/LS	*CTL	(attached to an e-mail, or as a fax image
8 047	O:TX Jobs/LS	*CTL	by I-Fax). [0 to 9999999/ 0 / 1] Note: Jobs merged for sending are counted separately. The L: counter counts the number of jobs scanned from within the document server mode screen at the operation panel.

- When a stored copy job is sent from the document server, the C: counter increments.
- When images stored on the document server by a network application or Palm2 are sent as an e-mail, the O: counter increments.

Technical Bulletin

PAGE: 72/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

8 051	T:TX Jobs/DesApl	*CTL	These SPs count the applications used to send files from the document server over
8 052	C:TX Jobs/DesApl	*CTL	the telephone line or over a network (attached to an e-mail, or as a fax image
8 054	P:TX Jobs/DesApl	*CTL	by I-Fax). Jobs merged for sending are counted separately.
8 055	S:TX Jobs/DesApl	*CTL	[0 to 9999999/ 0 / 1] The L: counter counts the number of jo
8 056	L:TX Jobs/DesApl	*CTL	sent from within the document server mode screen at the operation panel.
8 057	O:TX Jobs/DesApl	*CTL	

If the send is started from Desk Top Binder or Web Image Monitor, for example, then the O: counter increments.

After SP8077 on page1335

These SPs are not described in Service Manual for AG-C1.

8 131	T:S-to-Email Jobs	*CTL	[0 to 9999999/ 0 / 1]		
		These SPs count the total number of jobs (color or black-and-			
			to an e-mail, regardless of whether		
	the document server	was use	d or not.		
8 135	S: S-to-Email Jobs	*CTL	[0 to 9999999/ 0 / 1]		
		e SPs count the number of jobs (color or black-and-white) ned and attached to e-mail, without storing the original on the ment server.			
8 13x 1	B/W				
8 13x 2	Color				
8 13x 3	ACS				

- These counters count jobs, not pages.
- If the job is stored on the document server, after the job is stored it is determined to be color or black-and-white then counted.
- If the job is cancelled during scanning, or if the job is cancelled while the document is waiting to be sent, the job is not counted.
- If the job is cancelled during sending, it may or may not be counted, depending on what stage of the process had been reached when the job was cancelled.
- If several jobs are combined for sending to the Scan Router, Scan-to-Email, or Scan-to-PC, or if one job is sent to more than one destination. each send is counted separately. For example, if the same document is sent by Scan-to-Email as well as Scan-to-PC, then it is counted twice (once for Scan-to-Email and once for Scan-to-PC).

8 141	T:Deliv Jobs/Svr	*CT	[0 to 9999999/ 0 / 1]
		L	

Technical Bulletin

PAGE: 73/93

- These counters count jobs, not pages.
- The jobs are counted even though the arrival and reception of the jobs at the Scan Router server cannot be confirmed.
- If even one color image is mixed with black-and-white images, then the job is counted as a "Color" job.
- If the job is cancelled during scanning, or if the job is cancelled while the document is waiting to be delivered, the job is not counted.
- If the job is cancelled during sending, it may or may not be counted, depending on what stage of the process had been reached when the job was cancelled.
- Even if several files are combined for sending, the transmission counts as one job.

8 151	T:Deliv Jobs/PC	*CTL	[0 to 9999999/ 0 / 1]		
	These SPs count the total number of jobs (color or black-and-white) scanned and sent to a folder on a PC (Scan-to-PC). Note: At the present time, 8 151 and 8 155 perform identical counts.				
8 155	S:Deliv Jobs/PC	*CTL	[0 to 9999999/ 0 / 1]		
	These SPs count the total number of jobs (color or black-and-white) scanned and sent with Scan-to-PC.				
8 15x 1	B/W				
8 15x 2	Color				
8 15x 3	ACS	·			

- These counters count jobs, not pages.
- If the job is cancelled during scanning, it is not counted.
- If the job is cancelled while it is waiting to be sent, the job is not counted.
- If the job is cancelled during sending, it may or may not be counted, depending on what stage of the process had been reached when the job was cancelled.
- Even if several files are combined for sending, the transmission counts as one job.

8 191	T:Total Scan PGS	*CTL	These SPs count the pages scanned by each application that uses the scanner to
8 192	C:Total Scan PGS	*CTL	scan images. [0 to 9999999/ 0 / 1]
8 195	S:Total Scan PGS	*CTL	

Technical Bulletin

PAGE: 74/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

8 196 L:Total Scan *CTL PGS

- SP 8 191 to 8 196 count the number of scanned sides of pages, not the number of physical pages.
- These counters do not count reading user stamp data, or reading color charts to adjust color.
- Previews done with a scanner driver are not counted.
- A count is done only after all images of a job have been scanned.
- Scans made in SP mode are not counted.

Examples

- If 3 B5 pages and 1 A3 page are scanned with the scanner application but not stored, the S: count is 4.
- If both sides of 3 A4 sheets are copied and stored to the document server using the Store File button in the Copy mode window, the C: count is 6 and the L: count is 6.
- If both sides of 3 A4 sheets are copied but not stored, the C: count is 6.
- If you enter document server mode then scan 6 pages, the L: count is 6.

8 201	T:LSize Scan PGS	*CTL	[0 to 9999999/ 0 / 1]		
			r of large pages input with the		
			arge size paper (A3/DLT) scanned		
	for fax transmission are	not count	ed.		
		re display	ed in the SMC Report, and in the		
	User Tools display.				
8 205	S:LSize Scan PGS	*CTL	[0 to 9999999/ 0 / 1]		
			r of large pages input with the		
	scanner for scan jobs only. Large size paper (A3/DLT) scanned for fax				
	transmission are not counted.				
	Note: These counters are displayed in the SMC Report, and in the				
	User Tools display.				

8 211	T:Scan PGS/LS	*CTL	These SPs count the number of pages
8 212	C:Scan PGS/LS	*CTL	scanned into the document server .
8 215	S:Scan PGS/LS	*CTL	[0 to 9999999/ 0 / 1]
8 216	L:Scan PGS/LS	*CTL	The L: counter counts the number of pages stored from within the document server mode screen at the operation panel, and with the Store File button from within the Copy mode screen

- Reading user stamp data is not counted.
- If a job is cancelled, the pages output as far as the cancellation are counted.
- If the scanner application scans and stores 3 B5 sheets and 1 A4 sheet, the S: count is 4
- If pages are copied but not stored on the document server, these counters do not change.
- If both sides of 3 A4 sheets are copied and stored to the document server, the C: count is 6 and the L: count is 6.
- If you enter document server mode then scan 6 pages, the L: count is 6.

Technical Bulletin

PAGE: 75/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

8 221	ADF Org	g Feeds *CTL [0 to 9999999/ 0 / 1]					
	These S	Ps count the number of pages fed through the ADF for front					
	and bac	k side scanning.					
8 221 1	Front	Number of front sides fed for scanning:					
		With an ADF that can scan both sides simultaneously, the					
		Front side count is the same as the number of pages fed					
		for either simplex or duplex scanning.					
		With an ADF that cannot scan both sides simultaneously,					
		the Front side count is the same as the number of pages					
		fed for duplex front side scanning. (The front side is					
		determined by which side the user loads face up.)					
8 221 2	Back	Number of rear sides fed for scanning:					
		With an ADF that can scan both sides simultaneously, the					
		Back count is the same as the number of pages fed for					
		duplex scanning.					
		With an ADF that cannot scan both sides simultaneously,					
		the Back count is the same as the number of pages fed for					
		duplex rear-side scanning.					

- When 1 sheet is fed for duplex scanning the Front count is 1 and the Back count is 1.
- If a jam occurs during the job, recovery processing is not counted to avoid double counting. Also, the pages are not counted if the jam occurs before the first sheet is output.

8 231	Scan PGS/Mode	*CT [0 to 9999999/ 0 / 1]		
		number of pages scanned by each ADF ne work load on the ADF.		
8 231 1	Large Volume	Selectable. Large copy jobs that cannot be loaded in the ADF at one time.		
8 231 2	SADF	Selectable. Feeding pages one by one through the ADF.		
8 231 3	Mixed Size	Selectable. Select "Mixed Sizes" on the operation panel.		
8 231 4	Custom Size	Selectable. Originals of non-standard size.		
8 231 5	Platen	Book mode. Raising the ADF and placing the original directly on the platen.		
8 231 6	Mixed 1side/ 2side	Simplex and Duplex mode.		

- If the scan mode is changed during the job, for example, if the user switches from ADF to Platen mode, the count is done for the last selected mode.
- The user cannot select mixed sizes or non-standard sizes with the fax application so if the original's page sizes are mixed or non-standard, these are not counted.
- If the user selects "Mixed Sizes" for copying in the platen mode, the Mixed Size count is enabled.
- In the SADF mode if the user copies 1 page in platen mode and then copies 2 pages with SADF, the Platen count is 1 and the SADF count is 3.

Technical Bulletin

PAGE: 76/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

Model. / legi	31 1/01			טכ	atc. 22-3un-03	110.	100170
8 241	T:Scan PGS/Org *CT			[0 to	9999999/ 0 / 1]	
	These SPs count the total number of scanned pages by original					al	
			ess of whi	ch app	plication was ι	ised.	
8 242	C:Scan PGS	•		-	9999999/ 0 / 1	-	
		count the nui	mber of p	ages	scanned by or	iginal typ	e for
	Copy jobs.						
8 245	S:Scan PGS		*CTL	-	9999999/ 0 / 1		
		count the nui	mber of p	ages	scanned by or	iginal typ	e for
	Scan jobs.						
8 246	L:Scan PGS	•	*CTL	_	9999999/ 0 / 1		
					scanned and s		
					n at the opera		
	and with the				in the Copy mo	ode scre	en
		8 241	8 2	42	8 245	8 24	16
8 24x 1: Tex	t	Yes	Ye	S	Yes	Ye	S
8 24x 2: Tex	t/Photo	Yes	Ye	S	Yes	Ye	
8 24x 3: Pho		Yes	Ye	S	Yes	Ye	S
8 24x 4: Ge	nCopy, Pale	Yes	Ye	S	Yes	Ye	S
8 24x 5: Ma		Yes	Ye	S	No	Ye	S
8 24x 6: Noi	rmal/Detail	Yes	No)	No	No)
8 24x 7: Fine/Super		Yes	No)	No	No)
Fine							
8 24x 8: Bin	8 24x 8: Binary		No)	Yes	No)
8 24x 9: Gra	•	Yes	No		Yes	No	
8 24x 10: Co		Yes	No)	Yes	No)
8 24x 11: Ot	ther	Yes	Ye	S	Yes	Ye	S

• If the scan mode is changed during the job, for example, if the user switches from ADF to Platen mode, the count is done for the last selected mode.

8 251	T:Scan	*CTL	These SPs show how many times Image
	PGS/ImgEdt		Edit features have been selected at the
8 252	C:Scan	*CTL	operation panel for each application.
	PGS/ImgEdt		Some examples of these editing features
8 255	S : Scan	*CTL	are:
	PGS/ImgEdr		Erase> Border
8 256	L:Scan	*CTL	Erase> Center
	PGS/ImgEdt		Image Repeat

Technical Bulletin

PAGE: 77/93

Model: Aegis-P1/C1

8 257

O:Scan
PGS/ImgEdt

*CTL
Positive/Negative
[0 to 9999999/ 0 / 1]
Note: The count totals the number of times the edit features have been used. A detailed breakdown of exactly which features have been used is not given.

The L: counter counts the number of pages stored from within the document server mode screen at the operation panel, and with the Store File button from within the Copy mode screen.

8 261	T:Scan PGS/ColCr	*CTL	-	
8 262	C:Scan PGS/ ColCr	*CTL	-	
8 265	S:Scn PGS/Color	*CTL	-	
8 266	L:Scn PGS/ColCr	*CTL	-	
8 26x 1	Color Conversion	These SPs show how many times color		
8 26x 2	Color Erase	creation features have been selected at to operation panel.		
8 26x 3	Background			
8 26x 4	Other			

8 281	T:Scan PGS/TWAIN	*CTL	These SPs count the number of pages scanned using a TWAIN driver. These
8 285	S:Scan PGS/TWAIN	*CTL	counters reveal how the TWAIN driver is used for delivery functions. [0 to 9999999/ 0 / 1] Note: At the present time, these counters perform identical counts.

8 291	T:Scan PGS/Stamp	*CTL	These SPs count the number of pages stamped with the stamp in the ADF unit.
8 295	S:Scan PGS/Stamp	*CTL	[0 to 9999999/ 0 / 1] The L: counter counts the number of pages stored from within the document server mode screen at the operation panel, and with the Store File button from within the Copy mode screen

8 301	T:Scan PGS/Size	*CT	[0 to 9999999/ 0 / 1]		
		L			
	•		otal number of pages scanned by all		
	applications. Use these totals to compare original page size				
	(scanning) and output (p	printing) page size [SP 8-441].		
8 302	C:Scan PGS/Size	*CT	[0 to 9999999/ 0 / 1]		
		L			

Technical Bulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 78/93

Model: Aegis-P1/C1				Date: 22-Jun-09	No.: RG178
	These SPs count by size the total number of pages scanned by the Copy application. Use these totals to compare original page size (scanning) and output (printing) page size [SP 8-442].				
8 305	S:Scan PGS/Size	*CT L		9999999/ 0 / 1]	
	These SPs count by siz Scan application. Use to (scanning) and output p	hese tot	als to	compare original pa	
8 306	L:Scan PGS/Size	*CT L	[0 to	9999999/ 0 / 1]	
	These SPs count by size the total number of pages scanned and stored from within the document server mode screen at the operation panel, and with the Store File button from within the Copy mode screen. Use these totals to compare original page size (scanning) and output page size [SP 8-446].				the in the
8 30x 1	A3	-		-	
8 30x 2	A4				
8 30x 3	A5				
8 30x 4	B4				
8 30x 5	B5				
8 30x 6	DLT				
8 30x 7	LG				
8 30x 8	LT				
8 30x 9	HLT				
8 30x 10	Full Bleed				
8 30x 254	Other (Standard)				
8 30x 255	Other (Custom)				
		T			

8 311	T:Scan PGS/Rez	*CTL	[0 to 9999999/ 0 / 1]		
	These SPs count by resolution setting the total number of pages				
	scanned by applicat	oplications that can specify resolution settings.			

• After SP8651 on page1347

These SPs are not described in Service Manual for AG-C1.

8 661	T:Deliv PGS/Svr	*CTL	[0 to 9999999/ 0 / 1]	
	These SPs count by color mode the total number of pages sent to			
	a Scan Router server by both Scan and LS applications.			
8 665	S:Deliv PGS/Svr	*CTL	[0 to 9999999/ 0 / 1]	
	These SPs count by color mode the total number of pages sent a Scan Router server by the Scan application.			
8 66x 1	B/W			
8 66x 2	Color			

Note

The B/W and Color counts are done after the document is stored on the HDD of

Technical Bulletin

PAGE: 79/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

the Scan Router server.

If the job is canceled before storage on the Scan Router server finishes, the counts are not done.

The count is executed even if regardless of confirmation of the arrival at the Scan Router server.

8 671	T:Deliv PGS/PC	*CTL	[0 to 9999999/ 0 / 1]	
	These SPs count by color mode the total number of pages sent to			
	a folder on a PC (Scan-to-PC) with the Scan and LS applications.			
8 675	S: Deliv PGS/PC	*CTL	[0 to 9999999/ 0 / 1]	
	These SPs count by color mode the total number of pages sent with Scan-to-PC with the Scan application.			
8 67x 1	B/W			
8 67x 2	Color			

8 691	T:TX PGS/LS	*CT	These SPs count the number of pages sent
		L	from the document server. The counter for
8 692	C:TX PGS/LS	*CT	the application that was used to store the
		L	pages is incremented.
8 694	P:TX PGS/LS	*CT	[0 to 9999999/ 0 / 1]
		L	The L: counter counts the number of pages
8 695	S:TX PGS/LS	*CT	stored from within the document server
		L	mode screen at the operation panel. Pages
8 696	L:TX PGS/LS	*CT	stored with the Store File button from within
		L	the Copy mode screen go to the C: counter.

Note

Print jobs done with Web Image Monitor and Desk Top Binder are added to the count.

If several documents are merged for sending, the number of pages stored are counted for the application that stored them.

When several documents are sent by a Fax broadcast, the F: count is done for the number of pages sent to each destination.

8 701	TX PGS/Port	*CTL	[0 to 9999999/ 0 / 1]	
	used to send them.	the number of pages sent by the physical port n. For example, if a 3-page original is sent to 4 DN G4, the count for ISDN (G3, G4) is 12.		
8 701 1	PSTN-1			
8 701 2	PSTN-2			
8 701 3	PSTN-3			
8 701 4	ISDN (G3,G4)			
8 701 5	Network			

Technical **B**ulletin

Date: 22-Jun-09 No.: RG178054

PAGE: 80/93

Model: Aegis-P1/C1			Date: 22-Jun-09	No.: RG178	
8 711	T:Scan PGS/Comp	*CTL	[0 to 9999	9999/ 0 / 1]	
8 715	S:Scan PGS/Comp	*CTL	[0 to 9999	9999/ 0 / 1]	
	These SPs count to mode.	he numb	er of page	s sent by each com	pression
8 715 1	JPEG/JPEG2000				
8 715 2	TIFF(Multi/Single)				
8 715 3	PDF				
8 715 4	Other				
8 715 5	PDF/Comp				

8 741	RX PGS/Port	*CTL [0 to 9999999/ 0 / 1]		
	These SPs count to used to receive the	he number of pages received by the physical portem.		
8 741 1	PSTN-1	-		
8 741 2	PSTN-2	-		
8 741 3	PSTN-3	-		
8 741 4	ISDN (G3,G4)	-		
8 741 5	Network	-		

Technical Bulletin

PAGE: 81/93

Model: Aegis-P1/C1 No.: RG178054 Date: 22-Jun-09

After SP8781 on page1347
 This SP is not described in Service Manual for AG-C1.

8 791	LS Memory Remain	This SP displays the percent of space available on the document server for storing documents.
		[0 to 100 / 0 / 1]

After SP8941 on page1350
 These SPs are not described in Service Manual for AG-C1.

		IT OCTVICE IVIATIDATION AC-OT	•
8 951	AddBook	*CTL	
	Register		
	These SPs cour	nt the number of events whe	en the machine
	manages data re	egistration.	
8 951 1	User	User code registrations.	[0 to 9999999/ 0 /
	Code/User ID		1]
8 951 2	Mail Address	Mail address registrations.	
8 951 3	Fax	Fax destination	
	Destination	registrations.	
8 951 4	Group	Group destination	
		registrations.	
8 951 5	Transfer	Fax relay destination	
	Request	registrations for relay TX.	
8 951 6	F-Code	F-Code box registrations.	
8 951 7	Copy Program	Copy application	[0 to 255 / 0 / 255]
		registrations with the	
		Program (job settings)	
		feature.	
8 951 8	Fax Program	Fax application	
		registrations with the	
		Program (job settings)	
0.054.0	D : 1	feature.	
8 951 9	Printer	Printer application	
	Program	registrations with the	
		Program (job settings) feature.	
8 951 10	Scanner		
0 931 10		Scanner application registrations with the	
	Program	Program (job settings)	
		feature.	
	1	icatare.	

Technical Bulletin

PAGE: 82/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

On page1352

Scanner SP (D016 only)

• On page1355
Delete the following SPs.

5803	Description	Reading		
5605	Description	0	1	
5803-1	MUSIC Sensor: Rear			
5803-2	MUSIC Sensor:Center		t [V]	
5803-3	MUSIC Sensor:Front			
5803-4	LD Current:Y			
5803 5	LD Current:M	Input [mA]		
5803-6	LD Current:C			
5803 7	LD Current:K			
5803-8	BCU:3V Std Voltage (M)	Inpu	t [V]	
5803-10	ID Sensor Y:Direct	·	•	
5803-11	ID Sensor M:Direct	- Inner	4 F\ /1	
5803-12	ID Sensor C:Direct	Input [V]		
5803-13	ID Sensor K:Direct			
5803-16	ID Sensor Y:Diffused			
5803 17	ID Sensor M:Diffused	Input [V]		
5803 18	ID Sensor C:Diffused			
5803-19	Image Transfer:HV:Y	Input [kV]		
5803-20	Image Transfer:HV:M			
5803-21	Image Transfer:HV:C			
5803-22	Image Transfer:HV:K			
5803-23	Paper Transfer:HV	Input	[kV]	
5803-24	IOB:3V Std Voltage (M)	Inpu	t [V]	
5803-25	Drum Potential Sensor Y			
5803-26	Drum Potential Sensor M	- Innu	4 F\ /1	
5803-27	Drum Potential Sensor C	─ Inpu	t [V]	
5803-28	Drum Potential Sensor K			
5803-29	3V Std Voltage (IOB1)	Inpu	t [V]	
5803-30	TD Sensor Y: Voltage			
5803-31	TD Sensor M: Voltage	Innu	4 F\ /1	
5803-32	TD Sensor C: Voltage	─ Inpu	t [∀]	
5803-33	TD Sensor K: Voltage			
5803-34	TD Sensor Y			
5803-35	TD Sensor M	laari	+ F\ /1	
5803-36	TD Sensor C	─ Inpu	t [∀]	
5803-37	TD Sensor K			

Technical Bulletin

PAGE: 83/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

After SP5803-139 on page1374 These SPs are newly added.

5803 140	CTB_H8S-PORT9	Read	ding
	(Buffer Pass Unit: M379)	0	1
	Bit 0 Reserve Fan 4	-	-
	Bit 1 Reserved	-	-
	Bit 2 Lower Exhaust Fan	Normal	Error
	Bit 3 Lower Exhaust Fan	Normal	Error
	Bit 4 Reserve Fan 3	-	-
	Bit 5 Reserved	-	-
	Bit 6 Lower Cooling Fan	Normal	Error
	Bit 7 Lower Cooling Fan	Normal	Error

5803 141	CTB_H8S-PortA		Rea	ding
	(Buffe	r Pass Unit: M379)	0	1
	Bit 0	Interlock Switch: Front Door	Close	Open
	Bit 1	Debug monitor	SCI	
	Bit 2	Debug monitor	SCI	
	Bit 3	LED	On	Off
	Bit 4	Not used	-	-
	Bit 5	Not used	-	-
	Bit 6	Not used	_	_
	Bit 7	Not used	-	-

5803 142	CTB_H8S-PortB (Buffer Pass Unit: M379)		Read	ding
			0	1
	Bit 0	Drive Motor Left	Normal	Error
	Bit 1	Drive Motor Right	Normal	Error
	Bit 2	Drive Motor Left	Motor Lock	
	Bit 3	Drive Motor Left	CCW	CW
	Bit 4	Drive Motor Left	On	Off
	Bit 5	Drive Motor Right	Motor Lock	
	Bit 6	Drive Motor Right	CCW	CW
	Bit 7	Drive Motor Right	On	Off

5803 143	CTB_H8S-PortC	Read	Reading	
	(Buffer Pass Unit: M379)	0	1	
	Bit 0 Reserve Fan 2	-	-	
	Bit 1 Reserved	-	-	
	Bit 2 Upper Exhaust Fan	Normal	Error	
	Bit 3 Upper Exhaust Fan	Normal	Error	
	Bit 4 Reserve Fan 1	-	-	
	Bit 5 Reserved	-	-	
	Bit 6 Upper Cooling Fan	Normal	Error	
	Bit 7 Upper Cooling Fan	Normal	Error	

Technical Bulletin

PAGE: 84/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

5803 144	CTB_H8S-PortD			Read	ding
	(Buffe	r Pass Unit: M379)		0	1
	Bit 0	Transport Sensor 6	Р	aper detected	Paper not detected
	Bit 1	Transport Sensor 3	Р	aper detected	Paper not detected
	Bit 2	Transport Sensor 7	Р	aper detected	Paper not detected
	Bit 3	Transport Sensor 2	Р	aper detected	Paper not detected
	Bit 4	Transport Sensor 8	Р	aper detected	Paper not detected
	Bit 5	Transport Sensor 1	Р	aper detected	Paper not detected
	Bit 6	Not used		-	
	Bit 7	Not used		-	-

5803 145	145 CTB_H8S-PortE		Read	ding
	(Buffer	Pass Unit: M379)	0	1
	Bit 0	Not used	-	_
	Bit 1	Not used	-	-
	Bit 2	+24V	+24V On	+24V Off
	Bit 3	+24V INT	+24V_INT On	+24V_INT Off
	Bit 4	Not used	-	-
	Bit 5	Not used	-	-
	Bit 6	Transport Sensor 5	Paper detected	Paper not detected
	Bit 7	Transport Sensor 4	Paper detected	Paper not detected

■ After SP5803-172 on **page1381**These SPs are not described in Service Manual for AG-C1.

5803 181	A4LC1	T:CPU-Port7	Read	ding
	(G178	only)	0	1
	Bit 0	LCT Exit Sensor	Paper detected	Not detected
	Bit 1	_	-	-
	Bit 2	_	-	-
	Bit 3	-	-	-
	Bit 4	LCT Front Door Safety Switch	Close	Open
	Bit 5	-	-	-
	Bit 6	-	-	-
	Bit 7	-	-	_

5803 182	A4LCT:eIO2-PortP	Reading	
	(G178 only)	0	1

Technical Bulletin

PAGE: 85/93

Model: Aegis-P1/C1		Date: 22-Jun-09	No.: RG178	3054
Bit 0	-	-	-	
Bit 1	-	_	-	
Bit 2	-	-	-	
Bit 3	-	_	-	
Bit 4	-	-	-	
Bit 5	-	-	_	
Bit 6	Transport Sensor Bypass	Paper detected	Not detected	
Bit 7	-	-	_	

5803 183	A4LCT:eIO2-PortA		Read	ding
			0	1
	Bit 0	3rd Transport Sensor	Paper detected	Not detected
	Bit 1	3rd Lift Sensor	Upper limit	Not upper limit
	Bit 2	3rd Paper End Sensor	Paper detected	Not detected
	Bit 3	3rd Paper Feed Sensor	Paper detected	Not detected
	Bit 4	-	-	-
	Bit 5	3rd Paper Size Sensor 3	On	Off
	Bit 6	3rd Paper Size Sensor 2	On	Off
	Bit 7	3rd Paper Size Sensor 1	On	Off

When this LCT is installed in another mainframe, the upper tray of this LCT may show "4th".

5803 184	A4LCT:eIO2-PortB		Reading	
	(G178	only)	0	1
	Bit 0	-	-	-
	Bit 1	-	-	-
	Bit 2	-	_	-
	Bit 3	-	_	-
	Bit 4	3rd Paper Height Sensor 4	Off	On
	Bit 5	3rd Paper Height Sensor 3	Off	On
	Bit 6	3rd Paper Height Sensor 2	Off	On
	Bit 7	3rd Paper Height Sensor 1	Off	On

When this LCT is installed in another mainframe, the upper tray of this LCT may show "4th".

5803 185	A4LCT:eIO2-PortC			Reading		
	(G178	only)	0		1	
	Bit 0	4th Transport Sensor	Paper dete	ected	Not detected	
	Bit 1	4th Lift Sensor	Upper lir	nit	Not upper limit	
	Bit 2	4th Paper End Sensor	Paper dete	ected	Not detected	
	Bit 3	4th Paper Feed Sensor	Paper dete	ected	Not detected	
	Bit 4	-	-		-	
	Bit 5	4th Paper Size Sensor 3	On		Off	
	Bit 6	4th Paper Size Sensor 2	On		Off	

Technical Bulletin

On

PAGE: 86/93

Off

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "5th".

Bit 7 4th Paper Size Sensor 1

5803 186	A4LCT:elO2-PortD	Read	Reading	
	(G178 only)	0	1	
	Bit 0 -	_	_	
	Bit 1 -	-	-	
	Bit 2 -	-	-	
	Bit 3 -	-	-	
	Bit 4 4th Paper Height Sensor 4	Off	On	
	Bit 5 4th Paper Height Sensor 3	Off	On	
	Bit 6 4th Paper Height Sensor 2	Off	On	
	Bit 7 4th Paper Height Sensor 1	Off	On	

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "5th".

5803 187	A4LCT:eIO3-PortA		Reading	
	(G178	only)	0	1
	Bit 0	5th Transport Sensor	Paper detected	Not detected
	Bit 1	5th Lift Sensor	Upper limit	Not upper limit
	Bit 2	5th Paper End Sensor	Paper detected	Not detected
	Bit 3	5th Paper Feed Sensor	Paper detected	Not detected
	Bit 4	-	_	-
	Bit 5	5th Paper Size Sensor 3	On	Off
	Bit 6	5th Paper Size Sensor 2	On	Off
	Bit 7	5th Paper Size Sensor 1	On	Off

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "6th".

5803 188	A4LCT:eIO3-PortB	Read	Reading	
	(G178 only)	0	1	
	Bit 0 -	-	_	
	Bit 1 -	-	_	
	Bit 2 -	-	-	
	Bit 3 -	-	-	
	Bit 4 5th Paper Height Sensor 4	Off	On	
	Bit 5 5th Paper Height Sensor 3	Off	On	
	Bit 6 5th Paper Height Sensor 2	Off	On	
	Bit 7 5th Paper Height Sensor 1	Off	On	

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "6th".

PAGE: 87/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

5803 189	A4LCT:eIO2-PortE (G178 only) (By-pass Unit B833)		Reading	
			0	1
	Bit 0 -		-	-
	Bit 1 -		-	-
	Bit 2 Paper Len	gth Sensor	On	Off
	Bit 3 Paper Wid	th Switch 5	On	Off
	Bit 4 Paper Wid	th Switch 4	On	Off
	Bit 5 Paper Wid	th Switch 3	On	Off
	Bit 6 Paper Wid	th Switch 2	On	Off
	Bit 7 Paper Wid	th Switch 1	On	Off

5803 190	A4LCT:eIO3-PortC (G178 only)			Reading		
	(By-pa	ss Unit B833)		0	1	
	Bit 0	Relay Sensor	Pa	per detected	Not detected	
	Bit 1	Lift Sensor		Upper limit	Not upper limit	
	Bit 2	Paper End Sensor	Pa	per detected	Not detected	
	Bit 3	Paper Feed Sensor	Pa	per detected	Not detected	
	Bit 4	-		-	-	
	Bit 5	-		-	-	
	Bit 6	-		-	-	
	Bit 7	-		-	-	

5803 191	A4LCT:eIO3-PortD		Read	Reading	
	(G178	only)	0	1	
	Bit 0	Feed Unit Slide Detection	Close	Open	
	Bit 1	Feed Unit Set Detection	Set	Not set	
	Bit 2	-	-	_	
	Bit 3	Tray Lift Switch	On (Pushed)	Off	
	Bit 4	Tray Lower Limit Sensor	Not lower limit	Lower limit	
	Bit 5	-	-	_	
	Bit 6	Paper End Sensor	Off	On	
	Bit 7	Paper Near End Sensor	Off	On	

5803	Description	Reading	
5605	Description	0	1
5803 201	Platen Cover Sensor (D016 only)	Open	Close

5803 202	Scanner fan lock signal	Reading	
	(D016 only)	0	1
	Bit 0 Scanner HP Sensor	Not HP	HP
	Bit 1 Lamp Regulator Fan (Right)	Normal	Lock
	Bit 2 SBU Cooling Fan	Normal	Lock
	Bit 3 Scanner Intake Fan	Normal	Lock
	Bit 4 Scanner Unit Exhaust Fan	Normal	Lock
	Bit 5 Lamp Regulator Fan (Left)	Normal	Lock

Technical Bulletin

PAGE: 88/93

Model: Aegis-P1/C1	Date: 22-Jun-09	No.: RG178	3054	
Bit 6 Scanner	Motor Cooling Fan	Normal	Lock	
Bit 7 Not used		-	-	

On page 1388

ADF Input Check: SP6007 (D016 only)

• After SP 5804-169 on **page 1403**

These SPs (-170 to -175) are newly added and SPs (-190 to -206) are not described in Service Manual for AG-C1.

Description
Feed Motor 1 (Drive Motor Right in Buffer Pass Unit (M379))
Feed Motor 2 (Drive Motor Left in Buffer Pass Unit (M379))
Cool Fan Drv 1 (Upper Cooling Fan in Buffer Pass Unit (M379))
Exhaust Fan Drv 1 (Upper Exhaust Fan in Buffer Pass Unit (M379))
Cool Fan Drv 2 (Lower Cooling Fan in Buffer Pass Unit (M379))
Exhaust Fan Drv 2 (Lower Exhaust Fan in Buffer Pass Unit (M379))
to -199 only for G178
A4LCT Upper Feed Motor
A4LCT Middle Feed Motor
A4LCT Lower Feed Motor
A4LCT Upper Transport Motor
A4LCT Middle Transport Motor
A4LCT Lower Transport Motor
A4LCT Upper Relay Motor
A4LCT Middle Relay Motor
A4LCT Lower Relay Motor
A4LCT Exit Motor
Web Motor
to -206 only for D016
Scanner lamp1 (Exposure Lamp 1)
Scanner lamp2 (Exposure Lamp 2)
Scanner fanmotor A (Lamp Regulator Fan: Left and Right)
Scanner fanmotor B

Technical Bulletin

PAGE: 89/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

No. Description

No.	Description		
	(Scanner Motor Cooling Fan)		
206	Scanner fanmotor C		
200	(Scanner Intake and Exhaust Fan)		
From -210 to	-215 only for G178		
210	A4LCT Upper Pick-up SOL		
211	A4LCT Middle Pick-up SOL		
212	A4LCT Lower Pick-up SOL		
213	A4LCT Upper Separation Roller SOL		
214	A4LCT Middle Separation Roller SOL		
215	A4LCT Lower Separation Roller SOL		
_			
216	A3 LCT1:Paper Feed Motor 1		

On page 1405

ADF Output Check: SP6008 (D016 only)

• Add the following new content on the last page (P1429) of the chapter "Service Tables".

This content is newly added. Therefore, red text is not used.

Using SP Mode

CPM Down (SP1201)

This machine uses CPM (PPM) down control to compensate for insufficient fusing temperature or high temperature in small size (less than 228 mm) printing. The execution condition of this control differs depending on the temperature inside the machine (low temperature or normal temperature). The threshold between low and normal temperature can be adjustable with SP1107-018.

SP1107-018: Low Temp On/Off

This adjusts the threshold temperature for low temperature condition. [10 to 23 / 17 / 1 deg]

SP1201-001 and -002: Threshold Temperature for CPM Down

These SPs adjust DOWN or UP threshold.

If the detected fusing temperature is 30°C lower than a target temperature, the machine enters the CPM down mode.

Technical Bulletin

PAGE: 90/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

If the detected fusing temperature is 8°C lower than a target temperature, the machine enters the CPM up mode.

Note

- The target temperature is calculated referring to paper type, condition, print mode and etc.
- -001: Threshold temperature for CPM DOWN
 [0 to -50/ -30 / 1 deg]
- -002: Threshold temperature for CPM UP [0 to -50/ -8 / 1 deg]

SP1201-003 to -005: Basic CPM Down Rate

These SPs adjusts the Low Temp.: CPM Down (PPM) rate. The machine tries to detect a fusing temperature every 10 seconds (adjustable with SP1201-024). Whenever the machine gets CPM down, the machine enters a next mode.

For example, the machine enters the Low Temp.: 1st CPM Down after detecting 30°C lower than a target temperature. If the machine still detects that a fusing temperature is 30°C lower than a target temperature after 10 seconds, the machine enters the next mode (Low Temp.: 2nd CPM Down). The machine determines which mode the machine is now in every 10 seconds, and then goes forward or back one by one among these modes.

- -003: CPM down rate for Low Temp.:1st CPM Down [10 to 100/ 80 / 1 %]
- -004: CPM down rate for Low Temp.:2nd CPM Down [10 to 100/ 60 / 1 %]
- -005: CPM down rate for Low Temp.:3rd CPM Down [10 to 100/ 40 / 1 %]

SP1201-006 to -011: CPM Down Rate and Mode Threshold Temp

These SPs adjust CMP (PPM) down rate and mode threshold temperature for small size paper.

For example, the machine enters the "High Temp:1st CPM Down" mode if the paper size to be used is small size paper (less than 228 mm) and the temperature of the fusing unit reaches 215°C (threshold temperature for High Temp::1st CPM Dow) by default setting.

- -006: CPM down rate for High Temp.:1st CPM Down
 [10 to 100/ 80 / 1 %]
- -007: CPM down rate for High Temp.:2nd CPM Down
 [10 to 100/ 60 / 1 %]
- -008: CPM down rate for High Temp.:3rd CPM Down
 [10 to 100/ 40 / 1 %]
- -009: Down threshold for High Temp.:1st CPM Dow [160 to 240/ 215 / 1 deg]
- -010: Down threshold for High Temp.:2nd CPM Down [160 to 240/ 219 / 1 deg]
- -008: Down threshold for High Temp.:3rd CPM Down [160 to 240/ 222 / 1 deg]

Technical Bulletin

PAGE: 91/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

SP1201-012 to -023: CPM Down Rate for Each Mode

These SPs adjust the Low Temp.: CPM (PPM) Down rates for each paper type and machine's temperature.

Adjustable range

[0 to 3 / default: see the following table.]

0: No CPM down

1: Low Temp.: 1st CPM Down (Default: 80%) 2: Low Temp.: 2nd CPM Down (Default: 60%) 3: Low Temp.: 3rd CPM Down (Default: 40%)

Paper Type	Low Temp. inside	More than Low Temp.
	Machine	inside Machine
Plain	No Control	No Control
	(SP1201-012)	(SP1201-018)
Thin	No Control	No Control
	(SP1201-013)	(SP1201-019)
Middle Thick	No Control	No Control
	(SP1201-014)	(SP1201-020)
Thick 1	No Control	No Control
	(SP1201-015)	(SP1201-021)
Thick 2	No Control	No Control
	(SP1201-016)	(SP1201-022)
Thick 3	Mode 2	No Control
	(SP1201-017)	(SP1201-023)

Fixed Paper Interval (SP1207)

The "Fixed Paper Interval" SP is designed to prevent an image problem after the multiple printing (20 sheets or more) of a same image has been done. You can adjust the paper interval for each paper type and thickness with the following formula.

Paper interval = $460 \text{ (mm)} \times (A + B + C)$

- A: Settings for paper type and thickness (SP1207-010 to -069)
- B: Settings for paper size correction value (SP1207-100 to -104)
- C: Settings for environmental correction value (SP1207-105 to -107)

The longer paper interval is effective for some image problems. However, the machine productivity becomes lower if you set the paper interval longer. Refer to the following table about the productivity change for AG-C1/P1.

TITLE: Reference Table of Productivity Change

Paper Length Size	SP1207 Setting Value	Default CPM (PPM)	Changed CPM (PPM)	Productivity Rate
	1		39.0	43%
216 mm	2	90.4	23.2	26%
	3		16.5	18%

Technical Bulletin

PAGE: 92/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

Paper Length	SP1207	Default CPM	Changed CPM	Productivity
Size	Setting Value	(PPM)	(PPM)	Rate
	1		34.9	50%
297 mm	2	70.4	21.7	31%
	3		15.7	22%
	1		32.0	53%
364 mm	2	60.2	20.6	34%
	3		15.1	25%
	1		29.6	58%
432 mm	2	51.4	19.5	38%
	3		14.6	28%
	1		27.8	60%
488 mm	2	46.2	18.7	41%
	3		14.1	31%

Settings for Paper Type and Thickness

TITLE: Setting Table of Fixed Paper Interval: SP2701-xxx

	Thin	Plain	Middle Thick	Thick 1	Thick 2	Thick 3
Uncoated	-010	-011	-012	-013	-014	-015
Coated 1	-016	-017	-018	-019 -020		-021
Coated 2	-022	-023	-024	-025	-026	-027
Coated 3	-028	-029	-030	-031	-032	-033
Special 1	-034	-035	-036	-037	-038	-039
Special 2	-040	-041	-042	-043	-044	-045
Special 3	-046	-047	-048	-049	-040	-051
Special 4	-052	-053	-054	-055	-056	-057
Special 5	-058	-059	-060	-061	-062	-063
Special 6	-064	-065	-066	-067	-068	-069

There are 60 combinations of each paper type and thickness (6 types of thickness \times 10 types of paper type) for the "Fixed Paper Interval". These combinations can be adjusted with SP120-010 to -069.

Adjustable Range: [0 to 10 / 0 / 0.1/step]

Settings for Paper Size Correction Value

The setting for "Small Size Paper (182 < Small Size ≤ 216 mm)" can be adjusted with SP1207-100.</p>

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "Medium Size Paper (216 < Medium Size ≤ 297 mm)" can be adjusted with SP1207-101.</p>

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "Large 1 Size Paper (297 < Medium Size ≤ 364 mm)" can be adjusted with SP1207-102.</p>

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "Large 2 Size Paper (364 < Medium Size ≤ 432 mm)" can be adjusted with SP1207-103.</p>

Technical Bulletin

PAGE: 93/93

Model: Aegis-P1/C1 Date: 22-Jun-09 No.: RG178054

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "Large 3 Size Paper (432 < Medium Size ≤ 488 mm)" can be adjusted with SP1207-104.</p>

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

Settings for Environmental Correction Value

The setting for "LL condition" can be adjusted with SP1207-105.

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "MM condition" can be adjusted with SP1207-106.

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

The setting for "HH condition" can be adjusted with SP1207-107.

Adjustable Range: [-10 to 10 / **0** / 0.1/step]

◯ Note

Threshold temperature between LL condition and MM condition can be adjustable with SP1107-018.

Threshold temperature between MM condition and HH condition can be adjustable with SP1107-019.



PAGE: 1/7

☐ Tier 2


Model: Aegis-P1/C1 Dat		ie: 22-Jun-09	No.: RG178055		
Subject: Manual Corrections			Prepared by: N.iida		
Service Planning Dept.					
☐ Troubleshooting	☐ Part inf	orma	tion Actio	n required	
☐ Mechanical	☐ Electric	al	⊠ Servi	ce manual revision	
☐ Paper path	☐ Transm	iit/rec	eive 🗌 Retro	ofit information	
)	Service Planning Dept. Troubleshooting Mechanical	Service Planning Dept. Troubleshooting Part info	Service Planning Dept. Troubleshooting Part information Dechanical Electrical	Prepared by: N.i Service Planning Dept. Troubleshooting Part information Actio Mechanical Electrical Servi	

Other (

The service manual for the AG-C1 (D016) has been corrected in order to be updated and be used for both the copier model (D016) and printer model (G178).

- Add the following new or revised information which is shown in red text.
- On page 97

Prepare the Finisher for Docking



☐ Product Safety

- 1. Attach the entrance guide plate (marked "A") [A] provided with the mainframe (F x 2).
- 2. Remove the tape from the back of the sponge strip [B].
- 3. Attach the sponge strip to the top edge [C] of the finisher as shown above.




PAGE: 2/7

Model: Aegis-P1	Date:	No.:

On pages from 97 to 98

Prepare the Mainframe for Docking



- 1. Attach the docking bracket to the mainframe (F x 4: M4x8 provided with the mainframe).
- 2. Attach the ground plate provided with the mainframe to the bottom left of the mainframe $(\mathscr{F} \times 2)$.
- On page 267

Image Shift Check between the 1st and 2nd Pages



Use "T6000 (70W)", "mondi 90gsm" or "HummerMILL Color COPY 105gsm" paper to check the image quality of the printout.

Checking Procedure

To check the image shift on the output, do the following procedure.

- 1. Turn on the main power switch.
- 2. Press the "User Tool" button, and then the "Adjustment Settings for Operators" button.
- 3. For Copier D016 only, do the followings.
 - Select SP5070-001 (Switch print application).
 - Select "6:Printer", then press "OK" (default "3:Copv").
- 4. Select SP1710-001 ("Front" < "Image Pos:Sub").
- 5. Press the "APL Window" button on the top of the LCD.
- 6. Select a paper size and duplex print mode.
- 7. Press the "Print" button, and then the "OK" button to print the "Adjustment Printing" test pattern.

PAGE: 3/7

Model: Aegis-P1 Date: No.:


On page 272

The following step has been deleted.

- 7. Check the distance between the image edge and paper edge at two points [B1] and [B2] in the sub-scan direction.
 - Acceptable range: [B1] [B2] ≤ ±0.5 mm (A4 or LT SEF or more)

On page 273

The following description has been deleted.



If the two points [B₁] and [B₂] are still different, do the following procedure.

- 1. Check the gap between [B₁] and [B₂].
- 2. Enter the SP mode, and then select SP2-119-004.
- 3. Enter the gap between [B₁] and [B₂].
 - [B₁] > [B₂]: Enter a "-" value. "1" in the SP mode = 0.01 mm
 - [B₁] < [B₂]: Enter a "+" value. "1" in the SP mode = 0.01 mm
 - e.g.) If the gap ([B₁] [B₂]) is 0.1 mm, press " $^{\circ}$ " and enter "10". Note

"🏵" is the key for entering a "–" value.

- 4. Select SP2-118-004, and then press the "Execute" button.
- 5. Execute "MUSIC" with SP2-153-001.
- 6. Check the image skew again.



PAGE: 4/7

Model: Aegis-P1 Date: No.:

On pages from 274 to 291

Paper Type Adjustment

Overview

There are various types and sizes of paper in the market. Even if the correct paper type and size are selected in the operation panel, outputs may not satisfy the customer. Here is a summary for how to select the correct paper type in the field.

Paper Setting Selection


For details about this procedure, refer to the technical document issued by your technical support.

On page 470

Hot Roller Gear, Fusing Belt, Hot Roller and Heating Roller

Fusing Belt Assembly

- 1. Oil supply unit (Oil Supply Unit)
- 2. Fusing belt stripper plate (Fusing Belt Stripper Plate)
- 3. Heating roller fusing lamps (Heating Roller Fusing Lamps)



g178r883


4. Fusing knob shaft [A] on the hot roller (x 2)



Date:

PAGE: 5/7

No.:




- 5. Hold both edges [A] of the heating roller.
- After page 491, the "Fusing Knob Attachment Procedure for Printer Model (G178)" section is newly added.

Fusing Knob Attachment Procedure for Printer Model (G178)

When installing the fusing knob in the machine, the installation procedure of the fusing knob differs depending on when the machine has been produced. Check if two screw holes are on the front side of the hot roller.

For the fusing unit having screw holes on the front side of the hot roller

- 1. Replace the inner cover of the front left door with a new one.
- 2. Fusing unit (Fusing Unit)




3. Inner cover [A] for the fusing unit (x 3)

PAGE: 6/7

Model: Aegis-P1


Date:

No.:



g178r883

4. Attach the fusing knob shaft [A] to the font side of the hot roller (x 3).



5. Install the new inner cover [A] for the fusing unit (x 3).




- 6. Attach the fusing knob [A] to the fusing knob shaft (F x 1).
 - The color of the actual fusing knob is sky blue.

For the fusing unit having no screw holes on the front side of the hot roller


- 1. Replace the inner cover of the front left door with a new one.
- 2. Fusing unit (Fusing Unit)



PAGE: 7/7 Model: Aegis-P1 Date: No.:




3. Inner cover [A] for the fusing unit (F x 3)



g178r886

4. Attach the fusing knob shaft [A] to the base bracket [B] (F x 4).



g178r887

- 5. Attach the fusing knob shaft assembly [A] to the front side [B] of the hot roller (x 3).
- 6. Install the new inner cover [C] for the fusing unit (x 3).
- 7. Attach the fusing knob [D] to the fusing knob shaft (x 1).

CU	П

e: 23-Jun-09 N	lo.: RG178056


PAGE: 1/2


Model: AG-P1 / C1			Dat	e: 23-Jun	-09	No.: RG178056
Subject: Screw modification			Prepared by: N.iida			
From: PPBG QA/Service Planning Dept.						
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	☑ Part informat☐ Electrical☐ Transmit/rec☐ Other (☐ Service	n required ce manual revision fit information

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
03604008N	-	SCREW - M4X8	7→6	-	122	103	
09544008N	-	SCREW - M4X8	1→2	-	122	106	
D0164105	D0164108	FUSING UNIT:EU:ASS'Y	1	\bigcirc / \bigcirc	122	*	

Change

The screw applied for "Guide:Paper Exit Sub-unit:Upper" has been changed with a more reliable screw; not easily loosened.








Model: AG-P1 / C1 Date: 23-Jun-09 No.: RG178056

Reason

D1 of the fusing paper exit unit could fail to open as seen in figure 1. This is due to the loosened screw interfering as seen in figure 2.

Also, the loosened screw could cause the "Guide:Paper Exit Sub-unit:Upper" to dislocate, and narrow the gap of the paper feed path resulting in leaving rubbed marks on the sheets. Please re-fasten the screws or replace with "09544008N: SCREW - M4X8" when the above mentioned symptoms are found.





PAGE: 2/2

Technical Bulletin

PAGE: 1/1

Model: Aegis-P1/C1			Date: 24-Jun-09			No.: RG178057	
Subject: PCDU Coating Bar inventory request				Prepare	d by: Not	ouo iida	
From: PPBG QA/Service Planning Dept.							
Classification:	Troubleshooting	☐ Part inf	orma	tion		n required	
		☐ Electric	al		☐ Service	ce manual revision	
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	☐ Other ()	☐ Tier 2	<u> </u>	

The PCDU Coating Bar (part number G178 3731) manufactured prior to the mass production has been mistakenly distributed to the field.

Due to the incorrect shape of this part, it cannot be attached to the Cleaning Unit.

Please check the difference in shape as shown in the photo below. (The lower part is the incorrect part.)




REQUEST

Please check the spare parts in stock and dispose of the object part immediately. Please refer to the "Lot No." indicated on the parts number label for identification.

PART INFORMATION

G1783731: COATING BAR:ASS'Y

Lot No.C100408




Technical Bulletin

PAGE: 1/1

Model: Aegis-P1/C1			Dat	e: 30-Jun-	09	No.: RG178058	
Subject: Troubleshooting for White Line on Edges				Prepared by: N.iida			
From: PPBG QA/	Service Planning Dept.						
Classification:		☐ Part info	orma	tion	Action	required	
		☐ Electrication	al		☐ Service	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	\square Other ()	☐ Tier 2		

SYMPTOM



A white line appears on each edge of the paper when large size and heavy weight paper (A3 SEF or more, 200 g/m^2 or more) is used for printing or copying.

CAUSE

High bias current at the PTR for the leading and trailing edges of paper

SOLUTION

Adjust the setting of SP2426-001 to -232 within the range from 150% to 200%.

For example: SRA3, 300 gsm, Plain Mondi Color Copy paper

- 1. First input 200% with SP2426-006 and SP2426-017.
- 2. If the problem cannot be solved, decrease the settings of SP2426-006 and SP2426-017 in 10% steps.

NOTE:

The required SP numbers to be adjusted are different depending on the customer's job settings. The job setting is defined by the following conditions;

- Paper type
- Paper thickness
- Simplex or Duplex
- B/W or Full Color


Technical Bulletin

•	17102: 171					
30-Jun-09	No.: RG178059					
11						
parad by: N ::da						

PAGF: 1/1

Model: Aegis-P1/C1 Dat			e: 30-Jun-	09	No.: RG178059	
Subject: Troubles	shooting for Poor Image Trans	fer in LL		Prepared	d by: N.iid	da
From: PPBG QA/	Service Planning Dept.					
Classification:		☐ Part info	ormat	tion	☐ Action	required
		☐ Electrica	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM



Poor image transfer occurs on the outputs in LL condition (Temperature: 10°C or less, Humidity: 15% or less).

CAUSE

Insufficient bias current at the PTR in LL condition (especially for plain paper)

SOLUTION

- 1. Change the settings of SP2369-001, -002, -008 and -009 to "110%".
- 2. If the problem cannot be solved, change the settings of SP2369-001, -002, -008 and -009 to "120%".

Technical Bulletin

PAGE: 1/2

Model: Aegis-P1/C1 Dat		Date: 30-Jun-09		No.: RG178060		
Subject: Manual Correction: Skew Adjustment		Prepare	d by: N.iid	da		
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electric	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transmit/red		Transmit/receive		fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Manual Correction

The skew adjustment procedure below (blue text) has been deleted from the service manuals for AG-P1 (p.214) and C1 (p.275).

If the two points [B1] and [B2] are still different, do the following procedure.


- 1. Check the gap between [B1] and [B2].
- 2. Enter the SP mode, and then select SP2-119-004.
- 3. Enter the gap between [B1] and [B2].
 - [B1] □[B2]: Enter a "-" value. "1" in the SP mode = 0.01 mm
 - [B1] □[B2]: Enter a "+" value. "1" in the SP mode = 0.01 mm e.g.) If the gap ([B1] [B2]) is 0.1 mm, press "^(*)" and enter "10".

NOTE

- "(*)" is the key for entering a "-" value.
- 4. Select SP2-118-004, and then press the "Execute" button.
- 5. Execute "MUSIC" with SP2-153-001.
- 6. Check the image skew again.

Reason for this Correction

Image skew adjustment has been done at the factory by adjusting the skew motors in the LD units. Therefore, the image skew adjustment is not required in the field.



If paper skew [A] as shown above occurs, adjust the registration gate by moving the adjuster on the registration unit. For details, see the main service manual.

Model: Aegis-P1/C1

Technical Bulletin

Date: 30-Jun-09 No.: RG178060

PAGE: 2/2

If a parallelogram image [B] as shown above occurs, adjust the machine's level. This is because the parallelogram image [B] is caused by the inclination of the machine.

ACAUTION:

 Do not change the settings of SP2119 and SP2118 except when doing the LD unit adjustment at LD unit replacement. If the settings of SP2119 and SP2118 are changed, the original settings may not be recovered and a correct image may not be output.

☐ Product Safety

☐ Paper path

Technical Bulletin

Model: Aegis-F	P1/C1		Dat	e: 30-Jun-09	No.: RG178061
Subject:				Prepared by: N	√.iida
Multiple Test Print for Solid Color Image: TCRU/ORU			RU		
From: PPBG QA	Service Planning Dept.				
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion 🛛 Act	tion required
	☐ Mechanical	☐ Electrica	al	☐ Se	rvice manual revision

☐ Tier 2

☐ Retrofit information

PAGE: 1/3

The multiple test print (40 pages) for solid color image which is used for recovering oil gloss line problems is newly added to the function in the TCRU/ ORU mode. Refer to the following procedure to execute this test print.

Other (

☐ Transmit/receive

Note: This function is available for a machine in which an SD card (D0169501 or later) for TCRU/ORU has been installed.


Preparation

This test print function requires one of the following sizes of paper. Load paper in the paper tray.

A3, SRA3, DLT, 12"x18"

Printing the black solid image

1. For the D016 model, press the "Program" button on the operation panel. For the G178 model, press the "Printer function" button on the operation panel.




rtb55 001

2. Press the "Print" [A] button on the LCD.

Technical Bulletin


PAGE: 2/3

Model: Aegis-P1/C1 No.: RG178061 Date: 30-Jun-09



rtb55 002

3. Press the tray button [B] in which one of the correct paper sizes has been loaded.



rtb55 003

- 4. Press the "single colour BK" button [C].
 - NOTE: 1) Each color button can be used to print a solid color image. The result of this function does not differ depending on which color is selected.
 - 2) Confirm the color button carefully before pressing the color button. You cannot stop printing (20 sheets of paper is printed) once you have pressed the color button.
- 5. Printing starts automatically just after pressing the tray button.
 - Load paper in the selected tray or select another tray in step 3 if "Aborted Tray x: Paper end" is displayed on the LCD.
 - · Load the proper paper size in the selected tray or select another tray in step 3 if "Aborted Paper size not supported" is displayed on the LCD.



PAGE: 3/3

Model: Aegis-P1/C1 Date: 30-Jun-09 No.: RG178061

 Select another tray in step 3 if "Aborted Tray x: Paper end/ Paper size not supported" is displayed on the LCD. This message means that the selected tray is not available (an optional LCT is not installed).

- 6. The selected solid color image is printed on 20 sheets of paper (duplex print mode) first, and then the blue solid image is printed on 3 sheets of paper (simplex print mode).
 - The blue solid image is for checking the image quality.



7. "Completed" is displayed on the LCD after the machine has completed the test printing.

Technical Bulletin

PAGE: 1/3

Model: Aegis-P1/C1 Dat			ate: 30-Jun-09		No.: RG178062	
Subject: Standar	d procedure of the Paper Se	tting Select	ion	Prepared	d by: N.iid	da
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion		required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	☐ Other ()	☐ Tier 2	

Ricoh Japan is releasing the standard procedure of the Paper Setting Selection for AG-P1/C1 (G178/D016). This is the setting procedure which can be used by the field engineers at the customers' sites.

Paper Setting Selection

To improve fusing for each paper type and thickness, follow the "Paper Setting Selection Flow" shown below.

Paper Setting Selection Flow

- 1. Is paper which a customer is to use already evaluated by MQP?
 - Yes: Find the setting in the "Media List" issued by MQP, and then use that setting to print or copy.
 - No: Go to step 2.
- 2. Check if the paper which the customer is to use is coated paper or uncoated paper.
 - Coated paper: Use the "Coated: Special 3/ xxx" setting to print.
 - Uncoated paper: Use the "Uncoated: Special 6/ xxx" setting to print.
 - Change the SP settings referring to the "Recommended Settings Table" below. (The values with bold text in the recommended settings table must be changed from the default value.)

Note

- "xxx" means the paper thickness which the customer is to use. Select the correct paper thickness from the six paper thickness (thin, plain, middle thick, thick 1, thick 2 and thick 3).
- For details about the recommended settings for "Coated: Special 3/ xxx" and "Uncoated: Special 6/ xxx", see "Recommended Settings Table" described below.
- 3. Print a sample image.
- 4. Does a print quality problem still occur on the outputs?
 - No: Paper setting selection is successfully completed.
 - Yes: Go to step 5.
- 5. Try the countermeasures for the fusing problem (see "Fusing Problem" in the chapter "Troubleshooting" of the main manual).
- 6. Is the print quality problem solved?
 - Yes: Paper setting selection is successfully completed.
 - No: Ask your technical support.



PAGE: 2/3

Model: Aegis-P1/C1 Date: 30-Jun-09 No.: RG178062

Recommended Settings Table

Uncoated: Special 6

Thickness	Description	SP No.	NA	EU
	Temp. in Simplex and B/W	1-108-065	160 °C	160 °C
	Temp. in Simplex and FC	1-108-066	160 °C	160 °C
	Temp. in Duplex and B/W	1-108-077	160 °C	160 °C
Thin	Temp. in Duplex and FC	1-108-078	160 °C	160 °C
	Nip: Low Temp	1-905-065	510 msec	510 msec
	Nip: Over Low Temp	1-905-131	510 msec	510 msec
	Fusing Motor Speed	1-909-074	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-108-063	170°C	180 °C
	Temp. in Simplex and FC	1-108-064	170°C	180 °C
	Temp. in Duplex and B/W	1-108-075	170°C	180 °C
Plain	Temp. in Duplex and FC	1-108-076	170°C	180 °C
	Nip: Low Temp	1-905-066	510 msec	510 msec
	Nip: Over Low Temp	1-905-132	510 msec	510 msec
	Fusing Motor Speed	1-909-075	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-108-067	180 °C	185 °C
	Temp. in Simplex and FC	1-108-068	180 °C	185 °C
	Temp. in Duplex and B/W	1-108-079	180 °C	185 °C
Middle Thick	Temp. in Duplex and FC	1-108-080	180 °C	185 °C
	Nip: Low Temp	1-905-067	330 msec	330 msec
	Nip: Over Low Temp	1-905-133	330 msec	330 msec
	Fusing Motor Speed	1-909-076	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-108-069	190 °C	190°C
	Temp. in Simplex and FC	1-108-070	190 °C	190°C
	Temp. in Duplex and B/W	1-108-081	190 °C	190°C
Thick 1	Temp. in Duplex and FC	1-108-082 190 °C		190°C
	Nip: Low Temp	1-905-068	330 msec	330 msec
	Nip: Over Low Temp	1-905-134	330 msec	330 msec
	Fusing Motor Speed	1-909-077	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-108-071	195 °C	195 °C
	Temp. in Simplex and FC	1-108-072	195 °C	195 °C
	Temp. in Duplex and B/W	1-108-083	195 °C	195 °C
Thick 2	Temp. in Duplex and FC	1-108-084	195 °C	195 °C
	Nip: Low Temp	1-905-069	40 msec	40 msec
	Nip: Over Low Temp	1-905-135	40 msec	40 msec
	Fusing Motor Speed	1-909-078	-2.0%	-2.0%
	Temp. in Simplex and B/W	1-108-073	200°C	200°C
	Temp. in Simplex and FC	1-108-074	200°C	200°C
Thick 3	Nip: Low Temp	1-905-070	40 msec	40 msec
	Nip: Over Low Temp	1-905-136	40 msec	40 msec
	Fusing Motor Speed	1-909-079	-2.0%	-2.0%

PAGE: 3/3

Model: Aegis-P1/C1 Date: 30-Jun-09 No.: RG178062

Coated: Special 3

Thickness	Description	SP No.	NA	EU
	Temp. in Simplex and B/W	1-105-210	160 °C	160 °C
	Temp. in Simplex and FC	1-105-211	160 °C	160 °C
	Temp. in Duplex and B/W	1-105-222	160 °C	160 °C
Thin	Temp. in Duplex and FC	1-105-223	160 °C	160 °C
	Nip: Low Temp	1-905-047	510 msec	510 msec
	Nip: Over Low Temp	1-905-113	510 msec	510 msec
	Fusing Motor Speed	1-909-056	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-105-208	180 °C	180°C
	Temp. in Simplex and FC	1-105-209	180 °C	180°C
	Temp. in Duplex and B/W	1-105-220	180 °C	180°C
Plain	Temp. in Duplex and FC	1-105-221	180 °C	180°C
	Nip: Low Temp	1-905-048	510 msec	510 msec
	Nip: Over Low Temp	1-905-114	510 msec	510 msec
	Fusing Motor Speed	1-909-057	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-105-212	180 °C	185 °C
	Temp. in Simplex and FC	1-105-213	180 °C	185 °C
	Temp. in Duplex and B/W	1-105-224	180 °C	185 °C
Middle Thick	Temp. in Duplex and FC	1-105-225	180 °C	185 °C
	Nip: Low Temp	1-905-049	330 msec	330 msec
	Nip: Over Low Temp	1-905-115	330 msec	330 msec
	Fusing Motor Speed	1-909-058	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-105-214	195 °C	195 °C
	Temp. in Simplex and FC	1-105-215	195 °C	195 °C
	Temp. in Duplex and B/W	1-105-226	195 °C	195 °C
Thick 1	Temp. in Duplex and FC	1-105-227	195 °C	195 °C
	Nip: Low Temp	1-905-050	330 msec	330 msec
	Nip: Over Low Temp	1-905-116	330 msec	330 msec
	Fusing Motor Speed	1-909-059	-3.0%	-3.0%
	Temp. in Simplex and B/W	1-105-216	200°C	200°C
	Temp. in Simplex and FC	1-105-217	200°C	200°C
	Temp. in Duplex and B/W	1-105-228	200°C	200°C
Thick 2	Temp. in Duplex and FC	1-105-229	200°C	200°C
	Nip: Low Temp	1-905-051	40 msec	40 msec
	Nip: Over Low Temp	1-905-117	40 msec	40 msec
	Fusing Motor Speed	1-909-060	-2.0%	-2.0%
	Temp. in Simplex and B/W	1-105-218	200°C	200°C
	Temp. in Simplex and FC	1-105-219	200°C	200°C
Thick 3	Nip: Low Temp	1-905-052	40 msec	40 msec
	Nip: Over Low Temp	1-905-118	40 msec	40 msec
	Fusing Motor Speed	1-909-061	-2.0%	-2.0%

Technical Bulletin

PAGE: 1/1

Model: AG-P1 (G	G178)/ C1 (D016)		Dat	e: 13-Jul-0	9	No.: RG178063
Subject: Important Point for Drum Unit Installation				Prepared	d by: N.iid	da
From: PPBG QA/	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electrica	al		Service Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

The gap between the drum and development roller is precisely adjusted at the factory. However, this gap may be uneven if the drum unit is not correctly installed in the PCDU drawer after installing or replacing the drum unit. The uneven gap between the drum and the development roller may cause some image problems (white spots, uneven toner density, toner blocking in strips on the development roller and so on). Follow the important point for the drum unit installation as described below.

Important Point



• Rotate the drum lock nut [A] clockwise until the drum lock nut [A] stops and does not rotate any more, when installing or replacing the drum unit.


Technical Bulletin

PAGE: 1/1

Model: AG-P1 (G178)/ C1 (D016) Date			ate: 13-Jul-09		No.: RG178064	
Installation			Prepare	d by: N.iid	da	
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part informa		tion	☐ Action	required
	☐ Mechanical	☐ Electrical			⊠ Servic	e manual revision
	☐ Paper path	☐ Transmit/red		eive	☐ Retrof	it information
	☐ Product Safety	Other ()	⊠ Tier 2	

If the development unit with developer is removed, and then reinstalled in the main machine, the developer in the development unit may be uneven. This may cause image problems. Follow the action for development unit installation as described below, after maintaining the development unit.

Required Action



1. Reinstall the development unit [A] in the PCDU drawer after maintaining the development unit.



2. Turn the coupling gear [B] on the rear side of the development unit counterclockwise ten rotations or more as shown above. (This agitates the developer in the development unit, and then the developer becomes evenly distributed.)

Technical Bulletin

PAGE: 1/7

Reissued: 01-Nov-11

Model: Ad 1 1/01, AdE 1 1/01, Alies 1 1.5/01.5	Model: AG-P1/C1,AGL-P1/C1,Aries-P1.5/C1.5	Date: 03-Aug-09	No.: RG178065c
--	---	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: BufferPassUnit			Prepared by: H.Kawamura		
From: PP Tech Service Dept., 1st PP Tech Service Sect.					
Classification:	Troubleshooting	☐ Part informat	tion	Action required	
		☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the firmware release information for the **BufferPassUnit**.

Version	Program No.	Effective Date
03.000:06	M3791702D	November 2011 Production
02.030:05	M3791702C	October 2010 production
02.010 :05	M3791702B	May 2010 production
01.000:03	M3791702A	1st Mass production

Version	Modified Points or Symptoms Corrected		
03.000:06	 Modified Points: Countermeasure for cannot recover from failure of updating the firmware If the firmware update from SD card failed, such as power off, buffer pass did not start properly, and could not reupdate, and could not fix by replacing the board. This issue was fixed. Countermeasure for updating the firmware for downstream peripherals There was a possibility that the firmware of down stream peripherals could not update properly. So far this issue was not reported from Pro C900/ 900S/ 901/ 901S/ 720/ 720S. In order to prevent the above issue, a measure was implemented in this firmware. 		
02.030:05	Modified Points: ON and OFF signal of the Fore Edge Cut setting specified for 2 separate jobs are not switched between the jobs when the Trimmer Unit TR5020 is selected as the finishing peripheral due to the data transmission failure in the Buffer Pass Unit. For instance, the fore edge of the 2 nd job below will be falsely trimmed when running these jobs continuously. Ex. 1 st Job: Fore Edge Cut ON 2 nd Job: Fore Edge Cut OFF		
02.010 :05	* "Low Speed Mode" for the Aries-1.5 has been supported. * Lag in network communication while downloading a firmware for a		

PAGE: 2/7

Reissued: 01-Nov-11

Model: AG-P1/C1,AGL-P1/C1,Aries-P1.5/C1.5		Date: 03-Aug-09	No.: RG178065	
Version	Modified Points or Symptoms Corrected			
	downstream peripheral causes an error. * Jam occurs at the Stacker (SK5000 or SK5010) when sheets are fed alternately from the Cover Interposer and the Mainframe tray to the Stacker (SK5000 or SK5010).			
01.000:03	The limitations listed below are resolved by upgrading the Buffer Pass Unit to "V1.000:03". Object units are April and May production. In order to upgrade the object units to "V1.000:03", System and Engine fimwares must be versions listed below or later. System G1786091G V2.05 or later Engine G1785252D V3.000:12 or later [Limitations Resolved] All SCs involving the Buffer Pass unit are indicated as SC992 (Undefined			
	error). When the front door of the Buffer Pass indicates an open door of the mainfrar unit is lit.			
	Jam in the Buffer Pass unit is indicated on the operation panel as a jan occurrence at the paper exit of the mainframe, and the LED of the Buff Pass unit is lit. Firmware cannot be upgraded with the SD card.			
	[Object Serial Number] 8M37917(NA) S67T0400001 to S S67T0500001 to S			
	8M37927(EU/AP) S67T0400006, S6	7T0500005 to S67T050	00011	
	In Regard to April & May Production Buffer Pass Units Upon initial installation, upgrade the entire System to V 4.0(*1), then upgrade the Buffer Pass unit to "V1.000:03". If the Buffer Pass unit is to be installed to a System that runs on V4.0(*1), upgrade the unit to "V1.000:03". If an individually supported Engine firmware is applied, we recommend to upgrade the entire System to V4.0(*1), then upgrading the Buffer Pass Unit to "V1.000:03".			
	NOTE "V1.1000:03" is installed for June 2009 production Buffer Pass units (S6790600001 onward). If the unit is to be installed with the Aegis-P1, the System and Engine fimrwares must be the versions listed below or later. System G1786091G V2.05 or later Engine G1785252D V3.000:12 or later			
	Following describes the latest firmware combinations.			
	Please refer to <appendix 1=""> for update procedures.</appendix>			



PAGE: 3/7

Reissued: 01-Nov-11

Model: AG-P1	/C1,AGL-P1/C1,Aries-P1.5/C1	.5	Date: 03-Aug-0	9	No.: RG178065c
Version	Modified Points or Symptoms Corrected				
	Ensure to follow the procedures when updating.				
	[Version 4.0(*1)]				
	*Please make sure that AL	L versions lis	ted below are upo	dated co	ncurrently.
	Program Name	Program		Version	
	System	G178609		2.05	
	Websystem	G178609	3E	1.53	
	Network Support(NCS)	G178609		7.04	
	Engine	G178525		3.000:1	2
	LCDC	NA:G178		1.03	
		EU:G178			
	Animation	G178609		2.2	
	Language	G178597	9A	1.03	
	Fiery Server	<u> </u>		4.0	
	* Update to the following ve				
	015040	Program N		Version	
	CI5010	B8355510		V2.071	
	SR5000	B8305102		V1.820 V1.290	
	RB5000	Main:D392 Sub: D392		V1.290	-
	GB5000	3ub. D392	200200	V 1.00C	7.01
	P-Binder B1	D3915020	nC.	V0.28	
	P-Binder B2	D3915070		V0.20	
	P-Binder B3	D3915730		V0.13	
	P-Binder B4	D3915120		V0.15	
	P-Binder B5	D3915170		V0.25	
	BK5000	B8365550	В	V2.17:	15
	SK5000				
	1 st stacker	D3645620)_P1	V4.02:	12
	2 nd stacker	D3645620			
	Buffer Pass Unit	M3791702	2A	V1.000):03
	Type 5000				
	Note				
	Make sure to update the peripherals in order of proximity to the main				o the main
	frame.	untinalis bis	Jostina cavaral -	orinh o	
	Do not update consec				d15.
	For GB5000, 5 boards For RB5000, 2 boards				
	FUI NESUUU, 2 DUAIUS	can be upo	aleu conseculive	ıy.	



PAGE: 4/7

Reissued: 01-Nov-11

Model: AG-P1/C1,AGL-P1/C1,Aries-P1.5/C1.5 Date: 03-Aug-09 No.: RG178065c

<Appendix 1>

Please ensure to follow the procedures for the update.

The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware.

NOTE:


Do not do remote-update.

If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.

When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required.

When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 5/7

Reissued: 01-Nov-11

Model: AG-P1/C1,AGL-P1/C1,Aries-P1.5/C1.5	Date: 03-Aug-09	No.: RG178065c
---	-----------------	----------------

[Advance Preparation]

Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.

Unplug the LAN cable of the GW controller.

Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

1 of Alogio of		
Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version
System/Copy	G1786091G	V2.05
WebSys	G1786093E	V1.53
NCS	G1786092D	V7.04

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

1 01 7 togic 0 1			
Program name	Program No.	Version	
Engine	D0165252D	V3.000:12	

For Aegis-P1

Program name	Program No.	Version
Engine	G1785252G	V3.000:12

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

Technical Bulletin

PAGE: 6/7

Reissued: 01-Nov-11

Model: AG-P1/C1,AGL-P1/C1,Aries-P1.5/C1.5	Date: 03-Aug-09	No.: RG178065c
---	-----------------	----------------

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

1 01 7 togic 1 1			
Program name	Program No.	Version	
Animation	G1786094B	V2.2	

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

1 01 7 togic 0 1			
Program name	Program No.	Version	
Language	G1785980A	V1.06	•

For Aegis-P1

<u> </u>			
Program name	Program No.	Version	
Language	G1785979A	V1.03	

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

Technical Bulletin

PAGE: 7/7

Reissued: 01-Nov-11

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 03-Aug-09 No.: RG178065c

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

Make sure to update the peripherals in order of proximity to the main frame.

Do not update consecutively by selecting several peripherals.

For GB5000, 5 boards can be updated consecutively.

For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main: D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed.
- Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.

Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

PAGE: 1/2


Model: Aegis-F	Dat	e: 24-Jul-(09	No.: RG178066		
Subject: Manua C1	۱G-	Prepare	d by: N.iid	da		
From: PPBG QA	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
☐ Mechanical ☐ Electrical		al		Service Service	e manual revision	
☐ Paper path ☐ Transmit/red			eive	☐ Retrof	it information	
	☐ Product Safety	Other ()	☐ Tier 2	

The red text in the "ITB Bias Roller" replacement procedure below is newly added to the service manual of the AG-C1.


On pages 423 and 424

ITB Bias Roller

1. Image transfer belt (Image Transfer Belt)



2. Bias terminal unit [A] (x 2)




g178r132

3. ITB bias roller [B]

Technical Bulletin

Model: Aegis-P1 (G178)/ C1 (D016) Date: 24-Jul-09 No.: RG178066

PAGE: 2/2



4. Remove the terminal [C] from the ITB bias roller.

★ Important

Attach the terminal [C] to the new ITB bias roller when installing a new ITB roller. Otherwise, SC450 may be issued.

CAUTION

- This terminal [C] is easily broken because the terminal [C] is made of carbon. Never make an impact on the terminal.
- If the terminal is cracked or broken, replace it with a new one.

Technical Bulletin

PAGE: 1/25

Model: Aegis-P1(G178)/C1(D016)				e: 24-Jul-0)9	No.: RG178067
Subject: Manual Corrections for AG-P1/C1 SC and SP Tables				Prepared	d by: N.iid	da
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electric	al		Service Service	e manual revision
☐ Paper path ☐ Transmit/re			it/rec	eive	☐ Retrof	it information
	☐ Product Safety	☐ Other ()	☐ Tier 2	

The Service Manual for AG-P1/C1 was corrected as follows:

• On pages from 687 to 689

SC Number	Wrong SC Title	Correct SC Title
SC361	Low toner density error: M	Low toner density error: C
SC362	Low toner density error: C	Low toner density error: M
SC365	High toner density error: M	High toner density error: C
SC366	High toner density error: C	High toner density error: M
SC373	TD sensor adjustment error: M	TD sensor adjustment error: C
SC374	TD sensor adjustment error: C	TD sensor adjustment error: M
SC389	Quenching error: M	Quenching error: C
SC390	Quenching error: C	Quenching error: M

• On pages 702 and 703

SC Number	Wrong SC Title	Correct SC Title
SC458-004	Image Transfer Roller End: C	Image Transfer Roller End: M
	(MM)	(MM)
SC458-005	Image Transfer Roller End: C	Image Transfer Roller End: M
	(MH)	(MH)
SC458-006	Image Transfer Roller End: C	Image Transfer Roller End: M
	(HH)	(HH)

• On pages from 1492 to 1531

5803 50	RCB-eIO1-PORTB		Read	ding
			0	1
	Bit 0 Bit 7	PTR Motor Flag	Off	On
	Bit 1 Bit 6	Duplex Transport Motor 2 Flag	Off	On
	Bit 2 Bit 5	PTR Timing Motor Flag	Off	On
	Bit 3 Bit 4	Shift Roller Unit Motor Flag	Off	On
	Bit 4 Bit 3	PTR Timing Motor Flag	Off	On
	Bit 5 Bit 2	Registration Timing Motor Flag	Off	On
	Bit 6 Bit 1	Registration Entrance Motor	Off	On
		Flag		

PAGE: 2/25

 Model: Aegis-P1(G178)/C1(D016)
 Date: 24-Jul-09
 No.: RG178067

 Bit 7-Bit 0
 Registration Gate Motor Flag
 Off
 On

5803 51	RCB-eIO1-PORTL		Rea	ding
				1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3	PTR Lift Sensor	Off	On
	Bit 5 Bit 2	CIS Fan Alarm	Off	On
	Bit 6 Bit 1	Separation HV Alarm	Off	On
	Bit 7 Bit 0		-	-

5803 52	RCB-H8-PORT7	Rea	ding
		0	1
	Bit 0 Bit 7	-	-
	Bit 1 Bit 6	-	-
	Bit 2 Bit 5	-	-
	Bit 3 Bit 4	-	-
	Bit 4 Bit 3	-	-
	Bit 5 Bit 2 24VINTA2	Off	On
	Bit 6-Bit 1 24V_2BINT	Off	On
	Bit 7 Bit 0 24VINTA1	Off	On

5803 101	101 Mst elo1-PortC		Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		_	-
	Bit 3 Bit 4		_	-
	Bit 4 Bit 3	Development Fan Y Alarm	Off	On
	Bit 5 Bit 2	Development Fan M Alarm	Off	On
	Bit 6 Bit 1	Development Fan C Alarm	Off	On
	Bit 7 Bit 0	Development Fan K Alarm	Off	On

5803 102	Mst elo1-PortD		Read	ding
			0	1
	Bit 0 Bit 7	Ozone Fan-Y Alarm	Off	On
	Bit 1 Bit 6	Ozone Fan-M Alarm	Off	On
	Bit 2 Bit 5	Ozone Fan-C Alarm	Off	On
	Bit 3 Bit 4	Ozone Fan-K Alarm	Off	On
	Bit 4 Bit 3	Controller Fan1 Alarm	Off	On
	Bit 5 Bit 2	Controller Fan2 Alarm	Off	On
	Bit 6 Bit 1	Controller Fan3 Alarm	Off	On
	Bit 7 Bit 0	Controller Fan4 Alarm	Off	On

PAGE: 3/25

Model: Aegis-P1(G178)/C1(D016) Date: 24-Jul-09 No.: RG178067

5803 103	Mst elo1-PortE		Rea	ding
			0	1
	Bit 0 Bit 7	PSU Fan 1 Alarm	Off	On
	Bit 1 Bit 6	PSU Fan 2 Alarm	Off	On
	Bit 2 Bit 5	PSU Fan 3 Alarm	Off	On
	Bit 3 Bit 4	PSU Fan 4 Alarm	Off	On
	Bit 4 Bit 3	PSU Fan 5 Alarm	Off	On
	Bit 5 Bit 2	YM Laser Unit Fan	Off	On
	Bit 6 Bit 1	CK Laser Unit Fan	Off	On
	Bit 7 Bit 0	Registration Drawer Set Detection	Off	On

5803 104	Mst elo2-PortA		Reading	
			0	1
	Bit 0 Bit 7	Charge Cleaning Unit HP Sensor Y	Off	On
	Bit 1 Bit 6	Charge Cleaning Unit HP Sensor M	Off	On
	Bit 2 Bit 5	Charge Cleaning Unit HP Sensor C	Off	On
	Bit 3 Bit 4	Charge Cleaning Unit HP Sensor K	Off	On
	Bit 4 Bit 3	Registration Entrance Sensor	Off	On
	Bit 5 Bit 2	LCT Entrance Sensor	Off	On
	Bit 6 Bit 1	Duplex Transport Sensor 3	Off	On
	Bit 7 Bit 0	Duplex Transport Sensor 4	Off	On

5803 105	Mst elo2-PortD		Read	ding
			0	1
	Bit 0 Bit 7	Drum Cleaning Unit Set Sensor Y	Off	On
	Bit 1 Bit 6	Drum Cleaning Unit Set Sensor M	Off	On
	Bit 2 Bit 5	Drum Cleaning Unit Set Sensor C	Off	On
	Bit 3 Bit 4	Drum Cleaning Unit Set Sensor K	Off	On
	Bit 4 Bit 3	Drum Cleaning Motor Y	Off	On
	Bit 5 Bit 2	Drum Cleaning Motor M	Off	On
	Bit 6 Bit 1	Drum Cleaning Motor C	Off	On
	Bit 7 Bit 0	Drum Cleaning Motor K	Off	On

5803 106	Mst elo2-PortF		Reading	
			0	1
	Bit 0 Bit 7	Shift Roller HP Sensor	Off	On
	Bit 1 Bit 6	Registration Gate Lift Sensor	Off	On

PAGE: 4/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067	
	Bit 2 Bit 5	Registration Timing Sen	sor	Off	On
	Bit 3 Bit 4			-	-
	Bit 4 Bit 3			-	-
	Bit 5 Bit 2			-	-
	Bit 6 Bit 1			-	-
	Bit 7 Bit 0			-	-

5803 107	Mst elo2-PortL		Reading	
			0	1
	Bit 0 Bit 7	Toner End Sensor Y	Off	On
	Bit 1 Bit 6	Toner End Sensor M	Off	On
	Bit 2 Bit 5	Toner End Sensor C	Off	On
	Bit 3 Bit 4	Toner End Sensor K	Off	On
	Bit 4 Bit 3	Not used	-	-
	Bit 5 Bit 2	Not used	-	-
	Bit 6 Bit 1	Not used	-	-
	Bit 7 Bit 0	Not used	-	-

5803 108	Mst elo3-Port	Mst elo3-PortA		ding
			0	1
	Bit 0 Bit 7	Development Roller Rotation Sensor Y	Off	On
	Bit 1 Bit 6	Development Unit Y Set Detection	Off	On
	Bit 2 Bit 5	Development Unit Y Color Detection: Bit0	Off	On
	Bit 3 Bit 4	Development Unit Y Color Detection: Bit1	Off	On
	Bit 4 Bit 3	Development Roller Rotation Sensor M	Off	On
	Bit 5 Bit 2	Development Unit M Set Detection	Off	On
	Bit 6 Bit 1	Development Unit M Color Detection: Bit0	Off	On
	Bit 7-Bit 0	Development Unit M Color Detection: Bit1	Off	On

5803 109	Mst elo3-PortB		Reading	
				1
	Bit 0 Bit 7	Development Roller Rotation Sensor C	Off	On
	Bit 1 Bit 6	Development Unit C Set Detection	Off	On
	Bit 2 Bit 5	Development Unit C Color Detection: Bit0	Off	On
	Bit 3 Bit 4	Development Unit C Color Detection: Bit1	Off	On

PAGE: 5/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067	
	Bit 4 Bit 3	Development Roller Rot Sensor K	ation	Off	On
	Bit 5 Bit 2	Development Unit K Set Detection		Off	On
	Bit 6-Bit 1	Development Unit K Col Detection: Bit0	or	Off	On
	Bit 7 Bit 0	Development Unit K Col Detection: Bit1	or	Off	On

5803 110	Mst elo3-Port	D	Read	ding
			0	1
	Bit 0 Bit 7	Development Motor Y	Off	On
	Bit 1 Bit 6	Development Motor M	Off	On
	Bit 2 Bit 5	Development Motor C	Off	On
	Bit 3 Bit 4	Development Motor K	Off	On
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1	Waste Toner Transport Motor	Off	On
		1		
	Bit 7 Bit 0	Toner Supply Motor	Off	On

5803 111	Mst elo4-PortB		Reading	
			0	1
	Bit 0 Bit 7	Y Charge HV Alarm	Off	On
	Bit 1 Bit 6	Y Grid HV Alarm	Off	On
	Bit 2 Bit 5	Y Bias HV Alarm	Off	On
	Bit 3 Bit 4	M Charge HV Alarm	Off	On
	Bit 4 Bit 3	M Grid HV Alarm	Off	On
	Bit 5 Bit 2	M Bias HV Alarm	Off	On
	Bit 6 Bit 1	Toner Bottle Motor Y Error	Off	On
	Bit 7 Bit 0	Toner Bottle Motor M Error	Off	On

5803 112	Mst elo4-PortC		Reading	
			0	1
	Bit 0 Bit 7	C Charge HV Alarm	Off	On
	Bit 1 Bit 6	C Grid HV Alarm	Off	On
	Bit 2 Bit 5	C Bias HV Alarm	Off	On
	Bit 3 Bit 4	K Charge HV Alarm	Off	On
	Bit 4 Bit 3	K Grid HV Alarm	Off	On
	Bit 5 Bit 2	K Bias HV Alarm	Off	On
	Bit 6 Bit 1	Toner Bottle Motor C Error	Off	On
	Bit 7 Bit 0	Toner Bottle Motor K Error	Off	On

5803 113	Mst elo4-PortE	Rea	Reading	
		0	1	
	Bit 0 Bit 7	-	-	

Technical **B**ulletin

PAGE: 6/25

Model: Aegis-P1(G178)/C1(D016)		Date: 24-Jul-09		No.: RG178067	
Bit 1 Bit 6			-	-	
Bit 2 Bit 5			-	-	
Bit 3 Bit 4			-	-	
Bit 4 Bit 3	Toner Hopper Door Swit	ch	Off	On	
Bit 5 Bit 2			-	-	
Bit 6 Bit 1	Key Card Set Detection		Off	On	
Bit 7 Bit 0	Key Counter Set Detecti	on	Off	On	

5803 114	Mst elo2-PortM		Reading		
			0	1	
	Bit 0 Bit 7		-	-	
	Bit 1 Bit 6		-	-	
	Bit 2 Bit 5		-	-	
	Bit 3 Bit 4	Development CK Fan	Off	On	
	Bit 4 Bit 3	Registration Fan	Off	On	
	Bit 5 Bit 2		-	-	
	Bit 6 Bit 1		-	-	
	Bit 7 Bit 0		-	_	

5803 115	Mst elo3-PortE		Read	ding
			0	1
	Bit 0 Bit 7	+24V_2AINT	Off	On
	Bit 1 Bit 6	+24V_2BINT	Off	On
	Bit 2 Bit 5	+24V_1AINT	Off	On
	Bit 3 Bit 4	+24V_4A	Off	On
	Bit 4 Bit 3	+24V_4B	Off	On
	Bit 5 Bit 2	+24VINTA	Off	On
	Bit 6 Bit 1	TSNS_VCC	Off	On
	Bit 7 Bit 0		_	-

5803 116	16 Mst elo1-PortF		Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6	Not used	-	-
	Bit 2 Bit 5	Not used	-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		_	-
	Bit 7 Bit 0		_	-

5803 117	17 Mst elo1-PortP		Reading		
			0	1	
	Bit 0 Bit 7		-	-	
	Bit 1 Bit 6		-	-	
	Bit 2 Bit 5		-	-	

PAGE: 7/25

Model: Aegis-P1(G178)/C1(D016)		Date: 24-Jul-09		No.: RG178067
Bit 3 Bit 4			-	-
Bit 4 Bit 3			-	-
Bit 5 Bit 2	Fusing Exhaust Fan 1		Off	On
Bit 6-Bit 1	Fusing Exhaust Fan 2		Off	On
Rit 7 Rit 0	Fusing Exhaust Fan 3		Off	On

5803 118	Mst elo5-PortL		Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6	Waste Toner Bottle Full SensorNot used	Off	On
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	-

5803 119	Mst elo5-PortM		Mst elo5-PortM Reading		ding
			0	1	
	Bit 0 Bit 7		-	-	
	Bit 1 Bit 6		-	-	
	Bit 2 Bit 5	PTB Cooling Fan	Off	On	
	Bit 3 Bit 4		-	-	
	Bit 4 Bit 3		-	-	
	Bit 5 Bit 2		-	-	
	Bit 6 Bit 1	Waste Toner Bottle Near-Full	Off	On	
		Sensor			
	Bit 7 Bit 0		_	_	

5803 120	Mst elo5-PortB		Reading	
			0	1
	Bit 0 Bit 7	Fusing Fan 1	Off	On
	Bit 1 Bit 6	Fusing Fan 2	Off	On
	Bit 2 Bit 5	Fusing Fan 3	Off	On
	Bit 3 Bit 4	Fusing Fan 4	Off	On
	Bit 4 Bit 3	Fusing Fan 5	Off	On
	Bit 5 Bit 2	Fusing Fan 6	Off	On
	Bit 6 Bit 1	PTB FAN 1	Off	On
	Bit 7 Bit 0	PTB FAN 2	Off	On

5803 121	Mst elo5-PortC		Read	ding
			0	1
	Bit 0 Bit 7	Paper Cooling Fan 3	Off	On
	Bit 1 Bit 6	Paper Cooling Fan 1	Off	On
	Bit 2 Bit 5	Paper Cooling Fan 2	Off	On

RICOH Technical Bulletin

RICOH		T echnical B ulletin			n		PAGE: 8/25
Model: Aegis-P1(0	G178)/C1	(D016)		Date: 2	4-Jul-09	No.:	RG178067
Bit 3	Bit 4	B FAN			Off		On
Bit 4	Bit 3	xit Fan			Off		On
Bit 5	Bit 2				Off		On
Bit 6	Bit 1				Off		On
Bit 7	Bit 0 P	TB FAN 2			Off		On

5803 122	Mst elo5-PortD		Reading	
			0	1
	Bit 0 Bit 7	Not used	-	-
	Bit 1 Bit 6	Waste Toner Bottle Set Sensor	Off	On
	Bit 2 Bit 5	Decurler Unit HP Sensor	Off	On
	Bit 3 Bit 4	Decurler Unit Limit Sensor	Off	On
	Bit 4 Bit 3	Paper Exit Sensor	Off	On
	Bit 5 Bit 2	Switchback Lower Sensor	Off	On
	Bit 6 Bit 1	Exit Junction Timing Sensor	Off	On
	Bit 7 Bit 0	Switchback Sensor	Off	On

5803 123	Mst elo5-PortE		Read	ding
			0	1
	Bit 0 Bit 7	Duplex Transport Sensor 1	Off	On
	Bit 1 Bit 6	Duplex Transport Sensor 2	Off	On
	Bit 2 Bit 5	Inverter/ Paper Exit Drawer	Off	On
		Set Detection		
	Bit 3 Bit 4	Accordion Jam Sensor	Off	On
	Bit 4 Bit 3	Pressure Roller Lift Sensor	Off	On
	Bit 5 Bit 2	Oil End Sensor	Off	On
	Bit 6 Bit 1	Web End Sensor	Off	On
	Bit 7 Bit 0	+24V Power	Off	On

5803 124	Mst elo5-PortF		Reading	
			0	1
	Bit 0 Bit 7	+24VINT Power	Off	On
	Bit 1 Bit 6	Waste Toner Transport Motor	Off	On
		2 Sensor		
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	-

5803 125	Mst elo5-PortJ		Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5	Fusing Exit Sensor	Off	On

PAGE: 9/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067	
	Bit 3 Bit 4	PTB Jam Sensor		Off	On
	Bit 4 Bit 3			-	-
	Bit 5 Bit 2			-	-
	Bit 6 Bit 1			-	-
	Bit 7 Bit 0			-	_

5803 126	Mst elo5-PortP		Read	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5	Waste Toner Transport Motor 2	Off	On
	Bit 3 Bit 4	Paper Exit Motor Overload Signal	Off	On
	Bit 4 Bit 3	Fusing Unit Drawer Set Detection	Off	On
	Bit 5 Bit 2	Fusing Motor Overload Signal	Off	On
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	-

5803 127	Mst elo6-PortE		Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4	PTR HV Alarm	Off	On
	Bit 4 Bit 3	K ITB Roller HV Alarm	Off	On
	Bit 5 Bit 2	C ITB Roller HV Alarm	Off	On
	Bit 6 Bit 1	M ITB Roller HV Alarm	Off	On
	Bit 7 Bit 0	Y ITB Roller HV Alarm	Off	On

5803 128	Mst elo6-PortF		Reading	
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6	Front Left Door Open Switch	Off	On
	Bit 2 Bit 5	Inverter Motor Fan	Off	On
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	_

5803 129	Mst elo6-PortJ		Reading	
			0	1
	Bit 0 Bit 7		-	-

PAGE: 10/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067
Bit 1 Bit 6			-	-
Bit 2 Bit 5	Not used		-	-
Bit 3 Bit 4	Front Door Open Detect	ion	Off	On
Bit 4 Bit 3			-	-
Bit 5 Bit 2			-	-
Bit 6 Bit 1			-	-
Bit 7 Bit 0			-	-

5803 130	Mst elo3-Portl	_	Read	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5	+24V_EA1CH2INT	Off	On
	Bit 3 Bit 4	+24V_EA2CH4	Off	On
	Bit 4 Bit 3	+24V_EA1CH1INT	Off	On
	Bit 5 Bit 2	+24VINT	Off	On
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	_

5803 131	Mst elo4-PortA		Mst elo4-PortA Reading		ding
			0	1	
	Bit 0 Bit 7	Drum Motor Y Flag	Off	On	
	Bit 1 Bit 6	Drum Motor M Flag	Off	On	
	Bit 2 Bit 5	Drum Motor C Flag	Off	On	
	Bit 3 Bit 4	Drum Motor K Flag	Off	On	
	Bit 4 Bit 3	Charge Cleaning Motor Y Flag	Off	On	
	Bit 5 Bit 2	Charge Cleaning Motor M Flag	Off	On	
	Bit 6 Bit 1	Charge Cleaning Motor C Flag	Off	On	
	Bit 7 Bit 0	Charge Cleaning Motor K Flag	Off	On	

5803 132	Mst elo5-Port/	4	Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1	Oil Pump Alarm	Off	On
	Bit 7 Bit 0	Oil Supply Unit Sensor	Off	On

5803 133	3 133 Mst elo6-PortA		Read	Reading		
			0	1		
	Bit 0 Bit 7	+24V_3A	Off	On		
	Bit 1 Bit 6	+24V_3B	Off	On		
	Bit 2 Bit 5	+24V_3C	Off	On		

Technical **B**ulletin

PAGE: 11/25

Model: Aegis-P1(G178)/C1(D016)	Date: 24-	-Jul-09 N	o.: RG178067
Bit 3 Bit 4		-	-
Bit 4 Bit 3		-	-
Bit 5 Bit 2		-	-
Bit 6-Bit 1		-	-
Bit 7 Bit 0		-	-

5803 134	Mst elo6-PortB		Re	eading
			0	1
	Bit 0 Bit 7	+24VINT	Off	On
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	-

5803 135	Mst elo6-Port	C	Reading	
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6-Bit 1	Mechanical Counter 2 Set Detection	Off	On
	Bit 7 Bit 0	Mechanical Counter 1 Set Detection	Off	On

5803 136	5803 136 Mst elo6-PortD		Read	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3		-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1	PTB Motor Flag	Off	On
	Bit 7 Bit 0		-	-

5803 137	303 137 Mst elo6-PortL		Reading	
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6	FIB Boost Converter 3 Error	Off	On
	Bit 2 Bit 5		-	-

Technical Bulletin

PAGE: 12/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067
Bit 3 Bit	4		-	-
Bit 4 Bit	3 FIB Boost Converte	FIB Boost Converter 1 Error		On
Bit 5 Bit	2		-	-
Bit 6 Bit	1 FIB Boost Converte	FIB Boost Converter 2 Error		On
Bit 7 Bit	0		-	-

5803 138	Mst elo6-PortN	Л	Rea	ding
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6		-	-
	Bit 2 Bit 5	Inverter Motor Flag	Off	On
	Bit 3 Bit 4		-	-
	Bit 4 Bit 3	Not used	-	-
	Bit 5 Bit 2		-	-
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0		-	-

5803 139	Mst elo6-PortP		Reading	
			0	1
	Bit 0 Bit 7		-	-
	Bit 1 Bit 6	Duplex Transport Motor Flag	Off	On
	Bit 2 Bit 5		-	-
	Bit 3 Bit 4	Not used	-	-
	Bit 4 Bit 3	Decarler Feed Motor Flag	Off	On
	Bit 5 Bit 2	Pressure Roller Lift Motor Flag	Off	On
	Bit 6 Bit 1	Decarler Drive Motor Flag	Off	On
	Bit 7 Bit 0	Oil Supply Motor Flag	Off	On

5803 140	CTB_H8S-PORT9 (Buffer Pass Unit: M379)		Read	ding
			0	1
	Bit 0 Bit 7	Reserve Fan 4	-	-
	Bit 1 Bit 6	Reserved	-	-
	Bit 2 Bit 5	Lower Exhaust Fan	Normal	Error
	Bit 3 Bit 4	Lower Exhaust Fan	Normal	Error
	Bit 4 Bit 3	Reserve Fan 3	-	-
	Bit 5 Bit 2	Reserved	-	-
	Bit 6 Bit 1	Lower Cooling Fan	Normal	Error
	Bit 7 Bit 0	Lower Cooling Fan	Normal	Error

5803 141	CTB_H8S-PortA		Reading	
	(Buffer Pass Unit: M379)		0	1
	Bit 0 Bit 7	Interlock Switch: Front Door	Close	Open
	Bit 1 Bit 6	Debug monitor	SO	Cl
	Bit 2 Bit 5	Debug monitor	SCI	
	Bit 3 Bit 4	LED	On	Off
	Bit 4 Bit 3	Not used	-	ı

Technical Bulletin

PAGE: 13/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067		
	Bit 5 Bit 2	Not used			-	-
	Bit 6 Bit 1	Not used			-	-
	Bit 7 Bit 0	Not used		•	-	-

5803 142	CTB_H8S-PortB		Read	ding
	(Buffer Pass L	Jnit: M379)	0	1
	Bit 0 Bit 7	Drive Motor Left	Normal	Error
	Bit 1 Bit 6	Drive Motor Right	Normal	Error
	Bit 2 Bit 5	Drive Motor Left	Motor Lock	
	Bit 3 Bit 4	Drive Motor Left	CCW	CW
	Bit 4 Bit 3	Drive Motor Left	On	Off
	Bit 5 Bit 2	Drive Motor Right	Motor Lock	
	Bit 6 Bit 1	Drive Motor Right	CCW	CW
	Bit 7 Bit 0	Drive Motor Right	On	Off

5803 143	CTB_H8S-PortC		Read	ding
	(Buffer Pass U	Jnit: M379)	0	1
	Bit 0 Bit 7	Reserve Fan 2	-	-
	Bit 1 Bit 6	Reserved	-	-
	Bit 2 Bit 5	Upper Exhaust Fan	Normal	Error
	Bit 3 Bit 4	Upper Exhaust Fan	Normal	Error
	Bit 4 Bit 3	Reserve Fan 1	-	-
	Bit 5 Bit 2	Reserved	-	-
	Bit 6 Bit 1	Upper Cooling Fan	Normal	Error
	Bit 7 Bit 0	Upper Cooling Fan	Normal	Error

5803 144	CTB_H8S-PortD		Read	ding
	(Buffer Pass	(Buffer Pass Unit: M379)		1
	Bit 0 Bit 7	Transport Sensor 6	Paper detected	Paper not detected
	Bit 1 Bit 6	Transport Sensor 3	Paper detected	Paper not detected
	Bit 2 Bit 5	Transport Sensor 7	Paper detected	Paper not detected
	Bit 3 Bit 4	Transport Sensor 2	Paper detected	Paper not detected
	Bit 4 Bit 3	Transport Sensor 8	Paper detected	Paper not detected
	Bit 5 Bit 2	Transport Sensor 1	Paper detected	Paper not detected
	Bit 6 Bit 1	Not used	-	-
	Bit 7 Bit 0	Not used	-	_

5803 145	CTB_H8S-PortE	Reading		
	(Buffer Pass Unit: M379)	0	1	
	Bit 0 Bit 7 Not used	-	-	

PAGE: 14/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067
Bit 1 Bit 6	Not used		-	-
Bit 2 Bit 5	+24V		+24V On	+24V Off
Bit 3 Bit 4	+24V INT		+24V_INT O	n +24V_INT Off
Bit 4 Bit 3	Not used		-	-
Bit 5 Bit 2	Not used		-	-
Bit 6 Bit 1	Transport Sensor 5		Paper	Paper not
			detected	detected
Bit 7 Bit 0	Transport Sensor 4	•	Paper	Paper not
			detected	detected

5803	803 Description		ing	
5605	Description	0 1		
5803 150	Htg Roller Thermistor 1			
5803 151	Prs Roller Thermistor 2	Input [deg]		
5803 152	Thermopile			
5803 154	IOB:3V Std Voltage (S)	Input [V]		

5803 155	SIv elo1-PortK	Read	ding
		0	1
	Bit 0 Bit 7 -	-	-
	Bit 1 Bit 6 -	-	-
	Bit 2 Bit 5 -	-	-
	Bit 3 Bit 4 1st Paper Feed Motor Flag	Off	On
	Bit 4 Bit 3 -	-	-
	Bit 5 Bit 2 -	-	-
	Bit 6-Bit 1 -	-	-
	Bit 7-Bit 0 -	-	-

5803 156	803 156 Slv elo1-PortL		Reading	
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	1st Grip Motor	Off	On
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	2nd Paper Feed Motor	Off	On
	Bit 7 Bit 0	-	-	-

5803 157 Slv elo1-PortM		Rea	ding	
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-

Technical Bulletin

PAGE: 15/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067
Bit 4 Bit 3	2nd Grip Motor		Off	On
Bit 5 Bit 2	-		-	-
Bit 6 Bit 1	-		-	-
Bit 7 Bit 0	-	•	-	-

5803 158	Slv elo2-PortJ		Reading	
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	Zero Cross 1	Off	On
	Bit 3 Bit 4	Belt Centering Roller Sensor	Off	On
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	_	-	-

5803 159	Slv elo2-PortK		Rea	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	Vertical Relay Mot	Off	On
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	_	-	-
	Bit 6 Bit 1	_	-	-
	Bit 7 Bit 0	-	-	-

5803 160	SIv elo2-PortL		Rea	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	ITB Color Lift Motor Flag	Off	On
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	Belt Centering Roller Motor	Off	On
		Flag		
	Bit 7 Bit 0	-	-	-

5803 161	Slv elo1-PortB		Rea	ding
			0	1
	Bit 0 Bit 7	Paper Feed Sensor 1	Off	On
	Bit 1 Bit 6	Paper End Sensor 1	Off	On
	Bit 2 Bit 5	Vertical Transport Sensor 1	Off	On
	Bit 3 Bit 4	Paper Feed Sensor 2	Off	On
	Bit 4 Bit 3	Paper End Sensor 2	Off	On

PAGE: 16/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067	
	Bit 5 Bit 2	Vertical Transport Senso	or 2	Off	On
	Bit 6 Bit 1	Tray Lift Sensor 1		Off	On
	Bit 7 Bit 0	Tray Lift Sensor 2		Off	On

5803 162	803 162 Slv elo2-PortM		Reading	
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	ITB Black Lift Motor Flag	Off	On
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

5803 164	Slv elo1-PortN		Read	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	2nd Tray Lift Motor: Paper Height Sensor 1	Off	On
	Bit 3 Bit 4	2nd Tray Lift Motor: Paper Height Sensor 2	Off	On
	Bit 4 Bit 3	Rear Fence HP Sensor	Off	On
	Bit 5 Bit 2	Rear Fence Return Sensor	Off	On
	Bit 6 Bit 1	Left Tray Paper Sensor	Off	On
	Bit 7 Bit 0	-	-	-

5803 165	Slv elo2-Port	SIv elo2-PortA		ding
			0	1
	Bit 0 Bit 7	Paper Height Sensor 1	Off	On
	Bit 1 Bit 6	Paper Height Sensor 2	Off	On
	Bit 2 Bit 5	Paper Height Sensor 3	Off	On
	Bit 3 Bit 4	Paper Height Sensor 4	Off	On
	Bit 4 Bit 3	Front Side Fence Open Sensor	Off	On
	Bit 5 Bit 2	Front Side Fence Close Sensor	Off	On
	Bit 6 Bit 1	Rear Side Fence Open Sensor	Off	On
	Bit 7 Bit 0	Rear Side Fence Close Sensor	Off	On

5803 166	Slv elo2-PortC		Rea	ding
			0	1
	Bit 0 Bit 7	ITB Unit Drawer Set Detection	Off	On
	Bit 1 Bit 6	-	-	-

PAGE: 17/25

Model: Aegis-P1(G178)/C1(D016)	Date: 24-Jul-09	No.: RG178067
Bit 2 Bit 5 -	-	-
Bit 3 Bit 4	-	-
Bit 4 Bit 3	-	-
Bit 5 Bit 2 -	-	-
Bit 6-Bit 1 -	-	-
Bit 7 Bit 0 ITB Cleaning Mo	tor Off	On

5803 167	SIv elo2-PortE		Read	ding
			0	1
	Bit 0 Bit 7	Tray1: Right Tray Set Detection	Off	On
	Bit 1 Bit 6	Tray1: Left Tray Set Detection	Off	On
	Bit 2 Bit 5	Right Tray 1 Paper Sensor	Off	On
	Bit 3 Bit 4	Paper Size Switch 1	Off	On
	Bit 4 Bit 3	Paper Size Switch 2	Off	On
	Bit 5 Bit 2	Paper Size Switch 3	Off	On
	Bit 6 Bit 1	Paper Size Switch 4	Off	On
	Bit 7 Bit 0	Paper Size Switch 5	Off	On

5803 168	Slv elo2-PortF		Rea	ding
			0	1
	Bit 0 Bit 7	Lower Limit Sensor	Off	On
	Bit 1 Bit 6	Zero Cross 1	Off	On
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6-Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

5803 169	SIv elo2-PortN		Read	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	ITB Drive Motor Flag	Off	On
	Bit 4 Bit 3	ITB Black Lift Sensor	Off	On
	Bit 5 Bit 2	ITB Color Lift Sensor	Off	On
	Bit 6 Bit 1	ITB Cleaning Unit Set Sensor	Off	On
	Bit 7 Bit 0	-	-	-

5803	Description	Reading		
5605	Description	0	1	
5803 170	Belt Overrun Sensor:Front	Not overrun	Overrun	
5803 171	Belt Overrun Sensor:Rear	Not overrun	Overrun	

Technical Bulletin

PAGE: 18/25

Model: Aegis-P1(G178)/C1(D016)		Date: 24-Jul-09		No.: RG178	8067
5803 172	PTR Timing Sensor	No paper detected	Pape	r detected	

5803 181	A4LCT:CPU-Port7		Read	ding
	(G178 only)		0	1
	Bit 0 Bit 7	LCT Exit Sensor	Paper detected	Not detected
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	LCT Front Door Safety Switch	Close	Open
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

5803 182	5803 182 A4LCT:eIO2-PortP		Read	ding
	(G178 only)		0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6-Bit 1	Transport Sensor Bypass	Paper detected	Not detected
	Bit 7 Bit 0	-	-	-

5803 183	A4LCT:eIO2-	PortA	Rea	ding
			0	1
	Bit 0 Bit 7	3rd Transport Sensor	Paper detected	Not detected
	Bit 1 Bit 6	3rd Lift Sensor	Upper limit	Not upper limit
	Bit 2 Bit 5	3rd Paper End Sensor	Paper detected	Not detected
	Bit 3 Bit 4	3rd Paper Feed Sensor	Paper detected	Not detected
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	3rd Paper Size Sensor 3	On	Off
	Bit 6 Bit 1	3rd Paper Size Sensor 2	On	Off
	Bit 7 Bit 0	3rd Paper Size Sensor 1	On	Off
Note	\supset			

When this LCT is installed in another mainframe, the upper tray of this LCT may show "4th".

5803 184	A4LCT:eIO2-PortB	Reading	
	(G178 only)	0	1

Technical Bulletin

PAGE: 19/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	24-Jul-09	No.: RG178067
Bit 0 Bit	7 -		-	-
Bit 1 Bit	6 -		-	-
Bit 2 Bit	5 -		-	-
Bit 3 Bit	4 -		-	-
Bit 4 Bit	3 3rd Paper Height Sens	or 4	Off	On
Bit 5 Bit	2 3rd Paper Height Sens	or 3	Off	On
Bit 6-Bit	1 3rd Paper Height Sens	or 2	Off	On
Bit 7 Bit	0 3rd Paper Height Sens	or 1	Off	On
Note				

When this LCT is installed in another mainframe, the upper tray of this LCT may show "4th".

5803 185	A4LCT:eIO2-PortC		Rea	ding
	(G178 only)		0	1
	Bit 0 Bit 7	4th Transport Sensor	Paper detected	Not detected
	Bit 1 Bit 6	4th Lift Sensor	Upper limit	Not upper limit
	Bit 2 Bit 5	4th Paper End Sensor	Paper detected	Not detected
	Bit 3 Bit 4	4th Paper Feed Sensor	Paper detected	Not detected
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	4th Paper Size Sensor 3	On	Off
	Bit 6 Bit 1	4th Paper Size Sensor 2	On	Off
	Bit 7 Bit 0	4th Paper Size Sensor 1	On	Off

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "5th".

5803 186	A4LCT:eIO2-PortD		Rea	ding
	(G178 only)		0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	4th Paper Height Sensor 4	Off	On
	Bit 5 Bit 2	4th Paper Height Sensor 3	Off	On
	Bit 6 Bit 1	4th Paper Height Sensor 2	Off	On
	Bit 7 Bit 0	4th Paper Height Sensor 1	Off	On

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "5th".

5803 187	A4LCT:eIO3-PortA	Reading	
	(G178 only)	0	1
	Bit 0 Bit 7 5th Transport Sensor	Paper	Not detected

Technical Bulletin

PAGE: 20/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067
			detected	
Bit 1 Bit 6	5th Lift Sensor		Upper limit	Not upper limit
Bit 2 Bit 5	5th Paper End Sensor		Paper detected	Not detected
Bit 3 Bit 4	5th Paper Feed Sensor		Paper detected	Not detected
Bit 4 Bit 3	-		-	-
Bit 5 Bit 2	5th Paper Size Sensor	3	On	Off
Bit 6 Bit 1	5th Paper Size Sensor 2	2	On	Off
Bit 7-Bit 0	5th Paper Size Sensor	1	On	Off

Note

When this LCT is installed in another mainframe, the upper tray of this LCT may show "6th".

5803 188	A4LCT:eIO3-I	A4LCT:elO3-PortB		ding
	(G178 only)		0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	5th Paper Height Sensor 4	Off	On
	Bit 5 Bit 2	5th Paper Height Sensor 3	Off	On
	Bit 6 Bit 1	5th Paper Height Sensor 2	Off	On
	Bit 7 Bit 0	5th Paper Height Sensor 1	Off	On
Niete				

When this LCT is installed in another mainframe, the upper tray of this LCT may show "6th".

5803 189	5803 189 A4LCT:eIO2-PortE (G178 only) (By-pass Unit B833)		Rea	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	Paper Length Sensor	On	Off
	Bit 3 Bit 4	Paper Width Switch 5	On	Off
	Bit 4 Bit 3	Paper Width Switch 4	On	Off
	Bit 5 Bit 2	Paper Width Switch 3	On	Off
	Bit 6 Bit 1	Paper Width Switch 2	On	Off
	Bit 7 Bit 0	Paper Width Switch 1	On	Off

5803 190	A4LCT:eIO3-PortC (G178 only)		Re	Reading		
	(By-pass Unit B833)		0	1		
	Bit 0 Bit 7	Relay Sensor	Paper detected	Not detected		
	Bit 1 Bit 6	Lift Sensor	Upper limit	Not upper limit		
	Bit 2 Bit 5	Paper End Sensor	Paper detected	Not detected		

PAGE: 21/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No.: RG178067	
	Bit 3 Bit 4	Paper Feed Sensor		Paper detected	Not detected
	Bit 4 Bit 3	-		-	-
	Bit 5 Bit 2	-		-	-
	Bit 6 Bit 1	-		-	-
	Bit 7 Bit 0	-		-	-

5803 191	A4LCT:eIO3-PortD		Read	ding
	(G178 only)	(G178 only)		1
	Bit 0 Bit 7	Feed Unit Slide Detection	Close	Open
	Bit 1 Bit 6	Feed Unit Set Detection	Set	Not set
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	Tray Lift Switch	On (Pushed)	Off
	Bit 4 Bit 3	Tray Lower Limit Sensor	Not lower limit	Lower limit
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	Paper End Sensor	Off	On
	Bit 7 Bit 0	Paper Near End Sensor	Off	On

5803	Description	Reading		
3603	Description	0	1	
5803 201	Platen Cover Sensor (D016 only)	Open	Close	

5803 202	Scanner fan lock signal		Reading	
	(D016 only)		0	1
	Bit 0 Bit 7	Scanner HP Sensor	Not HP	HP
	Bit 1 Bit 6	Lamp Regulator Fan (Right)	Normal	Lock
	Bit 2 Bit 5	SBU Cooling Fan	Normal	Lock
	Bit 3 Bit 4	Scanner Intake Fan	Normal	Lock
	Bit 4 Bit 3	Scanner Unit Exhaust Fan	Normal	Lock
	Bit 5 Bit 2	Lamp Regulator Fan (Left)	Normal	Lock
	Bit 6 Bit 1	Scanner Motor Cooling Fan	Normal	Lock
	Bit 7 Bit 0	Not used	-	-

5803 211	A3LCT1:CPU-Port7		Read	ding
			0	1
	Bit 0 Bit 7	-	-	-
	Bit 1 Bit 6	-	-	-
	Bit 2 Bit 5	-	-	-
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	Right Door Open Switch	Close	Open
	Bit 5 Bit 2	Left Door Open Switch	Close	Open
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

Technical Bulletin PAGE: 22/25

Model: Aegis-P1(G178)/C1(D016)		Date: 24-Jul-09 N		No.: RG178067	
5803 212	A3LCT1:CPU-	Port9		Reading	
				0	1
	Bit 0 Bit 7	-		-	-
	Bit 1 Bit 6	-		-	-
	Bit 2 Bit 5	-		-	-
	Bit 3 Bit 4	-		-	-
	Bit 4 Bit 3	Dip Switch 101-1		On	Off
	Bit 5 Bit 2	Dip Switch 101-2		On	Off
	Bit 6 Bit 1	Dip Switch 101-3		On	Off
	Bit 7 Bit 0	Dip Switch 101-4		On	Off

5803 213	A3LCT1:eIO2-PortA		Reading	
			0	1
	Bit 0 Bit 7	LCT Paper Width Sensor 1: T1	Off	On
	Bit 1 Bit 6	LCT Paper Width Sensor 2: T1	Off	On
	Bit 2 Bit 5	LCT Paper Width Sensor 3: T1	Off	On
	Bit 3 Bit 4	LCT Paper Length Sensor 1	Off	On
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	-	-
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

5803 214	A3LCT1:eIO2-PortB		Rea	ding
			0	1
	Bit 0 Bit 7	LCT Paper Height Sensor 1:	Off	On
	Bit 1 Bit 6	LCT Paper Height Sensor 2:	Off	On
	Bit 2 Bit 5	LCT Paper Height Sensor 3: T1	Off	On
	Bit 3 Bit 4	LCT Paper Height Sensor 4: T1	Off	On
	Bit 4 Bit 3	LCT Paper End Sensor 1	Paper detected	Not detected
	Bit 5 Bit 2	LCT Paper Lift Sensor 1	Upper limit	Not upper limit
	Bit 6 Bit 1	LCT Tray Set Detection: T1	Set	Not set
	Bit 7 Bit 0	-	-	_

5803 215	A3LCT1:eIO2-PortC		Reading	
			0	1
	Bit 0 Bit 7	LCT Paper Width Sensor 1: T2	Off	On
	Bit 1 Bit 6	LCT Paper Width Sensor 2: T2	Off	On
	Bit 2 Bit 5	LCT Paper Width Sensor 3: T2	Off	On
	Bit 3 Bit 4	LCT Paper Length Sensor 2	Off	On
	Bit 4 Bit 3	-	-	-
	Bit 5 Bit 2	-	_	-

Technical **B**ulletin

PAGE: 23/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	No	D.: RG178067
Bit 6 Bit 1 -			-		-
Bit 7 Bit 0 -			-		-

5803 216	A3LCT1:eIO2-PortD		Read	ding
			0	1
	Bit 0 Bit 7	LCT Paper Height Sensor 1: T2	Off	On
	Bit 1 Bit 6	LCT Paper Height Sensor 2: T2	Off	On
	Bit 2 Bit 5	LCT Paper Height Sensor 3: T2	Off	On
	Bit 3 Bit 4	LCT Paper Height Sensor 4: T2	Off	On
	Bit 4 Bit 3	LCT Paper End Sensor 2	Paper detected	Not detected
	Bit 5 Bit 2	LCT Paper Lift Sensor 2	Upper limit	Not upper limit
	Bit 6 Bit 1	LCT Tray Set Detection: T2	Set	Not set
	Bit 7 Bit 0	-	-	-

5803 217	A3LCT1:eIO2	2-PortE	Rea	ding
	(By-pass Unit	: B833)	0	1
	Bit 0 Bit 7	Paper Width Switch 1	On	Off
	Bit 1 Bit 6	Paper Width Switch 2	On	Off
	Bit 2 Bit 5	Paper Width Switch 3	On	Off
	Bit 3 Bit 4	Paper Width Switch 4	On	Off
	Bit 4 Bit 3	Paper Width Switch 5	On	Off
	Bit 5 Bit 2	Paper Length Sensor	On	Off
	Bit 6 Bit 1		-	-
	Bit 7 Bit 0	-	-	-

5803 218	A3LCT1:eIO2-PortP		Read	ding
			0	1
	Bit 0 Bit 7	Air Assist fan 1: Front Error	No Error	Error
	Bit 1 Bit 6	Air Assist fan 1: Rear Error	No Error	Error
	Bit 2 Bit 5	Air Assist fan 1: Left Error	No Error	Error
	Bit 3 Bit 4	-	No Error	Error
	Bit 4 Bit 3	Air Assist fan 2: Front Error	No Error	Error
	Bit 5 Bit 2	Air Assist fan 2: Rear Error	No Error	Error
	Bit 6 Bit 1	Air Assist fan 2: Left Error	No Error	Error
	Bit 7 Bit 0	-	-	-

5803	219	A3LCT1:eIO3-	PortA	Read	ding
				0	1
		Bit 0 Bit 7	LCT Paper Feed Sensor 1	Paper detected	Not detected

Technical Bulletin

PAGE: 24/25

Model: Aegis-P1(G178)/C1(D016)		Date: 2	4-Jul-09	N	o.: RG178067
Bit 1 Bit 6	LCT Paper Feed Senso	r 2	Paper detected		Not detected
Bit 2 Bit 5	(Bypass) Paper Feed So	ensor	Paper detected		Not detected
Bit 3 Bit 4	-		-		-
Bit 4 Bit 3	LCT Grip Sensor 1		Paper detected		Not detected
Bit 5 Bit 2	LCT Grip Sensor 2		Paper detected		Not detected
Bit 6-Bit 1	(Bypass) Relay Sensor		Paper detected		Not detected
Bit 7 Bit 0	-		-		_

5803 220	A3LCT1:eIO3	-PortB	Reading	
			0	1
	Bit 0 Bit 7	LCT Vertical Transport Sensor 1	Paper detected	No paper
	Bit 1 Bit 6	LCT Vertical Transport Sensor 2	Paper detected	No paper
	Bit 2 Bit 5	LCT Vertical Transport Sensor 3	Paper detected	No paper
	Bit 3 Bit 4	-	1	-
	Bit 4 Bit 3	LCT Exit Sensor	Paper detected	No paper
	Bit 5 Bit 2	-	_	-
	Bit 6 Bit 1	-	-	-
	Bit 7 Bit 0	-	-	-

5803 221	A3LCT1:eIO3	-PortC	Reading	
			0	1
	Bit 0 Bit 7	LCT Entrance Sensor	Paper detected	No paper
	Bit 1 Bit 6	LCT Right Vertical Sensor	Paper detected	No paper
	Bit 2 Bit 5	LCT Horizontal Transport Entrance Sensor	Paper detected	No paper
	Bit 3 Bit 4	LCT Horizontal Transport Exit Sensor	Paper detected	No paper
	Bit 4 Bit 3	LCT Vertical Transport Entrance Sensor	Paper detected	No paper
	Bit 5 Bit 2	-	-	-
	Bit 6-Bit 1	LCT Horizontal Bridge Unit Set Detection	Set	Not set
	Bit 7 Bit 0	LCT Paper Exit Roller Contact Sensor	Contact	Not contact

Technical Bulletin

PAGE: 25/25

Model: Aegis-P1(G178)/C1(D016) Date: 24-Jul-09 No.: RG178067

5803 222	A3LCT1:eIO3-PortD		Read	ding
	(By-pass Unit	(By-pass Unit B833)		1
	Bit 0 Bit 7	Paper Near End Sensor	Off	On
	Bit 1 Bit 6	Paper End Sensor	Off	On
	Bit 2 Bit 5	Tray Lower Limit Sensor	Not low limit	Low limit
	Bit 3 Bit 4	Tray Lift Switch	On (Pushed)	Off
	Bit 4 Bit 3	Paper End Sensor (Tray)	Paper detected	No paper
	Bit 5 Bit 2	Lift Sensor	Upper limit	Not upper limit
	Bit 6 Bit 1	Bypass Set Detection	Set	Not set
	Bit 7 Bit 0	Bypass Slide Open Detection	Close	Open

5803 223	A3LCT1:eIO3-PortP		Read	ding
			0	1
	Bit 0 Bit 7	Reserved Sensor 1	-	-
	Bit 1 Bit 6	Reserved Sensor 2	-	-
	Bit 2 Bit 5	Reserved Sensor 3		
	Bit 3 Bit 4	-	-	-
	Bit 4 Bit 3	Dip Switch 740-1	On	Off
	Bit 5 Bit 2	Dip Switch 740-2	On	Off
	Bit 6 Bit 1	Dip Switch 740-3	On	Off
	Bit 7 Bit 0	Dip Switch 740-4	On	Off

Technical Bulletin

PAGE: 1/6

Model: AG-P1	/ C1		Dat	te: 03-Au	g-09	No.: RG178068
Subject: Firmwai	re Release Note: Animation			Prepare	d by: N.li	da
From: PPBG QA	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	n required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()	☐ Tier 2	

This RTB has been issued to announce the firmware release information on the **Animation.**

Version	Program No.	Effective Date
2.2	G1786094B	August 2009 production.

Version	Modif	fied Points or Symptom	s Adjusted
2.2	1. Animation graphics for	Buffer Pass Unit Type 5	5000, Perfect Binder GB5000,
	and Fuser Knob have be	een newly added.	
	Diago votov to Annondiv	. 45 for undata procedur	
	Please refer to <appendix follow="" make="" pi<="" sure="" td="" the="" to=""><td></td><td></td></appendix>		
	make sure to ronow the pr	ocedures when apaating	9 -
	*Please make sure that Al	LL versions listed below	are updated concurrently.
	Program Name	Program No.	Version
	System	G1786091G	2.05
	Websystem	G1786093E	1.53
	Network Support (NCS)	G1786092D	7.04
	Engine	G1785252G	3.000:12
	LCDC	NA:G1785971C	1.03
		EU : G1785972C	
	Animation	G1786094B	2.2
	Language	G1785979A	1.03
	Fiery Server	-	4.0
	* Update to the following		all peripherals listed below.
		Program No.	Version
	CI5010	B8355510F	V2.071:42
	SR5000	B8305102P	V1.820:59
	RB5000	Main : D3925510E	V1.290:04
		Sub: D3925520C	V1.060:01
	GB5000		
	P-Binder_B1	D3915020C	V0.28
	P-Binder_B2	D3915070B	V0.19
	P-Binder B3	D3915730A	V0.13
	P-Binder_B4	D3915120B	V0.15
	P-Binder_B5	D3915170A	V0.25
	BK5000	B8365550B	V2.17:15
	SK5000		

Technical **B**ulletin

PAGE: 2/6

Model: AG-P1 / C1 Date: 03-Aug-09 No.: RG178068

	2 nd stacker	D3645620 P2					
	Buffer Pass Unit Type 5000	M3791702A	V1.000:03				
	Note						
'	 Make sure to update the peripherals in order of proximity to the main frame. 						
		nsecutively by selecting eards can be updated co					
	• For RB5000, 2 bo	ards can be updated co	nsecutively.				

PAGE: 3/6

Model: AG-P1 / C1 Date: 03-Aug-09 No.: RG178068

<Appendix 1>


Please ensure to follow the procedures for the update.

The firmware of GW controller needs to be updated at a time.

Make sure to update in the order since there is the order also for the other firmware. NOTE:

- Do not do remote-update.
- If the currently-operated Fiery Server is updated from "Vx.x" to "V4.0", the HDD will be formatted, all the stored data will be deleted, and the various settings will return to the default since the system is reinstalled. Be sure to back-up the setting information, the imported data, the fonts, the customized profiles, etc., beforehand.
- When updating the Aegies-P1, please ensure to confirm the Engine Firmware version. If the version is 1.100:10 or 1.103:11, update to V1.108:11 will be required. When a direct update to the latest version is attempted from either Version1.100:10 or 1.103:11, WatchDogTimeOut ERROR(*1) could occur resulting in a non-functioning of the operation panel, and the machine will stop. As replacement of the BCU board will be required to resolve this error, please ensure to follow this correct procedure.

NOTE: This problem will not occur with the Aegis-C1.



(*1) WatchDogTimeOut ERROR

While the software timer resets the hardware timer in a certain interval, WatchDogTimeOut error occurs when this reset is not executed after a lapse of time specified and the hardware timer reaching a time-out state. This problem has been confirmed with versions 1.100:10 and 1.103:11 and has been resolved from 1.108:11. Hence firmware is updated in the particular order mentioned in above.

Technical Bulletin

PAGE: 4/6

Model: AG-P1 / C1 Date: 03-Aug-09 No.: RG178068

[Advance Preparation]

- Turn the power switch of Fiery Server off or unplug the power cable when updating since you will turn the main power off/on repeatedly.
- Unplug the LAN cable of the GW controller.
- Unplug the data cable of the peripheral just under the main frame not to operate during updating.

1. Firmware of GW controller Update

1-1. Copy the listed firmware below to the SD card..

For Aegis-C1

1 01 7 togic 0 1		
Program name	Program No.	Version
System/Copy	D0166091D	V1.04
Scanner	D0166097B	V1.05
WebSys	D0166093B	V1.03
WebUApl	D0166095C	V1.12
NCS	D0166092B	V7.04.1
NFA	D0166096B	V1.03

For Aegis-P1

Program name	Program No.	Version	
System/Copy	G1786091G	V2.05	
WebSys	G1786093E	V1.53	
NCS	G1786092D	V7.04	

- 1-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 1-3. Turn the main power on, select all after the selection screen is displayed, and update.

NOTE: For Aegis-C1, be sure to select till the next page.

1-4. Turn off the main power and remove the SD card from the slot when the update is completed.

NOTE: Go to the next step with the main power off.

2. Engine firmware Update

2-1. Copy the Engine firmware to "romdata" of the SD card.

For Aegis-C1

1 of Aegis-C i				
Program name	Program No.	Version		
Engine	D0165252D	V3.000:12		

For Aegis-P1

· · · · · · · · · · · · · · · · · · ·				
Program name	Program No.	Version		
Engine	G1785252G	V3.000:12		

- 2-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 2-3. Turn the main power on, select "Engine firmware" after the selection screen is displayed, and update.
- 2-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

PAGE: 5/6

Model: AG-P1 / C1 Date: 03-Aug-09 No.: RG178068

3. OpePanel Update

3-1. Copy the OpePanel firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
LCDC	NA:G1785975C	V1.06
	EU:G1785976C	

For Aegis-P1

Program name	Program No.	Version
LCDC	NA:G1785971C	V1.03
	EU:G1785972C	

- 3-1. Copy the OpePanel firmware to "romdata" of the SD card.
- 3-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 3-3. Turn the main power on, select "LCDC firmware" after the selection screen is displayed, and update.
- 3-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

4. Animation Update

4-1. Copy the Animation firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Animation	D0166094A	V1.6

For Aegis-P1

Program name	Program No.	Version
Animation	G1786094B	V2.2

- 4-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 4-3. Turn the main power on, select "Animation firmware" after the selection screen is displayed, and update.
- 4-4. Turn off the main power and remove the SD card from the slot when the update is completed. NOTE: Go to the next step with the main power off.

5. Language Update

5-1. Copy the Language firmware to "romdata" of the SD card.

For Aegis-C1

Program name	Program No.	Version
Language	G1785980A	V1.06

For Aegis-P1

Program name	Program No.	Version	
Language	G1785979A	V1.03	

- 5-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 5-3. Turn the main power on, select "Language firmware" after the selection screen is displayed, and update.

NOTE: Update by overwriting though the displayed versions of "ROM" and "NEW" might be the same since Opepanel has already been updated.

Technical Bulletin

PAGE: 6/6

Model: AG-P1 / C1 Date: 03-Aug-09 No.: RG178068

5-4. Turn off the main power and remove the SD card from the slot when the update is completed. 5-5. Turn on the main power and enter SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version". Turn off the main power and update the peripheral after confirming the version.

6. Peripheral Update

[Advance Preparation] Connect the data cable of the peripheral with the main power off. NOTE:

- Make sure to update the peripherals in order of proximity to the main frame.
- Do not update consecutively by selecting several peripherals.
- For GB5000, 5 boards can be updated consecutively.
- For RB5000, 2 boards can be updated consecutively.

6-1. Copy the firmware necessary for the machine configuration to "romdata" of the SD card.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1st STACKER	D3645620_P1(1st)	V4.05:13
2nd STACKER	D3645620_P1(2nd)	
Buffer Pass Unit	M3791702A	V1.000:03
Type5000		

- 6-2. Insert the SD card into Slot 2 (upper slot) with the main power off.
- 6-3. Turn the main power on, and update the peripherals in order of proximity to the main frame after the selection screen is displayed. Turn the main power off/on and restart when the update is completed. Update the next peripheral.
- 6-4. Turn off the main power and remove the SD card from the slot when all the update is completed.
- 6-5. Turn on the main power and select SP mode after "No Connection..." is displayed. Confirm the version by entering "SP7801: ROM No./Firmware Version".
- 6-6. Turn off the main power and update the Fiery server after confirming the version.

7. Fiery Server Update

[Advance Preparation] Turn on the power switch of the Fiery server or connect the power cable that has been unplugged.


Refer to "Fiery System Installation" in the service manual and do the Fiery Server Installation.

Technical Bulletin

РΔ	GE:	1/3
	\mathbf{v}	1/0

Model: AG-P1	(G178)/ C1 (D016)		Dat	te: 31-Jul-()9	No.: RG178069
Subject: Roller			Prepare	d by: N.iid	da	
From: PPBG QA	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2	

The pictures below show the roller width and roller interval of each roller. If roller trails appear on the outputs of AG-P1 (G178) or AG-C1 (D016), check the diagrams below and determine which roller causes the roller trails.



roller_trails-1

Main Machine (G178/D016)

- [1]: Pick-up Roller in Tray 1 or Tray 2
- [2]: Transport Rollers in the paper path from the paper tray to the registration unit
- [3]: Registration Timing Rollers or Shift Rollers
- [4]: Fusing Idle Rollers
- [5]: Paper Exit Transport Idle Roller
- [6]: Inverter Rollers, Switchback Rollers, Duplex Transport Rollers or Paper Exit Rollers

Finisher SR5000 (B830)

- [7]: Entrance Rollers
- [8]: Middle Transport Rollers
- [9]: Shift Tray Exit Rollers


PAGE: 2/3

Model: AG-P1 (G178)/ C1 (D016)

Date: 31-Jul-09 No.: RG178069

Countermeasure for Roller Trails from Shift Tray Exit Rollers [9]

Replace the shift tray exit idle roller with a new one if the roller trails appear on the output of AG-P1 (G178) or AG-C1 (D016). For details, refer to "RG178007" or "G178033" in the RTB.



roller_trails-2

Booklet Finisher BK5000 (B836)

[10]: Exit Rollers


[11]: Transport Rollers


PAGE: 3/3


Model: AG-P1 (G178)/ C1 (D016) Date: 31-Jul-09 No.: RG178069


Appendix

Please double-click on the diagrams below and activate Adobe Acrobat. Images will appear in A3 size. By printing them on an A3, output of these images will appear in **actual size**. This would hopefully make easy for verifying the actual rollers that cause the roller marks.










RTB [Subject: R oller Trails on Outputs] Appendix 1


G178/D016(Main)

- [1]: Pick-up Roller in the Tray 1 or Tray2
- [2]: Transport Rollers in the paper path from the paper tray to registration unit
- [3]: Registration Timing Rollers or Shift Rollers
- [4]: Fusing Idle Rollers
- [5]: Paper Exit Transport Idle Roller
- [6]: Inverter Rollers, Switchback Rollers, Duplex Transport Rollers or Paper Exit Rollers



RTB [Subject: R oller Trails on Outputs] Appendix 2

Finisher SR5000(B830)



[7]: Entrance Rollers

[8]: Middle Transport Rollers


[9]: Shift Tray Exit Rollers

RTB [Subject: Roller Trails on Outputs]

Appendix 3-1

Booklet Finisher BK5000 (B836)

[11]: Transport Rollers




RTB [Subject: Roller Trails on Outputs]

Appendix 3-2

Booklet Finisher BK5000 (B836)

[10]: Exit Rollers



Technical Bulletin

PAGE: 1/5

Model: AG-P1/C1 Date			:e: 31-Jul-0)9	No.: RG178070	
Subject: Release Aegis-P1/C1 EFI		Prepared	d by: N. I	ida		
From: PPMC Service Planning Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☐ Other (al		Service	required ce manual revision fit information

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

1.Newly Added Functions

-Support for New Peripherals

Book Binder GB5000 (Perfect Binder)

-Supporting of the Tray Association function

Selection made in the Command Work Station's paper catalog will rewrite the tray information on the engine side.

2.Problem Solving (Measures)

The following are the key problems that have been given countermeasures.

-Problems in the Field

	Symptom Details	Patch	Remarks
1	When recovering from SC794 (Error in stacker tray 2), print does not	1-12PJUX	Composite
	restart while the panel indicates "printing".		patch
2	Slanted dotted line appears in the gradient area of the print.		
3	A confusing error message indicating a button "Reset" is displayed after removing jammed paper.		
4	Function allowing users to specify the exit location of the unused tab sheets is missing.		
5	In a print job that consists of a blank page, even when specifying the blank sheet to be inserted from the Cover Interposer, the Cover Interposer does not feed the sheet.		
6	When selecting Z-fold with insertion of a blank sheet, the image(s) succeeding the blank sheet is turned 180 degrees.	1-12SAP3	
7	Request for the E7100 to be able to fold a two sided sheet into a 4-page book	1-12H5JX	
8	In a print job consisted of different paper types, pages are randomly printed	1-13747G	JFPR
	in simplex.	1-13746Y	problem
	RIP does not complete and job cannot start.		
	When printing from the Viewer, last minute change of copy set is invalid.		
	When setting Impose Page Mark, offset value cannot be set.		
12	When Tray Unit TK5000 is set to tray 1, paper size A3/DLT cannot be		
	selected.		
13	From CWS, job list in the column "order" does not reflect the requested		
	order.		



PAGE: 2/5

Model: AG-P1/C1 Date: 31-Jul-09 No.: RG178070

3. Cases involving Specification Adjustments

Among the cases that involved specification adjustments for the Gershwin3.0, the following 10 symptoms have been corrected for the Gershwin4.0.

	Symptoms
1	In the window "Kanji: CWS: Insert Tab", error message is indicated in Roman.
2	When interrupting a copy job with a print job and cancelling the copy job, machine stops as it indicates "printing".
3	Cancellation of a job under certain conditions could cause SC919(GW Restart).
4	Print job cannot be operated from the driver when the side cover of the Cover Interposer is left
	open.
5	Although input of characters other than a one-byte number is available for the "Document Box
	Password" of the PS driver, when such characters are input, they are not saved in the document
	box.
6	When incorrect password is input to the document box in tab "outline" of CWS job properties, the
	error message does not clear, and disables the CWS operation.
7	In tab "color setting" of the PS driver, some characters are displayed incorrectly.
8	Revision dates in the document tab of Webtools are indicated incorrectly.
9	When printing from the driver in the setting "Booklet: saddle stitch" + "Composite over print: ON",
	part(s) of the image are colored incorrectly.
10	Under certain conditions, the black characters are surrounded with Cyan.

PAGE: 3/5

Model: **AG-P1/C1** Date: 31-Jul-09 No.: RG178070

Note:

- It is necessary to update User Software / Printer Driver when you update the System Software Version 4.0.

Utility version: after updating User Software version 4.0

Windows

Command Work Station	4.8.0.11
Fiery Color Wise Pro Tools	3.10.0.11
Fiery Remote Scan	5.5.1.34
Fiery Remote Scan(TWAIN)	5.5.1.34
Fiery Printer Delete Utility	2.0.0.19
EFI Hot Folders	2.6.0.01
VDP Resource Manager	1.3.0.16
Fiery Bridge	1.1.0.28

Mac OS X

CWS Macintosh Edition	1.7.0f.05
Color Wise Pro Tools	3.11.0.11
Fiery Remote Scan	5.6.0f19
Fiery Remote Scan(TWAIN)	5.6.0f19
EFI Hot Folders	2.6.0f.03
OSX VDP Resource Manager	1.4.0.07

PAGE: 4/5

Model: **AG-P1/C1** Date: 31-Jul-09 No.: RG178070

- It is necessary to update firmware of the mainframe when you update the System Software Version 4.0.

Latest firmware version:

Aegis-C1

*Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	D0166091D	1.04
Scanner	D0166097B	1.05
WebSupport	D0166093B	1.03
WebUApl	D0166095C	1.12
Network Support (NCS)	D0166092B	7.04.1
Network DocBox(NFA)	D0166096B	1.03
Engine	D0165252D	3.000:12
LCDC	NA:G1785975C	1.06
	EU: G1785976C	
Animation	D0166094A	1.6
Language	G1785980A	1.06
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	
Type 5000		V1.000:03

Technical Bulletin

PAGE: 5/5

Model: AG-P1/C1 No.: RG178070 Date: 31-Jul-09

<u>Aegis-P1</u> *Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	G1786091G	2.05
Websystem	G1786093E	1.53
Network Support (NCS)	G1786092D	7.04
Engine	G1785252G	3.000:12
LCDC	NA:G1785971C	1.03
	EU : G1785972C	
Animation	G1786094B	2.2
Language	G1785979A	1.03
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	V1.000:03
Type 5000		

Technical Bulletin

PAGE: 1/16

Model: AG-P1 / C1 Dat		Date: 31-Jul-09		No.: RG178071		
Subject: Fiery Upgrading to Ver4.0		Prepared by: N.lida				
From: PPBG QA	Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part informa		tion	☐ Action	required
		☐ Electrical			Service	ce manual revision
☐ Paper path ☐ Transmit/rec		eive	☐ Retrof	fit information		
	☐ Product Safety	Other ()	☐ Tier 2	

Aegis-P1/C1 Fiery Controller System Software: Upgrading to Ver.4.0

The following guide describes the procedures for upgrading the Aegis-P1/C1 Fiery controller system software to Version 4.0.

The Fiery controller system software (Ver.4.0) is common system software applicable to both Aegis-P1 and C1 and automatically distinguishes the machine configuration. Reinstallation of the system software is required, as Version 4.0 will be provided in a full-build format. Please do the following procedure for the upgrade.

Upgrade Procedure

Step 1. Creating a USB memory for Ver.4.0 installation (Work time: 30 min)

Create a USB memory for Ver.4.0 installation using Ver.4.0 system software DVD, USB Prep Tool V1.2, and USB memory of more than 4GB. Please refer to "Service Manual" for details.

Step 2. Creating a backup of the Fiery controller (Work time: 30 min: Depends on usage status)

When the Fiery controller system software is re-installed, the HDD of the Fiery controller is formatted, and all the data is deleted. All settings are set back to the defaults, and imported print data, fonts, and customized profiles are also deleted. Backup is required for these reasons.

Please refer to the section "Aegis-P1/C1 Fiery Controller Backup Procedures" of this guide for details on backup creation.

Note: A client PC installed with Command Work Station (CWS) and Color Wise Pro Tools (CWPT) is required for creating the backup.

Step 3. Upgrading the Fiery controller to Ver.4.0 (Re-installation) (Work time: 45 min)

The same installation method as Ver.1.0 is applied for Ver.4.0. Please refer to the Service Manual for installation procedures.

For the P1, a message indicating "Fiery is disconnected" will appear on the operation panel screen when installation has completed. Press and hold the power button on the operation panel, wait for the LED lights to go off, then switch off the engine main power. During this process, the main power of the Fiery controller is not yet turned



PAGE: 2/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

off, as it would take approximately 3 minutes. When re-powering, please verify that the 7-seg-LED is off. Powering on the engine before a complete power off of the Fiery controller could cause trouble in booting.

For the C1, the Fiery will activate normally after completing the installation. If the Fiery does not activate normally, please follow the same procedure applied for the P1 for switching off the power.

Step 4. Restoring the backup created in Step 2 (Work time: Approx 30 min: Depends on usage status)

This procedure will restore the backup created in Step 2 after Ver.4.0 installation. Please refer to the section "Aegis-P1/C1 Fiery Controller Data Restore Procedure" of this guide for details on restoring the backed up data.

Step 5. Upgrading the PS driver (Work time: 15 min)

The PS driver of the Client PC must also be upgraded from Ver.1.0 to Ver.4.0 when completing the re-installation of the Fiery system. Please refer to the section "Aegis-P1/C1 PS Driver Ver.1.0→ 4.0 Upgrade Procedure" of this guide for details.

PAGE: 3/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

Aegis-P1/C1 Fiery Controller Backup Procedures

When the Fiery controller system software is re-installed, the HDD of the Fiery controller is formatted, and all the data is deleted. All settings are set back to the defaults, and imported print data, fonts, and customized profiles are also deleted. Backup is required for these reasons.

Please execute the following backup procedures when re-installing the Fiery controller system.

Also, please do not assign the HDD of the Fiery controller as the backup storage location.

1. Printing out the Setup Information Page


On the operation panel, press "Fiery" \rightarrow " Printable Info" \rightarrow "Configuration", then print out the configuration page.

2. System Backup

2.1 Backup of the Fiery settings

A backup of Fiery settings and address book can be created, but a backup of the server identification name cannot be created.

- (1) Activate CWS, and login with Administrator authentication.
- (2) Select "Server" → "Setup".
- (3) In the dialogue box below, select "Server" → "Backup/Restore".



- (4) Click "Backup Fiery settings...", assign a save location, then click "OK".
- (5) Wait for the backup process to complete, then click "OK".




Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

2-2. Backup of Fonts

This procedure will create a backup of fonts installed in the Fiery created by a third party.

PAGE: 4/16

- (1) Activate CWS (for Windows), login with the Administrator authentication.
- (2) Select "Server" → "Manage Fonts".
- (3) In the dialogue box below, select "Backup".



- (4) Assign a save location, then click "OK".
- (5) Wait for the backup process to complete, then click "OK".



Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071


2-3. Backup of Profiles

This procedure will back up customized profiles created with CWPT. Please refer to the CWPT help information for details.

PAGE: 5/16

(1) Activate CWPT, and select "Profile Manager".

(2) Select the profile you wish to download, then click on the green arrow.



- (3) Select the save location, and save.
- (4) Wait for the upload to complete, then click "OK".

2-4. Backup of Print Data

This procedure will archive print data in the Active Jobs.

- (1) Activate CWS, select the job you wish to archive, then right-click.
- (2) Select "Archives", assign a save location, then click "OK".

2-5. Downloading Scan Jobs

Backup/Restore of scan jobs sent to the mailbox cannot be created. Please follow the procedure below to download the scan job.

- (1) Activate Webtools, and select tab "Documents".
- (2) Type in a user name and password to access the mailboxes.
- (3) Click "My Documents", specify the document you wish to download, then start download.

Technical Bulletin


PAGE: 6/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

2-6. Backup of Spot-On Color Group

This procedure will backup customized Color (or substitute Color) groups created on CWPT Spot-On.

- (1) Activate CWPT, and select Spot-On.
- (2) Select the output profile.
- (3) Select the Color group you wish to upload, then click the icon circled in red in the following diagram.



(4) Select a save location, and save.



PAGE: 7/16


Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

2-7. Manual Backup of Color Setup

This procedure will back up the setting values that have been changed in the CWPT Color Setup.

The feature does not allow the system to read and restore the backup file. Therefore, current setting values must be recorded manually, and must be adjusted manually one at a time after completing the upgrade.

- (1) Activate CWPT, and select "Color Setup".
- (2) Using the key "PrintScreen" on the keyboard, take Screenshots of these tabs: "Color process flow", "Control bar", "Automatic trapping", "Progressive", and "Half-tone simulation". Paste the screenshots into the "Paint", application and save them. (Ensure that the characters are visible when determining the size of the screenshots.)




PAGE: 8/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071


Aegis-P1/C1 Fiery Controller Backup Restore Procedures

Please follow the procedures below to restore the backup after installing the system software Ver.4.0.

- 1. Restoring the Backup Settings
 - 1-1. Restore Fiery settings
 - (1) Activate CWS, and login with Administrator authentication.
 - (2) Select "Server" → "Setup".
 - (3) In the dialogue box below, select "Server" → "Backup/Restore".



(4) Click "Fiery settings Restore" to display the dialogue box below. Click "Approve".



- (5) Select and open the file saved in the previous backup procedure.
- (6) The Fiery will reboot when Restore has completed.




PAGE: 9/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

1-2. Font Restore

This procedure will restore the backup fonts.

- (1) Activate CWS (for Windows), and login with Administrator authentication.
- (2) Select "Server" → "Font manager".
- (3) The following dialogue box will appear. Select "Restore".



- (4) Select the folder saved in the previous backup procedure, and click "OK".
- (5) Wait for the backup process to complete, and click "OK".
- (6) Reboot the Fiery.



PAGE: 10/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

1-3. Restoring the Profiles

This procedure will restore the backup profiles. Please refer to the CWPT help information for details.

- (1) Activate CWPT, and select "Profile Manager".
- (2) Click "Browse", and select folder containing the backup profile.
- (3) Select the backup profile, and click the green arrow to download.



(4) Wait for the process to complete, and click "OK".

1-4. Restoring the Print Data

This procedure will restore the backup print data.

- (1) Activate CWS, and select "File" → "Import" → "Archived Jobs".
- (2) Assign the directory saved in the previous backup procedure. Wait for the job to appear, select the job, and click "OK".




PAGE: 11/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

1-5. Restoring the Spot-On Color Group

This procedure will restore the backup customized Color group (or the substitute Color).

- (1) Activate CWPT, and select "Spot-On".
- (2) Select "Output profile".
- (3) Select the location where you wish to add the Color group, and click the icon circled in red in the following diagram.



(4) Select the backup Color group, and download.

1-6. Restoring the Color Setup Values

This procedure will restore the backup setting value for the Color Setup.

- (1) Activate CWPT, and select "Color Setup".
- (2) Refer to the tab screenshots saved in the previous backup procedure, and input the setting values manually.

2. Printing out the Settings Information Page

On the operation panel, push "Fiery"→"Printable Information" → "Settings Information", and print out the settings information page.

Compare with the values printed out in the previous backup procedure, and confirm that the correct value is restored.



PAGE: 12/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071

Aegis-P1/C1 PS Driver Ver.4.0 Upgrade Procedures

Upgrading of the Aegis-P1/C1 Fiery controller to Ver4.0 will also require an upgrade of the PS driver of the PC client. The default driver names for each version are as below (for Windows)

Version	Driver Names
1.0	Pro C900 Fiery PS
2.0	Pro C900-900S Fiery PS
3.0	Pro C900-C900S Fiery PS v3
4.0	Pro C900-C900S Fiery PS v4

Please follow the procedures below for the upgrade.

1. Saving (export) the Customized Pre-settings

The following procedure is applicable only when pre-settings are registered. If pre-settings are not registered, please follow the procedures described in the section "Uninstalling the Ver.1.0-3.0 Printer Driver" of this guide.

Please refer to the help information for details.

(1) From "Start", open either the "Printer" or "Printer and Fax" folder. Right-click on the printer icon indicating PS driver Ver.1.0~3.0, and select "Printer Setup".







PAGE: 13/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071


(2) From the list box "Preset", select "Save and manage list of job templates".



(3) The "Job Templates" screen will appear. Select the pre-setting template you wish to save, and click "Export".



(4) Select the folder for saving, save the file name under the pre-setting name, then click "Save".



File extension for exported files is "sav".

This completes the exporting procedure.



PAGE: 14/16

2. Un-installing the Ver.1.0 to 3.0 PS Driver

"FieryPrinterDeleteUtility" is required to un-install the PS driver. Please install the "FieryPrinterDeleteUtility" from the user software DVD to the client PC in advance. Please refer to the section "Printing from Windows" of the "User Manual".

(1) From "Start", open either the "Printer" or "Printer and Fax" folder. Right-click on the printer icon indicating PS driver Ver.1.0~3.0, and select "Print Setup". Make sure of the driver to be uninstalled.



- (2) From "Start", select "All Programs" → "Fiery" → "FieryPrinterDeleteUtility", and activate "FieryPrinterDeleteUtility".
- (3) All printer driver types will appear. Specify the PS driver assigned in (1), and click "Delete the selected printer driver".






PAGE: 15/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071


(4) Confirm that the printer driver appears in the box "printer driver deleted". Click "Close", and reboot the client PC.



This completes the procedures for un-installing the printer driver.

- 3. Installing the PS Driver Ver.4.0 (User Software DVD)
 Please refer to the section "Print out from Windows" of the User Manual for details.
- 4. Importing the Saved Pre-settings
 This procedure will import the pre-settings saved in "1". Please refer to help information on print setup for details.

(1) Open "Print Setup" in the PS driver. From the "Preset" list box, select "Save and manage list of job templates".







PAGE: 16/16

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178071


(2) The "Job template" screen will appear. Click "Import".



(3) Select the saved pre-setting, and click "Open".



(4) In the "Pre-settings" list box, confirm that the setup name appears.



This completes the importing of the printer option setup.

Technical Bulletin

PAGE: 1/4 Reissued:16-Sep-09

Model: AG-P1 / C1	Date: 31-Jul-09	No.: RG178072a
-------------------	-----------------	----------------

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Toner Blister Conrol		Prepared by: N.iida		
From: PPBG QA	/Service Planning Dept.			
Classification:	☐ Troubleshooting	☐ Part information	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

This RTB is a revised version of "RTB No.RG178072". Refer to this RTB for "Toner Blister Control" instead of "RTB No.RG178072". There are many differences between this RTB and "RTB No.RG178072".

Countermeasure for Toner Blistering on Outputs

Overview

This explains the countermeasure for toner blistering by reducing the pressure roller temperature. In order to reduce the pressure roller temperature, new firmware has been released which includes new SP "Toner Blister Control (SP1-208-001)".

This SP mode allows the pressure roller of the machine to be away from the fusing belt before the machine has got a print job so that the temperature of the pressure roller can be kept as low as possible.

SP1208-001: Toner Blister Control

This SP is available in the following firmware versions.

	Program name	Program No.	Version	
AG-P1	System	G1786091G	V2.05	
	Engine	G1785252G	V3.000:12	
AG-C1	System	D0166091D	V1.04	
	Engine	D0165252D	V3.000:12	

Important

The adjustment of the fusing temperature and nip width of the fusing unit described on page 848 in the service manual for the AG-C1/P1 is not required to improve the blistered image on the outputs. This is because the "Toner Blister Control" compensates for the above adjustments.

If the blistered image cannot be solved by enabling the "Toner Reduction" (ON), enable "Toner Blister Control (SP1-208-001, 1: ON)".

Enabling Toner Reduction

• Turn on "Toner Reduction" in the printer driver.

Technical Bulletin

PAGE: 2/4

Reissued:16-Sep-09

Model: AG-P1 / C1 Date: 31-Jul-09 No.: RG178072a

Enabling Toner Blister Control

 For details, see the "Setting Procedure of the Toner Blister Control" described below.

Set-up Procedure for Toner Blister Control

Usage Limitation

- Do not copy or send a print job to the machine for 15 minutes (extra idle-rotation) at power-on after the "Ready" message has been shown on the operation panel.
- Touch the operation panel to recover the machine from the energy saver mode, and then wait for 15 minutes (extra idle-rotation) after the "Ready" message has been shown on the operation panel.
- DO NOT recover the machine from the energy saver mode by sending a print job.
 Otherwise, the print job may be executed just after the machine has recovered from the energy saver mode, and then the image of the outputs will be poor due to insufficient fusing temperature.

Procedure

- 1. Enter the SP mode, and then select SP1-208-001.
- 2. Change the setting of SP1-208-001 from "0" to "1".
- 3. Set the settings of SPs in the table shown below from the default or current value to the recommended value.

SP Title	SP No.	Default	Recommended
Fusing Temp Control 1/ Htg Roll: Reload	SP1-105-029	175°C	200°C
Fusing Temp Control 1/ Htg Roll: Rotation after Reload	SP1-105-030	175°C	200°C
Mode Shift Setting/ Idle Time:After Reload	SP1-107-034	7 minutes	15 minutes
Toner Blister Control/ Press Roll Ctr:Standby:Low Temp	SP1-208-005	100°C	135°C
Energy Saver Time	Set by "User Tools"	15 minutes	25 minutes

- 4. Turn off the main power by following the shut-down procedure.
- 5. Turn on the main power switch of the machine.

Note

- 1. Rebooting the machine (turning off and on the main power) is necessary to enable "Toner Blister Control (SP1-208-001)". Make sure to execute "step 4" and "step 5".
- 2. Make sure to return the settings of SPs in the table shown above to the default values if "Toner Blister Control (SP1-208-001)" is disabled ("0": OFF).

Model: AG-P1 / C1

Technical Bulletin

PAGE: 3/4 Reissued:16-Sep-09

Date: 31-Jul-09

No.: RG178072a

Appendix

Additional SPs for the Toner Blister Control

1208	Toner Blister Control
	These SPs are designed to improve the toner blister image on the outputs by reducing the temperature of the pressure roller in the fusing unit.
001	Blister 0:off/1:on
	Enables or disables the "Toner Blister Control".
	[0 or 1 / 0 / -]
	0 : Toner Blister Control OFF (default)
	1: Toner Blister Control ON
	If this SP is set to "1 (ON)", the machine pulls the pressure roller away from the fusing belt except during printing mode to prevent the temperature of the pressure roller from being too high. The machine pushes the pressure roller against the fusing belt just before a printing job is sent to the engine.
	• If this SP is set to "1 (ON)", the SPs from SP1-208-002 to - 013 are enabled, and then the temperature of the pressure roller is kept at 90°C.
002	Press Roll Ctr:Reload
	Adjusts the reload temperature of the pressure roller.
	[70 to 160 / 90 / 1°C /step]
003	Press Roll Ctr:Idle:Reload
	Adjusts the temperature of the pressure roller during the extra idle rotation after the reload.
	[70 to 160 / 90 / 1°C /step]
004	Press Roll Ctr:Standby:Normal Temp
	Adjusts the target temperature of the pressure roller in the stand- by mode of the normal temperature condition.
	[70 to 160 / 90 / 1°C /step]
005	Press Roll Ctr:Standby:Low Temp
	Adjusts the target temperature of the pressure roller in the stand- by mode of the low temperature condition.
	[70 to 160 / 100 / 1°C /step]
006	Press Roll Ctr:Standby:High Temp

PAGE: 4/4

Reissued:16-Sep-09

Model: AG-P1 / C1	Date: 31-Jul-09	No.: RG178072a		
Adjusts the target temperature of the by mode of the high temperature con	-	tand-		
[70 to 160 / 90 / 1°C /step]				
007 Thin:Press Roll Temp	Thin:Press Roll Temp			
Adjusts the target temperature of the paper.	pressure roller for the t	hin		
[70 to 160 / 90 / 1°C /step]				
008Normal:Press Roll Temp				
Adjusts the target temperature of the (normal) paper.	pressure roller for the p	olain		
[70 to 160 / 90 / 1°C /step]				
009Middle:Press Roll Temp				
Adjusts the target temperature of the middle thick paper.	pressure roller for the			
[70 to 160 / 90 / 1°C /step]				
010 Thick1:Press Roll Temp				
Adjusts the target temperature of the paper.	pressure roller for the t	hick1		
[70 to 160 / 90 / 1°C /step]				
011 Thick2:Press Roll Temp				
Adjusts the target temperature of the paper.	pressure roller for the t	hick2		
[70 to 160 / 90 / 1°C /step]				
012Thick3:Press Roll Temp				
Adjusts the target temperature of the paper.	pressure roller for the t	hick3		
[70 to 160 / 90 / 1°C /step]				
013 Press Roll Temp:Low Power Mode				
Adjusts the target temperature of the power mode.	pressure roller in the lo	ow		
[70 to 160 / 150 / 1°C /step]				

Technical Bulletin

PAGE: 1/8

Model: Aegis-P1/C1			Date: 11-Aug-09		-09	No.: RG178073
Subject: Manual Corrections for AG-P1/C1 Fusing SP Prepared by: N.iida						
From: PPBG QA/Service Planning Dept.						
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
		☐ Electric	al		⊠ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	☐ Tier 2	

The Service Manual for AG-P1/C1 was corrected in red text as follows:

• On pages from 953 to 966

1105*	Fusing Temp Control 1
029	Htg Roll: Reload
	Adjusts the reload temperature of the heating roller.
	[150 to 200 / 175 / 1°C]
030	Htg Roll: Rotation after Reload
	Adjusts the threshold temperature for the idle rotation of the heating
	roller after reload.
	[150 to 200 / 175 / 1°C]
031	Htg Roll: Stand-by: Normal Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for normal temperature.
	[150 to 200 / 175 / 1°C]
032	Htg Roll: Stand-by:Low Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for low temperature.
200	[150 to 200 / 185 / 1°C]
033	Htg Roll: Stand-by:High Temp.
	Adjusts the target temperature of the heating roller in stand-by mode
	for high temperature. [150 to 200 / 175 / 1°C]
040	Plain: BW: Uncoated
040	[130 to 200 / 175: NA, 180: EU / 1°C]
041	Plain: FC: Uncoated
041	[130 to 200 / 175: NA, 180: EU / 1°C]
042	Thin: BW: Uncoated
042	[130 to 200 / 160: NA, 165: EU / 1°C]
043	Thin: FC: Uncoated
043	[130 to 200 / 160: NA, 165: EU / 1°C]
044	Middle Thick: BW: Uncoated
	[130 to 200 / 175 / 1°C]
045	Middle Thick: FC: Uncoated
	[130 to 200 / 175 / 1°C]
046	Thick 1: BW: Uncoated
	[130 to 200 / 185 / 1°C]
047	Thick 1: FC: Uncoated

PAGE: 2/8

Model: Aeg	gis-P1/C1	Date: 11-Aug-09	No.: RG178073
	[130 to 200 / 185 / 1°C]		
048	Thick 2: BW: Uncoated		
	[130 to 200 / 190 / 1°C]		
049	Thick 2: FC: Uncoated		
	[130 to 200 / 190 / 1°C]		
050	Thick 3: BW: Uncoated		
	[130 to 200 / 195 / 1°C]		
051	Thick 3: FC: Uncoated		
	[130 to 200 / 195 / 1°C]		
052	Plain: Duplex BW: Uncoated		
	[130 to 200 / 175 : NA , 180 : EU / 1°C]		
053	Plain: Duplex FC: Uncoated		
	[130 to 200 / 175: NA, 180: EU / 1°C]		
054	Thin: Duplex BW: Uncoated		
	[130 to 200 / 160: NA, 165: EU / 1°C]		
055	Thin: Duplex FC: Uncoated		
	[130 to 200 / 160: NA, 165: EU / 1°C]		
056	Middle Thick: DUPLEX BW: Uncoated		
	[130 to 200 / 175 / 1°C]		
057	Middle Thick: DUPLEX FC: Uncoated		
050	[130 to 200 / 175 / 1°C]		
058	Thick 1: DUPLEX BW: Uncoated		
050	[130 to 200 / 185 / 1°C] Thick 1: FC: DUPLEX Uncoated		
039	[130 to 200 / 185 / 1°C]		
060	Thick 2: DUPLEX BW: Uncoated		
000	[130 to 200 / 190 / 1°C]		
061	Thick 2: DUPLEX FC: Uncoated		
	[130 to 200 / 190 / 1°C]		
068	Plain: BW: Coated P1		
	[130 to 200 / 175 / 1°C]		
069	Plain: FC: Coated P1		
	[130 to 200 / 175 / 1°C]		
070	Thin: BW: Coated P1		
	[130 to 200 / 165 / 1°C]		
071	Thin: FC: Coated P1		
	[130 to 200 / 165 / 1°C]		
072	Middle Thick: BW: Coated P1		
	[130 to 200 / 180: NA, 185: EU / 1°C]		
073	Middle Thick: FC: Coated P1		
	[130 to 200 / 180 : NA , 185 : EU / 1°C]		
074	Thick 1: BW: Coated P1		
	[130 to 200 / 180 : NA , 195 : EU / 1°C]		
075	Thick 1: FC: Coated P1		
	[130 to 200 / 180 : NA , 195 : EU / 1°C]		
076	Thick 2: BW: Coated P1		

PAGE: 3/8

[130 to 200 / 190 / 1°C] 077 Thick 2: FC: Coated P1 [130 to 200 / 190 / 1°C]	
077 Thick 2: FC: Coated P1 [130 to 200 / 190 / 1°C]	
[130 to 200 / 190 / 1°C]	
078 Thick 3: BW: Coated P1	
[130 to 200 / 195: NA, 200: EU / 1°C]	
079 Thick 3: FC: Coated P1	
[130 to 200 / 195: NA, 200: EU / 1°C]	
080 Plain: Duplex BW: Coated P1	
[130 to 200 / 175 / 1°C]	
081 Plain: Duplex FC: Coated P1	
[130 to 200 / 175 / 1°C]	
082 Thin: Duplex BW: Coated P1	
[130 to 200 / 165 / 1°C]	
083 Thin: Duplex FC: Coated P1	
[130 to 200 / 165 / 1°C]	
084 Middle Thick: DUPLEX BW: Coated P1	
[130 to 200 / 180: NA, 185: EU / 1°C]	
085 Middle Thick: DUPLEX FC: Coated P1	
[130 to 200 / 180 : NA , 185 : EU / 1°C]	
086 Thick 1: DUPLEX BW: Coated P1	
[130 to 200 / 180 : NA, 195 : EU / 1°C]	
087 Thick 1: FC: DUPLEX Coated P1	
[130 to 200 / 180: NA, 195: EU / 1°C]	
088 Thick 2: DUPLEX BW: Coated P1	
[130 to 200 / 190 / 1°C] 089 Thick 2: DUPLEX FC: Coated P1	
[130 to 200 / 190 / 1°C]	
096 Plain: BW: Coated P2	
[130 to 200 / 180 / 1°C]	
097 Plain: FC: Coated P2	
[130 to 200 / 180 / 1°C]	
098 Thin: BW: Coated P2	
[130 to 200 / 165 / 1°C]	
099 Thin: FC: Coated P2	
[130 to 200 / 165 / 1°C]	
100 Middle Thick: BW: Coated P2	
[130 to 200 / 185: NA, 175: EU / 1°C]	
101 Middle Thick: FC: Coated P2	
[130 to 200 / 185: NA, 175: EU / 1°C]	
102 Thick 1: BW: Coated P2	
[130 to 200 / 185: NA, 195: EU / 1°C]	
103 Thick 1: FC: Coated P2	
[130 to 200 / 185: NA, 195: EU / 1°C]	
104 Thick 2: BW: Coated P2	
[130 to 200 / 195: NA, 190: EU / 1°C]	
105 Thick 2: FC: Coated P2	

PAGE: 4/8

[130 to 200 / 195 : NA , 190 : EU / 1°C] 106 Thick 3: BW: Coated P2 [130 to 200 / 195 : NA , 200 : EU / 1°C] 107 Thick 3: FC: Coated P2	
106 Thick 3: BW: Coated P2 [130 to 200 / 195: NA, 200: EU / 1°C]	
107 Thick 3: FC: Coated P2	
107 ITHION O. I O. Obdica I Z	
[130 to 200 / 195 : NA , 200 : EU / 1°C]	
108 Plain: Duplex BW: Coated P2	
[130 to 200 / 180 / 1°C]	
109 Plain: Duplex FC: Coated P2	
[130 to 200 / 180 / 1°C]	
110 Thin: Duplex BW: Coated P2	
[130 to 200 / 165 / 1°C]	
111 Thin: Duplex FC: Coated P2	
[130 to 200 / 165 / 1°C] 112 Middle Thick: DUPLEX BW: Coated P2	
[130 to 200 / 185: NA, 175: EU / 1°C]	
113 Middle Thick: DUPLEX FC: Coated P2	
[130 to 200 / 185: NA, 175: EU / 1°C]	
114 Thick 1: DUPLEX BW: Coated P2	
[130 to 200 / 185: NA, 195: EU / 1°C]	
115 Thick 1: FC: DUPLEX Coated P2	
[130 to 200 / 185: NA, 195: EU / 1°C]	
116 Thick 2: DUPLEX BW: Coated P2	
[130 to 200 / 195 : NA, 190 : EU / 1°C]	
117 Thick 2: DUPLEX FC: Coated P2	
[130 to 200 / 195 : NA, 190 : EU / 1°C]	
124 Plain: BW: Coated P3	
[130 to 200 / 175 / 1°C]	
125 Plain: FC: Coated P3	
[130 to 200 / 175 / 1°C]	
126 Thin: BW: Coated P3	
[130 to 200 / 170 / 1°C]	
127 Thin: FC: Coated P3	
[130 to 200 / 170 / 1°C] 128 Middle Thick: BW: Coated P3	
[130 to 200 / 190: NA, 185: EU / 1°C]	
129 Middle Thick: FC: Coated P3	
[130 to 200 / 190: NA, 185: EU / 1°C]	
130 Thick 1: BW: Coated P3	
[130 to 200 / 190: NA, 195: EU / 1°C]	
131 Thick 1: FC: Coated P3	
[130 to 200 / 190: NA, 195: EU / 1°C]	
132 Thick 2: BW: Coated P3	
[130 to 200 / 195 / 1°C]	
133 Thick 2: FC: Coated P3	
[130 to 200 / 195 / 1°C]	
134 Thick 3: BW: Coated P3	

PAGE: 5/8

Model: Aeg	gis-P1/C1	Date: 11-Aug-09	No.: RG178073
	[130 to 200 / 200: NA, 195: EU / 1°C]		
135	Thick 3: FC: Coated P3		
	[130 to 200 / 200: NA, 195: EU / 1°C]		
136	Plain: Duplex BW: Coated P3		
	[130 to 200 / 175 / 1°C]		
137	Plain: Duplex FC: Coated P3		
	[130 to 200 / 175 / 1°C]		
138	Thin: Duplex BW: Coated P3		
	[130 to 200 / 170 / 1°C]		
139	Thin: Duplex FC: Coated P3		
	[130 to 200 / 170 / 1°C]		
140	Middle Thick: DUPLEX BW: Coated P3		
	[130 to 200 / 190 : NA, 185 : EU / 1°C]		
141	Middle Thick: DUPLEX FC: Coated P3		
	[130 to 200 / 190: NA, 185: EU / 1°C]		
142	Thick 1: DUPLEX BW: Coated P3		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
143	Thick 1: FC: DUPLEX Coated P3		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
144	Thick 2: DUPLEX BW: Coated P3		
	[130 to 200 / 195 / 1°C]		
145	Thick 2: DUPLEX FC: Coated P3		
	[130 to 200 / 195 / 1°C]		
152	Plain: BW: SP1		
	[130 to 200 / 185 : NA , 180 : EU / 1°C]		
153	Plain: FC: SP1		
	[130 to 200 / 185 : NA , 180 : EU / 1°C]		
154	Thin: BW: SP1		
455	[130 to 200 / 170 / 1°C]		
155	Thin: FC: SP1		
450	[130 to 200 / 170 / 1°C]		
156	Middle Thick: BW: SP1		
157	[130 to 200 / 185 / 1°C]		
157	Middle Thick: FC: SP1		
150	[130 to 200 / 185 / 1°C] Thick 1: BW: SP1		
130	[130 to 200 / 195: NA, 190: EU / 1°C]		
150	Thick 1: FC: SP1		
159	[130 to 200 / 195 : NA , 190 : EU / 1°C]		
160	Thick 2: BW: SP1		
100	[130 to 200 / 200: NA, 195: EU / 1°C]		
161	Thick 2: FC: SP1		
101	[130 to 200 / 200: NA, 195: EU / 1°C]		
162	Thick 3: BW: SP1		
102	[130 to 200 / 195 / 1°C]		
163	Thick 3: FC: SP1		
103	11110K 0. 1 O. OI 1		

[130 to 200 / 195 / 1°C] 164 Plain: Duplex BW: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 165 Plain: Duplex FC: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C]
164 Plain: Duplex BW: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 165 Plain: Duplex FC: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] Thin: BW: SP2 [130 to 200 / 180 / 1°C]
[130 to 200 / 185: NA, 180: EU / 1°C] 165 Plain: Duplex FC: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] Thin: BW: SP2
165 Plain: Duplex FC: SP1 [130 to 200 / 185: NA, 180: EU / 1°C] 166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 185: NA, 180: EU / 1°C] 166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
166 Thin: Duplex BW: SP1 [130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 170 / 1°C] 167 Thin: Duplex FC: SP1 [130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 170 / 1°C] 168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
168 Middle Thick: DUPLEX BW: SP1 [130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 185 / 1°C] 169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
169 Middle Thick: DUPLEX FC: SP1 [130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 185 / 1°C] 170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
170 Thick 1: DUPLEX BW: SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 195: NA, 190: EU / 1°C] 171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
171 Thick 1: FC: DUPLEX SP1 [130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 195: NA, 190: EU / 1°C] 172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
172 Thick 2: DUPLEX BW: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200: NA, 195: EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 200 : NA , 195 : EU / 1°C] 173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200 : NA , 195 : EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
173 Thick 2: DUPLEX FC: SP1 [130 to 200 / 200 : NA , 195 : EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 200 : NA , 195 : EU / 1°C] 180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
180 Plain: BW: SP2 [130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 180 / 1°C] 181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
181 Plain: FC: SP2 [130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
[130 to 200 / 180 / 1°C] 182 Thin: BW: SP2
182 Thin: BW: SP2
183 Thin: FC: SP2
[130 to 200 / 175 / 1°C]
184 Middle Thick: BW: SP2
[130 to 200 / 190 / 1°C]
185 Middle Thick: FC: SP2
[130 to 200 / 190 / 1°C]
186 Thick 1: BW: SP2
[130 to 200 / 200 / 1°C]
187 Thick 1: FC: SP2
[130 to 200 / 200 / 1°C]
188 Thick 2: BW: SP2
[130 to 200 / 190 : NA , 195 : EU / 1°C]
189 Thick 2: FC: SP2
[130 to 200 / 190 : NA, 195 : EU / 1°C]
190 Thick 3: BW: SP2
[130 to 200 / 200: NA, 195: EU / 1°C]
191 Thick 3: FC: SP2
[130 to 200 / 200: NA, 195: EU / 1°C]
192 Plain: Duplex BW: SP2

PAGE: 7/8

Model: Aeg	gis-P1/C1	Date: 11-Aug-09	No.: RG178073
	[130 to 200 / 180 / 1°C]		
193	Plain: Duplex FC: SP2		
	[130 to 200 / 180 / 1°C]		
194	Thin: Duplex BW: SP2		
	[130 to 200 / 175 / 1°C]		
195	Thin: Duplex FC: SP2		
	[130 to 200 / 175 / 1°C]		
196	Middle Thick: DUPLEX BW: SP2		
	[130 to 200 / 190 / 1°C]		
197	Middle Thick: DUPLEX FC: SP2		
	[130 to 200 / 190 / 1°C]		
198	Thick 1: DUPLEX BW: SP2		
	[130 to 200 / 200 / 1°C]		
199	Thick 1: FC: DUPLEX SP2		
	[130 to 200 / 200 / 1°C]		
200	Thick 2: DUPLEX BW: SP2		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
201	Thick 2: DUPLEX FC: SP2		
	[130 to 200 / 190: NA, 195: EU / 1°C]		
208	Plain: BW: SP3		
	[130 to 200 / 190: NA, 180: EU / 1°C]		
209	Plain: FC: SP3		
	[130 to 200 / 190: NA, 180: EU / 1°C]		
210	Thin: BW: SP3		
	[130 to 200 / 180 / 1°C]		
211	Thin: FC: SP3		
	[130 to 200 / 180 / 1°C]		
212	Middle Thick: BW: SP3		
	[130 to 200 / 190 / 1°C]		
213	Middle Thick: FC: SP3		
011	[130 to 200 / 190 / 1°C]		
214	Thick 1: BW: SP3		
045	[130 to 200 / 200 / 1°C]		
215	Thick 1: FC: SP3		
040	[130 to 200 / 200 / 1°C]		
216	Thick 2: BW: SP3		
247	[130 to 200 / 200 / 1°C] Thick 2: FC: SP3		
217			
210	[130 to 200 / 200 / 1°C]		
218	Thick 3: BW: SP3 [130 to 200 / 200 / 1°C]		
210	Thick 3: FC: SP3		
219	[130 to 200 / 200 / 1°C]		
220	Plain: Duplex BW: SP3		
	[130 to 200 / 190: NA, 180: EU / 1°C]		
221	Plain: Duplex FC: SP3		
	i iaiii. Dupiex i O. OF J		

Technical **B**ulletin

PAGE: 8/8

Model: Ae	gis-P1/C1	Date: 11-Aug-09	No.: RG178073
	[130 to 200 / 190: NA, 180: EU / 1°C]		
222	Thin: Duplex BW: SP3		
	[130 to 200 / 180 / 1°C]		
223	Thin: Duplex FC: SP3		
	[130 to 200 / 180 / 1°C]		
224	Middle Thick: DUPLEX BW: SP3		
	[130 to 200 / 190 / 1°C]		
225	Middle Thick: DUPLEX FC: SP3		
	[130 to 200 / 190 / 1°C]		
226	Thick 1: DUPLEX BW: SP3		
	[130 to 200 / 200 / 1°C]		
227	Thick 1: FC: DUPLEX SP3		
	[130 to 200 / 200 / 1°C]		
228	Thick 2: DUPLEX BW: SP3		
	[130 to 200 / 200 / 1°C]		
229	Thick 2: DUPLEX FC: SP3		
	[130 to 200 / 200 / 1°C]		


Model: AG-P1 / C1 Da			Dat	e: 31-Aug-	-09	No.: RG178074
Subject: TRANSPORT ROLLER			Prepared	d by: N.iid	da	
From: PPBG QA	Service Planning Dept.					
Classification:		□ Part info	rma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

Old part	New part	Description		Int		Page	Index
number	number	·					
G1784885	G1784855	TRANSPORT ROLLER:DRIVEN:PAPER EXIT UNIT		X/X	As a set	153	11
AA063675 -	_	SPRING - 5N	6→2	X/X	O/O	153	10
-	AA063678	SPRING - 3.5N	0→4			153	-
AF022171		TRANSPORT ROLLER:DRIVEN:DIA18X2	1→0	0	/O	153	16
	G1784855	TRANSPORT ROLLER:DRIVEN:PAPER EXIT UNIT	0→1			153	16

SYMPTOM

Curls, Scratches, or Roller Marks on paper edge







PAGE: 1/3

Numerous tiny scratches on paper edge


CAUSE


Shape of the Transport Rollers and their pressure applied to the paper

SOLUTION

Please exchange with the NEW Transport Rollers and NEW Springs.

The NEW Transport Rollers have been widened with a slight curve on the surface and a rounder edge. The NEW Springs will apply optimum amount of pressure.








PAGE: 2/3


Model: AG-P1 / C1 Date: 31-Aug-09 No.: RG178074

Change rollers (2x G1784855) + springs (4x AA063678)



Change roller (1x G1784855) only.

Parts catalog information




PAGE: 3/3

Model: AG-P1 / C1 Date: 31-Aug-09 No.: RG178074

REFERENCE

For the determination of whether or not the curls/scratches/marks are caused by the rollers, please check and compare the pitch of the curls/scratches/marks against the pitch of the rollers.



Technical Bulletin

PAGE: 1/5

Model: AG-P1 / C1 Date				t e : 15-Sep-09		No.: RG178075
Subject: Problems involving Update to Fiery Ver4.0					by: T.Sat	oh
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part informati		rmation		n required
	☐ Mechanical	☐ Electric	cal		☐ Servi	ce manual revision
	☐ Paper path	☐ Transm	nit/red	ceive	☐ Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	2

Problems involving Update to the Aegis-C1/P1 TENRYU Supported Version (G4.0)

1. Overview of the Problem

The following symptoms occur when updating from the initial Aegis-P1 (G1.0) and the initial Aegis-C1 (G2.0) to the Aegis-C1/P1 TENRYU supported version (G4.0).

Symptom "A"

When restoring backup setting data:

Symptom "A-1": Cannot active CWPT

Symptom "A-2": Cannot utilize the Remote Desktop

Symptom "B"

Cannot register/display Address Book data

Request to Regional HQ Service

Please consider the following support when updating from the initial Aegis-P1 (G1.0) and the initial Aegis-C1 (G2.0) to the Aegis-C1/P1 TENRYU supported version (G4.0).

Aegis-P1

Backup & Restore will not function. Please manually restore system data.

Supplementary explanation: Both symptoms "A-1" and "A-2" will not occur as long as Backup & Restore function is not used.

Symptom "B" (Address book problems) is irrelevant as it is a feature only on the AegisC1.

Aegis-C1

Backup & Restore will not function. Please manually restore system data.

Cannot register data in the address book. Please manually backup the address book on the current version (#GetAddressBook Admin), and wait until patch release to resolve symptom "B". When the patch is released, please make the settings manually.

In addition, the address book functions on the FieryScan Scan-to-E-mail. Please apply features such as the SMB/HoldQue/FTP to substitute the address book.

Following are the system settings available for backup/restore. (See appendix 1 for details.)

- System Setting
- · Virtual Printer Setting
- · Address Book
- · User Authentication Database

PAGE: 2/5

Model: AG-P1 / C1 Date: 15-Sep-09 No.: RG178075

- · Spot Color Setting
- · Paper Catalog Setting
- Job Log

2. Symptom "A" - Inactive CWPT

2.1. Symptom Details

CWPT will not activate if the backup system settings data on the initial Aegis-P1 (G1.0) or the initial Aegis-C1 (G2.0) are restored on the Aegis-C1/P1 TENRYU supported version (G4.0) -symptom "A-1". Due to this, among the backup system setting data, color related setting values cannot be utilized.

Also, the Remote Desktop will not function - symptom "A-2".




Fig 2.1.1. Backup/Restore of System Setting Data

"Table 2.1.1." displays the combination of the versions in which the symptom occurs.

Table 2.1.1. List of Symptom Occurring Version Combinations

		- julpioni - committee - commi					
		Backup					
		Aegis-P1 Initial ver. (G1.0)	Aegis-C1 Initial ver. (G2.0)	Aegis-C1/P1 New peripherals supported ver. (G3.0)	Aegis-C1/P1 TENRYU supported ver. (G4.0)		
Restore	Aegis-P1 Initial ver. (G1.0)	0	-	-	-		
	Aegis-C1Initial ver. (G2.0)	0	0	-	-		
	Aegis-C1/P1 New peripherals supported ver. (G3.0)	0	0	0	-		
	Aegis-C1/P1 TENRYU supported ver. (G4.0)	×	×	0	0		



PAGE: 3/5

Model: AG-P1 / C1 Date: 15-Sep-09 No.: RG178075

2.2. Cause

2.2.1. Symptom "A-1" - Inactive CWPT

CWPT could not be activated because different device names were assigned for the initial Aegis-P1 (G1.0) and the Aegis-C1/P1 TENRYU supporting version (G4.0).

However, if this is the cause, the same symptom is expected to occur between the initial Aegis-P1 (G1.0) / initial Aegis-C1 (G2.0) and the Aegis-C1/P1 new peripherals supporting version (G3.0), but works fine. This is being investigated at EFI.

Table 2.2.1. Assigned Device Names

	Device Names
Aegis-P1 initial ver. (G1.0)	Pro C900
Aegis-C1 initial ver. (G2.0)	Pro C900S
Aegis-C1/P1 new peripherals supported ver. (G3.0)	Pro C900- C900S
Aegis-C1/P1 TENRYU support ver. (G4.0)	Pro C900-
	C900S

2.2.2. Symptom "A-2" - Inactive Remote Desktop

Now being investigated at EFI.

2.3. Workaround

2.3.1. Symptom "A-1" - Inactive CWPT

This symptom will be resolved without having to change the device names.

2.3.2. Symptom "A-2" - Inactive Remote Desktop

Now being investigated at EFI.

2.4. Workaround Schedule

Patch to resolve the update problem from the Aegis-P1 initial version (G1.0) to the Aegis-C1/P1 TENRYU supported version (G4.0) has been released from EFI, and the symptom is being analyzed.

Unclear Points

The Color Profile which is included as a backup file for the Aegis-P1 initial version (G1.0) is eliminated on the Aegis-C1/P1 TENRYU supported version (G4.0).

RCL's inquiry to EFI

The reason why Color Profile created by the user has been eliminated from the backup data on the Aegis-C1/P1 TENRYU supported version (G4.0).

In addition, a patch has not been released to upgrade from the Aegis-C1 initial version (G2.0) to the Aegis-C1/P1 TENRY supported version (G4.0).

We are confirming the schedule for this matter.

Technical Bulletin

PAGE: 4/5

Model: AG-P1 / C1 Date: 15-Sep-09 No.: RG178075

3. Symptom "B" - Unable to register/display Address Book on the Aegis-C1/P1 TENRYU supported version (G4.0)

3.1. Symptom Details

Address Book data cannot be registered nor displayed on the Aegis-C1/P1 TENRYU supported version (G4.0).

Due to this, the Address Book backup data on the Aegis-P1 initial version (G1.0) and/or the Aegis-C1 initial version (G2.0) cannot be accessed on the Aegis-C1/P1 TENRYU supported version (G4.0).




Fig. 3.1.1. Backup of System Setting Data

3.2. Cause

Incorrect program for processing the Address Book

3.3. Workaround

Incorrect program for processing the Address Book has been resolved.

3.4. Workaround Schedule

Patch to resolve the problem has been released from EFI, and the symptom is being analyzed.

4. Affect on the QX

Symptom A will not occur on the QX since QX1.0 corresponds to the Aegis-C1/P1 new peripherals supported version (G3.0), and QX2.0 corresponds to the Aegis-C1/P1 TENRYU supported version (G4.0). (See Table 2.1.1)

As for Symptom B, the problem has been resolved on the QX2.0GM version.

Therefore, this case is irrelevant and has no affect on the QX.

Technical Bulletin

PAGE: 5/5

Model: AG-P1 / C1 Date: 15-Sep-09 No.: RG178075

Appendix 1: Available System Settings for Backup/Restore

Backup and Restore: System Settings

Fiery systems support a mechanism to backup and restore specific system settings. Back up and restore procedures are initiated by accessing: Server >> SetUp >> Server >> Backup/Restore (from inside Command Workstation), or by using Web Tools 2.0 (or later). A comprehensive list of settings that are backed up/restored includes*:

- All system settings with the exclusion of:
 - Server name -allows backup restore between same model
 - Date/time and Timezone settings
- Preflight setups*
- Virtual printer setups
- Address books
- User authentication database
- Modified spot colors*+
- Paper catalog*
- Job Log

Note: * Not all items are available on all systems. Individual items can be backed up and restored only when available on that system.

Note: + Modified Spot colors will be saved, e.g. user edits to the default spot colors included in the system. Custom spot colors, custom spot color groups and substitute colors will not be backed up.

Technical Bulletin

PAGE: 1/1

Model: AG-P1 / C1			Dat	:e: 16-Sep-	-09	No.: RG178076
Subject: Fusing Temperature Check				Prepared	d by: N.iid	da
From: PPBG QA/	Service Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	$oxed{\boxtimes}$ Other ()	☐ Tier 2	

SYMPTOM

The following SPs always display the wrong temperature ("0°C") of the fusing unit.

- SP1-106-003: Fusing Temp Display/ Htg Roll Temp: Center
- SP1-106-004: Fusing Temp Display/ Htg Roll Temp: End
- SP1-106-004: Fusing Temp Display/ Htg Roll Temp: End

CAUSE

These SPs are not enabled.

SOLUTION

To check the temperature of the fusing unit, use the following SPs.

- P5-803-150: Temperature at the ends of the heating roller
- P5-803-151: Temperature of the pressure roller
- P5-803-152: Temperature at the center of the heating roller

Technical Bulletin

PAGE: 1/2

Model: AG-P1 / C1		Dat	e: 30-Sep	-09	No.: RG178077	
Subject: Solution for Light Spots Image at Toner End			Prepared by: N.iida		da	
From: PPBG QA/Service Planning Dept.						
Classification:		☐ Part info	orma	tion		required
	☐ Mechanical	☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path ☐ Transmit/re		it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2	

SYMPTOM

The machine prints light spots (with or without solidified toner) on the output just before or after the machine has detected toner end.

CAUSE

The solidified toner is generated when the toner pump rotates without toner to determine if the toner bottle is empty or not. As a result, the solidified toner may cause light spots on the output.

SOLUTION

Before Image Problem

Change the following settings in the SP Mode to the recommended settings if a service engineer visits a customer site.

SP No.	SP Title	Default Setting	Recommended Setting
SP3-411-001	TNE Detect:Disp/Set TNE:Threshold:K	10 (times)	3 (times)
SP3-411-002	TNE Detect:Disp/Set TNE:Threshold:Col	10 (times)	3 (times)
SP3-411-007	TNE Detect:Disp/Set TNE:Start-up Thresh:K	500 (g)	150 (g)
SP3-411-008	TNE Detect:Disp/Set TNE:Start-up Thresh:Col	500 (g)	150 (g)

- SP3-411-001 adjusts the number of the toner end detection for the black toner.
- SP3-411-002 adjusts the number of the toner end detection for the cyan, magenta and yellow toner.
- SP3-411-007 adjusts the threshold amount for the start trigger of the black toner end detection.
- SP3-411-008 adjusts the threshold amount for the start trigger of the color (cyan, magenta and yellow) toner end detection.

PAGE: 2/2


Model: AG-P1 / C1 Date: 30-Sep-09 No.: RG178077

After Image Problem

If the machine prints light spots (with or without solidified toner) on the output just before or after the machine has detected toner end, print 200 - 400 sheets of paper (A3/ DLT) with 100% coverage (target color) to expel the solidified toner from the development unit. For details of how to print, see the following procedure.

For Printer G178

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" with SP2109-002.
- 3. Select one of colors (YMCK) with SP2-109-004 as shown below.



g178r691

"0": Not selected, "1": Selected

- [1] for "Black". Press the "3" key on the operation panel if you want to select this color
- [2] for **"Cyan"**. Press the **"2"** key on the operation panel if you want to select this color.
- [3] for **"Magenta"**. Press the **"1"** key on the operation panel if you want to select this color
- [4] for "Yellow". Press the "0" key on the operation panel if you want to select this color.
- 4. Press the "APL Window" button to enter the copy screen.
- 5. Print a test pattern 200 400 sheets from a PC.
- 6. Check the output if the problem is solved. If not, try this procedure again.
- 7. Exit the SP mode after the machine has completed printing.

For Copier D016

- 1. Enter the SP mode.
- 2. Select "20: 100% Coverage" with SP2109-002.
- 3. Select one of colors (YMCK) with SP2-109-004 as shown above.
- 4. Press the "APL Window" button to enter the copy screen.
- 5. Input a number of pages from 200 to 400 with the numeric keys, and then select "Full Color" mode.
- 6. Press the "Start" key on the operation panel.
- 7. Check the output if the problem is solved. If not, try this procedure again.
- 8. Exit the SP mode after the machine has completed printing.

Technical Bulletin

PAGE: 1/5

Model: AG-P1/C1 D		Date: 05-Oct-09		09	No.: RG178078	
Subject: Release note for Fiery Color Controller E-80 System Software Version 2.0		em	Prepared	d by: A.T	ājima	
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☑ Other (al		Servic	required ce manual revision fit information

This RTB is the release note for Fiery Color Controller E-80 System Software Version 2.0 for ProC900(P1)/ProC900s(C1).

1.Newly Added Functions

-Support of New Peripherals

Book Binder GB5000 (Perfect Binder)

-Supporting of the Tray Association function

Selection made in the Command Work Station's paper catalog will rewrite the tray information on the engine side.

2. Changed items from Ver.1.0 to Ver.2.0:

The items for E-80 will be changed from October 2009 mass production

011		5 ' "		
Old part	New part	Description	Int	Note
number	number			
M3826713 \		SERVICE:MEDIA:45085465	X/O	Service Kit
	M3826714	SERVICE: V2.0:45087907		
M3826730 \		DVD-ROM:	X/O	User
\	Į	USER_SOFT:45084435		Software
	M3826733	DVD-ROM:		
		USER_SOFT_V2.0:45087902		
M3826740 _\		DVD-ROM:	X/O	System
		SYSTEM_SOFT:45084434		Software
	M3826743	DVD-ROM:		DVD
		SYSTEM_V2.0: 45087901		
M3826715\		PACK:QX100:MEDIA:	X/O	Media
\	Į	NA:45084430		Package
	M3826719	PACK:MEDIA:V2.0		(NA)
		NA:45087903		
M3826716		PACK:QX100:MEDIA:	X/O	Media
		EU:45084432		Package
	M3826720	PACK:MEDIA:V2.0:		(EU)
		EU:45087905		
M3821010		MOTHER BOARD:	0/0	Motherboard
		S5387:45083548 B	-	Kit



Model: AG-P1/C1

Technical Bulletin

No.: RG178078 Date: 05-Oct-09

PAGE: 2/5

3. Cases involving Specification Adjustments

Among the cases that involved specification adjustments for the E-80 System Software Version 1.0, the following 10 symptoms have been corrected for the System software Version 2.0.

	Symptoms
1	In the window "Kanji: CWS: Insert Tab", error message is indicated in Roman.
2	When interrupting a copy job with a print job and cancelling the copy job, the machine stops as it indicates "printing".
3	Cancellation of a job under certain conditions could cause SC919 (GW Restart).
4	Print job cannot be operated from the driver when the side cover of the Cover Interposer is left open.
5	Although input of characters other than a one-byte number is available for the "Document Box Password" of the PS driver, when such characters are input, they are not saved in the document box.
6	When an incorrect password is input to the document box in the "outline" tab of CWS job properties, the error message does not clear, and disables the CWS operation.
7	In the "color setting" tab of the PS driver, some characters are displayed incorrectly.
8	Revision dates in the document tab of Webtools are indicated incorrectly.
9	When printing from the driver in the setting "Booklet: saddle stitch" + "Composite over print: ON", part(s) of the image are colored incorrectly.
10	Under certain conditions, the black characters are surrounded with Cyan.
11	It is impossible to refer and edit address book by e-mail.

PAGE: 3/5

Model: **AG-P1/C1** Date: 05-Oct-09 No.: RG178078

Note:

- It is necessary to update User Software / Printer Driver when you update to System Software Version 2.0.

Utility version: after updating User Software version 2.0

These versions are the same as the version for system software version 4.0 for Aegis-P1/C1 EFI

Windows

Command Work Station	4.8.0.11
Fiery Color Wise Pro Tools	3.10.0.11
Fiery Remote Scan	5.5.1.34
Fiery Remote Scan(TWAIN)	5.5.1.34
Fiery Printer Delete Utility	2.0.0.19
EFI Hot Folders	2.6.0.01
VDP Resource Manager	1.3.0.16
Fiery Bridge	1.1.0.28

Mac OS X

CWS Macintosh Edition	1.7.0f.05
Color Wise Pro Tools	3.11.0.11
Fiery Remote Scan	5.6.0f19
Fiery Remote Scan(TWAIN)	5.6.0f19
EFI Hot Folders	2.6.0f.03
OSX VDP Resource Manager	1.4.0.07

PAGE: 4/5

Model: **AG-P1/C1** Date: 05-Oct-09 No.: RG178078

- It is necessary to update firmware of the mainframe when you update the System Software Version 2.0.

Latest firmware version:

These versions are the same as the version required for system software version 4.0 for Aegis-P1/C1 EFI

Aegis-C1

*Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	D0166091D	1.04
Scanner	D0166097B	1.05
WebSupport	D0166093B	1.03
WebUApl	D0166095C	1.12
Network Support (NCS)	D0166092B	7.04.1
Network DocBox(NFA)	D0166096B	1.03
Engine	D0165252D	3.000:12
LCDC	NA:G1785975C	1.06
	EU: G1785976C	
Animation	D0166094A	1.6
Language	G1785980A	1.06
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	
Type 5000		V1.000:03

Technical Bulletin

PAGE: 5/5

Model: AG-P1/C1 No.: RG178078 Date: 05-Oct-09

<u>Aegis-P1</u> *Please make sure that ALL versions listed below are updated concurrently.

Program Name	Program No.	Version
System	G1786091G	2.05
Websystem	G1786093E	1.53
Network Support (NCS)	G1786092D	7.04
Engine	G1785252G	3.000:12
LCDC	NA:G1785971C	1.03
	EU : G1785972C	
Animation	G1786094B	2.2
Language	G1785979A	1.03
Fiery Server	-	4.0

* Update to the following versions is required for all peripherals listed below.

	Program No.	Version
CI5010	B8355510F	V2.071:42
SR5000	B8305102P	V1.820:59
RB5000	Main : D3925510E	V1.290:04
	Sub: D3925520C	V1.060:01
GB5000		
P-Binder_B1	D3915020C	V0.28
P-Binder_B2	D3915070B	V0.19
P-Binder_B3	D3915730A	V0.13
P-Binder_B4	D3915120B	V0.15
P-Binder_B5	D3915170A	V0.25
BK5000	B8365550B	V2.17:15
SK5000		
1 st stacker	D3645620_P1	V4.02:12
2 nd stacker	D3645620_P2	
Buffer Pass Unit	M3791702A	V1.000:03
Type 5000		



PAGE: 1/3

Reissued:10-Nov-09

Model: Aegis-P1	Date: 29-Sep-09	No.: RG178079a

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: SP value input procedure of LD unit			Prepared by: M.Kudoh		
From: PPBG QA/Service Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part informa	tion	Action required	
	☐ Mechanical	☐ Electrical		Service manual revision	
	☐ Paper path	☐ Transmit/red	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

When LD units are exchanged, it is necessary to change some SP data. However, the data sheet attached to the LD unit is not understood easily.

Explanation of the data sheet

KA data is not used

2点間基準値:Nor:LDA1 Nor:LDA2 Mir:LDA1 Mir:LDA2 (KC/MY:SP2-185-[001, 2, 5, 6/003, 4, 7, 8]) ► KA:255751, 255737, 255101, 255108

色間レジスト:Nor Mir LDA間主レジスト:Nor Mir (KC/MY:SP2-[101-001, 2, 102-36, 46/101-003, 4, 102-56, 66])

KB:-62, +78, +012, -004

LDA内主レジスト:Nor(KM):×1 ×2 ×3 ×4 ×5 ×6 (KC/MY:SP2-102-[030~035/050~055])

KC:+005, +011, +017, +011, +023, +035

LDA内主レジスト:Mir(CY):×1 ×2 ×3 ×4 ×5 ×6 (KC/MY:SP2-102-[040~045/060~065])

KD:-012, -025, -037, -005, -010, -014

LDA閒倍率誤差:Nor(KM):A B Mir(CY):A B (KC/MY:SP2-115-[001, 2, 5, 6/003, 4, 7, 8])

KE:+09, +09, -06, -05

Read the data from the example data sheet as follows:

Example 1: (KC / MY : SP2-[101-001, 2, 102-36, 46/ 101-003, 4, 102-56, 66]) KB: -62, +78, +012, -004

SP data when replacing KC LD unit	SP data when replacing MY LD unit
SP2-101-001 → -62	SP2-101-003 → -62 *
SP2-101-002 → +78 *	SP2-101-004 → +78 *
SP2-102-036 → +012	SP2-102-056 → +012
SP2-102-046 → -004	SP2-102-066 → -004

^{*} As an exception, these SP modes do not need to be programmed

If these SPs are programmed by mistake, a color registration problem occurs.

However, color registration is corrected by MUSIC condition settings (SP2-253-004 and 2-253-001) execution.

The biggest problem happens when SP2-101-001 is changed by mistake at the MY LD unit exchange. In this case, the writing position of K that is the standard of the color registration shifts.

Therefore, the position of the printing image not only shifts but also the position of the toner patch used to control the image density shifts.

As a result, abnormal image density and related SCs occur.

Example 2: (KC / MY : SP2-102-[030 ~ 035/ 050 ~ 055]) KC : +005, +011, +017, +011, +023, +035

SP data when replacing KC LD unit	SP data when replacing MY LD unit
SP2-102-030 → +005	SP2-102-050 → +005
SP2-102-031 → +011	SP2-102-051 → +011
SP2-102-032 → +017	SP2-102-052 → +017
SP2-102-033 → +011	SP2-102-053 → +011
SP2-102-034 → +023	SP2-102-054 → +023
SP2-101-035 → +035	SP2-101-055 → +035



PAGE: 2/3

Reissued:10-Nov-09

Model: Aegis-P1 Date: 29-Sep-09 No.: RG178079a

The list of SP numbers to be changed

	Blac	k/Cyan	Mage	nta/Yellow
	SP mode	Value	SP mode	Value
KB	SP2-101-001	Refer to the data sheet.	SP2-101-003	Do not change
	SP2-101-002	Do not change	SP2-101-004	Do not change
	SP2-102-036	Refer to the data sheet.	SP2-102-056	Refer to the data sheet.
	SP2-102-046	Refer to the data sheet.	SP2-102-066	Refer to the data sheet.
KC	SP2-102-030	Refer to the data sheet.	SP2-102-050	Refer to the data sheet.
	SP2-102-031	Refer to the data sheet.	SP2-102-051	Refer to the data sheet.
	SP2-102-032	Refer to the data sheet.	SP2-102-052	Refer to the data sheet.
	SP2-102-033	Refer to the data sheet.	SP2-102-053	Refer to the data sheet.
	SP2-102-034	Refer to the data sheet.	SP2-102-054	Refer to the data sheet.
	SP2-102-035	Refer to the data sheet.	SP2-102-055	Refer to the data sheet.
KD	SP2-102-040	Refer to the data sheet.	SP2-102-060	Refer to the data sheet.
	SP2-102-041	Refer to the data sheet.	SP2-102-061	Refer to the data sheet.
	SP2-102-042	Refer to the data sheet.	SP2-102-062	Refer to the data sheet.
	SP2-102-043	Refer to the data sheet.	SP2-102-063	Refer to the data sheet.
	SP2-102-044	Refer to the data sheet.	SP2-102-064	Refer to the data sheet.
	SP2-102-045	Refer to the data sheet.	SP2-102-065	Refer to the data sheet.
KE	SP2-115-001	Refer to the data sheet.	SP2-115-003	Refer to the data sheet.
	SP2-115-002	Refer to the data sheet.	SP2-115-004	Refer to the data sheet.
	SP2-115-005	Refer to the data sheet.	SP2-115-007	Refer to the data sheet.
	SP2-115-006	Refer to the data sheet.	SP2-115-008	Refer to the data sheet.
KF	SP2-152-001	Refer to the data sheet.	SP2-152-061	Refer to the data sheet.
	SP2-152-002	Refer to the data sheet.	SP2-152-062	Refer to the data sheet.
	SP2-152-003	Refer to the data sheet.	SP2-152-063	Refer to the data sheet.
	SP2-152-004	Refer to the data sheet.	SP2-152-064	Refer to the data sheet.
	SP2-152-005	Refer to the data sheet.	SP2-152-065	Refer to the data sheet.
KG	SP2-152-006	Refer to the data sheet.	SP2-152-066	Refer to the data sheet.
	SP2-152-007	Refer to the data sheet.	SP2-152-067	Refer to the data sheet.
	SP2-152-008	Refer to the data sheet.	SP2-152-068	Refer to the data sheet.
	SP2-152-009	Refer to the data sheet.	SP2-152-069	Refer to the data sheet.
	SP2-152-010	Refer to the data sheet.	SP2-152-070	Refer to the data sheet.
KH	SP2-152-011	Refer to the data sheet.	SP2-152-071	Refer to the data sheet.
	SP2-152-012	Refer to the data sheet.	SP2-152-072	Refer to the data sheet.
	SP2-152-013	Refer to the data sheet.	SP2-152-073	Refer to the data sheet.
	SP2-152-014	Refer to the data sheet.	SP2-152-074	Refer to the data sheet.
	SP2-152-015	Refer to the data sheet.	SP2-152-075	Refer to the data sheet.
KJ	SP2-152-031	Refer to the data sheet.	SP2-152-091	Refer to the data sheet.
	SP2-152-032	Refer to the data sheet.	SP2-152-092	Refer to the data sheet.
	SP2-152-033	Refer to the data sheet.	SP2-152-093	Refer to the data sheet.
	SP2-152-034	Refer to the data sheet.	SP2-152-094	Refer to the data sheet.
	SP2-152-035	Refer to the data sheet.	SP2-152-095	Refer to the data sheet.
KK	SP2-152-036	Refer to the data sheet.	SP2-152-096	Refer to the data sheet.
	SP2-152-037	Refer to the data sheet.	SP2-152-097	Refer to the data sheet.

Technical **B**ulletin

PAGE: 3/3

Reissued:10-Nov-09

Mc	odel: Aegis-P1			Date: 29-Sep-09	No.: RG178079a
	SP2-152-038	Refer to the data sheet.	SP2-152-098	Refer to the data sheet.	
	SP2-152-039	Refer to the data sheet.	SP2-152-099	Refer to the data sheet.	
	SP2-152-040	Refer to the data sheet.	SP2-152-100	Refer to the data sheet.	
KL	SP2-152-041	Refer to the data sheet.	SP2-152-101	Refer to the data sheet.	
	SP2-152-042	Refer to the data sheet.	SP2-152-102	Refer to the data sheet.	
	SP2-152-043	Refer to the data sheet.	SP2-152-103	Refer to the data sheet.	
	SP2-152-044	Refer to the data sheet.	SP2-152-104	Refer to the data sheet.	
	SP2-152-045	Refer to the data sheet.	SP2-152-105	Refer to the data sheet.	
KM	SP2-105-001	Refer to the data sheet.	SP2-105-017	Refer to the data sheet.	
	SP2-105-002	Refer to the data sheet.	SP2-105-018	Refer to the data sheet.	
	SP2-105-003	Refer to the data sheet.	SP2-105-019	Refer to the data sheet.	
	SP2-105-004	Refer to the data sheet.	SP2-105-020	Refer to the data sheet.	
	SP2-105-005	Refer to the data sheet.	SP2-105-021	Refer to the data sheet.	
	SP2-105-006	Refer to the data sheet.	SP2-105-022	Refer to the data sheet.	
	SP2-105-007	Refer to the data sheet.	SP2-105-023	Refer to the data sheet.	
	SP2-105-008	Refer to the data sheet.	SP2-105-024	Refer to the data sheet.	
KN	SP2-105-009	Refer to the data sheet.	SP2-105-025	Refer to the data sheet.	
	SP2-105-010	Refer to the data sheet.	SP2-105-026	Refer to the data sheet.	
	SP2-105-011	Refer to the data sheet.	SP2-105-027	Refer to the data sheet.	
	SP2-105-012	Refer to the data sheet.	SP2-105-028	Refer to the data sheet.	
	SP2-105-013	Refer to the data sheet.	SP2-105-029	Refer to the data sheet.	
	SP2-105-014	Refer to the data sheet.	SP2-105-030	Refer to the data sheet.	
	SP2-105-015	Refer to the data sheet.	SP2-105-031	Refer to the data sheet.	
	SP2-105-016	Refer to the data sheet.	SP2-105-032	Refer to the data sheet.	
KO	SP2-130-001	Refer to the data sheet.	SP2-130-017	Refer to the data sheet.	
	SP2-130-002	Refer to the data sheet.	SP2-130-018	Refer to the data sheet.	
	SP2-130-003	Refer to the data sheet.	SP2-130-019	Refer to the data sheet.	
	SP2-130-004	Refer to the data sheet.	SP2-130-020	Refer to the data sheet.	
	SP2-130-005	Refer to the data sheet.	SP2-130-021	Refer to the data sheet.	
	SP2-130-006	Refer to the data sheet.	SP2-130-022	Refer to the data sheet.	
	SP2-130-007	Refer to the data sheet.	SP2-130-023	Refer to the data sheet.	
	SP2-130-008	Refer to the data sheet.	SP2-130-024	Refer to the data sheet.	
KP	SP2-130-009	Refer to the data sheet.	SP2-130-025	Refer to the data sheet.	
	SP2-130-010	Refer to the data sheet.	SP2-130-026	Refer to the data sheet.	
	SP2-130-011	Refer to the data sheet.	SP2-130-027	Refer to the data sheet.	
	SP2-130-012	Refer to the data sheet.	SP2-130-028	Refer to the data sheet.	
	SP2-130-013	Refer to the data sheet.	SP2-130-029	Refer to the data sheet.	
	SP2-130-014	Refer to the data sheet.	SP2-130-030	Refer to the data sheet.	
	SP2-130-015	Refer to the data sheet.	SP2-130-031	Refer to the data sheet.	
	SP2-130-016	Refer to the data sheet.	SP2-130-032	Refer to the data sheet.	

Technical Bulletin

PAGE: 1/5

Model: AG-P1 / C1 Dat					09	No.: RG178080	
Subject: JAM37 or JAM38					Prepared by: Hidetoshi Kawamura		
From: PPBG QA/	Service Planning Dept.						
Classification:		☐ Part info	rma	ition		required	
	☐ Mechanical	☐ Electrical			☐ Service	ce manual revision	
☐ Paper path ☐ Transmit/		it/rec	eive	☐ Retrof	fit information		
	☐ Product Safety	Other ()	☐ Tier 2		

SYMPTOM

Frequent paper jams either JAM37 or JAM38


CAUSE

There are 2 causes

- · Dirty ozone filters [A].
- Attraction force of Paper Transport Belt changes due to various paper types.

The fan creates a vacuum to hold the paper against the Paper Transport Belt to transport the paper to the fusing unit. The airflow from the fan is exhausted through the ozone filter. The timing of the paper transport is related to the vacuum and a dirty ozone filter has a negative influence. This causes JAM37 and/or JAM38.

Some paper types will slip on the Paper Transport Belt and causes a JAM37 and/or JAM38 due to timing tolerances.



SOLUTION

Take the following actions if JAM 37 or JAM 38 frequently occurs.

- 1. Clean the ozone filter.
- 2. Attach the SEPARATION PLATE (P/N G1789530) inside the air duct.


By attaching the "Separation plate" inside the air duct, the airflow is improved and therefore the vacuum is increased.

The procedure for attaching the "Separation Plate" is shown on the next page.

PAGE: 2/5

Model: AG-P1 / C1 Date: 27-Oct-09 No.: RG178080

Procedure for attaching the "Separation Plate"







(NOTE) OVERLAPPING

Technical Bulletin

Model: AG-P1 / C1 Date: 27-Oct-09 No.: RG178080

PAGE: 3/5

3.REMOVE THE FAN ASSY (L)/(R)

FAN ASSY (L)

FAN ASSY (R)


PAGE: 4/5


Model: AG-P1 / C1 Date: 27-Oct-09 No.: RG178080

4.ASSEMBLE THE MEASURES PART

The Rear Controller is shown to explain the location of the Separation Plate. When installing the Separation Plate, there is **no need** to open the Rear Controller.

THE OTHER SIDE OF THIS PART







Model: AG-P1 / C1 Date: 27-Oct-09 No.: RG178080

*PHOTO GRAPH OF THE MEASURES PART



PAGE: 5/5



Technical Bulletin

PAGE: 1/1

Model: AG-P1 / C1 Date					09	No.: RG178081	
Subject: Consecutive JAM38 (C JAM)					Prepared by: Hidetoshi Kawamura		
From: PPBG QA/	Service Planning Dept.						
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	n required	
		☐ Electric	al		⊠ Service	ce manual revision	
☐ Paper path ☐ Transmit/r		it/rec	eive	☐ Retrof	fit information		
	☐ Product Safety	Other ()	☐ Tier 2		

Additional explanation for the Troubleshooting section in Service Manual for AG-P1/C1 is written in red.

4. Troubleshooting

Paper Problems


Consecutive JAM 38 (C JAM)

Change paper orientation from SEF to LEF if consecutive JAM 38 occurs when printing on thick paper. (Paper size: LT/ A4 SEF, Paper weight: 250 to 300 g/m2)

• Jam code 38: Fusing exit sensor does not detect paper within the specific timeframe.

Note

If less flexible thick SEF paper is used, there is a possibility that paper moves over the paper transport belt without touching it (see the picture below). As a result, JAM38 can occur. Changing the paper orientation from SEF to LEF can improve this.



Technical Bulletin

PAGE: 1/4

Model: AG-P1 / C1 Date					.09	No.: RG178082
Subject: Operation Guide for Test Print Tool				Prepare	d by: N.iid	da
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part information		tion		
		Mechanical			Service	e manual revision
☐ Paper path		Transm	it/rec	eive	⊠ Retrof	fit information
	☐ Product Safety ☐ Other ()	☐ Tier 2	

Overview

This "Test Print Tool" (PN: D0169503) has been designed to make a service engineer print a test print easily compared with using SP mode.

Important

- This tool supports the following languages; German, French, Spanish, Dutch, Italian, UK English and US English.
- This tool does not support custom size paper for printing.

Operation Procedure

- 1. Shut down the fiery controller.
- 2. Turn off the operation switch.
- 3. Turn off the main switch of the machine after the LED of the operation switch has turned off.
- 4. Remove the slot cover for SD cards (screw x 1).
- 5. Insert the "Test Print Tool (SD card)" in SD slot 1 or 2 of the machine.
 - If both SD slots are used, temporarily remove one of these from the SD slot.
- 6. Turn on the machine.

Important

This "Test Print Tool" cannot be used if another SD card tool (MEDIA SETTING TOOL or TCRU/ORU) has already been installed in the machine. First remove the other SD card from the machine, and then insert the "Test Print Tool" SD card in the machine.



PAGE: 2/4

Model: AG-P1 / C1 Date: 30-Oct-09 No.: RG178082




7. The configuration screen of the "Test Print Tool" automatically appears on the operation panel as shown above.

NOTE: The configuration screen of the "Test Print Tool" may change to the normal copier or print operation screen if no operation has been done for a certain time. To display the configuration screen of the "Test Print Tool";

- For the copier model, press the "Program" button on the operation panel.
- For the printer model, press the "Printer function" button on the operation panel.
- 8. Select one of three patterns in "Pattern Selection" or press the "Pattern No." button on the operation panel.

PAGE: 3/4

Model: AG-P1 / C1 Date: 30-Oct-09 No.: RG178082



To select the target pattern number, enter the number in the pattern entry screen shown above with numeric keys on the operation panel, and then press the "Enter" key.

0: No Pattern	19: Trim Area
1: 1-dot Grid Line: ch0	20: 100% Coverage
2: 1-dot Grid Line: ch1	21: Vertical Cross-stitch
3: 1-dot Grid Line: ch2	22: Horizontal Cross-stitch
4: 1-dot Grid Line: ch3	23: Hori. Cross-Stitch 012
5: 1-dot Grid Line: ch4	24: Hori. Cross-Stitch 670
6: 1-dot Grid Line: ch5	25: Horizontal Belt
7: 1-dot Grid Line: ch6	26: Vertical Belt
8: 1-dot Grid Line: ch7	27: Checkered Flag
9: 20 mm Grid	28: Stair
10: Slant Grid Pattern	29: Hori. Grayscale 20mm
11: 1-dot Horizontal Line	30: Hori. G-scale 20mm-wht Boards
12: 1-dot Vertical Lint	31: Hori. Grayscale 40mm-1
13: 2-dot Horizontal Line	32: Hori. Grayscale 40mm-2
14: 2-dpt Vertical Line	33: LP Ch. Power Adjst 1
15: 1-dot Independent	34: LP Ch. Power Adjst 2
16: 2-dot Independent	35: LP Ch. Power Adjst 3
17: 4-dot Independent	36: LP Ch. Power Adjst 4
18: Crop Marks	

- 9. Select the following settings:
 - Select the Print Color: "Black", "Cyan", "Magenta" or "Yellow"
 - Select the Tray: Tray1, Tray2... (Selectable trays depend on how many optional paper feed units are installed.)
 - Print Side: "Simplex" or "Duplex"
 - Output: "Face Down" or "Face Up"



PAGE: 4/4

Model: AG-P1 / C1 Date: 30-Oct-09 No.: RG178082

- 10. The "Print" button is activated after all settings have been made.
- 11. Enter the number of prints with the numeric keys on the operation panel.
- 12. Press the "Print" button.
 - To interrupt printing, press the "Stop" key on the operation panel.

Important

- Do not print any images (SMC reports or etc.) other than test patterns while this tool is used in the machine. Otherwise, a test pattern is superimposed on outputs. If you want to print other images than test patterns, enter "0 (no pattern)" in the "Enter Pattern No." screen of the "Test Print Tool" before printing.
- 13. Shut down the fiery controller after the test pattern printing has been done.
- 14. Turn off the operation switch, and then the main switch.
- 15. Remove the "Test Print Tool (SD card)" from the SD slot.
 - If you removed another SD card in step 5, reinsert it in the SD slot.
- 16. Reattach the slot cover for SD cards (screw x 1).
- 17. Turn on the machine, and then check the operation.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1 Date					-09	No.: RG178083	
Subject: Parts No. correction for E-80 FACI Kit					Prepared by: A. Tajima		
From: PPBG Service Planning Dept.							
Classification:	Troubleshooting	□ Part info	orma			required	
		☐ Electric	al			rice manual revision	
☐ Paper path ☐ Transmit/re		it/rec	eive	☐ Retrof	fit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2		

The part numbers for the E-80 FACI kit are wrong in the E-80 Parts Catalog. Please apply the following part number corrections to your E-80 Parts Catalog.

Wrong part	Corrected	Description	Part Catalog	Note	
number	part number		Page/Index No		
M3828630 \		Keyboard:Black:PS2-USB:Low	Page 7 / 2	Common parts with V-C2	
\		Profile:Generic:45060166		EFI FACI kit	
	D4508660	Keyboard:Black:PS/2-USB:			
		Low Profile: Generic: 45064546			
M3828610 \		Mouse:BlackPS/2-USB: Lighted	Page 7 / 3	Common parts with V-C2	
`		Scroll Wheel:Generic:45060352		EFI FACI kit	
	D4508670	MOUSE:PS/2:45064544			
M3828601		CBL:Power Cord:	Page 7 / 4	Common parts with V-C2	
		EUROPE:ROHS: 45052215		EFI FACI kit	
	M4508612	POWER SUPPLY			
		CORD:EU:45053565			
M3828602\		CBL:Power	Page 7 / 4	Common parts with V-C2	
\		Cord:U.K.:ROHS:45052216		EFI FACI kit	
	` D4508611	POWER SUPPLY			
		CORD:UK:45054061			
M3828603		CBL:Power Cord:800mm:250V:	Page 7 / 4	Common parts with V-C2	
		10A:AC: Black:ROHS:M3828603		EFI FACI kit	
	D4508615	POWER SUPPLY			
		CORD:EXTENSION:45070062			
M3828604		CBL:Power	Page 7 / 4	Common parts with V-C2	
		Cord:AUS:ROHS:45053111		EFI FACI kit	
	D4508613	POWER SUPPLY			
		CORD:AUS:45053566			
M3828620		Monitor:22 In:Widescreen:LCD:	Page 7 / 1	It is not common parts	
		Flat Panel:45060165		with V-C2 EFI FACI kit	
	M3828610	MONITOR_22IN_LCD:45064545			

Note:

The EFI part number is also a wrong old part number. Therefore, please do use the wrong part number to request to ship the part.

Technical Bulletin

PAGE: 1/5

Model: AegisP1/	te: 10-Nov	-09	No.: RG178084			
Subject: Provisi	Prepared by: T.Mimura					
From: PPMC Ser						
Classification:			orma	tion	Action	required
!	☐ Mechanical	☐ Electric	al		Service	ce manual revision
!	☐ Paper path ☐ Transmit/re		it/rec	eive	☐ Retrof	fit information
!	☐ Product Safety	Other ()	☐ Tier2	

SYMPTOM

When stacking the papers in the stack unit, a few sheets don't get adjusted correctly so some sheets don't get stapled.

CAUSE

Paper sticks together because of static electricity.

SOLUTION

Attach the Discharge Brush "B3011216" for Static Electricity Reduction.

PAGE: 2/5

Model: AegisP1/C1 Date: 10-Nov-09 No.: RG178084


Instructions

1. Remove the inner cover. (Screws x3)



Inner cover

2. Remove the retaining ring.



Paper exit guide plate Retaining ring



Technical Bulletin

PAGE: 3/5

Model: AegisP1/C1 Date: 10-Nov-09 No.: RG178084

3. Release the tip of the pressure spring (both front & rear) on the paper exit guide plate.




Pressure spring

View of the pressure springs from below



Pressure spring-



Pressure spring-

Technical Bulletin

PAGE: 4/5

Model: AegisP1/C1 Date: 10-Nov-09 No.: RG178084


4. Remove the paper exit guide plate from the frame.

Then remove the screws (front & rear) that hold the bracket and the discharge brush. (The bracket and discharge brush are fastened with the same screws.)



5. Attach "B3011216" (discharge brush for individual support) as shown in the photo below, then fasten it with the bracket to the paper exit guide plate.

Attaching Position of the Discharge Brush (for individual support)



Model: AegisP1/C1

Technical Bulletin

Date: 10-Nov-09 No.: RG178084

PAGE: 5/5

Appearance of the paper exit guide plate after attaching the discharge brush



6. Follow the procedure in reverse order to install the paper exit guide plate, and then attach the inner cover.

Technical Bulletin

PAGE: 1/56

Model: Aegis-P1 Date					-09	No.: RG178085
Subject: Manual Corrections					d by: N.iid	da
From: PPBG QA/Service Planning Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	Part info	al		⊠ Servic	required e manual revision fit information

The "SC Tables" and "Service Tables" for Perfect Binder have been added to the service manual for the "Model AG-C1/P1 Machine Code: D016/G178".

• Add the following new information.

SC Tables for Perfect Binder (D391)

control board.

Download Error

broken, defective

Master control board defectiveRelay control board defective

SC795-1	Α	Master-to-Slave Board Communication Errors	PB (D391)				
		Master/Slave Control Board Communication Error 1					
		Master control board could not communicate with	the slave				
		control board for over 5 sec. and issued the comm	nunication				
		alarm.					
		 Slave board connector loose, broken, defective 	e				
		Slave board defective					
		Master/Slave Control Board Communication Error	²				
		Slave control board could not communicate with t					
	control board for over 5 sec. and issued the communication						
		alarm.					
		Received data corrupted					
	Cycle the machine power off/on						
		Slave control board defective					
	Download Error The version of the clave central heard could not be detected at						
	The version of the slave control board could not be detected at						
		power on. Communication between the master and slave control					
		boards is not possible if the slave board firmware	cannot be				
		written to the board.					
		 Slave board firmware not written 					
		Cycle the machine power off/on					
		Slave control board defective	_				
SC795-2	Α	Master to Polav Poard Communication Error	PB (D391)				
30135-2		Master-to-Relay Board Communication Error	FB (D391)				

The master control board could not communicate with the relay

Master control board, relay control board connectors loose,

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The version of the master control board could not be detected at power on

Master control board firmware not written

SC795-3 A

Slave-to-Cutter Control Board Communication Error PB (D391)

Slave-to-Cutter Board Communication Error 1

Slave control board could not communicate with the cutter control board (it detected the communication alarm for over 5 sec.

- Cutter board connector loose, broken, defective
- Cutter control board defective

Slave-to-Cutter Board Communication Error 2

Cutter control board could not communicate with the slave control board and detected the communication alarm for over 5 sec. More than twice the maximum allowed alarm recovery time (2 to 3 sec.)

- Slave control board connectors loose, broken, defective
- Cutter control board connectors loose, broken, defective
- Slave control board defective
- Cutter control board defective

Download Error

The version of the firmware on the cutter control board could not be detected at power on. Communication between the slave and cutter control boards is not possible if the cutter board firmware cannot be written to the board.

- Cutter control board connection loose, broken, defective
- Cutter control board defective

SC795-4

Α

Bookbinder EEPROM Error

PB (D391)

PAGE: 2/56

EEPROM Read Error

After EEPROM write operation was completed, the data was read from the same address.

- Master control board EEPROM not installed, not installed correctly
- EEPROM defective

EEPROM Write Error

When data was written to the EEPROM, the EEPROM signaled that it was busy for longer than 25 ms and did not recover. The error time exceeded three times the maximum time allowed for recovery (8 ms)

- Master control board EEPROM not installed, not installed correctly
- EEPROM defective

		_	_	_
C	(2	a	F.	F

Master-to-Inserter Board Communication Error

PB (D391)

Communication Error at Initialization

Technical Bulletin

PAGE: 3/56

Model: Aegis-P1 No.: RG178085 Date: 24-Nov-09

> After the ConfigSet (parallel signal) went ON while the inserter connection status was being checked, the initialization did not end successfully within 5 sec. The error time exceeded three times the maximum time allowed for the initialization communication (1.5 ms).

- Inserter board connector loose, broken, defective
- Inserter board defective

Bookbinder-to-Inserter Communication Error

A command response for the inserter was not issued within the time prescribed for the timeout.

There was an overflow in memory where information required for paper feed is stored. (Master control board detection.)

- Inserter control board defective
- Inserter control board connector loose, broken, defective

Download Error

The version of the firmware on the inserter control board could not be detected at power on.

- Inserter control board defective
- Inserter control board connector loose, broken, defective

SC795-6 24V Check Signal Error 1

The 24V1 monitor signal of the master control board did not go off even though the front door switch was closed. (Relay circuit failed to go ON.)

- Front cover switch error
- 24V1 monitor signal error
- 24V1 power supply error

SC795-7 24V Check Signal Errors Α

PB (D391)

24V Check Signal Error 1

The top cover switch is open or the master control board 24V2 monitor signal failed to go OFF within 5 sec., even though the front door switch and top cover sensor are closed.

- Top cover switch error
- Front cover switch error
- Stacking cover switch error
- Master control board connection loose, broken, defective
- Master control board defective

24V Check Signal Error 2

The 24V2 check signal of the slave control board failed to go OFF within 5 sec. even though the front door and top cover are closed.

- Top cover switch error
- Front cover switch error
- Slave control board connection loose, broken, defective
- Slave control board defective

Technical Bulletin

PAGE: 4/56

Model: Ae	gis-P	1	Date:	24-Nov-09	No.: RG178085
SC795-8	A	24V Check Signal Error The 24V3 check signal of the slav within 5 sec. even though the from Front cover switch error Slave control board connectio Slave control board defective	nt door i	s closed.	-
SC795-9	Α	Power Supply Fan Lock Errors Power Supply Fan (R) Lock Power Supply Fan (C) Lock Power Supply Fan (L) Lock A fan lock signal was detected du supply fan motor in one of the powers. Two retries were attempted detection of the firs lock signal. Fan overload Confirm that there are no obstoperation of the fan Fan motor defective	wer sup at 12 s	ply fans (Rig ec. intervals	ht, Center, after
SC795-10	A	Spine Plate Lower Fan Errors Spine Plate Lower Fan (F) Lock Spine Plate Lower Fan (R) Lock A fan lock signal was detected fo of the lower spine plate fan moto at 12 sec. intervals after detection Fan overload Confirm that there are no obs operation of the fan Fan motor defective	rs. Two n of the	retries were first lock sign	attempted nal.
SC795-11	A	Spine Plate Upper Fan Errors Spine Plate Upper Fan (F) Lock Spine Plate Upper Fan (R) Lock A fan lock signal was detected for the upper spine plate fan mot at 12 sec. intervals after detection Fan overload Confirm that there are no obsoperation of the fan Fan motor defective	or 1 sec ors. Two	o retries were e first lock sig	e attempted gnal.
SC795-12	Α	Signature Fan 2 Error Signature Fan 2F Lock Signature Fan 2R Lock			PB (D391)

Technical Bulletin

PAGE: 5/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 A fan lock signal was detected for 1 sec. during rotation of one of the signature fan 2 motors (Front/Rear). Two retries were attempted at 12 sec. intervals after detection of the first lock signal. Fan overload Confirm that there are no obstructions interfering with operation of the fan Fan motor defective SC795-13 Signature Fan 1 Errors PB (D391) Α Signature Fan 1F Lock Signature Fan 1R Lock A fan lock signal was detected for 1 sec. during rotation of one of the signature fan 1 motors (Front/Rear). Two retries were attempted at 12 sec. intervals after detection of the first lock signal. Fan overload Confirm that there are no obstructions interfering with operation of the fan Fan motor defective SC795-14 Glue Supply Fan H Lock PB (D391) A fan overload/lock signal was detected for 1 sec. during rotation of the upper side glue supply fan motor. Two retries were attempted at 12 sec. intervals after the detection of the first lock signal. Fan overload Confirm that there are no obstructions interfering with operation of the fan Fan motor defective SC795-15 | A Glue Supply Fan L Lock PB (D391) A fan overload/lock signal was detected for 1 sec. during rotation of the lower glue supply fan motor. Two retries were attempted at 12 sec. intervals after the detection of the first lock signal. Fan overload Confirm that there are no obstructions interfering with operation of the fan Fan motor defective SC795-16 Grip HP Sensor (S93) Error Α PB (D391) The grip unit did not pull away from the HP sensor during operation.

The grip unit did not arrive at the HP sensor

-or-

Technical Bulletin

PAGE: 6/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Book grip motor (M43) connection loose, broken, defective Motor defective Grip HP sensor harness loose, broken, defective Sensor defective SC795-17 Main Grip Signature Sensor (S55) Α PB (D391) The main grip signature sensor did not go off after the main grip unit released the signature and moved the prescribed distance.

-or-The grip unit did not arrive at the sensor. Front and rear main grip motors (M23, M24) connection loose, broken, defective Motor defective Main grip signature sensor harness loose, broken, defective Sensor defective

SC795-18 Trimming Buffer HP Sensor: Left (S103) Error Α PB (D391) The trimmings buffer sensor (S103): Did not go ON within 3 sec. when it was supposed to move to the right to its home position. Did not go OFF within 5 sec. when it was supposed to move to the left away from its home position. Clear jammed trimming scraps away from the trimmings buffer Trimmings buffer motor (M37) connections loose, broken, defective Motor defective Sensor harness loose, broken, defective Sensor defective

SC795-19	Α	Trimming Buffer HP Sensor: Right (S100)	PB (D391)					
		Error						
		The trimmings buffer failed to move away from	The trimmings buffer failed to move away from the dump port on					
		top of the trimmings box or failed to arrive at	top of the trimmings box or failed to arrive at the port.					
		The trimmings buffer sensor: right (S100) did	The trimmings buffer sensor: right (S100) did not go OFF within 3					
		sec. when the trimmings buffer was suppose	ed to move away from					
		the sensor.						
		The trimmings buffer sensor: right (S100) did not go ON within 5						
		seconds when the trimmings buffer was supposed to arrive at the						
		sensor.						
		 Clear jammed trimming scraps away from 	n the trimmings buffer					
		Trimmings buffer motor (M37) connection	ns loose, broken,					
		defective						
		Motor defective						
		 Sensor harness loose, broken, defective 						
		 Sensor defective 						

SC795-20 A	Trimmings Buffer Motor (M37) Error	PB (D391)

Technical Bulletin

PAGE: 7/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 The trimmings buffer motor is not rotating.

- Clear jammed trimming scraps away from the trimmings buffer
- Trimmings buffer motor (M37) connections loose, broken, defective
- Motor defective
- Trimmings buffer sensor: left/right (S103/S100) harness loose, broken, defective
- Sensor defective

SC795-21 Book Press Plate Sensor (S104) Error PB (D391)

The trimmings buffer and book press plate did not move after the trimmings buffer motor turned on.

The book press plate sensor did not go OFF with 3 sec.. -or-

The book press plate sensor did not go ON within 3 sec.

- Clear jammed trimming scraps away from the trimmings buffer
- Trimmings buffer motor (M37) connections loose, broken, defective
- Motor defective
- Trimmings buffer sensor: left/right (S103/S100) harness loose, broken, defective
- Sensor defective

SC795-22 Α Book Buffer Tray HP Sensor (S78) PB (D391)

The book buffer tray failed to move to the rear or failed to move to the front.

The book buffer tray HP sensor failed to go ON within 3 sec. when the tray was supposed to move front to rear.

The book buffer tray HP sensor failed to go OFF within 3 sec. when the tray was supposed to move rear to front.

- Book jammed on the rail of the book buffer tray
- Book buffer tray overloaded
- Book buffer tray motor (M39) connections loose, broken, defective
- Motor defective
- Book buffer tray HP sensor (M78) harness loose, broken, defective
- Sensor defective

SC795-23 A Edge Press Plate HP Sensor (S90) Error PB (D391)

Technical Bulletin

PAGE: 8/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

During edge press plate operation during trimming:

The edge press plate HP sensor did not go OFF within the prescribed time because it failed to pull away from the HP sensor. The edge press plate HP sensor did not ON within the prescribed time because it failed to arrive at the HP sensor.

The edge press motor (M36) stopped when the press HP sensor (S90) switched ON, but after the motor stopped the HP sensor went OFF.

- Edge press motor (M36) connections loose, broken, defective
- Motor defective
- Edge press plate HP sensor (S90) harness loose, broken, defective
- Sensor defective

SC795-24 A Press End Sensor (S87) Error

PB (D391)

The press end sensor did not detect the release of the edge press plate (END of operation) against the book in the trimming unit. The sensor did not go ON within 8 sec.

-or-

The press end sensor went ON the edge press plate motor (M36) stopped, but the sensor went OFF again after the motor stopped.

- Edge press plate motor (M36) connections loose, broken, defective
- Motor defective
- Press end sensor (S87) harness loose, broken, defective
- Sensor defective

SC795-25 A Press Limit Sensor (S89) Error

PB (D391)

The press limit sensor went ON and detected the edge press plate beyond its maximum position.

- Edge press plate motor (M36) connections loose, broken, defective
- Motor defective
- Press limit sensor harness loose, broken, defective
- Sensor defective
- Plate out of position (see below)

Note: For a detailed description about how to correct this problem, please refer to the replacement and adjustment procedures in the Perfect Binder manual under "Trimming Unit" in the "Common Procedures" section.

SC795-26 A	Slide HP Sensor (S82) Error	PB (D391)
------------	-----------------------------	-----------

Technical Bulletin

PAGE: 9/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The slide motor (M44) did not leave the home position. When the slide was raised, the slide HP sensor did not go OFF within 180 mm of movement.

-or-

The slide motor (M44) did not reach the home position. The slide HP sensor did not go ON within 180 mm of movement after the slide was lowered.

- Signature has jammed during transport.
- Slide motor (M44) connections loose, broken, defective
- Motor defective
- Slide HP sensor (S82) harness loose, broken, defective
- Sensor defective

SC795-27 A Rotate HP Sensor 1 (S95) PB (D391)

Rotate motor 1 (M42) did not leave the home position and the HP sensor did not go OFF after enough time elapsed for rotation through an arc of 50°.

-or-

The motor did not arrive at the HP sensor. When rotate motor 1 (M42), rotate motor 2 (M41) were both initialized, their HP sensors did not turn ON after enough time elapsed for rotation through an arc of 440°.

- Jam or overload during book rotation.
- Rotate motor 1 (M42) connections loose, broken, defective
- Motor defective

Sensor defective

- Rotate HP sensor 1 (S95)harness loose, broken, defective
- Rotate HP sensor (S95) defective

SC795-28 A Rotate HP Sensor 2 (S91) PB (D391) Rotate motor 2 (M41) did not leave the home position and the HP sensor did not go OFF after enough time has elapsed for rotation through an arc of 30°. -orRotate motor 2 (M41) did not reach the home position and the HP sensor did not go ON after enough time had elapsed for rotation through an arc of 400°. I Jam or overload during book rotation. Rotate motor 2 (M41) connections loose, broken, defective Motor defective Rotate HP sensor (S91) harness loose, broken, defective

SC795-29	Δ	Cutter Motor (M35) Error	PB (D391)
00133-23	$\overline{}$	Cutter Motor (M33) Error	1 0 (0391)

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

One of the following occurred:

- The cutter blade did not move after it was moved to the rear (it did not leave home position).
- The blade did not move away from the cutting point on the blade cradle (it did not arrive at the home position).
- The blade did not move for a rear-to-front cut.
- The blade did not move away from the blade cradle to the front within 10 sec.
- When moving from the front, the blade did not reach the blade cradle within 10 sec.
- When moving from the rear, the blade did not reach the blade cradle.
- Cutter motor (M35) connections loose, broken, defective
- Motor defective
- Blade sensor 1, 2 (S84, S85) sensor harness loose, broken, defective
- Sensor defective
- Blade is dull, cutting poorly

Note: Sensors S84, S85 are on the cutter area PCB.

SC795-30

Trimmer Limit Sensor (S86) Error

PB (D391)

PAGE: 10/56

The blade reached the limit position and the trimmer limit sensor went ON.

- Cutter motor (M35) connections loose, broken, defective
- Motor defective
- Trimmer limit sensor (S86) harness loose, broken, defective
- Sensor defective

Note: For a detailed description about how to correct this problem, please refer to the replacement and adjustment procedures in the Perfect Binder manual under "Trimming Unit" in the "Common Procedures" section.

SC795-31

Book Lift Tray HP Sensor (S79) Error

PB (D391)

The book lift tray did not go up because the book tray lift HP sensor did not go OFF within 1 sec. after the book tray lift motor (M38) turned on to raise the tray.

-or-

Α

The book lift tray did not go down because the book tray lift HP sensor did not go ON within 1.5 sec. after the book tray lift motor (M38) turned on to lower the tray.

- Book tray lift motor (M38) connections loose, broken, defective
- Motor defective
- Book lift tray HP sensor (S79) harness loose, broken, defective
- Sensor defective

SC795-32 A Book Lift Tray Motor (M38) Error	PB (D391)
---	-----------

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The motor is not rotating. The encoder is checked for motor lock at 50 ms intervals.

- Book lift tray motor (M38) locked, blocked by the book press plate or a jammed book.
- Motor connections loose, broken, defective
- Motor defective
- Book lift tray HP sensor (S79) harness loose, broken, defective
- Sensor defective

SC795-33 | A | Book Buffer Tray HP Sensor (S78) Error

PB (D391)

PAGE: 11/56

The book buffer tray did not leave the home position. The book collection buffer tray HP sensor did not go OFF within 1 sec. after the book buffer tray motor (M39) turned on.

-or-

The book buffer tray did not reach the home position. After the book buffer tray motor (M39) turned on, the book buffer tray did not reach the HP sensor within 3.5 sec.

- Book collection buffer tray overloaded.
- Book buffer tray motor (M39) connections loose, broken, defective
- Motor defective
- Book buffer tray HP sensor (S78) harness loose, broken, defective
- Sensor defective

SC795-34 A Blade Cradle HP Sensor (S83) Error

PB (D391)

The blade cradle did not go up after the trimming blade cradle motor (M40) turned on long enough to raise the blade cradle 12 mm to switch the blade cradle HP sensor OFF.

-or-

The blade cradle did not go down after the trimming blade cradle motor (M40) turned on long enough to lower the cradle 21 mm to turn the blade cradle HP sensor ON.

- Blade cradle motor (M40) connections loose, broken, defective
- Motor defective
- Blade cradle HP sensor (S83) harness loose, broken, defective
- Sensor defective
- Book press plate or cutter has interfered with the blade cradle movement.

SC795-35

Α

Book Stacker Door Lock Solenoid (SOL5) Error

PB (D391)

The book stacker door is locked but the book stacker door sensor (\$98) did not go OFF.

Technical Bulletin

PAGE: 12/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Book stacker door lock solenoid (SOL5) connections loose, broken, defective Solenoid defective Book stacker door sensor harness loose, broken, defective Sensor defective SC795-36 Α Glue Heater (HTR1) Errors PB (D391) Heater failed to start: Error 1 600 sec. after the bookbinder left the energy save mode, the glue thermistor could not detect the target temperature (+-5). Heater (HTR1), glue temperature thermistor (S56) defective Heater failed to start: Error 2 After the glue thermistor detected a glue temperature of 50°C, it could not detect a temperature above 140°C within 200 sec. Heater, glue temperature thermistor (S56) defective Electrical Short in the Gluing Unit SC795-37 Α PB (D391) Heater short. The glue unit thermistor detected a temperature higher than 200C for longer than 1 sec. Heater wire break or short circuit. The gluing unit thermistor detected a temperature of less than 5C for more than 1 sec. (more than 10 sec. after power on). Glue level thermistor (S58) broken The AD value of the glue level thermistor (S58) remained at 1023 for 10 sec. Thermistor abnormal, wire breakage, short circuit, broken wire: Replace the gluing unit SC795-38 **Temperature** PB (D391) Α **Detection Error** Low temperature detected while regulating glue temperature. After adjustment of the glue temperature, the glue temperature thermistor (S56) detected a temperature lower than 135°C for more than 10 sec. Heater, glue temperature thermistor (S56) defective Glue level thermistor: Error 1 The glue level thermistor detected a temperature higher than 170°C for longer than 10 sec. after the glue had warmed up. Glue level thermistor (S58) defective Glue level thermistor: Error 2 The glue level thermistor detected a temperature higher than

SC795-39	Α	Protective Circuit Error	PB (D391)

Glue level thermistor (S58) defective

100°C for longer than 10 sec. after the glue had warmed up.

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

- The thermostat (THSW1) inside the gluing unit detected an abnormally high temperature.
- Abnormal thermostat detection
- Glue heater defective
- Thermostat defective

SC795-40 | A | Glue Surface Error 1

PB (D391)

PAGE: 13/56

The surface of the glue in the vat did not reach the lower or upper limit position. This error is issued when the glue surface was detected below the lower limit position 4 times in succession during the glue re-supply cycle.

- Glue has clogged in the vat
- Glue supply defective
- Glue level thermistor (S58) defective

SC795-41 A

Glue Surface Error 2

PB (D391)

The glue surface has not dropped below the upper limit mark. Without a glue vat refill, the glue level thermistor could not detect the level of the glue below the upper limit (full) level, even after the application of 25.42 g of glue.

- Glue application abnormal (not applying correctly)
- Glue level thermistor (S58) defective

SC795-42

Glue Level Thermistor (S58) Adjustment Error

PB (D391)

One of the following errors occurred in the adjustment data for the glue level thermistor:

- Glue level thermistor 1 value (low limit) was out of the range: 128°C±14°C)
- Glue level thermistor 2 value (high limit) was out of the range: 142°C±10°C)
- Glue level thermistor adjustment value 1 was larger than for adjustment 1.
- The difference between the values for adjustment 1 and 2 was less than 5°C.
- Slave control board connection loose, broken, defective
- Slave control board defective

SC795-43

Α

Timing Sensor (S5) Adjustment Error

PB (D391)

The value for the adjustment of the timing sensor exceeded the upper limit. When the A/D input for the timing sensor is lower than 3.0V to 3.5V, even if the timing sensor D/A output is as high as 3.5V, the A/D input value will not fall within the 3.0-to-3.5V range.

The value for the adjustment of the timing sensor was lower than the lower limit. When the A/D input for the timing sensor is higher than 3.0V to 3.5V, even if the timing sensor D/A output is as low as 0.1V, the A/D input value will not fall within the 3.0-to-3.5V range.

Technical Bulletin

PAGE: 14/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Timing sensor defective D/A converter defective A/D converter defective SC795-44 A Cover Registration Sensor (S21) Error PB (D391) The value for the adjustment of the cover registration sensor was higher than or lower than the target range: 3V to 3.5V Cover registration sensor (S21) defective D/A converter defective A/D converter defective SC795-45 Cover Horizontal Registration Sensor: PB (D391) Α Small (S71) The value for the adjustment of the cover registration sensor was higher than or lower than the target range: 3.2V to 3.5V Cover horizontal registration sensor: small (S71) defective D/A converter defective A/D converter defective SC795-46 Cover Horizontal Registration Sensor: Large PB (D391) Α (S72) The value for the adjustment of the cover horizontal registration sensor (for large covers) was higher than or lower than the target range: 3.2V to 3.54V Cover Horizontal Registration Sensor: Large (S72) defective D/A converter defective A/D converter defective SC795-47 Book Exit Sensor (S64) Error PB (D391) Α The value for the adjustment of the book exit sensor was higher than or lower than the target range: 3.2V to 3.54V Signature exit sensor defective D/A converter defective A/D converter defective SC795-48 Α Leading Edge Sensor (S65) Error PB (D391) The value for the adjustment of the leading edge sensor was higher than or lower than the target range: 3.2V to 3.54V Leading edge sensor S65) defective D/A converter defective A/D converter defective SC795-49 Trim Unit Entrance Sensor (S92) Error PB (D391) The value for the adjustment of the sensor was out of range. Trim unit entrance sensor (S92) harness loose, broken, defective Sensor defective

Technical Bulletin

PAGE: 15/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC795-50	Α	Book Registration Sensor (S88) Error	PB (D391)	
		The value for the adjustment of the book registration sensor was		
		out of range.		
		 Slide motor (M44) connections loose, broker 	n. defective	
		Motor defective	,	
		 Book registration sensor (S88) harness loose 	e broken defective	
		Sensor defective	o, bronon, dorodavo	
		Concor dolocave		
SC795-51	Α	LE Detection Sensor (S65) Error	PB (D391)	
0073331	' \	No book could be detected in the path for trimm	\ /	
		could not detect a leading edge of a book).	ing (the sensor	
			ook rotation plates	
		The book has slipped out of the grip of the b	ook rotation plates	
00705 50	Ι Δ	Dook Fuit Conson (CCA) Farrage	DD (D004)	
SC795-52	Α	Book Exit Sensor (S64) Error	PB (D391)	
		No book could be detected at the entrance of the	ne trimming unit.	
		-or-		
		The book did not arrive in the trimming unit bec	•	
		(The trim unit entrance sensor (S92) did not go		
		 Main grip lift motor (M22) connections loose 	, broken, defective	
		 Motor defective 		
		 Book exit sensor (S64) harness loose, broke 	en, defective	
		 Sensor defective 		
SC795-53	Α	Book Registration Sensor (S88) Error	PB (D391)	
		A book was not detected at the book registratio	n sensor pair (the	
		book registration sensor did not go ON).		
		 Book jammed, failed to arrive at book registi 	ration sensor	
		 Slide motor (M44) connections loose, broke 		
		 Motor defective 	,	
		 Book registration sensor (S88) harness loos 	e. broken. defective	
		 Sensor defective 	,,	
		 Sensor flag error, overload 		
SC795-54	Α	Book Exit Sensor (S64) Error	PB (D391)	
00/30-04		The book exit sensor went ON when the system	, ,	
		indicating that a book was at the book exit sens		
		=	וטו מטטעב נווב טטטג	
		grip and rotation unit.	in and rotation unit	
		 Book jammed at the entrance of the book gr Book evit sensor (S64) defective 	ip and rotation unit.	
		Book exit sensor (S64) defective		
00705 55	۱ ۸	Fuit Conson (CCA) Farrage	DD /D004\	
SC795-55	Α	Exit Sensor (S64) Error	PB (D391)	
		The slave control board could detect no paper a		
		the trimming unit. The entrance sensor did not of		
		within 6860 ms from when the signature exited	the gluing unit.	
		 Trim unit entrance sensor (S92) defective 		
			<u></u>	

Technical Bulletin

PAGE: 16/56 Model: Aegis-P1 No.: RG178085 Date: 24-Nov-09 SC795-56 Α Main Grip Signature Sensor (S55) Error PB (D391) No signature was detected in the gripper of the main grip unit. -or-No signature was detected in the main grip unit after the signature passed from the sub grip to the main grip. Main grip signature sensor (S55) defective SC795-57 Book Exit Sensor (S64) Error Α PB (D391) The trim unit entrance sensor remained ON (when no book should have been present). -or-The trim unit entrance sensor (S92) went ON when the system was turned on. -or-The book exit sensor (S64) remained ON after jam removal. Book jam at power on Main group lift motor (M22) connections loose, broken, defective Motor defective Book exit sensor (S64) harness loose, broken, defective Sensor defective SC795-58 Book Registration Sensor (S92) Lag Error PB (D391) The book registration sensor remained ON because the book did not move from the sensor location. The book registration sensor went on when the system was turned on. Book iam above the trimmer unit Slide motor (M44) connections loose, broken, defective Motor defective Book registration (S92) sensor harness loose, broken, defective Sensor defective SC795-59 Book Arrival Sensor (S76) Lag Error PB (D391) The book arrival sensor remained ON because the book did not leave the sensor location. The book remained in the book buffer area and failed to fall onto the book output tray. Slide motor (M44) connections loose, broken, defective Motor defective

SC795-60 A	Trimming Scrap Error	PB (D391)
------------	----------------------	-----------

Sensor defective

Book arrival sensor (S76) harness loose, broken, defective

Technical Bulletin

PAGE: 17/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 The trimming scraps did not fall from the trimmings buffer, or trimmings were jammed between the trimmings buffer and the book press plate. After retrieving the scraps after the 2nd cut (top edge) or 3rd cut (fore edge), the edge press plate sensor did not go ON. Trimming scraps have jammed in or around the trimmings Edge press plate motor (M36) connections loose, broken, defective Motor defective Edge press plate HP sensor (S90) harness loose, broken, defective Sensor defective SC795-61 Α Sub Grip Signature Lag Error PB (D391) The sub grip signature sensor remained ON because the signature failed to move out of the sub grip unit. Signature jam in the sub grip unit Sub grip signature sensor (S39) defective (did not go OFF even with sub grip unit open and the signature removed) SC795-62 Α Main Grip Lag Jam PB (D391) The main grip signature sensor remained ON because the book failed to move from the main grip unit to the trimming unit. Book jam in the main grip unit

Main grip signature sensor (S39) defective (did not go OFF even with the book removed)

SC795-63 Signature Thickness Error PB (D391) Signature thickness reading is smaller than the allowed minimum size. -or-Signature thickness reading is larger than the allowed maximum size. -or-The signature thickness reading did not change after the main grippers opened and closed. Signature thickness sensor (S50) defective.

SC796-1	Α	Glue Vat HP Sensor (S73) Error The glue vat HP sensor at the rear of the bookbinder f				
		ON within the prescribed time.				
		-or-				
		The glue vat HP sensor at the rear of the bookbinder failed to				
		OFF.				

Technical Bulletin

PAGE: 18/56

Model: Aegis-P1

Date: 24-Nov-09

No.: RG178085

Glue vat motor (M32) defective
Glue vat HP sensor (S73) defective
Sensor connector loose, broken, defective

SC796-2 A Glue Vat Roller Rotation Error PB (D391)

The glue vat roller did not start rotating within the prescribed time.

Glue vat roller motor (M25) defective
Glue vat roller rotation sensor (S59) defective
Sensor connector loose, broken, defective

SC796-3 A Glue Supply Motor (M33) Error PB (D391) The glue supply motor did not arrive at its home position. The glue supply HP sensor (S75) did not turn ON within the prescribed time after the glue supply motor (S33) turned on. -or The glue supply motor did not leave its home position. - Glue pellet supply lock - Glue supply motor (M33) defective - Glue supply HP sensor (S75) defective

Sensor connector loose, broken, defective

SC796-4 A Spine Fold HP Sensor: Left (S60) Error PB (D391) The spine fold plate did not reach the left HP sensor (the sensor did not go ON) within the prescribed time after the left spine fold plate motor turned on. -or The spine fold plate did not leave the left HP sensor position (the sensor did not go OFF within the prescribed time). Spine fold plate motor: left (M28) defective Spine fold HP sensor: left (S60) defective

Sensor connector loose, broken, defective

SC796-5 A Spine Fold Close Sensor: Left (S61) Error PB (D391) The sensor did not turn ON within the prescribed time, or the sensor was already OFF when the spine fold plate was supposed to move from the closed to the open position. -or The sensor did not go OFF within the prescribed time after the spine fold plate motor: left turned on to open the spine fold plate, or the sensor was already ON when the spine fold plate was supposed to move from the open to the closed position. Spine fold plate motor: left (M28) defective Spine fold close sensor: left (S61) defective Sensor connector loose, broken, defective

SC796-6	Α	Dual Spine Plate Sensor Error: Left	PB (D391)
---------	---	-------------------------------------	-----------

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The spine plate HP sensor (S60) and spine plate close sensor (S63) turned ON at the same time.

- Spine fold HP sensor: left (S60) defective
- Spine fold close sensor (S63) defective
- A sensor connector loose, broken, defective

SC796-7 A Spine Fold HP Sensor: Right (S66) Error

PB (D391)

PAGE: 19/56

The spine fold plate did not reach the right HP sensor within the prescribed time (sensor did not go ON) after the spine fold plate motor (M29) turned on to open the fold plate, or the right HP sensor was already OFF when the spine fold plate was supposed to move from the open to the closed position.

-or-

The spine fold plate did not leave the right HP sensor position (sensor did not go OFF) within the prescribed time after the spine fold motor: right turned on to close the fold plate.

- Spine fold motor: right (M29) defective
- Spine fold HP sensor: right (S66) defective
- Connector loose, broken, defective

SC796-8 A Spine Fold Close Sensor: Right (S69) Error

PB (D391)

The right fold plate close sensor did not go ON within the prescribed time after the spine fold plate motor: right turned on to close the fold plate, or the close sensor on the right was already OFF when the spine fold plate was supposed to close the plate.

-or-

The right spine fold plate close sensor did not go OFF within the prescribed time after the spine fold plate motor: right turned on to open the plate, or the spine fold page close sensor on the right was already ON when the spine fold plate was supposed to move from the open to the closed position.

- Spine fold motor: right (M29) defective
- Spine fold close sensor: right (S69) defective
- Sensor connector loose, broken, defective

SC796-9

Α

Dual Spine Plate Sensor Error: Right

PB (D391)

The spine fold HP sensor: right (S66) and spine fold close sensor: right (S69) turned ON at the same time.

- Spine fold HP sensor: right (S66) defective
- Spine fold close sensor: right (S69) defective
- Sensor connector loose, broken, defective

SC796-10	Α	Spine Plate	Open Sensor	(S62) Error
----------	---	-------------	-------------	-------------

PB (D391)

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The spine plate open sensor did not go ON within the prescribed time after the spine plate motor turned on to open the plate.

The spine plate open sensor did not go OFF within the prescribed time after the spine plate motor turned on to close the plate.

- Spine plate motor (M26) defective
- Spine plate open sensor (S62) defective
- Sensor or motor connector loose, broken, defective

SC796-11 A Spine Plate Closed Sensor (S63)

PB (D391)

PAGE: 20/56

The spine plate close sensor did not go ON within the prescribed time after the spine plate motor turned on to close the plate.

-or-

The spine plate close sensor did not go OFF within the prescribed time after the spine plate motor turned on to open the plate.

- Spine plate motor (M26) defective
- Spine plate closed sensor (S63) defective
- Motor or sensor connector loose, broken, defective

SC796-12 A Front Door Lock Error

PB (D391)

The right front door sensor did not go OFF even though the front doors closed and locked.

-or-

The right front door sensor did not go ON even though the front doors released and opened.

- The right front door solenoid (SOL3) defective
- Right front door sensor (S30) defective
- One or more of the front door switches (MSW1, 2, 4, 5, 6, 7) is defective
- Solenoid, sensor, or MSW connector loose, broken, defective

SC796-13

Α

Switchback Flapper HP Sensor (S10) Error

PB (D391)

The switchback flapper HP sensor in the stacking tray did not go ON after the motor turned on long enough to raise the flapper through an arc of 50 degrees.

-or-

The switchback flapper HP sensor did not go OFF after the motor remained on long enough to lower the flapper through an arc of 150 degrees.

- Switchback flapper HP sensor (S10) defective
- Switchback flapper motor (M8) defective
- Sensor or motor connector loose, broken, defective

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC796-14 | A | TE Press Lever HP Sensor (S3) Error

PB (D391)

PAGE: 21/56

The TE press lever HP sensor in the stacking tray did not go ON the TE press lever motor remained on long enough to move the lever through and arc of 30 degrees to release the lever.

-or-

The TE press lever HP sensor did not go OFF when the TE press lever motor remained on long enough to move the lever through and arc of 20 degrees to close the lever.

- TE press lever HP sensor (S3) defective
- TE press lever motor (M3) defective
- Sensor or motor connector loose, broken, defective

SC796-15

Jog Fence HP Sensor: Front/Small (S12) Error PB (D39)

The front jog fence HP sensor in the stacking tray for small size paper did not go ON within the prescribed time after the front jogger motor turned on long enough to move the fence front jog fence.

-or-

The front jog fence HP sensor for small size paper did not go OFF within the prescribed time after the front jogger motor turned on to move the front fence.

- Jog fence HP sensor: front/small (S12) defective
- Jogger motor: front (M4) defective
- Sensor or motor connector loose, broken, defective

SC796-16 A

Jog Fence HP Sensor: Front/Large (S14) ErrorPB (D391)

The front jog fence HP sensor for large size paper in the stacking tray did not go ON within the prescribed time after the front jogger motor turned on to move the front fence.

-or-

The front jog fence HP sensor for large size paper in the stacking tray did not go OFF within the prescribed time after the front jogger motor turned on to move the front fence.

- Jog fence HP sensor: front/large (S14) defective
- Jogger motor: front (M4) defective
- Sensor or motor connector loose, broken, defective

SC796-17

Α

Jog Fence HP Sensor: Rear/Small (S13) Error PB (D391)

The rear jog fence HP sensor for small size paper in the stacking tray did not go ON within the prescribed time after the rear jogger motor turned on to move the rear fence.

-or-

The rear jog fence HP sensor for small size paper in the stacking tray did not go OFF within the prescribed time after the rear jogger motor turned on to move the rear fence.

Technical Bulletin

PAGE: 22/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Jog fence HP sensor: rear/small (S13) defective Jogger motor: rear (M5) defective Sensor or motor connector loose, broken, defective SC796-18 Jog Fence HP Sensor: Rear/Large (S15) Error Α PB (D391) The rear jog fence HP sensor for large size paper in the stacking tray did not go ON after the rear jogger motor turned on to move the rear fence. -or-The rear jog fence HP sensor for large size paper in the stacking tray did not go OFF after the rear jogger motor turned on to move the rear fence. Jog fence HP sensor: rear/large (S15) defective Jogger motor: rear (M5) defective Sensor or motor connector loose, broken, defective SC796-19 Α Switchback Roller HP Sensor (S11) Error PB (D391) The switchback roller HP sensor in the stacking tray did not go ON after the motor turned on long enough to raise the roller through an arc of 40 degrees. The switchback roller HP sensor in the stacking tray did not go OFF after the motor turned on long enough to lower the roller through an arc of 20 degrees. Switchback roller HP sensor (S11) defective Switchback roller motor (M7) defective Sensor or motor connector loose, broken, defective SC796-20 Stacking Tray Lower Limit Sensor (S7) Error PB (D391) Stacking tray lower limit sensor did not go ON within the prescribe time after the stacking tray lift motor turned to lower the tray. -or-Stacking tray lower limit sensor did not go OFF within the prescribed time after the stacking tray lift motor turned on to raise tray. Stacking tray lower limit sensor (S7) defective Stacking tray lift motor (M2) defective Sensor or motor connector loose, broken, defective

SC796-21	Α	Paper Detection Sensor: Fron/Rear (S1/S2)	PB (D391)
		Error	

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The paper detection sensor at the front of the stacking tray did not go ON within the prescribed time after the stacking tray overflow sensor (S6) went ON and the stacking tray lift motor turned on to raise the tray. -or-

PAGE: 23/56

The paper detection sensor at the front of the stacking tray did not go OFF within the prescribed time after the stacking tray lift motor turned on to lower the tray.

-or-

The paper detection sensor at the rear of the stacking tray did not go ON within the prescribed time after the stacking tray overflow sensor (S6) went ON and the stacking tray lift motor turned on to raise the tray.

-or-

The paper detection sensor at the rear of the stacking tray did not go OFF within the prescribed time after the stacking tray lift motor turned on to lower the tray

- Paper Detect Sensor: Front (S1) defective
- Stacking Tray Lift Motor (M2) defective
- Sensor or motor connector loose, broken, defective

SC796-22 A Stacking Tray Overflow Sensor (S6) Error PB (D391)

The stacking tray overflow sensor did not go ON within the prescribed time after the stacking tray lift motor turned on to raise the tray.

-or-

The stacking tray overflow sensor did not go OFF within the prescribed time after the stacking tray lift motor turned on to lower the tray.

- Stacking Tray Overflow Sensor (S6) defective
- Stacking Tray Lift Motor (M2) defective
- Sensor or motor connector loose, broken, defective

SC796-23 A Dual Stacking Tray Errors PB (D391)

The Stacking Tray Lower Limit Sensor (S7) and Stacking Tray Overflow Sensor (S6) went ON at the same time.

- Stacking Tray Lower Limit Sensor (S7) defective
- Stacking Tray Overflow Sensor (S6) defective
- Sensor connector loose, broken, defective

The Stacking Tray Overflow Sensor (S6) went OFF when the stacking tray was raised to its upper limit. When the tray was raised, the stacking tray overflow sensor (S6) went OFF and: (1) the stacking tray empty sensor (S8) was OFF and (2) one or both the paper detect sensors (S1: Front/S2: Rear) were ON.

- Stacking Tray Empty Sensor (S8) defective
- Paper Detect Sensors: Front/Rear (S1/S2) defective
- Stacking Tray Overflow Sensor (S6) defective
- Stacking Tray Lift Motor (M2) defective
- Sensor or motor connector loose, broken, defective

Technical Bulletin

PAGE: 24/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC796-24 A Stacking Tray HP Sensor (S9) Error PB (D391)

The stacking tray HP sensor did not go ON within the prescribed time after the stacking tray motor turned on to move the tray toward the sensor.

-or
The stacking tray HP sensor did not go ON within the prescribed time after the stacking tray motor turned on to move the tray away from the sensor.

Stacking HP Sensor (S9) defective

Stacking Tray Motor (M9) defective

Sensor or motor connector loose, broken, defective

SC796-25 A Stacking Weight HP Sensor (S16) Error PB (D391) The stacking weight HP sensor did not go ON within the prescribed time the stacking weight motor turned on to move the tray toward the sensor. -or The stacking tray HP sensor did not go OFF within the prescribed time when the stacking tray motor turned on to move the tray away from the sensor. Stacking weight HP sensor did not go ON. Stacking Weight HP Sensor (S16) defective Stacking Weight Motor (M6) defective Sensor or motor connector loose, broken, defective

SC796-26	Α	Left Cover Guide Error	PB (D391)			
		The left cover guide HP sensor did not go ON within the				
		prescribed time after the left cover guide motor turned on.				
		 Cover Guide HP Sensor: Left (S27) defective 				
		 Cover Guide Motor: Left (M15 	5) defective			
		 Sensor or motor connector loose, broken, defective 				
		The left cover guide open sensor did not go ON within the				
		prescribed time after the left cover guide motor turned on to				
		retract the left cover guide.				
		 Cover Guide Open Sensor: Left (S28) defective 				
		 Cover Guide Motor: Left (M15) defective 				
		 Sensor or motor connector lo 	ose, broken, defective			

SC796-27	Α	Left Cover Guide Dual Sensor Errors			
		Cover Guide HP Sensor: Left (S27) and Cover Guide Open			
		Sensor: Left (S28) went ON at the same time.			
		 Cover Guide HP Sensor: Left (S27) defective 			
		 Cover Guide Open Sensor: Left (S28) defect 	ctive		
		 Sensor connector loose, broken, defective 			

SC796-28 A	Right Cover Guide Error	PB (D391)
------------	-------------------------	-----------

SC796-32 A

Technical Bulletin

PAGE: 25/56

PB (D391)

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 The right cover guide HP sensor did not go ON within the prescribed time after the right cover guide motor turned on. Cover Guide HP Sensor: Right (S22) defective Cover Guide Motor: Right (M16) defective The cover guide open sensor: right did not go ON within the prescribed time after the right cover guide motor turned on to move the right cover guide to the home position. Cover Guide HP Sensor: Right (S23) defective Cover Guide Motor: Right (M16) defective SC796-29 Α Right Cover Guide Dual Sensor Errors PB (D391) Cover Guide HP Sensor: Right (S22) and Cover Guide Open Sensor: Right (S23) went ON at the same time. Cover Guide HP Sensor: Right (S23) defective Cover Guide Open Sensor: Right (S23) defective Sensor connector loose, broken, defective SC796-30 Cover Registration HP Error Α PB (D391) Cover Registration HP Sensor: Small/Large (S71, S72) did not go ON within the prescribed time after the cover horizontal registration motor turned on. -or-Cover Registration HP Sensor: Small/Large (S71, S72) did not go OFF within the prescribed time after the cover horizontal registration motor turned on. Cover Horizontal Registration Motor (M31) defective Cover Horizontal Registration Sensor: Small/Large (S71, S72) defective Sensor or motor connector loose, broken, defective SC796-31 Α Sub Grip HP Sensor (S37) Error PB (D391) The sub grip HP sensor did not go ON within the prescribed time after the sub grip lift motor turned on to raise the sub grip unit. -or-The sub grip HP sensor did not go OFF within the prescribe time after the sub grip lift motor turned on to lower the sub grip unit. Sub Grip Lift Motor (M17) defective Sub Grip HP Sensor (S37) defective Sensor or motor connector loose, broken, defective

Sub Grip Size HP Sensor (S38) Error

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The sub grip size HP sensor did not go ON within the prescribed time after the sub grip size motor turned on for horizontal adjustment to the paper size.

-or-

The sub grip size HP sensor was already OFF when the sub grip size horizontal adjustment started (from the open to closed position).

- Sub Grip Size Motor (S19) defective
- Sub Grip Size HP Sensor (S38) defective
- Motor or sensor connector loose, broken, defective

The sub grip size HP sensor did not go OFF within the prescribed time after the sub grip size motor turned on to close sub grippers for horizontal adjustment of the paper size.

-or-

The sub grip size HP sensor was already ON when the sub grip size horizontal adjustment started (from the close to open position).

- Sub Grip Size Motor (S19) defective
- Sub Grip Size HP Sensor (S38) defective
- Motor or sensor connector loose, broken, defective

SC796-33 A Sub Grip Open Sensor (S40) Error

PB (D391)

PAGE: 26/56

The sub grip open sensor did not go ON within the prescribed time after the sub grip lift motor turned on to open the sub grip unit.

-or-

The sub grip open sensor did not go OFF within the prescribed time after the sub grip lift motor turned on to close the sub grip unit.

- Sub Open Motor (S20) defective
- Sub Grip Open Sensor (S40) defective
- Motor or sensor connector loose, broken, defective

SC796-34 A Sub Grip Close Sensor (S41) Error

PB (D391)

The sub grip close sensor did not go ON within the prescribed time after the sub grip lift motor turned on to close the sub grip unit.

-or-

The sub grip close sensor did not go OFF within the prescribed time after the sub grip open motor turned on to open the sub grip unit.

- Sub Grip Open Motor (S20) defective
- Sub Grip Open Close (S41) defective
- Motor or sensor connector loose, broken, defective

SC796-35	Α	Sub Grip Dual Sensor Error	PB (D391)
----------	---	----------------------------	-----------

Technical Bulletin

Model: Aegis-P1

Date: 24-Nov-09

No.: RG178085

The Sub Grip Open Sensor (S40) and Sub Grip Close Sensor (S41) went ON at the same time.

Sub Grip Open Sensor (S40) defective
Sub Grip Close Sensor (S41) defective
A sensor connector loose, broken, defective

SC796-36

Α

Α

Signature HP Sensor (S34) Error

PB (D391)

PAGE: 27/56

The signature HP sensor did not go ON within the prescribed time after the signature move motor turned on to move the sub grip to the home position.

-or-

The signature HP sensor did not go OFF within the prescribed time after the signature move motor turned on to move the sub grip to the signature transfer position (from sub grip to main grip).

- Signature Move Motor (M18) defective
- Signature HP Sensor (S34) defective
- Connector loose, broken, defective

SC796-37

Signature Main Grip Position Sensor (S35) Error

PB (D391)

The signature main grip position sensor did not go ON within the prescribed time after the signature move motor turned for delivery of the signature from the sub grip to the main grip.

Due to incorrect timing during delivery of the signature from sub grip to main grip, the signature was gripped at the main grip HP sensor position.

- Signature Move Motor (M18) defective
- Signature Main Grip Position Sensor (M35) defective
- Motor or sensor connector loose, broken, defective

The signature HP sensor did not go OFF within the prescribed time after the signature move motor turned on to move the sub grip to the home position.

- Signature Move Motor (M18) defective
- Signature Main Grip Position Sensor (M35) defective
- Motor or sensor connector loose, broken, defective

SC796-38

Main Grip Rotate Enable Sensor (S36) Error

PB (D391)

The main grip rotate enable sensor did not go ON within the prescribe time after the signature move motor turned on to move the sub grip to the home position.

-or-

Α

The main grip rotate enable sensor did not go OFF within the prescribed time after the signature move motor turned on to move the sub grip to the signature transfer position (from sub grip to main grip).

SC796-42 | A

Technical Bulletin

PAGE: 28/56

PB (D391)

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Signature Move Motor (M18) defective Main Grip Rotate Enable Sensor (S36) defective Motor or sensor connector loose, broken, defective SC796-39 Α Sub Grip Dual Sensor Error PB (D391) The Signature HP Sensor (S34) and Signature Main Grip Position Sensor (S35) went ON at the same time. Signature HP Sensor (S34) defective Signature Main Grip Position Sensor (M35) defective A sensor connector loose, broken, defective SC796-40 Α Main Grip HP Sensor (S44) Error PB (D391) The main grip HP sensor did not go ON within the prescribe time after the main grip lift motor turned on to raise the main grip unit, or the main grip HP sensor was already ON when the motor started to lower the main grip unit. -or-The main grip HP sensor did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit, or the main grip HP sensor was already ON when the motor started to lower the main grip unit. Main Grip Lift Motor (M22) defective Main Grip HP Sensor (S44) Error Motor or sensor connector loose, broken, defective SC796-41 Main Grip Press Sensor 1 (M48)Error PB (D391) The main grip press sensor 1 did not go ON within the prescribed time after the main grip lift motor turned on to raise the main grip unit from the main grip signature registration position. -or-The main grip press sensor 1 did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit to the main grip signature registration position. Main Grip Lift Motor (M22) defective Main Grip Press Sensor 1 (S48) defective Connector loose, broken, defective

Main Grip Press Sensor 2 (S49) Error

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The main grip press sensor 2 did not go ON within the prescribed time after the main grip lift motor turned on to lower the main grip unit and signature to the point where the signature was to be pressed into the center of the cover.

-or-

The main grip press sensor 2 did not go OFF within the prescribed time after the main grip lift motor turned on to raise the main grip unit away from the point where the signature was pressed into the center of the cover.

- Main Grip Lift Motor (M22) defective
- Main Grip Press Sensor 2 (S49) defective
- Motor or sensor connector loose, broken, defective

SC796-43 A Main Grip Signature Exit Error

PB (D391)

PAGE: 29/56

The signature exit sensor did not go ON after the main grip lift motor moved the signature to the delivery point when the signature was passed from the main grip unit to the signature exit roller.

- Main Grip Lift Motor (M22) defective
- Signature Exit Sensor (S64) defective
- Signature broken, bent
- Signature stuck in the main grip unit

SC796-44

Main Grip HP Sensor: High (S45) Error

PB (D391)

The main grip high HP sensor did not go ON within the prescribed time after the main grip lift motor turned on to raise the main grip unit.

-or-

Α

The main grip high HP sensor did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit.

- Main Grip Lift Motor (M22) defective
- Main Grip HP Sensor: High (S45) defective
- Motor or sensor connector loose, broken, defective

SC796-45

Main Grip Rotate HP Sensor (S43) Error

PB (D391)

The main grip rotate HP sensor did not go ON within the prescribed time after the main grip rotation motor turned to rotate the main grip unit for delivery of the signature from the sub grip unit.

-or-

The main grip rotate HP sensor did not go OFF with the prescribed time after the main grip rotation motor turned on to rotate the grip unit and signature to the vertical.

- Main Grip Rotation Motor (M21) defective
- Main Grip Rotate HP Sensor (S43) defective
- Motor or connector loose, broken, defective

Technical Bulletin

PAGE: 30/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC796-46	Α	Rotate-to-Binding Position Sensor (S42) Error	PB (D391)
		The main grip rotate-to-binding position sensor did not go ON within the prescribed time after the main grip rotation motor turned on to rotate the grip unit and signature to the vertical. -or- The main grip rotate to binding position sensor did not go OFF within the prescribed time after the main grip rotation motor turned to rotate the main grip unit to the left for delivery of the	
 signature from the sub grip unit. Main Grip Rotation Motor (M21) defective Rotate to Binding Position Sensor (S42) defective Motor or sensor connector loose, broken, defective 			
00700 47	Δ.	Main Oile Bulatine Bull Occasio France	DD (D004)
50/96-4/	Α	Main Grip Rotation Dual Sensor Errors	PB (D391)

SC796-47	Α	Main Grip Rotation Dual Sensor Errors PB			
		Main Grip Rotate HP Sensor (S43) and Rotate-to-Binding			
		Position Sensor (S42) went ON at the same time.			
		 Main Grip Rotate HP Sensor (S43) defective 			
		 Rotate to Binding Position Sensor (S42) defective 			
		 Sensor connector loose, broken, defective 			

SC796-48 A Main Grip Open/Close Sensor: Rear (S47, S48) PB (D391)

The rear main grip open sensor did not go ON within the prescribed time after the rear grip motor turned on to open the main grip unit.

-or-

The rear main grip open sensor did not go OFF within the prescribed time after the rear grip motor turned on to close the main grip unit.

- Grip Motor: Rear (M23) defective
- Main Grip Open Sensor: Rear (S47) defective
- Motor or sensor connector loose, broken, defective

The rear main grip close sensor did not go ON within the prescribed time after the rear grip motor turned on to close the main grip unit.

-or-

The rear main grip close sensor did not go OFF within the prescribed time after the rear grip motor turned on to open the main grip unit.

- Grip Motor: Rear (M23) defective
- Main Grip Close Sensor: Rear (S54) defective
- Motor or sensor connector loose, broken, defective

SC796-49	Α	Main Grip Encoder: Rear Sensor (S46) Error	PB (D391)	
		The rear main grip encoder sensor could not be detected		
		ON/OFF within the prescribed time after the rear grip motor		
		turned on to open and close the main grip unit.		

Technical Bulletin

PAGE: 31/56 No.: RG178085 Model: Aegis-P1 Date: 24-Nov-09 Grip Motor: Rear (M23) defective Main Grip Encoder: Rear Sensor (S46) defective Motor or sensor connector loose, broken, defective SC796-50 Α Rear Main Group Dual Sensor Error PB (D391) Main Grip Open Sensor: Rear (S47) and Main Grip Close Sensor: Rear (S48) went ON at the same time. Main Grip Open Sensor: Rear (S47) defective Main Grip Close Sensor: Rear (S48) defective A sensor connector loose, broken, defective SC796-51 Main Grip Open/Close Sensor: Front (S51, PB (D391) Α The front main grip open sensor did not go ON within the prescribed time after the front grip motor turned on to open the main grip unit. -or-The front main grip open sensor did not go OFF within the prescribed time after the front grip motor turned on to close the main grip unit. Grip Motor: Front (M24) defective Main Grip Open Sensor: Front (S51) defective Motor or sensor connector loose, broken, defective The front main grip close sensor did not go ON within the prescribed time after the front grip motor turned on to close the main grip unit. -or-The front main grip close sensor did not go OFF within the prescribed time after the front grip motor turned on to open the main grip unit. Grip Motor: Front (M24) defective Main Grip Close Sensor: Front (S53) defective Motor or sensor connector loose, broken, defective SC796-52 Main Grip Encoder: Front Sensor (S52) Error PB (D391) The front main grip encoder sensor could not be detected ON/OFF within 200 ms after the front grip motor turned on to open/close the main grip unit. Main Grip Encoder: Front Sensor (S52) defective Grip Motor: Front (M24) defective Main Grip Encoder: Front Sensor (S52) defective Sensor or motor connector loose, broken, defective SC796-53 Α Front Main Group Dual Sensor Error PB (D391)

Main Grip Open Sensor: Front (S51) and Main Grip Close

Sensor: Front (S53) went ON at the same time.

SC796-58

Technical Bulletin

PAGE: 32/56

PB (D391)

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Main Grip Open Sensor: Front (S51) defective Main Grip Close Sensor: Front (S53) defective Sensor connector loose, broken, defective SC796-54 Signature Exit Path HP Sensor (S67) Error Α PB (D391) The signature exit path HP sensor did not go ON within the prescribed time after the signature exit path motor turned on to retract the signature exit roller. -or-The signature exit path HP sensor did not go OFF within the prescribed time after the signature exit path motor turned on to move the signature exit roller. Signature Exit Path Motor (M30) defective Signature Exit Path HP Sensor (S67) defective Motor or sensor connector loose, broken, defective SC796-55 Signature Exit Path Press Sensor (S68) Error Α PB (D391) The signature exit path press sensor did not go ON within the prescribed time after the signature exit path motor turned on to feed the book into the nip of the signature exit roller. The signature exit path press sensor did not go OFF within the prescribed time after the signature exit path motor turned on to retract the signature exit roller. Signature Exit Path Motor (M30) defective Signature Exit Path Press Sensor (S68) defective Motor or sensor connector loose, broken, defective SC796-56 Signature Exit Roller Error PB (D391) The leading edge sensor did not go ON within the time prescribed for the signature exit roller to reverse feed the signature during signature exit. Signature Roller Exit Motor (M27) defective Leading Edge Sensor (S65) defective Signature torn, bent SC796-57 Inserter EEPROM Error PB (D391) CHECKSUM error at power on. -or-EEPROM write error. EEPROM not installed, or not installed correctly **EEPROM** defective

Inserter Drive Switch Sensor (S16) Error

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The drive switch sensor in the inserter did not go OFF within the time prescribed after the drive switch motor (M2) turned on.
-or-

The drive switch sensor in the inserter did not go ON within the time prescribed after the drive switching motor (M2) turned on.

- Drive switch motor (M2) defective
- Drive switch sensor (S16) defective
- Motor or sensor connector loose, broken, defective
- Connector loose, broken, defective

SC796-59 A Inserter Tray A Error

PB (D391)

PAGE: 33/56

Inserter Tray A (upper tray) failed to leave its lower limit sensor within the prescribed time after Tray A lift motor turned on.

- Lift Motor: Tray A (M3) defective
- Lower Limit Sensor: Tray A (S11) defective
- Motor or sensor connector loose, broken, defective

Inserter Tray A (upper tray) failed to arrive at its paper feed sensor within the prescribed time after the Tray A lift motor turned on.

- Lift Motor: Tray A (M3) defective
- Paper Feed Sensor: Tray A (S4) defective
- Motor or sensor connector loose, broken, defective

SC796-60 | A | Inserter Tray B Error

PB (D391)

Inserter Tray B (lower tray) failed to leave its lower limit sensor within the prescribed time after the Tray B lift motor turned on.

- Lift Motor: Tray B (M4) defective
- Lower Limit Sensor: Tray B (S12) defective
- Motor or sensor connector loose, broken, defective

Inserter Tray B (lower tray) failed to arrive at its paper feed sensor within the prescribed time after the Tray B lift motor turned on.

- Lift Motor: Tray B (M4) defective
- Paper Feed Sensor: Tray B (S10) defective
- Motor or sensor connector loose, broken, defective

SC796-61

Α

Α

Relay Unit EEPROM Error

PB (D391)

EEPROM write error (successful completion of data write operation not detected within the prescribed time).

- Relay board EEPROM not installed, or installed incorrectly
- EEPROM damaged
- Relay board defective

SC796-62

Relay/ Bookbinder Communication Error

PB (D391)

- Communication error between relay unit and bookbinder.
- Relay I/F cable disconnected or damaged
- Relay unit PCB in bookbinder damaged, not installed correctly
- PCB in relay unit damaged, not installed correctly

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

These are the conditions that must be met before the

SC796-63 D Lower Performance Mode Error

PB (D391)

PAGE: 34/56

The location where the error occurred has no effect on the operation of the horizontal feed path for downstream

- operation of the horizontal feed path for downstream delivery.
- The jam has occurred in the horizontal feed path but it can be removed easily.
- The unit where the error occurred allows use of the horizontal feed path.
- These conditions determine whether downstream delivery is possible after an error occurs in the bookbinder.

Correct the problem and release the bookbinder from the low performance mode. See Section 3 of the Perfect Binder manual for more about how to release the Perfect Binder from the low performance mode.

SC797-1 B Grip HP Sensor (S93) Error

PB (D391)

The grip HP sensor did not go OFF within the prescribed time because the main grip did not leave its home position.

The main grip unit did go ON because it did not arrive at the HP position after signature release.

- Book grip motor (M43) defective
- Grip HP sensor (S93) defective
- Sensor or motor harness loose, broken, defective

SC797-2 B

Grip End Sensor (S94) Error

PB (D391)

The grip end sensor (S94) did not go OFF after the grip unit released the signature and moved the prescribed distance.

- Book grip motor (M43) defective
- Grip end sensor (S94) defective
- Sensor or motor harness loose, broken, defective

The grip end sensor (S94) did not go ON because the grip unit did arrive at the sensor position.

- Book grip motor (M43) defective
- Grip end sensor (S94) defective
- Sensor or motor harness loose, broken, defective
- Data received for signature data was incorrect.

SC797-3

Trimmings Buffer HP Sensor: Left (S103) Error

PB (D391)

The trimmings buffer sensor: left (S103) did not go OFF within the prescribed time because it failed to leave the HP sensor.

-or-

The trimmings buffer sensor: left (S103) did not go ON within the prescribed time because it failed to arrive at the HP sensor.

Technical Bulletin RICOH PAGE: 35/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Trimmed scraps in or around the trimmings buffer Trimmings buffer motor (M37) defective Left trimmings buffer sensor (S103) defective Sensor or motor harness loose, broken, defective SC797-4 Trimmings Buffer HP Sensor: Right (S100) Error В PB (D391) Trimmings buffer did not reach the trimmings dump port because: The trimmings buffer sensor: right (S100) did not go OFF within the prescribed time because it failed to leave the HP sensor. The trimmings buffer sensor: right (S103) did not go ON within the prescribed time because it failed to arrive at the HP sensor. Trimmed scraps in or around the trimmings buffer Trimmings buffer motor (M37) defective Right trimmings buffer sensor (S100) defective Sensor or motor harness loose, broken, defective SC797-5 B Trimmings Buffer Motor (M37) Error PB (D391) Trimmings buffer motor (M37) is not running. Trimming scrap jam Trimmings buffer motor (M37) defective Right or left trimmings buffer sensor (S100, S103) defective Motor or sensor connections loose, broken, defective SC797-6 Failure to Detect Book Press Plate Position PB (D391) В The book press plate sensor (S104) did not go OFF because the trimmings buffer left the HP sensor position. -or-The book press plate sensor (S104) did not go ON because the trimmings buffer did not arrive at the HP sensor position. Trimming scraps jammed in or around the trimmings buffer Trimmings buffer motor (M37) defective Book press plate sensor (S104) defective Sensor or motor harness loose, broken, defective SC797-7 Book Buffer Tray HP Sensor (S78) Error PB (D391) В

The HP sensor did not go OFF within the prescribed time after the buffer tray the book buffer tray motor turned on to pull the tray to the rear.

-or-

The HP sensor did not go ON within the prescribed time after the book buffer tray motor turned on to push the tray to the front.

- Book has iammed on the rail of the buffer
- Buffer tray overloaded
- Book buffer tray motor (M39) defective
- Book buffer tray HP sensor (S78) defective
- Motor or sensor connection loose, broken, defective

Technical Bulletin

PAGE: 36/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC797-8 B Edge Press Plate HP Sensor (S90) The edge press plate did not go OFF within the prescribed time after the edge press plate motor turned on to press the plate against the spine of the book. -orThe edge press plate did not go ON within the prescribed time after the edge press plate motor turned on to pull the plate away the spine of the book. Edge press plate motor (M36) defective Edge press plate HP sensor (S90) defective Motor or sensor connection loose, broken, defective

SC797-9	В	Press end Sensor (S87) Error	PB (D391)
00/3/3	٦		\ /
		The press end HP sensor did not go OFF with	in the time
		prescribed for press END.	
		-or-	
		Press end sensor went OFF after press end s	ensor went ON and
		stopped the press motor (M36).	
		 Edge press plate motor (M36) defective 	
		 Press end sensor (S87) defective 	
		 Data received for signature data was incor 	rect because
		signature thickness sensor (S50) defective)
		 Motor or sensor harness loose, broken, de 	efective

SC797-10	В	Slide HP Sensor (S82) Error	PB (D391)
		The HP sensor did not go OFF within the pr	escribed time
		because the slide motor did not leave the he	ome position.
		-or-	
		The HP sensor did not go ON within the pre	scribed time
		because the slide motor did not arrive at the	home position.
		Signature jam, overload	
 Slide motor (M44) defective Slide HP sensor (S82) defective Motor or sensor harness loose, broken, defective 		 Slide motor (M44) defective 	
		 Slide HP sensor (S82) defective 	
		defective	

SC797-11	В	Book Rotation HP Sensor 1 (S95) Error	PB (D391)
		Book rotation sensor 1 did not go OFF becaurotation motor 1 (M41) did not leave the hom	
		-or- Book rotation sensor 1 did not go ON becaus	
		rotation motor 1 (M41) did not arrive at the ho-	
		At power on, book rotation motor 1 failed to r through the prescribed arc for initialization.	otate the left plate

Technical Bulletin

PAGE: 37/56

Model: Aegis-P1

Date: 24-Nov-09

No.: RG178085

Jam or overload during book rotation
Book rotation motor 1 (M41) defective
Book rotation HP sensor 1 (S95) defective

Motor or sensor harness loose, broken, defective

Motor or sensor harness loose, broken, defective

SC797-12 B Book Rotation HP Sensor 2 (S91) PB (D391)
Book rotation sensor 2 did not go OFF because the book rotation motor 1 (M42) did not leave the home position.

-orBook rotation sensor 1 did not go ON because the book rotation motor 1 (M42) did not arrive at the home position.

-orAt power on, book rotation motor 1 failed to rotate the left plate through the prescribed arc for initialization.

Jam or overload during book rotation

Book rotation motor 1 (M42) defective

Book rotation HP sensor 1 (S91) defective

SC797-13 B Cutter Motor (M35) Error The blade in the trimming unit did not move from the home position or reach the blade cradle during cutting. Blade is dull, cutting poorly Cutter motor (M35) defective Blade sensor 1, blade sensor 2 defective Motor or sensor harness loose, broken, defective Note: Blade sensors 1 and 2 (S84, S85) are mounted on the cutter control board.

SC797-14	B	Book Lift Tray HP Sensor (S79) Error	PB (D391)
		The book tray lift HP sensor did not go OFF	within the prescribed
		time after the book tray lift motor (M38) turn	ed on to raise the tray
		and receive a finished book from the trimmi	ng unit.
		-or-	
		The book tray lift HP sensor did not go ON	within the prescribed
		time after the book tray lift motor (M38) turn	ed on to lower the tray
		and book.	
		 Book jammed under the tray 	
		 Book tray lift motor (M38) defective 	
		 Book lift tray HP sensor (S79) defective 	
		 Motor or sensor harness loose, broken, 	defective

SC797-15	В	Book Lift Tray Motor (M38) Error	PB (D391)
		The book lift tray motor was not rotating	g.

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

- Book lift tray motor (M38) locked, blocked by the press plate or a jammed book
- Motor defective
- Book lift tray HP sensor (S79) defective
- Motor or sensor harness loose, broken, defective

SC797-16 В Book Buffer Tray HP Sensor (S78) Error

PB (D391)

PAGE: 38/56

The book collection buffer tray HP sensor did not go OFF within the prescribed time after the book buffer tray motor (M39) turned on to raise the tray.

-or-

The book collection buffer tray HP sensor did not go ON within the prescribed time after the book buffer tray motor (M39) turned on to lower the tray.

- Book buffer tray overloaded.
- Book buffer tray motor (M39) defective
- Book buffer tray HP sensor (M78) defective
- Motor or sensor harness loose, broken, defective

SC797-17 В Blade Cradle HP Sensor (S83) Error

PB (D391)

The blade cradle HP sensor did not go OFF within the prescribed time after the blade cradle motor (M40) turned on to raise it.

-or-

The blade cradle HP sensor did not go ON within the prescribed time after the blade cradle motor (M40) turned on to lower it.

- Edge press plate or cutter interfered with movement of the blade cradle
- Blade cradle motor (M40) defective
- Blade cradle HP sensor (S83) defective
- Motor or sensor harness loose, broken, defective

SC797-18

В

В

Book Door Lock Solenoid (SOL5) Error

PB (D391)

The book stack door is locked but the book door sensor (\$98) did not go OFF.

- Book door sensor (S98) defective
- Book door lock solenoid (SOL5) defective
- Solenoid or sensor harness loose, broken, defective

Glue Heater (HTR1) Error

PB (D391)

The heater failed to start because:

600 sec. after the bookbinder left the energy save mode, the glue thermistor did not detect the target temperature (153°C±5). -or-

After the glue thermistor detected a glue temperature of 50°C, it did not detect a temperature above 140°C within 200 sec.

SC797-19

Technical Bulletin

PAGE: 39/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Heater (HTR1) defective Glue thermistor (S56) defective SC797-20 В Electrical Short in the Gluing Unit PB (D391) A short circuit or wire breakage occurred in the gluing unit. The glue thermistor (S56) detected: A temperature over 200°C more than 1 sec. (short circuit) A temperature of less than 5°C for more than 1 sec. or more than 10 sec. after power on (wire breakage) The AD value of the glue level thermistor (\$58) remained at 1023 for 10 sec (wire breakage). Heater (HTR1) defective Glue thermistor (S56) defective SC797-21 В Temperature Detection Error PB (D391) After adjustment of the glue temperature, the glue temperature thermistor (S56) detected a temperature lower than 135C for more than 10 sec. Heater (HTR1) defective Glue thermistor (S56) defective The glue level thermistor detected a temperature higher than 170°C for longer than 10 sec. after the glue had warmed up. -or-The glue level thermistor detected a temperature higher than 100°C for longer than 10 sec. after the glue had warmed up. Glue level thermistor (S58) defective SC797-22 В **Protection Circuit Error** PB (D391) The thermostat (THSW1) inside the gluing unit detected an abnormally high temperature. Glue heater (HTR1)defective Thermostat (THSW1) defective SC797-23 В Glue Surface Error 1 PB (D391) The surface of the glue in the vat did not reach the lower limit position. This error occurred when the glue surface was detected below the lower limit position 4 times in succession during the glue replenishment cycle. Glue has clogged in the vat Glue supply defective Glue level thermistor (S58) defective The glue level thermistor could not detect the glue surface at the upper limit position: 1) After glue was detected above the low limit mark, and 2) After 12 glue packets were supplied, and 3) No glue had been recently applied. Glue has clogged in the vat Glue level thermistor (S58) defective

Technical Bulletin

PAGE: 40/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC797-24	В	Glue Surface Error 2 PB (D391)		
		Without a glue vat refill, the glue level thermistor could not		
		detect the level of the glue below the upper limit (full) level, even		
		after the application of 25.42 g of glue.		
		Glue application abnormal (not applying correctly)		
		 Glue level thermistor (S58) defective 		
	ı			
SC797-25	В	Glue Level Thermistor (S58) Adjustment Error PB (D391)		
		One of the following errors occurred in the adjustment data for		
		the glue level thermistor:		
		Glue level thermistor 1 value (low limit) was out of the range:		
		128°C±14C		
		2. Glue level thermistor 2 value (high limit) was out of the range:		
		142°C±10C		
		Glue level thermistor adjustment value 1 was larger than for		
		adjustment 1.		
		Replace the EEPROM on the slave control board		
	1	Tropiaco dio EEI Trom en dio ciavo condo podra		
SC797-26	В	Timing Sensor (S5) Adjustment Error PB (D391)		
		The value for the adjustment of the timing sensor was out of		
		range (3.0V to 3.5V)		
		Timing sensor (S5) defective		
		D/A converter defective		
		A/D converter defective		
<u></u>	1			
SC797-27	В	Cover Registration Sensor (S21) Error PB (D391)		
		The value for the adjustment of the cover registration sensor		
		was out of range (3.0V to 3.5V)		
		Cover registration (S21) sensor defective		
		D/A converter defective		
		 A/D converter defective 		
<u></u>	1			
SC797-28	В	Cover Horizontal Registration Sensor: Small PB (D391)		
		(S71)		
		The value for the adjustment of the cover horizontal registration		
		sensor: small was out of range (3.0V to 3.5V)		
		 Cover horizontal registration sensor: small (S71) defective 		
		D/A converter defective		
		A/D converter defective		
	1	1		
SC797-29	В	Cover Horizontal Registration Sensor: Large (S72) PB (D39	91)	
		The value for the adjustment of the cover horizontal registration sensor		
		large was out of range (3.0V to 3.5V)		
		Cover horizontal registration sensor: large (S72) defective		
		D/A converter defective		
		A/D converter defective		
	1	1 700 conventer delective		

Technical Bulletin

PAGE: 41/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC797-30	В	Book Exit Sensor (S64) Error	PB (D391)
		The value for the adjustment of the book exit s	ensor (S64) was
		out of range (3.2V to 3.54V)	
		 Signature Exit Sensor (S64) defective 	
		 D/A converter defective 	
		 A/D converter defective 	
SC797-31	В	Leading Edge Sensor (S65) Error	PB (D391)
		The value for the adjustment of the LE sensor	(S65) was out of
		range (3.2V to 3.54V)	
		 Leading edge sensor (S65) defective 	
		 D/A converter defective 	
		 A/D converter defective 	
SC797-32	В	Trim Unit Entrance Sensor (S92) Error	PB (D391)
		The adjusted value for the trim unit entrance se	ensor was higher
		or lower than the target range.	
		Book grip motor (M43) defective Trick (M43) defective	
		 Trim unit entrance sensor (S92) defective 	
		 Motor or sensor harness loose, broken, def 	ective
SC797-33	В	Dook Degistration Conser (COO) Error	DD (D204)
30/9/-33	В	Book Registration Sensor (S88) Error The adjusted value for the book registration was	PB (D391)
		The adjusted value for the book registration was than the target range.	as flighter of lower
		 Book grip motor (M43) defective 	
		 Book registration sensor (S88) defective 	
		 Motor or sensor harness loose, broken, def 	ective
		motor or concernations leader, protein, dor	001170
SC797-34	В	Leading Edge Sensor (S65) Error	PB (D391)
		A book was not detected in the path for trimming	` ,
		slave control board received the signal for tran	_
		book has fallen past the sensor.	'
		 Main grip motors: front/rear (M24/M23) defe 	ective.
		 Leading edge sensor (S65) defective 	
		 Motor or sensor connector loose, broken, d 	efective
SC797-35	В	Book Exit Sensor (S64) Error	PB (D391)
		The book exit sensor (S64) did not turn ON, even	
		transport end signal was received when the boo	•
		from the gluing unit to the trimming unit. No boo	k was detected at
		the entrance of the trimming unit.	_
		 Failure to deliver the signature (due to a jam 	1)
		 Signature path exit motor (M30) defective 	
		 Book exit sensor (S64) defective 	
		 Motor or sensor harness loose, broken, defe 	ective

Technical Bulletin

PAGE: 42/56

No.: RG178085 Model: Aegis-P1 Date: 24-Nov-09 SC797-36 В Book Exit Sensor (S64) Late Error PB (D391) A book was not detected in the trimming unit because the book registration sensor failed to go ON. Main grip lift motor (M22) defective Book exit sensor (S64) defective Motor or sensor harness loose, broken, defective SC797-37 В Book Exit Sensor (S64) Lag Error PB (D391) The book exit sensor detected a book at power on. The cover path was closed and there was no book at the LE sensor (S65) Book exit sensor (S64) defective Sensor harness loose, broken, defective Book Exit Sensor (S64) Error SC797-38 PB (D391) В The book exit sensor did not detect the signature within the prescribed time after the glued signature exited the gluing unit. Book exit sensor (S64) connector loose, broken, defective Sensor defective SC797-39 В Main Grip Signature Sensor (S55) Error PB (D391) No signature was detected in the main grip unit after the signature passed from the sub grip to the main grip. Main grip signature sensor (S55) defective Sensor connector loose, broken, defective SC797-40 Cutter Entrance Sensor Error PB (D391) The cutter entrance sensor (S65) went ON at power on after the finisher initialized. The signature exit senor remained ON after the power on jam recovery. Detected a signature jam at power on. SC797-41 Signature Registration Sensor Lag Error В The signature registration sensor went ON at warm-up after power on. When the signature exited and the lift tray lowered, the sensor went ON. Detected a jammed book at power on. Motor or sensor harness loose, broken, defective SC797-42 В Book Arrival Sensor (S76) After the book output operation ended, the book arrival sensor remained ON because the book failed to move from the buffer tray to the output tray.

Technical Bulletin

PAGE: 43/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Trimmings buffer motor (M37) defective Book arrival sensor (S76) defective Motor or sensor harness loose, broken, defective SC797-43 В Trimming Jam Scrap Error PB (D391) The strips cut from the book could not be dumped into the trimmings box or the strips jammed between the trimmings buffer and edge press plate and trimming stopped. Three attempts failed to restore operation, then the jam alert was Strips jammed between the edge press plate and trimmings buffer. Trimmings buffer motor (M37) defective Trimmings buffer HP sensors: right or left (S100, S103) defective Motor or sensor harness loose, broken, defective **Note:** Trimming strips wider that 29 mm at the bottom and top edges (1st and 2nd cuts) and wider than 41 mm at the fore edge (3rd cut) will cause the trimming unit to jam. SC797-44 В Sub Grip Signature Sensor (S39) Lag Error PB (D391) The sub grip signature sensor did not go OFF after the sub grippers released the signature to the main grip because the signature did not move. Signature jammed in sub grip unit Sub grip signature sensor defective Sensor connector loose, broken, defective SC797-45 В Main Grip Signature Sensor (S55) Lag Jam PB (D391) The main grip signature sensor did not go OFF after the main grippers released the signature to the trimming unit because the book did not move. Book jammed in main grip unit Main grip signature sensor (S55) defective Sensor connector loose, broken, defective SC797-46 В Signature Thickness Sensor (S50) Error PB (D391) The size of the signature measured by the signature thickness sensor was smaller than the minimum. Signature thickness sensor (S50) defective Sensor connector loose, broken, defective SC797-47 В Glue Vat Roller Rotation Error PB (D391) The glue vat roller sensor did not detect any rotation at the glue vat roller within the prescribed time after the glue vat roller motor turned on.

Technical Bulletin RICOH PAGE: 44/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Glue vat roller motor (M25) defective Glue vat roller rotation sensor (S59) defective Motor or sensor connector loose, broken, defective SC797-48 В Glue Supply Motor (M33) PB (D391) Error The glue supply HP sensor (S75) did not turn ON within the prescribed time after the glue supply motor (\$33) turned on. The motor did not arrive at its home position. Glue pellet jam in the glue feeder Glue supply motor (M33) defective Glue supply HP sensor (S75) defective Motor or sensor connector loose, broken, defective SC797-49 В Front Door Lock Error PB (D391) The right front door sensor did not go OFF even though the front doors were closed and locked. The right front door sensor did not go ON even though the front doors released and opened. Front doors are detected open even though the front doors are closed and locked. Right front door solenoid (SOL3) defective Right front door sensor (S30) defective Sensor connector loose, broken, defective One or more of the front door micro-switches (MSW1, 2, 4, 5, 6, 7) defective

00707.50		0 'table at Elassas IID 0 (040) E	DD (D004)
SC797-50	В	Switchback Flapper HP Sensor (S10) Error	PB (D391)
		The switchback flapper HP sensor did not go OI	
		prescribed time after the motor turned on long e	nough to raise
		the flapper through an arc of 50 degrees.	_
		-or-	
		The switchback flapper HP sensor did not go OI	FF within the
		prescribed time after the motor turned on long e	nough to lower
	the flapper through an arc of 150 degrees.		
		Switchback Flapper HP Sensor (S10) defect	ive
		 Switchback flapper motor (M8) defective 	
		 Motor or sensor connector loose, broken, de 	fective

SC797-51 B TE Press Lever HP Sensor (S3) Error PB (D391)
--

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The TE press lever HP sensor did not go ON when the TE press lever motor turned on to move the lever through an arc of 30 degrees to release the lever.

-or-

The TE press lever HP sensor did not go OFF when the TE press lever motor turned on to move the lever through an arc of 20 degrees to close the lever.

- TE press lever HP sensor (S3) defective
- TE press lever motor (M3) defective
- Sensor or motor connector loose, broken, defective

SC797-52

Jog Fence HP Sensor: Front/Small (S12) Error PB (D391

The front jog fence HP sensor for small size paper did not go ON within the prescribed time when the front jogger motor turned on to move the fence.

-or-

В

В

В

The front jog fence HP sensor for small size paper did not go OFF within the prescribed time when the front jogger motor turned on to move the fence.

- Jog fence HP sensor: front/small (S12) defective
- Jogger motor: front (M4) defective
- Sensor or motor connector loose, broken, defective

SC798-1

Jog Fence HP Sensor: Front/Large (S14) Error

PB (D391)

PAGE: 45/56

The front jog fence HP sensor for large size paper did not go ON within the prescribed time when the front jogger motor turned on to move the fence.

-or-

The front jog fence HP sensor for large size paper did not go OFF within the prescribed time when the front jogger motor turned on to move the fence.

- Jog fence HP sensor: front/large (S14) defective
- Jogger motor: front (M4) defective
- Sensor or motor connector loose, broken, defective

SC798-2

Jog Fence HP Sensor: Rear/Small (S13) Error

PB (D391)

The rear jog fence HP sensor for small size paper did not go ON within the prescribed time when the rear jogger motor turned on to move the fence.

-or-

The rear jog fence HP sensor for small size paper did not go OFF within the prescribed time when the rear jogger motor turned on to move the fence.

- Jog fence HP sensor: rear/small (S13) defective
- Jogger motor: rear (M5) defective
- Sensor or motor connector loose, broken, defective

Technical Bulletin

PAGE: 46/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

SC798-3	В	Jog Fence HP Sensor: Rear/Large (S15) Error	PB (D391)
		The rear jog fence HP sensor for large size paper within the prescribed time when the rear jogger representation to move the fence.	
		-or-	
		The rear jog fence HP sensor for large size paper	•
OFF within the prescribed time when the rear jogger m		gger motor	
		turned on to move the fence.	
		Jog fence HP sensor: rear/large (S15) defect	ive
		Jogger motor: rear (M5) defective	
		 Sensor or motor connector loose, broken, de 	fective

	1		
SC798-4	В	Switchback Roller HP Sensor (S11) Error	PB (D391)
		The switchback roller HP sensor did not go ON	within the
		prescribed time after the motor turned on to rais	e the roller
		through an arc of 40 degrees.	
		-or-	
		The switchback roller HP sensor did not go OFF	within the
		prescribed time when the motor turned on to low	er the roller
		through an arc of 20 degrees.	
		 Switchback Roller HP Sensor (S11) defective 	9
		 Switchback Roller Motor (M7) defective 	
		 Sensor or motor connector loose, broken, de 	efective

SC798-5	В	Stacking Tray Lower Limit Sensor (S7) Error	PB (D391)
		The stacking tray lower limit sensor did not go C	
		prescribed time when the stacking tray lift motor lower the tray.	turned on to
		-or-	
		The stacking tray lower limit sensor did not go C	
		prescribed time when the stacking tray lift motor	turned on to
	raise the tray 30 mm.		
		 Stacking Tray Lower Limit Sensor (S7) defect 	tive
		 Stacking Tray Lift Motor (M2) defective 	
		 Sensor or motor connector loose, broken, de 	efective

SC798-6	В	Paper Detection Sensor: Front/Rear (S1/S2)	PB (D391)
---------	---	--	-----------

Technical Bulletin

PAGE: 47/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The paper detection sensor at the front of the stacking tray did not go ON within the prescribed time after the stacking tray overflow sensor (S6) went ON and the stacking tray lift motor turned on to raise the tray.

-or-

The paper detection sensor at the front of the stacking tray did not go OFF within the prescribed time when the stacking tray lift motor turned on to lower the tray.

-or-

The paper detection sensor at the rear of the stacking tray did not go ON within the prescribed time after the stacking tray overflow sensor (S6) went ON and the stacking tray lift motor turned on to raise the tray.

-or-

The paper detection sensor at the rear of the stacking tray did not go OFF within the prescribed time when the stacking tray lift motor turned on to lower the tray.

- Paper Detect Sensor: Front (S1) defective
- Stacking Tray Lift Motor (M2) defective

SC798-7 B Stacking Tray Overflow Sensor (S6) Error PB (D391)

The stacking tray overflow sensor did not go ON within the prescribed time when the stacking tray lift motor turned on to raise the tray 70 mm.

-or-

The stacking tray overflow sensor did not go OFF within the prescribed time after the stacking tray lift motor turned on to lower the tray so paper could be removed from the tray by the operator.

- Stacking Tray Overflow Sensor (S6) defective
- Stacking Tray Lift Motor (M2) defective
- Sensor or motor connector loose, broken, defective

SC798-8 B Stacking Tray HP Sensor (S9) Error PB (D391) The stacking tray HP sensor did not go ON within the prescribed time when the stacking tray motor turned on to move the tray toward the sensor. -or-

The stacking tray HP sensor did not go OFF when the stacking tray motor turned on to move the tray away from the sensor.

- Stacking HP Sensor (S9) defective
- Stacking Tray Motor (M9) defective
- Sensor or motor connector loose, broken, defective

	SC798-9	В	Stacking Weight HP Sensor (S16) Error	PB (D391)
--	---------	---	---------------------------------------	-----------

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The stacking weight HP sensor did not go ON within the prescribed time when the stacking weight motor turned on to move the tray toward the sensor.

-or-

The stacking weight HP sensor did not go OFF within the prescribed time when the stacking tray motor turned on to move the tray away from the sensor.

- Stacking Weight HP Sensor (S16) defective
- Stacking Weight Motor (M6) defective
- Sensor or motor connector loose, broken, defective

SC798-10 B Sub Grip HP Sensor (S37) Error

PB (D391)

PAGE: 48/56

The sub grip HP sensor did not go ON within the prescribed time after the sub grip lift motor turned on to raise the sub grip unit.

-or-

The sub grip HP sensor did not go OFF within the prescribed time after the sub grip lift motor turned on to lower the sub grip unit.

- Sub Grip Lift Motor (M17) defective
- Sub Grip HP Sensor (S37) defective
- Sensor or motor connector loose, broken, defective

SC798-11 B Sub Grip Size HP Sensor (S38)

PB (D391)

The sub grip size HP sensor did not go ON within the prescribed time after the sub grip size motor turned on for horizontal adjustment to the paper size, or the sub grip size HP sensor was already OFF when the sub grip size horizontal adjustment started.

-or-

The sub grip size HP sensor did not go OFF within the prescribed time after the sub grip size motor turned on to close for horizontal adjustment to the paper size, or the sub grip size HP sensor was already ON when the sub grip size horizontal adjustment started.

- Sub Grip Size Motor (S19) defective
- Sub Grip Size HP Sensor (S38) defective
- Sensor or motor connector loose, broken, defective

SC798-12 B Sub Grip Open Sensor (S40) Error

PB (D391)

The sub grip open sensor did not go ON within the prescribed time after the sub grip lift motor turned on to open the sub grip unit.

-or-

The sub grip open sensor did not go OFF within the prescribed time after the sub grip lift motor turned on to close the sub grip unit.

Technical Bulletin

PAGE: 49/56 Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Sub Grip Open Motor (S20) defective Sub Grip Open Sensor (S40) defective Sensor or motor connector loose, broken, defective SC798-13 В Sub Grip Close Sensor (S41) Error PB (D391) The sub grip close sensor did not go ON within the prescribed time after the sub grip lift motor turned on to close the sub grip unit. -or-The sub grip close sensor did not go OFF within the prescribed time after the sub grip open motor turned on to open the sub grip unit. Sub Grip Open Motor (S20) defective Sub Grip Close Sensor (S41) defective Sensor or motor connector loose, broken, defective SC798-14 В Main Grip HP Sensor (S44) Error PB (D391) The main grip HP sensor did not go ON within the prescribed time after the main grip lift motor turned on to raise the main grip unit, or the main grip HP sensor was already ON when the motor started to lower the main grip unit. -or-The main grip HP sensor did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit, or the main grip HP sensor was already ON when the motor started to lower the main grip unit. Main Grip Lift Motor (M22) defective Main Grip HP Sensor (S44) Error Sensor or motor connector loose, broken, defective SC798-15 В Main Grip Press Sensor 1 (S48) Error PB (D391) The main grip press sensor 1 did not go ON within the prescribed time after the main grip lift motor turned on to raise the main grip unit from the main grip signature registration position. -or-The main grip press sensor 1 did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit to the main grip signature registration position. Main Grip Lift Motor (M22) defective

SC798-16 B Main Grip Press Sensor 2 (S49) Error	PB (D391)
---	-----------

Main Grip Press Sensor 1 (S48) defective

Sensor or motor connector loose, broken, defective

Technical Bulletin

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The main grip press sensor 2 did not go ON within the prescribed time after the main grip lift motor turned on to lower the main grip unit and signature to the point where the signature was to be pressed into the center of the cover.

PAGE: 50/56

PB (D391)

The main grip press sensor 2 did not go OFF within the prescribed time after the main grip lift motor turned on to raise the main grip unit away from the point where the signature was pressed into the center of the cover.

- Main Grip Lift Motor (M22) defective
- Main Grip Press Sensor 2 (S49) defective
- Sensor or motor connector loose, broken, defective

SC798-17 B Main Grip Signature Exit Error

The book exit sensor did not go ON within the prescribed time after the main grip lift motor moved the signature to the delivery point when the signature was passed from the main grip unit to the book exit roller.

- Signature broken, bent
- Signature jammed in the main grip unit
- Main Grip Lift Motor (M22) defective
- Book Exit Sensor (S64) defective
- Sensor or motor connector loose, broken, defective

SC798-18 B Main Grip HP Sensor: High (S45) Error PB (D391)

The main grip high HP sensor did not go ON within the prescribed time after the main grip lift motor turned on to raise the main grip unit.

-or-

The main grip high HP sensor did not go OFF within the prescribed time after the main grip lift motor turned on to lower the main grip unit.

- Main Grip Lift Motor (M22) defective
- Main Grip HP Sensor: High (S45) defective
- Sensor or motor connector loose, broken, defective

SC798-19 B Main Grip Open Sensor: Rear/Front (S47, S48) PB (D391)

The rear main grip open sensor did not go ON within the prescribed time after the rear grip motor turned on to open the main grip unit.

-or-

The rear main grip open sensor did not go OFF within the prescribed time after the rear grip motor turned on to close the main grip unit.

- Grip Motor: Rear (M23) defective
- Main Grip Open Sensor: Rear (S47) defective

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

The rear main grip close sensor did not go ON within the prescribed time after the rear grip motor turned on to close the main grip unit.

-or-

The rear main grip close sensor did not go OFF within the prescribed time after the rear grip motor turned on to open the main grip unit.

- Grip Motor: Rear (M23) defective
- Main Grip Close Sensor: Rear (S54) defective
- Sensor or motor connector loose, broken, defective

SC798-20 B Main Grip Encoder: Rear Sensor (S46) Error

PB (D391)

PAGE: 51/56

The rear main grip encoder sensor could not be detected ON/OFF within the prescribed time after the rear grip motor turned on to open and close the main grip unit.

- Main Grip Encoder: Rear Sensor (S46) defective
- Grip Motor: Rear (M23) defective
- Main Grip Encoder: Rear Sensor (S46) defective
- Sensor or motor connector loose, broken, defective

SC798-21

Main Grip Open/Close Sensor: Front (S51,S53) PB (D391)

The front main grip open sensor did not go ON within the prescribed time after the front grip motor turned on to open the main grip unit.

-or-

В

The front main grip open sensor did not go OFF within the prescribed time after the front grip motor turned on to close the main grip unit.

- Grip Motor: Front (M24) defective
- Main Grip Open Sensor: Front (S51) defective
- Sensor or motor connector loose, broken, defective

The front main grip close sensor did not go ON within the prescribed time after the front grip motor turned on to close the main grip unit.

-or-

The front main grip close sensor did not go OFF within the prescribed time after the front grip motor turned on to open the main grip unit.

- Grip Motor: Front (M24) defective
- Main Grip Close Sensor: Front (S53) defective
- Sensor or motor connector loose, broken, defective

SC798-22

В

Main Grip Encoder: Front Sensor (S52) Error

PB (D391)

The front main grip encoder sensor could not be detected ON/OFF within the prescribed time after the front grip motor turned on to open/close the main grip unit.

Technical Bulletin

PAGE: 52/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085 Main Grip Encoder: Front Sensor (S52) defective Grip Motor: Front (M24) defective Main Grip Encoder: Front Sensor (S52) defective Sensor or motor connector loose, broken, defective SC798-23 Signature Exit Path HP Sensor (S67) Error В PB (D391) The signature exit path HP sensor did not go ON within the prescribed time after the signature exit path motor turned on to retract the signature exit roller. The signature exit path HP sensor did not go OFF within the prescribed time after the signature exit path motor turned on to move the signature exit roller. Signature Exit Path Motor (M30) defective Signature Exit Path HP Sensor (S67) defective Sensor or motor connector loose, broken, defective SC798-24 В Signature Exit Path Press Sensor (S68) Error The signature exit path press sensor did not go ON within the prescribed time after the signature exit path motor turned on to feed the book into the nip of the signature exit roller. -or-The signature exit path press sensor did not go OFF within the prescribed time after the signature exit path motor turned on to retract the signature exit roller. Signature Exit Path Motor (M30) defective Signature Exit Path Press Sensor (S68) defective Sensor or motor connector loose, broken, defective SC798-25 Inserter Drive Switch Sensor (S16) PB (D391) В The drive switch sensor in the inserter unit did not go OFF within the time prescribed for the drive switching motor (M2) to switch drives. -or-The drive switch sensor in the inserter unit did not go ON within the prescribed time. Drive switch motor (M2) defective Drive switch sensor (S16) defective Sensor or motor connector loose, broken, defective SC798-26 В Inserter Tray A Error PB (D391)

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

Inserter Tray A (upper tray) failed to leave its lower limit sensor (S11) within the prescribed time after the Tray A lift motor turned on.

PAGE: 53/56

-or-

Inserter Tray A (upper tray) failed to arrive at its paper feed sensor (S4) within the prescribed time after the Tray A lift motor turned on.

- Lift Motor: Tray A (M3) defective
- Lower limit sensor: Tray A (S11) defective
- Paper feed sensor (S4) defective
- Sensor or motor connector loose, broken, defective

SC798-27 B Inserter Tray B Error PB (D391) Inserter Tray B (lower tray) failed to leave its lower limit sensor (S12) within the prescribed time after the Tray B lift motor turned on. -orInserter Tray B (lower tray) failed to arrive at its paper feed sensor (S10) within the prescribed time after the Tray B lift motor turned on. - Lift Motor: Tray B (M4) defective - Lower Limit Sensor: Tray B (S12) defective - Sensor or motor connector loose, broken, defective

SP Tables for Perfect Binder (D391)

6524	Stack Thickness Volume Adjustment		
001	0 mm Adjust	[1 to 1023 / 97 / 1]	
002	25 mm Adjust	[1 to 1023 / 865 / 1]	

6525	Glue Remain Thermistor: Wet Side	
001	Glue Vat: Wet Side Lower Limit	[0 to 255 / 132 / 1]
002	Glue Vat: Wet Side Upper Limit	[0 to 255 / 142 / 1]

6526	Input Check: Perfect Binder	Perfect Binder (D391)
001	Entrance sensor	
002	Timing Sensor	
003	Jog Sensor HP: Front	
004	Jog Sensor HP: Rear	
005	Jog Sensor HP: Front Large	
006	Jog Sensor HP: Rear Large	
007	Cover Path: Sensor 1	
800	Cover Path: Sensor 2	

Technical **B**ulletin

PAGE: 54/56

Model: Aegis-P1 Date: 24-Nov-09 No.: RG178085

wodei.	Aegis-P1	Date: 24-Nov-09	No.: RG17
009	Signature Path: Sensor 1		
010	Signature Path: Sensor 2		
011	Inserter Communication Sensor: Before	Joining	
012	Switchback Flapper HP Sensor		
013	Switchback Roller HP Sensor		
014	Cover Registration Sensor		
015	Straight-Through Exit Sensor		
016	TE Press Lever HP Sensor		
017	Stack Overflow Sensor		
018	Tray Lower Limit Sensor		
019	Paper Detect Sensor: Front		
020	Paper Detect Sensor: Rear		
021	Cover Guide HP Sensor: Right		
022	Cover Guide HP Sensor: Left		
023	Cover Guide Open Sensor: Right		
024	Cover Guide Open Sensor: Left		
025	Stack Weight Move HP Sensor		
026	Stack Tray HP Sensor		
027	Front Door SW		
028	Top Cover Sensor		
029	Top Cover Switch		
030	Glue Tank Cover Sensor		
031	Temperature Start Switch		
032	Inserter Connect Signal		
033	Glue Tank Empty Sensor		
034	Glue Tank Full Sensor		
035	24 V Guard 1		
036	24 V Guard 2		
037	Stack Tray Empty Sensor		
038	Front Door Lock Sensor		
039	Power Supply Fan Lock: Left		
040	Sub Grip Upper HP Sensor		
041	Signature Exit Sensor		
042	Size Move HP Sensor		
043	Registration Unit HP Sensor		
044	Post Main Grip Encoder Sensor		
045	24V 2 Check Signal		
046	Spine Fold Press Sensor: Right		
047	Main Grip HP Sensor: Left	mall	
048 049	Cover Horizontal Registration Sensor: S Cover Horizontal Registration Sensor: La		
050	Glue Tank HP Sensor	ai y c	
050	Main Grip HP Sensor		
052	Main Grip Front Encoder Sensor		
053	24V 3 Check Signal		
054	Main Grip Press Sensor: Left		
007	I Main One i 1633 Ochsor. Leit		

Technical Bulletin

Date: 24-Nov-09 No.: RG178085

PAGE: 55/56

Model: A	Aegis-P1	Date: 24-Nov-09	No.: RG17
055	Main Grip Press Sensor: Small		
056	Sub Grip Paper Sensor		
057	Sub Grip Open Sensor		
058	Sub Grip Close Sensor		
059	Spine Fold Close Sensor: Left		
060	Spine Plate Open Sensor		
061	Spine Plate Closed Sensor		
062	Spine Fold HP Sensor: Left		
063	Spine Fold HP Sensor: Right		
064	Cutter LE Detect Sensor		
065	Main Grip Rotate Enable Sensor		
066	Main Grip Rotate Bind Position Sensor		
067	Main Grip Rotate HP Sensor		
068	Rear Main Grip Open Sensor		
069	Rear Main Grip Close Sensor		
070	Front Main Grip Open Sensor		
071	Front Main Grip Close Sensor		
072	Main Grip Signature Sensor		
073	Thermostat Abnormal		
074	Glue Heater Thermistor		
075	Glue Unit HP Sensor		
076	Book Output Path HP Sensor		
077	Book Output Path Push Sensor		
078	Sub Grip HP Sensor		
079	Signature Main Grip Position Sensor		
080	Signature Fan 2 Lock: Rear		
081	Signature Fan 2 Lock: Front		
082	Signature Fan 1 Lock: Rear		
083	Signature Fan 1 Lock: Front		
084	Power Supply Fan Lock: Center		
085	Power Supply Fan Lock: Rear		
086	Spine Plate Fan Lock: Upper Rear		
087	Spine Plate Fan Lock: Front		
088	Spine Plate Fan Lock: Lower Rear		
089	Spine Plate Fan Lock: Lower Front		
090	Glue Tank Roller: Rotate Detect Sensor		
091	Glue Tank HP Sensor: Front		
092	Glue Supply Fan: Lock 1		
093	Glue Supply Fan Lock 2		
094	Book Catch Fence HP Sensor		
095	Output Stack Door Sensor		
096	Output Stack Door Switch		
097	Book Buffer Tray HP Sensor		
098	Trim Scrap Buffer HP Sensor: Right		
099	Press HP Sensor		
100	Blade Cradle HP Sensor		

Technical Bulletin

PAGE: 56/56

Model: A	Aegis-P1	Date: 24-Nov-09	No.: RG178085
101	Cutter Limit Sensor		
102	Cutter Area Sensor 1		
103	Entrance Path Sensor		
104	Book Registration Sensor		
105	Cutter Area Sensor 2		
106	LE Detect Sensor		
107	Grip End Sensor		
108	Book Rotate HP Sensor 1: Right		
109	Press End Sensor		
110	Slide HP Sensor		
111	Grip HP Sensor		
112	Book Rotate HP Sensor 2: Left		
113	Press Limit Sensor		
114	Trim Scrap Box Sensor		
115	Book Arrival Sensor		
116	Book Detect Sensor: Output Tray		
117	Output Tray HP Sensor		
118	Trim Scrap Buffer HP Sensor		
119	Trim Scrap Box Full Sensor		
120	Front Door SW: Center		
121	Front Door SW: 36V		
122	Thrust Plate Sensor		
123	Upper Tray Empty Sensor		
124	Lower Tray Empty Sensor		
125	Upper Tray Pickup Sensor		
126	Lower Tray Pickup Sensor		
127	Inserter Cover Sensor		
128	Lower Tray Paper Out Sensor		
129	Lower Tray Registration Sensor		
130	Upper Tray Registration Sensor		
131	Upper Tray: Large Paper Sensor		
132	Upper Tray: Small Paper Sensor		
133	Lower Tray Lower Limit Sensor		
134	Transport Sensor: Midway		
135	Inserter Unit Sensor		
136	Upper Tray Lower Limit Sensor		
137	Drive Gear Switching Sensor		
138	Transport Sensor 1		
139	Transport Sensor 2		
140	Relay Unit Transport Sensor		
141	Relay Unit Front Door Sensor		

Technical Bulletin

PAGE: 1/12

Model: Aegis-P1/C1			Dat	e: 07-Des	-09	No.: RG178086
Subject: Request for Replacement of Parts Containing RoHS Restricted Substances				Prepare	d by: N.ii	ida
From: PP Service Planning Department 1G						
Classification:	Troubleshooting	☐ Part info	information Action		required	
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()	☐ Tier2	

This RTB is applied only for the EU market.

PROBLEM

PBDE contained in the PSU exceeds the limit of 1000ppm, which is a regulation enforced by RoHS. Therefore, the PSU is inapplicable.

REQUEST

Please replace the PSU with the modified PSU (P/N: G1789907 MODIFICATION: POWER: SUPPLY: UNIT) from ESPC inventory on your next service visit.

The removed unit contains substances which are restricted by RoHS and must be disposed of according to local laws/regulations.

OBJECT SERIAL NUMBER

Please replace the PSU for field machines having the following S/N:

Buffer Pass Unit Type 5000

Product Code	From	То	Q'ty
M37927	S6790500006	S6790500011	6
M37927	S6790700023		1
M37927	S6790700027	S6790700029	3
M37927	S6790700032	S6790700035	4
		Total	14



Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

Pro C900/900S

Product Code	RCL(RPS)	Srial Number	MB&R	Q'ty
1 Toduct Code	From	То	Srial Number	Q ty
G17897	S3290190051		M8792900005	1
G17897	S3290190054		S3292700014	1
G17897	S3290190055		S3293000016	1
G17897	S3290190056		S3293100012	1
G17897	S3290190057		S3292700012	1
G17897	S3290190058		M8793000012	1
G17897	S3290190059		S3293100002	1
G17897	S3290190060		S3293100010	1
G17897	S3290190061		M8792700014	1
G17897	S3290190062		M8793100004	1
G17897	S3290190063		M8793100005	1
G17897	S3290190064		M8793100013	1
G17897	S3290190065		S3293100001	1
G17897	S3290290001		M8793100001	1
G17897	S3290290002		M8793000011	1
G17897	S3290290003		S3293100004	1
G17897	S3290290005		M8793100003	1
G17897	S3290290006		S3293100011	1
G17897	S3290290007		M8793100002	1
G17897	S3290290008		M8793000002	1
G17897	S3290390002		M8793100011	1
G17897	S3290390003		M8792900009	1
G17897	S3290390004		S3292900015	1
G17897	S3290390005		M8793100014	1
G17897	S3290390006		M8792900011	1
G17897	S3290390007		S3292900014	1
G17897	S3290390009		M8793200010	1
G17897	S3290390010		M8793200003	1
G17897	S3290390013		M8793100008	1
G17897	S3290390014		M8792900006	1
G17897	S3290390015		M8793100009	1
G17897	S3290390016		S3292900016	1
G17897	S3290390017		S3293200001	1
G17897	S3290390019		M8793200001	1
G17897	S3290390032		S3293200002	1
G17897	S3290390033		M8793200002	1
G17897	S3290390034		M8793200009	1
G17897	S3290390035		M8793200004	1
G17897	S3290390036		S3293200004	1
G17897	S3290390037		S3293300003	1
G17897	S3290390038		M8793200005	1
G17897	S3290390039		M8793200008	1
G17897	S3290390040		S3293300002	1
G17897	S3290390042		S3293300005	1
G17897	S3290490001		M8793300004	1
317007	50200 1 00001		14107 00000004	

	Srial Number	MB&R	Q'ty
From	То	Srial Number	Q ty
S3290490002		M8793300015	1
S3290490005		M8793300005	1
S3290690003		M8793300020	1
S3290690005		S3293300006	1
S3290690006		M8793400010	1
S3290690007		M8793300012	1
S3290690009		S3293300004	1
S3290690010		M8793300014	1
S3290690011		S3293300007	1
S3290690012		S3293300008	1
S3290690013		M8793400003	1
S3290690014		M8793300009	1
S3290690015		M8793300007	1
S3290690016		M8793300008	1
S3290690017		M8793400001	1
S3290690018		M8793400008	-
S3290690019		M8793400002	1
S3290690020		M8793300013	1
S3290690021		M8793300006	1
S3290690022		M8793300016	1
S3290690023		M8793300010	1
S3290690024		M8793300017	1
S3290690025		M8793300018	-
S3290690026		M8793300019	-
S3290690027		M8793300011	-
S3290690028		S3293400002	1
S3290790005		S3293400005	1
S3290790006		M8793400007	1
S3290790007		M8793400006	1
S3290790008		M8793400009	1
S3290790014		S3293400006	1
S3290790015			1
			1
			1
			1
			1
	S3290790004		3
			5
			3
			3
			3
			1
	\$3290490005 \$3290690005 \$3290690006 \$3290690007 \$3290690009 \$3290690010 \$3290690011 \$3290690011 \$3290690011 \$3290690014 \$3290690015 \$3290690016 \$3290690018 \$3290690018 \$3290690019 \$3290690020 \$3290690021 \$3290690021 \$3290690022 \$3290690025 \$3290690025 \$3290690025 \$3290690026 \$3290690027 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290690028 \$3290790006 \$3290790006 \$3290790006 \$3290790001 \$3290790015 \$3290790015 \$3290790015 \$3290790001 \$3290790002 \$3290790001 \$3290790001 \$3290790001 \$3290790001 \$3290790001 \$3290790001 \$3290790001 \$3290790001	\$3290490005 \$3290690003 \$3290690006 \$3290690007 \$3290690009 \$3290690010 \$3290690011 \$3290690012 \$3290690013 \$3290690014 \$3290690015 \$3290690016 \$3290690017 \$3290690019 \$3290690020 \$3290690021 \$3290690022 \$3290690023 \$3290690024 \$3290690025 \$3290690025 \$3290690025 \$3290690026 \$3290690027 \$3290690028 \$3290790005 \$3290790005 \$3290790016 \$3290790016 \$3290790017 \$3290790017	S3290490005 M8793300005 S3290690003 M8793300020 S3290690005 S3293300006 S3290690006 M8793400010 S3290690007 M8793300012 S3290690009 S3293300004 S3290690010 M8793300014 S3290690011 S3293300007 S3290690012 S3293300008 S3290690013 M8793400003 S3290690014 M8793300007 S3290690015 M8793300007 S3290690016 M8793300000 S3290690017 M8793400001 S3290690018 M8793400002 S3290690019 M8793300001 S3290690021 M8793300016 S3290690022 M8793300010 S3290690023 M8793300010 S3290690024 M8793300011 S3290690025 M8793300011 S3290690026 M8793300011 S3290790005 S3293400002 S3290790006 M8793400000 S3290790007 M8793400000 S3290790008 M8793400000 S3290790001

PAGE: 2/12



PAGE: 3/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

REPLACEMENT METHOD

Please refer to the procedures below for the replacement work.


Procedure

For Pro C900/900S (page 3): Work time is approximately 30 min.

For Buffer Pass Unit Type 5000 (page 11): Work time is approximately 17 min.

Procedure for Pro C900/900S

1. Take out 3 screws at the rear top. Remove the cover in the arrow direction. (2 hooks)



2. Take out 2 screws at the rear bottom.








PAGE: 4/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086


3. Take out 2 Sems Screws and open the rear cover. (Open carefully)









4. Take out 5 Connectors of the board which is shown in the right bottom of the picture.












Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

5. Take out 3 clamps.



6. Take out 4 screws and open the cover.







PAGE: 5/12

7. Take out 2 clamps.



8. Take out 2 screws and a hook, then hold to the right.








PAGE: 6/12


Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

9. Take out 4 Connectors and a clamp.



10. Take out 5 screws and a stopper, then remove the PSU.







PAGE: 7/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086


11. Remove the harness from the PSU.





The wires break easily, so pull them from the board at the root of wires.

12. Connect the Harness which was removed at step 11 to the replacement PSU.




13. Install the PSU with 5 Screws and a Stopper.















PAGE: 8/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086


14. Set 4 Connectors and 3 Clamps.



15. Close the cover and attach 4 screws.




16. Set Clamps (3 points)




Technical Bulletin

PAGE: 9/12


Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086



18. Fix 2 Screws and 1 hook.



19. Close the rear cover.





Model: Aegis-P1/C1

Technical Bulletin

Date: 07-Des-09 No.: RG178086

20. Fix Screws at rear bottom.








PAGE: 10/12

21. Fix 2 Sems Screws and replace the cover (2 Hooks) .





22. Fix Screws. (3 points)




PAGE: 11/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

Procedure for Buffer Pass Unit Type 5000

1.Remove Left Side Cover (Take out 6 Tapping Screw:4x8) and Right Side Cover (Take out 6 Tapping Screw:4x8).




2.Remove Rear Cover (Take out 5 Tapping Screw:4x8)






3. Take out 5 PSU Connectors in red circles and 1 Cable Clamp in a blue circle.



4. Take out 5 Sems Screws and remove PSU.






PAGE: 12/12

Model: Aegis-P1/C1 Date: 07-Des-09 No.: RG178086

5. Install Replacement PSU in the reverse order of step 3 and step 4.



Attach the Rear Cover, Left Side Cover and Right Side Cover in the reverse order of step 1 and step 2.



RICOH

Technical Bulletin

	PAGE. 1/2
	No.: RG178087
. ł	Kawamura
or	n required
,i,c	e manual revision

DACE. 1/2

Also see **RTB 97**

Model: AG-P1 /	C1		Dat	e: 08-Dec	-09	No.: RG178087
Subject: Solution for Relay Board failure G178-5281			Prepare	d by: H. I	Kawamura	
From: PPBG QA	From: PPBG QA/Service Planning Dept.					
Classification:	Classification: 🛛 Troubleshooting 🔻 Part information		orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G1785281	G1785304	PCB:RB	1	\times/\bigcirc	187	4	

SYMPTOM

Various SCs occur.

SC304, 305, 306, 307, 344, 345, 346, 347, 477, 479, 490, 520, 521, 523, 524, 530-01, 601, 675-01, 991,

CAUSES

The card inside the relay melts, due to exposure to heat. The contacts of the relay do not close correctly.

The relay works as an interlock switch for several power supply lines.


Several SC calls occur when the card is deformed.

Factors for melting of the card are:

- The heat generated by the cement resistors near the relay raises the temperature inside the relay.
- Load on the fusing motor increases.
 - Mechanical drive load on the fusing motor increases due to the following factors.
 - → PM parts in the fusing unit are used more than the PM replacement cycle.
 - ♦ By using paper that contains a lot of calcium carbonate, the oil application gets dirty, and the oil film on the fusing belt gets less uniform.

As a result, the electrical current in the fusing motor increases. This causes the cement resistors and relay to generate more heat than usual.

The relay itself generates heat (depends on the resistance of the contacts of the relay)



PAGE: 2/2

Model: AG-P1 / C1 Date: 08-Dec-09 No.: RG178087

SOLUTION

To prevent the generation of heat," soft start circuit" and "circuit for prevent generating heat at the cement resistor" were added to the board as a modification.


As a result, the p/n changes from G1785281 to **G1785304**. When relay failure occurs, use the part with p/n **G1785304** as a replacement.

Procedure for distinguish between defective RB board and good RB board After turning

If the LED lights on the machine with the front door closed, check the LED condition on IOB 1 and IOB2. If the condition is the following, Relay (RY2) on the RB board is most likely out of order.

IOB 1: LED 104, 105 and 106 are OFF. (LED 101, 102, 103, 107, 108, 109, and 110 are ON)

IOB 2: LED 103 is OFF. (LED 101, 102, and 104 are ON. Please ignore all other LEDs)



RICOH

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1 Da			Dat	Date: 14-Dec-09		No.: RG178088
Subject: Release note System Patch EXP01 (Composite01) for Software Version3.0 for Aegis-P1/C1 EFI) for	Prepare	d by: N. I	ida
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☐ Other (al		Service	n required be manual revision fit information

This RTB is the release note System Patch EXP01 (Composite01) for Software Version3.0 for Aegis-P1/C1 EFI

Files included in this release					
File name	File size				
1-12PJUX.EXE	11.2MB				

1.Newly Added Functions

none

2.Problem Solving (Measures)

Following are the key problems that have been given measures.

-Problems in the Field

Defect #	Description
1-10P9DY	Tab Kick out UI not available in "insert tab" menu
1-11V1JU	A slanted line is printed on a part of the gradation.
1-120GDP	Print stops with having displayed "Printing" after SC794.
1-1214ZT	The operator can not understand what Reset means.
1-125C5H	Raster path jobs will not pull pages from the post fuser trays after upgrade to 3.0

3.Installation instructions

- To install run patch by double click and follow the step by step instructions from the install wizard
- 2. When install complete, you will be given option to restart/reboot the system.
- 3. Restart system: you will see
 - a. restart
 - b. fiery startup
 - c. install patch
 - d. reboot
- 4. Reboot system: you will see
 - a. reboot
 - b. fiery startup
 - c. install patch
 - d. reboot
- 5. Verify patch install correct on configuration page.

Note1: Patch does not change Fiery version.

	J	

PAGE: 1/4

Model: AG-P1/C1 Da				Date: 29-Dec-09		No.: RG178089
Subject: Release note for System Software Version4.0 for Aegis-P1/C1 EFI				Prepared	d by: N. Ii	ida
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☐ Other (al		Service	required ce manual revision fit information

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release				
File name	File size			
1-14N2CZ.exe	137 MB			

1.Newly Added Functions

-None

2.Problem Solving (Measures)

Following are the key problems that have been given countermeasures.

-Problems in the Field

No	Symptom Details	Remarks
1	Thick1, 2 can be selected to BodyPaper.	Spec adjustment
2	When "Tray1, 2 and 7" are selected, "Coated" cannot be selected to input tray in the	Spec adjustment
_	cover.	
	P-bind:A choice of Body Paper Size becomes only A4 & LT.	Spec adjustment
	In consecutive Mismatch, Timer does not begin with a set point.	Spec adjustment
6	In Gang-up print, "Thick3" and "BackedCopied" are excluded and cannot be set.	Spec adjustment
	BM4.0:There is the combination of BodySize and CoverSize that cannot do maximum Trim when set Spine value.	Spec adjustment
	P-bind:After Process & hold, when covers are increased in Preview, Jam occurs.	Spec adjustment
	BM4.0:Saddle print: Thin paper is demanded when Pre-Printed is specified and no	Spec adjustment
	paper is in Interposer Upper/Lower Tray.	
	Impose:Paper cannot be fed from the inteposer Tray.	Field problem
11	An error occurs when try to lauch CWPT after restoring Feiry settings of Gershwin	Field problem
	2.0 to Gershwin 4.0.	
	It is impossible to refer and edit address book.	Field problem
	MIB acquired with Paper Tray empty state is different from specifications.	Field problem
14	PB job starts when PB inter poser tray is opened.	-
	RingBinder:A wrong error message is displayed when print a ring bind job with the ring comb empty state.	Field problem
16	Performance with sub set staple job.	Field problem
17	After the subset staple job is printed, it stays in "Printing" state.	Field problem
18	Unexpected Watermark is printed on MacOS10.	-
19	The setting of the "Scale" function does not work.	Field problem
20	Full-bleed print support on custom-size paper	Spec modified



PAGE: 2/4

Model: **AG-P1/C1** Date: 29-Dec-09 No.: RG178089

Note:

- It is necessary to update User Software / Printer Driver when you update the System Software Version 4.0.(Part No : D0167145)

Fixed with User Software

1	UI is not correct in the combination of "Pre-Printed" and "Thin".UI is not correct in the combination of "Pre-Printed" and "Thin".	
2	Perfect Binder:	
	There is no "Thick3(221-300)" in the weight of the cover pages.Perfect Binder:	
	Paper weight category "Thick3(221-300)" is not included in the selection for cover	
	pages.	
3	PaperCatalog:	
	When Tray is overwritten, the application error is displayed.PaperCatalog:	
	When Tray is overwritten, the overwritten command is not reflected and an	
	application error is displayed.	
4	Unselectable Cover Paper Size can be chosen to Tray1.Inapplicable paper size	
	(SRA3) is displayed as a selectable size when selecting Tray1 Inapplicable tray	
	(Tray 1) is displayed as a selectable tray when selecting SRA3.	
5	<u> </u>	
6	Booklet job created without Cover by BM3 cannot be changed to Booklet job with	
	Cover by BM4.Booklet job without Cover created on the BM3 cannot be changed to	a
	Booklet job with Cover on the BM4.	
7	Paper Catalog:	Field problem
	The settings of the catalog can be changed from Paper Catalog although it is already	,
	set to a Tray. Paper Catalog:	
	Paper Catalog settings can be falsely changed even after designating the Tray	

PAGE: 3/4

Model: AG-P1/C1 Date: 29-Dec-09 No.: RG178089


Installation instructions

- 1. Execute **1-14N2CZ.exe** and follow the instructions in the Fiery Patch Downloader
- 2. Notes about the Fiery Patch Downloader
 - a. Login must be **admin**. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password
 - c. Hostname can be either the IP address or the Fiery server name.
- 3. After the patch is downloaded, and when prompted by Fiery Patch Downloader, choose **Reboot**.
- 4. When the Fiery has come to Idle, verify the patch ID on the **System Update Log**.
- 5. It should contain the patch number **1-14N2CZ**.

Note 1: When executing **1-14N2CZ.exe**, if you choose **Restart later** when prompted by the Fiery Patch Downloader, please make sure you manually reboot the server for changes to take effect.

Note 2: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server.

- To run this patch downloader on a Vista 32bit or 64bit client, follow the steps below:
 - Right-click on the "1-14N2CZ.exe" and select 'Properties'




 Select 'Run this program in compatibility mode for: Windows XP' and click 'OK'



PAGE: 4/4

Model: **AG-P1/C1** Date: 29-Dec-09 No.: RG178089



o Double-click the program and follow the instruction to install the patch.

RICOH

Technical Bulletin


PAGE: 1/6

Model: AG-P1 / C1 Dat				e: 15-Jan-	·10	No.: RG178090	
Subject: Countermeasure for Blurred Image				Prepare	d by: H.K	awamura	
From: PPBG QA							
Classification:	□ Troubleshooting	□ Part info	orma	tion	Action	n required	
	☐ Mechanical ☐ Electrica		ical		☐ Service manual revision		
☐ Paper path		☐ Transm	it/rec	eive	ve Retrofit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	G1782623	HOLDER:DUCT:ENTRANCE	0→4	×/O	218	-	
G1782552	-	SEAL:FRAME:CHARGE:RIGHT INNER REAR	4→0	-	164	18	

Change/Reason: From the result of our verification, we found out that by increasing the speed of air flow inside the charge corona unit, blurred Image can be reduced. Removing the "Seal: Frame Charge Right Inner Rear" at the entrance of the duct, which controls the air flow, and attach a new part on the duct, in order to increase the air flow to reduce the blurred image. Attention: If you removed the "seal" and did not attach the new part (Holder), air flow changes and

Attention: If you removed the "seal" and did not attach the new part (Holder), air flow changes and will cause some failure in the machine.






PAGE: 2/6

Model: AG-P1 / C1 Date: 15-Jan-10 No.: RG178090

SYMPTOM

Blurred Image caused by ozone will appear (see below).



CAUSE

Most likely, ozone inside the charge corona unit is not perfectly removed.

SOLUTION

By changing the opening area of the duct entrance, more ozone is removed from the charge corona unit, which will reduce the occurrence of blurred images.

The procedure for modifying the duct is described on the next page.

PAGE: 3/6

Model: AG-P1 / C1 Date: 15-Jan-10 No.: RG178090

PROCEDURE


In this procedure, cyan is used for an example; however, we recommend you to modify all four colours.

This modification is done above the Image Transfer Belt; therefore, please protect the belt using sheets of paper or remove the Image Transfer Belt before you start modifying the duct.

1. Remove the Charge Corona Unit, the Drum Cleaning Unit, the Drum Unit, and the Development Unit. Protect the Image Transfer Belt using sheets of paper before you start modifying the duct, as shown below.



2. Pull out the connector [A], and disconnect it.





Model: AG-P1 / C1 Date: 15-Jan-10 No.: RG178090






PAGE: 4/6

3. Unscrew the screw indicated below, and remove the duct by sliding the duct towards the back of the mainframe.



4. Disconnect the connector from the location indicated below








PAGE: 5/6

Model: AG-P1 / C1 Date: 15-Jan-10 No.: RG178090

5. After removing the duct, peel off the seal [B]




6. Clean with alcohol and attach Holder:Duct:Entrance G1782623 to the duct, where it is indicated as [C] in the picture below.





PAGE: 6/6

Model: AG-P1 / C1 Date: 15-Jan-10 No.: RG178090



7. To put back the duct, do the same procedure in reverse.

RICOH

Technical Bulletin

PAGE: 1/1

Model: AG-P1 / 0	C1, AGL-P1/C1		Dat	te: 21-Jan-	10	No.: RG178091
Subject: Notice c	of exclusive parts for AGL-P1/0	C1		Prepared	d by: N.iid	da
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

We would like to inform the exclusive parts for AGL-P1/C1. Except for the parts mentioned below, all the parts are common with AG-P1/C1; therefore, please add the following part numbers to the parts catalog for Model AG-P1/C1 (G178/D016).

New part number	Description	Page	Index	Note
M0781658	PLATE:NAME PLATE:C720	21	25	
D0971658	PLATE:NAME PLATE:C720S	21	25	
D0975301	PCB:BCU:SUB-ASS'Y	189	8	
M0785300	PCB:BCU:SUB-ASS'Y	189	8	
M0786022	PCB:CONT:EX1:AEGIS-P1LT:ASS'Y	197	13	
D0976014	PCB:CONT:EX1:AEGIS-C1LT:ASS'Y	197	13	
M0780480	DVD-ROM:SYS_AG-LT:EXP:ASS'Y	415	7	

PAGE: 1/3

Reissued:10-Jan-12

Model: AG-P1 / C1, AGL-P1 / C1	Date: 18-Feb-10	No.: RG178092a
--------------------------------	-----------------	----------------


RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Partial d	iscoloration; void of color(s)		Prepared	d by: N.lida bg
From: PPBG QA/	Service Planning Dept.			
Classification:		☐ Part information	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

SYMPTOM

Partial discoloration; void of color(s). The photo below shows an example of an output not showing Cyan.



CAUSE

A dust shield glass that was inserted at an angle jams and peels off the guiding seal and blocks the laser beam, leaving the blocked area not written.






PAGE: 2/3

Reissued:10-Jan-12


Model: AG-P1 / C1, AGL-P1 / C1	Date: 18-Feb-10	No.: RG178092a
--------------------------------	-----------------	----------------

Details of the cause


1. The dust shield glass is inserted in the bracket at an angle.



2. The tip of the dust shield glass jams against the guiding seal.



3. When the dust shield glass is inserted forcefully at an angle as shown above, the guiding seal is peeled off and squeezed, and blocks the path of the laser beam. Void of certain color(s) occurs due to this blockage.



For reference, the guiding seal is attached to determine the positioning of the dust shield glass.



PAGE: 3/3

Reissued:10-Jan-12

SOLUTION

If the guiding seal is peeled off, do the following


Order the following part

For Yellow and Cyan

New part number	Description	Q'ty	Int	Page	Index	Note
G1782091	PROTECTION:SHIELD GLASS:LEFT:ASS'Y	2	-	85	13	

For Magenta and Black

New part	Description	Q'ty	Int	Page	Index	Note
number						
G1782092	PROTECTION:SHIELD GLASS:RIGHT:ASS'Y	2	-	85	14	



- 1. Remove the entire guiding seal that has been peeled off.
- 2. Remove the release paper from the new part.
- 3. Attach the part to the original location

Notes on inserting the dust shield glass

To prevent the guiding seal from peeling off,

- aim the center of the slot
- maintain level
- insert the dust shield glass gently

If interference is felt, do not forcefully insert the dust shield glass. Pull out the dust shield glass and redo the above until a smooth insertion is confirmed.

RICOH

Technical Bulletin

PAGE: 1/1

Model: AG-P1			Dat	e: 12-Mar	-10	No.: RG178093
Subject: Recove	ry from "Please wait"			Prepare	d by: Hire	oaki Matsui
From: PPBG Ser	vice Planning Dept.					
Classification:		☐ Part info	orma	tion	Action	n required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

SYMPTOM

The GW controller cannot activate and the machine stalls in "Please wait" status if the setting for "SP5193-001; External Controller Info. Settings" is "0; No external controller installed".

Because an external controller is not specified in this situation, the GW controller cannot detect a connection time-out, which disables entering the SP mode (to change the setting for a recovery) and remains in "Please wait" status.

CAUSE

The GW controller cannot detect a connection if the SP is set as shown above.

SOLUTION

To recover from "Please Wait" status, use the TCRU/ORU SD Card.

Procedure

- 1. Turn off the machine.
- 2. Insert the TCRU/ORU SD card into Slot 1 or Slot 2.
- 3. Turn on the machine, and wait approximately 4 minutes while "Please Wait" still appears on the operation panel.
- 4. Wait for the TCRU/ORU menu to appear, and then enter SP5193-001 and change the setting.
- 5. Turn off the machine and make sure that the Fiery controller is turned off. (Wait for approximately 3 minutes).
- 6. Turn on the machine.

Note

- 1. The symptom will not occur with the Aegis-C1 as it is installed with a copy application.
- 2. A Test Print Tool SD card (D0169503) could be used as a substitute for the TCRU/ORU SD card.



PAGE: 1/22

Reissued:13-Apr-10

Model: AG-P1 / C1	Date: 29-Mar-10	No.: RG178094a

RTB Reissue

The items in **bold italics** were corrected or added.


Subject: LDU fie	eld modification for Aegis		Prepared	d by: N.iida
From: PPBG Se	rvice Planning Dept.			
Classification:	☐ Troubleshooting	☐ Part information	tion	
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☐ Tier 2

SYMPTOM

Occurrences of SC Codes such as SC240, 241, 242, 243, and SC250-257 caused by LD (Laser Diode) errors.

CAUSE

SC Codes occur due to loss in power of the laser, which is caused by filming that occurs inside the LED when the laser hits residual chemical substances, which are formed when condensation builds up in the process of manufacturing the LDA (Laser Diode Arrays), causing a chemical reaction.



SOLUTION

On your next service visit, please replace all four LDUs for the affected units having the object serial numbers.

If a Laser Unit (G1782030) has been previously replaced to resolve SC Code occurrences, please make sure to replace the two LDUs installed in the other Laser Unit.

e.g. If the "Left side Laser Unit" has been previously replaced to resolve SC242 (LD error: M), two LDUs of Black & Cyan in the Right-side Laser Unit should be replaced on your next service visit.

				Left side Laser Unit		Right side	j	
_				Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
	No.		Machine's serial number		YM_LDU(ST2) _SerialNO	CK_LDU(ST1) _SerialNO	CK_LDU(ST2) _SerialNO	
	1	Pro C900	S328100010xx	61080700xxx	61080700xxx	61080700xxx	61080700xxx	



PAGE: 2/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Although the standard procedure follows a replacement of the entire Laser Unit, to enable replacements of just the LDUs for this field rework, a special adjustment has been given to the LDUs, which are assigned with the following P/N:

G1789908: MODIFICATION :LDU:MK


2 pcs of the above parts are required.

G1789909: MODIFICATION:LDU:YC


2 pcs of the above parts are required.

Please be notified that a total of four LDUs will be required for each unit; two MK LDUs and two YC LDUs. (Part names are shown as "MK" and "YC", but this does NOT mean 1 "MK" LDU will cover both magenta and black; you need one for magenta and one for black.)

LDUs to be installed in the Laser Unit are as shown in the diagram below.



"ST1" and "ST2" indicate the installation position in the Laser Unit.





PAGE: 3/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Serial Numbers of the Affected Units

Aegis having the LDU Issue

Total Number of Affected Units in Asia: 5

		Left side Laser Unit		Right side Laser Unit			
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
No.	Machines' name	Machine's serial number	YM_LDU(ST1) _SerialNO	YM_LDU(ST2) _SerialNO	CK_LDU(ST1) _SerialNO	CK_LDU(ST2) _SerialNO	
1	Pro C900	S3281100005	61080700368	61080700361	61080700367	61080700360	
2	Pro C900	S3281100006	61080700351	61080700350	61080700349	61080700348	
3	Pro C900	S3281100007	61080700190	61080700191	61080700295	61080700280	
4	Pro C900	S3281100008	61080700265	61080700264	61080700272	61080700270	
5	Pro C900	S3281100009	61080700269	61080700268	61080700256	61080700255	

Aegis having the LDU Issue

Total Number of Affected Units in EU: 97

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and do NOT require replacement.

		Left side	Laser Unit	Right	side		
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
	Machines'	RPL Machine's	YM LDU(ST1)	YM LDU(ST2)	CK LDU(ST1)	CK LDU(ST2)	
No.	name	serial number	SerialNO	SerialNO	SerialNO	SerialNO	
1	Pro C900S		61080600127	61080600118	61080600091	61080600122	
2		M8780900006	61080600129	61080600126	61080600099	61080600116	
3		M8780900007	61080600084	61080600083	61080600269	61080700011	
4	Pro C900S	M8780900008	61080700018	61080700027	61080700009	61080600485	
5	Pro C900	S3280800042	61080600160	61080600159	61080600135	61080600161	
6	Pro C900	S3280800043	61080600246	61080600285	61080600239	61080600206	
7	Pro C900	S3280800044	61080600336	61080600335	61080600180	61080600337	
8	Pro C900	S3280800045	61080600235	61080600249	61080600245	61080600306	
9	Pro C900	S3280800046	61080600256	61080600217	61080600210	61080600216	
10	Pro C900	S3280800047	61080600314	61080600313	61080600315	61080600324	
11	Pro C900	S3280800048	61080600339	61080600316	61080600321	61080600185	
12	Pro C900	S3280800049	61080600154	61080600184	61080600156	61080600155	
13	Pro C900	S3280800050	61080600252	61080600213	61080600251	61080600214	
14	Pro C900	S3280900001	61080600279	61080600055	61080600276	61080600230	
15	Pro C900	S3280900002	61080500453	61080500456	61080500461	61080500443	
16	Pro C900	S3280900003	61080500444	61080500459	61080500460	61080500447	
17	Pro C900	S3280900004	61080500455	61080500450	61080500438	61080500458	
	Pro C900	S3280900005	61080500469	61080500467	61080500422	61080500451	
19	Pro C900	S3280900006	61080500465	61080500466	61080500446	61080500454	
20	Pro C900	S3280900007	61080500484	61080500483	61080500432	61080500457	
21	Pro C900	S3280900008	61080500429	61080500423	61080500433	61 08 05 00 425	
22	Pro C900	S3280900009	61080500424	61080500442	61080500464	61080500463	
23	Pro C900	S3280900010	61080500476	61080500462	61080500478	61080500468	
24	Pro C900	S3280900011	61080500394	61080500390	61080500396	61080600003	
25	Pro C900	S3280900012	61080500405	61080500372	61080600007	61080600005	
26	Pro C900	S3280900013	61080600009	61080600004	61080600221	61080600222	
27	Pro C900	S3280900014	61080600002	61080600006	61080500384	61080600218	
28	Pro C900	S3280900015	61080500385	61080500373	61080500386	61080600219	
29	Pro C900	S3281000105	61080500365	61080600220	61080500383	61080500371	
30	Pro C900	S3281000106	61080500475	61080500485	61080500477	61080500470	
31	Pro C900	S3281000107	61080500479	61080500445	61080500448	61080500441	
32	Pro C900	S3281000108	61080500452	61080500439	61080600106	61080600085	
33	Pro C900	S3281000109	61080500440	61080500449	61080600107	61080600128	
34	Pro C900	S3281000110	61080600236	61080600302	61080600296	61080600291	
35	Pro C900	S3281000111	61080600272	61080600274	61080600205	61080600275	
36	Pro C900	S3281000112	61080600120	61080600087	61080600082	61080600125	
37	Pro C900	S3281000113	61080600086	61080600124	61080600094	61080600092	
38	Pro C900	S3281000114	61080600119	61080600123	61080600090	61080600108	
39	Pro C900	S3281000115	61080700013	61080600333	61080700010	61080600036	
40	Pro C900	S3281000116	61080600034	61080600466	61080600041	61080600484	



PAGE: 4/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Aegis having the LDU Issue

Total Number of Affected Units in EU: 97

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and

do NOT require replacement.

	do NC	T require replac					•
			Left side	Laser Unit	Right side	Laser Unit	
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
	Manufations.	DDL Maskins's	YM LDU(ST1)	YM LDU(ST2)	OK L DU(CT1)	CK LDU(ST2)	
No.	Machines'	RPL Machine's			CK_LDU(ST1)		
	name	serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO	
41	Pro C900	S3281000117	61080600288	61080600289	61080600035	61080600049	
42	Pro C900	S3281000118	61080600044	61080600298	61080600297	61080600027	
43	Pro C900	S3281000119	61080600038	61080600047	61080600022	61080600048	
44		S3281000120	61080600040	61080600293	61080600227	61080600226	
45		S3281000121	61080600303	61080600292	61080600284	61080600305	
46	Pro C900	S3281000122	61080700040	61080700042	61080700045	61080700041	
47	Pro C900	S3281000123	61080700058	61080700077	61080700067	61080700070	
48	Pro C900	S3281000124	61080700065	61080700064	61080700072	61080700069	
	Pro C900	S3281000125	61080700292	61080700255	61080700261	61080700291	
50	Pro C900	S3281000126	61080700297	61080700279	61080700248	61080700272	
51	Pro C900	S3281000127	61080700127	61080700129	61080700233	61080700078	
52	Pro C900	S3281000128	61080700278	61080700293	61080700277	61080700270	
	Pro C900	S3281000129	61080600495	61080600477	61080700025	61080700264	
	Pro C900	S3281000130	61080700262	61080700263	61080700024	61080700265	
-	Pro C900	S3281000131	61080700084	61080700079	61080700027	61080700266	
	Pro C900	S3281000131	61080700081	61080700079	61080700027	61080700285	
	Pro C900	S3281000133	61080700083	61080700228	61080700219	61080700224	
	Pro C900		61080700083				
		S3281000134		61080700152	61080700151	61080700132	
	Pro C900	S3281000135	61080700230	61080700125	61080700126	61080700128	
60		S3281000136	61080700130	61080700131	61080700232	61080700229	
61	Pro C900	S3281000137	61080700112	61080700113	61080700030	61080700010	
62	Pro C900	S3281000138	61080700034	61080700013	61080700009	61080700008	
63		S3281000139	61080700033	61080700032	61080700011	61080700031	
64	Pro C900	S3281000140	61080700012	61080700280	61080600438	61080600377	
65	Pro C900	S3281000141	61080700006	61080700294	61080700044	61080700062	
66		S3281000142	61080700043	61080700061	61080700060	61080700038	
67	Pro C900	S3281000143	61080700059	61080700039	61080600021	61080600103	
68	Pro C900	S3292500021	61080700384	61080700390	61080700377	61080700376	
		S3292500005	61080700383	61080700375	61080700382	61080700381	
70		S3292500012	61080700383	61080700373			
					61080700373	61080700372	
71	Pro C900	S3292500009	61080700379	61080700363	61080700364	61080700365	
72	Pro C900S		61080700370	61080700366	61080700369	61080700362	
73	Pro C900	S3292500016	61080700354	61080700355	61080700358	61080700359	
74	Pro C900	S3292500010	61080700339	61080700340	61080700347	61080700341	
75	Pro C900	S3292500011	61080700274	61080700273	61080700338	61080700337	
76	Pro C900	S3292500015	61080700284	61080600356	61080700259	61080700257	
77	Pro C900	S3292500014	61080700267	61080700266	61080700155	61080700153	
78	Pro C900	S3292500007	61080700122	61080700123	61080700154	61080700086	
79	Pro C900	S3292500033	61080700165	61080700089	61080700172	61080700137	
	Pro C900	S3292500018	61080700246	61080700156	61080700170	61080700158	
		M8792600003	61080700087	61080700162	61080700088	61080700169	
82		S3292600001	61080700160	61080700161	61080700167	61080700166	
		M8792600001		61080700101	61080700230	61080700138	
		S3292600007			61080700139		
		M8792600007				61080700103	
				61080700143	61080700157		
		M8792800019		61080700018	61080700105	61080700104	
		M8792800012		61080700184	61080700317	61080700183	
		M8792600006	61080700320	61080700180	61080700321	61080700307	
	Pro C900	S3292500034	61080700305	61080700322	61080700316	61080700333	
90	Pro C900	S3292500031	61080700314	61080700315	61080700331	61080700313	
91		M8792600007	61080700207	61080700343	61080700243	61080700329	
92	Pro C900	S3292500017	61080700159	61080700244	61080700312	61080700242	
	Pro C900	S3292500013	61080700236	61080700241	61080700171	61080700179	
		M8792600002	61080700226	61080700237	61080700229	61080700168	
	Pro C900	S3292900003		61081099999	61081000030		*1
	Pro C900	S3292500019	61081000033	61081000037	61081000035	61081000034	•
97		S3292900019	61081000032	61081000037	61081000023	61081000024	
9/	1-10 0900	00Z3Z3UUUU8	01001000029	01001000022	01001000033	01001000023	ш



PAGE: 5/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Aegis having the LDU Issue

Total Number of Affected Units in NA: 185

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and do NOT require replacement.

	do NO	T require replac	cement.			
			Left	side	Right	side
_	_		Magenta LDU	Yellow LDU	Black LDU	Cyan LDU
	Manhiman'	DEL Machine's	VM LDU(CT1)	VM LDU(CT2)	CK LDU(CT1)	CK LDU(ST2)
No.	Machines'	REI Machine's	YM_LDU(ST1)	YM_LDU(ST2)	CK_LDU(ST1)	
	name	serial number	_SerialNO	_SerialNO	_SeriaINO	_SerialNO
1	Pro C900S	M8780900001	61080600398	61080600392	61080600399	61080600497
2	Pro C900S	M8780900002	61080600460	61080600456	61080600452	61080600459
3	Pro C900S	M8780900003	61080700022	61080700024	61080600493	61080600449
4		M8780900004	61080600453	61080600479	61080600418	61080600417
5	Pro C900	S3280700002	61080400243	61080400240	61080400227	61080400226
6	Pro C900	S3280700003	61080400224	61080400223	61080400237	61080400233
7	Pro C900	S3280700004	61080400241	61080400244	61080400242	61080400230
8	Pro C900	S3280700005	61080400232	61080400234	61080400231	61080400245
9	Pro C900	S3280700006	61080400236	61080500275	61080500273	61080500274
	Pro C900	S3280700007	61080500210	61080500217	61080500218	61080500211
	Pro C900	S3280700008	61080500210	61080500272	61080500214	61080500212
12	Pro C900	S3280700009	61080500211	61080500272	61080500214	61080500215
13	Pro C900	S3280700003	61080500215	61080500229	61080500227	61080500238
	Pro C900	S3280700010	61080500225	61080500223	61080500234	61080500236
	Pro C900	S3280700011	61080500235	61080500304	61080500234	61080500329
		S3280700012 S3280700013		61080500304	61080500303	
			61080500302 61080500307			61080500301
	Pro C900	S3280700014		61080500308	61080500323	61080500312
	Pro C900	S3280700015	61080500311	61080500338	61080500342	61080500341
	Pro C900	S3280700016	61080500306	61080500331	61080500325	61080500330
20		S3280700017	61080500328	61080500305	61080500327	61080500351
21	Pro C900	S3280700018	61080500359	61080500360	61080500357	61080500355
22	Pro C900	S3280700019	61080500354	61080500349	61080500356	61080500348
23	Pro C900	S3280700020	61080500353	61080500352	61080500350	61080500319
	Pro C900	S3280700021	61080500314	61080500313	61080500316	61080500318
		S3280700022	61080500324	61080500320	61080500309	61080500315
26	Pro C900	S3280700023	61080500317	61080500310	61080500322	61080500187
27	Pro C900	S3280700046	61080500195	61080500201	61080500199	61080500194
28	Pro C900	S3280700047	61080500088	61080500196	61080500189	61080500190
29	Pro C900	S3280700048	61080500193	61080500198	61080500188	61080500197
30	Pro C900	S3280700049	61080500100	61080500120	61080500116	61080500185
31	Pro C900	S3280700050	61080500119	61080500101	61080500099	61080500200
32	Pro C900	S3280700051	61080500097	61 08 05 00 1 18	61080500117	61080500202
33	Pro C900	S3280700052	61080500209	61080500230	61080500208	61080500253
34	Pro C900	S3280800001	61080600203	61080600080	61080600224	61080600069
35	Pro C900	S3280800002	61080600260	61080600281	61080600261	61080600262
36	Pro C900	S3280800003	61080600208	61080600068	61080600225	61080600076
37	Pro C900	S3280800004	61080600207	61080600234	61080600209	61080600066
	Pro C900	S3280800005	61080600026	61080600259	61080600015	61080600016
	Pro C900	S3280800006	61080600032	61080600017	61080600031	61080600011
40	Pro C900	S3281000001	61080600454	61080600465	61080600455	61080600451
41	Pro C900	S3281000002	61080600464	61080600450	61080600494	61080600491
	Pro C900		61080600480	61080600481	61080600448	61080600490
43	Pro C900	S3281000003	61080600395	61080600420	61080600448	61080600404
44	Pro C900	S3281000004	61080600413	61080600420	61080600421	61080600441
	Pro C900	S3281000003	61080600413	61080600410	61080600443	61080600357
	Pro C900	S32810000007	61080700006	61080700004	61080600411	61080700003
47	Pro C900	S3281000007		61080600365	61080600366	
			61080600353			61080600364
	Pro C900	S3281000009	61080600498 61080600349	61080700008	61080700033	61080700032
49 50	Pro C900	S3281000010		61080600350	61080700005	61080700002
	Pro C900	S3281000011	61080600384	61080600406	61080600385	61080600386
51	Pro C900	S3281000012	61080600402	61080600389	61080600409	61080600414
	Pro C900	S3281000013		61080600348	61080600351	61080600352
	Pro C900	S3281000014	61080600430	61080600446	61080600437	61080600444
	Pro C900	S3281000015	61080600432	61080600367	61080600447	61080600445
	Pro C900	S3281000016	61080600361	61080600359	61080600439	61080600376
	Pro C900	S3281000017	61080600378	61080600431	61080600379	61080600435
	Pro C900	S3281000018	61080600436	61080600363	61080600463	61080600461
58	Pro C900	S3281000019	61080600434	61080600380	61080700046	61080700073
	Pro C900	S3281000020	61080700066	61080700075	61080700298	61080700053
60	Pro C900	S3281000021	61080700068	61080700074	61080700052	61080700047



PAGE: 6/22 Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Aegis having the LDU Issue

Total Number of Affected Units in NA: 185

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and do NOT require replacement

	do NO	T require repla					1
			Left	side		side	
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
	Machines'	REI Machine's	YM_LDU(ST1)	VM LDH(ST2)	CK_LDU(ST1)	CK LDU(ST2)	
No.		serial number					
	name	serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO	
61	Pro C900	S3281000022	61080700115	61080700109	61080700101	61080700116	
62	Pro C900	S3281000023	61080700100	61080700102	61080700017	61080700016	
63		S3281000024	61080700019	61080700028	61080700015	61080700035	
64		S3281000025	61080700022	61080700271	61080700021	61080700023	
		S3281000026	61080700150		61080700147	61080700145	
66		S3281000027	61080700110	61080700148		61080700111	
67	Pro C900	S3281000028	61080600046	61080600412	61080600043	61080600405	
68		S3281000029	61080600487	61080600412	61080600500	61080600476	
69		S3281000030	61080700104			61080700099	
70		S3281000031	61080700104	61080700100	61080700107	61080700101	
71	Pro C900	S3281000031	61080700108	61080700102	61080700071	61080700049	
72	Pro C900						
		S3281000033	61080700026	61080700020	61080700109	61080700103	
73		S3281000034	61080700092		61080700094	61080700095	
74		S3281000035	61080700086		61080700088	61080700089	
75	Pro C900	S3281000036	61080700096	61080700097	61080700090	61080700091	
76	Pro C900	S3281000037	61080700080	61080700081	61080700082	61080700083	
77	Pro C900	S3281000038	61080700074			61080700077	
78		S3281000039	61080700084	61080700085		61080700079	
79		S3281000040	61080700140	61080700141	61080700134	61080700135	
80	Pro C900	S3281000041	61080700142	61080700136	61080700143	61080700137	
81		S3281000042	61080700144	61080700145		61080700129	
82	Pro C900	S3281000043	61080700123	61080700124	61080700138	61080700139	
83	Pro C900	S3281000044	61080700130	61080700122	61080700267	61080700268	
84		S3281000045	61080700125	61080700131	61080700126	61080700132	
85	Pro C900	S3281000046	61080700127	61080700133	61080700110	61080700116	
86		S3281000047	61080700111	61080700117	61080700118	61080700112	
87	Pro C900	S3281000048	61080700119	61080700113	61080700114	61080700120	
88		S3281000049	61080700115	61080700121	61080700062	61080700068	
89	Pro C900	S3281000050	61080700063	61080700069	61080700064	61080700070	
90		S3281000051	61080700066	61080700072	61080700067	61080700073	
91	Pro C900	S3281000052	61080700049	61080700057	61080700052	61080700058	
92	Pro C900	S3281000053	61080700048	61080700056	61080700054	61080700060	
93	Pro C900	S3281000054	61080700055	61080700061	61080700007	61080700042	
94		S3281000055	61080700041	61080700043	61080600023	61080700044	
95	Pro C900	S3281000056	61080700045	61080700038	61080700046	61080700039	
96	Pro C900	S3281000057	61080700053	61080700059	61080700212	61080700213	
97	Pro C900	S3281000058	61080700206	61080700207	61080700214	61080700208	
98	Pro C900	S3281000059	61080700215	61080700209	61080700216	61080700217	
99	Pro C900	S3281000060	61080700210	61080700211	61080700047	61080700040	
	Pro C900	S3281000061	61080700065		61080700200	61080700194	
-	Pro C900	S3281000062				61080700196	
	Pro C900	S3281000063	61080700203		61080700204		
	Pro C900	S3281000064	61080700198		61080700188	61080700189	
_	Pro C900	S3281000065	61080700184		61080700192	61080700193	
	Pro C900	S3281000066	61080700186		61080700176	61080700177	
	Pro C900	S3281000067	61080700170		61080700178		
107	Pro C900	S3281000068	61080700172	61080700173	61080700180	61080700181	
108		S3281000069	61080700174		61080700158	61080700159	
109		S3281000070	61080700174	61080700167	61080700160	61080700161	
	Pro C900	S3281000070	61080700168		61080700162	61080700163	
111		S3281000071	61080700152	61080700146	61080700164	61080700165	
	Pro C900	S3281000072	61080700153	61080700148	61080700147	61080700155	
113		S3281000074			61080700149	61080700150	
-							
114		S3281000075				61080600383	
	Pro C900	S3281000076	61080600387	61080600388	61080600433	61080600496	
	Pro C900	S3281000077	61080700352	61080700353	61080600397	61080600440	
117		S3281000078					
	Pro C900	S3281000079	61080600375		61080600381	61080600382	
	Pro C900	S3281000080	61080700234		61080700226	61080700227	
120	Pro C900	S3281000081	61080700221	61080700222	61080700236	61080700237	



PAGE: 7/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Aegis having the LDU Issue

Total Number of Affected Units in NA: 185

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and do NOT require replacement.

	do NOT require replacement. Left side Right side									
			Lett Magenta LDU		Right Black LDU	t side Cyan LDU				
		B-144 44 4								
No.	Machines'	REI Machine's			CK_LDU(ST1)					
	name	serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO				
121	Pro C900	S3281000082	61080700356		61080700336					
122 123	Pro C900 Pro C900	S3281000083	61080700223	61080700225	61080700389					
124	Pro C900	S3281000084 S3281000085	61081000005 61080600368	61081000004 61080600371	61080700218 61080700387	61080700220 61081000003				
	Pro C900	S3281000086								
126	Pro C900	S3281000087	61080600117	61080600344	61080600329	61080600295				
127	Pro C900	S3281000088			61080600104					
	Pro C900 Pro C900	S3281000089 S3281000090	61080600334 61080700124	61080600342 61080700120						
-	Pro C900	S3281000091	61080700140		61080700141					
131	Pro C900	S3281000092	61080700048	61080700050	61080700285	61080700286				
132	Pro C900	S3281000093	61080700287	61080700289		61080700002				
	Pro C900 Pro C900	S3281000094 S3281000095								
	Pro C900	S3281000096								
	Pro C900	S3281000097			61080700300					
137	Pro C900	S3281000098	61080700288	61080700054		61080700296				
138 139		S3281000099 S3281000100	61080700276 61080700257	61080700274 61080700256						
	Pro C900	S3281000100	61080700252	61080700236						
141	Pro C900	S3281000102		61080700258						
142	Pro C900	S3281000103	61080700275	61080700260						
143	Pro C900	S3281000104	61080700269	61080700290	61080700108					
	Pro C900 Pro C900	S3281000178 S3281000179	61080700098 61080600401	61080700114 61080600396						
	Pro C900	S3286000031	61081000019							
	Pro C900	S3294900016			61081000020					
		S3294900012	61081000016	61081000009						
-	Pro C900 Pro C900	S3294900071 S3286000034	61081000007 61080700209	61081000014						
151	Pro C900	S3286000034	61080700209	61081000006 61080700346						
152	Pro C900	S3294900018	61080700309	61080700205						
153	Pro C900	S3294900015	61080700306	61080700293						
	Pro C900	S3294900064		61080700235						
	Pro C900 Pro C900	S3294900014 S3294900061	61080700328 61080700154	61081000011 61081000031	61080700334 61080700319					
157	Pro C900	S3286000036								
158	Pro C900	S3286000049	61080700095	61080700330	61080700327	61080700292				
	Pro C900	S3294900068			61080700093					
160 161	Pro C900 Pro C900	S3294900065 S3294900017			61080700091					
162	Pro C900	S3286000039	61080700187	61080700188						
163	Pro C900	S3286000009	61080700176		61080700182					
	Pro C900	S3294900073	61080700174		61080700300					
	Pro C900 Pro C900	S3294900056 S3286000050			61080700252 61080700249					
	Pro C900	S3294900069	61080700254	61080700303						
168	Pro C900	S3294900070	61080700194	61080700200	61080700199	61080700193				
169	Pro C900	S3294900076	61080700197	61080700198	61080700189	61080700191				
	Pro C900	S3286000030			61080700225					
	Pro C900 Pro C900	S3286000035 S3294900072			61080700204 61080700234		<u> </u>			
	Pro C900	S3286000025			61080700234					
174	Pro C900	S3286000029	61080700222	61080700220	61080700278	61080700279				
	Pro C900	S3286000001	61080700144		61080700133					
176 177	Pro C900 Pro C900	S3286000033 S3286000032			61080700276 61080700218	61080700277 61080700219				
	Pro C900	S3286000010			61080700218					
179	Pro C900	S3294900074	61080700210	61080700211	61080700216	61080700217				
180	Pro C900	S3286000015	61080700311	61080700318	61080700286	61080700287				
		S3286000024			61080700281	61080700248				
	Pro C900 Pro C900	S3286000038 S3286000042		61080700282	61080700291 61081000190	61080700290 61081000185	*1			
184	Pro C900	S3286000021	61081000038	61081000044	61081000112		*1			
		M8795000001				61081101117				



Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

LDU Replacement Procedure


Notes on the replacement work

• Do NOT touch the PCB with bare hands. Grip the bracket made of die-cast aluminum when holding the LDU.





• Check the LDU serial number indicated under the barcode (see the photo below) and mark the corresponding serial number on the data sheet (see the diagram of the data sheet below) to avoid mixing up the installation position. The serial number is indicated as ST1 or ST2 on the data sheet depending on the position. In addition to this marking, indicate the color. Indication of the color on the data sheet will be very important in the latter procedure when inputting the information on the data sheet into the SP modes.




The barcode attached to the top-right of the LDU corresponds to the 11 digit LDU serial number indicated on the top-left of the data sheet.

PAGE: 8/22

e.g.) AGA on the barcode is read as 61.

Barcode : <u>AGA</u>091200001

Data sheet: 61091200001





PAGE: 9/22

Reissued:13-Apr-10


Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

Work Flow

NOTE

Approx work time is indicated in the brackets.

"N" indicates the total number of LDUs requiring the replacement.



NOTE

Step 1 required only for the Aegis-C1; removal of the "Top-right Cover".



Reissued:13-Apr-10

Model: AG-P1 / C1 No.: RG178094a Date: 29-Mar-10

Step 1 Disconnecting the LCT-MF


- 1-1. Remove the I/F connector cover [A]. (screw x 2)1-2. Remove the LCT-MF I/F connectors [B] from the mainframe.





PAGE: 10/22

1-3. Open the front cover of the LCT-MF and remove the screw [C].






PAGE: 11/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

- 1-4. Separate the LCT-MF from the mainframe.
- 1-5. Disconnect the ground cable [E] from the mainframe. (M4x8 screw x 1)
- 1-6. If connected, disconnect the LCT-MF heater relay harness [D] from the mainframe.






Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a


Step 2 Removing the Exterior Parts

2-1 Removing the Front Top Cover



- 2-1-1. Open the right and left front doors.
- 2-1-2. Open the toner hopper door [A].
- 2-1-3. Remove the front top cover [B]. (screw x 2)








PAGE: 12/22

2-2 Removing the Rear Top Cover

2-2-1. Remove the rear top cover [A]. (screw x 3)







Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a


- 2-3 Removing the Control Panel Arm
- 2-3-1. Remove the cap [A].
- 2-3-2. Remove the arm top cover [B]. (screw x 2)







PAGE: 13/22


- 2-3-3. Remove the screw [C].
- 2-3-4. Remove the arm left cover [D]. (screw x 2)
- 2-3-5. Remove the arm right cover [E]. (screw x 2)





2-3-6. Remove the arm [F]. (screw x 4, connector x 1)








Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a


2-4 Removing the Toner Hopper Unit

- 2-4-1. Open the toner hopper door.
- 2-4-2. Release the toner lock levers [A].
- 2-4-3. Remove the toner bottles.




2-4-4. Remove the top right cover [A]. (screw x 2) 2-4-5. Remove the top left cover [B]. (screw x 2)





PAGE: 14/22

- 2-4-6. Disconnect the harness [C].
- 2-4-7. Remove the four screws.
- 2-4-8. Grip the handles [D] and remove the toner hopper unit.






PAGE: 15/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

2-5 Removing the Metal Cover of the Laser Unit


2-5-1. Remove the metal cover of the laser unit [A]. (screw x 4)




Step 3 Replacing the LDU

3-1. Remove the laser unit top cover [A]. (screw x 9) Note

- Don't touch any optical parts inside the LD unit.
- Be careful not to pinch the chains located on both sides when reattaching the laser unit top cover.
- First, fasten screw "1", and then screw "2" in the reassembly procedure. The seven other screws can be fastened in any order.



- 3-2. Remove the LD Unit. (connector x4, roundhead screw x2)
 - * Do NOT remove the spacer(s). Spacers are applied to compensate for the deviation unique to each unit.
 - * Spacers may or may not be applied depending on the unit, and their positions and types are unique to each unit.






 Reissued:13-Apr-10

 Model: AG-P1 / C1
 Date: 29-Mar-10
 No.: RG178094a

* Spacer Types



parent

Black 50μ mTransparent 75μ mWhite 100μ m

25 μ m

PAGE: 16/22

Step 4 Reattaching the Outer Covers

Reattach the outer covers following the reverse order of removal.

Step 5 Connecting the LCT-MF

Connect the LCT-MF following the reverse order of disconnection.

Step 6 Inputting the SP Data

- 6-1. Disable the automatic MUSIC and Process Control adjustment by changing the SP2-193-001 value to "0" and SP3-501-001 to "1".
- 6-2. Disable 2-point detection by changing the SP2-186-001 value to "0".
- 6-3. Input the LD unit adjustment settings.

Refer to APPENDIX 1-4 to write in the <u>values indicated in PINK</u> (which correspond to the <u>SP values indicated in GREEN</u>) into the table below, and then input those values into the SP.

NOTE

- These values are needed for resetting the Laser Unit related SP values in case the SP values are initialized.
- Please keep the data sheet together with the "SP MODE FACTORY SET" sheet, which should be attached as an accessory to the mainframe, inside the machine.
- If the "SP MODE FACTORY SET" sheet has been lost, print out SP5990-002 and keep it together with the data sheet inside the machine.

^{3-3.} Install the new LD Unit, and close the top cover. (connector x4, roundhead screw x2)

^{*} Reconfirm the LD Unit serial number to avoid installation in the wrong slot.



PAGE: 17/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

EXAMPLE 1 Yellow LDU <<See APENDIX 1>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01		:		-

EXAMPLE 2 Cyan LDU <<See APPENDIX 2>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (<i>PINK</i>)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01				-

EXAMPLE 3 Black LDU <<See APPENDIX 3>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (<i>PINK</i>)	SP No. (GREEN)	Value (PINK)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03				
2-115-002	-00				! !



PAGE: 18/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

EXAMPLE 4 Magenta LDU <<See APPENDIX 4>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00) 		

- 6-4. Reset the "Main Magnification Table" setting by inputting "1" in SP2-180-007.
- 6-5. Power cycle the machine.
- 6-6. Execute SP2-180-003 to clear the "MUSIC Result" setting.
- 6-7. Execute 2-point detection for each color by executing SP2-184-001 (for Black), -002 (for Magenta), -003 (for Cyan) and -004 (for Yellow).
- 6-8. Enable 2-point detection by changing the SP2-186-001 value to "1" (Auto).
- 6-9. Execute the manual MUSIC adjustment; SP2-153-004 (for rough adjustment) and SP2-153-001 (for fine adjustment).
- 6-10. Enable the automatic MUSIC and Process Control adjustment; set the SP2-193-001 value to "1" (Music ON) and SP3-501-001 value to "0" (Process Control ON).

Step 7 Checking the Image Quality

Finish the replacement procedure by printing out the PS Test Page and checking its image quality.




PAGE: 19/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

<<APENDIX 1>>

SP Values are *indicated in GREEN*, and Values in PINK. These values correspond one-on-one in order, described in the same row.





SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01				




PAGE: 20/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

<<APENDIX 2>>

SP Values are *indicated in GREEN*, and Values in PINK. These values correspond one-on-one in order, described in the same row.





SP No. (GREEN)	Value (<i>PINK</i>)	SP No. (GREEN)	Value (<i>PINK</i>)	SP No. (GREEN)	Value (<i>PINK</i>)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01		1		1




PAGE: 21/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

<<APENDIX 3>>

SP Values are *indicated in GREEN*, and Values in PINK. These values correspond one-on-one in order, described in the same row.





EXAMPLE 3 B	lack LDU				
SP No. (GREEN)	Value (<i>PINK</i>)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (<i>PINK</i>)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03				
2-115-002	-00		i I		1




PAGE: 22/22

Reissued:13-Apr-10

Model: AG-P1 / C1 Date: 29-Mar-10 No.: RG178094a

<<APENDIX 4>>

SP Values are *indicated in GREEN*, and Values in PINK. These values correspond one-on-one in order, described in the same row.







EXAMPLE 4 IV	iagenta LDU				
SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value <i>(PINK)</i>	SP No. (GREEN)	Value (PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00				

Model: AG-P1/C1			Date: 09-Apr-10		10	No.: RG178095
Subject: Engine Log Capture Tool / Procedures			Prepare	d by: Hire	oaki Matsui	
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	□ Part infe	orma	tion	ion	
	☐ Mechanical	☐ Electric	☐ Electrical		Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Summary

Detailed information on the machine status was not available for engine-related issues. A debug cable for log capturing will be distributed to the field to enable collection of such data for log analysis.

Part information

The debug cable is exclusive to the Aegis-P1/C1.

Please add the following part number to your parts catalog.

New part number	Description	Page	Index	Note
G1785397	Debug cable	415	8	Add




G1785397 Debug cable

Required Equipment

- Serial Cross Cable (D-sub 9-pin)
- Serial RS232C to USB Converter

Choose the connector type suitable for the PC.





Serial Cross cable (D-sub 9pin)



Serial RS232C to USB Converter

Technical Bulletin

PAGE: 2/5

Model: AG-P1/C1 Date: 09-Apr-10 No.: RG178095

NOTE 1: A USB converter is not required if the PC is equipped with a serial port.

NOTE 2: Procuring 2 each of the cable and converter is preferable (to allow log capturing from both Master and Slave PCUs simultaneously for work time reduction and data accuracy.)

Basic Idea of Log Capturing

The Aegis engine runs on two CPUs (Master CPU / Slave CPU)

Although log capture only from the Master CPU is required in most cases, logs from the Slave CPU could also be required depending on the symptom.

If two debug cables are available, capture the logs from Master and Slave simultaneously. If only one debug cable is available, first capture the logs from the Master, and then from the Slave.


IMPORTANT: Entire logs from the beginning of the job until the symptom occurrence is required for log analysis.

Overall Workflow

- 1. Connect the Deb debug ug cable(s) to Master (and Slave).
- 2. Set up Tera Term and start the log capturing. (Tera Term is free software.)
- 3. Start the job.
- 4. Wait until the expected symptom occurs.
- 5. Stop the log capturing process.
- 6. Disconnect the cable(s).

Connecting the Debug cable

1. Connect the debug cable to the IOB2 board.




2. Connect the other end of the debug cable to the serial port or to the USB port on the PC using a USB-serial conversion cable.

PAGE: 3/5


Model: AG-P1/C1 Date: 09-Apr-10 No.: RG178095

Setting up Tera Term (Log Monitor)

- 1. Activate Tera Term.
- 2. Open "Terminal setup" by selecting [Setup] > [Terminal], and specify the settings as shown below.



3. Open "Serial port setup" by selecting [setup] > [Serial port], and specify the settings as shown below.



- 4. If an additional debug cable is available, connect it to the Slave and open another Tera Term Pro window (for the Slave).
- 5. Create two separate lists; one for the Master and one for the Slave.

 Press the "Enter" key to allow the cursor to appear in the command window.

 Type "ver" in the Debug monitor, and press the "Enter" key.

 The engine version will appear as shown below.

master	slave
Dbg> ver	Dbg> ver
EngVersion 0.302:07 Machine Aegis-C1	EngVersion 0.302:07 Machine Aegis-C1(Slave Side)



PAGE: 4/5

Model: AG-P1/C1 Date: 09-Apr-10 No.: RG178095

Sample: Tera Term Log Display

Indication for Master at Powerup	Indication for Slave at Power up
+[7m	-[7m
CPU reset	CPU reset
- [0m=== Debug Monitor for Aegis-P1 ===	+ [0m=== Debug Monitor for Aegis-P1 ===
EngVersion: 0.107C:00	EngVersion: 0.107C:00
-setMachineArea!>[2]	[startup]start cpu if task
SpInitEnd!	Dual Port RAM check O.K.!!!
reqInitSystemDomain	[startup]start timer task
SystemInitEnd!	[startup]NV-RAM intialize is started
sndInitEndForSystemDomain	[startup]NV-RAM initialize is success
Get_Engine_SP_END	[startup]start stm conrtol task
IFSP Rapi Init	[startup]start slave I/O task
getRealSender & RealRapiSenderBridge initialize.	[startup]start lct control task
hotspot rapiRX Engine Ready Assert	[startup]start fuser conrtol task
SystemDomainInitEnd!	[startup]start lct main task
startup]start cpu if task	[startup]start lct feed task
Dual Port RAM check O.K.!!!	[startup]start tr belt conrtol task
[startup]start timer task	[startup]start tr belt drive task
startup]NV-RAM intialize is started	[startup]start drum conrtol task
startup]NV-RAM initialize is finished	[startup]start slv brimmtr task
[startup]start sp task	[startup]start slv high vol task
startup start RCB I/F task	SIO Init End!
startup]start RCB sender task	
startup]start RCB receiver task	[fuser_ctrl]InitTask end
startup]start stm conrtol task	【タンデムトレイセット検知】
startup]start status conrtol task	[tr belt ctrl]InitTask end
startup]start status dev conrtol task	[tr belt drive]InitTask end
startup]start master I/O task	Idrum IllnitTask end
startup]start print conrtol task	[LCT IF config::01 00
startup]start process conrtol task	LCT I7 config::01 00 LI Start Timer 3032
startup]start paper conrtol task	LI_OOMM_NO_CONNECT
startup]start finisher conrtol task	LI_COMM_NO_CONNECT
startup]start fuser drive task	[drum_ctrl]0 Drum Slow Down End
startupIstart write conrtol task	I Timer End
startup]start write dev. conrtol task	steering position:0[step]
startup]start optical conrtol task	steering position:0[step]
startupIstart toner conrtol task	[drum_ctrl]0 Drum Slow Down End
startup]start color regist control task	[drum_ctrl]1 Drum Slow Down End
startup start color regist device task	[drum ctrl]2 Drum Slow Down End
startup]start procon task	[drum_ctrl]3 Drum Slow Down End
startup]start procon device task	steering position:0[step]
startup]start mst brimmtr task	steering position:0[step]
startupIstart mst high vol task	[drum_ctrl]0 Drum Slow Down End
exit_ctrl]victoria wake up!!	[drum_ctrl]1 Drum Slow Down End
tonerIRFID ASAP wake up!!	[drum_ctrl]2 Drum Slow Down End
MIO Init End!	[drum_ctrl]3 Drum Slow Down End
Print Ctri Initi Complete	steering position:0[step]
MD] MUSIC-GAVD Init.	steering position:0[step]
MD] LDA 間主走査倍率與差補正值.	[drum_ctrl]0 Drum Slow Down End
MD] mN4:0 mN2:1.mN1x4:0	[drum_ctrl]1 Drum Slow Down End
MD] mN1:0,mN2:0,mN1x4:0	[drum_ctrl]2 Drum Slow Down End
MD] mN1:-1,mN2:0,mN1x4:4	[drum_ctrl]3 Drum Slow Down End
MD] mN1:0,mN2:0,mN1x4:0	TP AD:241.TP TEMP:43
MD] GavdDPhaseSetAria1tol. mode;	THERMOPILE SNS CHK PASSED!
MD] MagLDAp:10,MagtblLDAp:10,Mag2detLDAp:0.	SNS CHK PASSED!
MD] MagLDAp:10,MagtblLDAp:10 Mag2detLDAp:0.	[drum_ctrl]0 Drum Slow Up End
[MD] MagLDAp:2,MagfblLDAp:2,Nag2detLDAp:0. [MD] MagLDAp:2,MagtblLDAp:2,Mag2detLDAp:0.	[drum_ctrl]1 Drum Slow Up End
mD) magLDAD:2,maglblLDAD:2/Mag20etLDAD:0.	[drum_ctrl]2 Drum Slow Up End


Please ignore the corrupted characters that will appear on the log monitor list. Characters are only corrupted because the logs contain two-byte-data.

PAGE: 5/5


Model: AG-P1/C1 Date: 09-Apr-10 No.: RG178095

Capturing the Logs


- Select [File] > select [Log], type in a file name, and click [Open]. Pop-up window will appear. Save the file name as "xxx.txt" or "xxx.log".
- 2. Start the job.



- 3. Wait until the expected symptom occurs.
- 4. If the expected symptom occurs, type "log" in the debug monitor and press the "Enter" key. This will enable capturing of further detailed information on the symptom. (This is not a mandatory procedure.)



5. Click [Close] in the "Tera Term Log" window.



Technical Bulletin

PAGE: 1/1


Model: AG-P1/C1			Dat	Date: 26-Apr-10		No.: RG178096
Subject: EMPTY BOTTLE:DEVELOPER:ASS'Y				Prepared by: N.iida		
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	G1783115	EMPTY	0→1	-	229	20	
		BOTTLE:DEVELOPER:ASS'Y					

Empty bottle for developer removal has been registered as a new service/spare part.

Note

- Remove the seal [A].
- \cdot The bottle can be connected to any of the outlets [B].



Technical Bulletin

PAGE: 1/17

Model: AG-P1/C1			Date: 20-May-10		-10	No.: RG178097
Subject: Relay board field modification for Aegis			Prepared by: N.iida			
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Mechanical ☐ Electrica		al		Service	required se manual revision fit information
	☐ Paper path ☐ Product Safety	☐ Transm☐ Other (iivrec)	Tier 2	

Although the previously issued RTB "RG178087" had announced to replace the relay board only when confirming a failure, a new relay board free of charge will be distributed to the field to prevent failure risks. Field replacement rework is required for the machines installed with the old relay board with p/n: G1785281.

SYMPTOM

Various SC occurs.

SC304, 305, 306, 307, 344, 345, 346, 347, 477, 479, 490, 520, 521, 523, 524, 530-01, 601, 675-01, 991,

CAUSE

The CARD inside the relay melts, due to exposure to heat. The contacts of the relay do not close correctly.

The relay works as an interlock switch for several power supply lines.

Several SC calls occur when the CARD is deformed.

Factors for melting of the CARD are:

- The heat generated by the cement resistors near the relay raises the temperature inside the relay.
- Load on the fusing motor increases.
 - Mechanical drive load on the fusing motor increases because of the following factors.
 - → PM parts in the fusing unit are used more than the PM replacement cycle.
 - ♦ By using paper that contains a lot of calcium carbonate, the oil application gets dirty, and the oil film on the fusing belt gets less uniform.


As a result, the electrical current of the fusing motor increases. This causes the cement resistors and relay to generate more heat than usual.

• The relay itself generates heat (depends on the resistance of the contacts of the relay)



PAGE: 2/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097



SOLUTION

Please replace the relay board for machines having the following serial numbers at your next service visit. If the machine is installed with the relay board p/n G1785281, replacement with the new relay board p/n G1789911 is required. Replacement is not required if the machine is already installed with relay board p/n G1785304. Please refer to the next page for distinguishing between the old/new relay boards. Replacement will take approximately 15 minutes.

P/N G1785281	Old type	Replacement required
P/N G1785304	New type	Replacement not required
P/N G1789911	New type	Different p/n specially assigned for this particular field rework

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

Distinguishing the Relay Boards

Please refer to the following for distinguishing the new and old relay boards.

> P/N [a]

Old: G1785281 New: G1785304 or G1789911

> Number of Relays [b]


Old: Relay x 4 New: Relay x 5

> Number of Cement Resistors [c]


Old: Resistor x 2 New: Resistor x 1

Board Shape [d]

The new relay board has a "cut" as shown in the photo below; circled [D].



Part number G1785281



PAGE: 3/17

Part number G1785304 or G1789911



Model: AG-P1/C1

Technical Bulletin

Date: 20-May-10 No.: RG178097

Serial Number of the Affected Units

Total Number of Affected Units in EU: 484

Note: 4 units unidentified with the RPL serial numbers (currently investigated) are colored light blue in the following tables and are temporarily described with an RCL serial number.

	Model Name	RPL Machine's Serial No.
1		S3281290009
2		S3290390012
3	Pro C900	S7002600001
4	Pro C900	S7093400001
	Pro C900	S3202500004
5		
6	Pro C900	S3202500005
7	Pro C900	S3202700002
8	Pro C900	S3280600034
9	Pro C900	S3280600035
10	Pro C900	S3280600036
11	Pro C900	S3280600037
12	Pro C900	S3280800042
13	Pro C900	S3280800043
14	Pro C900	S3280800044
15	Pro C900	S3280800045
16	Pro C900	S3280800046
17	Pro C900	S3280800047
18	Pro C900	S3280800048
19	Pro C900	S3280800049
20	Pro C900	S3280800050
21	Pro C900	S3280900003
22	Pro C900	S3280900003
23	Pro C900	S3280900004
24 25	Pro C900	S3280900006
25	Pro C900	S3280900007
26	Pro C900	S3280900008
27	Pro C900	S3280900009
28	Pro C900	S3280900010
29	Pro C900	S3280900011
30	Pro C900	S3280900012
31	Pro C900	S3280900013
32	Pro C900	S3280900014
33	Pro C900	S3280900015
34	Pro C900	S3281000105
35	Pro C900	S3281000106
36	Pro C900	S3281000107
37	Pro C900	S3281000108
38	Pro C900	S3281000109
39	Pro C900	S3281000110
40	Pro C900	S3281000111
41	Pro C900	S3281000111
		S3281000112
42 42	Pro C900	
43	Pro C900	S3281000114
44	Pro C900	S3281000115
45	Pro C900	S3281000116
46	Pro C900	S3281000117
47	Pro C900	S3281000118
48	Pro C900	S3281000119
49	Pro C900	S3281000120
50	Pro C900	S3281000121
	. '	-

	Model Name	RPL Machine's Serial No.
E 4	Dro COCO	
51	Pro C900	S3281000122
52	Pro C900	S3281000123
53	Pro C900	S3281000124
54	Pro C900	S3281000125
55	Pro C900	S3281000126
56	Pro C900	S3281000127
57	Pro C900	S3281000128
58	Pro C900	S3281000129
59	Pro C900	S3281000130
60	Pro C900	S3281000131
61	Pro C900	S3281000132
62	Pro C900	S3281000133
		S3281000134
63	Pro C900	
64	Pro C900	S3281000135
65	Pro C900	S3281000136
66	Pro C900	S3281000137
67	Pro C900	S3281000138
68	Pro C900	S3281000139
69	Pro C900	S3281000140
70	Pro C900	S3281000141
71	Pro C900	S3281000142
72	Pro C900	S3281000143
73	Pro C900	S3283600001
74	Pro C900	S3283600002
75	Pro C900	S3290100006
76	Pro C900	S3290100007
77	Pro C900	S3290100008
78	Pro C900	S3290100009
79	Pro C900	S3290100010
80	Pro C900	S3292500001
81	Pro C900	S3292500002
82	Pro C900	S3292500003
83	Pro C900	S3292500004
84	Pro C900	S3292500005
85	Pro C900	S3292500006
86	Pro C900	S3292500007
87	Pro C900	S3292500008
88	Pro C900	S3292500009
89	Pro C900	S3292500010
90	Pro C900	S3292500011
91	Pro C900	S3292500012
92	Pro C900	
		S3292500013
93	Pro C900	S3292500014
94	Pro C900	S3292500015
95	Pro C900	S3292500016
96	Pro C900	S3292500017
97	Pro C900	S3292500018
98	Pro C900	S3292500019
99	Pro C900	S3292500020
100	Pro C900	S3292500020
.	L	L

	Model Name	RPL Machine's
101	Dro COOO	Serial No.
	Pro C900	S3292500021
102	Pro C900	S3292500022
103	Pro C900	S3292500023
104	Pro C900	S3292500024
105	Pro C900	S3292500025
106	Pro C900	S3292500026
107	Pro C900	S3292500027
108	Pro C900	S3292500028
109	Pro C900	S3292500029
110	Pro C900	S3292500030
111	Pro C900	S3292500031
112	Pro C900	S3292500032
113	Pro C900	S3292500033
114		S3292500034
	Pro C900	
115	Pro C900	S3292500035
116	Pro C900	S3292500036
117	Pro C900	S3292600001
118	Pro C900	S3292600002
119	Pro C900	S3292600003
120	Pro C900	S3292600004
121	Pro C900	S3292600005
122	Pro C900	S3292600006
123	Pro C900	S3292600007
124	Pro C900	S3292600008
125	Pro C900	S3292600009
126		
	Pro C900	S3292700001
127	Pro C900	S3292700002
128	Pro C900	S3292700003
129	Pro C900	S3292700004
130	Pro C900	S3292700005
131	Pro C900	S3292700006
132	Pro C900	S3292700007
133	Pro C900	S3292700008
134	Pro C900	S3292700010
135	Pro C900	S3292700011
136	Pro C900	S3292700012
137	Pro C900	S3292700013
138	Pro C900	S3292700014
100	D== COOO	C000070001F
140	Pro Cann	S3292700015
	Pro C900	S3292800001
141	Pro C900	S3292800002
142	Pro C900	S3292800004
143	Pro C900	S3292800005
144	Pro C900	S3292800006
145	Pro C900	S3292800007
146	Pro C900	S3292800007
147	Pro C900	S3292800008
148	Pro C900	S3292800009
149	Pro C900	S3292800010
150	Pro C900	S3292800011
L		Location

PAGE: 4/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	RPL Machine's Serial No.
151	Pro C900	S3292800012
152	Pro C900	S3292800013
153	Pro C900	S3292800014
154	Pro C900	
		S3292800015
155	Pro C900	S3292800016
156	Pro C900	S3292900001
157	Pro C900	S3292900002
158	Pro C900	S3292900004
159	Pro C900	S3292900005
160	Pro C900	S3292900006
161	Pro C900	S3292900007
162	Pro C900	S3292900008
163	Pro C900	S3292900009
164	Pro C900	S3292900010
165	Pro C900	S3292900011
166	Pro C900	S3292900012
167	Pro C900	S3292900013
168	Pro C900	S3292900014
169	Pro C900	S3292900015
170	Pro C900	S3292900016
171	Pro C900	S3293000001
172	Pro C900	S3293000002
173	Pro C900	S3293000003
174	Pro C900	S3293000004
175	Pro C900	S3293000005
176	Pro C900	
		S3293000006
177	Pro C900	S3293000007
178	Pro C900	S3293000008
179	Pro C900	S3293000009
180	Pro C900	S3293000010
181	Pro C900	S3293000011
182	Pro C900	S3293000012
183	Pro C900	S3293000013
184	Pro C900	S3293000014
185	Pro C900	S3293000015
186	Pro C900	S3293000016
187	Pro C900	S3293100001
188	Pro C900	S3293100002
189	Pro C900	S3293100003
190	Pro C900	S3293100004
191	Pro C900	S3293100005
192	Pro C900	S3293100006
193	Pro C900	S3293100007
194	Pro C900	S3293100008
195	Pro C900	S3293100009
196	Pro C900	S3293100010
197	Pro C900	S3293100011
198	Pro C900	S3293100012
199	Pro C900	S3293200001
200	Pro C900	S3293200002

	Model Name	RPL Machine's Serial No.
201	Pro C900	S3293200003
202	Pro C900	S3293200004
203	Pro C900	S3293200005
204	Pro C900	
		S3293200006
205	Pro C900	S3293200007
206	Pro C900	S3293200008
207	Pro C900	S3293200009
208	Pro C900	S3293200010
209	Pro C900	S3293200011
210	Pro C900	S3293200012
211	Pro C900	S3293300001
212	Pro C900	S3293300002
213	Pro C900	S3293300003
214	Pro C900	S3293300004
215	Pro C900	S3293300005
216	Pro C900	S3293300006
217	Pro C900	S3293300007
218	Pro C900	S3293300008
		S3293300009
219	Pro C900	
220	Pro C900	S3293400001
221	Pro C900	S3293400002
222	Pro C900	S3293400003
223	Pro C900	S3293400004
224	Pro C900	S3293400005
225	Pro C900	S3293400006
226	Pro C900	S3293400007
227	Pro C900	S3293400008
228	Pro C900	
		S3293400009
229	Pro C900	S3293400010
230	Pro C900	S3293500001
231	Pro C900	S3293500002
232	Pro C900	S3293500003
233	Pro C900	S3293500004
234	Pro C900	S3293500005
235	Pro C900	S3293500007
236	Pro C900	S3293500007
237	Pro C900	S3293500009
238	Pro C900	S3293500010
239	Pro C900	S3293500011
240	Pro C900	S3293500012
241	Pro C900	S3293500013
242	Pro C900	S3293500014
243	Pro C900	S3293600001
244	Pro C900	S3293600002
245	Pro C900	S3293600003
246	Pro C900	S3293600004
247	Pro C900	S3293600005
248	Pro C900	S3293600006
249	Pro C900	S3293600007
250	Pro C900	S3293600008
200	. 10 0000	3320000000

	Model Name	RPL Machine's Serial No.
251	Pro C900	S3293600009
252	Pro C900	S7002500001
253	Pro C900	S7002500003
254	Pro C900	S7002600002
255	Pro C900	S7002700001
256	Pro C900	S7002700002
257	Pro C900	S7002700003
258	Pro C900	S7002700004
259	Pro C900	S7002700005
260	Pro C900	S7002700006
261	Pro C900	
		S7002700007
262	Pro C900	S7002800001
263	Pro C900	S7093400002
264	Pro C900	S7093400003
265	Pro C900	S7093400004
266	Pro C900	S7093400005
267	Pro C900	S7093500001
268	Pro C900	S7093500002
269	Pro C900	S7093600001
270	Pro C900	S7093600002
271	Pro C900S	M8793300015
272	Pro C900S	M8793500026
273	Pro C900S	M8702500001
274	Pro C900S	M8702500005
275	Pro C900S	M8702500006
276	Pro C900S	M8702500007
277	Pro C900S	M8702500008
278	Pro C900S	M8702500010
279	Pro C900S	M8702500011
280	Pro C900S	M8702600003
281		M8792600001
	Pro C900S	
282	Pro C900S	M8792600002
283	Pro C900S	M8792600003
284	Pro C900S	M8792600004
285	Pro C900S	M8792600005
286	Pro C900S	M8792600006
287	Pro C900S	M8792600007
288	Pro C900S	M8792600008
289	Pro C900S	M8792600009
290	Pro C900S	M8792600010
291	Pro C900S	M8792600011
292	Pro C900S	M8792600012
293	Pro C900S	M8792600013
294	Pro C900S	M8792600014
295	Pro C900S	M8792600015
296	Pro C900S	M8792600016
297	Pro C900S	M8792600017
298	Pro C900S	M8792600018
299	Pro C900S	M8792600019
300	Pro C900S	M8792700001
		•

PAGE: 5/17



Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	RPL Machine's Serial No.
301	Pro C900S	M8792700002
302	Pro C900S	M8792700003
303	Pro C900S	M8792700004
304	Pro C900S	M8792700005
305	Pro C900S	M8792700006
306	Pro C900S	M8792700007
307	Pro C900S	M8792700008
308		M8792700009
	Pro C900S	
309	Pro C900S	M8792700010
310	Pro C900S	M8792700011
311	Pro C900S	M8792700012
312	Pro C900S	M8792700013
313	Pro C900S	M8792700014
314	Pro C900S	M8792700015
315	Pro C900S	M8792700016
316	Pro C900S	M8792700017
317	Pro C900S	M8792700018
318	Pro C900S	M8792700019
319	Pro C900S	M8792700020
320	Pro C900S	M8792700021
321	Pro C900S	
		M8792700022
322	Pro C900S	M8792700023
323	Pro C900S	M8792800001
324	Pro C900S	M8792800002
325	Pro C900S	M8792800003
326	Pro C900S	M8792800004
327	Pro C900S	M8792800005
328		M8792800006
329	Pro C900S	
	Pro C900S	M8792800007
330	Pro C900S	M8792800008
331	Pro C900S	M8792800009
332	Pro C900S	M8792800010
333	Pro C900S	M8792800011
334	Pro C900S	M8792800012
335	Pro C900S	M8792800013
336	Pro C900S	M8792800014
337	Pro C900S	M8792800015
338	Pro C900S	M8792800016
339	Pro C900S	M8792800017
340	Pro C900S	M8792800018
341	Pro C900S	M8792800019
342	Pro C900S	M8792800020
343	Pro C900S	M8792900001
344	Pro C900S	M8792900002
345	Pro C900S	M8792900003
346	Pro C900S	M8792900004
347	Pro C900S	M8792900005
348	Pro C900S	M8792900006
349	Pro C900S	M8792900007
350	Pro C900S	M8792900008
		5.020000

Model Name			DDL Markins's
352		Model Name	RPL Machine's Serial No.
353 Pro C900S M8792900012 354 Pro C900S M8793000001 355 Pro C900S M8793000002 357 Pro C900S M8793000003 358 Pro C900S M8793000004 359 Pro C900S M8793000006 361 Pro C900S M8793000007 362 Pro C900S M8793000009 363 Pro C900S M8793000010 365 Pro C900S M8793000010 366 Pro C900S M8793000011 366 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100001 375 Pro C900S M879310001 378	351	Pro C900S	M8792900009
354 Pro C900S M8792900012 355 Pro C900S M8793000001 356 Pro C900S M8793000002 357 Pro C900S M8793000004 358 Pro C900S M8793000006 360 Pro C900S M8793000006 361 Pro C900S M8793000009 362 Pro C900S M8793000010 365 Pro C900S M8793000010 366 Pro C900S M8793000011 367 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100010 378 Pro C900S M8793100011 379 <td>352</td> <td>Pro C900S</td> <td>M8792900010</td>	352	Pro C900S	M8792900010
354 Pro C900S M8792900012 355 Pro C900S M8793000001 356 Pro C900S M8793000002 357 Pro C900S M8793000004 358 Pro C900S M8793000006 360 Pro C900S M8793000006 361 Pro C900S M8793000009 362 Pro C900S M8793000010 365 Pro C900S M8793000010 366 Pro C900S M8793000011 367 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100010 378 Pro C900S M8793100011 379 <td>353</td> <td>Pro C900S</td> <td>M8792900011</td>	353	Pro C900S	M8792900011
355			
356 Pro C900S M8793000002 357 Pro C900S M8793000003 358 Pro C900S M8793000004 359 Pro C900S M8793000006 361 Pro C900S M8793000007 362 Pro C900S M8793000009 363 Pro C900S M879300001 365 Pro C900S M879300001 366 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100000 375 Pro C900S M8793100001 376 Pro C900S M879310001 379 Pro C900S M879310001 370 Pro C900S M879310001 370 Pro C900S M879310001 370			
357 Pro C900S M8793000003 358 Pro C900S M8793000004 359 Pro C900S M8793000006 360 Pro C900S M8793000006 361 Pro C900S M8793000009 362 Pro C900S M8793000009 363 Pro C900S M8793000010 365 Pro C900S M8793000011 366 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100000 375 Pro C900S M8793100001 376 Pro C900S M8793100010 377 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 <td></td> <td></td> <td></td>			
358 Pro C900S M8793000004 359 Pro C900S M8793000005 360 Pro C900S M8793000006 361 Pro C900S M8793000007 362 Pro C900S M8793000009 363 Pro C900S M8793000010 365 Pro C900S M8793000011 366 Pro C900S M8793000013 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100006 374 Pro C900S M8793100009 375 Pro C900S M8793100009 376 Pro C900S M879310001 378 Pro C900S M879310001 379 Pro C900S M879310001 381 Pro C900S M879310001 382 Pro C900S M879320000 383			
359 Pro C900S M8793000006 360 Pro C900S M8793000006 361 Pro C900S M8793000008 362 Pro C900S M8793000009 363 Pro C900S M8793000010 364 Pro C900S M8793000011 365 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 372 Pro C900S M8793100006 374 Pro C900S M8793100006 375 Pro C900S M8793100000 376 Pro C900S M8793100000 377 Pro C900S M8793100000 378 Pro C900S M879310001 378 Pro C900S M879310001 379 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200000 383			
360 Pro C900S M8793000006 361 Pro C900S M8793000008 362 Pro C900S M8793000009 363 Pro C900S M8793000010 364 Pro C900S M8793000011 365 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100010 376 Pro C900S M8793100011 379 Pro C900S M8793100011 379 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200000 384 <td></td> <td></td> <td></td>			
361 Pro C900S M8793000007 362 Pro C900S M8793000008 363 Pro C900S M8793000010 364 Pro C900S M8793000011 365 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100000 376 Pro C900S M8793100010 377 Pro C900S M8793100011 379 Pro C900S M8793100011 379 Pro C900S M8793100011 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200001 384 Pro C900S M8793200005 387 <td></td> <td></td> <td></td>			
362 Pro C900S M8793000008 363 Pro C900S M8793000009 364 Pro C900S M8793000010 365 Pro C900S M8793000011 366 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100002 370 Pro C900S M8793100004 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100000 375 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200001 383 Pro C900S M8793200000 384 Pro C900S M8793200000 385 Pro C900S M8793200000 387 <td></td> <td></td> <td></td>			
363 Pro C900S M8793000009 364 Pro C900S M8793000011 365 Pro C900S M8793000012 366 Pro C900S M8793000013 367 Pro C900S M8793100001 368 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100010 379 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200001 383 Pro C900S M8793200000 384 Pro C900S M8793200000 385 Pro C900S M8793200000 386 <td>361</td> <td>Pro C900S</td> <td>M8793000007</td>	361	Pro C900S	M8793000007
364 Pro C900S M8793000010 365 Pro C900S M8793000011 366 Pro C900S M8793000012 367 Pro C900S M8793100001 368 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200005 385 Pro C900S M8793200006 386 Pro C900S M8793200001 389 <td>362</td> <td>Pro C900S</td> <td>M8793000008</td>	362	Pro C900S	M8793000008
365 Pro C900S M8793000011 366 Pro C900S M8793000012 367 Pro C900S M8793000013 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200001 383 Pro C900S M8793200000 384 Pro C900S M8793200000 385 Pro C900S M8793200000 387 Pro C900S M8793200000 388 Pro C900S M8793200010 392 <td>363</td> <td>Pro C900S</td> <td>M8793000009</td>	363	Pro C900S	M8793000009
366 Pro C900S M8793000012 367 Pro C900S M8793000013 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100006 372 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 376 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200000 386 Pro C900S M8793200000 387 Pro C900S M8793200000 388 Pro C900S M8793200010 390 Pro C900S M8793200010 392 <td>364</td> <td>Pro C900S</td> <td>M8793000010</td>	364	Pro C900S	M8793000010
367 Pro C900S M8793000013 368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100004 371 Pro C900S M8793100004 372 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200006 387 Pro C900S M8793200006 388 Pro C900S M8793200000 389 Pro C900S M879320001 390 Pro C900S M879320001 393	365	Pro C900S	M8793000011
368 Pro C900S M8793100001 369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 376 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200001 390 Pro C900S M879320001 391 Pro C900S M879320001 392	366	Pro C900S	M8793000012
369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100009 375 Pro C900S M8793100009 376 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200004 385 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M879320001 391 Pro C900S M879320001 392 Pro C900S M879320001 393	367	Pro C900S	M8793000013
369 Pro C900S M8793100002 370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200004 385 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200010 391 Pro C900S M8793200011 393 Pro C900S M8793200012 394 <td>368</td> <td>Pro C900S</td> <td>M8793100001</td>	368	Pro C900S	M8793100001
370 Pro C900S M8793100003 371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200005 387 Pro C900S M8793200005 388 Pro C900S M8793200000 389 Pro C900S M879320001 390 Pro C900S M879320001 391 Pro C900S M879320001 392 Pro C900S M879320001 393	369	Pro C900S	
371 Pro C900S M8793100004 372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100009 376 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M879320001 391 Pro C900S M8793200011 392 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300003 397			
372 Pro C900S M8793100005 373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100008 376 Pro C900S M8793100010 377 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200006 387 Pro C900S M8793200007 389 Pro C900S M8793200000 390 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 <td></td> <td></td> <td></td>			
373 Pro C900S M8793100006 374 Pro C900S M8793100007 375 Pro C900S M8793100008 376 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300001 396 Pro C900S M8793300005 397 <td></td> <td></td> <td></td>			
374 Pro C900S M8793100007 375 Pro C900S M8793100008 376 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200007 389 Pro C900S M8793200000 390 Pro C900S M8793200010 391 Pro C900S M8793200011 392 Pro C900S M8793200011 393 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300006 397 Pro C900S M8793300006 398 <td></td> <td></td> <td></td>			
375 Pro C900S M8793100008 376 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M8793200000 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300005 397 Pro C900S M8793300006 398 <td></td> <td></td> <td></td>			
376 Pro C900S M8793100009 377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793200001 382 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M8793200000 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300005 397 Pro C900S M8793300006			
377 Pro C900S M8793100010 378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200000 390 Pro C900S M8793200001 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300006			
378 Pro C900S M8793100011 379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300005 399 Pro C900S M8793300006			
379 Pro C900S M8793100012 380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200006 387 Pro C900S M8793200006 389 Pro C900S M8793200009 390 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300003 397 Pro C900S M8793300005 398 Pro C900S M8793300006	377	Pro C900S	M8793100010
380 Pro C900S M8793100013 381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200006 387 Pro C900S M8793200006 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	378	Pro C900S	M8793100011
381 Pro C900S M8793100014 382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	379	Pro C900S	M8793100012
382 Pro C900S M8793200001 383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	380	Pro C900S	M8793100013
383 Pro C900S M8793200002 384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300005 398 Pro C900S M8793300006	381	Pro C900S	M8793100014
384 Pro C900S M8793200003 385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300005 399 Pro C900S M8793300006	382	Pro C900S	M8793200001
385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200008 390 Pro C900S M8793200010 391 Pro C900S M8793200011 392 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300006	383	Pro C900S	M8793200002
385 Pro C900S M8793200004 386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200008 390 Pro C900S M8793200010 391 Pro C900S M8793200011 392 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300006	384	Pro C900S	M8793200003
386 Pro C900S M8793200005 387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200008 390 Pro C900S M8793200010 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300006 399 Pro C900S M8793300006	385	Pro C900S	
387 Pro C900S M8793200006 388 Pro C900S M8793200007 389 Pro C900S M8793200008 390 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	386		
388 Pro C900S M8793200007 389 Pro C900S M8793200008 390 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300006 399 Pro C900S M8793300006			
389 Pro C900S M8793200008 390 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006			
390 Pro C900S M8793200009 391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300005 398 Pro C900S M8793300006			
391 Pro C900S M8793200010 392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300006			
392 Pro C900S M8793200011 393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300006			
393 Pro C900S M8793200012 394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300006 399 Pro C900S M8793300006			
394 Pro C900S M8793300001 395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	392	Pro C900S	M8793200011
395 Pro C900S M8793300002 396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	393		M8793200012
396 Pro C900S M8793300003 397 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	394	Pro C900S	M8793300001
397 Pro C900S M8793300004 398 Pro C900S M8793300005 399 Pro C900S M8793300006	395	Pro C900S	M8793300002
398 Pro C900S M8793300005 399 Pro C900S M8793300006	396	Pro C900S	M8793300003
399 Pro C900S M8793300006	397	Pro C900S	M8793300004
	398	Pro C900S	M8793300005
400 Pro C900S M8793300007	399	Pro C900S	M8793300006
	400	Pro C900S	M8793300007

	Model Name	RPL Machine's Serial No.
401	Pro C900S	M8793300008
402	Pro C900S	M8793300009
403	Pro C900S	M8793300010
404	Pro C900S	M8793300011
405	Pro C900S	M8793300012
	Pro C900S	M8793300012
406 407	Pro C900S	
407	Pro C900S	M8793300014
		M8793300016
409	Pro C900S	M8793300017
410	Pro C900S	M8793300018
411	Pro C900S	M8793300019
412	Pro C900S	M8793300020
413	Pro C900S	M8793400001
414	Pro C900S	M8793400002
415	Pro C900S	M8793400003
416	Pro C900S	M8793400004
417	Pro C900S	M8793400005
418	Pro C900S	M8793400006
419	Pro C900S	M8793400007
420	Pro C900S	M8793400008
421	Pro C900S	M8793400009
422	Pro C900S	M8793400010
423	Pro C900S	M8793400011
424	Pro C900S	M8793400012
425	Pro C900S	M8793400013
426	Pro C900S	M8793400014
427	Pro C900S	M8793400015
428	Pro C900S	M8793400016
429	Pro C900S	M8793400017
430	Pro C900S	M8793400017
431	Pro C900S	M8793400019
432	Pro C900S	M8793500013
433	Pro C900S	M8793500001
434	Pro C900S	M8793500003
435	Pro C900S	M8793500004
436	Pro C900S	M8793500005
437	Pro C900S	M8793500006
438	Pro C900S	M8793500007
439	Pro C900S	M8793500008
440	Pro C900S	M8793500009
441	Pro C900S	M8793500010
442	Pro C900S	M8793500011
443	Pro C900S	M8793500012
444	Pro C900S	M8793500013
445	Pro C900S	M8793500014
446	Pro C900S	M8793500015
447	Pro C900S	M8793500016
448	Pro C900S	M8793500017
449	Pro C900S	M8793500018
450	Pro C900S	M8793500019
		•

PAGE: 6/17



PAGE: 7/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

Model Name			RPL Machine's
452 Pro C900S M8793500021 453 Pro C900S M8793500023 454 Pro C900S M8793500023 455 Pro C900S M8793500024 456 Pro C900S M8793600001 457 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600016 473 Pro C900S M8793600016 474 Pro C900S V7402500001 476 Pro C900S V7402600001 477 <th></th> <th>Model Name</th> <th></th>		Model Name	
453 Pro C900S M8793500022 454 Pro C900S M8793500023 455 Pro C900S M8793500024 456 Pro C900S M8793500025 457 Pro C900S M8793600001 458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 476 Pro C900S V7402600001 479 <td>451</td> <td>Pro C900S</td> <td>M8793500020</td>	451	Pro C900S	M8793500020
454 Pro C900S M8793500023 455 Pro C900S M8793500024 456 Pro C900S M8793500025 457 Pro C900S M8793600001 458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600007 464 Pro C900S M8793600007 464 Pro C900S M8793600010 467 Pro C900S M8793600010 468 Pro C900S M8793600011 469 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600010 474 Pro C900S V7402500001 476 Pro C900S V7402500001 477 Pro C900S V7493300001 478 <td>452</td> <td>Pro C900S</td> <td>M8793500021</td>	452	Pro C900S	M8793500021
455 Pro C900S M8793500024 456 Pro C900S M8793500025 457 Pro C900S M8793600001 458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 465 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 475 Pro C900S V7402500001 476 Pro C900S V7402700001 479 Pro C900S V7493500001 481 <td>453</td> <td>Pro C900S</td> <td>M8793500022</td>	453	Pro C900S	M8793500022
456 Pro C900S M8793500025 457 Pro C900S M8793600001 458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600007 463 Pro C900S M8793600007 464 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7493300001 480 Pro C900S V7493500001 481 <td>454</td> <td>Pro C900S</td> <td>M8793500023</td>	454	Pro C900S	M8793500023
457 Pro C900S M8793600001 458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 465 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 472 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 <td>455</td> <td>Pro C900S</td> <td>M8793500024</td>	455	Pro C900S	M8793500024
458 Pro C900S M8793600002 459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 465 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 475 Pro C900S V7402500002 477 Pro C900S V7493300001 478 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001	456	Pro C900S	M8793500025
459 Pro C900S M8793600003 460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 465 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001	457	Pro C900S	M8793600001
460 Pro C900S M8793600004 461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600009 465 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 475 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001	458	Pro C900S	M8793600002
461 Pro C900S M8793600005 462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600008 465 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500001 477 Pro C900S V7402700001 478 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001	459	Pro C900S	M8793600003
462 Pro C900S M8793600006 463 Pro C900S M8793600007 464 Pro C900S M8793600008 465 Pro C900S M8793600010 466 Pro C900S M8793600011 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500001 477 Pro C900S V7402600001 478 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001	460	Pro C900S	M8793600004
463 Pro C900S M8793600007 464 Pro C900S M8793600008 465 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600015 471 Pro C900S M8793600015 472 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402700001 478 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493500002 482 Pro C900S V7493600001	461	Pro C900S	M8793600005
464 Pro C900S M8793600008 465 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	462	Pro C900S	M8793600006
464 Pro C900S M8793600008 465 Pro C900S M8793600009 466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	463	Pro C900S	M8793600007
466 Pro C900S M8793600010 467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001			M8793600008
467 Pro C900S M8793600011 468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	465	Pro C900S	M8793600009
468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 483 S7090490001	466	Pro C900S	M8793600010
468 Pro C900S M8793600012 469 Pro C900S M8793600013 470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 483 S7090490001	467	Pro C900S	M8793600011
470 Pro C900S M8793600014 471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 477 Pro C900S V7402700001 478 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	468	Pro C900S	
471 Pro C900S M8793600015 472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	469	Pro C900S	M8793600013
472 Pro C900S M8793600016 473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7493300001 479 Pro C900S V7493500001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	470	Pro C900S	M8793600014
473 Pro C900S M8793600017 474 Pro C900S S3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 483 S7090490001	471	Pro C900S	M8793600015
474 Pro C900S \$3292900003 475 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500002 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 \$7090490001	472	Pro C900S	M8793600016
475 Pro C900S V7402500001 476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	473	Pro C900S	M8793600017
476 Pro C900S V7402500002 477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493600001 482 Pro C900S V7493600001 483 S7090490001	474	Pro C900S	S3292900003
477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	475	Pro C900S	V7402500001
477 Pro C900S V7402600001 478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	476	Pro C900S	V7402500002
478 Pro C900S V7402700001 479 Pro C900S V7493300001 480 Pro C900S V7493500001 481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	477	Pro C900S	V7402600001
480 Pro C900S V7493500001 481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	478	Pro C900S	V7402700001
481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	479	Pro C900S	V7493300001
481 Pro C900S V7493500002 482 Pro C900S V7493600001 483 S7090490001	480	Pro C900S	V7493500001
482 Pro C900S V7493600001 483 S7090490001	481	Pro C900S	
483 S7090490001	482		
			S7090490001
	484		

PAGE: 8/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

Total Number of Affected Units in AP: 38

	Model Name	REI Machine's
		Serial No.
1	Pro C900S	M8790100001
2	Pro C900S	M8790100002
3	Pro C900S	M8790100003
4	Pro C900S	M8790100004
5	Pro C900S	M8790200001
6	Pro C900S	M8790200002
7	Pro C900S	M8790400001
8	Pro C900S	M8790500001
9	Pro C900S	M8790500002
10	Pro C900S	M8790500003
11	Pro C900S	M8790500004
12	Pro C900S	M8790900001
13	Pro C900S	M8790900002
14	Pro C900S	M8790900003
15	Pro C900	S3281100005
16	Pro C900	S3281100006
17	Pro C900	S3281100007
	Pro C900	S3281100008
19	Pro C900	S3281100009
20	Pro C900	S3281100010
21	Pro C900	S3281100011
22	Pro C900	S3281100012
23		S3281200001
24		S3281200002
25	Pro C900	S3281200003
26	Pro C900	S3281200004
27		S3281200005
28	Pro C900	S3281200006
29		S3290100011
30	Pro C900	S3290100012
31	Pro C900	S3290500001
32	Pro C900	S3290500002
33	Pro C900	S3290500003
34		S3290700001
35		S3290800001
36	Pro C900	S3290900001
37	Pro C900	S3291000001
38	Pro C900	S3291000002
UU	1 10 0000	3320100000Z



Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

Total Number of Affected Units in NA: 936

	Model Name	REI Machine's
		Serial No.
1	Pro C900	S3280700002
2	Pro C900	S3280700003
3	Pro C900	S3280700004
4	Pro C900	S3280700005
5	Pro C900	S3280700006
6	Pro C900	S3280700007
7	Pro C900	S3280700008
8	Pro C900	S3280700009
9	Pro C900	S3280700010
10	Pro C900	S3280700011
11	Pro C900	S3280700012
12	Pro C900	S3280700013
13	Pro C900	S3280700014
14	Pro C900	S3280700015
15	Pro C900	S3280700016
16	Pro C900	S3280700017
17	Pro C900	S3280700017
18	Pro C900	S3280700019
19	Pro C900	S3280700019
20	Pro C900	S3280700021
21	Pro C900	S3280700021
22		
 	Pro C900	S3280700023
23	Pro C900	S3280700046
24	Pro C900	S3280700047
25	Pro C900	S3280700048
26	Pro C900	S3280700049
27	Pro C900	S3280700051
28	Pro C900	S3280700052
29	Pro C900	S3280800001
30	Pro C900	S3280800002
31	Pro C900	S3280800003
32	Pro C900	S3280800004
33	Pro C900	S3280800005
34	Pro C900	S3280800006
35	Pro C900	S3281000001
36	Pro C900	S3281000002
37	Pro C900	S3281000003
38	Pro C900	S3281000004
39	Pro C900	S3281000005
40	Pro C900	S3281000006
41	Pro C900	S3281000007
42	Pro C900	S3281000008
43	Pro C900	S3281000009
44	Pro C900	S3281000010
45	Pro C900	S3281000011
46	Pro C900	S3281000012
47	Pro C900	S3281000013
48	Pro C900	S3281000014
49	Pro C900	S3281000015
50	Pro C900	S3281000016

	Model Name	REI Machine's
F-4		Serial No.
51	Pro C900	S3281000017
52	Pro C900	S3281000018
53	Pro C900	S3281000019
54	Pro C900	S3281000020
55	Pro C900	S3281000021
56	Pro C900	S3281000022
57	Pro C900	S3281000023
58	Pro C900	S3281000024
59	Pro C900	S3281000025
60	Pro C900	S3281000026
61	Pro C900	S3281000027
62	Pro C900	S3281000028
63	Pro C900	S3281000029
64	Pro C900	S3281000030
65	Pro C900	S3281000031
66	Pro C900	S3281000032
67	Pro C900	S3281000033
68	Pro C900	S3281000034
69	Pro C900	S3281000035
70	Pro C900	S3281000036
71	Pro C900	S3281000037
72	Pro C900	S3281000038
73		S3281000039
74	Pro C900	
	Pro C900	S3281000040
75	Pro C900	S3281000041
76	Pro C900	S3281000042
77	Pro C900	S3281000043
78	Pro C900	S3281000044
79	Pro C900	S3281000045
80	Pro C900	S3281000046
81	Pro C900	S3281000047
82	Pro C900	S3281000048
83	Pro C900	S3281000049
84	Pro C900	S3281000050
85	Pro C900	S3281000051
86	Pro C900	S3281000052
87	Pro C900	S3281000053
88	Pro C900	S3281000054
89	Pro C900	S3281000055
90	Pro C900	S3281000056
91	Pro C900	S3281000057
92	Pro C900	S3281000058
93	Pro C900	S3281000059
94	Pro C900	S3281000060
95	Pro C900	S3281000061
96	Pro C900	S3281000062
97	Pro C900	S3281000063
98	Pro C900	S3281000064
99	Pro C900	S3281000065
100	Pro C900	S3281000066

	Model Name	REI Machine's
	Woder Name	Serial No.
101	Pro C900	S3281000067
102	Pro C900	S3281000068
103	Pro C900	S3281000069
104	Pro C900	S3281000070
105	Pro C900	S3281000071
106	Pro C900	S3281000072
107	Pro C900	S3281000073
108	Pro C900	S3281000074
109	Pro C900	S3281000075
110	Pro C900	S3281000076
111	Pro C900	S3281000077
112	Pro C900	S3281000078
113	Pro C900	S3281000079
114	Pro C900	S3281000080
115	Pro C900	S3281000081
116	Pro C900	S3281000082
117	Pro C900	S3281000083
118	Pro C900	S3281000084
119	Pro C900	S3281000085
120	Pro C900	S3281000086
121	Pro C900	S3281000087
122	Pro C900	S3281000088
123	Pro C900	S3281000089
124	Pro C900	S3281000090
125	Pro C900	S3281000091
126	Pro C900	S3281000092
127	Pro C900	S3281000093
128	Pro C900	S3281000094
129	Pro C900	S3281000095
130	Pro C900	S3281000096
131	Pro C900	S3281000097
132	Pro C900	S3281000098
133	Pro C900	S3281000099
134	Pro C900	S3281000100
135	Pro C900	S3281000101
136	Pro C900	S3281000102
137	Pro C900	S3281000103
138	Pro C900	S3281000104
139	Pro C900	S3281000178
140	Pro C900	S3281000179
141	Pro C900	S3286000001
142	Pro C900	S3286000002
143	Pro C900	S3286000003
144	Pro C900	S3286000003
145	Pro C900	S3286000004 S3286000005
146	Pro C900	S3286000005 S3286000006
147	Pro C900	S32860000007
148	Pro C900	S3286000007 S32860000008
149	Pro C900	S3286000008 S3286000009
150	Pro C900	S3286000010
. 50		2020000010

PAGE: 9/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	REI Machine's Serial No.
151	Pro C900	S3286000011
152	Pro C900	S3286000012
153	Pro C900	S3286000013
154	Pro C900	S3286000014
155	Pro C900	S3286000015
156	Pro C900	S3286000016
157		
	Pro C900	S3286000017
158	Pro C900	S3286000018
159	Pro C900	S3286000019
160	Pro C900	S3286000020
161	Pro C900	S3286000021
162	Pro C900	S3286000022
163	Pro C900	S3286000023
164	Pro C900	S3286000024
165	Pro C900	S3286000025
166	Pro C900	S3286000026
167	Pro C900	S3286000027
168	Pro C900	S3286000028
169	Pro C900	S3286000029
170	Pro C900	S3286000030
171	Pro C900	S3286000031
172	Pro C900	S3286000032
173	Pro C900	S3286000033
174	Pro C900	S3286000034
175	Pro C900	S3286000035
176	Pro C900	S3286000036
177	Pro C900	S3286000037
178	Pro C900	S3286000038
179	Pro C900	S3286000039
180	Pro C900	S3286000040
181	Pro C900	S3286000041
182	Pro C900	S3286000042
183	Pro C900	S3286000043
184	Pro C900	S3286000044
185	Pro C900	S3286000045
186	Pro C900	S3286000046
187	Pro C900	S3286000047
188	Pro C900	S3286000048
189	Pro C900	S3286000049
190	Pro C900	S3286000050
191	Pro C900	S3290100001
192	Pro C900	S3290100002
193	Pro C900	S3290100003
194	Pro C900	S3290100004
195	Pro C900	S3290100005
196	Pro C900	S3294900001
197	Pro C900	S3294900002
198	Pro C900	S3294900003
199	Pro C900	S3294900004
200	Pro C900	S3294900005
L200		12220-200000

		_
	Model Name	REI Machine's
201	Pro C900	Serial No. S3294900006
202		S3294900007
	Pro C900	
203	Pro C900	S3294900008
204	Pro C900	S3294900009
205	Pro C900	S3294900010
206	Pro C900	S3294900011
207	Pro C900	S3294900012
208	Pro C900	S3294900013
209	Pro C900	S3294900014
210	Pro C900	S3294900015
211	Pro C900	S3294900016
212	Pro C900	S3294900017
213	Pro C900	S3294900018
214	Pro C900	S3294900019
215	Pro C900	S3294900020
216	Pro C900	S3294900021
217	Pro C900	S3294900022
218	Pro C900	S3294900023
219	Pro C900	S3294900024
220	Pro C900	S3294900025
221	Pro C900	S3294900026
222	Pro C900	S3294900027
223	Pro C900	S3294900028
224	Pro C900	S3294900029
225	Pro C900	S3294900030
226	Pro C900	S3294900031
227	Pro C900	S3294900032
228	Pro C900	S3294900033
229	Pro C900	S3294900034
230	Pro C900	S3294900035
231	Pro C900	S3294900036
232	Pro C900	S3294900037
233	Pro C900	S3294900038
234	Pro C900	S3294900039
235	Pro C900	S3294900040
236	Pro C900	S3294900041
237	Pro C900	S3294900042
238	Pro C900	S3294900043
239	Pro C900	S3294900044
240	Pro C900	S3294900045
241	Pro C900	S3294900043
241		
243	Pro C900	S3294900047
243	Pro C900	S3294900048
	Pro C900	S3294900049
245	Pro C900	S3294900050
246	Pro C900	S3294900051
247	Pro C900	S3294900052
248	Pro C900	S3294900053
249	Pro C900	S3294900054
250	Pro C900	S3294900055

	Model Name	REI Machine's
054		Serial No.
251	Pro C900	S3294900056
252	Pro C900	S3294900057
253	Pro C900	S3294900058
254	Pro C900	S3294900059
255	Pro C900	S3294900060
256	Pro C900	S3294900061
257	Pro C900	S3294900062
258	Pro C900	S3294900063
259	Pro C900	S3294900064
260	Pro C900	S3294900065
261	Pro C900	S3294900066
262	Pro C900	S3294900067
263	Pro C900	S3294900068
264	Pro C900	S3294900069
265	Pro C900	S3294900070
266	Pro C900	S3294900071
267	Pro C900	S3294900072
268	Pro C900	S3294900073
269	Pro C900	S3294900074
270	Pro C900	S3294900075
271	Pro C900	S3294900076
272	Pro C900	S3294900077
273	Pro C900	S3294900078
274	Pro C900	S3294900079
275	Pro C900	S3294900080
276	Pro C900	S3294900081
277	Pro C900	S3294900082
278	Pro C900	S3294900083
279	Pro C900	S3294900084
280	Pro C900	S3294900085
281	Pro C900	S3294900086
282	Pro C900	S3294900087
283	Pro C900	S3294900088
284	Pro C900	S3294900089
285	Pro C900	S3294900090
286	Pro C900	S3294900091
287	Pro C900	S3294900092
288	Pro C900	S3294900093
289	Pro C900	S3294900094
290	Pro C900	S3295000001
291	Pro C900	S3295000002
292	Pro C900	S3295000003
293	Pro C900	S3295000004
294	Pro C900	S3295300001
295	Pro C900	S3295300001
296	Pro C900	S3295300002 S3295300004
297	Pro C900	S3295300004 S3295300005
298	Pro C900	S3295300005 S3295300006
299	Pro C900	S3295300000 S3295300007
300	Pro C900	S3295400001
550		23200-00001

PAGE: 10/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	REI Machine's Serial No.
301	Pro C900	S3295400003
302	Pro C900	S3295400004
303	Pro C900	S3295400005
304	Pro C900	S3295400006
305	Pro C900	S3295400007
306	Pro C900	S3295400008
307	Pro C900	S3295400009
308	Pro C900	S3295400010
309	Pro C900	S3295400011
310	Pro C900	S3295400012
311	Pro C900	S3295400013
312	Pro C900	S3295400014
313	Pro C900	S3295400015
314	Pro C900	S3295400016
315	Pro C900	S3295400017
316	Pro C900	S3295400018
317	Pro C900	S3295400019
318	Pro C900	S3295400020
319	Pro C900	S3295400021
320	Pro C900	S3295400022
321	Pro C900	S3295500001
322	Pro C900	S3295500002
323	Pro C900	S3295500003
324	Pro C900	S3295500004
325	Pro C900	S3295500005
326	Pro C900	S3295500006
327	Pro C900	S3295500007
328	Pro C900	S3295500008
329	Pro C900	S3295500009
330	Pro C900	S3295500010
331	Pro C900	S3295500011
332	Pro C900	S3295500013
333	Pro C900	S3295500014
334	Pro C900	S3295500015
335	Pro C900	S3295500016
336	Pro C900	S3295500017
337	Pro C900	S3295500018
338	Pro C900	S3295500019
339	Pro C900	S3295500020
340	Pro C900	S3295500021
341	Pro C900	S3295500022
342	Pro C900	S3295500023
343	Pro C900	S3295500024
344	Pro C900	S3295500025
345	Pro C900	S3295500026
346	Pro C900	S3295500027
347	Pro C900	S3295500028
348	Pro C900	S3295500029
349	Pro C900	S3295500030
350	Pro C900	S3295500031

	Model Name	REI Machine's
251		Serial No.
351	Pro C900	S3295500032
352	Pro C900	S3295500033
353	Pro C900	S3295500034
354	Pro C900	S3295500035
355	Pro C900	S3295500036
356	Pro C900	S3295500037
357	Pro C900	S3295500038
358	Pro C900	S3295500039
359	Pro C900	S3295500040
360	Pro C900	S3295500041
361	Pro C900	S3295500042
362	Pro C900	S3295500043
363	Pro C900	S3295700001
364	Pro C900	S3295700002
365	Pro C900	S3295700003
366	Pro C900	S3295700004
367	Pro C900	S3295700005
368	Pro C900	S3295700006
369	Pro C900	S3295700007
370	Pro C900	S3295700008
371		S3295700009
372	Pro C900	
	Pro C900	S3295700010
373	Pro C900	S3295700011
374	Pro C900	S3295700012
375	Pro C900	S3295700013
376	Pro C900	S3295700014
377	Pro C900	S3295700015
378	Pro C900	S3295700016
379	Pro C900	S3295700017
380	Pro C900	S3295700018
381	Pro C900	S3295700019
382	Pro C900	S3295700020
383	Pro C900	S3295700021
384	Pro C900	S3295700022
385	Pro C900	S3295700023
386	Pro C900	S3295700024
387	Pro C900	S3295700025
388	Pro C900	S3295700026
389	Pro C900	S3295700027
390	Pro C900	S3295700028
391	Pro C900	S3295700029
392	Pro C900	S3295700030
393	Pro C900	S3295700031
394	Pro C900	S3295800001
395	Pro C900	S3295800002
396	Pro C900	S3295800003
397	Pro C900	S3295800004
398	Pro C900	S3295800005
399	Pro C900	S3295800005
400	Pro C900	S3295800007
400	1 10 0900	33293600007

	Model Name	REI Machine's Serial No.
401	Pro C900	S3295800008
402	Pro C900	S3295800009
403	Pro C900	S3295800010
404	Pro C900	S3295800011
405	Pro C900	S3295800012
406	Pro C900	S3295800013
407	Pro C900	S3295800014
408	Pro C900	S3295800015
409	Pro C900	S3295800016
410	Pro C900	S3295800017
411	Pro C900	S3295800018
412	Pro C900	S3295800019
413	Pro C900	S3295800020
414	Pro C900	S3295800021
415	Pro C900	S3295800021
416	Pro C900	
417	Pro C900	S3295800023 S3295800024
418		
419	Pro C900	S3295800025
420	Pro C900	S3295800026 S3295800027
420	Pro C900	
422	Pro C900	S3295800028
	Pro C900	S3295800029
423	Pro C900	S3295800030
424	Pro C900	S3295800031
425	Pro C900	S3295800032
426	Pro C900	S3295800033
427	Pro C900	S3295900001
428 429	Pro C900	S3295900002
430	Pro C900	S3295900003
	Pro C900	S3295900004
431	Pro C900	S3295900005
432	Pro C900	S3295900006
433	Pro C900	S3295900007
434	Pro C900	S3296000001
435	Pro C900	S3296000002
436	Pro C900	S3296000003
437	Pro C900	S3296000004
438	Pro C900	S3296000005
439	Pro C900	S3296000006
440	Pro C900	S3296000007
441	Pro C900	S3296000008
442	Pro C900	S3296000009
443	Pro C900	S3296000036
444	Pro C900	S3296000040
445	Pro C900	S3296000043
446	Pro C900	S3296000046
447	Pro C900	S7004900001
448	Pro C900	S7004900002
449	Pro C900	S7004900003
450	Pro C900	S7004900004

PAGE: 11/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	REI Machine's Serial No.
451	Pro C900	S7004900005
452	Pro C900	S7004900006
453	Pro C900	S7004900009
454	Pro C900	S7004900010
455	Pro C900	S7005000001
456	Pro C900	S7005100001
457	Pro C900	S7005100002
458	Pro C900	S7005100003
459	Pro C900	S7005100004
460	Pro C900	S7005100005
461	Pro C900	S7005100006
462	Pro C900	S7095400001
463	Pro C900	S7095500001
464	Pro C900	S7095500002
465	Pro C900	S7095500003
466	Pro C900	S7095500004
467	Pro C900	S7095500005
468	Pro C900	S7095500006
469	Pro C900	S7095500007
470	Pro C900	S7095500008
471	Pro C900	S7095600001
472	Pro C900	S7095600002
473	Pro C900	S7095800001
474	Pro C900	S7095800002
475	Pro C900	S7095800003
476	Pro C900	S7095800004
477	Pro C900	S7095800005
478	Pro C900	S7095900001
479	Pro C900	S7095900002
480	Pro C900	S7095900003
481	Pro C900	S7095900005
482	Pro C900	S7095900006
483	Pro C900	S7095900007
484	Pro C900	S7095900008
485	Pro C900	S7095900009
486	Pro C900S	M8704900001
487	Pro C900S	M8705000020
488	Pro C900S	M8705000021
489	Pro C900S	M8705000049
490	Pro C900S	M8705100016
491	Pro C900S	M8795000001
492	Pro C900S	M8795000002
493	Pro C900S	M8795000003
494	Pro C900S	M8795000004
495	Pro C900S	M8795000005
496	Pro C900S	M8795000006
497	Pro C900S	M8795000007
498	Pro C900S	M8795000008
499	Pro C900S	M8795000009
500	Pro C900S	M8795000010

	M. LIN	REI Machine's
	Model Name	Serial No.
501	Pro C900S	M8795000011
502	Pro C900S	M8795000012
503	Pro C900S	M8795000013
504	Pro C900S	M8795000014
505	Pro C900S	M8795000015
506	Pro C900S	M8795000016
507	Pro C900S	M8795000017
508	Pro C900S	M8795000018
509	Pro C900S	M8795000019
510	Pro C900S	M8795000020
511	Pro C900S	M8795000021
512	Pro C900S	M8795000022
513	Pro C900S	M8795000023
514	Pro C900S	M8795000024
515	Pro C900S	M8795000025
516	Pro C900S	M8795000025
517	Pro C900S	M8795000027
518	Pro C900S	M8795000028
519	Pro C900S	M8795000029
520	Pro C900S	M8795000023
521	Pro C900S	M8795000031
522	Pro C900S	M8795000031
523		
524	Pro C900S Pro C900S	M8795000033 M8795200001
525	Pro C900S	M8795200001 M8795200002
526	Pro C900S	M8795200003
527	Pro C900S	M8795200004
528	Pro C900S	M8795200005
529	Pro C900S	M8795200006
530	Pro C900S	M8795200007
531	Pro C900S	M8795200007
532	Pro C900S	M8795200009
533	Pro C900S	M8795200010
534	Pro C900S	M8795200011
535	Pro C900S	M8795200011
536	Pro C900S	M8795200013
537	Pro C900S	M8795200014
538	Pro C900S	M8795200015
539	Pro C900S	M8795200015
540	Pro C900S	M8795200017
541	Pro C900S	M8795200017 M8795200018
542		
543	Pro C900S	M8795200019
544	Pro C900S	M8795200020 M8795200021
	Pro C900S	
545	Pro C900S	M8795200022
546	Pro C900S	M8795200023
547	Pro C900S	M8795200024
548	Pro C900S	M8795200025
549	Pro C900S	M8795200026
550	Pro C900S	M8795200027

	Model Name	REI Machine's Serial No.
551	Pro C900S	M8795200028
552	Pro C900S	M8795300001
553	Pro C900S	M8795300002
554	Pro C900S	M8795300003
555	Pro C900S	M8795300004
556	Pro C900S	M8795300005
557	Pro C900S	M8795300006
558	Pro C900S	M8795300007
559	Pro C900S	M8795300008
560	Pro C900S	M8795300009
561	Pro C900S	M8795300010
562	Pro C900S	M8795300011
563	Pro C900S	M8795300012
564	Pro C900S	M8795300013
565	Pro C900S	M8795300014
566	Pro C900S	M8795300015
567	Pro C900S	M8795300016
568	Pro C900S	M8795300017
569	Pro C900S	M8795300018
570	Pro C900S	M8795300019
571	Pro C900S	M8795300020
572	Pro C900S	M8795300021
573	Pro C900S	M8795300022
574	Pro C900S	M8795300023
575	Pro C900S	M8795300024
576	Pro C900S	M8795300025
577	Pro C900S	M8795300026
578	Pro C900S	M8795300027
579	Pro C900S	M8795300028
580	Pro C900S	M8795300029
581	Pro C900S	M8795300030
582	Pro C900S	M8795300031
583	Pro C900S	M8795300032
584	Pro C900S	M8795300033
585	Pro C900S	M8795300034
586	Pro C900S	M8795300035
587	Pro C900S	M8795300036
588	Pro C900S	M8795300037
589	Pro C900S	M8795300038
590	Pro C900S	M8795300039
591	Pro C900S	M8795300040
592	Pro C900S	M8795300041
593	Pro C900S	M8795300042
594	Pro C900S	M8795300043
595	Pro C900S	M8795300044
596	Pro C900S	M8795300045
597	Pro C900S	M8795300046
598	Pro C900S	M8795300047
599	Pro C900S	M8795300048
600	Pro C900S	M8795300049

PAGE: 12/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

	Model Name	REI Machine's Serial No.
601	Pro C900S	M8795300050
602	Pro C900S	M8795300051
603	Pro C900S	M8795300052
604	Pro C900S	M8795300053
605	Pro C900S	M8795300054
606	Pro C900S	M8795300055
607	Pro C900S	M8795300056
608	Pro C900S	M8795300057
609	Pro C900S	M8795300058
610	Pro C900S	M8795300059
611	Pro C900S	M8795300060
612	Pro C900S	M8795300061
613	Pro C900S	M8795300062
614	Pro C900S	M8795300063
615	Pro C900S	M8795300064
616	Pro C900S	M8795300065
617	Pro C900S	M8795300066
618	Pro C900S	M8795300067
619	Pro C900S	M8795300068
620	Pro C900S	M8795300069
621	Pro C900S	M8795300070
622	Pro C900S	M8795300071
623	Pro C900S	M8795300072
624	Pro C900S	M8795300073
625	Pro C900S	M8795300074
626	Pro C900S	M8795300075
627	Pro C900S	M8795300076
628	Pro C900S	M8795300077
629	Pro C900S	M8795400001
630	Pro C900S	M8795400002
631	Pro C900S	M8795400003
632	Pro C900S	M8795400004
633	Pro C900S	M8795400005
634	Pro C900S	M8795400006
635	Pro C900S	M8795400009
636	Pro C900S	M8795400010
637	Pro C900S	M8795400011
638	Pro C900S	M8795400012
639	Pro C900S	M8795400013
640	Pro C900S	M8795400014
641	Pro C900S	M8795400015
642	Pro C900S	M8795400016
643	Pro C900S	M8795400017
644	Pro C900S	M8795400018
645	Pro C900S	M8795400019
646	Pro C900S	M8795400020
647	Pro C900S	M8795400021
648	Pro C900S	M8795400022
649	Pro C900S	M8795400023
650	Pro C900S	M8795400024

	Model Name	REI Machine's
054		Serial No.
651	Pro C900S	M8795400025
652	Pro C900S	M8795500001
653	Pro C900S	M8795500002
654	Pro C900S	M8795500003
655	Pro C900S	M8795500004
656	Pro C900S	M8795500005
657	Pro C900S	M8795500006
658	Pro C900S	M8795500007
659	Pro C900S	M8795500008
660	Pro C900S	M8795500009
661	Pro C900S	M8795500010
662	Pro C900S	M8795500011
663	Pro C900S	M8795500013
664	Pro C900S	M8795500014
665	Pro C900S	M8795500015
666	Pro C900S	M8795500016
667	Pro C900S	M8795500017
668	Pro C900S	M8795500018
669	Pro C900S	M8795500019
670	Pro C900S	M8795500020
671	Pro C900S	M8795500021
672	Pro C900S	M8795500022
673	Pro C900S	M8795500023
674	Pro C900S	M8795500024
675	Pro C900S	M8795500025
676	Pro C900S	M8795500026
677	Pro C900S	M8795500027
678	Pro C900S	M8795500028
679	Pro C900S	M8795500029
680	Pro C900S	M8795500030
681	Pro C900S	M8795500031
682	Pro C900S	M8795500032
683	Pro C900S	M8795500033
684	Pro C900S	M8795500034
685	Pro C900S	M8795500035
686	Pro C900S	M8795500036
687	Pro C900S	M8795500037
688	Pro C900S	M8795500038
689	Pro C900S	M8795500039
690	Pro C900S	M8795500040
691	Pro C900S	M8795500041
692	Pro C900S	M8795500042
693	Pro C900S	M8795500043
694	Pro C900S	M8795500044
695	Pro C900S	M8795500045
696	Pro C900S	M8795500046
697	Pro C900S	M8795500047
698	Pro C900S	M8795500048
699	Pro C900S	M8795500049
700	Pro C900S	M8795500050

	Model Name	REI Machine's Serial No.
701	Pro C900S	M8795500051
702	Pro C900S	M8795500052
703	Pro C900S	M8795500053
704	Pro C900S	M8795500054
705	Pro C900S	M8795500055
706	Pro C900S	M8795500056
707	Pro C900S	M8795500057
708	Pro C900S	M8795500058
709	Pro C900S	M8795500059
710	Pro C900S	M8795500060
711	Pro C900S	M8795500061
712	Pro C900S	M8795500062
713	Pro C900S	M8795500063
714	Pro C900S	M8795500064
715	Pro C900S	M8795500065
716	Pro C900S	M8795500066
717	Pro C900S	M8795500067
718	Pro C900S	M8795500068
719	Pro C900S	M8795500069
720	Pro C900S	M8795500070
721	Pro C900S	M8795500071
722	Pro C900S	M8795500072
723	Pro C900S	M8795500073
724	Pro C900S	M8795500074
725	Pro C900S	M8795500075
726	Pro C900S	M8795500076
727	Pro C900S	M8795500077
728	Pro C900S	M8795600001
729	Pro C900S	M8795600002
730	Pro C900S	M8795600003
731	Pro C900S	M8795600004
732	Pro C900S	M8795600005
733	Pro C900S	M8795600006
734	Pro C900S	M8795600007
735	Pro C900S	M8795600008
736	Pro C900S	M8795600009
737	Pro C900S	M8795600010
738	Pro C900S	M8795600011
739	Pro C900S	M8795600011
740	Pro C900S	M8795600013
741	Pro C900S	M8795600014
742	Pro C900S	M8795600015
743	Pro C900S	M8795600016
744	Pro C900S	M8795600017
745	Pro C900S	M8795600017
743 746	Pro C900S	M8795600018
747	Pro C900S	M8795600019
748		M8795600021
749	Pro C900S Pro C900S	M8795600021
750	Pro C900S	M8795600022
, 50	1 10 03003	19107 330000023

PAGE: 13/17

No.: RG178097 Model: AG-P1/C1 Date: 20-May-10

	Model Name	REI Machine's Serial No.
751	Pro C900S	M8795600024
752	Pro C900S	M8795600025
753	Pro C900S	M8795600026
754	Pro C900S	M8795600027
755	Pro C900S	M8795600028
756	Pro C900S	M8795600029
757	Pro C900S	M8795600030
758	Pro C900S	M8795600031
759	Pro C900S	M8795600032
760	Pro C900S	M8795600033
761	Pro C900S	M8795600034
762	Pro C900S	M8795700001
763	Pro C900S	M8795700002
764	Pro C900S	M8795700003
765	Pro C900S	M8795700004
766	Pro C900S	M8795700005
767	Pro C900S	M8795700006
768	Pro C900S	M8795700007
769	Pro C900S	M8795700008
770	Pro C900S	M8795700009
771	Pro C900S	M8795700010
772	Pro C900S	M8795700011
773	Pro C900S	M8795700011 M8795700012
774	Pro C900S	M8795700012
775	Pro C900S	M8795700014
776	Pro C900S	M8795700014 M8795700015
777	Pro C900S	M8795700016
778	Pro C900S	M8795700017
779	Pro C900S	M8795700017
780	Pro C900S	M8795700019
781	Pro C900S	M8795700020
782	Pro C900S	M8795700021
783	Pro C900S	M8795700022
784	Pro C900S	M8795700022
785	Pro C900S	M8795700024
786	Pro C900S	M8795700025
787	Pro C900S	M8795700026
788	Pro C900S	M8795700027
789	Pro C900S	M8795700027
790	Pro C900S	M8795700029
791	Pro C900S	M8795700029
792	Pro C900S	M8795700030
793	Pro C900S	M8795700031
794	Pro C900S	M8795700032
795	Pro C900S	M8795700033
796		M8795700034 M8795700035
797	Pro C900S	
	Pro C900S	M8795700036 M8795700037
798 799	Pro C900S	M8795700037
	Pro C900S	M8795700038
800	Pro C900S	M8795700039

	Model Name	REI Machine's		Model Name	REI Machine's
001		Serial No.	051		Serial No.
801	Pro C900S	M8795800001	851	Pro C900S	M8795900002
802	Pro C900S	M8795800002	852	Pro C900S	M8795900003
803	Pro C900S	M8795800003	853	Pro C900S	M8795900004
804	Pro C900S	M8795800004	854	Pro C900S	M8795900005
805	Pro C900S	M8795800005	855	Pro C900S	M8795900006
806	Pro C900S	M8795800006	856	Pro C900S	M8795900007
807	Pro C900S	M8795800007	857	Pro C900S	M8795900008
808	Pro C900S	M8795800008	858	Pro C900S	M8795900009
809	Pro C900S	M8795800009	859	Pro C900S	M8795900010
810	Pro C900S	M8795800010	860	Pro C900S	M8795900011
811	Pro C900S	M8795800011	861	Pro C900S	M8795900012
812	Pro C900S	M8795800012	862	Pro C900S	M8795900013
813	Pro C900S	M8795800013	863	Pro C900S	M8795900014
814	Pro C900S	M8795800014	864	Pro C900S	M8795900015
815	Pro C900S	M8795800015	865	Pro C900S	M8795900016
816	Pro C900S	M8795800016	866	Pro C900S	M8795900017
817	Pro C900S	M8795800017	867	Pro C900S	M8795900018
818	Pro C900S	M8795800018	868	Pro C900S	M8795900019
819	Pro C900S	M8795800019	869	Pro C900S	M8795900020
820	Pro C900S	M8795800020	870	Pro C900S	M8795900021
821	Pro C900S	M8795800021	871	Pro C900S	M8795900022
822	Pro C900S	M8795800022	872	Pro C900S	M8795900023
823	Pro C900S	M8795800023	873	Pro C900S	M8795900024
824	Pro C900S	M8795800024	874	Pro C900S	M8795900025
825	Pro C900S	M8795800025	875	Pro C900S	M8795900026
826	Pro C900S	M8795800026	876	Pro C900S	M8795900027
827 828	Pro C900S	M8795800027	877	Pro C900S	M8795900028
829	Pro C900S	M8795800028	878	Pro C900S	M8795900029
830	Pro C900S	M8795800029	879	Pro C900S	M8795900030
831	Pro C900S	M8795800030	880 881	Pro C900S	M8795900031
832	Pro C900S Pro C900S	M8795800031 M8795800032	882	Pro C900S	M8795900032 M8795900033
833	Pro C900S	M8795800032 M8795800033	883	Pro C900S Pro C900S	M8795900033
834	Pro C900S	M8795800033 M8795800034	884		M8795900034 M8795900035
835	Pro C900S	M8795800034 M8795800035	885	Pro C900S	M8795900035
836	Pro C900S	M8795800035	886		M8795900037
837	Pro C900S	M8795800037	887		M8795900037
838	Pro C900S	M8795800038	888	Pro C900S	M8795900039
839	Pro C900S	M8795800039	889	<u> </u>	M8795900040
840	Pro C900S	M8795800039	890	Pro C900S	M8796000001
841	Pro C900S	M8795800040	891	Pro C900S	M8796000001
842	Pro C900S	M8795800041	892	Pro C900S	M8796000002
843	Pro C900S	M8795800042	893	Pro C900S	M8796000003
844	Pro C900S	M8795800044 M8795800045	894	Pro C900S	M8796000005
845	Pro C900S	M8795800045 M8795800046	895	Pro C900S	M8796000005 M8796000006
846	Pro C900S	M8795800048	896	Pro C900S	M8796000007
847	Pro C900S	M8795800048	897	Pro C900S	M8796000007 M8796000008
848	Pro C900S	M8795800049 M8795800050	898	Pro C900S	M8796000009
849	Pro C900S	M8795800050	899	Pro C900S	M8796000010
850	Pro C900S	M8795900031	900	Pro C900S	M8796000011
550	0 00000	14107 0000001	300	1 10 00000	14107 30000011

Model Name REI Machine's Serial No. 851 Pro C900S M8795900002 852 Pro C900S M8795900003 853 Pro C900S M8795900005 854 Pro C900S M8795900006 855 Pro C900S M8795900007 856 Pro C900S M8795900009 857 Pro C900S M8795900010 859 Pro C900S M8795900011 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900011 867 Pro C900S M8795900011 868 Pro C900S M8795900012 870 Pro C900S M8795900018 868 Pro C900S M8795900020 871 Pro C900S M8795900021 872			
851 Pro C900S M8795900002 852 Pro C900S M8795900003 853 Pro C900S M8795900004 854 Pro C900S M8795900005 855 Pro C900S M8795900007 856 Pro C900S M8795900009 857 Pro C900S M8795900009 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900018 868 Pro C900S M8795900020 870 Pro C900S M8795900020 871 Pro C900S M8795900022 872 Pro C900S M8795900022 873 Pro C900S M8795900023 873 <th></th> <th>Model Name</th> <th></th>		Model Name	
852 Pro C900S M8795900004 853 Pro C900S M8795900004 854 Pro C900S M8795900005 855 Pro C900S M8795900000 856 Pro C900S M8795900000 857 Pro C900S M8795900000 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900017 867 Pro C900S M8795900010 870 Pro C900S M8795900010 870 Pro C900S M8795900020 870 Pro C900S M8795900022 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 <th>051</th> <th>Dro C000C</th> <th></th>	051	Dro C000C	
853 Pro C900S M8795900004 854 Pro C900S M8795900005 855 Pro C900S M8795900006 856 Pro C900S M8795900000 857 Pro C900S M8795900009 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 <td> </td> <td></td> <td></td>			
854 Pro C900S M8795900005 855 Pro C900S M8795900006 856 Pro C900S M8795900007 857 Pro C900S M8795900009 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900017 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900022 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 <td></td> <td></td> <td></td>			
855 Pro C900S M8795900006 856 Pro C900S M8795900007 857 Pro C900S M8795900008 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900022 873 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M879590003 879			
856 Pro C900S M8795900007 857 Pro C900S M8795900008 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900022 873 Pro C900S M8795900022 874 Pro C900S M8795900024 875 Pro C900S M8795900025 875 Pro C900S M8795900029 879 Pro C900S M879590003 879 Pro C900S M879590003 880			
857 Pro C900S M8795900009 858 Pro C900S M8795900010 860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900020 871 Pro C900S M8795900021 871 Pro C900S M8795900023 872 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 <td> </td> <td></td> <td></td>			
858 Pro C900S M8795900009 859 Pro C900S M8795900010 860 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900020 871 Pro C900S M8795900022 872 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900031 882 <td></td> <td></td> <td></td>			
859 Pro C900S M8795900011 860 Pro C900S M8795900012 861 Pro C900S M8795900013 862 Pro C900S M8795900014 863 Pro C900S M8795900015 864 Pro C900S M8795900015 865 Pro C900S M8795900017 867 Pro C900S M8795900017 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900027 877 Pro C900S M879590003 880 Pro C900S M879590003 881 Pro C900S M879590003 882 Pro C900S M879590003 883			
860 Pro C900S M8795900011 861 Pro C900S M8795900012 862 Pro C900S M8795900013 863 Pro C900S M8795900014 864 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900022 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900027 877 Pro C900S M8795900022 878 Pro C900S M879590003 880 Pro C900S M879590003 881 Pro C900S M879590003 882 Pro C900S M879590003 883			
861 Pro C900S M8795900012 862 Pro C900S M8795900014 863 Pro C900S M8795900015 865 Pro C900S M8795900016 866 Pro C900S M8795900017 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900024 875 Pro C900S M8795900025 876 Pro C900S M8795900028 877 Pro C900S M8795900029 879 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 883 Pro C900S M8795900036 884 <td> </td> <td></td> <td></td>			
862 Pro C900S M8795900014 863 Pro C900S M8795900015 864 Pro C900S M8795900016 865 Pro C900S M8795900017 866 Pro C900S M8795900019 867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900030 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900036 885 <td> </td> <td></td> <td></td>			
863 Pro C900S M8795900015 864 Pro C900S M8795900016 865 Pro C900S M8795900017 866 Pro C900S M8795900018 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900031 882 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 <td></td> <td></td> <td></td>			
864 Pro C900S M8795900016 865 Pro C900S M8795900017 867 Pro C900S M8795900017 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900025 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 884 Pro C900S M8795900034 884 Pro C900S M8795900036 885 Pro C900S M8795900036 886 Pro C900S M8795900039 887 <td></td> <td></td> <td></td>			
865 Pro C900S M8795900017 866 Pro C900S M8795900017 867 Pro C900S M8795900018 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900030 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900034 882 Pro C900S M8795900034 883 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900039 887 Pro C900S M8795900039 888 <td></td> <td></td> <td></td>			
866 Pro C900S M8795900018 867 Pro C900S M8795900019 868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900026 874 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900030 879 Pro C900S M8795900031 881 Pro C900S M8795900031 882 Pro C900S M8795900034 884 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 <td></td> <td></td> <td></td>			
867 Pro C900S M8795900019 868 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 876 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900030 880 Pro C900S M8795900030 881 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 888 Pro C900S M8795900000 889 <td></td> <td></td> <td></td>			
868 Pro C900S M8795900019 869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900028 878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900030 888 Pro C900S M8795900030 889 Pro C900S M8795900000 899 <td>866</td> <td>Pro C900S</td> <td>M8795900017</td>	866	Pro C900S	M8795900017
869 Pro C900S M8795900020 870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900024 873 Pro C900S M8795900025 874 Pro C900S M8795900025 875 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900039 889 Pro C900S M8795900000 890 Pro C900S M8796000001 891 <td>867</td> <td>Pro C900S</td> <td>M8795900018</td>	867	Pro C900S	M8795900018
870 Pro C900S M8795900021 871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 876 Pro C900S M8795900029 877 Pro C900S M8795900029 878 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 884 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900000 890 Pro C900S M8796000001 891 Pro C900S M8796000000 892 <td>868</td> <td></td> <td>M8795900019</td>	868		M8795900019
871 Pro C900S M8795900022 872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900037 888 Pro C900S M8795900039 889 Pro C900S M8795900000 890 Pro C900S M8795900000 891 Pro C900S M8796000001 892 Pro C900S M8796000002 893 Pro C900S M8796000006 894 <td>869</td> <td>Pro C900S</td> <td>M8795900020</td>	869	Pro C900S	M8795900020
872 Pro C900S M8795900023 873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900027 876 Pro C900S M8795900027 877 Pro C900S M8795900029 878 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900030 889 Pro C900S M8795900000 889 Pro C900S M8795900000 891 Pro C900S M879600000 892 Pro C900S M879600000 893 Pro C900S M879600000 894	870	Pro C900S	M8795900021
873 Pro C900S M8795900024 874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900028 878 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8795900001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000000 895 Pro C900S M8796000000 896 <td>871</td> <td>Pro C900S</td> <td>M8795900022</td>	871	Pro C900S	M8795900022
874 Pro C900S M8795900025 875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900028 878 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900000 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000000 894 Pro C900S M8796000000 895 Pro C900S M8796000000 896 <td>872</td> <td>Pro C900S</td> <td>M8795900023</td>	872	Pro C900S	M8795900023
875 Pro C900S M8795900026 876 Pro C900S M8795900027 877 Pro C900S M8795900028 878 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900000 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000000 898 <td>873</td> <td>Pro C900S</td> <td>M8795900024</td>	873	Pro C900S	M8795900024
876 Pro C900S M8795900027 877 Pro C900S M8795900028 878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000000 898 Pro C900S M8796000000	874	Pro C900S	M8795900025
877 Pro C900S M8795900028 878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000000 898 Pro C900S M8796000000	875	Pro C900S	M8795900026
878 Pro C900S M8795900029 879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900039 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000001	876	Pro C900S	M8795900027
879 Pro C900S M8795900030 880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M87960000010	877	Pro C900S	M8795900028
880 Pro C900S M8795900031 881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000009 898 Pro C900S M8796000009 899 Pro C900S M8796000010	878	Pro C900S	M8795900029
881 Pro C900S M8795900032 882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000001	879	Pro C900S	M8795900030
882 Pro C900S M8795900033 883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900037 886 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000006 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	880	Pro C900S	M8795900031
883 Pro C900S M8795900034 884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000005 894 Pro C900S M8796000005 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	881	Pro C900S	M8795900032
884 Pro C900S M8795900035 885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	882	Pro C900S	M8795900033
885 Pro C900S M8795900036 886 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	883	Pro C900S	M8795900034
886 Pro C900S M8795900037 887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	884	Pro C900S	M8795900035
887 Pro C900S M8795900038 888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	885	Pro C900S	M8795900036
888 Pro C900S M8795900039 889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000009 898 Pro C900S M8796000010	886	Pro C900S	M8795900037
889 Pro C900S M8795900040 890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001	887	Pro C900S	M8795900038
890 Pro C900S M8796000001 891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001	888	Pro C900S	M8795900039
891 Pro C900S M8796000002 892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001	889	Pro C900S	M8795900040
892 Pro C900S M8796000003 893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001	890	Pro C900S	M8796000001
893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001 899 Pro C900S M8796000010	891	Pro C900S	M8796000002
893 Pro C900S M8796000004 894 Pro C900S M8796000005 895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000001 899 Pro C900S M8796000010	892	Pro C900S	M8796000003
895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	893	Pro C900S	
895 Pro C900S M8796000006 896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	894	Pro C900S	M8796000005
896 Pro C900S M8796000007 897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010	895		
897 Pro C900S M8796000008 898 Pro C900S M8796000009 899 Pro C900S M8796000010			
898 Pro C900S M8796000009 899 Pro C900S M8796000010			
899 Pro C900S M8796000010			

PAGE: 14/17



PAGE: 15/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097


	Madal Nama	REI Machine's		
	Model Name	Serial No.		
901	Pro C900S	M8796000012		
902	Pro C900S	M8796000013		
903	Pro C900S	M8796000014		
904	Pro C900S	M8796000015		
905	Pro C900S	M8796000016		
906	Pro C900S	M8796000017		
907	Pro C900S	M8796000018		
908	Pro C900S	M8796000019		
909	Pro C900S	M8796000020		
910	Pro C900S	M8796000021		
911	Pro C900S	M8796000024		
912	Pro C900S	M8796000025		
913	Pro C900S	M8796000028		
914	Pro C900S	M8796000029		
915	Pro C900S	M8796000031		
916	Pro C900S	M8796000032		
917	Pro C900S	V7405100001		
918	Pro C900S	V7495400001		
919	Pro C900S	V7495400002		
920	Pro C900S	V7495400003		
921	Pro C900S	V7495700001		
922	Pro C900S	V7495700002		
923	Pro C900S	V7495700003		
924	Pro C900S	V7495700004		
925	Pro C900S	V7495700005		
926	Pro C900S	V7495800001		
927	Pro C900S	V7495800002		
928	Pro C900S	V7495800003		
929	Pro C900S	V7495800004		
930	Pro C900S	V7495900001		
931	Pro C900S	V7495900002		
932	Pro C900S	V7495900003		
933	Pro C900S	V7495900004		
934	Pro C900S	V7495900005		
935	Pro C900S	V7495900006		
936	Pro C900S	V7495900007		

PAGE: 16/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

Replacement Procedures


1. Remove the rear top cover [A] (screw x 3)




2. Remove the two screws that attach the rear controller box to the mainframe.



- 3. Loosen the fixing pins at rear right and left bottom with a flat-headed screwdriver.
- 4. Open the rear controller box, while holding the right side. (Viewed from the rear).









PAGE: 17/17

Model: AG-P1/C1 Date: 20-May-10 No.: RG178097

- 5. Open the rear controller box.
- 6. Open the AC drive board bracket (screw x 4).



7. Remove the Relay Board [A] (screw x 2, connector x 9)



8. After replacing the Relay Board, follow the steps above in reverse order to complete the process.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C	Dat	Date: 08-Jun-10		No.: RG178098		
Subject: Oil leaks from the Oil Tank Filter				Prepared by: N.iida		
From: PPBG Service Planning Dept.						
Classification:	Troubleshooting	☐ Part info	orma	tion		required
	☐ Mechanical	☐ Electrical		Electrical Serv		ce manual revision
☐ Paper path ☐ Transmit/ı		it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2	

SYMPTOM

Oil leaks from the Oil Tank Filter


CAUSE

A fault in the current engine firmware clears the PM counter of the Oil Tank Filter when clearing the PM counter of the fusing unit. When the counter of the fusing unit is cleared upon its replacement, the correct PM interval of the Oil Tank Filter cannot be identified as it is falsely cleared, disabling its replacement at the correct timing. Calcium carbonate deposits are formed in the Oil Tank Filter over time, degrading the filtering function, and may cause oil leaks.

SOLUTION

The fault in the current engine firmware will be fixed and the modified firmware will be released in mid July. Please apply the temporary solution described below until the release of the modified firmware.

 On your next service visit, please check for any calcium carbonate deposits in the Oil Tank Filter. If the entire filter is covered with the deposits, replace with a new filter regardless of the PM counter having or not having reached 400K. Replacement is required for both filters.






PAGE: 2/2

Model: AG-P1/C1 Date: 08-Jun-10 No.: RG178098

2. Replace both filters circled below when replacing the fusing unit.



Technical Bulletin

PAGE: 1/3

Model: AG-P1/C	Dat	Date: 08-Jun-10		No.: RG178099			
Subject: Important Notes on Engine Firmware Update					Prepared by: N.iida		
From: PPBG Service Planning Dept.							
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required	
		☐ Electrical ☐ Servi		Service	ce manual revision		
☐ Paper path ☐ Transmit/re		it/rec	eive	Retro	fit information		
	☐ Product Safety	Other ()	☐ Tier 2		

Important Notes on Engine Firmware Update

1. General

Settings/conditions most effective for various paper types based on the results from MQP (Media Qualification Program) have been reflected in the default settings for "Special3/Special6". This modification will automatically take effect by upgrading the engine firmware to 3.005 or newer; default settings for "Special3/Special6" will be rewritten by installing the firmware. The affected SPs are as listed below. Please refer to the table for details on the modified values.

SP1-105-

208,209,210,211,212,213,214,215,218,219,220,221,222,223,224,225,226,227

SP1-108-

063,064,065,066,067,068,069,070,071,072,073,074,075,076,077,078,079,080,

081,082,083,084

SP1-905-

048,049,050,114,115,116

SP1-909-

057,058,059,060,061,074,076,077,078,079

2. Notes on upgrading the engine firmware to version 3.005:12 or newer

Fusing problems could occur with customers currently using Special3/Special6 bacause the new firmware rewrites the fusing-related default values. To avoid such problems, make sure to modify the related SP values after upgrading the firmware.

Procedure

- a. Check whether the customer uses Special 3 or Special 6.
- b. If used, print out an SMC report.(SP5990-002)
- c. Upgrade the Engine firmware.
- d. Refer to the SMC report and re-input the values for the following SP settings.

Technical Bulletin

PAGE: 2/3

Model: AG-P1/C1 Date: 08-Jun-10 No.: RG178099

Coated:Sp	pecial 3					
Thickness	Description	SP No.	NA model		EU model	
			Current value	Modified	Current value	Modified
				value		value
	Temp. in Simplex and B/W	1-105-210	180 deg	160 deg	180 deg	160 deg
	Temp. in Simplex and FC	1-105-211	180 deg	160 deg	180 deg	160 deg
Thin	Temp. in Duplex and B/W	1-105-222	180 deg	160 deg	180 deg	160 deg
60-75g/m2	Temp. in Duplex and FC	1-105-223	180 deg	160 deg	180 deg	160 deg
	Nip: Low Temp	1-905-047	510 msec	510 msec	510 msec	510 msec
	Nip: Over Low Temp	1-905-113	510 msec	510 msec	510 msec	510 msec
	Fusing Motor Speed	1-909-056	-3.0 %	-3.0 %	-3.0 %	-3.0 %
	Temp. in Simplex and B/W	1-105-208	190 deg	180 deg	180 deg	180 deg
	Temp. in Simplex and FC	1-105-209	190 deg	180 deg	180 deg	180 deg
Plain	Temp. in Duplex and B/W	1-105-220	190 deg	180 deg	180 deg	180 deg
76-100g/m2	Temp. in Duplex and FC	1-105-221	190 deg	180 deg	180 deg	180 deg
3.	Nip: Low Temp	1-905-048	330 msec	510 msec	330 msec	510 msec
	Nip: Over Low Temp	1-905-114	330 msec	510 msec	330 msec	510 msec
	Fusing Motor Speed	1-909-057	0 %	-3.0 %	-3.0 %	-3.0 %
	Temp. in Simplex and B/W	1-105-212	190 deg	180 deg	190 deg	185 deg
NA: al all a	Temp. in Simplex and FC	1-105-213	190 deg	180 deg	190 deg	185 deg
Middle Thick	Temp. in Duplex and B/W	1-105-224	190 deg	180 deg	190 deg	185 deg
101-	Temp. in Duplex and FC	1-105-225	190 deg	180 deg	190 deg	185 deg
126g/m2	Nip: Low Temp	1-905-049	40 msec	330 msec	40 msec	330 msec
	Nip: Over Low Temp	1-905-115	40 msec	330 msec	40 msec	330 msec
	Fusing Motor Speed	1-909-058	-2.0 %	-3.0 %	-2.0 %	-3.0 %
	Temp. in Simplex and B/W	1-105-214	200 deg	195 deg	200 deg	195 deg
	Temp. in Simplex and FC	1-105-215	200 deg	195 deg	200 deg	195 deg
Thick 1	Temp. in Duplex and B/W	1-105-226	200 deg	195 deg	200 deg	195 deg
127-	Temp. in Duplex and FC	1-105-227	200 deg	195 deg	200 deg	195 deg
156g/m2	Nip: Low Temp	1-905-050	40 msec	330 msec	40 msec	330 msec
	Nip: Over Low Temp	1-905-116	40 msec	330 msec	40 msec	330 msec
	Fusing Motor Speed	1-909-059	-2.0 %	-3.0 %	-2.0 %	-3.0 %
	Temp. in Simplex and B/W	1-105-216	200 deg	200 deg	200	200 deg
	Temp. in Simplex and FC	1-105-217	200 deg	200 deg	200	200 deg
Thick 2	Temp. in Duplex and B/W	1-105-228	200 deg	200 deg	200	200 deg
157-	Temp. in Duplex and FC	1-105-229	200 deg	200 deg	200	200 deg
220g/m2	Nip: Low Temp	1-905-051	40 msec	40 msec	40 msec	40 msec
	Nip: Over Low Temp	1-905-117	40 msec	40 msec	40 msec	40 msec
	Fusing Motor Speed	1-909-060	-3.0 %	-2.0 %	-2.0 %	-2.0 %
	Temp. in Simplex and B/W	1-105-218	200 deg	205 deg	200 deg	205 deg
Thick 3	Temp. in Simplex and FC	1-105-219	200 deg	205 deg	200 deg	205 deg
221-	Nip: Low Temp	1-905-052	40 msec	40 msec	40 msec	40 msec
300g/m2	Nip: Over Low Temp	1-905-118	40 msec	40 msec	40 msec	40 msec
	Fusing Motor Speed	1-909-061	-3.0 %	-2.0 %	0 %	-2.0 %

Model: AG-P1/C1

Technical Bulletin

Date: 08-Jun-10 No.: RG178099

PAGE: 3/3

Uncoated :	:Special 6					
Thickness	Description	SP	NA model		EU model	
			Current value	Modified	Current value	Modified
				value		value
	Temp. in Simplex and B/W	1-108-065	170 deg	160 deg	175 deg	160 deg
Thin	Temp. in Simplex and FC	1-108-066	170 deg	160 deg	175 deg	160 deg
	Temp. in Duplex and B/W	1-108-077	170 deg	160 deg	175 deg	160 deg
60-75g/m2	Temp. in Duplex and FC	1-108-078	170 deg	160 deg	175 deg	160 deg
	Nip: Low Temp	1-905-065	510 msec	510 secc	510 msec	510 msec
	Nip: Over Low Temp	1-905-131	510 msec	510 msec	510 msec	510 msec
	Fusing Motor Speed	1-909-074	0 %	-3.0 %	-3.0 %	-3.0 %
	Temp. in Simplex and B/W	1-108-063	170 deg	170 deg	170 deg	180 deg
	Temp. in Simplex and FC	1-108-064	170 deg	170 deg	170 deg	180 deg
Plain	Temp. in Duplex and B/W	1-108-075	170 deg	170 deg	170 deg	180 deg
76-100g/m2	Temp. in Duplex and FC	1-108-076	170 deg	170 deg	170 deg	180 deg
3	Nip: Low Temp	1-905-066	510 msec	510 msec	510 msec	510 msec
	Nip: Over Low Temp	1-905-132	510 msec	510 msec	510 msec	510 msec
	Fusing Motor Speed	1-909-075	-3.0 %	-3.0 %	-3.0 %	-3.0 %
	Temp. in Simplex and B/W	1-108-067	185 deg	180 deg	180 deg	185 deg
Middle	Temp. in Simplex and FC	1-108-068	185 deg	180 deg	180 deg	185 deg
Middle Thick	Temp. in Duplex and B/W	1-108-079	185 deg	180 deg	180 deg	185 deg
101-	Temp. in Duplex and FC	1-108-080	185 deg	180 deg	180 deg	185 deg
126g/m2	Nip: Low Temp	1-905-067	330 msec	330 msec	330 msec	330 msec
	Nip: Over Low Temp	1-905-133	330 msec	330 msec	330 msec	330 msec
	Fusing Motor Speed	1-909-076	0 %	-3.0 %	-3.0 %	-3.0 %
	Temp. in Simplex and B/W	1-108-069	180 deg	190 deg	190 deg	190 deg
	Temp. in Simplex and FC	1-108-070	180 deg	190 deg	190 deg	190 deg
Thick 1	Temp. in Duplex and B/W	1-108-081	180 deg	190 deg	190 deg	190 deg
127-	Temp. in Duplex and FC	1-108-082	180 deg	190 deg	190 deg	190 deg
156g/m2	Nip: Low Temp	1-905-068	330 msec	330 msec	330 msec	330 msec
	Nip: Over Low Temp	1-905-134	330 msec	330 msec	330 msec	330 msec
	Fusing Motor Speed	1-909-077	0 %	-3.0 %	0 %	-3.0 %
	Temp. in Simplex and B/W	1-108-071	190 deg	195 deg	200 deg	195 deg
	Temp. in Simplex and FC	1-108-072	190 deg	195 deg	200 deg	195 deg
Thick 2	Temp. in Duplex and B/W	1-108-083	190 deg	195 deg	200 deg	195 deg
157-	Temp. in Duplex and FC	1-108-084	190 deg	195 deg	200 deg	195 deg
	Nip: Low Temp	1-905-069	40 msec	40 msec	40 msec	40 msec
	Nip: Over Low Temp	1-905-135	40 msec	40 msec	40 msec	40 msec
	Fusing Motor Speed	1-909-078	-3.0 %	-2.0 %	-2.0 %	-2.0 %
	Temp. in Simplex and B/W	1-108-073	200 deg	205 deg	200 deg	205 deg
Thick 3	Temp. in Simplex and FC	1-108-074	200 deg	205 deg	200 deg	205 deg
221-	Nip: Low Temp	1-905-070	40 msec	40 msec	40 msec	40 msec
300g/m2	Nip: Over Low Temp	1-905-136	40 msec	40 msec	40 msec	40 msec
	Fusing Motor Speed	1-909-079	-3.0 %	-2.0 %	-2.0 %	-2.0 %

K	ш	U	

Model: AG-P1

Classification:

Technical Bulletin

Date:		No.: RG178100				
d Mylars	Prep	Prepared by: N.iida				
□ Part information		☐ Action required				
☐ Electrical		☐ Service manual revision				
☐ Transmit/receive		☐ Retrofit information				

☐ Tier 2

PAGE: 1/2


Additional Explanation on the Red Mylars attached to the PAPER EXIT GUIDE:UPPER

Other (

)

Attaching two red mylars [B] to the paper exit guide was a temporary solution for jams where the paper curls and interferes with the sensor holes in a duplex print on B5 thin paper on machines with the PAPER EXIT GUIDE: UPPER of a lot produced in the early stages of its mass production. However, as these attached mylars were eventually torn or peeled-off, the shape of the paper exit guide had been modified as a permanent solution, which eliminated the use of these mylars.

If new mylars are needed for replacement, please place an order with p/n G1787926 [C].



Subject: Additional Explanation on Attaching the Red Mylars

☐ Troubleshooting

☐ Product Safety


☐ Mechanical☐ Paper path

From: PPBG Service Planning Dept.

Technical Bulletin

Model: AG-P1 Date: No.: RG178100





PAGE: 2/2









P/N G1787926 3 sensor type (final design)

Machine production level: Mass production





The shape of the paper exit guide (areas circled in red below) has been modified to prevent interference with the paper. Red mylars are no longer needed to prevent jams.



Technical Bulletin


PAGE: 1/1

Model: AG-P1/C1			Date: 09-Jun-10		-10	No.: RG178101		
Subject: Upper frame for Fusing unit				Prepared by: N.iida				
From: PPBG Ser	vice Planning Dept.							
Classification:	Troubleshooting	□ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inferen	ormat	tion	Action required			
	☐ Mechanical	☐ Electric	☐ Electrical☐ Transmit/receive		☐ Service manual revision			
	☐ Paper path	☐ Transm			Retro	fit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	G1784126	FRAME:UPPER:ASS'Y	0→1	1	127	17	
-	D0164221	STAY:FRAME:UPPER	0→1	1	127	18	

The above two parts have been newly added as spare parts.

Please apply these parts when modifying the current fusing unit (with 1 hole for oil supply) to the NEW fusing unit (with 2 holes.)



Technical Bulletin

PAGE: 1/1

Model: AG-P1 Dat				e: 17-Jun-	10	No.: RG178103			
Subject: Separate P/N for the BCU board and NVRAM					d by: N.iid	da			
From: PPBG Ser	vice Planning Dept.								
Classification:	☐ Troubleshooting	⊠ Part info	ormat	tion	☐ Action	required			
	☐ Mechanical	☐ Electric	Electrical Se		Service	ce manual revision			
	☐ Paper path	☐ Transmit/rec		☐ Transmit/receive		eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G1785340 -		PCB:BCU	1→0				
	G 1785300	PCB:BCU:SUB-ASS'Y	0→1	O/O	189	8	
	► 14075856	RAM - FM18L08-70-P	0→1	O/O	189	11	

Change: Parts supply procedure has been changed to supply the BCU board and the NVRAM separately.

Reason: NVRAM is not needed in most cases when ordering the BCU board.

Model: AG-P1/C1, AGL-P1/C1 Dat				e: 23-Jun-	·10	No.: RG178104						
Subject: The modified developer unit				Prepared	d by: N.iid	da						
From: PPBG Service Planning Dept.												
Classification:	Troubleshooting	□ Part info	ormat	tion	Action	n required						
		☐ Electric	☐ Electrical		☐ Service	ce manual revision						
	☐ Paper path	☐ Transmit/rec		☐ Transmit/recei		☐ Transmit		☐ Transmit		eive	Retroi	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2							

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
D0163100	D0163101	DEVELOPMENT UNIT:Y:ASS'Y	1	O/O	89	*	
D0163102	D0163103	DEVELOPMENT UNIT:C:ASS'Y	1	O/O	89	*	
D0163104	D0163105	DEVELOPMENT UNIT:M:ASS'Y	1	O/O	89	*	
D0163106	D0163107	DEVELOPMENT UNIT:BK:ASS'Y	1	O/O	89	*	


Change: Design modification in the contact areas between the bearings and the augers inside the developer unit

Reason: To prevent firefly spots originating from toner clumps. The modified development unit is designed to reduce the chances of toner leakage into the bearing which generates the toner clumps.

Modification Details


Modifications as mentioned below have been implemented in the 3 locations A, B, & C, to reduce the amount of toner leakage into the bearings.

- 1. Narrow pitch fins have been added to the tip of the augers in order to circulate the toner away from the bearings.
- 2. Partitions have been added to maximize the function of the added narrow pitch fins.
- 3. Slanted partitions have been added to prevent toner from directly contacting the bearings.



PAGE: 2/2

Model: AG-P1/C1, AGL-P1/C1 Date: 23-Jun-10 No.: RG178104




Model: AG-P1/C1, AGL-P1/C1			Date: 23-Jun-10		-10	No.: RG178105
Subject: Modified manufacturing process for the Drums					d by: N.iid	da
From: PPBG Service Planning Dept.						
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	□ Part info □ Electric □ Transm □ Other (al		Service	n required be manual revision fit information

ľ	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G1789510	D0169510	PHOTOCONDUCTOR:DIA100	4	0/0	87	11	

Change: The manufacturing process of the Aluminum Drum Shell has been modified.

Reason: The above modification has been implemented to prevent uneven density (bandings) originating from inaccurate circularity of the drums. The new process has improved the circularity of the drums, providing the new drums with higher accuracy in the external diameter deviation; improvement in its tolerance specification from the previous 35 μ m to the current 26 μ m.




Please replace with the modified "D0169510" drums when encountering <u>80mm pitch</u> <u>bandings</u> as shown on the following page.

PAGE: 2/2


Model: AG-P1/C1, AGL-P1/C1 Date: 23-Jun-10 No.: RG178105

The drums produced in the previous manufacturing process tend to deform in a square shape as shown below causing the uneven density (or bandings) to occur at approximately 80mm intervals. This distance corresponds to a quarter of the drum circumference of 314mm; diameter of 100mm. Because the circularity is not distorted to form a perfect square, the interval of the uneven density (or bandings) ranges between 60-100mm.



How to check for bandings

Bandings are difficult to identify in a single color output. Use two different colors and make a solid print on A3/DLT to check for bandings.



14			
U		,	П

PAGE: 1/1

Model: AG-P1 Creo	Date: 11-Jun-10	No.: RG178102
-------------------	-----------------	---------------

Subject: Firmware Release Note: v1.0 System EXP				Prepared by: S.Ishibashi		
From: PPBG QA/Service Planning Dept.						
Classification:	Troubleshooting	☐ Part informat	tion	Action required		
		Electrical		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☐ Tier 2		

This RTB has been issued to announce the firmware release information for the ${\bf v1.0}$ System EXP.

Version	Program No.	Effective Date
1.0	M0437550	1st Mass production

Version	Modified Points or Symptom Corrected
1.0	1st Mass production

Technical Bulletin

PAGE: 1/5

Reissued: 13-Sep-10

Model: AG-P1 Date				ate: 6-July-10		No.: RG178106a
Subject: Upgrad 80	ling to SP1: Creo Color C	Prepared	d by: S.Is	shibashi		
From: PPBG/Ser	vice Plannning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

Upgrading to SP1: Creo Color Controller C-80

The following information and equipment will be sent to you from Gree Region Company:

Part number - M0436800

Note: The part number is temporary.

The part cannot be ordered because it will not be registered as a service part. The part will be provided free of charge for all MIF.

Color Controller C-80 SP1 UPGRADE S/W KIT:

- DVD #3 Documents (with Multi Languages Release Note)
- DVD #4 SP1 software
- Release Note (English)

Target:

- C-80 of all MIF
- New installation

When to perform the upgrade to SP1:

- Please perform the upgrade to SP1 on your next PM visit for the Aegis.

 Visit to the customer site purposed for the upgrade to SP1 is NOT required.
- New installation

Procedure:

Check the current program:

Open Color Controller C-80 application Workspace. From the **Help** menu, select **About**.



PAGE: 2/5

Reissued: 13-Sep-10

Model: **AG-P1** Date: 6-July-10 No.: RG178106a



If "SP1" is displayed, upgrade to SP1 is unnecessary.

Installation steps: (Takes about 20 minutes)

- 1. Exit the Color Controller C-80 application.
- 2. Insert the SP1 DVD (DVD#4) into the DVD drive.
- 3. Browse the DVD media and double click **setup.exe**.






PAGE: 3/5

Reissued: 13-Sep-10

Model: AG-P1 Date: 6-July-10 No.: RG178106a

4. Click Yes.



5. Click OK.



6. Click Yes.






PAGE: 4/5

Reissued: 13-Sep-10

Model: AG-P1 Date: 6-July-10 No.: RG178106a

7. Select **Yes**, I want to restart my computer now.



- 8. Click **Finish**. Color Controller C-80 automatically restarts.
- 9. Once the Color Controller C-80 application Workspace opens, from the **Help** menu, select **About** and verify that SP1 is installed.



Change the printer driver on the client PC.
 Remove the printer driver from the client PC and re-install it using the instructions on page 15 of the user guide.

After Installation:

Replace the current Disk #3 with the new Disk #3 and Disk #4 from the upgrade kit, and store in the Color Controller C-80 DVD case.

Reissued: 13-Sep-10

Technical Bulletin

PAGE: 5/5

Model: AG-P1 Date: 6-July-10 No.: RG178106a

New features: (Please refer to Ricoh_SP1_Release_Notes.

- Windows7 support
- 2. Mac OS X 10.6 support

Note:

- 1. Rosetta must be installed and running on Mac OS X 10.6.
- 2. On Mac OS X 10.6 64-bit, you must run 64-bit applications in 32-bit mode.
- Full Bleed support

Functionality:

Make settings on SP-2-111-001, 002, 003, 004:

Margin setting (Trim setting#) 2111: Erase Margin Adj

- -001 Leading Edge $[4.0] \rightarrow [0]$
- -002 Trailing Edge $[2.5] \rightarrow [0]$
- -003 Front Side $[2.0] \rightarrow [0]$
- -004 Rear Side $[2.0] \rightarrow [0]$

Specifying "Full bleed printing" will allow the CCS to print the page in full size of the selected page size.

If "Full bleed printing" is not specified, the CCS will print the page with a 200 pixel margin on all sides.

Limitations:

"Fit to output sheet size" option will not work together with "Full bleed printing" option.

This is a system constraint.

If SP-2-111 is not adjusted for full bleed printing, the printer will cut off the output at midway even when the CCS is specified for full bleed printing.

- 4. Bonjour support
- Honor duplex tray yes/no from printer 5.
- Printing from Planet Press

Using the Planet Press PPD

Creo Color Server Update Tool (Auto Upd) support 7. Please refer to Server Update Utility.pdf.

Note:

Creo Color Server Update Tool does not support the Proxy with authentication.

Classification:

Marks

Model: AG-P1 / C1

Technical Bulletin

	Date: 14-Ju	I-10	No.: RG178107			
or Roller	Prepar	ed by: Hird	oaki Matsui			
☐ Part info	ormation	Action	required			
☐ Electric	al	☐ Service manual revision				
☐ Transm	it/receive	□ Retro				

X Tier 2


PAGE: 1/12

SYMPTOM

Depending on the print pattern, either of the roller marks shown below could appear when making booklets on the BK5000.

Other (

)




Subject: BK5000 Modified Exit/Driven Rollers for Roller

☐ Troubleshooting

☐ Paper path

☐ Product Safety

From: PPBG QA/Service Planning Dept.




CAUSE

The previous Exit Rollers with large ribs causes excessive pressure against the sheets.

SOLUTION

Paper Exit Rollers and Driven Rollers have been modified as described below.



Technical Bulletin

PAGE: 2/12

Date: 14-Jul-10 Model: AG-P1 / C1 No.: RG178107

Replacement Procedures: Stapler Tray Exit Rollers & Driven Rollers


The modified parts are as follows: B8369501: DRIVEN ROLLER x1


B8369502: BUSHING x2

B8369503: EXIT ROLLER:STAPLER TRAY x1









PAGE: 3/12

Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

Step1. Replacing the Driven Rollers


Step1-1. Open the front door, and remove the inner cover. (Screw x2)



Tapping screws; 3x8

Inner cover


Step1-2. Remove the "Guide Plate: Lower: Open and Close". Remove the Retaining Ring.



PAGE: 4/12

Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

Step1-3. Face the unit from the upstream side, and remove the two springs.



Step1-4. Pull out the booklet stapler unit.




Booklet Stapler Unit


PAGE: 5/12

Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

Step1-5. Remove the Guide Plate while pulling up the Positioning Roller.



Step1-6. Remove the Driven Rollers and the two Springs from the guide plate.



Step 1-7. Slide in the Booklet Stapler Unit back to its normal position.



Model: AG-P1 / C1

Technical Bulletin

Date: 14-Jul-10

PAGE: 6/12


No.: RG178107

Step 1-8. Install the new Driven Rollers on the guide plate.



Driven Rollers

Step 1-9. Slide the Rollers in the direction of the arrow, and install the Bushing as shown in the photo below.



Step 1-10. Lift up the end of the Driven Rollers, and install the other Bushing as shown in the photo below.

Lift up and tilt the Driven Rollers





Model: AG-P1 / C1

Technical Bulletin

Date: 14-Jul-10 No.: RG178107

PAGE: 7/12

Step 1-11. Attach the two Springs removed in "Step1-6"...



Spring x2

PAGE: 8/12


Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

Step 2. Removing the Exit Rollers

Step 2-1. Remove the Rear Cover.



Step2-2. Loosen the Belt Tensioner.




(3) Tighten the screw while the pressure is released.

Model: AG-P1 / C1


 Ulletin
 PAGE: 9/12

 Date: 14-Jul-10
 No.: RG178107

Step2-3. Remove the Pulley and the Bushing.



Step2-4. Remove the Retaining Ring and the Bushing.



Retaining Ring / Bushing

Model: AG-P1 / C1

Technical Bulletin

Date: 14-Jul-10 No.: RG178107

PAGE: 10/12

Step2-5. Pull out the Booklet Stapler Unit, and remove the Exit Rollers.



Booklet Stapler Unit



Remove the Exit Rollers by pulling it out horizontally, and then vertically.

PAGE: 11/12

Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

Step 3. Installation of the New Parts and Put-back Procedures

Step 3-1. Install the new Exit Rollers and the Guide Plate installed with the new Driven Rollers.

- 1. Exit Rollers: Follow the steps "Step2-3" to "Step2-5" in reverse order.
- 2. Guide Plate: Follow "Step1-5" in reverse order.

Step 3-2. Reattach the removed parts.

- 1. Inner-cover, Retaining Ring, Springs: Follow the steps "Step1-1" to "Step1-3" in reverse order.
- 2. Set the Tensioner in its original position.






- (1) Loosen this screw.
- (3) Tighten the screw while the pressure is applied.
- (2) Check that the Tensioner is pulled by the spring and pressure is applied to the Belt.
- 3. Attach the Rear Cover.

Model: AG-P1 / C1 Date: 14-Jul-10 No.: RG178107

IMPORTANT Side Effect 1




Incomplete Feed-out of Trailing Edge

PAGE: 12/12

The reduction of curl adjustment at the paper exit could cause the sheet to remain incompletely fed – the trailing edge stays in the Exit Roller area, which could result in incorrect folding positions or jams caused by collision with the succeeding sheet.

Side Effect 2



Curls Generated in Leading Edge

As the sheets are fed out with the curls less-adjusted, the leading edge is curled immediately after having been fed out from the exit rollers, which could result in jams. Rate of jam occurrence rises especially when feeding "thin and/or curled" sheets.

Technical Bulletin

PAGE: 1/1

Model: AG-P1			Dat	e: 14-Jul-1	10	No.: RG178108
Subject: Stacker	Max Capacity Adj for Jam Pre	vention		Prepared	d by: Hiro	aki Matsui
From: PPBG Ser	vice Planning Dept.					
Classification:		☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	⊠ Tier 2	

GENRAL

Maximum stacking capacity of the SK5000 can be adjusted to prevent or reduce the chances of jams caused by the following reasons:

- 1. Curled sheets (Curls cannot be removed completely by the De-curl unit.)
- 2. Lump(s) formed in the stacked sheets (as in the photo below) caused by a particular area of the image containing high toner density



ADJUSTMENT PROCEDURE

User Tools >> Adjustment Settings for Skilled Operators >> Login >> 6770-001

Select from the options below.

- 0 100% (Default)
- 1 75%
- 2 50%
- 3 25%

NOTE: The above setting will apply to both stackers if two stackers are installed.

Technical Bulletin

PAGE: 1/28

Model: AG-P1/0	C1	Dat	Date: 30-Jul-10		No.: RG178109	
Subject: LDU fiel	d modification for Aegis		Prepared	d by: N.iid	da	
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	☐ Part informa		tion		required
		☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Background

A defect of a different kind has been found in the modified LDUs (Laser Diode Units) previously supplied to resolve the LDU defect described in RTB RG178094a.

This RTB has been issued to announce the problem and solution for the newly identified LDU defect.


SYMPTOM

Occurrences of SC Codes such as SC240, 241, 242, 243 caused by LD (Laser Diode) error.

CAUSE


1. LDU Issue Type1

SC Codes occur due to a loss in power of the laser, which is caused by a filming that occurs inside the LED when the laser hits the residual chemical substances, which are formed when condensation builds up in the process of manufacturing the LDA (Laser Diode Arrays), causing a chemical reaction. (This LDU defect has been announced to the field in RTB RG178094a.)



2. LDU Issue Type2

Machines of a particular lot have been identified with defect in the laser diode arrays in which the laser is not emitted due to a partially "darkened area" caused by a false production process. (This is the newly identified LDU defect.)





PAGE: 2/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

SOLUTION

On your next service visit, please replace all four LDUs for the affected units of the serial numbers described on the following pages.

Although the standard procedure follows a replacement of the entire Laser Unit, to enable replacements of only the LDUs instead of the entire unit for this field rework, a special adjustment has been applied to the LDUs and are assigned with the following P/N:

Part Number	Description	Note
D0169901	MODIFICATION: LD UNIT: MK	2 pcs required
D0169902	MODIFICATION: LD UNIT: YC	2 pcs required

In addition to the units described above, the following units which were not considered defective in "LDU Issue Type 1" must also be replaced.

Part Number	Description	Note
G1789908	MODIFICATION: LDU: MK	2 pcs required
G1789909	MODIFICATION: LDU: YC	2 pcs required




PAGE: 3/28


Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Please be notified that a total of four LDUs will be required for each laser unit; two MK LDU and two YC LDU. (The LDUs are described as "MK" and "YC", but does NOT mean one "MK" LDU will cover both magenta and black.)

LDUs to be installed in the Laser Unit are as shown in diagram below.



"ST1" and "ST2" indicate the installing position in the Laser Unit.






PAGE: 4/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

If the Imaging Unit has been previously replaced to resolve SC error problems, check the serial number of the Imaging Unit by referring to the photos below. LDU replacement is required if the serial number of the Imaging Unit is included in the serial numbers of the affected units. If not, the Imaging Unit is applicable and does not require replacement of the LDU.

Checking the Serial Number of the Imaging Unit



Affected Imaging Units (standard service parts)

- K00SF0030002 ~ K00SF0030022
- K00SF0040001 ~ K00SF0040040
- K00SF0050001 ~ K00SF0050006

Example: If the Imaging Unit (of the left hand side; a normal service part) had been previously replaced to resolve SC242 (LD error: M), the serial number of the Imaging Unit is to be checked.

For instance, if the serial number is K00SF0030010, four LDUs of both left and right sides are to be replaced because this serial number comes under the affected units.

However, for instance, if the serial number is K00SF0040045, two LDUs of only the right side are to be replaced because this serial number does not come under the affected units.



PAGE: 5/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Serial Number of the Affected Units

Asia: Affected units of "LDU Issue Type 1" are the 5 units described in the list below.

Affected units of "LDU Issue Type 2" have been resolved in advance.

Aegis having the LDU Issue

Total Number of Affected Units in Asia: 5

10101	110111001 017	lootod Offito III / Ele				
			Left side I	Laser Unit	Right side	Laser Unit
_			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU
No.	Machines' name	Machine's serial number	YM_LDU(ST1) _SerialNO	YM_LDU(ST2) _SerialNO	CK_LDU(ST1) _SerialNO	CK_LDU(ST2) _SerialNO
1	Pro C900	S3281100005	61080700368	61080700361	61080700367	61080700360
2	Pro C900	S3281100006	61080700351	61080700350	61080700349	61080700348
3	Pro C900	S3281100007	61080700190	61080700191	61080700295	61080700280
4	Pro C900	S3281100008	61080700265	61080700264	61080700272	61080700270
5	Pro C900	S3281100009	61080700269	61080700268	61080700256	61080700255



PAGE: 6/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

EU: Affected units of "LDU Issue Type 1" are the 97 units described in the list below. No affected units for "LDU Issue Type 2".

Aegis having the LDU Issue

Total Number of Affected Units in EU: 97

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and

do NOT require replacement.

			Left side I	_aser Unit	Right side	Laser Unit	
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
	Machines'	RPL Machine's	YM_LDU(ST1)	YM_LDU(ST2)	CK_LDU(ST1)	CK_LDU(ST2)	
No.	name	serial number	_SerialNO	SerialNO	_SerialNO	_SerialNO	
	Hairie	Serial Humber	_SerialivO	_SeriaiNO	_SerialivO	_SerialivO	
1	Pro C900S	M8780900005	61080600127	61080600118	61080600091	61080600122	
2	Pro C900S	M8780900006	61080600129	61080600126	61080600099	61080600116	
	Pro C900S	M8780900007	61080600084	61080600083	61080600269	61080700011	
	Pro C900S	M8780900008	61080700018	61080700027	61080700009	61080600485	
	Pro C900	S3280800042	61080600160	61080600159	61080600135	61080600161	
	Pro C900	S3280800043	61080600246	61080600285	61080600239	61080600206	
7	Pro C900	S3280800044	61080600336	61080600335	61080600180	61080600337	
	Pro C900	S3280800045	61080600235	61080600249	61080600245	61080600306	
9	Pro C900	S3280800046	61080600256	61080600217	61080600210	61080600216	
10	Pro C900	S3280800047	61080600314	61080600313	61080600315	61080600324	
11	Pro C900	S3280800048	61080600339	61080600316	61080600321	61080600185	
	Pro C900	S3280800049	61080600154	61080600184	61080600156	61080600155	
	Pro C900	S3280800050	61080600252	61080600213	61080600251	61080600214	
14	Pro C900	S3280900001	61080600279	61080600055	61080600276	61080600230	
15	Pro C900	S3280900002	61080500453	61080500456	61080500461	61080500443	
16	Pro C900	S3280900003	61080500444	61080500459	61080500460	61080500447	
	Pro C900	S3280900004	61080500455	61080500450	61080500438	61080500458	
18	Pro C900	S3280900005	61080500469	61080500467	61080500422	61080500451	
19	Pro C900	S3280900006	61080500465	61080500466	61080500446	61080500454	
20	Pro C900	S3280900007	61080500484	61080500483	61080500432	61080500457	
21	Pro C900	S3280900008	61080500429	61080500423	61080500433	61080500425	
22	Pro C900	S3280900009	61080500424	61080500442	61080500464	61080500463	
23	Pro C900	S3280900010	61080500476	61080500462	61080500478	61080500468	
24	Pro C900	S3280900011	61080500394	61080500390	61080500396	61080600003	
25	Pro C900	S3280900012	61080500405	61080500372	61080600007	61080600005	
26	Pro C900	S3280900013	61080600009	61080600004	61080600221	61080600222	
27	Pro C900	S3280900014	61080600002	61080600006	61080500384	61080600218	
28	Pro C900	S3280900015	61080500385	61080500373	61080500386	61080600219	
	Pro C900	S3281000105	61080500365	61080600220	61080500383	61080500371	
	Pro C900	S3281000106	61080500475	61080500485	61080500477	61080500470	
	Pro C900	S3281000107	61080500479	61080500445	61080500448	61080500441	
	Pro C900	S3281000108	61080500452	61080500439	61080600106	61080600085	
	Pro C900	S3281000109	61080500440	61080500449	61080600107	61080600128	
	Pro C900	S3281000110	61080600236	61080600302	61080600296	61080600291	
	Pro C900	S3281000111	61080600272	61080600274	61080600205	61080600275	
	Pro C900	S3281000112	61080600120	61080600087	61080600082	61080600125	
	Pro C900	S3281000113	61080600086	61080600124	61080600094	61080600092	
	Pro C900	S3281000114	61080600119	61080600123	61080600090	61080600108	
	Pro C900	S3281000115	61080700013	61080600333	61080700010	61080600036	
40	Pro C900	S3281000116	61080600034	61080600466	61080600041	61080600484	
41	Pro C900	S3281000117	61080600288	61080600289	61080600035	61080600049	
	Pro C900	S3281000118	61080600044	61080600298	61080600297	61080600027	
	Pro C900	S3281000119	61080600038	61080600047	61080600022	61080600048	
	Pro C900	S3281000120	61080600040	61080600293	61080600227	61080600226	
45	Pro C900	S3281000121	61080600303	61080600292	61080600284	61080600305	



97 Pro C900

S3292900008

Model: AG-P1 / C1

Technical Bulletin

PAGE: 7/28 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in EU: 97

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and

do NOT require replacement. Left side Laser Unit Right side Laser Unit Magenta LDU Yellow LDU Black LDU Cyan LDU RPL Machine's YM LDU(ST1) YM_LDU(ST2) CK_LDU(ST1) CK_LDU(ST2) Machines' No. name serial number SerialNO SerialNO SerialNO SerialNO 46 Pro C900 S3281000122 47 Pro C900 S3281000123 48 Pro C900 S3281000124 49 Pro C900 S3281000125 50 Pro C900 S3281000126 51 Pro C900 S3281000127 52 Pro C900 S3281000128 53 Pro C900 S3281000129 54 Pro C900 S3281000130 55 Pro C900 S3281000131 56 Pro C900 S3281000132 57 Pro C900 S3281000133 58 Pro C900 S3281000134 59 Pro C900 S3281000135 60 Pro C900 S3281000136 61 Pro C900 S3281000137 62 Pro C900 S3281000138 63 Pro C900 S3281000139 64 Pro C900 S3281000140 65 Pro C900 S3281000141 66 Pro C900 S3281000142 67 Pro C900 S3281000143 68 Pro C900 S3292500021 69 Pro C900 S3292500005 70 Pro C900 S3292500012 71 Pro C900 S3292500009 Pro C900S M8792600008 73 Pro C900 S3292500016 74 Pro C900 S3292500010 75 Pro C900 S3292500011 76 Pro C900 S3292500015 77 Pro C900 S3292500014 78 Pro C900 S3292500007 79 Pro C900 S3292500033 80 Pro C900 S3292500018 81 Pro C900S M8792600003 82 Pro C900 S3292600001 83 Pro C900S M8792600004 84 Pro C900 S3292600007 85 Pro C900S M8792600005 86 Pro C900S M8792800019 Pro C900S M8792800012 88 Pro C900S M8792600006 89 Pro C900 S3292500034 90 Pro C900 S3292500031 Pro C900S M8792600007 92 Pro C900 S3292500017 93 Pro C900 S3292500013 94 Pro C900S M8792600002 95 Pro C900 S3292900003 96 Pro C900 S3292500019



PAGE: 8/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

NA: Affected units of "LDU Issue Type 1" are the 185 units described in the list below from #1 \sim #185.

Affected units of "LDU Issue Type 2" are the 79 units described in the list below from $\#186 \sim \#264$.

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

do NOT require replacement.		Left side		Right side			
			Magenta LDU Yellow LDU		Black LDU		
		REI Machine's	YM LDU(ST1)	YM LDU(ST2)	CK LDU(ST1)	CK LDU(ST2)	
No.	Machines' name	serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO	
1	Pro C900S	M8780900001	61080600398	61080600392	61080600399	61080600497	
2	Pro C900S	M8780900001	61080600460	61080600456	61080600452	61080600459	
3	Pro C900S	M8780900003	61080700022	61080700024	61080600493	61080600449	
4	Pro C900S	M8780900004	61080600453	61080600479	61080600418	61080600417	
5	Pro C900	S3280700002	61080400243	61080400240	61080400227	61080400226	
6	Pro C900	S3280700002	61080400224	61080400223	61080400237	61080400233	
7	Pro C900	S3280700004	61080400241	61080400244	61080400242	61080400230	
8	Pro C900	S3280700005	61080400232	61080400234	61080400231	61080400245	
9	Pro C900	S3280700005	61080400236	61080500275	61080500273	61080500274	
10	Pro C900	S3280700007	61080500210	61080500217	61080500218	61080500214	
11	Pro C900	S3280700007	61080500210	61080500277	61080500214	61080500216	
12	Pro C900	S3280700008	61080500211	61080500272	61080500214	61080500215	
13	Pro C900	S3280700009	61080500215	61080500237	61080500227	61080500213	
14	Pro C900	S3280700011	61080500225	61080500223	61080500234	61080500206	
15	Pro C900	S3280700011	61080500238	61080500304	61080500303	61080500329	
16	Pro C900	S3280700012	61080500302	61080500332	61080500321	61080500323	
17	Pro C900	S3280700013	61080500302	61080500308	61080500323	61080500301	
18	Pro C900	S3280700014	61080500307	61080500338	61080500342	61080500341	
19	Pro C900	S3280700015	61080500311	61080500331	61080500342	61080500341	
20	Pro C900	S3280700017	61080500328	61080500331	61080500327	61080500351	
21	Pro C900	S3280700017	61080500359	61080500360	61080500357	61080500355	
22	Pro C900	S3280700019	61080500354	61080500349	61080500356	61080500338	
23	Pro C900	S3280700010	61080500353	61080500352	61080500350	61080500319	
24	Pro C900	S3280700021	61080500314	61080500313	61080500316	61080500318	
25	Pro C900	S3280700022	61080500324	61080500320	61080500309	61080500315	
26	Pro C900	S3280700023	61080500317	61080500310	61080500322	61080500187	
27	Pro C900	S3280700046	61080500195	61080500201	61080500199	61080500194	
28	Pro C900	S3280700047	61080500088	61080500196	61080500189	61080500190	
29	Pro C900	S3280700048	61080500193	61080500198	61080500188	61080500197	
30	Pro C900	S3280700049	61080500100	61080500120	61080500116	61080500185	
31	Pro C900	S3280700050	61080500119	61080500101	61080500099	61080500200	
32	Pro C900	S3280700051	61080500097	61080500118	61080500117	61080500202	
33	Pro C900	S3280700052	61080500209	61080500230	61080500208	61080500253	
34	Pro C900	S3280800001	61080600203	61080600080	61080600224	61080600069	
35	Pro C900	S3280800002	61080600260	61080600281	61080600261	61080600262	
36	Pro C900	S3280800003	61080600208	61080600068	61080600225	61080600076	
37	Pro C900	S3280800004	61080600207	61080600234	61080600209	61080600066	
38	Pro C900	S3280800005	61080600026	61080600259	61080600015	61080600016	
39	Pro C900	S3280800006	61080600032	61080600017	61080600031	61080600011	
40	Pro C900	S3281000001	61080600454	61080600465	61080600455	61080600451	
41	Pro C900	S3281000002	61080600464	61080600450	61080600494	61080600491	
42	Pro C900	S3281000003	61080600480	61080600481	61080600448	61080600490	
43	Pro C900	S3281000004	61080600395	61080600420	61080600421	61080600404	
44	Pro C900	S3281000005	61080600413	61080600410	61080600443	61080600441	
45	Pro C900	S3281000006	61080600442	61080600407	61080600467	61080600357	



PAGE: 9/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

	do 140 i require i	replacement.	. l off	side	Right	side	1
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	1
			Magerila LDO	I CIOW LDO	DIACK LDO	Cyan LDO	
No.	Machines' name	REI Machine's	YM_LDU(ST1)	YM_LDU(ST2)	CK_LDU(ST1)	CK_LDU(ST2)	
INU.	Machines hame	serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO	
46	Pro C900	S3281000007	61080700006	61080700004	61080600411	61080700003	
47	Pro C900	S3281000007	61080600353	61080700004	61080600366	61080600364	
		S3281000009	61080600498	61080700008	61080700033	61080700032	
49 50	Pro C900	S3281000010	61080600349	61080600350	61080700005	61080700002	
	Pro C900	S3281000011	61080600384	61080600406	61080600385	61080600386	
51	Pro C900	S3281000012	61080600402	61080600389	61080600409	61080600414	
52	Pro C900	S3281000013	61080600354	61080600348	61080600351	61080600352	
53	Pro C900	S3281000014	61080600430	61080600446	61080600437	61080600444	
54	Pro C900	S3281000015	61080600432	61080600367	61080600447	61080600445	
55	Pro C900	S3281000016	61080600361	61080600359	61080600439	61080600376	
56	Pro C900	S3281000017	61080600378	61080600431	61080600379	61080600435	
57	Pro C900	S3281000018	61080600436	61080600363	61080600463	61080600461	
58	Pro C900	S3281000019	61080600434	61080600380	61080700046	61080700073	
	Pro C900	S3281000020	61080700066	61080700075	61080700298	61080700053	
	Pro C900	S3281000021	61080700068	61080700074	61080700052	61080700047	
	Pro C900	S3281000022	61080700115	61080700109	61080700101	61080700116	
62	Pro C900	S3281000023	61080700100	61080700102	61080700017	61080700016	
63	Pro C900	S3281000024	61080700019	61080700028	61080700015	61080700035	
64	Pro C900	S3281000025	61080700022	61080700271	61080700021	61080700023	
65	Pro C900	S3281000026	61080700150	61080700149	61080700147	61080700145	
	Pro C900	S3281000027	61080700110	61080700148	61080700146	61080700111	
67	Pro C900	S3281000028	61080600046	61080600412	61080600043	61080600405	
	Pro C900	S3281000029	61080600487	61080600403	61080600500	61080600476	
	Pro C900	S3281000030	61080700104	61080700105	61080700098	61080700099	
	Pro C900	S3281000031	61080700106	61080700100	61080700107	61080700101	
	Pro C900	S3281000032	61080700108	61080700102	61080700071	61080700049	
72	Pro C900	S3281000033	61080700026	61080700020	61080700109	61080700103	
73	Pro C900	S3281000034	61080700092	61080700093	61080700094	61080700095	
74	Pro C900	S3281000035	61080700086	61080700087	61080700088	61080700089	
	Pro C900	S3281000036	61080700096	61080700097	61080700090	61080700091	
76	Pro C900	S3281000037	61080700080	61080700081	61080700082	61080700083	
77	Pro C900	S3281000038	61080700074	61080700075	61080700076	61080700077	
78	Pro C900	S3281000039	61080700084	61080700085	61080700078	61080700079	
	Pro C900	S3281000040	61080700140	61080700141	61080700134	61080700135	
80	Pro C900	S3281000041	61080700142	61080700136	61080700143	61080700137	
	Pro C900	S3281000042	61080700144	61080700145	61080700128	61080700129	
82	Pro C900	S3281000043	61080700123	61080700124	61080700138	61080700139	
83	Pro C900	S3281000044	61080700130	61080700122	61080700267	61080700268	
84	Pro C900	S3281000045	61080700125	61080700131	61080700126	61080700132	
85	Pro C900	S3281000046	61080700127	61080700133	61080700110	61080700116	
86	Pro C900	S3281000047	61080700111	61080700117	61080700118	61080700112	
87	Pro C900	S3281000048	61080700119	61080700113	61080700114	61080700120	
88	Pro C900	S3281000049	61080700115	61080700121	61080700062	61080700068	
	Pro C900	S3281000050	61080700063	61080700069	61080700064	61080700070	
90	Pro C900	S3281000051	61080700066	61080700072	61080700067	61080700073	
91	Pro C900	S3281000052	61080700049	61080700057	61080700052	61080700058	
92	Pro C900	S3281000053	61080700048	61080700056	61080700054	61080700060	
93	Pro C900	S3281000054	61080700055	61080700061	61080700007	61080700042	
	Pro C900	S3281000055	61080700041	61080700043	61080600023	61080700044	
	Pro C900	S3281000056	61080700045	61080700038	61080700046	61080700039	



PAGE: 10/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

No. Machines' name				Left	side	Right	side
No. Machines' name				Magenta LDU	Yellow LDU	Black LDU	Cyan LDU
Serial Number	Vo.	Machines' name		_ ` ` '	_ ` ` ′	_ ` '	CK_LDU(ST2)
97 Pro C900			serial number	_SerialNO	_SerialNO	_SerialNO	_SerialNO
Pro C900	96	Pro C900	S3281000057	61080700053	61080700059	61080700212	61080700213
Pro C900	97		S3281000058	61080700206	61080700207	61080700214	61080700208
100 Pro C900	98	Pro C900	S3281000059	61080700215	61080700209	61080700216	61080700217
101 Pro C900	99	Pro C900	S3281000060	61080700210	61080700211	61080700047	61080700040
102 Pro C900	100	Pro C900	S3281000061	61080700065	61080700071	61080700200	61080700194
103 Pro C900	101	Pro C900	S3281000062	61080700201	61080700195	61080700202	61080700196
104 Pro C900	102	Pro C900	S3281000063	61080700203	61080700197	61080700204	61080700205
105 Pro C900	103	Pro C900	S3281000064	61080700198	61080700199	61080700188	61080700189
106 Pro C900	104	Pro C900	S3281000065	61080700184	61080700185	61080700192	61080700193
107 Pro C900	105	Pro C900	S3281000066	61080700186	61080700187	61080700176	61080700177
108 Pro C900	106	Pro C900	S3281000067	61080700170	61080700171	61080700178	61080700179
109 Pro C900 S3281000070 61080700166 61080700167 61080700160 61080700161 110 Pro C900 S3281000071 61080700168 61080700169 61080700162 610807001 111 Pro C900 S3281000072 61080700152 61080700146 61080700144 61080700147 61080700147 61080700147 61080700147 61080700147 61080700147 61080700147 61080700147 61080700147 61080700149 61080700149 61080700149 61080700149 61080700149 61080700149 61080700149 61080700149 61080700149 61080700149 61080700151 61080700156 61080700157 61080700149 61080700151 61080600424 61080600426 61080700151 6108060031 6108060033 61080600424 61080600338 61080600433 6108060033 6108060033 61080600338 61080600337 61080600337 61080600337 61080600337 61080600337 61080600337 61080600337 61080600337 61080600337 61080600334 61080700226 61080700226 6108070022 61080700226 6108070022	107	Pro C900	S3281000068	61080700172		61080700180	61080700181
110 Pro C900 \$3281000071 \$61080700168 \$61080700169 \$61080700162 \$61080700161 111 Pro C900 \$3281000072 \$61080700152 \$61080700146 \$61080700164 \$61080700164 \$61080700164 \$61080700164 \$61080700164 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700149	108	Pro C900	S3281000069	61080700174	61080700175	61080700158	61080700159
111 Pro C900 S3281000072 61080700152 61080700146 61080700164 610807001 112 Pro C900 S3281000073 61080700153 61080700148 61080700147 610807001 113 Pro C900 S3281000074 61080700156 61080700157 61080700149 610807001 114 Pro C900 S3281000075 61080600424 61080600426 61080700151 610806003 115 Pro C900 S3281000076 61080600387 61080600388 61080600433 610806004 116 Pro C900 S3281000077 61080700352 61080700353 61080600397 610806004 117 Pro C900 S3281000078 61080600372 61080600373 610806003 118 Pro C900 S3281000081 61080600375 61080600369 61080600381 610806003 119 Pro C900 S3281000084 61080700234 61080700225 61080700226 610807002 120 Pro C900 S3281000085 61080700225 61080700236 610807002	109	Pro C900	S3281000070	61080700166	61080700167	61080700160	61080700161
112 Pro C900 \$3281000073 \$61080700153 \$61080700148 \$61080700147 \$61080700147 \$61080700147 \$61080700147 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700149 \$61080700151 \$6108060033 \$6108060033 \$6108060033 \$6108060033 \$6108060033 \$6108060033 \$6108060033 \$6108060034 \$61080600372 \$61080600373 \$61080600373 \$6108060033 \$61080600373 \$6108060033 \$61080600373 \$61080600333 \$61080600333 \$61080600333	110	Pro C900	S3281000071	61080700168	61080700169	61080700162	61080700163
113 Pro C900 \$3281000074 \$61080700156 \$61080700157 \$61080700149 \$61080700149 \$61080700149 \$61080700151 \$61080600337 \$61080600426 \$61080700151 \$61080600331 \$61080600426 \$61080700151 \$61080600331 \$61080600433 \$61080600433 \$61080600433 \$61080600433 \$61080600433 \$61080600443 \$61080600397 \$61080600347 \$61080600375 \$61080600372 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$610806003373 \$610806003373 \$610806003373 \$610806003373 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$610807003367 \$610807003367 \$610807003367	111	Pro C900	S3281000072	61080700152	61080700146	61080700164	61080700165
114 Pro C900 \$3281000075 \$61080600424 \$61080600426 \$61080700151 \$610806003 115 Pro C900 \$3281000076 \$61080600387 \$61080600388 \$61080600433 \$610806004 116 Pro C900 \$3281000077 \$61080700352 \$61080700353 \$61080600397 \$6108060034 117 Pro C900 \$3281000078 \$61080600423 \$61080600372 \$61080600373 \$610806003 118 Pro C900 \$3281000079 \$61080600375 \$61080600369 \$61080600381 \$610806003 119 Pro C900 \$3281000080 \$61080700234 \$61080700235 \$61080700226 \$610807002 120 Pro C900 \$3281000081 \$61080700221 \$61080700222 \$61080700236 \$6108070023 121 Pro C900 \$3281000082 \$61080700223 \$61080700357 \$61080700336 \$61080700336 122 Pro C900 \$3281000083 \$61080700223 \$61080700225 \$61080700389 \$61080700336 123 Pro C900 \$3281000086 \$610806003368	112	Pro C900	S3281000073	61080700153	61080700148	61080700147	61080700155
114 Pro C900 S3281000075 61080600424 61080600426 61080700151 610806003 115 Pro C900 S3281000076 61080600387 61080600388 61080600433 610806004 116 Pro C900 S3281000077 61080700352 61080700353 61080600397 610806004 117 Pro C900 S3281000078 61080600423 61080600372 61080600373 610806003 118 Pro C900 S3281000079 61080600375 61080600369 61080600381 610806003 119 Pro C900 S3281000080 61080700234 61080700235 61080700226 610807002 120 Pro C900 S3281000081 61080700221 61080700222 61080700236 610807002 121 Pro C900 S3281000082 61080700235 61080700357 61080700357 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336 61080700336	113	Pro C900	S3281000074	61080700156	61080700157	61080700149	61080700150
116 Pro C900 S3281000077 61080700352 61080700353 61080600397 610806004 117 Pro C900 S3281000078 61080600423 61080600372 61080600373 610806003 118 Pro C900 S3281000079 61080600375 61080600369 61080600381 610806003 119 Pro C900 S3281000080 61080700234 61080700235 61080700226 610807002 120 Pro C900 S3281000081 61080700221 61080700222 61080700236 610807002 121 Pro C900 S3281000082 61080700356 61080700357 61080700336 610807003 122 Pro C900 S3281000083 61080700223 61080700225 61080700389 610807003 123 Pro C900 S3281000084 61081000005 61081000004 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387 61080700387	114	Pro C900			61080600426	61080700151	61080600383
117 Pro C900 \$3281000078 \$61080600423 \$61080600372 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700236 \$61080700226 \$61080700236 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$610807003218 \$610	115	Pro C900	S3281000076	61080600387	61080600388	61080600433	61080600496
117 Pro C900 \$3281000078 \$61080600423 \$61080600372 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600373 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080600381 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700226 \$61080700236 \$61080700226 \$61080700236 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$61080700336 \$610807003218 \$610	116	Pro C900	S3281000077	61080700352	61080700353	61080600397	61080600440
119 Pro C900 \$3281000080 61080700234 61080700235 61080700226 6108070022 120 Pro C900 \$3281000081 61080700221 61080700222 61080700236 6108070023 121 Pro C900 \$3281000082 61080700356 61080700357 61080700336 6108070033 122 Pro C900 \$3281000083 61080700223 61080700225 61080700389 6108070023 123 Pro C900 \$3281000084 61081000005 61081000004 61080700218 610807002 124 Pro C900 \$3281000085 61080600368 61080600371 61080700387 610810000 125 Pro C900 \$3281000086 61080700386 61081000002 61080700385 610810000 126 Pro C900 \$3281000087 61080600117 61080600344 61080600329 610806003 127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000099 61080600334 61080600331 6108			S3281000078	61080600423	61080600372	61080600373	61080600374
120 Pro C900 S3281000081 61080700221 61080700222 61080700236 6108070023 121 Pro C900 S3281000082 61080700356 61080700357 61080700336 6108070033 122 Pro C900 S3281000083 61080700223 61080700225 61080700389 6108070023 123 Pro C900 S3281000084 61081000005 61081000004 61080700218 610807002 124 Pro C900 S3281000085 61080600368 61080600371 61080700387 610810000 125 Pro C900 S3281000086 61080700386 61081000002 61080700385 610810000 126 Pro C900 S3281000087 61080600117 61080600344 61080600329 610806003 127 Pro C900 S3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 S3281000099 61080600334 61080600342 6108070004 6108070004 129 Pro C900 S3281000099 61080700124 61080700120 61080	118	Pro C900	S3281000079	61080600375	61080600369	61080600381	61080600382
121 Pro C900 \$3281000082 61080700356 61080700357 61080700336 6108070033 122 Pro C900 \$3281000083 61080700223 61080700225 61080700389 6108070033 123 Pro C900 \$3281000084 61081000005 61081000004 61080700218 610807002 124 Pro C900 \$3281000085 61080600368 61080600371 61080700387 610810000 125 Pro C900 \$3281000086 61080700386 61081000002 61080700385 610810000 126 Pro C900 \$3281000087 61080600311 61080600344 61080600329 610806003 127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000089 61080600334 61080600342 6108070004 6108070004 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 610807	119	Pro C900	S3281000080	61080700234	61080700235	61080700226	61080700227
122 Pro C900 S3281000083 61080700223 61080700225 61080700389 61080700339 123 Pro C900 S3281000084 61081000005 61081000004 61080700218 610807002 124 Pro C900 S3281000085 61080600368 61080600371 61080700387 610810000 125 Pro C900 S3281000086 61080700386 6108100002 61080700385 610810000 126 Pro C900 S3281000087 61080600117 61080600344 61080600329 610806002 127 Pro C900 S3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 S3281000089 61080600334 61080600342 61080700004 6108070001 129 Pro C900 S3281000090 61080700124 61080700120 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141 61080700141	120	Pro C900	S3281000081	61080700221	61080700222	61080700236	61080700237
122 Pro C900 \$3281000083 \$61080700223 \$61080700225 \$61080700389 \$61080700389 \$61080700389 \$61080700389 \$61080700389 \$61080700389 \$61080700218 \$61080700218 \$61080700218 \$61080700218 \$61080700218 \$61080700218 \$61080700218 \$61080700218 \$610807002218 \$610807002218 \$610807002218 \$610807002218 \$610807002218 \$6108100002 \$61080700387 \$6108100002 \$61080700385 \$6108100002 \$61080700385 \$6108100002 \$61080700385 \$6108100002 \$61080700385 \$6108100002 \$61080700385 \$61080600329 \$61080600329 \$61080600329 \$61080600329 \$61080600329 \$61080600331 \$61080600331 \$61080600331 \$61080600331 \$6108070004 \$6108070004 \$6108070004 \$6108070004 \$6108070004 \$6108070001 \$61080700135 \$6108070014 \$61080700014 \$610807000141 \$61080700141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141 \$610807000141	121	Pro C900	S3281000082	61080700356	61080700357	61080700336	61080700335
124 Pro C900 \$3281000085 \$61080600368 \$61080600371 \$61080700387 \$610810000 125 Pro C900 \$3281000086 \$61080700386 \$61081000002 \$61080700385 \$610810000 126 Pro C900 \$3281000087 \$61080600117 \$61080600344 \$61080600329 \$610806002 127 Pro C900 \$3281000088 \$61080600343 \$61080600331 \$61080600104 \$610806003 128 Pro C900 \$3281000089 \$61080600334 \$61080600342 \$61080700004 \$6108070004 129 Pro C900 \$3281000090 \$61080700124 \$61080700120 \$61080700135 \$6108070014 130 Pro C900 \$3281000091 \$61080700140 \$61080700037 \$61080700141 \$6108070014							61080700388
125 Pro C900 \$3281000086 61080700386 61081000002 61080700385 6108100002 126 Pro C900 \$3281000087 61080600117 61080600344 61080600329 610806002 127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000089 61080600334 61080600342 61080700004 610807000 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 6108070014	123	Pro C900	S3281000084	61081000005	61081000004	61080700218	61080700220
125 Pro C900 \$3281000086 61080700386 61081000002 61080700385 6108100002 126 Pro C900 \$3281000087 61080600117 61080600344 61080600329 610806002 127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000089 61080600334 61080600342 61080700004 610807000 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 6108070014							61081000003
126 Pro C900 \$3281000087 61080600117 61080600344 61080600329 610806002 127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000089 61080600334 61080600342 61080700004 610807000 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 6108070014							61081000001
127 Pro C900 \$3281000088 61080600343 61080600331 61080600104 610806003 128 Pro C900 \$3281000089 61080600334 61080600342 61080700004 6108070000 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 6108070011 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 6108070014							61080600295
128 Pro C900 \$3281000089 61080600334 61080600342 61080700004 6108070000 129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 6108070014	127	Pro C900	S3281000088	61080600343	61080600331	61080600104	61080600345
129 Pro C900 \$3281000090 61080700124 61080700120 61080700135 610807001 130 Pro C900 \$3281000091 61080700140 61080700037 61080700141 610807001							61080700003
130 Pro C900 S3281000091 61080700140 61080700037 61080700141 610807001							61080700118
	130	Pro C900	S3281000091	61080700140	61080700037	61080700141	61080700136
131 Pro C900	131	Pro C900	S3281000092	61080700048	61080700050	61080700285	61080700286
	132						61080700002
							61080700254
							61080700055
			S3281000096	61080700014	61080700119	61080700283	61080700001
							61080700250
							61080700296
							61080700005
							61080700238
							61080700244



PAGE: 11/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

			Left	side	Right	side	1
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	İ
		REI Machine's	YM LDU(ST1)	YM LDU(ST2)	CK LDU(ST1)	CK_LDU(ST2)	
No.	Machines' name	serial number	_SerialNO	SerialNO	SerialNO	SerialNO	
		Serial Humber	_SerialivO	_SelialivO	_SerialivO	_Senano	
141	Pro C900	S3281000102	61080700247	61080700258	61080700273	61080700241	
142	Pro C900	S3281000103	61080700275	61080700260	61080700249	61080700251	
143	Pro C900	S3281000104	61080700269	61080700290	61080700108	61080700107	
144	Pro C900	S3281000178	61080700098	61080700114	61080700117	61080700099	
145	Pro C900	S3281000179	61080600401	61080600396	61080600425	61080600391	
146	Pro C900	S3286000031	61081000019	61081000026	61081000028	61081000021	
147	Pro C900	S3294900016	61080700304	61081000010	61081000020	61081000027	
148	Pro C900	S3294900012	61081000016	61081000009	61081000015	61081000008	
149	Pro C900	S3294900071	61081000007	61081000014	61081000012	61081000013	
150	Pro C900	S3286000034	61080700209	61081000006	61080700344	61080700325	
151	Pro C900	S3286000020	61080700208	61080700346	61080700206	61080700308	
152	Pro C900	S3294900018	61080700309	61080700205	61080700323	61080700326	
153	Pro C900	S3294900015	61080700306	61080700293	61080700324	61080700271	
154	Pro C900	S3294900064	61080700262	61080700235	61081000017	61081000018	
155	Pro C900	S3294900014	61080700328	61081000011	61080700334	61081000034	
156	Pro C900	S3294900061	61080700154	61081000031	61080700319	61080700332	
157	Pro C900	S3286000036	61080700260	61080700342	61080700378	61080700371	
158	Pro C900	S3286000049	61080700095	61080700330	61080700327	61080700292	
159	Pro C900	S3294900068	61080700251	61080700094	61080700093	61080700258	
160	Pro C900	S3294900065	61080700092	61080700253	61080700091	61080700261	
161	Pro C900	S3294900017	61080700090	61080700097	61080700178	61080700096	
162	Pro C900	S3286000039	61080700187	61080700188	61080700186	61080700177	
163	Pro C900	S3286000009	61080700176	61080700185	61080700182	61080700181	
164	Pro C900	S3294900073	61080700174	61080700173	61080700300	61080700175	
165	Pro C900	S3294900056	61080700301	61080700302	61080700252	61080700296	
166	Pro C900	S3286000050	61080700254	61080700303	61080700249	61080700298	
167	Pro C900	S3294900069	61080700250	61080700247	61080700196	61080700201	
168	Pro C900	S3294900070	61080700194	61080700200	61080700199	61080700193	
169	Pro C900	S3294900076	61080700197	61080700198	61080700189	61080700191	
170	Pro C900	S3286000030	61080700245	61080700263	61080700225	61080700231	
171	Pro C900	S3286000035	61080700224	61080700240	61080700204	61080700233	
172	Pro C900	S3294900072	61080700203	61080700232	61080700234	61080700297	
173	Pro C900	S3286000025	61080700202	61080700192	61080700221	61080700294	
174	Pro C900	S3286000029	61080700222	61080700220	61080700278	61080700279	
175	Pro C900	S3286000001	61080700144	61080700275	61080700133	61080700163	
176	Pro C900	S3286000033	61080700282	61080700007	61080700276	61080700277	
177	Pro C900	S3286000032	61080700195	61080700164	61080700218	61080700219	
178	Pro C900	S3286000010	61080700214	61080700215	61080700212	61080700213	
179	Pro C900	S3294900074	61080700210	61080700211	61080700216	61080700217	
180	Pro C900	S3286000015	61080700311	61080700318	61080700286	61080700287	
181	Pro C900	S3286000024	61080700289	61080700288	61080700281	61080700248	
182	Pro C900	S3286000038	61080700283	61080700282	61080700291	61080700290	
183	Pro C900	S3286000042	61080700285	61080700284	61081000190	61081000185	*1
184	Pro C900	S3286000021	61081000038	61081000044	61081000112	61081000113	*1
185	Pro C900S	M8795000001	61081101190	61080700183	61081101119	61081101117	*1
. 00		57 55555551	0.001101100	5 7 5 5 5 7 5 5 7 5 5	5.001101110	5.001101111	н .



PAGE: 12/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

			Left side Right side				
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
		REI Machine's	YM LDU(ST1)	YM LDU(ST2)	CK LDU(ST1)	CK_LDU(ST2)	
No.	Machines' name	serial number	SerialNO	SerialNO	SerialNO	SerialNO	
		Schai Humber	_ochano	_Ochanvo	_ochano	_ochano	
	Pro C900	S3205200001	-	-	-	-	
	Pro C900	S3205200002	-	-	-	-	
		S3205200003	-	-	-	-	
189	Pro C900	S3205200004	-	-	-	-	
190	Pro C900	S3205200005	-	-	-	-	
191	Pro C900	S3205200006	-	-	-	-	
	Pro C900	S3205200007	-	-	-	-	
193	Pro C900	S3205200008	-	-	-	-	
194	Pro C900	S3205200009	-	-	-	-	
	Pro C900	S3205200010	-	-	-	-	
	Pro C900	S3205200011	-	-	-	-	
	Pro C900	S3205200012	-	-	-	-	
	Pro C900	S3205200013	-	-	-	-	
		S3205200014	-	-	-	-	
200	Pro C900	S3205200016	i	-	-	ı	
201	Pro C900	S3205200017	-	-	-	-	
202	Pro C900	S3205200018	ī	-	-	1	
203	Pro C900	S3205200019	-	-	-	-	
204	Pro C900	S3205200020	-	-	-	-	
205	Pro C900	S3205200021	-	-	-	-	
206	Pro C900	S3205200022	-	-	-	-	
207	Pro C900	S3205200023	-	-	-	-	
208	Pro C900	S3205300001	-	-	-	-	
209	Pro C900	S3205300002	-	-	-	-	
210	Pro C900	S3205300003	-	-	-	-	
211	Pro C900	M8705100036	-	-	-	-	
212	Pro C900	M8705100038	-	-	-	-	
213	Pro C900	M8705100039	-	-	-	-	
214	Pro C900	M8705100049	-	-	-	-	
215	Pro C900	M8705100052	-	-	-	-	
216	Pro C900	M8705200001	-	-	-	-	
217	Pro C900	M8705200002	-	-	-	-	
218	Pro C900	M8705200003	-	-	-	-	
219	Pro C900	M8705200004	-	-	-	-	
220	Pro C900	M8705200005	-	-	-	-	
221	Pro C900	M8705200006	-	-	-	-	
222	Pro C900	M8705200007	-	-	-	-	
223	Pro C900	M8705200008	-	-	-	-	
224	Pro C900	M8705200009	-	-	-	-	
225	Pro C900	M8705200010	-	-	-	-	
226	Pro C900	M8705200011	-	-	-	-	
	Pro C900	M8705200012	-	-	-	-	
228	Pro C900	M8705200013	-	-	-	-	
229	Pro C900	M8705200014	-	-	-	-	
230		M8705200015	-	-	-	-	



PAGE: 13/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Aegis having the LDU Issue

Total Number of Affected Units in NA: 264

NOTE: Cells colored in light blue indicate the units that are already installed with the modified parts and do NOT require replacement.

			Left side		Right side		
			Magenta LDU	Yellow LDU	Black LDU	Cyan LDU	
No.	Machines' name	REI Machine's serial number	YM_LDU(ST1) _SerialNO	YM_LDU(ST2) _SerialNO	CK_LDU(ST1) _SerialNO	CK_LDU(ST2) _SerialNO	
231	Pro C900	M8705200016	-	-	-	-	
232	Pro C900	M8705300001	-	-	-	-	
233	Pro C900	M8705300002	-	-	-	-	
234	Pro C900	M8705300003	-	-	-	-	
235	Pro C900	M8705300004	-	-	-	-	
236	Pro C900	M8705300006	-	-	-	-	
237	Pro C900	M8705300007	-	-	-	-	
238	Pro C900	M8705300008	-	-	-	-	
239	Pro C900S	M8705300009	-	-	-	-	
240	Pro C900S	M8705300010	-	-	-	-	
241	Pro C900S	M8705300011	-	-	-	-	
242	Pro C900S	M8705300012	-	-	-	-	
243	Pro C900 C-80 CREO	S7005200001	-	-	-	-	
244	Pro C900 C-80 CREO	S7005300001	-	-	-	-	
245	Pro C720	S9705200004	-	-	-	-	
246	Pro C720	S9705300001	-	-	-	-	
247	Pro C720	S9705300002	-	-	-	-	
248	Pro C720S	V8905300001	-	-	-	-	
249	Pro C720S	V8905300002	-	-	-	-	
250	Pro C720S	V8905300003	-	-	-	-	
251	Pro C720S	V8905300004	-	-	-	-	
252	Pro C720S	V8905300005	-	-	-	-	
253	Pro C720S	V8905300006	-	-	-	-	
254	Pro C720S	V8905300007	-	-	-	-	
255	Pro C720S	V8905300008	-	-	-	-	
256	Pro C720S	V8905300009	-	-	-	-	
257	Pro C720S	V8905300011	-	-	-	-	
	Pro C720S	V8905300012	-	-	-	-	
	Pro C720S	V8905300013	-	-	-	-	
	Pro C720S	V8905300015	-	-	-	-	
261		V8905300016	-	-	-	-	
	Pro C720S	V8905300017	-	-	-	-	
263	Pro C720S	V8905300018	-	-	-	-	
264	Pro C720S	V8905300019	-	-	-	-	

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

LDU Replacement Procedure


Notes on the replacement work

• Do NOT touch the PCB with bare hands. Grip the bracket made of die-cast aluminum when holding the LDU.





• Check the LDU serial number indicated under the barcode (see the photo below) and mark the corresponding serial number on the data sheet (see the diagram of the data sheet below) to avoid mixing up the installation position. The serial number is indicated as ST1 or ST2 on the data sheet depending on the position. In addition to this marking, indicate the color. Indication of the color on the data sheet will be very important when inputting the information on the data sheet into the SP modes.



The barcode attached to the top-right of the LDU corresponds to the 11 digit LDU serial number indicated on the top-left of the data sheet.

PAGE: 14/28


Example: AGA on the barcode is read

as 61.

Barcode : <u>AGA</u>091200001

 \downarrow \uparrow

Data sheet: 61091200001




Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Work Flow

NOTE

Approx work time is indicated in brackets.

"N" indicates the total number of LDUs requiring the replacement.



NOTE


Step 1 required only for the Aegis-C1; removal of the "Top-right Cover".

PAGE: 15/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

Step 1 Disconnecting the LCT-MF


- 1-1. Remove the I/F connector cover [A]. (screw x 2)1-2. Remove the LCT-MF I/F connectors [B] from the mainframe.





PAGE: 16/28

1-3. Open the front cover of the LCT-MF and remove the screw [C].




Technical Bulletin

PAGE: 17/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

- 1-4. Separate the LCT-MF from the mainframe.
- 1-5. Disconnect the ground cable [E] from the mainframe. (M4x8 screw x 1)
- 1-6. If connected, disconnect the LCT-MF heater relay harness [D] from the mainframe.






Date: 30-Jul-10 Model: AG-P1 / C1 No.: RG178109

Step 2 Removing the Exterior Parts

2-1 Removing the Front Top Cover



- 2-1-1. Open the right and left front doors.2-1-2. Open the toner hopper door [A].2-1-3. Remove the front top cover [B]. (screw x 2)








PAGE: 18/28


2-2 Removing the Rear Top Cover


2-2-1. Remove the rear top cover [A]. (screw x 3)



Model: AG-P1 / C1 No.: RG178109 Date: 30-Jul-10


- 2-3 Removing the Control Panel Arm
- 2-3-1. Remove the cap [A]. 2-3-2. Remove the arm top cover [B]. (screw x 2)







PAGE: 19/28


- 2-3-3. Remove the screw [C].
- 2-3-4. Remove the arm left cover [D]. (screw x 2)
- 2-3-5. Remove the arm right cover [E]. (screw x 2)





2-3-6. Remove the arm [F]. (screw x 4, connector x 1)






Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109


2-4 Removing the Toner Hopper Unit


- 2-4-1. Open the toner hopper door.
- 2-4-2. Release the toner lock levers [A].
- 2-4-3. Remove the toner bottles.



2-4-4. Remove the top right cover [A]. (screw x 2)








PAGE: 20/28

- 2-4-6. Disconnect the harness [C].
- 2-4-7. Remove the four screws.
- 2-4-8. Grip the handles [D] and remove the toner hopper unit.




Technical Bulletin

PAGE: 21/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

2-5 Removing the Metal Cover of the Laser Unit


2-5-1. Remove the metal cover of the laser unit [A]. (screw x 4)



Step 3 Replacing the LDU


3-1. Remove the laser unit top cover [A]. (screw x 9) Note

- Don't touch any optical parts inside the LD unit.
- Be careful not to pinch the chains located on both sides when reattaching the laser unit top cover.
- First, fasten screw "1", and then screw "2" in the reassembly procedure. The seven other screws can be fastened in any order.



- 3-2. Remove the LD Unit. (connector x4, roundhead screw x2)
 - * Do NOT remove the spacer(s). Spacers are applied to compensate for the deviation unique to each unit.

*Spacers may or may not be applied depending on the unit, and their positions and types are






PAGE: 22/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

*Spacer types



- 3-3. Install the new LD Unit, and close the top cover. (connector x4, roundhead screw x2)
 - * Reconfirm the LD Unit serial number to avoid installation in the wrong slot.

Step 4 Reassembling the Outer Covers

Reassemble the outer covers following the reverse order of removal.

Step 5 Connecting the LCT-MF

Connect the LCT-MF following the reverse order of disconnection.

Step 6 Inputting the SP Data

- 6-1. Disable the automatic MUSIC and Process Control adjustment by changing the SP2-193-001 value to "0" and SP3-501-001 to "1".
- 6-2. Disable the 2-point detection by changing the SP2-186-001 value to "0".
- 6-3. Input the LD unit adjustment settings.

Refer to APPENDIX 1-4 to write in the <u>values indicated in PINK</u> (which correspond to the <u>SP values indicated in GREEN</u>) into the table below, and then input those values into the SP.

NOTE

- These values are needed for resetting the Laser Unit related SP values in case the SP values are initialized.
- Please keep the data sheet together with the "SP MODE FACTORY SET" sheet, which should be attached as an accessory to the mainframe, inside the machine.
- If the "SP MODE FACTORY SET" sheet has been lost, print out SP5990-002 and keep it together with the data sheet inside the machine.



PAGE: 23/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

EXAMPLE 1 Yellow LDU (See APPENDIX 1)

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01		! !		

EXAMPLE 2 Cyan LDU (See APPENDIX 2)

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01		i i		i I I

EXAMPLE 3 Black LDU (See APPENDIX 3)

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03		i I I		i I I
2-115-002	-00		! !		! !



PAGE: 24/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

EXAMPLE 4 Magenta LDU (See APPENDIX 4)

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00		i i		

- 6-4. Reset the "Main Magnification Table" setting by inputting "1" in SP2-180-007.
- 6-5. Power cycle the machine.
- 6-6. Execute SP2-180-003 to clear the "MUSIC Result" setting.
- 6-7. Execute the 2-point detection for each color by executing SP2-184-001 (for Black), -002 (for Magenta), -003 (for Cyan) and -004 (for Yellow).
- 6-8. Enable the 2-point detection by changing the SP2-186-001 value to "1" (Auto).
- 6-9. Execute the manual MUSIC adjustment; SP2-153-004 (for rough adjustment) and SP2-153-001 (for fine adjustment).
- 6-10. Enable the automatic MUSIC and Process Control adjustment; set the SP2-193-001 value to "1" (Music ON) and SP3-501-001 value to "0" (Process Control ON).

Step 7 Checking the Image Quality

Finish the replacement procedure by printing out the PS Test Page and checking its image quality.




Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

PAGE: 25/28

APPENDIX 1

SP Values are indicated in GREEN, and Values in PINK.





EXAMPLE 1 Yellow LDU						
SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	
2-102-066	+002	2-105-025	109	2-130-025	654	
2-102-060	-008	2-105-026	105	2-130-026	653	
2-102-061	-015	2-105-027	109	2-130-027	656	
2-102-062	-024	2-105-028	107	2-130-028	660	
2-102-063	-005	2-105-029	111	2-130-029	647	
2-102-064	-011	2-105-030	105	2-130-030	655	
2-102-065	-016	2-105-031	109	2-130-031	664	
2-115-007	-04	2-105-032	106	2-130-032	634	
2-115-008	-01		1			



位置が正しいこと 正しい銘板であること Model: AG-P1 / C1


PAGE: 26/28

No.: RG178109

Date: 30-Jul-10

APPENDIX 2

SP Values are indicated in GREEN, and Values in PINK.







SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01		i		i

カバー:オプティカルハウジング: 組立の 組み付け状態に異常なきこと

が 銘板の位置および内容確認: 位置が正しいこと 正しい銘板であること

PAGE: 27/28


Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

APPENDIX 3

SP Values are indicated in GREEN, and Values in PINK.









EXAMPLE 3 Black LDU						
SP No.	Value	SP No.	Value	SP No.	Value	
(GREEN)	(PINK)	(GREEN)	(PINK)	(GREEN)	(PINK)	
2-101-001	-62	2-105-001	108	2-130-001	632	
2-102-036	+000	2-105-002	105	2-130-002	670	
2-102-030	+005	2-105-003	108	2-130-003	648	
2-102-031	+010	2-105-004	106	2-130-004	638	
2-102-032	+015	2-105-005	109	2-130-005	634	
2-102-033	+004	2-105-006	105	2-130-006	652	
2-102-034	+010	2-105-007	106	2-130-007	639	
2-102-035	+014	2-105-008	105	2-130-008	665	
2-115-001	-03		į		į	
2-115-002	-00					

PAGE: 28/28

Model: AG-P1 / C1 Date: 30-Jul-10 No.: RG178109

APPENDIX 4

SP Values are indicated in GREEN, and Values in PINK.





EXAMPLE 4 Magenta LDU						
SP No.	Value	SP No.	Value	SP No.	Value	
(GREEN)	(PINK)	(GREEN)	(PINK)	(GREEN)	(PINK)	
2-102-056	+000	2-105-017	108	2-130-017	632	
2-102-050	+005	2-105-018	105	2-130-018	670	
2-102-051	+010	2-105-019	108	2-130-019	648	
2-102-052	+015	2-105-020	106	2-130-020	639	
2-102-053	-004	2-105-021	109	2-130-021	634	
2-102-054	+010	2-105-022	105	2-130-022	652	
2-102-055	+014	2-105-023	106	2-130-023	639	
2-115-003	-03	2-105-024	105	2-130-024	666	
2-115-004	+00					

Technical Bulletin

PAGE: 1/3

Reissued: 04-Jul-11

Model: AG-P1/C1	Date: 13-Sep-10	No.: RG178110b
Model: AG-P1/C1	Date: 13-Sep-10	No.: RG178110b

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Release	e note for Aegis-P1/C1 EFI Pa	Prepared by: T. Satoh		
From: 1st PP Service Planning Sec., PP Service Planning				
Classification:	☐ Troubleshooting	☐ Part information	tion	☐ Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release			
File name	File size		
R0205531.exe	89.1 MB		

Problem Solving (Measures)

Following are the key problems that have been given countermeasures.

Files included in this release

Folder Name/ File Name/ File Size/ Reboot

1st/ 1-143G1J.exe/ 1,381,928/ not Exclusive

/ 1-14ASK1.exe/ 3,340,864/ not Exclusive

/ 1-14QOCG.exe/ 1,659,392/ not Exclusive

/ 1-157PIC.exe/ 2,661,312/ not Exclusive

/ 1-166VI5.exe/ 10,448,808/ Exclusive

2nd/ 1-157W91.exe/ 3,329,184/ not Exclusive

/ 1-1555EN.exe/ 3,329,184/ not Exclusive

/ 1-169LYL.exe/ 6,431,248/ not Exclusive

/ 1-152SUR.exe/ 3,447,360/ not Exclusive

/ 1-15ZNHE.exe/ 3,190,560/ not Exclusive

/ 1-15PZTE.exe/ 9,663,984/ not Exclusive

/ 1-153U4F.exe/ 4,904,320/ not Exclusive

/ 1-15L211.exe/ 2,003,520/ not Exclusive

/ 1-15M2R6.exe/ 3,195,856/ not Exclusive

/ 1-15S0Ql.exe/ 1,612,264/ not Exclusive

/ 1-169LZP.exe/ 3,193,376/ Exclusive

3rd/ 1-16CG41.exe/ 3,181,032/ not Exclusive

/ 1-16MO95.exe/ 3,193,360/ not Exclusive

/ 1-16G6Q6.exe/ 1,370,928/ not Exclusive

/ 1-16FG9A.exe/ 1,702,160/ not Exclusive

/ 1-16G6PJ.exe/ 11,039,736/ not Exclusive

/ 1-16ZGXB.exe/ 3,191,672/ not Exclusive

/ 1-16SQ5Y.exe/ 7,681,888/ not Exclusive

Note: Important!!! Strictly follow the installation order as indicated here above.

Technical Bulletin

PAGE: 2/3

Reissued: 04-Jul-11

Model: **AG-P1/C1** Date: 13-Sep-10 No.: RG178110b

Issue(s) addressed with this release

- Separator page is not correctly printed
- After removing ADF jam, the original is scanned with overlapping 1 page
- A cyan line is not printed when print it with 600DPI
- EFI Impose page rotation problem
- PowerPoint2003:Striped pattern is printed on the image which stuck
- Media Size in Consumables is not correct
- Gradation pictures are wrong with the setting of "CompositeOverprint:ON"+"Text/Graphics Quality:Best"+ Booklet
- A slanted line is printed on a part of the gradation
- Paper in PerfectBinderBin, it does not recovery print
- After Process & hold, when body papers are increased in Preview, an error message for the cover is displayed
- During Ripping, Job error occurs
- Some white texts are printed with black
- During printing a subset staple job and become the "Printing" state eternally
- Job is printed without changing Input tray
- Fiery PJL Readback fails
- Gradient is not smooth with default setting printing
- Performance lowers after having removed JAM
- Issue with C900 when imposing VDP data with freeform master
- Not possible to align the paper trays other then plain paper
- When "External charge unit" and "User Authentication" were used together, Print of next job becomes possible when cancel a job even if it is assumed that there is not a card
- Tray Association with SRA3 Paper Catalog is not displayed when ProC900 is patched with 1-14N2CZ
- Duplex print is slow when print it in Stacker
- Fiery PJL Readback fails(USTATUS)
- Feature request for additional staple positions
- Job log stops on the way

Preparation before Installation

- 1. Please print out the configuration page. Verify the **Server Info** section. It should show the version number "4.0". And also verify the **Update Information** section. It should show "1-14N2CZ"
- 2. Please install "1-14N2CZ", if the **Update Information** section is blank. Or please install the system 4.0 again, if the version number is not 4.0.

Note

- 1. You should keep to the correct installation order when installing patches.
- 2. You should execute a reboot when you install an "Exclusive" patch.

(The patch names that you installed will be shown in the configuration after reboot.)

Installation Instructions

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute 1-xxxxxx.exe and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader

Technical Bulletin

PAGE: 3/3

Reissued: 04-Jul-11

Model: **AG-P1/C1** Date: 13-Sep-10 No.: RG178110b

- a. Login must be admin. This is fixed and cannot be modified.
- b. Password is the Fiery administrator login password.
- c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Restart later (not Exclusive) then apply the next patch.

or

Reboot. (Exclusive)

- 5 Wait until the Fiery comes to Idle and print the configuration page.
- 6 Verify that the System Update Log section contains the patch number 1-xxxxxx.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C	Dat	e: 27-Sep	t-10	No.: RG178111		
Subject: Higher tolerance in manufacturing process					d by: N.iid	da
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting	□ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	$\hfill \square$ Other ()	☐ Tier 2	

This RTB has been issued to provide a supplementary explanation of the reason for the following p/n changes announced in the PCIL and the requirements when replacing these parts.


Old part	New part	Description	Q'ty		Int	Page	Index	Note
number	number							
G1781759	G1781773	ARM:TURN:UPPER	1	X/X	X/O	28	22	
		LOWER:WELDING			As a			
G1781764	G1781772	SHAFT:KNOB:OPERATION	1	X/X	set	28	16	
		SUB-UNIT						
G1781767	G1781771	SHAFT:KNOB:ARM:SMALL	1	X/X	X/O	28	12	
G1781780	G1781774	ARM:TURN:LEFT AND	1	X/X	As a	28	14	
		RIGHT:WELDING			set			

Change: Higher tolerance

Reason: A problem was found in the assembling process of these parts at the factory.

The 4 relative parts have been modified to gain higher tolerance.

If a machine requires replacement of these parts, please replace them as a set as described in the table above and diagram below.



K	

PAGE: 1/1

Model: AG-P1/C	Dat	te: 30-Sept	t-10	No.: RG178112					
Subject: KEYTOP - PRINTER					Prepared by: N.iida				
From: PPBG Ser	vice Planning Dept.								
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required			
	☐ Mechanical	☐ Electric	al		Service	ce manual revision			
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information			
	☐ Product Safety	Other ()	☐ Tier 2				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	B2341571	KEYTOP - PRINTER NA	0→1	-	32	3	
-	B2341577	KEYTOP - PRINTER EU	0→1	-	32	3	

New types of hard keys have been added. The design of the hard keys will differ depending on the type of controller installed in the printer. Please attach the hard key according to the controller type when replacing the operation panel.

Туре	Embedded Controller	External Controller E80 or C80
	G1781844: KEYTOP:PRINTER:EFI:AEG_P1	B2341571: KEYTOP - PRINTER NA Printer
		B2341577: KEYTOP - PRINTER EU

Technical Bulletin

PAGE: 1/1


Model: AG-P1/C	Dat	te: 30-Sept	t-10	No.: RG178113		
Subject: WASHE		Prepared	d by: N.iid	da		
From: PPBG Service Planning Dept.						
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
!	☐ Mechanical	☐ Electric	al		Service	ce manual revision
!	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G1781769	WASHER:M4	0→1	-	172	31	

Change: WASHER:M4 newly added

Reason: A screw hole in the drive section was damaged in the manufacturing process. 'Washer: M4' has been added to prevent this problem. Damage to this screw

hole has not been reported from the field.



PAGE: 1/1

Reissued:14-Oct-10

= -110 : 0 : 0 : 0 : 0 : 0 : 0 : 0 : 0 : 0	Model: AG-P1 / C1	Date: 30-Sept-10	No.: RG178114a
--	-------------------	------------------	----------------

RTB Reissue


The items in **bold italics** were corrected or added.

Subject: Change in screw type in the fuser unit				Prepared by: N.iida			
From: PPBG Service Planning Dept.							
Classification:	☐ Troubleshooting	□ Part informa	tion	☐ Action required			
	☐ Mechanical	☐ Electrical	☐ Service manual revision				
	☐ Paper path	☐ Transmit/red	eive	☐ Retrofit information			
	☐ Product Safety	Other ()	☐ Tier 2			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
04544008Q	_	TAPPING SCREW - M4X8	7→0	0/0	123	101	
	G8327900A	SCREW:SPRING	0→7				
	►G8327900	WASHER:ROUND POINT:M4X10					
03603006N	_	SCREW:M3X8	2→1	0/0	133	102	* See
	08046123	HEXAGONAL	0→1			108	diagram
	▶	BOLT:W/WASHER:M3X8					below
03604012N	_	SCREW:M4X12	2→0	0/0	135	107	
	08010238	HEXAGON HEAD BOLT:DOUBLE	0→2				
	-	SCREW:M4X14					
03530080N	_	SCREW:M3X8	2→0	0/0	135	109	
	09573010N	SCREW:SMALL	0→2				
	▶	ROUND/SPRING:M3X10					
03603010N	_	SCREW:M3X10	2→0	0/0	135	112	
	09573010N	SCREW:SMALL	0→2				
	•	ROUND/SPRING:M3X10					

Change/Reason: Screw types have been changed in the fuser unit to prevent loosening.

NOTE: Among 2 "M3x8" screws used in this section, only the screw indicated in red in the diagram below has been changed.




Technical Bulletin

Model: AG-P1 / C1 Da				te:		No.: RG178115
Subject: Switchback junction gate				Prepare	d by: N.iid	da
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	\square Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description	Q'ty	lr	nt	Page	Index
G1784711	G1784918	SHAFT:GATE:SWITCHBACK:L OWER	1	\times/\times	As a set	155	2
-	H1103157	ROLLER:BELT TENSIONER	0→2	-	×/O	155	16

Change/Reason:

Parts have been added and modified in the paper exit area to resolve dog-ears which had occurred in the media qualification test. Dog-ears owing to the parts described in this bulletin have not been reported from the field.



'Roller: Belt Tensioners' have been added to function as spacers.

PAGE: 1/2

SYMPTOM

Dog-ear could occur when duplex printing on 13 x 19 inch paper.

CAUSE


Depending on the orientation of the E-type retaining rings which are installed on the edges of the switchback junction gate in the duplex path area, the paper interferes with the E-type retaining rings when duplex printing on 13 x 19 inch size paper.


PAGE: 2/2

Model: AG-P1 / C1 Date: No.: RG178115

SOLUTION

SHAFT:GATE:SWITCHBACK:LOWER has been modified and ROLLER:BELT TENSIONER (x2) have been added to allow the E-type retaining ring to be positioned away from the paper path to avoid interference with the sheet.





Technical Bulletin


PAGE: 1/2

Model: AG-P1/AG-C1 Date			ite:		No.: RG178116		
Subject: Modified rollers for better grip				Prepare	d by: N.iid	da	
From: PPBG Ser	vice Planning Dept.						
Classification:	Troubleshooting	□ Part info	orma	tion Action requir		n required	
		☐ Electric] Electrical ☐ Ser		Service	ce manual revision	
	☐ Paper path	☐ Transmit/red		☐ Transmit/receive ☐ Reti		Retrof	fit information
	☐ Product Safety	Other () Tier 2			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G1784950	G1784946	EXIT ROLLER:PRESS FIT	1	X/O	150	2	
G1784942 –		TRANSPORT ROLLER:EXIT	3→1	-	156	4	
	G1784944	TRANSPORT	0→2	X/O	156	16	
	*	ROLLER:REVERSE:PRESS FIT					


Change/Reason:

Material of the EXIT ROLLER and TRANSPORT ROLLER has been changed from EPDM rubber to urethane for better grip. When a replacement is required for any of the following 3 rollers, replace them as a set.



PAGE: 2/2

Model: AG-P1/AG-C1 Date: No.: RG178116



Technical Bulletin

Model: AG-P1 / C1			Dat	te: 30-Sept	:-10	No.: RG178117
Subject: Change in screw type: Front-top cover				Prepared	d by: N.iid	da
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting	□ Part info	orma	tion	ion Action required	
	☐ Mechanical	☐ Electrica	al		Service	ce manual revision
	☐ Paper path	☐ Transmit/re		eive:	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	


Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
04504008N		TAPPING SCREW: M4X8	11→9	0/0	20	104	
	04524008N	TAPPING SCREW:M4X8	0→2		20	108	

Change/Reason:

Screws applied to the front-top cover have been changed to prevent damage to the harness when attaching the cover (See figure 1).

The new screws will allow securing a 0.6mm gap between the frame and the screw head (See figure 2).


Please refer to figures 3-1 and 3-2 for details.



PAGE: 1/3

Model: AG-P1 / C1 Date: 30-Sept-10 No.: RG178117


New screws will secure a 0.6mm gap to prevent damage to the harness.





PAGE: 3/3

Model: AG-P1 / C1 Date: 30-Sept-10 No.: RG178117



Technical Bulletin

ate: 30-Sept-10	No.: RG178118
-----------------	---------------

PAGE: 1/1


Model: Aegis-P1/C1 Dat			ate	e: 30-Sept	-10	No.: RG178118	
Subject: Protection sheet added to fan				Prepared by: N.iida			
From: PPBG Ser	vice Planning Dept.						
Classification:	Troubleshooting	□ Part inform	nati	ation Action require		required	
	☐ Mechanical	☐ Electrical			☐ Service manual re		
	☐ Paper path	☐ Transmit/re	ece	eive	Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G1787307	SHEET:FAN:CABLE	0→1	-	208	11	

Change/Reason:

Improvement in the factory assembling process: a protection sheet has been added to the fan component to prevent damage to the harness.

95.Electrical Section 15 (D016/G178)



Technical Bulletin

PAGE: 1/2 Reissued: 13-Oct-10

Date: 21-Nov-06

No.: RB835001h

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1, B-C3/C3.5/C4, V-C2

RTB Reissue

The items in bold italics have been added.

THE ROTTE IT DO	a italios have been added	^ .			
Subject: Cover Interposer Tray CI5000			Prepared by: J. Ohno		
From: PPBG Ser	vice Planning Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part informa☐ Electrical☐ Transmit/rec	Service manual revision		

This RTB has been issued to announce the firmware release information for the Cover Interposer.

Version	Program No.	Effective Date
03.010:46	B8355510H	May 2010 production
02.073:44	B8355510G	December 2009 production
02.071:42	B8355510F	April 2009 production
02.070:41	B8355510E	April 2009 production
02.067:40	B8355510D	Jan 2009 production
02.064:37	B8355510C	Sep 2008 production
02.050:32	B8355510B	Feb 2008 production
02.030:26	B8355510A	Nov 2007 production
01.000:20	B8355510	1st Mass production.

Version	Modified Points or Symptom Corrected
03.010:46	The Inserter is supported by the Pro C901/C901S.
	Symptoms Corrected: Program download to the Cover Interposer Tray Cl5010 and any other downstream peripherals results in failure in the following configuration: Pro C901/C901S mainframe + Buffer Pass Unit Type 5000 + Cover Interposer Tray Cl5010 + any downstream peripheral The Cover Interposer Tray Cl5010 will not feed the cover sheets and the control panel indicates 'Printing' due to a data transmission error between the Cover Interposer and the Pro C901/C901S/C900/C900S.
02.073:44	 Modified Points For CI5010/CI5000, to prevent the false positive of the following symptom. When the switch is turned on with the papers are set at the 1st tray, some of the paper sizes are not detected correctly. To prevent the false positive of the following symptom. When sending the job from the Web Image Monitor, which the job's 1st paper is fed from the CI5000/5010, paper set error occurs.
02.071:42	Other changes: The Venus C2 supports the Ring Binder.

Technical Bulletin

PAGE: 2/2

Reissued: 13-Oct-10

Model: Aries-C1.5/P1.5, AG-C1/P1, AGL-C1/P1, Date: 21-Nov-06 No.: RB835001h B-C3/C3.5/C4, V-C2

Version	Modified Points or Symptom Corrected
02.070:41	Symptom corrected:
	 During a job that involves paper feeding from the Inserter, the job cannot be completed if the Inserter cover is opened.
	 During a job that involves paper feeding from the Inserter, the job cannot be completed if the paper on the feeder tray is dragged out.
	• During a job that involves paper feeding from the Inserter, the job cannot be completed if a jam occurs on the Inserter or a downstream peripheral.
02.067:40	Other changes:
	Support for Katana-C2/P1.
02.064:37	Changes:
	Support for Aegis-C1/P1.
02.050:32	Other changes:
	Support for Bellini-C3.5(Katana-C1.5).
02.030:26	Other changes:
	Supports the D014/D015 copier.
01.000:20	1st Mass production

Technical Bulletin

PAGE: 1/4

Model: AG-P1/C1			Date: 04-Oct-10		10	No.: RG178119	
Subject: Update Procedure: TEST PRINT TOOL				Prepared by: N.iida			
From: PPBG Service Planning Dept.							
Classification:	Troubleshooting	☐ Part info	art information		Action	required	
	☐ Mechanical	☐ Electrical ☐ Transmit/receive			Service	Service manual revision	
	☐ Paper path			eive	□ Retrof	Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2		

A Test Print Tool (p/n D0169503) is available for the following 4 models: AG-P1/C1,AGL-P1/C1.

By following the update procedure described in this bulletin, the Test Print Tool will also be available for the Aries-P1.5/C1.5.

Note

In the update procedure, 3 files are replaced and 4 files are added in the module folder. Do NOT delete or replace any other files. If deleted or replaced, the Test Print Tool will not activate. Please work carefully as the system will NOT recover if the update procedure is followed incorrectly.

Replaced Files

fact.mod fact_gw11.mac fact_tg11.mac

Added Files

fact_D095.mod fact_D095_gw11.mac fact_M077.mod fact_M077_gw11.mac

The update file is saved in the following location:

TBD


File name: UpV2.zip

PAGE: 2/4


Model: AG-P1/C1 Date: 04-Oct-10 No.: RG178119

Update Procedure

- 1. Download 'UpV2.zip' to your PC.
- 2. Unzip 'UpV2.zip', and open the 'UpV2' folder.



3. Insert the 'Test Print Tool SD Card' into your PC, and open the module folder.







Model: AG-P1/C1 Date: 04-Oct-10 No.: RG178119

PAGE: 3/4

4. Drag & drop all files from the 'UpV2' folder to the module folder.



5. Select 'Yes to All' in the dialog box below.






PAGE: 4/4

Model: AG-P1/C1 Date: 04-Oct-10 No.: RG178119

6. The update procedure is completed when all files are copied onto the module folder.



K	П

PAGE: 1/17

Model: AG-P1 / C1			Dat	Date: 18-Oct-10		No.: RG178120
Subject: LDU service part release				Prepared by: N.iida		
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	☐ Part info	orma	tion		required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	☐ Other ()	☐ Tier 2	

General

Recovery from LD Errors (SC240, 241, 242, 243) required the entire replacement of the imaging unit and was costly.

To reduce the cost and allow recovery by replacing only the LDU (Laser Diode Unit), the LDU has been registered as a standard service part.

Please refer to the following procedure for LDU replacement.

Part Information

The LDUs have been registered with the following p/n.

Part Number	Description
G1782041	Laser Diode Unit:MK:Ass'y
G1782042	Laser Diode Unit:YC:Ass'y




PAGE: 2/17


Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

The LDUs are described as "MK" and "YC", but does NOT mean one "MK" LDU will cover both magenta and black.

LDUs to be installed in the Laser Unit are as shown in the diagram below.



"ST1" and "ST2" indicate the installing position in the Laser Unit.



Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

LDU Replacement Procedure

Notes on the replacement work

• Do NOT touch the PCB with bare hands. Grip the bracket made of die-cast aluminum when holding the LDU.





• Check the LDU serial number indicated under the barcode (see photo below) and mark the corresponding serial number on the data sheet (see diagram of the data sheet below) to avoid confusion of mixing up the installation position. The serial number is indicated as ST1 or ST2 on the data sheet depending on the position. In addition to this marking, indicate the color. Indication of the color on the data sheet will be very important in the latter procedure when inputting the information described on the data sheet into the SP.




The barcode attached to the top-right of the LDU corresponds to the 11-digit LDU serial number indicated on the top-left of the data sheet.

PAGE: 3/17

Example) <u>AGA</u> on the barcode is read as 61.

Barcode: <u>AGA</u>091200001

Data sheet: 61091200001



PAGE: 4/17


Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

Work Flow

NOTE

Approx work time is indicated in the brackets.

"N" indicates the total number of LDUs requiring the replacement.



NOTE

Step 1 required only for the Aegis-C1; removal of the "Top-right Cover".

Model: AG-P1 / C1

PAGE: 5/17 Date: 18-Oct-10 No.: RG178120


Step 1 Disconnecting the LCT-MF

- 1-1. Remove the I/F connector cover [A]. (screw x 2)1-2. Remove the LCT-MF I/F connectors [B] from the mainframe.





1-3. Open the front cover of the LCT-MF and remove the screw [C].




Model: AG-P1 / C1

Technical Bulletin

Date: 18-Oct-10 No.: RG178120

PAGE: 6/17

- 1-4. Separate the LCT-MF from the mainframe.
- 1-5. Disconnect the ground cable [E] from the mainframe. (M4x8 screw x 1)
- 1-6. If connected, disconnect the LCT-MF heater relay harness [D] from the mainframe.






Date: 18-Oct-10 Model: AG-P1 / C1 No.: RG178120

Step 2 Removing the Exterior Parts

2-1 Removing the Front Top Cover



- 2-1-1. Open the right and left front doors.2-1-2. Open the toner hopper door [A].2-1-3. Remove the front top cover [B]. (screw x 2)








PAGE: 7/17

2-2 Removing the Rear Top Cover


2-2-1. Remove the rear top cover [A]. (screw x 3)




PAGE: 8/17


Model: AG-P1 / C1 No.: RG178120 Date: 18-Oct-10


- 2-3 Removing the Control Panel Arm
- 2-3-1. Remove the cap [A]. 2-3-2. Remove the arm top cover [B]. (screw x 2)







- 2-3-3. Remove the screw [C].
- 2-3-4. Remove the arm left cover [D]. (screw x 2)
- 2-3-5. Remove the arm right cover [E]. (screw x 2)





2-3-6. Remove the arm [F]. (screw x 4, connector x 1)






Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120


2-4 Removing the Toner Hopper Unit


- 2-4-1. Open the toner hopper door.
- 2-4-2. Release the toner lock levers [A].
- 2-4-3. Remove the toner bottles.



2-4-4. Remove the top right cover [A]. (screw x 2)








PAGE: 9/17

- 2-4-6. Disconnect the harness [C].
- 2-4-7. Remove the four screws.
- 2-4-8. Grip the handles [D] and remove the toner hopper unit.




Technical Bulletin

PAGE: 10/17

2-5 Removing the Metal Cover of the Laser Unit


2-5-1. Remove the metal cover of the laser unit [A]. (screw x 4)




Step 3 Replacing the LDU

3-1. Remove the laser unit top cover [A]. (screw x 9) Note

- Don NOT touch any optical parts inside the LD unit.
- Be careful not to pinch the chains located on both sides when reassembling the laser unit top cover.
- First, fasten screw "1", and then screw "2" when reassembling. The seven other screws can be fastened in any order.




- 3-2. Remove the LD Unit. (connector x4, roundhead screw x2)
 - * Do NOT remove the spacer(s). Spacers are installed to compensate for the deviation unique to each unit. Spacers may or may not be applied depending on the unit, and their positions and types are unique to each unit.



PAGE: 11/17

Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

*Spacer types



- 3-3. Install the new LD Unit, and close the top cover. (connector x4, roundhead screw x2)
 - * Reconfirm the LD Unit serial number to avoid installation in the wrong slot.

Step 4 Reassembling the Outer Covers

Reassemble the outer covers following the reverse order of removal.

Step 5 Connecting the LCT-MF

Connect the LCT-MF following the reverse order of disconnection.

Step 6 Inputting the SP Data

- 6-1. Disable the automatic MUSIC and Process Control adjustment by changing the SP2-193-001 value to "0" and SP3-501-001 to "1".
- 6-2. Disable the 2-point detection by changing the SP2-186-001 value to "0".
- 6-3. Input the LD unit adjustment settings.

Refer to APPENDIX 1-4 to write in the <u>values indicated in PINK</u> (which correspond to the <u>SP values indicated in GREEN</u>) into the table below, and then input those values into the SP.

NOTE

- These values are needed for resetting the Laser Unit related SP values in case the SP values are initialized.
- Please keep the data sheet together with the "SP MODE FACTORY SET" sheet, which should be attached as an accessory to the mainframe, inside the machine.
- If the "SP MODE FACTORY SET" sheet has been lost, print out SP5990-002 and keep it together with the data sheet inside the machine.

PAGE: 12/17

Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

EXAMPLE 1 Yellow LDU <<See APENDIX 1>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01				! ! !

EXAMPLE 2 Cyan LDU <<See APPENDIX 2>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01		i i		i I

EXAMPLE 3 Black LDU <<See APPENDIX 3>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03				i I I
2-115-002	-00				



PAGE: 13/17

Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

EXAMPLE 4 Magenta LDU <<See APPENDIX 4>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00		i i		

- 6-4. Reset the "Main Magnification Table" setting by inputting "1" in SP2-180-007.
- 6-5. Power cycle the machine.
- 6-6. Execute SP2-180-003 to clear the "MUSIC Result" setting.
- 6-7. Execute the 2-point detection for each color in SP2-184-001 (for Black), -002 (for Magenta), -003 (for Cyan) and -004 (for Yellow).
- 6-8. Enable the 2-point detection by changing the SP2-186-001 value to "1" (Auto).
- 6-9. Execute the manual MUSIC adjustment; SP2-153-004 (for rough adjustment) and SP2-153-001 (for fine adjustment).
- 6-10. Enable the automatic MUSIC and Process Control adjustment; set the SP2-193-001 value to "1" (Music ON) and SP3-501-001 value to "0" (Process Control ON).

Step 7 Checking the Image Quality

Finish the replacement procedure by printing out the PS Test Page and check its image quality.




Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

PAGE: 14/17

<<APENDIX 1>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.





EXAMPLE 1 Yellow LDU						
SP No.	Value	SP No.	Value	SP No.	Value	
(GREEN)	(PINK)	(GREEN)	(PINK)	(GREEN)	(PINK)	
2-102-066	+002	2-105-025	109	2-130-025	654	
2-102-060	-008	2-105-026	105	2-130-026	653	
2-102-061	-015	2-105-027	109	2-130-027	656	
2-102-062	-024	2-105-028	107	2-130-028	660	
2-102-063	-005	2-105-029	111	2-130-029	647	
2-102-064	-011	2-105-030	105	2-130-030	655	
2-102-065	-016	2-105-031	109	2-130-031	664	
2-115-007	-04	2-105-032	106	2-130-032	634	
2-115-008	-01					




位置が正しいこと 正しい銘板であること

PAGE: 15/17

Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

<<APENDIX 2>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.





	W.	ail		
	Ξ.	H	Ģ	
S	200	33	8	
ì	10	u	ži.	

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01		i		Ì

カバー:オプティカルハウジング: 組立の 組み付け状態に異常なきこと

☆ 銘板の位置および内容確認: 位置が正しいこと 正しい銘板であること

Date: 18-Oct-10


PAGE: 16/17

No.: RG178120


Model: AG-P1 / C1

<<APENDIX 3>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.







PAGE: 17/17

Model: AG-P1 / C1 Date: 18-Oct-10 No.: RG178120

<<APENDIX 4>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.





EXAMPLE 4 M	<u>lagenta LDU</u>	l			
SP No.	Value	SP No.	Value	SP No.	Value
(GREEN)	(PINK)	(GREEN)	(PINK)	(GREEN)	(PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00				

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5			Date: 21-Oct-10		No.: RG178121	
Subject: Notes on Handling the Developer unit				Prepared by: Junji Kobayashi		
From: PPBG Service Planning Dept.						
Classification:		☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path ☐ Transmit/re		it/rec	eceive Retro		fit information
	☐ Product Safety	\square Other ()	⊠Tier 2	

This RTB has been issued to announce the correct handling procedure of the developer unit to prevent fluctuation of the PG (gap between the development roller and the drum) which could occur in the front side of the drum.


The following problems could occur if the drums are not handled in the correct way:

- 1) Difference in image density
- 2) Different density between left and right sides on a page
- 3) Toner adhesion to the development rollers
- 4) Scratches on the drums resulting from toner adhesion to the development rollers
- 5) Toner clumps caused by narrowed PG

Notes on Handling the Developer Units

- Always hold the prescribed locations when handling the developer unit.
- Never apply external pressure to the front and rear plates and the stay.

Hold the Case and the Cover when handling the developer unit.



PAGE: 2/2

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5

Date: 21-Oct-10


No.: RG178121

DO NOT hold any metal plates





Attention needed for the following parts



Applying external pressure will deform the front and rear plates in vertical and horizontal directions, resulting in fluctuation of the PG.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5			Dat	te: 21-Oct-10		No.: RG178122
Subject: Notes on Handling the Photoconductive Drum				Prepared by: Junji Kobayashi		
From: PPBG Service Planning Dept.						
Classification:		☐ Part informa☐ Electrical		tion	☐ Action	required
					☐ Service manual revision	
	☐ Paper path	☐ Transmit/red		eceive R		fit information
	☐ Product Safety	Other ()	⊠ Tier 2	2

This RTB has been issued to announce the correct handling procedure of the photoconductive drums to prevent fluctuation of the PG (gap between the development roller and the drum) which could occur at the front side of the drum.


The following problems could occur if the drums are not handled in the correct way:


- 1) Different density between left and right sides on a page
- 2) Toner adhesion to the development rollers
- 3) Scratches on the drums resulting from toner adhesion to the development rollers
- 4) Toner clumps caused by narrowed PG

Notes on Fastening the Drum Knob

- Always pull out the developer unit and remove the drum cleaner when fastening the drum knob.
- Never try to further fasten the drum knob when the drum cleaner is installed.

Keep the developer unit drawn out when fastening the drum knob.





PAGE: 2/2

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5

Date: 21-Oct-10

No.: RG178122

Do NOT fasten the drum knob when the developer unit is installed.

Do NOT fasten the drum knob when the drum cleaner is installed.





If the drum knob is loosened while the drum cleaner is installed, make sure to remove the drum cleaner before fastening the drum knob.

Never fasten the drum knob when the drum cleaner is installed.

Doing so could apply pressure to the drum and narrow the PG on the front side.



PAGE: 1/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1	Date:	No.: RG178123a
----------------------------	-------	----------------

RTB Reissue The items in **bold italics** were corrected or added.

Subject: Troubleshooting for Firefly			Prepared by: Junji Kobayashi		
From: PPBG Se	rvice Planning Dept.				
Classification:		☐ Part information		Action required	
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

Summary

'Firefly spots' (also called 'Fireflies') is a result of poor transfer caused by toner clumps spurted out from the development unit. Since there are several factors that could generate toner clumps in multiple areas, it is important to identify the cause and resolve the problem accordingly by following the procedures described in this bulletin.

Symptom

'Firefly spots' is a name given for an abnormal image in which a white spot with a core is generated on the printout caused by toner clumps. White spots that do not have the core are caused by different reasons. Please consider white spots to be 'Fireflies' if any trace of toner clumps are observed in the white spot.

Cause/Solution and Troubleshooting

The following table gives a summary of the causes/solutions for the symptoms observed.

Cause

Oudse				-
Occurrence Timings	No	Symptom Detail (Solid print)	Cause	Solution
After/Before Toner Bottle Replacement	_	Numerous Fireflies; more than 30 on a sheet of DLT	Toner clumps are generated when the toner pump attempts to supply toner from a near-end toner bottle.	 Replace with a new toner bottle as soon as toner near-end is detected. Print approx 200-400 solid prints on DLT to dispose of possible toner clumps generated in the toner supply and the development unit. Modify the SP value – this reduces the chances of activating the toner supply pump in an empty bottle status.
Occurrence Unrelated to Toner Bottle Replacement	11"	Few; less than 30 on a sheet of DLT	Toner clumps are generated inside the development unit.	 Confirm correct installation of the bushings on the rear side for the 3 shafts. If the bushings are installed incorrectly, adjust and then print out approx 200 of solid prints on DLT. If the bushings are installed correctly and the occurrence rate is acceptable, print approx 200 solid prints on DLT. If the occurrence rate/conditions are unacceptable, install a new development unit.
	Ш		Toner clumps are generated due to the	Check whether toner is adhered to the surface of the development rollers. If adhered, install a

Technical Bulletin

PAGE: 2/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1			Date:	No.: RG178123a	
		narrowed gap between the development rollers and the drum, which is caused by a loosened drum knob upon drum replacement.	new development unit. However, if the amount of toner adhesion is small, wipe off the toner. • Whether or not toner adhesion is observed, confirm complete fastening of the drum knob by referring to the last section of this document "Fastening the Drum Knob". • If the development unit doesn't require replacement, print approx 200 solid prints on DLT to dispose of toner clumps from the development unit.		
IV	-	Toner clumps are generated by bad storing conditions; temp, humidity, vertical position of the bottle.	 Replace the toner bottle Print approx 200-400 sol dispose of possible toner c the toner supply and devel 	lumps generated in	
V	-	Toner clumps are generated inside the sub-hopper. Note: Firefly spots originating in the sub-hopper unit has never been reported.	If the occurrence rate is approx 200 solid prints on If the occurrence rate/counacceptable, install a new	DLT. nditions are	


NOTE: Please note that "a few Fireflies on DLT, approx 10 pages" is considered the maximum performance of the machine.

PAGE: 3/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a

Troubleshooting work flow



Install a new development unit. [NOTE 2]

Refer to the section "Notes on Handling the Developer Unit".




PAGE: 4/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a

NOTE 1: Checking for toner adhesion on the development rollers

Toner adhered to the development rollers could be hidden, covered with developer. Wipe off the developer from an area of approx 30mm in width from the edge of the rollers.



- * Make sure to perform this check regardless of the drum knob condition because toner adhesion could occur after replacing the drum and/or drum cleaning unit.
- * Toner adhesion to the development rollers will cause scratches on the drum surface.

NOTE 2


A slight amount of toner adhesion can be removed by using the adhesive side of some packing tape.

However, install a new development unit if the amount of toner adhesion is considerable. NEVER apply alcohol for toner removal.

Alcohol will dissolve the toner, and the dissolved toner could adhere to the development rollers and cause further problems.

PAGE: 5/14

Reissued:16-Nov-10





PAGE: 6/14


Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a


NOTE 3: Check for the 3 bushing positions

STEP 1: Remove the development unit from the slide rails, and remove the rear gear cover.(Cover:Gear:Development Unit:Ass'y)

STEP 2: Check the gap between the flanged edge of the white plastic bushing and the black cover for the 2 shafts; Agitator and Toner Supply located on the rear side of the unit.




Recommended gap width: 0.8mm [at least 0.5mm]




PAGE: 7/14

Reissued:16-Nov-10




STEP 3: Check that the Bearing protrudes from the flange of the Collect bushing.



Technical Bulletin

IIETIN PAGE: 8/14

Reissued:16-Nov-10





PAGE: 9/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1	Date:	No.: RG178123a
----------------------------	-------	----------------

NOTE 4

The modified SP values are set as defaults for the following units.

Model	Machine No.	
	D01600	48C1-110051~
C1-DOM		
C1-Asia	D01629	M8700100001~
P1-DOM	G17800	48BE-110072∼
P1-Asia	G17829	S3200100001~
MB&R REI	G17896	S3200180001~
MB&R RPL	G17897	S3200190001~
BaseEngine REI (controller excluded)	M07696	S9600180001~
BaseEngine RPL (controller excluded)	M07697	S9600190001~

NOTE 5

Approx 600 pages of solid prints in DLT at maximum is required to dispose of the toner clumps contained in 150g of toner in the Sub-hopper, and 65g in the development unit.

NOTE 6

If the Fireflies reappear with a moderate print volume and toner consumption, the problem is expected to be originating in the development unit.

Reference: 1 increment in toner remaining indicator, print volume 100k

NOTE 7


Fireflies originating in the sub-hopper unit have never been reported.

Technical Bulletin

PAGE: 10/14

Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a



Technical Bulletin

PAGE: 11/14

Reissued:16-Nov-10

NOTE 8

- * YMC development units will continue to operate even if the job switches from FC mode to mono-color mode. If job operation is continued in this condition, toner clumps are more likely to be generated rather than being disposed of, because the toner consumption rate of the YMC development units is only 2.5%.
- * Proceed to 'YES' if the Fireflies are expected to be caused for the above reason.

NOTE 9 SP modification: Advantages & Disadvantages **Advantage:**

- 1) Reduces the chances of generating toner clumps in the YMC development units.
- 2) Minimized operation of the YMC stations will enable longer life of their development, drum, drum cleaner, and charger units.

Disadvantage:

Productivity is slightly reduced because the system requires a little less than 5 seconds to switch from FC mode to Mono-color mode, and a little less than 7 seconds in the reverse order. (In addition, 2-3 minutes is required because Process Control is carried out if the temperature is low, immediately after powering on or after a long pause.)

Technical Bulletin

PAGE: 12/14

Reissued:16-Nov-10

Information required for problem analysis

Please obtain the following information when Fireflies are reported from the field.

- 1. Storing conditions of the toner bottles (vertical/horizontal)
 - → Storing the toner bottles in the vertical position could cause toner clumps to form.
- 2. Occurrence level and number of Fireflies per sheet
 - → Firefly occurrence is prescribed in the Product Standards as "2 Fireflies, radius of 2mm or larger, on 2 continuously fed DLT.
- 3. Occurrence interval; kp
 - → Fireflies tend to occur at an interval of 100-150 kp according to the investigations to date.
- 4. Whether or not the development unit has been replaced (for PM) before the Firefly occurrence
 - → Loose drum knob could cause Fireflies, Drum streaks, etc.
- Job details
 (Image containing high usage rate of certain color(s), image density, POP printing or photo images, etc)
- 6. Site environment (Temperature, humidity, whether or not other units are installed in the site, air cleanness, etc.)
- 7. SMC report
- 8. Master log, if available

PAGE: 13/14


Reissued:16-Nov-10

Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a

NOTES ON HANDLING THE DEVELOPMENT UNIT

- Always hold on to the prescribed locations when handling the development unit.
- Never apply external pressure to the front and rear plates and the stay.

Hold the Case and the Cover when handling the development unit.




DO NOT HANDLE LIKE THIS





Attention needed for the following parts



Applying external pressure will deform the front and rear plates in vertical and horizontal directions, resulting in fluctuation of the PG (gap between development roller and photoconductive drum).

Reason: To avoid fluctuation of the PG

The following adverse effects could occur if the correct procedure is not followed:

- 1) Difference in image density
- 2) Different density between left and right sides on a page
- 3) Toner adhesion on the development rollers
- 4) Scratches on the drums resulting from toner adhesion on the development rollers
- 5) Toner clumps caused by reduced PG

PAGE: 14/14

Reissued:16-Nov-10


Model: AG-P1/C1, AGL-P1/C1 Date: No.: RG178123a

FASTENING THE DRUM KNOB

- Always pull out the development unit and remove the drum cleaner when fastening the drum knob.
- Never try to further fasten the drum knob when the drum cleaner is installed.

Keep the development unit drawn out when fastening the drum knob.





Do NOT fasten the drum knob when the development unit is installed. Do NOT fasten the drum knob when the drum cleaner is installed.





If the drum knob is loosened while the drum cleaner is installed, make sure to remove the drum cleaner before fastening the drum knob.

Never fasten the drum knob when the drum cleaner is installed. Doing so could apply pressure to the drum and narrow the PG in the front side.

Reason: To avoid fluctuation of the PG in the front side

The following adverse effects could occur if the correct procedure is not followed:

- 1) Different density between left and right sides on a page
- 2) Toner adhesion to the development rollers
- 3) Scratches on the drums resulting from toner adhesion to the development rollers
- 4) Toner clumps caused by reduced PG

Technical Bulletin

PAGE: 1/2


Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date			e: 25-Oct-	10	No.: RG178124	
Subject: LED Indication Sequence (POST Code)			Prepare	d by: Jun	ji Kobayashi	
From: PPBG Ser	vice Planning Dept.					
Classification:		☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

Reason to Issue

This RTB has been issued to announce the method for checking whether or not the controller board is defective when a controller board related SC code is notified. LEDs indicate the process of power supply followed by the CPU activation.

LED Configuration

The diagram below shows the LED configuration. The controller status can be checked by observing the sequence of the LED turning on, off, or flashing.



These LEDs are used to check the system activation process which follows the POST; power on self test.

PAGE: 2/2

Date: 25-Oct-10


No.: RG178124

LED Indication Sequence (POST Code)

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5

■ Checking the LED Status

The LEDs will turn OFF, turn ON, or FLASH in the following order when powering on the machine.



System activation up to Step 4 is expected to complete in 15 seconds after powering on the machine.

Technical Bulletin

PAGE: 1/1


Model: AG-P1/C	1,AGL-P1/C1		Dat	te: 25-Oct-	10	No.: RG178125
Subject: ADJUSTING SCANNER PIN			Prepare	d by: N.lic	da	
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2	

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	A0069104	ADJUSTING SCANNER PIN	0→1	-	415	8	
		(4PCS/SET)					

The following description had been missing in the section "150.Special Tools".

Please apply the correction to your parts catalog.

The pin is a common part for B-C3/C3.5 models.




PAGE: 1/3

Model: AG-P1/C1,AGL-P1/C1			Dat	e: 04-Nov	-10	No.: RG178126
Subject: Titanium-coated Development Rollers			Prepare	d by: N.li	da	
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	□ Part info □ Electric □ Transm □ Other (al		Service	n required ce manual revision fit information


This RTB has been issued to announce the release of the development units effective for Ghosting. These modified development units are based on D0163101, D0163103, D0163105, and D0163107 and are installed with titanium-coated development rollers to lower the chances of Ghosting.


New part	Description	Q'ty	Int	Page	Index	Note
number						
D0163130	DEVELOPMENT UNIT:TITANIUM:Y:ASS'Y	-	ı	89	*	
D0163131	DEVELOPMENT UNIT:TITANIUM:C:ASS'Y	-	ı	89	*	
D0163132	DEVELOPMENT UNIT:TITANIUM:M:ASS'Y	-	ı	89	*	
D0163133	DEVELOPMENT UNIT:TITANIUM:BK:ASS'Y	-	-	89	*	

Example of 'Ghosting'



61mm






Model: AG-P1/C1,AGL-P1/C1 Date: 04-Nov-10 No.: RG178126

Supplying the Modified Development Units

- ➤ The modified development units will be supplied along with D0163101, D0163103, D0163105, and D0163107 and shall be installed only when requiring support for the Ghosting issue.
- The modified development units are more expensive than the generic development units because their development rollers are coated with titanium.
- ➤ Delivery will take approximately 2 months after order placements (although this will depend on the stock.) The extra time required for delivery is due to the additional process of coating titanium over the stainless steel rollers.

Difference in Visual Appearance

Generic and modified development units can be distinguished by the color of their development rollers as the titanium-coated development rollers are gold in color. The only difference between the generic and modified development units is their development rollers.






PAGE: 2/3


PAGE: 3/3

Effect of the Development Units Installed with Titanium-coated Development Rollers

The graph below describes the relation between density differential and print volume. While stainless steel development rollers require replacement of the developer at approximately 30K, the titanium-coated development rollers lengthen the replacement interval to approximately 200K.



Density differential is calculated by making 6 measurements on a printout for locations A to F and taking the average density differentials of A-D (rear), B-E (center), and C-F (front).



IMPORTANT

- 200K should be regarded as a reference, because accuracy in confirming Ghosting by visual appearance and effectiveness of the modified development unit will vary depending on the printed images.
- The modified development unit is effective but will not completely eliminate Ghosting. This must be explained to and agreed by the customer in advance.
- All 4 development units (Y, C, M, Bk) must be replaced as a set. Replacement of only one color will have no effect for images containing 2 or more colors.

Technical Bulletin

PAGE: 1/25

Model: AG-P1 / C1 Date			e: 29-Nov	No.: RG178127		
Subject: Mercury decal issue of Aegis			Prepared by: H.Matsui			
From: PPBG Service Planning Dept.						
Classification:	Troubleshooting	☐ Part info	ormat	tion		required
	☐ Mechanical	☐ Electrica	al		Service	e manual revision
	☐ Paper path	Transm	it/rec	eive	Retrof	it information
	☐ Product Safety	Other ()	☐ Tier 2	

Please be noted that this RTB is targeted only for the **NA market**.

GENERAL

Many of the Aegis installed in the field had not been attached with the prescribed decal that indicates that the control panel of the unit contains mercury, which violates the state of Vermont's laws (and several other states) in the U.S.


We kindly request you to attach the prescribed decal to the units on your next service visit.

SOLUTION

Please order the following decal and attach it to the Electrical Box for the affected units on your next service visit.

Part Number	Description
G1789910	DECAL:VERMONT:2
Lamp(s) in LCD Pan ning Unit Contain N Dispose According State or Federal La	ercury, to Local,

Where to attach the decal





PAGE: 2/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

Affected Units

Pre Production Units

Affected pre-production units are registered with the following serial numbers and have been installed in the field before Nov 2008.

No	Product Description	Serial Numbers	Number of affected units
1	Pro C900	S3280700002 ~ S3281000179	136

Mass Production Units

Affected mass production units manufactured in Feb 2010 are registered with the following serial numbers.

No	Product Description	Serial Numbers	Number of affected units
1	Pro C720	S9704900001 ~ S9704900013	12
2	Pro C720S	V8904900001 ∼ V8904900012	12
3	Pro C900	S3286000001 ~ S3205000001	336
4	Pro C900 Base Unit	S7095500001 ~ S7095900003	9
5	Pro C900 E-80 QX	S7095400001 ~ S7095900002	10
6	Pro C900 C-80 CREO	S7004900001 ~ S7095900009	13
7	Pro C900s	M8704900001 \sim M8796000033	456
8	Pro C900S E-80 QX	V7495700001 ∼ V7495900007	16

Model: AG-P1 / C1

Technical Bulletin

Date: 29-Nov-10 No.: RG178127

PAGE: 3/25

Supplementary Explanation of Machine Serial Numbers

The serial number of a mass production unit is an 11 digit number which is composed of tht MC type No., production year, production month (+48), and a 5 digit sequential number.

(Pre-production units do not use the above numbering system.)

Example of a serial number registered for a Pro C900 machine

Model / Brand	Serial number - numbering method.
G17817	S32
	Mc type No. Year (Month+48) (Sequential numbering from 00001 each month.)
	Serial number "S3294900017" is composed of the following information:
	● Mc Type No. = S32 (Pro C900)
	• Year = 9 (2009 production)
	• Month +48 = 49 $(49 - 48 = 1 = January production)$
	• Sequential Number = 00017
	This indicates that the unit is a Pro C900 and was the 17 th unit manufactured in the month of January in year 2009.
	(*) Year = 0 indicates that the unit was manufactured in year 2010.

Table of MC Type No.

No	Product Description	MC type NO.
1	Pro C720	S97
2	Pro C720S	V89
3	Pro C900	S32
4	Pro C900 Base Unit	S70
5	Pro C900 E-80 QX	S70
6	Pro C900 C-80 CREO	S70
7	Pro C900s	M87
8	Pro C900S E-80 QX	V74



Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

PAGE: 4/25

Serial Numbers of Affected Pre Production Units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	-	S3280700002	C900	2008/09/16
2	-	S3280700003	C900	2008/09/12
3	-	S3280700004	C900	2008/09/12
4	-	S3280700005	C900	2008/09/12
5	-	S3280700006	C900	2008/09/12
6	-	S3280700007	C900	2008/09/16
7	-	S3280700008	C900	2008/09/29
8	-	S3280700009	C900	2008/09/16
9	-	S3280700010	C900	2008/09/16
10	-	S3280700011	C900	2008/09/16
11	-	S3280700012	C900	2008/09/12
12	-	S3280700013	C900	2008/09/29
13	-	S3280700014	C900	2008/09/29
14	-	S3280700015	C900	2008/09/29
15	-	S3280700017	C900	2008/10/01
16	-	S3280700019	C900	2008/10/01
17	-	S3280700020	C900	2008/09/30
18	-	S3280700021	C900	2008/09/16
19	-	S3280700022	C900	2008/09/30
20	-	S3280700023	C900	2008/09/30
21	-	S3280700046	C900	2008/09/30
22	-	S3280700047	C900	2008/10/01
23	-	S3280700048	C900	2008/09/30
24	-	S3280700049	C900	2008/10/01
25	-	S3280700051	C900	2008/10/02
26	-	S3280700052	C900	2008/10/02
27	-	S3280800001	C900	2008/10/20
28	-	S3280800002	C900	2008/10/20
29	-	S3280800003	C900	2008/10/20
30	-	S3280800004	C900	2008/10/20
31	-	S3280800005	C900	2008/10/20
32	-	S3280800006	C900	2008/10/20
33	-	S3281000001	C900	2008/10/20
34	-	S3281000002	C900	2008/10/20
35	-	S3281000003	C900	2008/10/20
36	-	S3281000004	C900	2008/10/27
37	-	S3281000005	C900	2008/10/20
38	-	S3281000006	C900	2008/10/20
39	-	S3281000007	C900	2008/10/20
40	-	S3281000008	C900	2008/10/20
41	-	S3281000009	C900	2008/10/20
42	-	S3281000010	C900	2008/10/20
43	-	S3281000011	C900	2008/10/21
44	-	S3281000012	C900	2008/10/22
45	-	S3281000013	C900	2008/10/21
46	-	S3281000014	C900	2008/11/05
47	-	S3281000015	C900	2008/10/23
48	_	S3281000016	C900	2008/10/27
49	_	S3281000017	C900	2008/10/27
50	-	S3281000018	C900	2008/10/23
55		00201000010	3000	2000/10/20



PAGE: 5/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

No.	Serial #	MB&R Serial #	Product Description	Completion Date
51	- Serial #	S3281000019	C900	2008/10/23
52	<u> </u>	S3281000019	C900	2008/10/23
53	<u>-</u>	S3281000020	C900	2008/10/29
54		S3281000021	C900	2008/10/29
55	-		C900	
56	-	S3281000023		2008/10/28
57	-	S3281000024	C900 C900	2008/10/28 2008/10/28
58	-	S3281000025	C900	2008/10/28
59		S3281000026		
	-	S3281000027	C900	2008/10/28
60 61	-	S3281000028	C900	2008/11/05
	-	S3281000029	C900	2008/10/29
62	-	S3281000030	C900	2008/10/28
63	-	S3281000031	C900	2008/10/28
64	-	S3281000032	C900	2008/10/30
65	-	S3281000033	C900	2008/10/29
66	-	S3281000034	C900	2008/10/30
67	-	S3281000035	C900	2008/10/29
68	-	S3281000036	C900	2008/10/29
69	-	S3281000038	C900	2008/10/29
70	-	S3281000039	C900	2008/10/29
71	-	S3281000040	C900	2008/10/29
72	-	S3281000041	C900	2008/10/29
73	-	S3281000042	C900	2008/10/29
74	-	S3281000043	C900	2008/11/06
75	-	S3281000044	C900	2008/10/30
76	-	S3281000045	C900	2008/10/30
77	-	S3281000046	C900	2008/10/29
78	-	S3281000047	C900	2008/10/29
79	-	S3281000048	C900	2008/10/29
80	-	S3281000049	C900	2008/10/29
81	-	S3281000050	C900	2008/11/04
82	-	S3281000051	C900	2008/11/06
83	-	S3281000052	C900	2008/10/31
84	-	S3281000053	C900	2008/11/04
85	-	S3281000054	C900	2008/10/31
86	-	S3281000055	C900	2008/10/31
87	-	S3281000056	C900	2008/11/05
88	-	S3281000057	C900	2008/11/04
89	-	S3281000058	C900	2008/10/31
90		S3281000059	C900	2008/11/06
91	-	S3281000060	C900	2008/10/31
92	-	S3281000061	C900	2008/11/04
93	-	S3281000062	C900	2008/11/04
94	-	S3281000063	C900	2008/10/31
95	-	S3281000064	C900	2008/11/05
96	-	S3281000065	C900	2008/10/31
97	-	S3281000067	C900	2008/11/05
98	-	S3281000068	C900	2008/11/05
99	-	S3281000069	C900	2008/11/04
100	-	S3281000070	C900	2008/11/04



PAGE: 6/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

	900. 136 un		Duadust Description	Commission Data
No.	Serial #	MB&R Serial #	Product Description	Completion Date
101	-	S3281000071	C900	2008/11/04
102	-	S3281000072	C900	2008/11/06
103	-	S3281000073	C900	2008/11/04
104	-	S3281000074	C900	2008/10/31
105	-	S3281000075	C900	2008/11/04
106	-	S3281000076	C900	2008/11/07
107	-	S3281000077	C900	2008/11/05
108	-	S3281000078	C900	2008/11/12
109	-	S3281000079	C900	2008/10/31
110	-	S3281000080	C900	2008/11/04
111	-	S3281000081	C900	2008/10/31
112	-	S3281000082	C900	2008/11/10
113	-	S3281000083	C900	2008/11/06
114	-	S3281000084	C900	2008/11/05
115	-	S3281000085	C900	2008/11/05
116	-	S3281000086	C900	2008/11/05
117	-	S3281000087	C900	2008/10/27
118	-	S3281000088	C900	2008/10/27
119	-	S3281000089	C900	2008/11/06
120	-	S3281000090	C900	2008/10/28
121	-	S3281000091	C900	2008/11/10
122	-	S3281000092	C900	2008/10/27
123	-	S3281000093	C900	2008/10/27
124	-	S3281000094	C900	2008/10/27
125	-	S3281000095	C900	2008/10/27
126	-	S3281000096	C900	2008/10/27
127	-	S3281000097	C900	2008/10/27
128	-	S3281000098	C900	2008/11/10
129	-	S3281000099	C900	2008/10/27
130	-	S3281000100	C900	2008/10/27
131	-	S3281000101	C900	2008/10/30
132	-	S3281000102	C900	2008/10/27
133	-	S3281000103	C900	2008/10/27
134	-	S3281000104	C900	2008/10/27
135	-	S3281000178	C900	2008/10/28
136	-	S3281000179	C900	2008/10/30

Technical Bulletin

Date: 29-Nov-10 No.: RG178127

PAGE: 7/25

Serial Numbers of Affected Mass Production Units

Pro C720: 12 units

Model: AG-P1 / C1

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	S9704900001	S9691280032	Pro C720	2010/1/25
2	S9704900002	S9691280030	Pro C720	2010/1/25
3	S9704900003	S9691280026	Pro C720	2010/1/25
4	S9704900004	S9691280025	Pro C720	2010/1/25
5	S9704900005	S9691280024	Pro C720	2010/1/25
6	S9704900006	S9691280017	Pro C720	2010/1/25
7	S9704900007	S9691280008	Pro C720	2010/1/26
8	S9704900008	S9691280012	Pro C720	2010/1/26
9	S9704900009	S9691280021	Pro C720	2010/1/27
10	S9704900010	S9691280011	Pro C720	2010/1/27
11	S9704900011	S9691280020	Pro C720	2010/1/27
12	S9704900013	S9691280029	Pro C720	2010/1/27

Pro C720S: 12 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	V8904900001	S9691280033	Pro C720s	2010/1/25
2	V8904900002	S9691280034	Pro C720s	2010/1/25
3	V8904900003	S9691280027	Pro C720s	2010/1/25
4	V8904900004	S9691280023	Pro C720s	2010/1/25
5	V8904900005	S9691280006	Pro C720s	2010/1/26
6	V8904900006	S9691280010	Pro C720s	2010/1/26
7	V8904900007	S9691280013	Pro C720s	2010/1/26
8	V8904900008	S9691280015	Pro C720s	2010/1/26
9	V8904900009	S9691280028	Pro C720s	2010/1/26
10	V8904900010	S9691280022	Pro C720s	2010/1/27
11	V8904900011	S9691280031	Pro C720s	2010/1/26
12	V8904900012	S9691280018	Pro C720s	2010/1/27

Pro C900 base Unit: 9 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	S7095500001	S7090580013	Pro C900 Base Unit	2009/7/17
2	S7095500002	S7090580015	Pro C900 Base Unit	2009/7/17
3	S7095600001	S7090580010	Pro C900 Base Unit	2009/8/7
4	S7095600002	S7090580006	Pro C900 Base Unit	2009/8/27
5	S7095800001	S7090580009	Pro C900 Base Unit	2009/10/2
6	S7095800002	S7090580001	Pro C900 Base Unit	2009/10/2
7	S7095800003	S7090580008	Pro C900 Base Unit	2009/10/2
8	S7095800004	S7090480007	Pro C900 Base Unit	2009/10/13
9	S7095900003	S7090880001	Pro C900 Base Unit	2009/11/5



PAGE: 8/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

Pro C	Pro C900: 336 units					
No.	Serial #	MB&R Serial #	Product Description	Completion Date		
1	S3286000001	S3281080030	Pro C900	2008/12/11		
2	S3286000002	S3281080053	Pro C900	2008/12/11		
3	S3286000003	S3281080061	Pro C900	2008/12/23		
4	S3286000004	S3281080056	Pro C900	2009/2/18		
5	S3286000005	S3281080048	Pro C900	2008/12/11		
6	S3286000006	S3281080055	Pro C900	2008/12/11		
7	S3286000007	S3281080051	Pro C900	2008/12/11		
8	S3286000008	S3281080050	Pro C900	2008/12/11		
9	S3286000009	S3281080018	Pro C900	2008/12/12		
10	S3286000010	S3281080033	Pro C900	2008/12/11		
11	S3286000011	S3281080047	Pro C900	2008/12/11		
12	S3286000012	S3281080072	Pro C900	2008/12/12		
13	S3286000013	S3281080057	Pro C900	2008/12/12		
14	S3286000014	S3281080066	Pro C900	2008/12/12		
15	S3286000015	S3281080035	Pro C900	2008/12/12		
16	S3286000016	S3281080060	Pro C900	2008/12/12		
17	S3286000017	S3281080058	Pro C900	2008/12/15		
18	S3286000018	S3281080054	Pro C900	2008/12/12		
19	S3286000019	S3281080046	Pro C900	2008/12/15		
20	S3286000020	S3281080006	Pro C900	2008/12/16		
21	S3286000021	S3281080064	Pro C900	2008/12/15		
22	S3286000022	S3281080059	Pro C900	2008/12/22		
23	S3286000023	S3281080052	Pro C900	2008/12/16		
24	S3286000024	S3281080036	Pro C900	2008/12/15		
25	S3286000025	S3281080028	Pro C900	2008/12/16		
26	S3286000026	S3281080043	Pro C900	2008/12/16		
27	S3286000027	S3281080071	Pro C900	2008/12/16		
28	S3286000028	S3281080063	Pro C900	2008/12/16		
29	S3286000029	S3281080029	Pro C900	2008/12/17		
30	S3286000030	S3281080025	Pro C900	2008/12/17		
31	S3286000031	S3281080001	Pro C900	2008/12/17		
32	S3286000032	S3281080032	Pro C900	2008/12/17		
33	S3286000033	S3281080031	Pro C900	2008/12/18		
34	S3286000034	S3281080005	Pro C900	2008/12/18		
35	S3286000035	S3281080026	Pro C900	2008/12/17		
36	S3286000036	S3281080012	Pro C900	2008/12/18		
37	S3286000037	S3281080049	Pro C900	2008/12/19		
38	S3286000038	S3281080037	Pro C900	2008/12/19		
39	S3286000039	S3281080017	Pro C900	2008/12/19		
40	S3286000040	S3281080045	Pro C900	2008/12/18		
41	S3286000041	S3281080042	Pro C900	2008/12/18		
46	S3286000042	S3281080038	Pro C900	2008/12/18		
42	S3286000043	S3281080041	Pro C900	2009/1/5		
43	S3286000044	S3281080039	Pro C900	2008/12/19		
44	S3286000045	S3281180009	Pro C900	2008/12/19		
45	S3286000046	S3281080082	Pro C900	2008/12/22		
47	S3286000047	S3281080086	Pro C900	2008/12/19		
48	S3286000048	S3281080040	Pro C900	2009/1/5		
49	S3286000049	S3281080013	Pro C900	2009/1/5		
50	S3286000050	S3281080021	Pro C900	2009/1/5		

Technical Bulletin

PAGE: 9/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

	2900: 336 units			
No.	Serial #	MB&R Serial #	Product Description	Completion Date
51	S3294900001	S3281180022	Pro C900	2009/1/6
52	S3294900002	S3281180020	Pro C900	2009/1/6
53	S3294900003	S3281180005	Pro C900	2009/1/6
54	S3294900004	S3281180008	Pro C900	2009/1/6
55	S3294900005	S3281180028	Pro C900	2009/1/6
56	S3294900006	S3281180035	Pro C900	2009/1/7
57	S3294900007	S3281180039	Pro C900	2009/1/7
58	S3294900008	S3281180013	Pro C900	2009/1/6
59	S3294900009	S3281180029	Pro C900	2009/1/12
60	S3294900010	S3281180024	Pro C900	2009/1/7
61	S3294900011	S3281180023	Pro C900	2009/1/7
62	S3294900012	S3281080003	Pro C900	2009/1/9
63	S3294900013	S3281180032	Pro C900	2009/1/7
64	S3294900014	S3281080010	Pro C900	2009/1/7
65	S3294900015	S3281080008	Pro C900	2009/1/8
66	S3294900016	S3281080002	Pro C900	2009/1/7
67	S3294900017	S3281080016	Pro C900	2009/1/12
68	S3294900018	S3281080007	Pro C900	2009/1/8
69	S3294900019	S3281180002	Pro C900	2009/1/8
70	S3294900020	S3281180018	Pro C900	2009/1/8
71	S3294900021	S3281180012	Pro C900	2009/1/8
72	S3294900022	S3281180025	Pro C900	2009/1/8
73	S3294900023	S3281180019	Pro C900	2009/1/9
74	S3294900024	S3281180010	Pro C900	2009/1/9
75	S3294900025	S3281180014	Pro C900	2009/1/9
76	S3294900026	S3281180033	Pro C900	2009/1/9
77	S3294900027	S3281180021	Pro C900	2009/1/9
78	S3294900028	S3281080078	Pro C900	2009/1/9
79	S3294900029	S3281180036	Pro C900	2009/1/12
80	S3294900030	S3281180016	Pro C900	2009/1/13
81	S3294900031	S3281080065	Pro C900	2009/1/12
82	S3294900032	S3281080062	Pro C900	2009/1/13
83	S3294900033	S3281080088	Pro C900	2009/1/12
84	S3294900034	S3281080068	Pro C900	2009/1/12
85	S3294900035	S3281080079	Pro C900	2009/1/13
86	S3294900036	S3281080084	Pro C900	2009/1/14
87	S3294900037	S3281280062	Pro C900	2009/1/14
88	S3294900038	S3281280051	Pro C900	2009/1/13
89	S3294900039	S3281280052	Pro C900	2009/1/13
90	S3294900040	S3281280049	Pro C900	2009/1/14
91	S3294900041	S3281280081	Pro C900	2009/1/14
92	S3294900042	S3281280047	Pro C900	2009/1/14
93	S3294900043	S3281280044	Pro C900	2009/1/13
94	S3294900044	S3281280046	Pro C900	2009/1/15
95	S3294900045	S3281280054	Pro C900	2009/1/15
96	S3294900046	S3281280035	Pro C900	2009/1/15
97	S3294900047	S3281280036	Pro C900	2009/1/15
98	S3294900048	S3281280056	Pro C900	2009/1/15
99	S3294900049	S3281280074	Pro C900	2009/1/14
100	S3294900050	S3281280082	Pro C900	2009/1/16
100	0020 - 300000	00201200002	1 10 0300	2003/1/10

Technical Bulletin

PAGE: 10/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

	2900: 336 units	MD0D Ossiel #	Duradicat Description	Ozwalstian Data
No.	Serial #	MB&R Serial #	Product Description	Completion Date
101	S3294900051	S3281280092	Pro C900	2009/1/16
102	S3294900052	S3281280080	Pro C900	2009/1/16
103	S3294900053	S3281280042	Pro C900	2009/1/16
104	S3294900054	S3281280053	Pro C900	2009/1/16
105	S3294900055	S3281280038	Pro C900	2009/1/15
106	S3294900056	S3281080020	Pro C900	2009/1/19
107	S3294900057	S3281080074	Pro C900	2009/1/19
108	S3294900058	S3281180007	Pro C900	2009/1/16
109	S3294900059	S3281080070	Pro C900	2009/1/20
110	S3294900060	S3281080075	Pro C900	2009/1/19
111	S3294900061	S3281080011	Pro C900	2009/1/19
112	S3294900062	S3281080083	Pro C900	2009/1/20
113	S3294900063	S3281080090	Pro C900	2009/1/20
114	S3294900064	S3281080009	Pro C900	2009/1/20
115	S3294900065	S3281080015	Pro C900	2009/1/21
116	S3294900066	S3281080073	Pro C900	2009/1/19
117	S3294900067	S3281080080	Pro C900	2009/1/19
118	S3294900068	S3281080014	Pro C900	2009/1/20
119	S3294900069	S3281080022	Pro C900	2009/1/21
120	S3294900070	S3281080023	Pro C900	2009/1/21
121	S3294900071	S3281080004	Pro C900	2009/3/2
122	S3294900072	S3281080027	Pro C900	2009/1/21
123	S3294900073	S3281080019	Pro C900	2009/1/20
124	S3294900074	S3281080034	Pro C900	2009/3/2
125	S3294900075	S3281080044	Pro C900	2009/3/2
126	S3294900076	S3281080024	Pro C900	2009/3/2
127	S3294900077	S3281080085	Pro C900	2009/3/2
128	S3294900078	S3281180037	Pro C900	2009/3/3
129	S3294900079	S3281180015	Pro C900	2009/3/2
130	S3294900080	S3281080081	Pro C900	2009/3/2
131	S3294900081	S3281180030	Pro C900	2009/3/2
132	S3294900082	S3281180011	Pro C900	2009/3/2
133	S3294900083	S3281080077	Pro C900	2009/3/2
134	S3294900084	S3281080076	Pro C900	2009/3/4
135	S3294900085	S3281180027	Pro C900	2009/3/2
136	S3294900086	S3281180040	Pro C900	2009/3/2
137	S3294900087	S3281180017	Pro C900	2009/3/2
138	S3294900088	S3281180034	Pro C900	2009/3/2
139	S3294900089	S3281180003	Pro C900	2009/3/3
140	S3294900090	S3281180006	Pro C900	2009/3/2
141	S3294900091	S3281180004	Pro C900	2009/3/3
142	S3294900092	S3281180001	Pro C900	2009/3/2
143	S3294900093	S3281180038	Pro C900	2009/3/3
144	S3294900094	S3281180031	Pro C900	2009/3/3
145	S3295000001	S3281280117	Pro C900	2009/3/3
146	S3295000001 S3295000002	S3290180074	Pro C900	2009/2/17
147	S3295000002 S3295000003	S3281280136	Pro C900	2009/2/17
148	S3295000003 S3295000004	S3281180042	Pro C900	2009/2/17
149	S3295300004 S3295300001	S3281280079	Pro C900	2009/2/25
150	S3295300002	S3281280142	Pro C900	2009/5/11

Technical Bulletin

PAGE: 11/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

P10 (Pro C900: 336 units					
No.	Serial #	MB&R Serial #	Product Description	Completion Date		
151	S3295300004	S3281280126	Pro C900	2009/5/15		
152	S3295300005	S3281280087	Pro C900	2009/5/19		
153	S3295300006	S3290180058	Pro C900	2009/6/3		
154	S3295300007	S3290180065	Pro C900	2009/6/2		
155	S3295400001	S3281280022	Pro C900	2009/6/3		
156	S3295400003	S3281280021	Pro C900	2009/6/3		
157	S3295400004	S3281280075	Pro C900	2009/6/3		
158	S3295400005	S3281280040	Pro C900	2009/6/4		
159	S3295400006	S3281280094	Pro C900	2009/6/4		
160	S3295400007	S3281280033	Pro C900	2009/6/4		
161	S3295400008	S3281280045	Pro C900	2009/6/4		
162	S3295400009	S3281280067	Pro C900	2009/6/5		
163	S3295400010	S3281280023	Pro C900	2009/6/5		
164	S3295400011	S3281280154	Pro C900	2009/6/5		
165	S3295400012	S3281280158	Pro C900	2009/6/5		
166	S3295400013	S3281280149	Pro C900	2009/6/8		
167	S3295400014	S3281280153	Pro C900	2009/6/8		
168	S3295400015	S3281280167	Pro C900	2009/6/8		
169	S3295400016	S3281280147	Pro C900	2009/6/8		
170	S3295400017	S3290180040	Pro C900	2009/6/9		
171	S3295400018	S3281280166	Pro C900	2009/6/9		
172	S3295400019	S3281280084	Pro C900	2009/6/9		
173	S3295400020	S3281280180	Pro C900	2009/6/9		
174	S3295400021	S3290180042	Pro C900	2009/6/26		
175	S3295400022	S3290180095	Pro C900	2009/6/26		
176	S3295500001	S3290180068	Pro C900	2009/7/7		
177	S3295500002	S3290180073	Pro C900	2009/7/7		
178	S3295500003	S3290180045	Pro C900	2009/7/7		
179	S3295500004	S3290180090	Pro C900	2009/7/9		
180	S3295500005	S3290180034	Pro C900	2009/7/9		
181	S3295500006	S3290180077	Pro C900	2009/7/9		
182	S3295500007	S3290180106	Pro C900	2009/7/9		
183	S3295500008	S3290180085	Pro C900	2009/7/13		
184	S3295500009	S3290180104	Pro C900	2009/7/9		
185	S3295500010	S3290180124	Pro C900	2009/7/10		
186	S3295500011	S3290180129	Pro C900	2009/7/10		
187	S3295500013	S3290180130	Pro C900	2009/7/13		
188	S3295500014	S3290180061	Pro C900	2009/7/10		
189	S3295500015	S3290180003	Pro C900	2009/7/16		
190	S3295500016	S3290180007	Pro C900	2009/7/17		
191	S3295500017	S3290180008	Pro C900	2009/7/17		
192	S3295500018	S3290180084	Pro C900	2009/7/16		
193	S3295500019	S3290180030	Pro C900	2009/7/17		
194	S3295500020	S3290180014	Pro C900	2009/7/17		
195	S3295500021	S3290180083	Pro C900	2009/7/17		
196	S3295500022	S3290180012	Pro C900	2009/7/17		
197	S3295500023	S3290180121	Pro C900	2009/7/17		
198	S3295500024	S3290180006	Pro C900	2009/7/17		
199	S3295500025	S3290180024	Pro C900	2009/7/20		
200	S3295500026	S3290180117	Pro C900	2009/7/20		

Technical Bulletin

PAGE: 12/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

No.	Serial #	MB&R Serial #	Product Description	Completion Date
201	S3295500027	S3290180098	Pro C900	2009/7/20
202	S3295500028	S3290180063	Pro C900	2009/7/20
203	S3295500029	S3290180114	Pro C900	2009/7/20
204	S3295500030	S3290180046	Pro C900	2009/7/20
205	S3295500031	S3290180122	Pro C900	2009/7/21
206	S3295500031	S3290180122 S3290180110	Pro C900	2009/7/21
207	S3295500032	S3290180050	Pro C900	2009/7/21
208	S3295500034	S3290180030 S3290180027	Pro C900	2009/7/21
209	S3295500035	S3290180100 S3290180100	Pro C900	2009/7/21
210	S3295500036	S3290180100 S3290180025	Pro C900	2009/7/21
211	S3295500037		Pro C900	
212		S3290180039	Pro C900	2009/7/21
	S3295500038	S3290280012	-	2009/9/4
123	S3295500039	S3290280015	Pro C900	2009/7/31
214	S3295500040	S3290280042	Pro C900	2009/9/1
215	S3295500041	S3290280022	Pro C900	2009/9/1
216	S3295500042	S3290280001	Pro C900	2009/7/31
217	S3295500043	S3290280005	Pro C900	2009/8/13
218	S3295700001	S3290780032	Pro C900	2009/9/11
219	S3295700002	S3290780035	Pro C900	2009/9/11
220	S3295700003	S3290780033	Pro C900	2009/9/11
221	S3295700004	S3290780046	Pro C900	2009/9/11
222	S3295700005	S3290780049	Pro C900	2009/9/11
223	S3295700006	S3290880028	Pro C900	2009/9/15
224	S3295700007	S3290880017	Pro C900	2009/9/14
225	S3295700008	S3290880031	Pro C900	2009/9/14
226	S3295700009	S3290880019	Pro C900	2009/9/15
227	S3295700010	S3290880025	Pro C900	2009/9/16
228	S3295700011	S3290880024	Pro C900	2009/9/18
229	S3295700012	S3290880018	Pro C900	2009/9/18
230	S3295700013	S3290880013	Pro C900	2009/9/22
231	S3295700014	S3290880005	Pro C900	2009/9/22
232	S3295700015	S3290880014	Pro C900	2009/9/22
233	S3295700016	S3290880049	Pro C900	2009/9/23
234	S3295700017	S3290880056	Pro C900	2009/9/23
235	S3295700018	S3290880012	Pro C900	2009/9/23
236	S3295700019	S3290880004	Pro C900	2009/9/23
237	S3295700020	S3290880047	Pro C900	2009/9/24
238	S3295700021	S3290880052	Pro C900	2009/9/24
239	S3295700022	S3290880007	Pro C900	2009/9/24
240	S3295700023	S3290880002	Pro C900	2009/9/25
241	S3295700024	S3290880038	Pro C900	2009/9/25
242	S3295700025	S3290880009	Pro C900	2009/9/25
243	S3295700026	S3290880006	Pro C900	2009/9/28
244	S3295700027	S3290880001	Pro C900	2009/9/28
246	S3295700028	S3290780048	Pro C900	2009/10/2
247	S3295700029	S3290780044	Pro C900	2009/10/5
248	S3295700030	S3290780031	Pro C900	2009/10/2
245	S3295700031	S3290880021	Pro C900	2009/9/28
249	S3295800001	S3290880036	Pro C900	2009/10/5
250	S3295800002	S3290780047	Pro C900	2009/10/5

Technical Bulletin

PAGE: 13/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

	2900: 336 units	MD®D Coriol #	Draduct Description	Completion Date
No.	Serial #	MB&R Serial #	Product Description	Completion Date
251	S3295800003	S3290880043	Pro C900	2009/10/5
252	S3295800004	S3290880053	Pro C900	2009/10/5
253	S3295800005	S3290880015	Pro C900	2009/10/6
254	S3295800006	S3290880046	Pro C900	2009/10/6
255	S3295800007	S3290880055	Pro C900	2009/10/6
256	S3295800008	S3290880074	Pro C900	2009/10/16
257	S3295800009	S3290880079	Pro C900	2009/10/16
258	S3295800010	S3290880078	Pro C900	2009/10/16
259	S3295800011	S3290880072	Pro C900	2009/10/16
260	S3295800012	S3290880081	Pro C900	2009/10/16
261	S3295800013	S3290980010	Pro C900	2009/10/20
262	S3295800014	S3290880080	Pro C900	2009/10/20
263	S3295800015	S3290880085	Pro C900	2009/10/21
264	S3295800016	S3290980009	Pro C900	2009/10/21
265	S3295800017	S3290980001	Pro C900	2009/10/21
266	S3295800018	S3290980002	Pro C900	2009/10/21
267	S3295800019	S3290980008	Pro C900	2009/10/22
268	S3295800020	S3290880042	Pro C900	2009/10/22
269	S3295800021	S3290880045	Pro C900	2009/10/22
270	S3295800022	S3290880050	Pro C900	2009/10/23
271	S3295800023	S3290880061	Pro C900	2009/10/23
272	S3295800024	S3290880051	Pro C900	2009/10/23
273	S3295800025	S3290880029	Pro C900	2009/10/23
274	S3295800026	S3290880035	Pro C900	2009/10/26
275	S3295800027	S3290880039	Pro C900	2009/10/26
276	S3295800028	S3290880034	Pro C900	2009/10/26
277	S3295800029	S3290880073	Pro C900	2009/10/26
278	S3295800030	S3290980019	Pro C900	2009/10/30
279	S3295800031	S3290980030	Pro C900	2009/10/30
280	S3295800032	S3290980025	Pro C900	2009/10/30
281	S3295800033	S3290980028	Pro C900	2009/10/30
282	S3295900001	S3290980040	Pro C900	2009/11/9
283	S3295900002	S3290980043	Pro C900	2009/11/9
284	S3295900003	S3290980035	Pro C900	2009/11/9
285	S3295900004	S3290980047	Pro C900	2009/11/17
286	S3295900005	S3290980049	Pro C900	2009/11/19
287	S3295900006	S3290980055	Pro C900	2009/11/19
288	S3295900007	S3290980029	Pro C900	2009/11/19
289	S329600001	S3291080016	Pro C900	2009/11/13
290	S3296000001 S3296000002	S3291080015	Pro C900	2009/12/2
291	S3296000002 S3296000003		Pro C900	2009/12/1
		S3291080011		
292	S3296000004	S3291080004	Pro C900	2009/12/2
293	S3296000005	S3291080029	Pro C900	2009/12/7
294	S3296000006	S3291080043	Pro C900	2009/12/7
295	S3296000007	S3291080044	Pro C900	2009/12/8
296	S3296000008	S3291080017	Pro C900	2009/12/9
297	S3296000009	S3291080021	Pro C900	2009/12/9
298	S3296000010	S3291180021	Pro C900	2009/12/14
299	S3296000011	S3291180023	Pro C900	2009/12/14
300	S3296000012	S3291180017	Pro C900	2009/12/15

Technical Bulletin

PAGE: 14/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

LIO (Pro C900: 336 units						
No.	Serial #	MB&R Serial #	Product Description	Completion Date			
301	S3296000013	S3291180020	Pro C900	2009/12/15			
302	S3296000014	S3291180019	Pro C900	2009/12/15			
303	S3296000015	S3291180016	Pro C900	2009/12/15			
304	S3296000016	S3291180015	Pro C900	2009/12/15			
305	S3296000017	S3291180014	Pro C900	2009/12/16			
306	S3296000018	S3291180010	Pro C900	2009/12/16			
307	S3296000019	S3291180011	Pro C900	2009/12/16			
308	S3296000020	S3291180018	Pro C900	2009/12/16			
309	S3296000021	S3291180022	Pro C900	2009/12/17			
310	S3296000022	S3291180025	Pro C900	2009/12/17			
311	S3296000023	S3291180034	Pro C900	2009/12/18			
312	S3296000024	S3291180039	Pro C900	2009/12/18			
313	S3296000025	S3291180035	Pro C900	2009/12/18			
314	S3296000026	S3291180046	Pro C900	2009/12/21			
315	S3296000027	S3291180041	Pro C900	2009/12/22			
316	S3296000028	S3291180040	Pro C900	2009/12/22			
317	S3296000029	S3291180036	Pro C900	2009/12/22			
318	S3296000030	S3291180037	Pro C900	2009/12/23			
319	S3296000031	S3291180038	Pro C900	2009/12/23			
320	S3296000032	S3291180029	Pro C900	2009/12/22			
321	S3296000033	S3291180024	Pro C900	2009/12/23			
322	S3296000034	S3291180033	Pro C900	2009/12/22			
323	S3296000035	S3291180032	Pro C900	2009/12/23			
324	S3296000036	S3291180002	Pro C900	2009/12/23			
325	S3296000037	S3291180028	Pro C900	2009/12/30			
326	S3296000038	S3291180027	Pro C900	2009/12/23			
327	S3296000039	S3291180030	Pro C900	2009/12/29			
328	S3296000040	S3291180007	Pro C900	2009/12/29			
329	S3296000041	S3291180044	Pro C900	2009/12/29			
330	S3296000042	S3291180031	Pro C900	2009/12/29			
331	S3296000043	S3291180004	Pro C900	2009/12/30			
332	S3296000044	S3291180042	Pro C900	2009/12/30			
333	S3296000045	S3291180048	Pro C900	2010/1/5			
334	S3296000046	S3291080040	Pro C900	2010/1/5			
335	S3296000047	S3291180043	Pro C900	2010/1/5			
336	S3205000001	S3291280004	Pro C900	2010/2/3			



PAGE: 15/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

Pro C900 Base Unit: 9 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	S7095500001	S7090580013	Pro C900 Base Unit	2009/7/17
2	S7095500002	S7090580015	Pro C900 Base Unit	2009/7/17
3	S7095600001	S7090580010	Pro C900 Base Unit	2009/8/7
4	S7095600002	S7090580006	Pro C900 Base Unit	2009/8/27
5	S7095800001	S7090580009	Pro C900 Base Unit	2009/10/2
6	S7095800002	S7090580001	Pro C900 Base Unit	2009/10/2
7	S7095800003	S7090580008	Pro C900 Base Unit	2009/10/2
8	S7095800004	S7090480007	Pro C900 Base Unit	2009/10/13
9	S7095900003	S7090880001	Pro C900 Base Unit	2009/11/5

Pro C900 E-80 QX: 10 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	S7095400001	S7090480006	Pro C900 E-80 QX	2009/7/21
2	S7095500003	S7090580014	Pro C900 E-80 QX	2009/9/18
3	S7095500004	S7090580017	Pro C900 E-80 QX	2009/7/22
4	S7095500005	S7090580011	Pro C900 E-80 QX	2009/7/22
5	S7095500006	S7090580018	Pro C900 E-80 QX	2009/7/23
6	S7095500007	S7090580012	Pro C900 E-80 QX	2009/7/22
7	S7095500008	S7090580016	Pro C900 E-80 QX	2009/7/23
8	S7095800005	S7090480009	Pro C900 E-80 QX	2009/10/22
9	S7095900001	S7090880006	Pro C900 E-80 QX	2009/11/4
10	S7095900002	S7090980026	Pro C900 E-80 QX	2009/11/4

Pro C900 C-80 CREO: 13 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	S7004900001	S7090780007	Pro C900 C-80 CREO	2010/1/6
2	S7004900002	S7090780001	Pro C900 C-80 CREO	2010/1/6
3	S7004900003	S7090780009	Pro C900 C-80 CREO	2010/1/6
4	S7004900004	S7090780004	Pro C900 C-80 CREO	2010/1/6
5	S7004900005	S7090780006	Pro C900 C-80 CREO	2010/1/7
6	S7004900006	S7090780002	Pro C900 C-80 CREO	2010/1/7
7	S7004900009	S7090780015	Pro C900 C-80 CREO	2010/1/29
8	S7004900010	S7090780011	Pro C900 C-80 CREO	2010/1/29
9	S7095900005	S7090780005	Pro C900 C-80 CREO	2009/12/1
10	S7095900006	S7090780021	Pro C900 C-80 CREO	2009/12/1
11	S7095900007	S7090780003	Pro C900 C-80 CREO	2009/12/1
12	S7095900008	S7090780008	Pro C900 C-80 CREO	2009/12/1
13	S7095900009	S7090780014	Pro C900 C-80 CREO	2009/12/1



PAGE: 16/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

Pro C900S: 456 units					
No.	Serial #	MB&R Serial #	Product Description	Completion Date	
1	M8704900001	S3290580001	Pro C900S	2010/1/28	
2	M8704900002	S3291280041	Pro C900S	2010/1/29	
3	M8704900003	S3291280034	Pro C900S	2010/1/29	
4	M8704900004	S3291280021	Pro C900S	2010/1/29	
5	M8704900005	S3291280040	Pro C900S	2010/1/29	
6	M8704900006	S3291280033	Pro C900S	2010/1/29	
7	M8704900007	S3291280029	Pro C900S	2010/1/29	
8	M8704900008	S3291280042	Pro C900S	2010/1/29	
9	M8704900009	S3291280032	Pro C900S	2010/1/29	
10	M8704900010	S3291280026	Pro C900S	2010/2/1	
11	M8704900011	S3291280023	Pro C900S	2010/2/1	
12	M8704900012	S3291280020	Pro C900S	2010/2/1	
13	M8704900013	S3291280003	Pro C900S	2010/2/1	
14	M8704900014	S3291280024	Pro C900S	2010/2/1	
15	M8705000001	S3291280007	Pro C900S	2010/2/1	
16	M8705000002	S3291280013	Pro C900S	2010/2/2	
17	M8705000003	S3291280009	Pro C900S	2010/2/2	
18	M8705000004	S3291280006	Pro C900S	2010/2/2	
19	M8705000005	S3291280015	Pro C900S	2010/2/2	
20	M8705000006	S3291280016	Pro C900S	2010/2/2	
21	M8705000007	S3291280010	Pro C900S	2010/2/2	
22	M8705000008	S3291280014	Pro C900S	2010/2/2	
23	M8705000009	S3291280037	Pro C900S	2010/2/2	
24	M8705000010	S3291280035	Pro C900S	2010/2/3	
25	M8795000001	S3281280105	Pro C900S	2009/2/18	
26	M8795000002	S3281280150	Pro C900S	2009/2/17	
27	M8795000003	S3281280148	Pro C900S	2009/2/18	
28	M8795000004	S3281280123	Pro C900S	2009/2/12	
29	M8795000005	S3281280029	Pro C900S	2009/2/13	
30	M8795000006	S3281280002	Pro C900S	2009/2/16	
31	M8795000007	S3281280010	Pro C900S	2009/2/13	
32	M8795000008	S3281280020	Pro C900S	2009/2/13	
33	M8795000009	S3281280124	Pro C900S	2009/2/13	
34	M8795000010	S3281280120	Pro C900S	2009/2/16	
35	M8795000011	S3281280129	Pro C900S	2009/2/13	
36	M8795000012	S3281280127	Pro C900S	2009/2/16	
37	M8795000013	S3281280125	Pro C900S	2009/2/16	
38	M8795000014	S3281280130	Pro C900S	2009/2/16	
39	M8795000015	S3281280133	Pro C900S	2009/2/17	
40	M8795000016	S3281280131	Pro C900S	2009/2/17	
41	M8795000017	S3281280134	Pro C900S	2009/2/18	
46	M8795000018	S3281280113	Pro C900S	2009/2/18	
42	M8795000019	S3281280115	Pro C900S	2009/2/18	
43	M8795000020	S3281280135	Pro C900S	2009/2/19	
44	M8795000021	S3281280101	Pro C900S	2009/2/20	
45	M8795000022	S3281280102	Pro C900S	2009/2/20	
47	M8795000023	S3281280090	Pro C900S	2009/2/19	
48	M8795000024	S3281280043	Pro C900S	2009/2/19	
49	M8795000025	S3281280093	Pro C900S	2009/2/19	
50	M8795000026	S3281280097	Pro C900S	2009/2/19	

Technical Bulletin

PAGE: 17/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

No.	Serial #	MB&R Serial #	Product Description	Completion Date
51	M8795000027			2009/2/20
		S3281280066	Pro C900S	
52	M8795000028	S3281280099	Pro C900S	2009/2/19
53	M8795000029	S3281280028	Pro C900S	2009/2/20
54	M8795000030	S3281280037	Pro C900S	2009/3/2
55	M8795000031	S3281280008	Pro C900S	2009/3/2
56	M8795000032	S3281280083	Pro C900S	2009/3/2
57	M8795000033	S3281280031	Pro C900S	2009/2/25
58	M8795200001	S3281280009	Pro C900S	2009/4/7
59	M8795200002	S3281080069	Pro C900S	2009/4/7
60	M8795200003	S3281180041	Pro C900S	2009/4/7
61	M8795200004	S3281180043	Pro C900S	2009/4/8
62	M8795200005	S3281180044	Pro C900S	2009/4/8
63	M8795200006	S3281280175	Pro C900S	2009/4/8
64	M8795200007	S3281280024	Pro C900S	2009/4/8
65	M8795200008	S3281280039	Pro C900S	2009/4/9
66	M8795200009	S3281280015	Pro C900S	2009/4/9
67	M8795200010	S3281280012	Pro C900S	2009/4/14
68	M8795200011	S3281280003	Pro C900S	2009/4/14
69	M8795200012	S3281280114	Pro C900S	2009/4/14
70	M8795200013	S3281280057	Pro C900S	2009/4/15
71	M8795200014	S3281280030	Pro C900S	2009/4/15
72	M8795200015	S3281280017	Pro C900S	2009/4/15
73	M8795200016	S3281280006	Pro C900S	2009/4/16
74	M8795200017	S3281280027	Pro C900S	2009/4/16
75	M8795200018	S3281280013	Pro C900S	2009/4/16
76	M8795200019	S3281280026	Pro C900S	2009/4/16
77	M8795200020	S3281280025	Pro C900S	2009/4/17
78	M8795200021	S3281180026	Pro C900S	2009/4/17
79	M8795200022	S3281280004	Pro C900S	2009/4/20
80	M8795200023	S3281280098	Pro C900S	2009/4/20
81	M8795200024	S3281280107	Pro C900S	2009/4/20
82	M8795200025	S3281280005	Pro C900S	2009/5/1
83	M8795200026	S3281280103	Pro C900S	2009/4/23
84	M8795200027	S3281280085	Pro C900S	2009/4/23
85	M8795200028	S3281280118	Pro C900S	2009/4/24
86	M8795300001	S3281280108	Pro C900S	2009/5/6
87	M8795300002	S3281280072	Pro C900S	2009/5/11
88	M8795300003	S3281280116	Pro C900S	2009/5/5
89	M8795300004	S3281280159	Pro C900S	2009/5/5
90	M8795300005	S3281280157	Pro C900S	2009/5/6
91	M8795300005 M8795300006	S3281280095	Pro C900S	2009/5/6
92	M8795300007	S3281280086	Pro C900S	2009/5/6
93	M8795300007 M8795300008	S3281280059	Pro C900S	2009/5/6
94	M8795300009	S3281280171	Pro C900S	2009/5/7
95			Pro C900S	2009/5/7
	M8795300010	S3281280128		
96	M8795300011	S3281280096	Pro C900S	2009/5/7
97	M8795300012	S3281280019	Pro C900S	2009/5/21
98	M8795300013	S3281280007	Pro C900S	2009/5/7
99	M8795300014	S3281280001	Pro C900S	2009/5/7
100	M8795300015	S3281280172	Pro C900S	2009/5/7

Technical Bulletin

PAGE: 18/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

No.	Serial #	MB&R Serial #	Product Description	Completion Date
101	M8795300016	S3281280165	Pro C900S	2009/5/7
102	M8795300017	S3281280041	Pro C900S	2009/5/8
103	M8795300018	S3281280137	Pro C900S	2009/5/8
104	M8795300019	S3290180036	Pro C900S	2009/5/8
105	M8795300020	S3281280156	Pro C900S	2009/5/8
106	M8795300021	S3281280181	Pro C900S	2009/5/8
107	M8795300022	S3281280160	Pro C900S	2009/5/11
108	M8795300023	S3281280076	Pro C900S	2009/5/12
109	M8795300024	S3281280164	Pro C900S	2009/5/12
110	M8795300025	S3281280162	Pro C900S	2009/5/12
111	M8795300026	S3281280151	Pro C900S	2009/5/12
112	M8795300027	S3281280161	Pro C900S	2009/5/13
113	M8795300028	S3281280065	Pro C900S	2009/5/13
114	M8795300029	S3281280174	Pro C900S	2009/5/13
115	M8795300030	S3281280152	Pro C900S	2009/5/13
116	M8795300031	S3281280061	Pro C900S	2009/5/14
117	M8795300032	S3281280014	Pro C900S	2009/5/14
118	M8795300033	S3281280050	Pro C900S	2009/5/14
119	M8795300034	S3281280048	Pro C900S	2009/5/14
120	M8795300035	S3281280060	Pro C900S	2009/5/15
121	M8795300036	S3281280170	Pro C900S	2009/5/15
122	M8795300037	S3281280163	Pro C900S	2009/5/15
123	M8795300038	S3281280179	Pro C900S	2009/5/15
124	M8795300039	S3281280071	Pro C900S	2009/5/18
125	M8795300040	S3281280141	Pro C900S	2009/5/18
126	M8795300041	S3281280100	Pro C900S	2009/5/18
127	M8795300042	S3281180045	Pro C900S	2009/5/19
128	M8795300043	S3281280016	Pro C900S	2009/5/18
129	M8795300044	S3281280018	Pro C900S	2009/5/19
130	M8795300045	S3281280068	Pro C900S	2009/5/21
131	M8795300046	S3281280073	Pro C900S	2009/5/20
132	M8795300047	S3281280169	Pro C900S	2009/5/20
133	M8795300048	S3281280069	Pro C900S	2009/5/20
134	M8795300049	S3281280112	Pro C900S	2009/5/21
135	M8795300050	S3281280143	Pro C900S	2009/5/22
136	M8795300051	S3281280178	Pro C900S	2009/5/21
137	M8795300052	S3281280122	Pro C900S	2009/5/22
138	M8795300053	S3281280055	Pro C900S	2009/5/26
139	M8795300054	S3290180081	Pro C900S	2009/5/22
140	M8795300055	S3281280078	Pro C900S	2009/5/26
141	M8795300056	S3281280011	Pro C900S	2009/5/26
142	M8795300057	S3281280064	Pro C900S	2009/5/26
143	M8795300057 M8795300058	S3281280088	Pro C900S	2009/5/27
144	M8795300059	S3290180079	Pro C900S	2009/5/27
145		S3290180079	Pro C900S	2009/5/27
	M8795300060			
146	M8795300061	S3290180009	Pro C900S	2009/5/27
147	M8795300062	S3290180016	Pro C900S	2009/5/27
148	M8795300063	S3290180087	Pro C900S	2009/5/27
149	M8795300064	S3290180059	Pro C900S	2009/5/28
150	M8795300065	S3290180010	Pro C900S	2009/5/28

Technical Bulletin

PAGE: 19/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

	29005: 456 units	MB&R Serial #	Product Description	Completion Date
No.	Serial #		_	Completion Date
151	M8795300066	S3281280145	Pro C900S	2009/5/28
152	M8795300067	S3281280139	Pro C900S	2009/5/28
153	M8795300068	S3281280155	Pro C900S	2009/5/28
154	M8795300069	S3281280110	Pro C900S	2009/5/28
155	M8795300070	S3281280034	Pro C900S	2009/5/29
156	M8795300071	S3281280063	Pro C900S	2009/5/29
157	M8795300072	S3281280032	Pro C900S	2009/5/29
158	M8795300073	S3281280106	Pro C900S	2009/5/29
159	M8795300074	S3281280104	Pro C900S	2009/6/22
160	M8795300075	S3281280138	Pro C900S	2009/5/29
161	M8795300076	S3281280144	Pro C900S	2009/6/1
162	M8795300077	S3281280140	Pro C900S	2009/6/1
163	M8795400001	S3281280119	Pro C900S	2009/6/1
164	M8795400002	S3281080067	Pro C900S	2009/6/1
165	M8795400003	S3281280146	Pro C900S	2009/6/1
166	M8795400004	S3281280121	Pro C900S	2009/6/2
167	M8795400005	S3281280109	Pro C900S	2009/6/2
168	M8795400006	S3281280132	Pro C900S	2009/6/2
169	M8795400009	S3290180031	Pro C900S	2009/6/19
170	M8795400010	S3281280176	Pro C900S	2009/6/19
171	M8795400011	S3281280173	Pro C900S	2009/6/23
172	M8795400012	S3281280168	Pro C900S	2009/6/22
173	M8795400013	S3281280070	Pro C900S	2009/6/23
174	M8795400014	S3281280091	Pro C900S	2009/6/23
175	M8795400015	S3281280077	Pro C900S	2009/6/23
176	M8795400016	S3281280089	Pro C900S	2009/6/23
177	M8795400017	S3281280058	Pro C900S	2009/6/24
178	M8795400018	S3281280177	Pro C900S	2009/6/23
179	M8795400019	S3290180070	Pro C900S	2009/6/24
180	M8795400019	S3290180019	Pro C900S	2009/6/24
181	M8795400021	S3290180057	Pro C900S	2009/6/24
182	M8795400021	S3290180052	Pro C900S	2009/6/25
183	M8795400022	S3290180011	Pro C900S	2009/6/25
184	M8795400024	S3290180056	Pro C900S	2009/6/26
185	M8795400024	S3290180000 S3290180002	Pro C900S	2009/6/26
186	M8795500001	S3290180002 S3290180041	Pro C900S	2009/6/20
		S3290180041 S3290180062		
187	M8795500002		Pro C900S	2009/7/6
188	M8795500003	S3290180060	Pro C900S	2009/7/7
189	M8795500004	S3290180028	Pro C900S	2009/7/8
190	M8795500005	S3290280009	Pro C900S	2009/7/8
191	M8795500006	S3290180127	Pro C900S	2009/7/8
192	M8795500007	S3290180078	Pro C900S	2009/7/8
193	M8795500008	S3290180102	Pro C900S	2009/7/15
194	M8795500009	S3290180107	Pro C900S	2009/7/8
195	M8795500010	S3290180072	Pro C900S	2009/7/9
196	M8795500011	S3290180076	Pro C900S	2009/7/9
197	M8795500013	S3290180099	Pro C900S	2009/7/14
198	M8795500014	S3290180022	Pro C900S	2009/7/10
199	M8795500015	S3290180055	Pro C900S	2009/7/10
200	M8795500016	S3290180044	Pro C900S	2009/7/13

Technical Bulletin

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

PAGE: 20/25

	2900S: 456 units		1	
No.	Serial #	MB&R Serial #	Product Description	Completion Date
201	M8795500017	S3290180066	Pro C900S	2009/7/13
202	M8795500018	S3290180105	Pro C900S	2009/7/13
203	M8795500019	S3290180021	Pro C900S	2009/7/13
204	M8795500020	S3290180048	Pro C900S	2009/7/13
205	M8795500021	S3290180133	Pro C900S	2009/7/13
206	M8795500022	S3290180054	Pro C900S	2009/7/14
207	M8795500023	S3290180067	Pro C900S	2009/7/14
208	M8795500024	S3290180116	Pro C900S	2009/7/14
209	M8795500025	S3290180035	Pro C900S	2009/7/14
210	M8795500026	S3290180125	Pro C900S	2009/7/14
211	M8795500027	S3290180082	Pro C900S	2009/7/14
212	M8795500028	S3290180108	Pro C900S	2009/7/15
123	M8795500029	S3290180118	Pro C900S	2009/7/15
214	M8795500030	S3290180119	Pro C900S	2009/7/15
215	M8795500031	S3290180001	Pro C900S	2009/7/15
216	M8795500032	S3290180005	Pro C900S	2009/7/15
217	M8795500033	S3290180103	Pro C900S	2009/7/15
218	M8795500034	S3290180051	Pro C900S	2009/7/15
219	M8795500035	S3290180123	Pro C900S	2009/7/16
220	M8795500036	S3290180109	Pro C900S	2009/7/16
221	M8795500037	S3290180049	Pro C900S	2009/7/16
222	M8795500038	S3290180071	Pro C900S	2009/7/16
223	M8795500039	S3290180094	Pro C900S	2009/7/23
224	M8795500040	S3290180029	Pro C900S	2009/7/23
225	M8795500041	S3290180089	Pro C900S	2009/7/23
226	M8795500042	S3290180086	Pro C900S	2009/7/23
227	M8795500043	S3290180015	Pro C900S	2009/7/24
228	M8795500044	S3290180120	Pro C900S	2009/7/24
229	M8795500045	S3290180004	Pro C900S	2009/7/24
230	M8795500046	S3290180020	Pro C900S	2009/7/24
231	M8795500047	S3290180064	Pro C900S	2009/7/24
232	M8795500048	S3290180112	Pro C900S	2009/7/24
233	M8795500049	S3290180023	Pro C900S	2009/7/24
234	M8795500050	S3290280007	Pro C900S	2009/7/27
235	M8795500051	S3290180026	Pro C900S	2009/7/27
236	M8795500052	S3290180018	Pro C900S	2009/7/27
237	M8795500053	S3290180088	Pro C900S	2009/7/27
238	M8795500054	S3290180017	Pro C900S	2009/7/27
239	M8795500055	S3290180047	Pro C900S	2009/7/27
240	M8795500056	S3290180080	Pro C900S	2009/7/28
241	M8795500057	S3290180101	Pro C900S	2009/7/27
242	M8795500058	S3290280055	Pro C900S	2009/7/28
243	M8795500059	S3290280019	Pro C900S	2009/7/28
244	M8795500060	S3290280026	Pro C900S	2009/7/28
246	M8795500061	S3290280013	Pro C900S	2009/7/28
247	M8795500062	S3290280041	Pro C900S	2009/7/28
248	M8795500063	S3290280031	Pro C900S	2009/7/29
245	M8795500064	S3290280025	Pro C900S	2009/7/29
249	M8795500065	S3290280017	Pro C900S	2009/7/29
250	M8795500066	S3290280043	Pro C900S	2009/9/4

Technical Bulletin

PAGE: 21/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

No.	Serial #	MB&R Serial #	Product Description	Completion Date
			_	
251	M8795500067	S3290280024	Pro C900S	2009/7/29
252	M8795500068	S3290280008	Pro C900S	2009/9/4
253	M8795500069	S3290280027	Pro C900S	2009/8/13
254	M8795500070	S3290280004	Pro C900S	2009/9/1
255	M8795500071	S3290280003	Pro C900S	2009/7/30
256	M8795500072	S3290280044	Pro C900S	2009/7/30
257	M8795500073	S3290280016	Pro C900S	2009/7/31
258	M8795500074	S3290180115	Pro C900S	2009/8/3
259	M8795500075	S3290180069	Pro C900S	2009/8/3
260	M8795500076	S3290180092	Pro C900S	2009/8/3
261	M8795500077	S3290180097	Pro C900S	2009/8/3
262	M8795600001	S3290280059	Pro C900S	2009/8/4
263	M8795600002	S3290180043	Pro C900S	2009/8/4
264	M8795600003	S3290180037	Pro C900S	2009/8/4
265	M8795600004	S3290180091	Pro C900S	2009/8/5
266	M8795600005	S3290180053	Pro C900S	2009/8/5
267	M8795600006	S3290180013	Pro C900S	2009/8/31
268	M8795600007	S3290280020	Pro C900S	2009/9/1
269	M8795600008	S3290180032	Pro C900S	2009/8/5
270	M8795600009	S3290180128	Pro C900S	2009/8/5
271	M8795600010	S3290180093	Pro C900S	2009/8/6
272	M8795600011	S3290180126	Pro C900S	2009/8/6
273	M8795600012	S3290280014	Pro C900S	2009/8/31
274	M8795600013	S3290280010	Pro C900S	2009/9/1
275	M8795600014	S3290180075	Pro C900S	2009/8/11
276	M8795600015	S3290180131	Pro C900S	2009/8/11
277	M8795600016	S3290180038	Pro C900S	2009/8/12
278	M8795600017	S3290280011	Pro C900S	2009/9/1
279	M8795600018	S3290180132	Pro C900S	2009/8/12
280	M8795600019	S3290180096	Pro C900S	2009/8/12
281	M8795600020	S3290780017	Pro C900S	2009/8/26
282	M8795600021	S3290180113	Pro C900S	2009/8/20
283	M8795600022	S3290180111	Pro C900S	2009/8/21
284	M8795600023	S3290280002	Pro C900S	2009/8/21
285	M8795600024	S3290280006	Pro C900S	2009/9/1
286	M8795600025	S3290780010	Pro C900S	2009/8/27
287	M8795600026	S3290780004	Pro C900S	2009/8/31
288	M8795600027	S3290780016	Pro C900S	2009/8/31
289	M8795600028	S3290780020	Pro C900S	2009/8/31
290	M8795600029	S3290780018	Pro C900S	2009/8/31
291	M8795600029	S32907800010	Pro C900S	2009/8/31
292	M8795600031	S3290780002 S3290780005	Pro C900S	2009/8/31
293	M8795600031	S3290780003	Pro C900S	2009/8/31
294	M8795600032	S3290780007	Pro C900S	2009/9/1
295		S3290780007 S3290780006	Pro C900S	2009/9/2
	M8795600034	S3290780006 S3290780001		2009/9/2
296	M8795700001		Pro C900S	
297	M8795700002	S3290780012	Pro C900S	2009/9/2
298	M8795700003	S3290780009	Pro C900S	2009/9/3
299	M8795700004	S3290780019	Pro C900S	2009/9/2
300	M8795700005	S3290780011	Pro C900S	2009/9/3

Technical Bulletin

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

PAGE: 22/25

	3900S: 456 units			II 2
No.	Serial #	MB&R Serial #	Product Description	Completion Date
301	M8795700006	S3290780022	Pro C900S	2009/9/3
302	M8795700007	S3290780003	Pro C900S	2009/9/3
303	M8795700008	S3290780013	Pro C900S	2009/9/3
304	M8795700009	S3290780015	Pro C900S	2009/9/4
305	M8795700010	S3290780023	Pro C900S	2009/9/4
306	M8795700011	S3290780026	Pro C900S	2009/9/8
307	M8795700012	S3290780029	Pro C900S	2009/9/8
308	M8795700013	S3290780014	Pro C900S	2009/9/8
309	M8795700014	S3290780043	Pro C900S	2009/9/9
310	M8795700015	S3290780036	Pro C900S	2009/9/8
311	M8795700016	S3290780038	Pro C900S	2009/9/9
312	M8795700017	S3290780039	Pro C900S	2009/9/9
313	M8795700018	S3290780040	Pro C900S	2009/9/9
314	M8795700019	S3290780024	Pro C900S	2009/9/9
315	M8795700020	S3290780027	Pro C900S	2009/9/10
316	M8795700021	S3290780021	Pro C900S	2009/9/29
317	M8795700022	S3290780034	Pro C900S	2009/9/10
318	M8795700023	S3290780041	Pro C900S	2009/9/10
319	M8795700024	S3290780030	Pro C900S	2009/9/10
320	M8795700025	S3290780028	Pro C900S	2009/9/10
321	M8795700026	S3290780042	Pro C900S	2009/9/11
322	M8795700027	S3290780037	Pro C900S	2009/9/16
323	M8795700028	S3290780025	Pro C900S	2009/9/16
324	M8795700029	S3290880020	Pro C900S	2009/9/17
325	M8795700030	S3290880023	Pro C900S	2009/9/16
326	M8795700031	S3290880026	Pro C900S	2009/9/17
327	M8795700032	S3290880030	Pro C900S	2009/9/21
328	M8795700033	S3290880027	Pro C900S	2009/9/17
329	M8795700034	S3290880022	Pro C900S	2009/9/21
330	M8795700035	S3290880016	Pro C900S	2009/9/18
331	M8795700036	S3290780045	Pro C900S	2009/9/23
332	M8795700037	S3290880062	Pro C900S	2009/9/25
333	M8795700038	S3290880048	Pro C900S	2009/9/28
334	M8795700039	S3290880032	Pro C900S	2009/9/28
335	M8795800001	S3290880008	Pro C900S	2009/10/8
336	M8795800002	S3290880041	Pro C900S	2009/10/8
337	M8795800003	S3290880037	Pro C900S	2009/10/8
338	M8795800004	S3290880063	Pro C900S	2009/10/8
339	M8795800005	S3290880060	Pro C900S	2009/10/8
340	M8795800006	S3290880065	Pro C900S	2009/10/9
341	M8795800007	S3290880058	Pro C900S	2009/10/9
342	M8795800008	S3290880011	Pro C900S	2009/10/9
343	M8795800009	S3290880010	Pro C900S	2009/10/12
344	M8795800010	S3290880075	Pro C900S	2009/10/12
345	M8795800011	S3290880033	Pro C900S	2009/10/9
346	M8795800012	S3290880067	Pro C900S	2009/10/12
347	M8795800013	S3290880069	Pro C900S	2009/10/12
348	M8795800014	S3290880059	Pro C900S	2009/10/13
349	M8795800015	S3290880068	Pro C900S	2009/10/13
350	M8795800016	S3290880057	Pro C900S	2009/10/13
				====:

Technical Bulletin

PAGE: 23/25 Date: 29-Nov-10 No.: RG178127

Pro C900S: 456 units

Model: AG-P1 / C1

	2900S: 456 units	MD0D Ossiel #	Duradicat Danamintian	Ormanistica Data
No.	Serial #	MB&R Serial #	Product Description	Completion Date
351	M8795800017	S3290880066	Pro C900S	2009/10/14
352	M8795800018	S3290880044	Pro C900S	2009/10/14
353	M8795800019	S3290880040	Pro C900S	2009/10/14
354	M8795800020	S3290880077	Pro C900S	2009/10/15
355	M8795800021	S3290880070	Pro C900S	2009/10/14
356	M8795800022	S3290880054	Pro C900S	2009/10/15
357	M8795800023	S3290880076	Pro C900S	2009/10/15
358	M8795800024	S3290880064	Pro C900S	2009/10/16
359	M8795800025	S3290980007	Pro C900S	2009/10/19
360	M8795800026	S3290980013	Pro C900S	2009/10/19
361	M8795800027	S3290880083	Pro C900S	2009/10/19
362	M8795800028	S3290880084	Pro C900S	2009/10/19
363	M8795800029	S3290880082	Pro C900S	2009/10/23
364	M8795800030	S3290880071	Pro C900S	2009/10/20
365	M8795800031	S3290980011	Pro C900S	2009/10/20
366	M8795800032	S3290980012	Pro C900S	2009/10/22
367	M8795800033	S3290980005	Pro C900S	2009/10/22
368	M8795800034	S3290980044	Pro C900S	2009/10/27
369	M8795800035	S3290980048	Pro C900S	2009/10/27
370	M8795800036	S3290980020	Pro C900S	2009/10/27
371	M8795800037	S3290880003	Pro C900S	2009/10/28
372	M8795800038	S3290980034	Pro C900S	2009/10/27
373	M8795800039	S3290980021	Pro C900S	2009/10/28
374	M8795800040	S3290980022	Pro C900S	2009/10/28
375	M8795800041	S3290980015	Pro C900S	2009/10/28
376	M8795800042	S3290980014	Pro C900S	2009/10/29
377	M8795800044	S3290980006	Pro C900S	2009/10/29
378	M8795800045	S3290980003	Pro C900S	2009/10/29
379	M8795800046	S3290980004	Pro C900S	2009/10/30
380	M8795800048	S3290980039	Pro C900S	2009/11/4
381	M8795800049	S3290980045	Pro C900S	2009/11/4
382	M8795800050	S3290980054	Pro C900S	2009/11/4
383	M8795800051	S3290980056	Pro C900S	2009/11/4
384	M8795900001	S3290980065	Pro C900S	2009/11/4
385	M8795900002	S3290980058	Pro C900S	2009/11/4
386	M8795900003	S3290980053	Pro C900S	2009/11/5
387	M8795900004	S3290980066	Pro C900S	2009/11/5
388	M8795900005	S3290980064	Pro C900S	2009/11/6
389	M8795900006	S3290980067	Pro C900S	2009/11/6
390	M8795900007	S3290980046	Pro C900S	2009/11/6
391	M8795900008	S3290980026	Pro C900S	2009/11/6
392	M8795900009	S3290980016	Pro C900S	2009/11/11
393	M8795900010	S3290980018	Pro C900S	2009/11/11
394	M8795900011	S3290980024	Pro C900S	2009/11/11
395	M8795900012	S3290980017	Pro C900S	2009/11/11
396	M8795900013	S3290980057	Pro C900S	2009/11/17
397	M8795900014	S3290980050	Pro C900S	2009/11/19
398	M8795900015	S3290980033	Pro C900S	2009/11/20
399	M8795900016	S3290980038	Pro C900S	2009/11/20
400	M8795900017	S3290980037	Pro C900S	2009/11/20

Model: AG-P1 / C1

Technical Bulletin

Date: 29-Nov-10 No.: RG178127

PAGE: 24/25

	29005: 456 UNITS	MDOD Coriol #	Braduot Description	Completion Date	
No.	Serial #	MB&R Serial #	Product Description	Completion Date	
401	M8795900018	S3290980032	Pro C900S	2009/11/20	
402	M8795900019	S3290980036	Pro C900S	2009/11/23	
403	M8795900020	S3290980027	Pro C900S	2009/11/23	
404	M8795900021	S3290980031	Pro C900S	2009/11/23	
405	M8795900022	S3290980061	Pro C900S	2009/11/24	
406	M8795900023	S3290980023	Pro C900S	2009/11/24	
407	M8795900024	S3290980059	Pro C900S	2009/11/24	
408	M8795900025	S3290980063	Pro C900S	2009/11/24	
409	M8795900026	S3290980060	Pro C900S	2009/11/25	
410	M8795900027	S3290980062	Pro C900S	2009/11/25	
411	M8795900028	S3290980042	Pro C900S	2009/11/25	
412	M8795900029	S3290980041	Pro C900S	2009/11/25	
413	M8795900030	S3290980052	Pro C900S	2009/11/30	
414	M8795900031	S3290980051	Pro C900S	2009/11/30	
415	M8795900032	S3291080008	Pro C900S	2009/11/30	
416	M8795900033	S3291080003	Pro C900S	2009/11/30	
417	M8795900034	S3291080034	Pro C900S	2009/11/30	
418	M8795900035	S3291080036	Pro C900S	2009/11/30	
419	M8795900036	S3291080010	Pro C900S	2009/12/1	
420	M8795900037	S3291080006	Pro C900S	2009/12/1	
421	M8795900038	S3291080002	Pro C900S	2009/12/1	
422	M8795900039	S3291080019	Pro C900S	2009/12/1	
423	M8795900040	S3291080007	Pro C900S	2009/12/2	
424	M8796000001	S3291080005	Pro C900S	2009/12/2	
425	M8796000002	S3291080012	Pro C900S	2009/12/2	
426	M8796000003	S3291080018	Pro C900S	2009/12/2	
427	M8796000004	S3291080014	Pro C900S	2009/12/3	
428	M8796000005	S3291080013	Pro C900S	2009/12/3	
429	M8796000006	S3291080041	Pro C900S	2009/12/3	
430	M8796000007	S3291080033	Pro C900S	2009/12/3	
431	M8796000008	S3291080037	Pro C900S	2009/12/3	
432	M8796000009	S3291080032	Pro C900S	2009/12/3	
433	M8796000010	S3291080035	Pro C900S	2009/12/3	
434	M8796000011	S3291080038	Pro C900S	2009/12/4	
435	M8796000012	S3291080027	Pro C900S	2009/12/4	
436	M8796000012	S3291080026	Pro C900S	2009/12/4	
437	M8796000014	S3291080031	Pro C900S	2009/12/4	
438	M8796000015	S3291080028	Pro C900S	2009/12/4	
439	M8796000015	S3291080039	Pro C900S	2009/12/7	
440	M8796000017	S3291080039	Pro C900S	2009/12/7	
441	M8796000017 M8796000018	S3291080024 S3291080042	Pro C900S	2009/12/7	
442	M8796000019	S3291080042	Pro C900S	2009/12/8	
443	M8796000019	S3291080025	Pro C900S	2009/12/8	
444	M8796000020	S3291080030	Pro C900S	2009/12/8	
444	M8796000021		Pro C900S	2009/12/8	
		S3291180013	Pro C900S		
446	M8796000023	S3291180012		2009/12/9	
447	M8796000024	S3291180005	Pro C900S	2009/12/9	
448	M8796000025	S3291080023	Pro C900S	2009/12/9	
449	M8796000026	S3291180009	Pro C900S	2009/12/16	
450	M8796000027	S3291180008	Pro C900S	2009/12/16	

Technical Bulletin

PAGE: 25/25

Model: AG-P1 / C1 Date: 29-Nov-10 No.: RG178127

Pro C900S: 456 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
451	M8796000028	S3291080020	Pro C900S	2009/12/16
452	M8796000029	S3291080022	Pro C900S	2009/12/16
453	M8796000030	S3291180026	Pro C900S	2009/12/23
454	M8796000031	S3291180006	Pro C900S	2009/12/23
455	M8796000032	S3291180003	Pro C900S	2009/12/29
456	M8796000033	S3291180045	Pro C900S	2009/12/29

Pro C900S E-80 QX: 16 units

No.	Serial #	MB&R Serial #	Product Description	Completion Date
1	V7495700001	S7090580007	Pro C900S E-80 QX	2009/9/23
2	V7495700002	S7090580003	Pro C900S E-80 QX	2009/9/22
3	V7495700003	S7090580004	Pro C900S E-80 QX	2009/9/24
4	V7495700004	S7090880003	Pro C900S E-80 QX	2009/9/24
5	V7495700005	S7090580005	Pro C900S E-80 QX	2009/9/25
6	V7495800001	S7090580002	Pro C900S E-80 QX	2009/10/6
7	V7495800002	S7090480004	Pro C900S E-80 QX	2009/10/7
8	V7495800003	S7090480005	Pro C900S E-80 QX	2009/10/7
9	V7495800004	S7090480008	Pro C900S E-80 QX	2009/10/7
10	V7495900001	S7090880004	Pro C900S E-80 QX	2009/11/5
11	V7495900002	S7090880002	Pro C900S E-80 QX	2009/11/17
12	V7495900003	S7090880005	Pro C900S E-80 QX	2009/11/17
13	V7495900004	S7090780016	Pro C900S E-80 QX	2009/11/17
14	V7495900005	S7090780022	Pro C900S E-80 QX	2009/11/17
15	V7495900006	S7090780019	Pro C900S E-80 QX	2009/11/19
16	V7495900007	S7090780020	Pro C900S E-80 QX	2009/11/20

Technical Bulletin

PAGE: 1/9

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5	Date: 06-Dec-10	No.: RG178128d
---	-----------------	----------------

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Notes on Handling PCDUs to prevent drum scratching			Prepared by: H. Kawamura	
From: PPBG Ser	vice Planning Dept.			
Classification:		☐ Part information	on Action required	
	☐ Mechanical	☐ Electrical	☐ Service manual revision	
	☐ Paper path	☐ Transmit/recei	ve Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the correct handling procedure of the PCDU* to prevent scratches on the drum, which occurs when the PG* is narrower at the front side of the drum than the rear side.

NOTE

- * PCDU includes the photoconductive drums and the development units.
- * PG is the gap between the drum and the development rollers


1. Primary Considerations When Handling the PCDU

Take note of the information in the following section to avoid the problems listed below.

- 1) Different density between left and right sides on a page
- 2) Toner adhesion to the development rollers
- 3) Scratches on the drums resulting from toner adhesion to the development rollers
- 4) Toner clumps caused by narrowed PG

1-1. Confirming Attachment of the Inner Cover

The Inner Cover must always be fastened with the 3 screws circled in blue in the photo below when in operation. Note that these screws not only function to hold the cover but fix the PCDU to the mainframe.



Confirm complete fastening of the 3 screws.



Never operate the machine without the Inner Cover or the screws.

The development unit will be positioned incorrectly when operated without the Inner Cover and the screws, causing scratches on the drum surface and uneven image density.

PAGE: 2/9

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

1-2. Confirming Correct Installation of the Developer Unit

- Proper engagement of the drum internal and drum drive external gears -

Make sure the development unit is correctly installed by checking the appearance of the knob and the screw holes.

When the development unit is correctly installed...







The surface of the knob and the adjacent area (black-colored) is almost flush, as shown in the left photo. Also, the screw holes for attaching the inner cover should be clearly visible as shown in the center and right photos.

When the development unit is incorrectly installed...







The surface of the knob is clearly protruding against the adjacent area (black-colored) and the screw holes are sunk in and are not clearly visible, as shown in the photos above. In this case, the unit is bounced back towards the front side because the drum internal and drum drive external gears are not properly engaged as shown below.





Drum internal gear





Technical Bulletin

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d


If the development unit is not correctly installed, pull out the PCDU and slightly reposition the drum so that the internal and external gears are engaged properly.





PAGE: 3/9

Do not attempt to forcefully fasten the (cross-shaped) drawer stop knob by shoving in the unit. Doing so will NOT help install the unit completely but will only damage the teeth of the internal gear.





When the gears are not engaged properly, the drum cleaning unit pushes the drum towards the direction in which the PG is narrowed. Printing in this condition will cause toner to adhere to the development rollers and generate scratches on the drum surface.

The following SCs may occur if the drum surface has been scratched and reveals the aluminum substrate.

SC error name	Color	SC code
	K	320
Development bias: high voltage error	С	321
Development bias. High voltage entit	М	322
	Υ	323

If the above SC occurs and heavy scratches are observed on the drum surface, replace the drum with a new one.

Technical Bulletin

PAGE: 4/9

Reissued: 23rd-Apr-13


Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

2. Correct Procedures for Fastening the Drum Knob

Take note of the information in the following section to avoid the problems listed below.


- 1) Different density between left and right sides on a page
- 2) Toner adhesion to the development rollers
- 3) Scratches on the drums resulting from toner adhesion to the development rollers
- 4) Toner clumps caused by narrowed PG
- Always pull out the development unit and remove the drum cleaner when fastening the drum knob.
- Never attempt to further fasten the drum knob when the drum cleaning unit is installed.





Do NOT fasten the drum knob when the development unit is installed. Do NOT fasten the drum knob when the drum cleaning unit is installed.





If the drum knob is loosened with the drum cleaning unit installed, make sure to remove the drum cleaning unit, and then fasten the knob.

Fastening the drum knob with the drum cleaning unit installed will cause the drum cleaning unit to apply pressure to the drum and narrow the PG at the front side.

Technical Bulletin


PAGE: 5/9

Reissued: 23rd-Apr-13


Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

Tighten the Drum Knob so that the groove on the Drum Knob goes past the plastic protrusion on the PCDU as shown in the photo below.

Note: Turn the drum knob until it stops and cannot be further tightened.



Correct Drum Knob Position



Incorrect Drum Knob Position


PAGE: 6/9

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

Diagrams showing the drum knob position


[Incompletely tightened drum knob] [Completely tightened drum knob]



3. Handling the Development Unit

Take note of the information in the following section to avoid the problems listed below.

- 1) Variation in image density
- 2) Different density between left and right sides on a page
- 3) Toner adhesion to the development rollers
- 4) Scratches on the drums resulting from toner adhesion to the development rollers
- 5) Toner clumps caused by narrowed PG
- Always hold the prescribed locations when handling the development unit.
- Never apply external pressure to the front and rear plates and the stay.



Do not grip the face plates or the stay.


Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d





Applying external pressure will deform the front and rear plates in vertical and horizontal directions, resulting in fluctuation of the PG.



PAGE: 7/9

4. Procedure: Remove toner adhesion on Mg sleeve that causes drum scratches


If the drum knob is not tightened completely, the PG will be narrower. As a result, drum scratching occurs. With toner adhered on the Mg sleeve, do the following procedure to repair the Mg sleeve so that you are able to use the development unit.

Step 1. Stick packing tape against the surface of the development rollers to remove toner.

- 1-1. Remove the developer from the unit.
- 1-2. Pull out the development unit and remove the drum cleaning unit and OPC drum.
- 1-3. Rotate the development rollers downwards using your fingers until the developer is completely poured out.

Note

- Be careful not to pull the top cover entrance seal when rotating the development rollers.
- Working with gloves is recommended to prevent oil on your fingers from adhering to the rollers. Make



Technical Bulletin


PAGE: 8/9

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

sure to thoroughly wash your hands in advance if gloves are not available.

1-4. Stick the packing tape against the surface of the development rollers and peel off the toner. Repeat this procedure. (Vacuuming the toner in advance will make this process easier.)





NOTE

- Make sure the packing tape adhesives do not adhere to the development rollers.
- NEVER apply solvent to remove toner from the development rollers. Solvent will dissolve the toner, which will then adhere to the development rollers even more strongly.
- Make sure to completely remove toner adhered to the development rollers. Toner will build up on any toner particles remaining on the development roller.

Step 2. Set the drum and the drum cleaning unit, and install the development unit in the mainframe.

Scratches on the drum surface may be observed in areas corresponding to the toner adhesion on the development rollers. Replace with a new drum if scratches are confirmed.

Notes on Fastening the Drum Knob. (Reference P.4 "2. Correct Procedures for Fastening the Drum Knob")

- Make sure the drum cleaning unit is not installed when setting the drum and fastening the knob.
- Turn the drum knob clockwise and check that fastening is complete.
- DO NOT 'loosen → fasten' the drum knob after installing the cleaning unit. Doing so will reduce the PG at the front side.

Step 3. Pour in the developer, and execute Process Control (SP 3-820-002).

Step 4. Print out 2 full-bleed solid images (on A4/LT-Portrait) for the required color.

Technical Bulletin

PAGE: 9/9

Reissued: 23rd-Apr-13

Model: AG-P1/C1, AGL-P1/C1, Aries-P1.5/C1.5 Date: 06-Dec-10 No.: RG178128d

Step 5. Check if the density differs between the front and rear sides of the full-bleed solid image by visual appearance.

• If density differs between the front and rear sides, do Step 6.

Step 6. Check for toner adhesion after printing.

- 6-1. Print 1000 pages of low pixel density images; density approximately 5%.
- 6-2. Pull out the development unit, and check for any scratches on the drum surface.
- 6-3. Remove the drum cleaning unit and the drum, and check for any toner adhesion on the development rollers.

If toner is not adhered to the development rollers:

- a. And if the front and rear sides appear to be the same density, the drum has no problem and is usable.
 - → Toner adhesion is expected to have been caused by 'incorrect fastening of the drum knob'.
- b. And if the front side appears dense, print another 4000 pages. If toner adhesion does not recur, the drum has no problem and is usable.
 - → Toner adhesion is expected to have been caused by 'incorrect fastening of the drum knob'.

If toner is adhered to the development rollers, PG may be exceeding the specification.

* In this case, RCL requests you to send the affected development unit to RPS-Katsuta for investigation.

Technical Bulletin

Model: AG-P1/C1,AGL-P1/C1			Date: 05	-Jan-11	No.: RG178129
Subject: Release of the Modified Fusing with "Hardened" Hot Roller			Prepared by: N.lida		
From: PPBG Service Planning Dept.					
Classification:		□ Part info	ormation	☐ Action	n required
	☐ Mechanical	☐ Electric	al	☐ Servi	ce manual revision
	☐ Paper path ☐ Transmit/receive		☐ Retrofit information		
	☐ Product Safety	\square Other ()	☐ Tier 2	?


This RTB has been issued to announce the release of the modified fusing unit targeted for users who demand better fusibility with thick paper.

Better fusibility with thick paper is made possible by the "hardened" hot roller which applies a higher nip pressure. The modified fusing unit is also effective for issues such as "wrinkles", "worm tracks", "toner blisters", and "oil stains on 1st side of duplex printing". However, due to the difference in the component parts, trade-offs such as "separation jams with thin paper" and "oil drops" do exist.

The modified fusing unit should be able to meet customer demands provided that both positive and negative effects are well understood in advance.

NOTE: The effects on fusibility will differ depending on the paper type.

Main Modified Points



	Current Fuser	Modified Fuser	Remarks
Hardness of the Hot Roller	42±3 (LTV)	55+3/-2 (HTV)	Measuring device: Asker C
Surface pressure (N/cm²)	39.4	54.2	+37%
L	19.25	18.25	
Nip width M	17.75	16.75	
(mm) S	16.25	15.25	
Pressure roller blade Oil pad Oil pan L Oil felt	Included	Elminat ed	Reduced torque

Rubber durometer (JIS-A)

PAGE: 1/15

HTV: Vulcanized in high temp - Solid 15-100 LTV: Vulcanized in low temp - Liquid 5-90



PAGE: 2/15

Model: AG-P1/C1, AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

Comparison Table

This is a comparison table describing the components that differ from the standard fusing unit. Components not described in this table are common with the standard fusing unit.

Standard Dart Numbers	Modified Dort Numbers	Q'ty	Page	Index	Note
Standard Part Numbers	Modified Part Numbers	_		*	NOLE
D0164113	D0164301	1	123	^	
FUSING UNIT:NA:ASS'Y	FUSING UNIT:NA:ASS'Y:HARD			*	
D0164114	D0164302	1	123	*	
FUSING UNIT:EU	FUSING UNIT:EU:ASS'Y:HARD				
D0164485	D0164339	1	129	12	
HOT ROLLER	HOT ROLLER:PRESS FIT:HARD				
PM 800K	PM 400K				
G1784284	AA061075	2	131	19	
SPRING:PRESSURE SUB-UNIT	COMPRESSION				
	SPRING:PRESSURE:515N				
-	AA081020	2	131	37	Add *1
	PLAIN SHAFT				
	BEARING:DIA12XDIA20X8				
-	D0164440	1	131	38	Add *1
	SHAFT:PRESSURE:ARM:HARD				
G1784255	D0164441	2	131	15	
ARM:PRESSURE SUB-UNIT	ARM:PRESSURE SUB-UNIT				
G1784276	D0164442	1	131	30	
ARM:PRESSURE SUB-UNIT:LOWER	ARM:PRESSURE SUB-UNIT:LOWER				
REAR	REAR				
G1784275	D0164443	1	131	16	
ARM:PRESSURE SUB-UNIT:LOWER	ARM:PRESSURE SUB-UNIT:LOWER				
FRONT	FRONT				
G1784354	D0164445	1	127	3	
BRACKET:WEB:DRIVE	BRACKET:WEB:DRIVE				
D0164225	D0164468	1	123	26	
COVER:FUSING UNIT:REAR	REAR COVER:HARD FUSING UNIT				
-	AA143803	2	127	200	Add *2
	FLANGED HEXAGONAL HEAD				
	BOLT:CASTER				

NOTE


The standard fusing unit CANNOT be installed with the "hardened" hot roller and modified due to the difference in the durability of the frames.



PAGE: 3/15

Model: AG-P1/C1, AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

*1) Parts indexed 37 and 38 are service parts newly added for the modified fusing unit.






PAGE: 4/15

Date: 05-Jan-11 No.: RG178129 Model: AG-P1/C1,AGL-P1/C1

*2) The screws indexed 200 have been added to the locations shown in the diagram below in the modified fusing unit.



FLANGED HEXAGONAL HEAD BOLT:CASTER



Model: AG-P1/C1, AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

How to distinguish the Standard and Modified fusing units


1. Fusing unit

Standard





Modified



PAGE: 5/15



Although the units can be distinguished by the p/n indicated on the packaging boxes, it could be tricky after the units are installed in the mainframe. To enable distinction, the modified units are marked with blue stickers on the cover and the arm as shown in the photos above.




Model: AG-P1/C1, AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

2. Hot Roller

Standard



Modified



PAGE: 6/15

The modified fusing unit is marked with a blue sticker on the outer ring of the hot roller, which becomes visible by removing the fusing knob.

* Do NOT attempt to install the hardened hot roller in a standard fusing unit, and vice versa. Nip width and relative properties will not meet their target values and could result in jams, SCs, and image problems.

3. Pressure Spring

Standard



Modified



The pressure spring in the modified fusing unit has a marking along the side.


* The pressure spring does not require periodical replacement.




Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

4. Pressure Arm

Standard







Modified



PAGE: 7/15





The arm for the standard unit is not durable enough to operate the modified unit and will cause the shaft to wear. The arm for the modified unit made of thicker plate is installed with a bushing to prevent wear and also has a different shape.

* The pressure arm does not require periodical replacement.

Technical Bulletin

Model: AG-P1/C1, AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

5. Rear Cover





Modified



PAGE: 8/15

To avoid contact between the ribs on the cover and the pressure arm caused by the shape change of the pressure arm, the ribs on the cover have been partially removed.

Ulletin Page: 9/15

No.: RG178129

Model: AG-P1/C1,AGL-P1/C1


6. Addition of Securing Screws

Standard





Date: 05-Jan-11



Screws to attach the upper and lower frames have been newly added to secure higher durability of the entire unit and Bracket:Web:Drive(p/n:G1784354) has been changed in shape to allow easy access to the screw.

P/N of the newly added M5x10 screw:

AA143803 / FLANGED HEXAGONAL HEAD BOLT:CASTER



PAGE: 10/15

Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

Please consider the following notes before operating a machine installed with the modified fusing unit.

- · SP Adjustment
 - 1. SP1907-001 (Fusing Motor Rotation)

Rotation speed of the fusing motor must be modified to coordinate with the new nip width.

SP1907-001: Fusing Motor Rotation					
Standard Modified					
Rotation Speed	1196.9 rpm	1208.9 rpm			

NOTE: Make sure to adjust the above setting according to the type of fusing unit (standard or modified) installed.

- · Parts Requiring Periodical Replacements
 - 1. Hot Roller

PM interval 400K

The hardness of the hot roller will gradually decrease over time. Make sure to replace with a new roller at every 400K to maintain the best performance.

2. Drive Gear

G1781491 Gear: Fusing Drive Sub-unit: O/C: Ass'y

PM interval 4000K

This gear lifts and lowers the pressure roller. The modified fusing unit will not only apply more stress to this gear but may also cause it to break due to abrasion and fatigue considering the higher pressure applied when the pressure and hot rollers are in contact, hence periodical replacement of this gear is required.

NOTE: All the teeth of gear (p/n G1781491) must be applied with 1g of Alvania Grease (p/n G1552876) upon replacement.



Model: AG-P1/C1,AGL-P1/C1


Technical Bulletin

 Date: 05-Jan-11
 No.: RG178129

Applying Grease to the Gear (p/n G1781491)


<u>Tip 1</u>

Divide 1g of grease equally to 12 locations on the teeth. Rotation of the gear will then distribute the grease evenly and thoroughly.



Tip 2

1g of grease is approximately the size of an M4x8 screw.





PAGE: 12/15

Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

Effect

	Improvements	Mechanism of the Effect
1	Better fusibility	The "hardened" hot roller applies higher pressure to the nip of the hot and pressure rollers.
2	Effective for wrinkles and worm tracks	Elimination of the oil application components reduces the rotation load on the pressure roller allowing its better correlation with the hot roller, which is effective for worm tracks.
		The "hardened" hot roller allowing a more even nip (pressure distributed equally) is also effective for wrinkles.
3	Effective for toner blisters	The "hardened" hot roller applies higher pressure to the nip of the hot and pressure rollers.
4	Effective for oil stains on 1 st side of duplex printing	Elimination of the oil application components has reduced the overall amount of oil applied to the surface of the pressure roller, ultimately reducing the amount of oil transferred from the roller to the paper.
		However, this issue will remain for the very first output immediately after an idling operation, because the sufficient amount of oil applied to the fusing belt is absorbed by this first sheet via the pressure roller. Feeding speed (or distance between the sheets) will also affect the output because the process of "oil transference from the belt to the pressure roller" and "oil transference from the pressure roller to the paper" is continuously repeated every time a sheet passes the nip.

Side Effects

	Issues	Cause	Solutions and Workarounds
1	 Fusing belt wrap-around jams under the following conditions: Non-coated standard paper of 80gsm or lighter LE margin set to minimum; 4.2 +/- 0.7mm (4.0 mm if high temp and humidity with thin paper), and max toner amount (1.56 mg/square cm) 	The "hardened" hot roller causes the nip to face upwards, directing the fused paper towards the stripper pawl, which makes it difficult for the paper to separate from the belt.	* Increase LE margin * Switch to a different paper type * Replace with the standard fusing unit. LE: Leading edge

Technical Bulletin

PAGE: 13/15

Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

	Issues	Cause	Solutions and Workarounds
2	Oil Adhesion with Thin Paper	Due to the elimination of the oil application components, the decrease in the amount of oil applied to the surface of the pressure roller causes thin and flexible paper to wrap around the pressure roller easier. The oil accumulated at the pressure roller stripper pawl then adheres to the paper. The issue rarely occurs with the	* Switch to a different paper type; paper evaluated 120 or higher on the Clark Stiffness Tester is recommended. * Replace with the standard unit
		very first output of a job because the surface of the pressure roller is applied with a sufficient amount of oil allowing the paper to easily separate from the pressure roller.	
3	Damaged fusing belt and pressure roller * Gloss streaks become visible in a shorter period of time with the modified fusing unit in comparison to the standard fusing unit when the job is run with "Thick Paper + Wide Nip". Test results as follows:	Higher nip pressure caused by the "hardened" hot roller causes the edges of the paper (especially paper with jagged edges) to wear the surface of the fusing belt and the pressure roller faster than the standard fusing unit.	Replace the fusing belt and pressure roller. (This workaround also applies for standard units.)
	HML28lb, Narrow Nip> Same 70W, Narrow Nip> Same POD Gloss 128, Medium Nip> Same ColotecG280g, Wide Nip> Faster		

Technical Bulletin

PAGE: 14/15

Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129


	Issues	Cause	Solutions and Workarounds
4	Gloss Residues: Pressure Roller If the LE on the 1st side contains a low coverage image and the TE on the 1st side contains a solid image (high coverage), the low coverage image on the LE could overlay on the TE while fusing the 2nd side (1st side is in contact with the pressure roller) under these conditions: * Coated paper * 1 original fed in automatic duplex, or 1-3 original fed in manual duplex The overlaid (residual) image will gradually become less noticeable over time. See additional explanation on the following page. LE: Leading edge TE: Trailing edge	* Due to the elimination of the oil application components, oil is applied to the pressure roller via the fusing belt. Therefore, the first sheet fed attracts the largest amount of oil from the pressure roller while the amount of oil transferred to the following sheets gradually decreases. * When fusing the 2 nd side, oil on the surface of the pressure roller is absorbed by the low coverage image on the LE of the 1 st side resulting in a residual image being created on the pressure roller, which is then overlaid onto the TE consisting of a solid image. Uneven oil on the pressure roller surface is essentially caused by the elimination of the pressure roller blade.	When observed with 1-3 original manual duplex: * Switch to automatic duplex * Feed a test sheet to absorb (erase) the overlaid image * Switch the LE and TE so that the solid image is on the LE When observed with 1 original automatic duplex: * Feed a test sheet to absorb (erase) the overlaid image * Switch the LE and TE so that the solid image is on the LE Note The same problem will occur with standard units if the oil application components are eliminated.

PAGE: 15/15


Model: AG-P1/C1,AGL-P1/C1 Date: 05-Jan-11 No.: RG178129

Additional Explanation of Pressure Roller Gloss Residues

The following is an example of a 1st side image likely to cause the side effect.



The following is a view of the pressure roller from below and explains how the side effect is generated when fusing the 2nd side in a duplex print job.



1. The surface of the pressure roller is applied with sufficient amount of oil via the fusing belt until the sheet enters the nip to fuse the 2nd side. While fusing the 2nd side, the pressure roller is in contact with the 1st side.



2. As the sheet passes the nip, the sheet absorbs the sufficient amount of oil applied to the surface of the pressure roller except for the area containing the low coverage image on LE, leaving oil on the pressure roller in the shape of the low coverage image.



3. The residual oil (image) on the surface of the pressure roller then adheres to the TE. The residual image is only noticeable because the TE is composed of a solid image.

Technical Bulletin

PAGE: 1/1

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5 Date			ate: 11-Jan-11		No.: RG178130	
Subject: Notes on Cleaning the Developer Unit			Prepared by: Hiroaki Matsui			
From: PPBG QA/Service Planning Dept.						
Classification:		☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrica	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	⊠ Tier 2	


This RTB has been issued to announce important notes on handling the development rollers to prevent toner clumps on the development rollers from generating scratches on the drum surface.

Note

Always rotate the development rollers clockwise when required to rotate them manually on occasion of cleaning maintenance, etc.


Rotating the development rollers counterclockwise with the developer installed will cause toner to adhere to the development rollers (see Reference below), resulting in higher chances of damaging the drums. Make sure to clear out the developer from the unit in advance when rotating the developer rollers counterclockwise.

Also, please do NOT clear the PM counter if the developer removed is to be re-installed and used again.



Reference

Rotating the development rollers counterclockwise with the developer installed will cause the entrance seal to deflect (especially at the edge).



Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Dat	Date: 05-Jul-11		No.: RG178131a
Subject: Release note for Aegis-P1/C1 EFI Patches				Prepare	d by: T. S	Satoh
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion	☐ Action	n required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release				
File name File size				
R0205573.exe 6.95 MB				

Problem Solving

Following are the key problems that have been given countermeasures.

Files included in this release

Folder Name/ File Name/ File Size/ Reboot

1st/ 1-18LQLE.exe/ 1,196,592/ not Exclusive 2nd/ (Blank folder)

3rd/ 1-18SOFL.exe/ 1,341,464/ not Exclusive

4th/ 1-181A8R.exe/ 3,197,328/ not Exclusive

5th/ 1-190YWR.exe/ 1,803,040/ not Exclusive

Note: Important!!! Strictly follow the installation order as indicated here above.

Issue(s) addressed with this release

- 1-18LQLE: Print after inserting a blank page in the end of the PDF page, and Fiery mistakes the page ordering if the PDF is printed again after changing the copy number.
- 1-18SOFL: Fiery improved the ripping performance for JPEG with page rotation. (Mac10.5 Preview Application)
- 1-181A8R: Increase/decrease of Counter value are different between MIB value and SP value.
- 1-190YWR: Print Counter with User Code Auth. and/or External Charge Unit does not increase correctly.

Technical Bulletin

PAGE: 2/2

Model: **AG-P1/C1** Date: 05-Jul-11 No.: RG178131a

Preparation before Installation

- 1. Please print out the configuration page. Verify the **Server Info** section. It should show the version number "4.0". Also verify the **Update Information** section. It should show "1-14N2CZ"
- 2. Please install "1-14N2CZ", if the **Update Information** section is blank. Or please install the system
- 4.0 again, if the version number is not 4.0.

Note

- 1. You should keep to the install order when the patch will be installed.
- 2. You should execute a reboot when you install an "**Exclusive**" patch.

(The patch names that you installed will be shown in the configuration after reboot.)

Installation Instructions

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute 1-xxxxxx.exe and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader
 - a. Login must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Restart later (not Exclusive) then apply next patch.

Reboot. (Exclusive)

- 5 Wait until the Fiery comes to Idle and print the configuration page.
- Werify that the System Update Log section contains the patch number 1-xxxxxx.

Technical Bulletin

PAGE: 1/2

Model: Aegis-P1/C1 Aries Lt P1/C1 Da			Dat	te: 15th-Fe	eb-11	No.: RG178132
Subject: Notice for Exhasuting Developer			Prepared by: H. Kawamura			
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting	☐ Part info	orma	tion		required
		☐ Electric	al		⊠ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

General

This RTB has been issued to inform you the procedure for exchanging the developer from the development unit. By following the procedure in the service manual, developer in the development unit may not be exchanged completely; therefore, please follow the following procedure when replacing the developer.

Cause

Incomplete developer exhaust

The valve for exhausting the developer does not open properly; therefore, the developer may not exhaust completely.

Incomplete developer fill

The developer may clog the exit of the developer bottle and it may not go into the development unit completely.

Procedure

Developer Exhaust

- 1. Set the empty developer bottle on the development unit, select the color from SP 2-255-001, then execute SP 2-255-002
- 2. Check the Developer Exhaust Results from SP 2-255-009 to 2-255-012
- 3. Re-exhaust the developer SP 2-355-002 Whenever, exhausting the developer, please exhaust it **twice**
- 4. If the developer bottle feels light, please re-exhaust the developer.

Developer Fill

- 1. Before opening the plastic bag, shake the bottle a few times.
- 2. Execute "developer fill" and select the color from SP 2-256-001, then SP2-256-002
- 3. While filling the developer, apply vibration.

NOTE: When applying vibration constantly, push the developer bottle slightly so that the developer bottle moves about 3mm either side of the bottle as shown below.


Technical Bulletin

PAGE: 2/2

Model: Aegis-P1/C1 Aries Lt P1/C1

Date: 15th-Feb-11

No.: RG178132




Model: AG-P1/C	Dat	te: 23-Mar-	-11	No.: RG178133				
Subject: Modified Connector Guide Pin					Prepared by: N.lida			
From: PPBG Service Planning Dept.								
Classification:	☐ Troubleshooting	□ Part info	ormat	tion	Action	n required		
	☐ Mechanical	☐ Electrica	al		Service	ce manual revision		
	☐ Paper path	☐ Transmit/red		☐ Transmit/receive		eive	eive Retrofit informa	
	☐ Product Safety	\square Other ()	☐ Tier 2	î		

Old part New part Description		Q'ty	Int	Page	Index	Note	
number	number						
AA143797	G1784615	CONNECTOR GUIDE PIN	2	X/O	193	8	
AA143797 _	_	CONNECTOR GUIDE PIN	6→4	-	175	10	*1
	G1787515	CONNECTOR GUIDE PIN	0→2	X /〇	175	17	


Change: Shape of the Connector Guide Pin

Reason: Higher reliability in the connection of the Drawer Connector



*1 Only the Connector Guide Pins for the Drawer Connector of the Paper Exit Unit have changed.

78.Drive Section 4 (D016/G178)



Technical Bulletin

PAGE: 1/6

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5				te: 23-Mar-11		No.: RG178134		
Subject: Rework to Prevent SC328					Prepared by: H. Matsui			
From: PPBG Ser	vice Planning Dept.							
Classification:	□ Troubleshooting	☐ Part info	ormat	tion				
	☐ Mechanical	☐ Electric	al	☐ Sen		ce manual revision		
☐ Paper path ☐		☐ Transmit/receive		☐ Retrofit information				
	☐ Product Safety	t Safety)	☐ Tier 2			

Symptom

SC328 (Toner supply motor error)

Cause


Variations in the precision of assembly of the bushing/holders that fix the sub-hopper units' drive shaft apply stress and causes wear on the drive shaft. (Abrasion of the drive shaft occurs at the bushing closest to "Holder-A".)


Solution

Please remove "Holder-A" at your next service visit for the affected units (see the next page for the list of affected units).

NOTES

- The bushings and Holder-B will give enough support to secure the drive shaft. Removal of the Holder-A will not affect the function.
- Removing the Holder-A will prevent further abrasion of the drive shaft and SC328.
- A worn drive shaft can be continuously used and will not affect the function.







PAGE: 2/6

No.: RG178134

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5

Date: 23-Mar-11

Affected Units

Total Number of Affected units in NA: 1967

No	Product Description	Serial Numbers	Affecte	d units
			QTY	Total
1	Pro C720	S9704900001 - S9706000013	112	114
		S9714900001, S9714900002	2	
2	Pro C720S	V8904900001 - V8906000045	434	434
3	Pro C900	S3286000001 - S3286000050	50	433
		S3294900001 - S3296000047	285	
		S3205000001 - S3205800002	98	
4	Pro C900 Base Unit	S7095500001 - S7095900003	9	9
5	Pro C900 E-80 QX	S7095400001 - S7095900002	10	18
		S7005000001 - S7006000001	8	
6	Pro C900 C-80 CREO	S7004900001 - S7005600002	27	27
7	Pro C900S	M8795000001 - M8796000033	432	718
		M8704900001 - M8705900011	276	
		M8714900001 - M8714900010	10	
8	Pro C900s E-80 QX	V7495700001 - V7495900007	16	32
		V7405100001 - V7405100011	11	
		V7414900001 - V7414900005	5	
9	Pro C901	T0105800001 - T0106000016	30	37
		T0114900001 - T0114900007	7	
10	Pro C901S	V9905800001 - V9906000044	116	145
		V9914900001 - V9914900029	29	

Total Number of Affected units in EU: 435

No	Product Description	Serial Numbers	Affecte	d units
			QTY	Total
1	Pro C720	S9702700001 - S9703300001	15	17
		S9712500001, S9712500002	2	
2	Pro C720S	V8902700003 - V8903300011	36	52
		V8912500001 - V8912500016	16	
3	Pro C900	S3293300004 - S3293600009	37	79
		S3202500001 - S3203400001	41	
		S3212500001	1	
4	Pro C900S	M8793300006 - M8793600017	75	200
		M8702500001 - M8703400006	120	
		M8712500001 - M8712500005	5	
5	Pro C900 C-80 CREO	S7093400002 - S7093600002	8	32
		S7002800002 - S7003300002	21	
		S7012500001 - S7012500003	3	
6	Pro C900s E-80 QX	V7493300001 - V7493600001	4	11
		V7402500001 - V7403200001	7	
7	Pro C901	T0112500001 - T0112500019 , T0112700004	20	20
8	Pro C901S	V9903600017, V9903600018	24	24
		V9912500001 - V9912500019		
		V9912600015, V9912600019, V9912700002		

Affected units in Asia

No	Product Description	Serial Numbers			
1	Pro C720	S9701200003 or older			
2	Pro C720S	V8910100001 or older			

Technical Bulletin

Date: 23-Mar-11 No.: RG178134

PAGE: 3/6

3	Pro C900	S3200800004 or older
4	Pro C900S	M8700700005 or older
7	Pro C901	T0110100001 or older (T0110100001 has been modified.)
8	Pro C901S	V9910100001 or older (V9910100001 has been modified.)

Supplementary Explanation on Machine Serial Numbers

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5

Serial numbers for mass production units are an 11 digit number which is composed of MC type No., production year, production month +48(NA) / +24(EU) / +0(Asia), and a 5 digit sequential number. (Pre-production units do not apply the above numbering system.)

Example of a serial number registered for a Pro C900 machine

=>	ample of a serial	I number registered for a Pro C900 machine
	Model / Brand	Serial number - numbering method.
	G17817	S32
		Mc type No. Year (Month+ XX) (Sequential numbering from 00001 each month.)
		XX = 48 NA XX = 24 EU XX = 0 Asia
		(In the case of NA) Serial number "S3294900017" is composed of the following information: Mc Type No. = S32 (Pro C900) Year = 9 (2009 production) Month +48 = 49 (49 - 48 = 1 = January production) Sequential Number = 00017 This indicates that the unit is a Pro C900 and was the 17 th unit manufactured in the month of January in year 2009.
		(*) Year = 0 indicates that the unit was manufactured in year 2010.

Table of MC Type No.

No	Product Description	MC type NO.
1	Pro C720	S97
2	Pro C720S	V89
3	Pro C900	S32
4	Pro C900 Base Unit	S70
5	Pro C900 E-80 QX	S70
6	Pro C900 C-80 CREO	S70
7	Pro C900s	M87
8	Pro C900S E-80 QX	V74
9	Pro C901	T01
10	Pro C901S	V99

PAGE: 4/6

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5

Date: 23-Mar-11 No.: RG178134

"Holder A" Removal Procedure

Note: Make sure the machine power is turned off before doing this procedure.

1. Open both front doors, and remove the front upper cover.



2. Remove the cover of the Yellow development unit, and draw out the Yellow development unit.






3. Remove the rear upper cover, and open the rear unit.



4. Remove the cooling fan.



Remove the two screws to remove the cooling fan.


PAGE: 5/6

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5

Date: 23-Mar-11


No.: RG178134

5. Disconnect 3 connectors, remove the snap ring, and remove 1 screw fixing the Yellow sub-hopper and 2 screws fixing the Holder-A.






5-1. Disconnect 3 connectors here.



- **5-3.** Remove 1 screw fixing the subhopper, and 2 screws fixing the Holder-A.
- **5-2.** Remove the snap ring and slide the bushing to the right.
- 6. Release the Yellow sub-hopper halfway, and remove the Holder-A.



6-1. Lift up the Holder-A.

6-2. Pull out both sub-hopper and Holder-A together to the front. (The sub-hopper is released halfway.)

Note:

Holder-A is locked in place with the side plate of the mainframe. To release the lock, lift up Holder-A as you pull it out to the front together with the sub-hopper. The sub-hopper is released halfway in this condition.


Do not remove the Toner Supply Tube.

PAGE: 6/6

Model: AG-P1 / C1 , AGL-P1/C1 , Aries-P1.5/C1.5

Date: 23-Mar-11

No.: RG178134



To remove the Holder-A, rotate it clockwise, and then slide it to the left.

Holder-A



NOTE Holder-A shown above is applied for C901/C901S. The shape of Holder-A is different for C900/C900s/C720/C720s but the removal procedure is the same.

Appearance after removing Holder-A



After removing the Holder-A, the ball bearing will remain and be of no use.

However, the ball bearing should NOT be removed to prevent the risk of dropping the retaining ring into the machine.

Also, leaving the ball bearing will not affect the function.

7. Follow the above steps 1~6 in reverse order to complete the procedure.

Technical **B**ulletin

PAGE: 1/1

Model: AG-P1/C	Date: 20-Apr-11		11	No.: RG178135		
Subject: CD-ROI		Prepared by: N.lida				
From: PPBG Ser	vice Planning Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electric ☐ Transm ☐ Other (al		Service	required ce manual revision fit information

Change: Part number **Reason:** Content revision

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
G1780421	M0647902	CD-ROM:MANUAL:RICOH_ADMIN:ASS'Y	1	X/O	229	34
G1780423	M0647900	CD-ROM:MANUAL:RICOH_USER:ASS'Y	1	As a	229	34
				set		


Technical **B**ulletin

PAGE: 1/1

Model: AG-P1 / C1 , AGL-P1/C1 Date					/-11	No.: RG178136		
Subject: New part HEXAGONAL BOLT					Prepared by: Hiroaki Matsui			
From: 1st PP Ser	rvice Planning Sec., PP Se	rvice Planning						
Classification:	Troubleshooting	□ Part info	orma	tion	Action	n required		
	☐ Mechanical	☐ Electric	☐ Electrical ☐ Transmit/rec		Service	ce manual revision		
	☐ Paper path	☐ Transm			it/receive		Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2)		

This RTB has been issued to announce the release of the HEXAGONAL BOLT as a new service part.

New part	Description		Int	Page	Index	Note
number						
G1781134	HEXAGONAL BOLT:M20X70		-	25	105	



Technical Bulletin

PAGE: 1/1

Model: AG-P1/AG-C1 , AGL-P1/AGL-C1 Date			e: 25-May	-11	No.: RG178137			
Subject: Change the Exit Roller					d by: H.M	1atsui		
From: 1st PP Ser	vice Planning Sec, PP Service	Planning						
Classification:	Troubleshooting	shooting		tion		required		
	☐ Mechanical	☐ Electrical			☐ Service manual revis			
	☐ Paper path	☐ Transmit/rece		☐ Transmit/ı		eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G1784946 _	-	EXIT ROLLER:PRESS FIT	1	X/X	151	2	
	►M0774946	EXIT ROLLER					

Change/Reason:

To improve paper feeding performance for thick paper in the paper exit including the switchback path


Technical Bulletin


PAGE: 1/1

Model: Aries-P1.5/C1.5 , AGL-P1/C1 Da			Dat	e: 30-May	-11	No.: RG178138
Subject: New part Frames					d by: Hire	oaki Matsui
From: 1st PP Ser	rvice Planning Sec., PP Se	rvice Planning				
Classification:	Troubleshooting	□ Part info	□ Part informate □ Part informate		ation	
	☐ Mechanical	☐ Electric	☐ Electrical		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	☐ Transmit/red		Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the release of the following frames as new service parts.

New part	Description		Int	Page	Index	Note
number						
G1781162	FRAME:CONTROL UNIT:LEFT:COAT		-	211	16	
G1781142	BASE:CONTROL UNIT:WELDING	1	-	211	17	
G1781225	STAY:LARGE CAPACITY TRAY:RIGHT	1	-	217	16	





Technical Bulletin

PAGE: 1/2

Model: Aegis-P1/C1			Dat	e: 23-May	-11	No.: RG178139
Subject: Manual Correction for Aegis-P1.0/C1.0					d by: Hide	etoshi Kawamura
From: 1st PP Service Planning Sec., PP Service Planning						
Classification:	☐ Troubleshooting	☐ Part informa		tion	required	
		☐ Electrical			⊠ Servic	ce manual revision
	☐ Paper path	☐ Transmit/rec		eive	Retrof	fit information
	☐ Product Safety	☐ Other ()	☐ Tier 2	

The Service Manual for Aegis-P1/C1 was corrected

- On page 659, the area surrounded by the red box below is corrected
- On page 738, SCs related to Buffer Pass Unit are added

Page 659, Process Control Self Check SP3821

Displayed Code	ltem	Major Cause				
	VdHome Error 2 (SC436 to SC439)	V0 (SP3571) below -700V, or VdHome (SP3772) below -500V. • Potential sensor relay board damaged • Drum abnormal • Drum motor not operating				
16	 Action: Do SP2260 001 to check the function of the potential sensor. Do SP2261 to check the Vd reading. For more, see Section 6. This error occagain if Vd is less than -500V. Remove the malfunctioning PCDU with a functioning PCDU, turn the machine then on, then do the potential sensor check again. If the replaced PCDU does not function normally, then the problem is on the masside, or the potential sensor relay board is malfunctioning. If the replaced PCDU functions normally, then there may be a problem with a drum or the charge unit. Replace the PCDU. 					

Correction

Major Cause

Vo (SP3571) below -700V or VdHome (SP3572) below -500

- Potential sensor relay board damaged
- Drum abnormal
- Drum motor not operating



PAGE: 2/2

Model: Aegis-P1/C1 Date: 23-May-11 No.: RG178139

Page 738, SC 5xx

Correction

Two SC codes were missing from the service manual related to the Buffer Pass Unit SC 525 and SC 526 $\,$

No.	Туре	Details (Symptom, Possible Cause, Troubleshooting Procedures)
		Drive motor (right) error (M379)
		The machine detects a lock signal of the drive motor (right) in the buffer pass unit (M379) for 1.2 seconds after the drive motor (right) has rotated for 2 seconds.
525 B		Harness disconnected or broken Defective drive motor (right) (M379)
		Check or replace the harness. Replace the motor (right).

No.	Туре	Details (Symptom, Possible Cause, Troubleshooting Procedures)
		Drive motor (left) error (M379)
		The machine detects a lock signal of the drive motor (left) in the buffer pass unit (M379) for 1.2 seconds after the drive motor (left) has rotated for 2 seconds.
526	В	Harness disconnected or broken Defective drive motor (left) (M379)
		Check or replace the harness. Replace the motor (left).

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Dat	Date: 05-Jul-11		No.: RG178140
Subject: Release note for Aegis-P1/C1 EFI Patches				Prepared by: T. Satoh		
From: PPBG Ser	vice Planning Dept.					
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required
	☐ Mechanical	☐ Electric	ctrical		☐ Service manual revision	
☐ Paper path ☐ Tr		☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release					
File name	File size				
R0205580.exe	43.6 MB				

Problem Solving (Measures)

Following are the key problems that have been given countermeasures.

Files included in this release

Folder Name/ File Name/ File Size/ Reboot

1st/ 1-18U1L4.exe/ 5,140,344/ not Exclusive

2nd/ 1-19DTMJ.exe/ 4,423,000/ not Exclusive

3rd/ 1-19FRM0.exe/ 3,186,392/ not Exclusive

4th/ 1-19FHI5.exe/ 1,196,344/ not Exclusive

5th/ 1-19JBUW.exe/ 1,916,336/ not Exclusive

6th/ 1-19K4KP.exe/ 2,592,256/ not Exclusive

7th/ 1-1908YL.exe/ 7,201,424/ not Exclusive

8th/ 1-19SKBZ.exe/ 13,737,240/ not Exclusive

9th/ 1-19Q0OH.exe/ 4,970,560/ not Exclusive

10th/ 1-1A0OPJ.exe/ 2,116,864/ not Exclusive

Note: Important!!! Strictly follow the installation order as indicated here above.

Issue(s) addressed with this release

- 1-18U1L4: After we applied a patch, we could not get a normal print result.
- 1-19DTMJ: SC919 and SC991 occur in printing.
- 1-19FRM0: Fiery may fail to close a page.
- 1-19FHI5: Paper is not fed from the correct tray if PS-File print via Virtual Printer.
- 1-19JBUW: The image behind the blank page will slip off in the top right corner.
- 1-19K4KP: Jobs are not displayed in accordance with the order of "Date/Time" in the joblog.
- 1-19O8YL: Cannot print HPT correctly.
- 1-19SKBZ: If RIP is executed via without PS drv, pattern image collapses.
- 1-19Q0OH: Customer is unable to select Color Mode, within CWS, under Booklet, 1-up perfect setting.
- 1-1A0OPJ: If specific data has been printed, "Scale to Fit" is not applied.

Technical Bulletin

PAGE: 2/2

Model: **AG-P1/C1** Date: 05-Jul-11 No.: RG178140

Preparation before Installation

- 1. Please print out the configuration page. Verify the **Server Info** section. It should show the version number "4.0". Also verify the **Update Information** section. It should show "1-14N2CZ"
- 2. Please install "1-14N2CZ", if the **Update Information** section is blank. Or please install the system
- 4.0 again, if the version number is not 4.0.

Note

- 1. You should keep to the install order when the patch is installed.
- 2. You should execute the reboot when you install an "**Exclusive**" patch.

(The patch names that you installed will be shown in the configuration after reboot.)

Installation Instructions

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute 1-xxxxxx.exe and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader
 - a. Login must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Restart later (not Exclusive) then apply next patch.

Reboot. (Exclusive)

- Wait until the Fiery comes to Idle and print the configuration page.
- Werify that the System Update Log section contains the patch number 1-xxxxxx.


Technical Bulletin

PAGE: 1/1

Model: AG-P1 / C1 , AGL-P1/C1 Da			Dat	e: 09-Aug	-11	No.: RG178141
Subject: Modify the Part Catalog (Add the Ball Bearing)			Prepared by: Hiroaki Matsui			
From: 1st PP Service Planning Sec., PP Service Planning						
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
		☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	☐ Tier 2	

This RTB has been issued to modify the part catalog as follows.

New part	Description	Q'ty	Int	Page	Index	Note
number						
07413503	BALL BEARING - 5X10X4	1	-	173	115	



Technical Bulletin

PAGE: 1/1

Model: AG-P1 / C1 , AGL-P1/C1			Dat	te: 21-Sept-11		No.: RG178142
Subject: Manual Correction for Aegis/Aegis-Light				Prepared by: H Matsui		
From: 1st PP Service Planning Sec., PP Service Planning						
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		⊠ Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

The Service Manual for Aegis-P1/C1 and Aegis-Light-P1/C1 are corrected

- On pages 450 in Appendices, area surrounded by red box in figure below is corrected.
 - 4. Insert a sheet [A] of paper (A4 or LT SEF) under the shift
 - Set the paper so that the leading edge [C] of the paper is aligned with the front edge [E] of the registration timis
 - 6. Install the registration drawer unit in the mainframe.
 - 7. Check that the value of SP1916-001 is set to "1.61".
 - 8. Execute the "CIS LED Power Adjustment" with SP1912-

Correction

(Wrong) Install the registration drawer unit in the machine.

(Correct) Install the registration drawer unit in the machine and close the front cover.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date: 26-Oct-11		11	No.: RG178143	
Subject: Release note for Aegis-P1/C1 EFI Patches				Prepared by: T. Satoh			
From: PP Tech Service Dept., 1st PP Tech Service Sect.							
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required	
	☐ Mechanical	☐ Electric	trical		☐ Service manual revision		
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	\boxtimes Other ()			

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release					
File name	File size				
R0205601.exe	41.9 MB				

Problem Solving (Measures)

Following are the key problems that have been given measures.

Files included in this release

Folder Name/ File Name/ File Size/ Reboot

1st/ 1-19UMTK.exe/ 1,240,016/ not Exclusive

2nd/ 1-1A9NOT.exe/ 1,235,552/ not Exclusive

3rd/ 1-1AYSGZ.exe/ 1,717,064/ not Exclusive

4th/ 1-1ASJLD.exe/ 1,151,560/ not Exclusive

5th/ 1-1BJJUP.exe/ 1,517,064/ not Exclusive

6th/ 1-1B64QX.exe/ 1,253,736/ not Exclusive

7th/ 1-1BM5UM.exe/ 1,518,024/ not Exclusive

8th/ 1-1BN9NF.exe/ 2,668,160/ not Exclusive

9th/ 1-1BRK0K.exe/ 1,520,856/ not Exclusive

10th/ 1-1BTCl9.exe/ 9,613,952/ not Exclusive

11th/ 1-1B26V3.exe/ 21,313,664/ not Exclusive

Note: Important!!! Strictly follow the installation order as indicated here above.

Issue(s) addressed with this release

- 1-19UMTK: RGB image with Pure Black prints incorrectly.
- 1-1A9NOT: If B5 size data is imposed and printed with B4 size, Configure is printed with B5 size.
- 1-1AYSGZ: When 2 at center of the staple has been requested, Fiery show PS error (Rangecheck Error)
- 1-1ASJLD: PS VM error occurs by printing a specific .ps file.
- 1-1BJJUP: Impose: Scaling is not applied even if the template which set "Scale" is used.
- 1-1B64QX: CWS5:PS data are classified as PCL
- 1-1BM5UM: Impose page rotation problem.
- 1-1BN9NF: MixedMedia: A blank paper is added when a duplex printing of the page.
- 1-1BRK0K: Connection with Fiery and printer run out
- 1-1BTCI9: Fiery Server is rebooted when pre-flight will be executed.
- 1-1B26V3: Fiery Server stops when PDF file will be imported via CWS.

Technical Bulletin

PAGE: 2/2

Model: **AG-P1/C1** Date: 26-Oct-11 No.: RG178143

Preparation before Installation

1. Please print out the configuration page. Verify the **Server Info** section. It should show the version number "4.0". And also verify the **Update Information** section. It should show the "1-14N2CZ"

2. Please install the "1-14N2CZ", if the **Update Information** section is blank. Or please install the system 4.0 again, if the version number is not 4.0.

Note

- 1. You should keep to install order when the patch will be installed.
- 2. You should execute the reboot when you install the patch of "**Exclusive**". (The patch names that you installed will be shown in the configuration after reboot.)

Installation Instructions

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute 1-xxxxxx.exe and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader
 - a. Login must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Restart later (not Exclusive) then apply next patch.

Reboot. (Exclusive)

- 5 Wait until the Fiery comes to Idle and print the configuration page.
- Werify that the System Update Log section contains the patch number 1-xxxxxx.

Technical Bulletin

PAGE: 1/1

Model: Aegis C1/P1 AG-C1Lt/P1Lt Da			Dat	te: 18-Nov	-11	No.: RG178144	
Subject: Key top for Java VM Option					Prepared by: H. Kawamura		
From: 1st Tech S]					
Classification:	Troubleshooting	□ Part inf	information		☐ Action	n required	
	☐ Mechanical ☐ Electric		cal		☐ Service manual revision		
		☐ Transm	smit/receive		Retrof	fit information	
	☐ Product Safety	□ Other ()	☑ Tier 2	,	

This RTB informs the part which needs to be ordered when the customer uses the JAVA VM Option

If the customer uses the JAVA VM Option, please order the following part

Part number: B2341574

Part Name: KEYTOP:KINO_MENU:NA

Procedure



1. Remove the blank key top on the operation panel

2. Insert the Key top for JAVA VM, Part number B2341574

Technical Bulletin

PA	IGE	:: 1	/1

Model: AG-P1/C1			Date: 14-Dec-11		-11	No.: RG178145	
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: T. Satoh			
From: PP Solution Support Sec. PP Tech Service Dept.							
Classification:	☐ Troubleshooting	☐ Part informa		tion	☐ Action	required	
	☐ Mechanical	☐ Electrication	cal		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec		Transmit/receive		fit information	
	☐ Product Safety	$oxed{\boxtimes}$ Other ()			

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release						
File name	File size					
R0205603.exe	192 KB					

Problem Solving (Measures)

System/Web update did not function since 10 October 2011 for Fiery servers that run on either Windows XPe SP2 or XPe SP3.

Steps to reproduce

NA

Prerequisite(s)

Installation instructions

Installation on FACI systems:

- 1. Execute 1-1CO771.exe and follow the instructions
- 2. Fiery must be rebooted in order for changes to take effect.

Installation on non-FACI systems:

- 1. Enable remote desktop on the server.
- 2. With a Windows XP client, using remote desktop to the Fiery server
- 3. Execute 1-1CO771.exe and follow the instructions
- 4. Fiery must be rebooted in order for changes to take effect.

Known Issues



PAGE: 1/2

Reissued:27-Mar-12

Model: AG-P1/C1	Date: 25-Jan-12	No.: RG178146a

RTB Reissue

The items in **bold italics** were corrected or added.


Subject: Part information for paper exit unit				Prepared by: Hidetoshi Kawamura		
From: 1st Tech service Sect., PP Tech Service Dept.						
Classification:	☐ Troubleshooting	□ Part informate □ Part informate	ion	Action required		
	☐ Mechanical	☐ Electrical		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☐ Tier 2		

This RTB has been issued to announce changes in paper exit unit, which must be replaced as a set

This RTB only applies to machines that have 4 exit rollers.

For machines with 2 exit rollers, please order the same part as before.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AA063675	AA063675	SPRING - 5N	2→4	X/X	153	10	X/O
AA084059	AA084059	BALL BEARING HOLDER	6→8	X/X	153	9	as a set
G1784885	G1784855	TRANSPORT ROLLER: DRIVEN:PAPER	3→2	X/X	153	11	
		EXIT UNIT					
M3791627	M3791627	TRANSPORT ROLLER:DRIVEN	1→3	X/X	153	16	
G1784661	G1784648	GUIDE:EXIT:LOWER	1	X/X	151	3	
G1784663	G1784659	GUIDE:EXIT:UPPER:WELDING	1	X/X	153	8	
G1784684	M0774662	BRACKET:EXIT:SENSOR	1	X/X	153	13	
G1784761	G1784657	BRACKET:STOPPER:FRAME:UPPER	1	X/X	151	1	
G1784800	G1784658	COVER:UPPER:FRAME	1	X/X	153	1	
G1784945	G1784656	GUIDE PLATE:PAPER EXIT UNIT:EXIT	1	X/X	153	18	
G1784946	M0774946	EXIT ROLLER	1	X/X	151	2	






PAGE: 2/2

Reissued:27-Mar-12

Model: AG-P1/C1 Date: 25-Jan-12 No.: RG178146a




Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1 Da				e: 25-Jan-	12	No.: RG178147		
Subject: Part information for HDD				Prepared by: Hidetoshi Kawamura				
From: 1st Tech service Sect., PP Tech Service Dept.								
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required		
		☐ Electrical		☐ Electrical			Service	e manual revision
	☐ Paper path	☐ Transmit/rec		eive	Retrof	fit information		
	☐ Product Safety	Other ()	☐ Tier 2			

This RTB has been issued to announce changes in the HDD, which have to be replaced as a set

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
14077038	14077453	CPU:LF80537GF0484M(SLGFJ)	1	X/X	215	105	X/O
R0367502	R0367523	PCB:FB13-L2-AEGIS	1	X/X	215	13	as a set




8		11	_
		, ,	

RICOH		chnical B ulletin				PAGE: 1 /1		
Model: AG-P1/C1			Date: 25-Jan-12			No.: RG178148		
Subject: Part information for frame					red by: Hid	letoshi Kawamura		
From: 1st Tech s	service Sect., PP Tech Se	rvice Dept.						
Classification:	Troubleshooting	□ Part info	ormat	tion	Action	n required		
	☐ Mechanical ☐ Electrical			☐ Service manual revision				
	☐ Paper path	☐ Transm	Transmit/receive		Retro	fit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2	2		

This RTB has been issued to announce a change in the frame.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
07010050N	M0771192	PLAIN WASHER:BASE:LOWER	2	X/O	211	109	X/O
G1781190	M0771191	FULL DUG POINT	2	X/O	211	8	as a set
		SCREW:BASE:LOWER					



PAGE: 1/2

Reissued:27-Mar-12

Model: AG-P1/C1	Date: 25-Jan-12	No.: RG178149a
1110d01: 7/d 1 1/01	Dato. 20 ban 12	1101101701404


RTB Reissue


The items in **bold italics** were corrected or added.

	bela hance word dorroo	100.0.0.0.0.0.0.				
Subject: Part information for drive section			Prepared by: Hidetoshi Kawamura			
From: 1st Tech service Sect., PP Tech Service Dept.						
Classification:	☐ Troubleshooting	□ Part informate □ Part informate	tion	Action required		
	☐ Mechanical	☐ Electrical		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☐ Tier 2		

This RTB has been issued to announce a change in the Drive section

Old part	New part	Description		Int	Page	Index	Note
number	number						
AA063691	M0774685	COMPRESSION SPRING:JOINT:10N	1	X/X	175	5	X/X
B2344385	D0594398	JOINT:PAPER EXIT UNIT:DRIVE	1	X/X	175	6	as a set
G1784573	M0774682	SHAFT:DRIVE:COUPLING:PRESS FIT	1	X/X	175	2	
G1784892	M0774684	SHAFT:DRIVE:COUPLING:EXIT	1	X/X	145	20	
	D0594399	JOINT:PAPER EXIT UNIT:MAIN	1	·	145	33	







PAGE: 2/2

Reissued:27-Mar-12

Model: AG-P1/C1 Date: 25-Jan-12 No.: RG178149a

Image of "JOINT PAPER EXIT UNIT: MAIN"



JOINT: PAPER EXIT UNIT: MAIN is newly added to the SHAFT: DRIVE: COUPLING: EXIT.

Technical Bulletin


PAGE: 1/2

Model: AG-P1/C	Dat	e: 25-Jan-	12	No.: RG178150				
Subject: Part information for LCT					Prepared by: Hidetoshi Kawamura			
From: 1st Tech service Sect., PP Tech Service Dept.								
Classification:	☐ Troubleshooting	□ Part info	orma	tion	Action	required		
	☐ Mechanical	☐ Electric	al		☐ Service manual revision			
	☐ Paper path ☐ Transmit/		nit/receive		☐ Retrofit information			
	☐ Product Safety	Other ()	☐ Tier 2			

This RTB has been issued to announce a change in the LCT, which needs to be replaced as a set


Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	D3552753	PLATE:GRIP	1	X/O	267	28	X/O
04514008N		TAPPING SCREW:4X8	23	O/O	267	101	as a set

For TAPPING SCREW: 4X8, quantity has been changed from 19 to 23



Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
07200040E		RETAINING RING - M4	4	O/O	277	104	X/O
D3554589	D3554565	BRACKET:PAPER SIZE	2	X/O	277	15	as a set
		SENSOR:ROLLER:PEEN					
D3554598		ROLLER:SLIDER	0	X/O	277	16	

RETAINING RING-M4 changed from 5 to 4, and ROLLER SLIDER changed from 1 to 0.




Model: AG-P1/C1

Technical Bulletin

Date: 25-Jan-12 No.: RG178150

PAGE: 2/2

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
07200060E		RETAINING RING – M6	2	O/O	267	102	X/O
B8343389	D4534449	SHAFT:LINK:PIERCE	1	X/O	267	11	as a set
B8343390		CONTACT POINT STAY	0	X/O	267	10	
B8343400	D4533400	GUIDE:STOPPER:LEFT	1	X/O	267	2	



		1 - 1

PAGE: 1/3

Model: AG-P1/0	Model: AG-P1/C1					No.: RG178151
Subject: Part info		Prepared by: Hidetoshi Kawamura				
From: 1st Tech Service Sect., PP Tech Service Dept.						
Classification:	☐ Troubleshooting	□ Part info	orma	tion	Action	n required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the grease for the fusing unit gears.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	VSSG9002	FLUOTRIBO MG GREASE : 100G	1		377	9	

When replacing the pressure roller or fusing roller for PM, please lubricate the gears with this grease.


The amount: 2 grams at each location, and spread evenly on the top half of the gears

PAGE: 2/3

Model: AG-P1/C1 Date: 25-Jan-12 No.: RG178151

Location to put the grease

1. Gear:Z70:Hot Roller







Model: AG-P1/C1

Technical Bulletin

Date: 25-Jan-12 No.: RG178151

PAGE: 3/3

3. GEAR: PRESSURE ROLLER



Technical Bulletin

PAGE: 1/2


Model: AG-P1/C1 Da				e: 27-Jan-	12	No.: RG178152		
Subject: New Part - Sheet for the Decurl Unit					Prepared by: Shinnosuke Sasaki			
From: 1st PP Ted	ch Service Sec., PP Tech Serv							
Classification:	Troubleshooting	□ Part informa		mation		required		
		☐ Electric	Electrical		☐ Service manual revision			
	☐ Paper path ☐ Transmit/		nsmit/receive		☐ Retrof	fit information		
	☐ Product Safety	Other ()	⊠ Tier 2			

This RTB has been issued to announce the release of the following new service part.

72.Paper Exit Section 13 (D016/G178)

New part	Description	Q'ty	Int	Page	Index	Note
number						
M0774706	SHEET:DECURA:MIDDLE	1	-	163	20	

72.Paper Exit Section 13 (D016/G178)



Purpose


This part was added to prevent possible injuries when fingers accidentally get caught in the Decurl unit.




PAGE: 2/2

Model: AG-P1/C1 Date: 27-Jan-12 No.: RG178152

Note on attaching the sheet





PAGE: 1/2


Model: V-C2/C3	Model: V-C2/C3 R4000			e: 30-May	<i>'</i> -11	No.: RD350006	
Subject: New guide part for LCIT					d by: Tak	seshi Toriumi	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.							
Classification:	☐ Troubleshooting	⊠ Part info	orma	tion	☐ Action	n required	
	☐ Mechanical	☐ Electric	cal [Service	ce manual revision	
	☐ Paper path ☐ Transmit		it/rec	eive	Retro	fit information	
	☐ Product Safety	Other ()	☐ Tier 2		

This RTB has been issued to announce that the tray part for the LCIT has been changed

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
04533006N	-	TAPPING SCREW - M3X6	1-0	-	11	104	X/O
B8343358	B8343356	COVER:UPPER REAR	1	X/X	11	10	as a set
B8343334	B8343343	GUIDE:UPPER REAR	1	X/X	11	14	
B8343349	B8343345	RACK:UPPER	1	X/X	11	16	

B8343345, B8343343, B8343356, 04533006N

5.Paper Tray 3 (D350)



Technical Bulletin


PAGE: 2/2

Model: V-C2/C3 R4000 Date: 30-May-11 No.: RD350006

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
04533006N	-	TAPPING SCREW - M3X6	1-0	-	9	101	X/O
D3503339	D3503345	RACK:UPPER	1	X/X	9	9	as a set
B8343332	B8343341	GUIDE:UPPER FRONT	1	X/X	9	10	
B8343357	B8343355	GUIDE:LM-6:UPPER FRONT:PEEN	1	X/X	9	11	

D3503339, B8343341, B8343355, 04533006N

4.Paper Tray 2 (D350)



Technical Bulletin


PAGE: 1/1

Model: AGL-P1/C1		Dat	Date: 02-Feb-12		No.: RG178153		
Subject: New Part(IPU Harness Cover)			Prepare	d by: Shii	nnosuke Sasaki		
From: 1st PP Ted	ch Service Sec., PP Tech Serv	rice Dept.,					
Classification:	☐ Troubleshooting	□ Part infe	orma	tion	☐ Action required		
	☐ Mechanical	☐ Electrical			☐ Service manual revis		
	☐ Paper path	☐ Transmit/rec		eive	Retro	fit information	
	☐ Product Safety	Other ()	⊠ Tier 2		

The following Harness Cover has been newly registered as a service part.

New par	Description	Q'ty	Int	Page	Index	Note
number						
G178620	86206 COVER:IMAGE PROCESSING UNIT		-	195	14	

88.Electrical Section 8 (D016/G178)



Replacement of this cover is described in the following section of your service manual:

3. Replacement and Adjustment > Electrical Components > IPU

Technical Bulletin

PAGE: 1/4

Model: AG-P1/C1 Date:		Date: 23-Feb-12		No.: RG178154			
Subject: Release note for Aegis-P1/C1 EFI Patches					l by: Mi	yuki Yoshikawa	
From: PP Solutio	n Support Sec.						
Classification:	☐ Troubleshooting	☐ Part info	ormatio	on [Action required		
	☐ Mechanical	☐ Electric	al	☐ Servi		ce manual revision	
	☐ Paper path	☐ Transmit/rece		ceive Retro		fit information	
	☐ Product Safety	\boxtimes Other ()				

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Files included in this release					
File name File size					
R0205605.exe	182MB				

Problem Solving (Measures)

Following are the key problems that have been given measures.

Files included in this release

Folder Name/ File Name/ File Size/ Reboot

1st/ 01/ 1-1BQAJJ.exe/ 3,204,136 byte/ not Exclusive

1st/ 02/ 1-1C4JFX.exe / 7,202,776 byte/ not Exclusive

1st/ 03/ 1-1BVLTL.exe / 7,203,480 byte/ not Exclusive

1st/ 04/ 1-1CGPMB.exe/ 7,204,368 byte/ not Exclusive

1st/ 05/ 1-1BQ9T8.exe/ 2,432,640 byte/ not Exclusive

1st/ 06/ 1-1BNTDO.exe/ 1,324,760 byte/ not Exclusive

1st/ 07/ 1-1B26VU.exe/ 163,421,856 byte/ not Exclusive

Note: Important!!! Strictly follow the installation order as indicated here above.

Issue(s) addressed with this release

- 1-1BQAJJ: After recovery from a Paper End condition when SEF jobs are being printed, LEF paper is requested.
- 1-1C4JFX: Patch to address duplex printing issue with PCL5 data.
- 1-1BVLTL: The MIB value is not updated when printing particular job via raw port 9101.
- 1-1CGPMB: Output is wrong when a particular PCL file is printed.
- 1-1BQ9T8: A 2 at Left staple job cannot be printed on short edge feed paper.
- 1-1BNTDO: An error message appears when printing a particular file with Mixed Media.
- 1-1B26VU: If CMYK Source is set to None in Virtual Printer's settings, a conflict message is displayed when the driver's properties are opened.

Technical Bulletin

PAGE: 2/4

Model: **AG-P1/C1** Date: 23-Feb-12 No.: RG178154

Preparation before Installation

- Please print out the configuration page. Verify the **System Updates Log** section.
- The prerequisites listed below must be installed in the order specified before the **1-1BQAJJ**.exe patch is applied:
 - •1-14N2CZ.exe
 - •1-166VI5.exe
 - •1-15PZTE.exe
- Do NOT install any of the following patches after installing the **1-1BQAJJ**.exe patch. If you are required to install any of the patches below, do so before installing the 1-1BQAJJ.exe patch:
 - •1-19ZWOG.exe
 - •1-19FRM0.exe
 - •1-190YWR.exe
 - •1-181A8R.exe
- The prerequisites listed below must be installed in the order specified before the **1-1C4JFX**.exe, **1-1BVLTL**.exe and **1-1CGPMB**.exe patch is applied:
 - •1-14N2CZ.exe
 - •1-166VI5.exe
 - •1-169LYL.exe
 - •1-15PZTE.exe
 - •1-16FG9A.exe
 - •1-16G6PJ.exe
 - •1-16SQ5Y.exe
 - •1-18U1L4.exe
 - •1-1B26V3.exe
- Do NOT install any of the following patches after installing the **1-1BVLTL**.exe patch. If you are required to install any of the patches below, do so before installing the 1-1BVLTL.exe patch:
 - •1-19O8YL.exe
 - •1-1C4JFX.exe
- Do NOT install any of the following patches after installing the **1-1CGPMB**.exe patch. If you are required to install any of the patches below, do so before installing the 1-CGPMB.exe patch:
 - •1-1BVLTL.exe
 - •1-1C4JFX.exe
 - •1-19O8YL.exe

Technical Bulletin

PAGE: 3/4

Model: **AG-P1/C1** Date: 23-Feb-12 No.: RG178154

- The prerequisites listed below must be installed in the order specified before the **1-1BQ9T8**.exe patch is applied:
 - •1-14N2CZ.exe
 - •1-166VI5.exe
 - •1-169LYL.exe
 - •1-15PZTE.exe
 - •1-15L211.exe
 - •1-16FG9A.exe
 - •1-16G6PJ.exe
 - •1-16SQ5Y.exe
 - •1-18U1L4.exe
 - •1-1A0OPJ.exe
 - •1-1B26V3.exe
- The prerequisites listed below must be installed in the order specified before the **1-1BNTDO**.exe patch is applied:
 - •1-14N2CZ.exe
 - •1-166VI5.exe
 - •1-169LYL.exe
 - •1-152SUR.exe
 - •1-15PZTE.exe
 - •1-153U4F.exe
 - •1-15L211.exe
 - •1-16FG9A.exe
 - •1-16G6PJ.exe
 - •1-16SQ5Y.exe
 - •1-18U1L4.exe
 - •1-1A0OPJ.exe •1-1B26V3.exe
 - •1-1BQ9T8..exe
 - The prerequisites listed below must be installed in the order specified before the **1-1BQAJJ**.exe patch is applied:
 - •1-14N2CZ.exe
 - •1-15L211.exe
 - •1-19Q0OH.exe

Note

- 1. You should keep to install order when the patch will be installed.
- 2. You should execute the reboot when you install the patch of "Exclusive". (The patch names that you installed will be shown in the configuration after reboot.)
- 3. You should execute the reboot when you installed all patches.
- 4. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Technical Bulletin

PAGE: 4/4

Model: **AG-P1/C1** Date: 23-Feb-12 No.: RG178154

Installation Instructions

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute 1-xxxxxx.exe and follow the instructions in the Fiery Patch Downloader.
- Notes about the Fiery Patch Downloader
 - a. Login must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Restart later (not Exclusive) then apply next patch.

or

Reboot. (Exclusive)

- 5 Wait until the Fiery comes to Idle and print the configuration page.
- 6 Verify that the System Update Log section contains the patch number 1-xxxxxx.

Technical Bulletin

PAGE: 1/2

Model: Katana-C2 (D059)		Dat	Date: 26-Jan-12		No.: RD059095			
Subject: Part Changes - New ball bearings-				Prepare	d by: A. T	Takada		
From: PP Service Planning Department 1G								
Classification:	Troubleshooting	□ Part info	orma	tion Action required		required		
		☐ Electrica	rical		Service	ce manual revision		
	☐ Paper path	☐ Transmit/rec		☐ Transmit/receive		mit/receive		fit information
	☐ Product Safety	\square Other ()	☐ Tier 2			

Change: New ball bearings

Reason: To prevent possible breakage of the ball bearings installed in the transfer timing


roller of the registration unit

Model: Katana-C2 (D059)

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
B2342628	M0777428	BALL BEARING :REGISTRATION:DRIVEN:FRONT	1	X/O	82	17	Change
B2342629	M0777429	BALL BEARING :REGISTRATION:DRIVEN:REAR	1	X/O	82	18	Change
-	G0603293	SPACER:6.1X8.5X0.5	2	X/O	83	23	Add

NOTE: When replacing the above parts, replace all 3 parts as a set.

33.Paper Registration 2 (D059/D060/D061)






PAGE: 2/2

Model: Katana-C2 (D059) Date: 26-Jan-12 No.: RD059095

Close up view




Technical Bulletin

Model: AG C1-P1		Dat	ate: 10-Apr-12		No.: RG178155	
Subject: Note for failure ITB				Prepare	d by: н к	(awamura
From: 1st PP Tech Service Sec., PP Tech Service Dept.,						
Classification:	Troubleshooting	☐ Part info	orma	tion		n required
	☐ Mechanical	☐ Electric	☐ Electrical		☐ Servi	ce manual revision
	☐ Paper path	☐ Transm	☐ Transmit/rec		Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	


This RTB is only for RAC and RE, to announce about defective ITBs for Pro C900


Detail

2 pieces of defective ITBs have been distributed to either NSPC, ESPC or both. The defective ITBs have 33 mm longer circumference than the correct ones.



If a defective ITB is used, tension cannot be applied and SC 476 will appear. The photos below show the defective ITB in which tension is not applied even the handle is turned to left.





PAGE: 1/2

Technical Bulletin

PAGE: 2/2

Model: AG C1-P1 Date: 10-Apr-12 No.: RG178155

The target lots number are 091111 and 111111.

The lot number is printed in the part number decal attached to the component box.

Each lot contains 80 pieces of ITB

In the total of 160 ITB, there are 2 defective ITBs.

Procedure for checking

- 1. Check the lot number written on the component box.
- 2. If the lot number is the target number, 091111 or 111111, please check the serial number of te ITB written at the back side of the ITB, indicated in the white circle below.



Defective ITBs have the following serial numbers

- -R0311002-041
- -R0311002-042

If the serial number is either of the above, please use another ITB

3. Even if a defective ITB is used, the ITB will not fit properly; therefore, SC 476 will appear; therefore, replace the ITB

Technical Bulletin

PAGE: 1/1

Model: Aegis P1 / C1 AGL P1/ C1 Date			e: 07-Jun-	12	No.: RG178156	
Subject: Correction on Perfect Binder (GB5000)'s supported paper thickness for signature					d by: H. I	Kawamura
From: 1st PP Ted	ch Service Section, PP Tech S	ervice Dep.				
Classification:	Troubleshooting	☐ Part info	orma	tion Action		required
	☐ Mechanical	☐ Electrical		⊠ Serv		e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	Other ()	☐ Tier2	

Please apply the following correction to your service manual in the section:

7. Specification > Option Specifications > Perfect Binder (D391) > Perfect Binder (D391)

Perfect Binder (D391)

Paper Positioning	Center aligned	Center aligned				
Delivery	Face-down	Face-down				
Signature Thickness	10 to 200 sheets (64 to 80 g/m²) 10 to 150 sheets (81 to 105 g/m²) Max. thickness: Up to 23 mm (0.9 in.)					
D	Signature	Width: 182 to 228.6 mm Length: 257 to 320 mm				
Paper Size	Cover	Width: 257 to 330.2 mm Length: 364 to 487.7 mm				
Day of This large	Signature	64 to 163 g/m ²				
Paper Thickness	Cover	90 to 300 g/m ²				
	Width	139.7 mm to 216 mm				

Incorrect: 64 to 163gsm

Correct: 64 to 105gsm *

^{* 106} to 163gsm paper is available for slip sheets, however, limited to 10 sheets.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1 Date		ate: 13-Jun-12		No.: RG178157		
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared	d by: Tal	kahiro Satoh	
From: PP Solution	n Support Sec. PP Tech Servic	ce Dept.				
Classification:	Troubleshooting	☐ Part info	ormat	tion	Action	required
		☐ Electric	al	☐ Serv		e manual revision
	☐ Paper path	☐ Transmit/red		mit/receive		fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)				
1-1E8G0M.exe	When printing using the direct queue [port 9101], the next job is not				
	transmitted until the current job is printed out.				

Before installing 1-1E8G0M. exe:

- 1. Known issues listed below, read before installing **1-1E8G0M**.exe patch:
 - None
- 2. The following prerequisites must be installed in the order specified before the **1-1E8G0M**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-169LYL.exe
 - 1-15PZTE.exe
 - 1-16FG9A.exe
 - 1-16G6PJ.exe
 - 1-16SQ5Y.exe
 - 1-18U1L4.exe
 - 1-1B26V3.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1E8G0M**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1E8G0M**.exe patch:
 - None.
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1E8G0M**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader



Model: AG-P1/C1

Technical Bulletin

Date: 13-Jun-12 No.: RG178157

PAGE: 2/2

a. Logon must be admin. This is fixed and cannot be modified.

- b. Password is the Fiery administrator login password.
- c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1E8G0M**.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C	Date	e: 26-Jun-	-12	No.: RG178158		
Subject: Release note for Aegis-P1/C1 EFI Patch					d by: Tal	kahiro Satoh
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	☐ Action	required
		☐ Electric	al		Service	e manual revision
☐ Paper path ☐ Transmit/r			it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1F1WPN.exe	- CMYK Simulation Profile setting is not honored when Properties of
	shared Printer driver is launched after setting up a virtual printer.

Before installing 1-1F1WPN. exe:

- 1. Known issues listed below, read before installing **1-1F1WPN**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1F1WPN**.exe patch is installed:
 - 1-14N2CZ.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1F1WPN**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1F1WPN**.exe patch:
 - None.
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1F1WPN**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1F1WPN**.



Model: AG-P1/C1

Technical Bulletin

Date: 26-Jun-12 No.: RG178158

PAGE: 2/2

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1 Date					12	No.: RG178159
Subject: Release note for Aegis-P1/C1 EFI Patch					d by: Hir	oshi Wada
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
☐ Paper path ☐ Transmit/re			it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1F1X94.exe	- A character with a specific font is printed incorrectly for a particular file.

Before installing 1-1F1X94. exe:

- 1. Known issues listed below, read before installing **1-1F1X94**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1K94**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-169LYL.exe
 - 1-152SUR.exe
 - 1-15PZTE.exe
 - 1-153U4F.exe
 - 1-16FG9A.exe
 - 1-16G6PJ.exe
 - 1-16SQ5Y.exe
 - 1-18U1L4.exe
 - 1-1B26V3.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1F1X94**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1F1X94**.exe patch:
 - 1-19DTMJ.exe
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1F1X94**.exe and follow the instructions in the Fiery Patch Downloader.



PAGE: 2/2

Model: **AG-P1/C1** Date: 19-Jul-12 No.: RG178159

- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1F1X94**.

Technical Bulletin

PAGE: 1/10

Reissued:19-Oct-12

Model: Aries-P1.	5/C1.5, AG-P1/C1	e: 01-Oct-	12	No.: RM077075a		
Subject: New ser	vice part: External Power Sup	Prepared	d by: Jun	ji Kobayashi		
From: PP Tech S	ervice Dept., 1st PP Tech Serv					
Classification:	☐ Troubleshooting	□ Part info	ormat	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path ☐ Transmit/re			eive	Retrof	fit information
	☐ Product Safety	$\hfill \Box$ Other ()	☐ Tier 2	

General

This bulletin provides information on the External Power Supply Unit exclusive to the Aries-P1.5/C1.5 and Aegis-P1/C1. The external PSU, which activates the exhaust fans located behind the PCDU, was registered as a service part to counter uneven density issues (dark bands) caused by ozone accumulation that occur under specific conditions. (See 'Cause' on the following page.)

Part information

Please add the following part to your Aries-P1.5/C1.5 and Aegis-P1/C1 parts catalog.

Part number	Description	Page	Index	Note
M0772500	Service Parts: Power Supply Unit	87	17	Add For ProC900
M0772500	Service Parts: Power Supply Unit	93	20	Add For ProC901



M0772500 Service Part: Power Supply Unit

AC power cable included - NA 125V

- EU 250V



Model: Aries-P1.5/C1.5, AG-P1/C1


Technical Bulletin

Reissued:19-Oct-12

Date: 01-Oct-12

Symptom

40mm wide dark bands appear at 314mm intervals



Cause

Normally, the exhaust fans behind the PCDU that operate for a prescribed time after completing a job could ventilate the ozone in approximately two hours. However, when the machine is run, if not all, under most of the following conditions, ozone emission increases and causes the ozone to easily accumulate.

- Charge Corona exceeds 100K
- Machine is operated in low temperature/low humidity environment, and the correction values are applied to the Charge corona unit according to the environment
- Machine is left unused overnight in a low temperature/humidity environment with its power turned off

Dark Bands could appear on the first job in the morning when meeting the above conditions.

Solution

<u>First step:</u> Replace the drum and the charge corona unit. If this doesn't resolve the dark bands, do the next step.

<u>Second step:</u> Set the machine so that the exhaust fans continue to operate while the machine power is turned on. (You may want to ask for customer approval when applying this setting to the SP.)

How to activate the exhaust fans

- 1. From the control panel, go to [User Tools] [System Settings] [Timer Settings], and set the Panel Off Timer to "Off".
- 2. Change the settings for the ozone and developer unit fans in the following SPs: SP1-940-03, -04; default 56 (=60min) \rightarrow 1270 (=21 hours)
- 3. Change the low power mode fusing unit temp to 0 degrees C in the following SPs: SP1-202-01, -02; default 110 (=100 degrees C) → 0 degrees C

Finally, if both of the above steps do not resolve the problem, again, ask for customer approval and install the external power supply unit.

PAGE: 2/10

No.: RM077075a

Technical Bulletin

PAGE: 3/10

Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a

Notes on Using the External PSU

- When using the external PSU, confirm that the LED is lit before turning on the main power. If the main power is turned on while the LED is not lit, this will result in SC.
- The LED will not light up if the breaker switch is turned off or if the timer is set to off.
- Refer to the last section of this document for instructions on how to switch supply source between Pro C900 / Pro C901 and the external PSU.

PAGE: 4/10


Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a


How to Install the External PSU

Caution: Make sure the external PSU and main power are turned off before carrying out the following procedure.

1. Open the rear controller box.



2. Open the connector cover and connect the harness from the external PSU.




PAGE: 5/10


Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a

3. Disconnect the fan connectors from the IOB (CN241/CN243).



- 4. Relay the harnesses from the external PSU.
- 4-1. Connect the two connectors from the external PSU circled in red to CN241 and CN243.






PAGE: 6/10

Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a

4-2. Connect the two connectors circled in red to the fan connectors.



Technical **B**ulletin

PAGE: 7/10

Reissued:19-Oct-12


Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a


4-3. Connect the ground cable.












PAGE: 8/10 Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a

5. Close the rear controller box.










6. Connect the power cable to the external PSU.






PAGE: 9/10

Reissued:19-Oct-12

Model: Aries-P1.5/C1.5, AG-P1/C1 Date: 01-Oct-12 No.: RM077075a

7. Turn on the breaker switch.



Back side of PSU

Breaker ON



Front side of PSU

LED lights up




PAGE: 10/10

Reissued:19-Oct-12


Switching Supply Between Pro C900 / Pro C901 and the External PSU

When the external PSU is used



The LED will light up by default when the external PSU is connected.

When Pro C900 / Pro C901 is used



Technical Bulletin

PAGE: 1/1

Model: Aries-P1.	.5/C1.5, AG-P1/C1	e: 01-Oct-	12	No.: RM077076		
	of Failure - Adjustment #0218 of for Skilled Operators	nt	Prepared	d by: Hide	etoshi Kawamura	
From: PP Tech S	ervice Dept., 1st PP Tech Serv	vice Sect.				
Classification:	Troubleshooting	☐ Part info	orma	tion		required
	☐ Mechanical ☐ Electrical					e manual revision
☐ Paper path ☐ Transmit/rec				eive	☐ Retrof	fit information
	☐ Product Safety	\square Other ()	⊠ Tier 2	

General

"0218: Adjust Maximum Image Density" of the Adjustment Setting for Skilled Operators menu was found with a failure as described in 'Symptom' below. Until a solution becomes available, it is requested to field technicians and users to refrain from applying this adjustment. As a workaround, adjust the maximum toner amount in the SP mode as this will substitute the effect generated by "0218: Adjust Maximum Image Density."

Symptom

While adjustment made in "0218: Adjust Maximum Image Density" changes the target value for process control in order to achieve the target image density, once process control is executed during a job, the system will ignore the adjustment made in "0218" and return to the default process control target value.

Cause

Software bug

Solution

Bug fix: TBD

Workaround

1. Set the value for "0218: Adjust Maximum Image Density" to "0".

2. Apply the following SP setting.

SP	Color	Default	-5	-4	-3	-2	-1	+1	+2	+3	+4	+5
3-531-	Bk	0.476	0.376	0.396	0.416	0.436	0.456	0.496	0.516	0.536	0.556	0.576
001												
3-531-	С											
002												
3-531-	М											
003												
3-531-	Υ											
004												

Important: DO NOT apply a value higher than 0.576.

3. Execute process control (SP 3820-002) for the above SP modification to take effect.


PAGE: 1/2

Model: Aries-P1.	.5/C1.5, AG-P1/C1	te: 14-Nov	-12	No.: RM077078			
Subject: Release	e note: modified development u	Prepare	d by: Hide	etoshi Kawamura			
From: PP Tech S	ervice Dept., 1st PP Tech Ser						
Classification:	☐ Troubleshooting	□ Part info	orma	tion	Action	required	
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision	
	☐ Paper path ☐ Transmit/re			eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2		

This RTB has been issued to announce the release of the new development units. The doctor gap of the modified development units is adjusted to achieve the optimum developer/toner mixture mass per area effective for the image quality issue known as "fuzzy lines".


Part Information


Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
M0773290	M0773294	Development Unit: Yellow	1	O/O	95	*	Change
M0773291	M0773295	Development Unit: Magenta	1	0/0	95	*	Change
M0773292	M0773296	Development Unit: Cyan	1	O/O	95	*	Change
M0773293	M0773297	Development Unit: Black	1	O/O	95	*	Change



PAGE: 2/2

Explanation of Fuzzy Lines






The symptom known as "fuzzy lines" is a result of insufficient supply of toner/developer mixture to the drum surface via the development rollers.

Photos A and B below show the slit between the upper and lower development rollers viewed from the drum.

Photo A: The "fuzzy" condition of the toner/developer mixture is reflected directly to the output, generating the fuzzy lines.

Photo B: The mixture is solid and generates proper output.



Cut in Serial Numbers

From June 2012 production V9910600001 ~

T0106000001 ~

PAGE: 1/2

Reissued:08-Jan-13

Model: AG-P1 (G178)	Date: 21-Dec-12	No.: RG178160a

RTB Reissue

The items in **bold italics** were corrected or added.

Subject: Perfect rollers	Binder Jam300/Jam303 caus	Prepared	by: T.Miyamoto	
From: 1st Tech se	ervice Sect., PP Tech Service			
Classification:	☐ Troubleshooting	☐ Part informati	ion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path ☐ Transmit/rece			☐ Retrofit information
	☐ Product Safety	☐ Other ()	☐ Tier 2

SYMPTOM

JAM300 (P-Binder: Job Data Error) and JAM 303 (P-Binder: Cover Registration Sensor: Late) could occur on a Perfect Binder in use with a ProC900.

Note: This symptom has been reported only in the above configuration.

CAUSE

Fusing oil of the ProC900 adheres to the paper transport rollers in the Perfect Binder via the printed paper, causing the rollers to swell and feed the paper faster than the prescribed speed.

ACTION


Replace the following 3 parts.

- D391 1335 Transport Roller: M3: PF4140P645B1 (See figure 1.)
- D391 1341 Transport Roller: M4: PF4140P729B1 (See figure 2.)
- D391 1331 Transport Roller: M1: PF4140P633C3 (See figure 2.)

These rollers should be replaced at approximately 1200kp, A4/LT.

Figure 1: Perfect Binder P/C; page 110, index #5

55.Cover Feed Regist Section 1 (D391)






PAGE: 2/2

Reissued:08-Jan-13

Model: AG-P1 (G178)	Date: 21-Dec-12	No.: RG178160a
---------------------	-----------------	----------------

Figure 2: Perfect Binder P/C; page 126, index #3, index #18



Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date: 5-Sep-13			No.: RG178161
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared	d by: Y.	Okano	
From: PP Solutio	n Support Sec. PP Tech Servi	ce Dept.				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1GF8FB.exe	- Printer Counter behavior is incorrect, when a job is printed from
	Document Server.

Before installing 1-1GF8FB.exe:

- 1. Known issues listed below, read before installing **1-1GF8FB**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1GF8FB**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-152SUR.exe
 - 1-15PZTE.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1GF8FB**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1GF8FB**.exe patch:
 - 1-1BQAJJ.exe
 - 1-19ZWOG.exe
 - 1-190YWR.exe
 - 1-181A8R.exe
 - 1-18L6E7.exe
 - 1-188AT1.exe
 - 1-160XYY.exe
 - 1-169LZP.exe
 - 1-16ZGXB.exe
 - 1-16MO95.exe
 - 1-16CG41.exe
 - 1-15M2R6.exe
 - 1-15ZNHE.exe
 - 1-1555EN.exe



PAGE: 2/2

Model: **AG-P1/C1** Date: 5-Sep-13 No.: RG178161

- 1-157W91.exe
- 1-19FRM0.exe
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute 1-1GF8FB.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1GF8FB**.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date	e: 5-Sep-	13	No.: RG178162	
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared by: Y. Okano				
From: PP Solutio	n Support Sec. PP Tech Servi	ce Dept.					
Classification:	☐ Troubleshooting	☐ Part informa		tion	☐ Action	n required	
	☐ Mechanical	☐ Electric	al	☐ Serv		vice manual revision	
	☐ Paper path	ath Transmit/red		eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()			

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1HU4PQ.exe	- Unable to disable IPv6 option.

Before installing 1-1HU4PQ.exe:

- 1. Known issues listed below, read before installing **1-1HU4PQ**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1HU4PQ**.exe patch is applied:
 - 1-14N2CZ.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1HU4PQ**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1HU4PQ**.exe patch:
 - None.
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute 1-1HU4PQ.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1HU4PQ**.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date	e: 5-Sep-	13	No.: RG178163
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared by: Y. Okano			
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification:	Troubleshooting	☐ Part informa		tion	☐ Action	n required
	☐ Mechanical	☐ Electrical		trical		ce manual revision
	☐ Paper path	☐ Transmit/red		eive	☐ Retrof	fit information
	☐ Product Safety	⊠ Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1HNSEB.ex	e - An assertion error is observed while processing a particular file.

Before installing 1-1HNSEB.exe:

- 1. Known issues listed below, read before installing **1-1HNSEB**.exe patch:
 - This patch does fix the assertion issue but the job will not print because PDF data is bad and unprintable.
- 2. The following prerequisites must be installed in the order specified before the **1-1HNSEB**.exe patch is applied:
 - 1-14N2CZ.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1HNSEB**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1HNSEB**.exe patch:
 - 1-19SKBZ.exe
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1HNSEB**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1HNSEB**.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date: 5-Sep-13		13	No.: RG178164
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: Y. Okano		
From: PP Solutio	n Support Sec. PP Tech Servi	ce Dept.				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1IIDES.exe	- Input Tray setting is not honored while printing with a virtual printer.

Before installing 1-1IIDES.exe:

- 1. Known issues listed below, read before installing **1-1IIDES**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1IIDES**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-169LYL.exe
 - 1-152SUR.exe
 - 1-15PZTE.exe
 - 1-153U4F.exe
 - 1-15L211.exe
 - 1-16FG9A.exe
 - 1-16G6PJ.exe
 - 1-16SQ5Y.exe
 - 1-17XIFZ.exe
 - 1-18U1L4.exe
 - 1-1A0OPJ.exe
 - 1-1B26V3.exe
 - 1-1BN9NF.exe
 - 1-1BQ9T8.exe
 - 1-1BNTDO.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1IIDES**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1IIDES**.exe patch:
 - 1-18LQLE.exe
 - 1-19FHI5.exe



PAGE: 2/2

Model: **AG-P1/C1** Date: 5-Sep-13 No.: RG178164

4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.

5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1IIDES**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1IIDES**.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date: 5-Sep-13			No.: RG178165	
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared by: Y. Okano				
From: PP Solution Support Sec. PP Tech Service Dept.							
Classification:	☐ Troubleshooting	☐ Part informa		tion	☐ Action	n required	
	☐ Mechanical	☐ Electric	al	☐ Serv		vice manual revision	
	☐ Paper path	oath Transmit/red		eive	Retrof	fit information	
	☐ Product Safety	Other ()			

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1J017Y.exe	- Garbled data occurs with Impose settings for a particular job.

Before installing 1-1J017Y.exe:

- 1. Known issues listed below, read before installing **1-1J017Y**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1J017Y**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-169LYL.exe
 - 1-152SUR.exe
 - 1-15PZTE.exe
 - 1-153U4F.exe
 - 1-16FG9A.exe
 - 1-16G6PJ.exe
 - 1-16SQ5Y.exe
 - 1-179ZXD.exe
 - 1-18U1L4.exe
 - 1-1B26V3.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1J017Y**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1J017Y**.exe patch:
 - 1-19DTMJ.exe
 - 1-19SKBZ.exe
 - 1-1F1X94.exe
 - 1-1HNSEB.exe
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.



PAGE: 2/2

Model: **AG-P1/C1** Date: 5-Sep-13 No.: RG178165

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute 1-1J017Y.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1J017Y**.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date: 18-Sep-13			No.: RG178166
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: Hiroshi Wada		
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification:	Troubleshooting	☐ Part informat		tion	☐ Action	required
				☐ Servi		ice manual revision
	☐ Paper path	per path		eive	☐ Retrof	fit information
	☐ Product Safety	Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1JHCG8.exe	- A Compatibility patch to support Web Configure on Internet Explorer
	10.

Before installing 1-1JHCG8.exe:

- 1. Known issues listed below, read before installing **1-1JHCG8**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **1-1JHCG8**.exe patch is applied:
 - None.
- 3. Do NOT install any of the following patch(es) after installing the **1-1JHCG8**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1JHCG8**.exe patch:
 - None.
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute 1-1JHCG8.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. Verify that the System Updates Log section contains the patch number **1-1JHCG8**.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date: 15-Nov-13		-13	No.: RG178167
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: Y. Okano		
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification: Troubleshooting Part info		information		☐ Action	Action required	
	☐ Mechanical	☐ Electrical		☐ Service manu		ce manual revision
	☐ Paper path ☐ Transmit		「ransmit/receive ☐ Retrofit		fit information	
	☐ Product Safety	Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
1-1KPSM2.exe	- Validity period of the SSL authentication certificate was extended
	due to its expiration.

Before installing 1-1KPSM2.exe:

- 1. Known issues listed below, read before installing **1-1KPSM2**.exe patch:
 - None.
- The following prerequisites must be installed in the order specified before the 1-1KPSM2.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-1JHCG8.exe
- 3. Do NOT install any of the following patch(es) after installing the **1-1KPSM2**.exe patch. If you must install any of the patch(es) below, do so before installing the **1-1KPSM2**.exe patch:
 - None
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **1-1KPSM2**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.



Model: AG-P1/C1

Technical Bulletin

Date: 15-Nov-13 No.: RG178167

PAGE: 2/2

7. Verify that the System Updates Log section contains the patch number **1-1KPSM2**.

Technical Bulletin

PAGE: 1/2

Model: AG-P1/C1			Date	e: 15-Nov	-13	No.: RG178168
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: Y. Okano		
From: PP Solution Support Sec. PP Tech Service Dept.						
Classification:	Classification: Troubleshooting Part inform		ormat	tion	Action	required
	☐ Mechanical	☐ Electrical			Service	ce manual revision
	☐ Paper path ☐ Transmit/r		it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	⊠ Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT136127.exe	- Images might not be printed correctly due to the incorrect imageable
	area dimensions in PPD.

Before installing FIT136127.exe:

- 1. Known issues listed below, read before installing **FIT136127**.exe patch:
 - None.
- 2. The following prerequisites must be installed in the order specified before the **FIT136127**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-15L211.exe
- 3. Do NOT install any of the following patch(es) after installing the **FIT136127**.exe patch. If you must install any of the patch(es) below, do so before installing the **FIT136127**.exe patch:
 - None.
- 4. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **FIT136127**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.

Model: AG-P1/C1

Technical Bulletin

Date: 15-Nov-13 No.: RG178168

PAGE: 2/2

7. Verify that the System Updates Log section contains the patch number **FIT136127**.

Technical Bulletin

PAGE: 1/3

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1			Date: 29-Nov-13			No.: RM077098
Subject: Summa - Toner	Prepared I	by: J. K	obayashi			
From: PP Tech Service Dept., 1st PP Tech Service Sect.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	Part info	al	eive	Servic	required e manual revision it information


General

This bulletin summarizes the information announced in previously released RTBs for image quality problems originating in the development unit and provides an explanation of the differences between toner degradation and developer degradation along with the correct actions required to avoid unneeded developer replacements, which in fact, often take place without successful results due to misunderstanding toner degradation and developer degradation.

How does toner degrade?

Toner degrades when fresh toner is not supplied to the development unit due to its low consumption rate, which is caused by the following 3 factors:

- Low image coverage ratio
- Idling of C, M, Y development units when printing in B/W mode
- Idling of the mainframe while optional devices are in operation



PAGE: 2/3

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1 Date: 29-Nov-13 No.: RM077098

What are the major problems caused by toner degradation?

Developer will last for its prescribed PM yield of 1200Kp.

Do not replace the developer when encountering the following problems as these problems are caused by toner degradation, not developer degradation.

Symptom	Cause	Solution	RTB
a) Scratched image	 Change in the charge applied to the toner affects the development capacity and transferability. Toner transfer conditions for LE and TE are set incorrectly. 	 Replace with fresh toner. Optimize the paper settings with Advanced setting in Paper Library 	●RM077077b ●RM077032a
b) Uneven density	 Change in the charge applied to the toner affects the development capacity and transferability. 	 Replace with fresh toner. User adjustment #0220 Adjust Density Difference Across Feed Direction 	RM077077bAdjustment Settings for Skilled Operators
c) Mottled effect	 Transferability reduces under the following conditions: Printing in FC following a long B/W job Paper conditions 	 Replace with fresh toner for C,M,Y Use a different paper Optimize controller settings 	●RM077077b ●RM077095
d) Toner scattering	 Low toner fluidity in the development unit (= high toner concentration) disables the sensor to properly detect the toner amount. * Incorrect initial developer installation is also a possible cause. 	Confirm proper developer replacement Replace with fresh toner	●RM077072c ●RM077077b
e) Clogged doctor gap	 Low toner fluidity in the development unit (= high toner concentration) causes toner clumps to form that clog the doctor gap. 	● Clean the doctor gap ■ Remove toner clumps	●RM077031b

PAGE: 3/3

No.: RM077098

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1 Date: 29-Nov-13


Improvements brought from the new toner

Wax contained in the toner was changed to a new wax with higher heat resistivity and tolerance for degradation. Application of this new toner has made improvements for the following:


- SC36x (toner density errors) as a result of clogged sub-hopper, which occurs when heat resistivity and fluidity of the toner reduces under high temperature environment.
- Toner scattering as a result of low toner fluidity in the dev unit (= high toner concentration), disabling proper toner detection.
- Dirty background as a result of toner overflowing from the drum cleaning and ITB cleaning units.

New toner bottle

In line with the new toner, the toner bottle was modified.



The lot number of the toner bottle is on the bottom cap.



Lot number information

Toner bottles of the following s/n or later contain the new toner:

	Black	Cyan	Magenta	Yellow
RAC	30108222 ~	30327921 ~	30128021 ~	30148121 ~
RE	3B0317-05 ~	3B0557-02 ~	3B0267-02 ~	3B0257-08 ~
RA	25835901 ~	25835501 ~	25834001 ~	25835901 ~

Technical Bulletin

PAGE: 1/6

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1 Dat			e: 29-Nov-	13	No.: RM077099		
Subject: Summary of OPC drum related problems					Prepared by: J. Kobayashi		
From: PP Tech Service Dept., 1st PP Tech Service Sect.							
Classification:	☑ Troubleshooting☑ Mechanical☑ Paper path☑ Product Safety	Part inf Electric Transm Other (al		Servi	n required ce manual revision fit information	


General

This bulletin summarizes the information announced in previously released RTBs for image quality problems originating in the OPC drum. Details are described on how the drum wears along with the recommended actions to avoid unnecessary drum replacements when encountering problems originating in other components. It is important to take note that images are affected at a 314 mm interval (= drum circumference), if the image quality problem is caused by drum scratches.

How do drum scratches occur?

Cause 1: Drum scratches caused by cleaning components

Contact between the cleaning components and OPC drum in the repeated cleaning operation wears the drum surface over time. As shown in the illustration below, the drum used for Aries consists of 5 layers. While the topmost overcoat layer is hard and durable, the charge transfer and charge generation layers are much more delicate. Once the overcoat layer is removed through abrasion, the two layers beneath will wear out very quickly, resulting in abnormal images. This however will not occur for 2,400kp, which is the prescribed drum life, provided that the machine is used under normal conditions.




PAGE: 2/6

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1

Date: 29-Nov-13 No.: RM077099


Cause 2: Drum scratches caused by insufficient lubrication

If the drum surface is not sufficiently lubricated, excess friction between the drum and cleaning blade could cause the cleaning bade to flip (or bend) and scratch the drum.



Cause 3: Drum scratches caused by narrow PG

Another factor that causes drum scratches is a narrow PG (potential gap), in which the gap between the development roller and drum is narrower than the specification. In this condition, stress is applied to the developer in the development process because the developer is forced to move through a narrow gap, generating excess electrical current along with heat and pressure. As a result, developer adheres to the surface of the development roller and toner accumulation continues, eventually scratching the drum.



Solution to drum scratch problems <u>Drum scratches caused by cleaning components</u>


Replace with a new drum.

Drum scratches caused by insufficient lubrication

Replace with a new drum. Make sure to lubricate the new drum before installing.

Drum scratches caused by narrow PG

- A narrow PG could be caused by an incompletely fastened drum knob. Refer to the following RTB for the proper drum knob fastening procedure.
 - > RG178128d (pages 5~9)
- Check that the drum is properly installed.
 - > RG178128d (page 4)
- Remove the toner adhered to the surface of the development roller.
 - > RG178128d





PAGE: 3/6

 Do #208 "Execute Toner Refreshing" in the Adjustment Settings for Skilled Operators Menu.

NOTE: The developer DOES NOT have to be replaced.

If the DG (doctor gap) is clogged with toner, remove the clogged toner with a piece of paper, then do #208 "Execute Toner Refreshing" again.

Date: 29-Nov-13

PAGE: 4/6

No.: RM077099

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1

Image quality problems caused by the OPC drum

Symptom 1


Images appear unclear and fuzzy when running the machine in a high temperature and high humidity operational environment.

Cause

In a high temperature/humidity environment, corona products cause the lubricant powder to decompose and ionize, which combines with moisture. In this condition, the drum surface resistivity is reduced and dots are not aligned as expected to properly develop the electrostatic image.


Solution

Do #203 "Execute Photoconductor Refreshing" of the Adjustment Settings for Skilled Operators to remove the affected lubricant powder (decomposed and ionized), which stays only on the surface layer.



Symptom 2

Vertical lines appear at a 314 mm interval (= drum circumference).





PAGE: 5/6

Symptom 3


Image density appears uneven, and darker compared to the surrounding area, when running the machine in a low temperature and low humidity environment.

Cause

Corona products penetrate the drum surface layer and change the charge characteristics.

Solution

Keep the exhaust fans running continuously to completely get rid of corona products from the system by modifying the settings below.



- 1. Enter User Tools → System Settings → Timer Setting, and set the Timer Setting to OFF.
- 2. SP1-940-03: Ozone fan timer setting (default: 56min) Change this value to "1270" min.
 - SP1-940-04: Development fan timer setting (default: 56min)

Change this value to "1270" min.

SP1-202-01: Heating roller temperature in low power mode (default: 110 degrees C) Change this value to "0" degrees C.

^{*} See RTB RM077075a for details.

Date: 29-Nov-13 No.: RM077099

PAGE: 6/6

Problems that are NOT caused by the OPC drum

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1

Drums should NOT be replaced to resolve the problems described in the table below.

Symptom	Cause	Solution	RTB
a) SC396~ SC399	• Most of these SCs are caused by drum motor lock as a result of stuck waste toner in the development gap between the development roller and OPC drum, which occurs when the drum rotation suddenly stops in an abnormal state.	 Power cycle the machine a few times. Manually turn the development roller with your hands to remove stuck waste toner. 	●RM077086a
b) Uneven density randomly	• Change in the charge applied to the toner affects the development capacity and transferability. Possible causing factors are: low PV per job, high ratio of text, high usage rate of finishing options, high ratio of B/W print jobs, which apply stress to the color toners.	 Enable ACS to prevent idling of CMY units. Increase the amount of toner exhausted in the toner refresh mode. 	●RM077095 ●RM077077b
c) Vertical streaks	 If the streaks do not appear at 314mm intervals (= drum circumference), the problem is caused by either of the following: Dirty charge unit caused by toner scattering Change in charge level caused by unevenly lubricated drum surface 	 Replace with new toner. Remove toner clumps. Positively replace parts at the prescribed PM yield. 	●RM077031b
d) Horizontal bands	 If the streaks do not appear at 314mm intervals (= drum circumference), the bands should be considered as "shock-jitter/banding". 	● Do troubleshooting procedures for "shock-jitter/banding".	●RM077019g
e) Dirty printout	 Low toner fluidity causes contamination inside the machine results in the following: Toner scattering around the development unit Degradation of waste toner collection in the ITB unit 	Replace with new toner.Remove toner clumps	 RM077072c RM077098 New toner bottle contains new toner from certain Lot Nos.
f) Dirty backgroun d	● Low toner fluidity in the development unit disables the sensor to properly detect the amount of toner in the unit. As a result, the sensor detects extremely high toner concentration.	Replace with new toner.Remove toner clumps.	●RM077072c ●RM077098

Notes: Please refer to RTB RM077098 for how to find a Lot. No. on a new toner bottle.

Technical Bulletin

Model: Aries P1.5/C1.5, Aegis C1/P1 Date			e: 05-Feb	-14	No.: RM077104	
Subject: Part Information- DRUM Knob fastening tool				Prepared	d by: T.M	liyamoto
From: PP Service	: PP Service Planning Department 1G					
Classification:	☐ Troubleshooting	□ Part info	orma	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier 2	

The following part was added as an individual service part.

Reason: To prevent drum scratching caused by narrower PG.

Fastening the drum knob incompletely will cause the drum cleaning unit to apply pressure to the drum and narrow the PG at the front side. Then, developer piled up on the mag roller will scratch the drum.

This tool assists the tightening drum knob completely, because the drum knob might be incompletely tightened when it is done without the tool.

New P/N	Description	Q'ty	Int	Page	Index	Note
D1792445	KNOB:TORQUE LIMITER MECHANICAL CLUTCH:ASS'Y	1	-	377	10	Add



Add **D1792445**

PAGE: 1/3

NOTE:

(Precondition)

When you install the drum and fasten the drum knob with the tool, the Drum Cleaning Unit should not be installed on the PCDU.

If the drum knob is loosened with the drum cleaning unit installed, make sure to remove the drum cleaning unit, and then fasten the knob.

Model: Aries P1.5/C1.5, Aegis C1/P1

Date: 05-Feb-14

No.: RM077104

Fastening the drum knob with the drum cleaning unit installed will cause the drum cleaning unit to apply pressure to the drum and narrow the PG at the front side.

Procedure to fasten the drum knob with the tool

1. Insert the tool into the drum knob.







Date: 05-Feb-14

PAGE: 3/3


No.: RM077104

2. Turn the drum knob clockwise until the tool runs idle.



3. Confirm the drum knob position.

Model: Aries P1.5/C1.5, Aegis C1/P1



(Detailed information of the correct drum knob position is included in RG178128d)

☐ Mechanical

☐ Paper path

☐ Product Safety

Technical Bulletin

☐ Electrical

Other (

☐ Transmit/receive

Model: Aries P1.5/C1.5, AegisP1/C1			Date: 07-Feb-14 No.: RM07710			
Subject: White line caused by incorrect insertion of the dust shield glass			Prep	Prepared by: T.Miyamoto		
From: PP Service	e Planning Department 1G	;				
Classification:	□ Troubleshooting	□ Part info	rmation	☐ Action	n required	

⊠ Tier 2

☐ Service manual revision

☐ Retrofit information

PAGE: 1/2


SYMPTOM

White line, that appears specifically after cleaning the dust shield glass in the laser unit


CAUSE

After cleaning the dust shield glass and sliding it back into the laser unit, it is falsely inserted at an angle, causing the guide seal attached inside the bracket to peel off. The guide seal removed and squashed inside the bracket blocks the laser, resulting in the white line.


1. The dust shield glass is inserted into the bracket at an angle.



2. The tip of the dust shield glass catches the guide seal.



3. The guide seal is peeled off and squeezed inside, creating a blockage in the optical path.





PAGE: 2/2

Model: Aries P1.5/C1.5, AegisP1/C1 Date: 07-Feb-14 No.: RM077105

PREVENTIVE MEASURE

Take note of the following 2 points when cleaning the dust shield glass to prevent the guide seal from peeling off.

- · When inserting the dust shield glass into the bracket, insert it straight, not at an angle.
- Insert the dust shield glass into the bracket gently and make sure the tip of the glass is not catching the guide seal. If you feel the glass is caught, pull it out and slide it in again. Repeat the procedure until you confirm proper insertion.

What to do when the guide seal has been peeled off from the bracket

<u>Temporary solution</u>: Cut the peeled off portion of the guide seal, then insert the shield glass.


<u>Permanent solution</u>: Procure new brackets. (Brackets have been newly registered as service parts.)

For Yellow and Cyan

New p/n	Description
G1782091	PROTECTION:SHIELD GLASS:LEFT:ASS'Y

For Magenta and Black

New p/n	Description
G1782092	PROTECTION:SHIELD GLASS:RIGHT:ASS'Y



	П


PAGE: 1/1

Model: AG-P1/C1 Da			Dat	e: 28-Feb-	14	No.: RG178169
Subject: Part information for frame section3			Prepared	d by: Hiro	oaki H Matsui	
From: 1st Tech se	ervice Sect., PP Tech Service	Dept.				
Classification:	Troubleshooting	□ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Please add the following part to Frame Section 3 of your parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G1787174	DUCT:INTERMEDIATE TRANSFER:LOWER RIGHT	1	1	221	20	New Index

101.Frame Section 3 (D016/G178)



Technical Bulletin

PAGE: 1/2

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1 Date			te: 07-Feb-	-14	No.: RM077106	
Subject: Troubleshooting skew correction error (SC270,271 and 272)				Prepared	by: T. M	iyamoto
From: PP Tech Se	ervice Dept., 1st PP Tech Serv	ice Sect.				
Classification:		☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electrical			☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	☐ Other ()	⊠ Tier 2	

SYMPTOM

SC270: Skew correction error Y SC271: Skew correction error M SC272: Skew correction error C

CAUSE

The value in SP2-104-001 \sim 003 (Skew Adjustment Display) exceeds the upper limit and locks the skew correction motor.

SOLUTION

When encountering SC270 or SC271 or SC272, do the following procedure before replacing the laser unit.

1. Do the following SP to initialize the skew adjustment values.

SP2-117-001	Resets the skew adjustment value for the C skew correction motor
SP2-117-002	Resets the skew adjustment value for the M skew correction motor
SP2-117-003	Resets the skew adjustment value for the Y skew correction motor

2. Confirm the adjustment values are all reset to "0" in the following SP.

SP2-104-001	Displays the C skew adjustment value against Bk
SP2-104-002	Displays the M skew adjustment value against Bk
SP2-104-003	Displays the Y skew adjustment value against Bk

- 3. Execute MUSIC (S2-153-001; MUSIC Condition Settings 1 Manual Execute: Mode a)
- 4. Execute MUSIC again. (MUSIC needs to be executed twice in succession.)
- 5. Check if the skew amount results in the range "+15 micro m \sim -15 micro m" in the following SP.

SP2-181-011	Skew amount C
SP2-181-027	Skew amount M
SP2-181-043	Skew amount Y



PAGE: 2/2

Model: Aries-P1.5/C1.5, AG-P1/C1, AGL-P1/C1

Date: 07-Feb-14 No.: RM077106

6. If the results do not fall within the range, execute MUSIC again and check the results.

7. If the skew amount is still beyond the range, replace the laser unit and/or IOB1 to complete the procedure.

Possible cause of the problem: Defective skew correction motor or IOB1.


PA	١G	F:	1	-
	マ		/	

Model: AG-P1/C1				te: 11-Mar	-14	No.: RG178170
Subject: Part information for frame section3					d by: Hird	oaki H Matsui
From: 1st Tech s	ervice Sect., PP Tech Service	e Dept.				
Classification:	Troubleshooting	□ Part inf	orma	tion	Action	n required
	☐ Mechanical	☐ Electrical			☐ Service	ce manual revision
	☐ Paper path	☐ Transmit/rece		eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

Please add the following part to the 34. PCDU 1 Section

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G1783475	SPONGE:COUPLING:TONER SUPPLY:DEVELOPMENT UNIT	1	1	87	18	New Index

34.PCDU 1 (D016/G178)




Technical **B**ulletin

PAGE: 1/1

Model: Aries P1.5		Date: 22-Apr-14		No.: RM077112		
Subject: Part Info	Prepared by: T.Miyamoto			Miyamoto		
From: PP Service						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part inf☐ Electric☐ Transm☐ Other (al		☐ Servi	on required ice manual revision ofit information 2

Please add the following part to your parts catalog.

Model	P/N	Description	Q'ty	Int	Page	Index	Note
Aries P1.5/C1.5			1	-	277	16	Add
AG P1/C1	D3554586	STAY:END FENCE	1	-	277	17	Add
LCIT5020			1	-	17	17	Add



Technical Bulletin

PAGE: 1/5

Model: AG-P1/C1			Dat	e: 03-Sep	-14	No.: RG178171
Subject: Release note for Aegis-P1/C1 EFI Patch					d by: Hire	oshi Wada
From: PP Solutio	n Support Sec. PP Tech Servic	e Dept.				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety)		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT204758.exe	- Configure application does not active from WebTools, if Java
	1.7u51 is installed on the Windows OS or Mac OS.

Before installing FIT204758.exe:

- 1. Please refer to the patch Addendum for additional information regarding this release.
- 2. Known issues listed below, read before installing FIT204758.exe patch:
 - None.
- 3. The following prerequisites must be installed in the order specified before the **FIT204758**.exe patch is applied:
 - 1-14N2CZ.exe
- 4. Do NOT install any of the following patch(es) after installing the **FIT204758**.exe patch. If you must install any of the patch(es) below, do so before installing the **FIT204758**.exe patch:
 - 1-1JHCG8.exe
 - 1-1H9BQT.exe
- 5. This patch is not exclusive. It may be installed along with other patches. One server Reboot is sufficient for all patches to take effect on the system.
- 6. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute FIT204758.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)



PAGE: 2/5

Model: **AG-P1/C1** Date: 03-Sep-14 No.: RG178171

6. Wait until the Fiery controller reaches Idle and print the Configuration page.

7. Verify that the System Updates Log section contains the patch number **FIT204758**.

PAGE: 3/5

Model: **AG-P1/C1** Date: 03-Sep-14 No.: RG178171

Fiery Patch Addendum

This patch will make the Fiery compatible with Java Runtime Environment (JRE) 1.7u51 and above versions installed in client machine. After applying patch to the Fiery Servers, Fiery Configure application for Fiery Servers can be launched from Microsoft Windows and Apple Inc. Macintosh OSX client machine as well.

Known Limitations:

- After installing/updating the JRE 1.7u51 on Macintosh OSX client machine, sometimes Safari browser does not recognize newly installed Java due to this user may unable to launch Configure application from Safari browser. To resolve this problem, please try the below mentioned options:
 - Reboot the Macintosh OSX client machine manually, after installing/updating the JRE 1.7u51.
 - Enable the Java Web contents from Safari browser Preferences -> Security tab.
 Please see the below Screenshot 1.




(Screenshot - 1)

Enable the Java from System Preferences -> Java Control Panel -> Security tab.
 Please see the below Screenshot - 2.



PAGE: 4/5

Model: **AG-P1/C1** Date: 03-Sep-14 No.: RG178171




(Screenshot - 2)

- If Safari 5.x browser does not recognize Java 7, please update the Safari 5.x to Safari 6.x version. Or use Firefox browser to launch Configure application.
- To avoid security vulnerability, Apple has added restriction on Safari browser for signed Java applet to access local directories. Backup/Restore functionality of Configure requires access to local directory to read/write file. To remove the above restriction please do the following steps:
 - 1. Launch Preferences window from Safari and open the Security tab.
 - 2. Click on "Manage Website Settings..." button.
 - 3. Select "Java" from left hand side applications list.
 - 4. Select "Run in Unsafe Mode" from drop down for a particular Fiery.
 - 5. Click "Trust" button on pop-up window for confirmation.



PAGE: 5/5

Model: **AG-P1/C1** Date: 03-Sep-14 No.: RG178171



(Screenshot - 3)

Technical Bulletin

Model: AG-P1/C1			Dat	Date: 18-Mar-15		No.: RG178172				
Subject: Release note for Aegis-P1/C1 EFI Patch					Prepared by: Seigo Ishibashi					
From: 3rd PP Tech Service Sect., PP Tech Service Dept.										
Classification:	☐ Troubleshooting	☐ Part info	rma	tion	Action	required				
	☐ Mechanical	☐ Electrical		☐ Electrical		☐ Electrica			☐ Service	e manual revision
	☐ Paper path	☐ Transmit/rece		t/receive		fit information				
	☐ Product Safety	Other ()						

PAGE: 1/5

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT100556467.e	- 12-digit patch ID truncated on the server configuration page.
xe	

Before installing FIT100556467.exe:

- 1. Please refer to the patch Addendum for additional information regarding this release.
- 2. Known issues listed below, read before installing FIT100556467.exe patch:
 - None.
- The following prerequisites must be installed in the order specified before the FIT100556467.exe patch is applied:
 - 1-14N2CZ.exe
- 4. Do NOT install any of the following patch(es) after installing the **FIT100556467**.exe patch. If you must install any of the patch(es) below, do so before installing the **FIT100556467**.exe patch:
 - None.
- 5. This patch is not exclusive if installed manually. One server Reboot is sufficient for all patches to take effect on the system. System Updates may require an exclusive install if this patch becomes a prerequisite for a future patch.
- 6. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **FIT100556467**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)



Date: 18-Mar-15

PAGE: 2/5

No.: RG178172

Model: AG-P1/C1 Wait until the Fiery controller reaches Idle and print the Configuration page. 6.

- If the controller does not eventually reach Idle, please manually start the Fiery service. 7.
- Verify that the System Updates Log section contains the patch number FIT100556467.

PAGE: 3/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178172

Fiery Patch Addendum

This patch will make the Fiery compatible with Java Runtime Environment (JRE) 1.7u51 and above versions installed in client machine. After applying patch to the Fiery Servers, Fiery Configure application for Fiery Servers can be launched from Microsoft Windows and Apple Inc. Macintosh OSX client machine as well.

Known Limitations:

- After installing/updating the JRE 1.7u51 on Macintosh OSX client machine, sometimes Safari browser does not recognize newly installed Java due to this user may unable to launch Configure application from Safari browser. To resolve this problem, please try the below mentioned options:
 - Reboot the Macintosh OSX client machine manually, after installing/updating the JRE 1.7u51.
 - Enable the Java Web contents from Safari browser Preferences -> Security tab.
 Please see the below Screenshot 1.




(Screenshot - 1)

 Enable the Java from System Preferences -> Java Control Panel -> Security tab. Please see the below Screenshot - 2.



PAGE: 4/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178172




(Screenshot - 2)

- If Safari 5.x browser does not recognize Java 7, please update the Safari 5.x to Safari 6.x version. Or use Firefox browser to launch Configure application.
- To avoid security vulnerability, Apple has added restriction on Safari browser for signed Java applet to access local directories. Backup/Restore functionality of Configure requires access to local directory to read/write file. To remove the above restriction please do the following steps:
 - 1. Launch Preferences window from Safari and open the Security tab.
 - 2. Click on "Manage Website Settings..." button.
 - 3. Select "Java" from left hand side applications list.
 - 4. Select "Run in Unsafe Mode" from drop down for a particular Fiery.
 - 5. Click "Trust" button on pop-up window for confirmation.



PAGE: 5/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178172



(Screenshot - 3)

Technical Bulletin

PAGE: 1/5

Model: AG-P1/C1			Dat	e: 18-Mar	-15	No.: RG178173
Subject: Release note for Aegis-P1/C1 EFI Patch					d by: Sei	igo Ishibashi
From: 3rd PP Ted	ch Service Sect., PP Tech Serv	vice Dept.				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT100541586.e	- PDF file imported to Command WorkStation might result in
xe	error while RIPping.

Before installing FIT100541586.exe:

- 1. Please refer to the patch Addendum for additional information regarding this release.
- 2. Known issues listed below, read before installing FIT100541586.exe patch:
 - None.
- 3. The following prerequisites must be installed in the order specified before the **FIT100541586**.exe patch is applied:
 - 1-14N2CZ.exe
 - 1-166VI5.exe
 - 1-169LYL.exe
 - 1-152SUR.exe
 - 1-15PZTE.exe
 - 1-153U4F.exe
 - 1-16FG9A.exe
 - 1-16G6PJ.exe
 - 1-16SQ5Y.exe
 - 1-17XIFZ.exe
 - 1-18U1L4.exe
 - FIT100556467.exe
- 4. Do NOT install any of the following patch(es) after installing the **FIT100541586**.exe patch. If you must install any of the patch(es) below, do so before installing the **FIT100541586**.exe patch:
 - 1-1HNSEB.exe
 - 1-19SKBZ.exe
- 5. This patch is not exclusive if installed manually. One server Reboot is sufficient for all patches to take effect on the system. System Updates may require an exclusive install if this patch becomes a prerequisite for a future patch.



PAGE: 2/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178173

6. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **FIT100541586**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. Before rebooting the system, to ensure that the patch file is completely processed, please wait up to 60 seconds until the file is done processing.
- 5. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. (If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)
- 6. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 7. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 8. Verify that the System Updates Log section contains the patch number FIT100541586.

PAGE: 3/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178173

Fiery Patch Addendum

This patch will make the Fiery compatible with Java Runtime Environment (JRE) 1.7u51 and above versions installed in client machine. After applying patch to the Fiery Servers, Fiery Configure application for Fiery Servers can be launched from Microsoft Windows and Apple Inc. Macintosh OSX client machine as well.

Known Limitations:

- After installing/updating the JRE 1.7u51 on Macintosh OSX client machine, sometimes Safari browser does not recognize newly installed Java due to this user may unable to launch Configure application from Safari browser. To resolve this problem, please try the below mentioned options:
 - Reboot the Macintosh OSX client machine manually, after installing/updating the JRE 1.7u51.
 - Enable the Java Web contents from Safari browser Preferences -> Security tab.
 Please see the below Screenshot 1.



(Screenshot - 1)

Enable the Java from System Preferences -> Java Control Panel -> Security tab.
 Please see the below Screenshot - 2.



PAGE: 4/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178173




(Screenshot - 2)

- If Safari 5.x browser does not recognize Java 7, please update the Safari 5.x to Safari 6.x version. Or use Firefox browser to launch Configure application.
- To avoid security vulnerability, Apple has added restriction on Safari browser for signed Java applet to access local directories. Backup/Restore functionality of Configure requires access to local directory to read/write file. To remove the above restriction please do the following steps:
 - 1. Launch Preferences window from Safari and open the Security tab.
 - 2. Click on "Manage Website Settings..." button.
 - 3. Select "Java" from left hand side applications list.
 - 4. Select "Run in Unsafe Mode" from drop down for a particular Fiery.
 - 5. Click "Trust" button on pop-up window for confirmation.



PAGE: 5/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178173



(Screenshot - 3)

Technical Bulletin

PAGE: 1/5

Model: AG-P1/C1		Date: 18-Mar-15		-15	No.: RG178174		
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared by: Seigo Ishibashi			
From: 3rd PP Tech Service Sect., PP Tech Service Dept.							
Classification:	Troubleshooting	☐ Part information		ion			
	☐ Mechanical ☐ Electrical			☐ Service manual revision			
	☐ Paper path	☐ Transmit/receive		eive	☐ Retrofit information		
	☐ Product Safety	\boxtimes Other ()			

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT221379.exe	- OpenSSL security was updated for Windows-based Fiery
	controller.

Before installing FIT221379.exe:

- 1. Please refer to the patch Addendum for additional information regarding this release.
- 2. Known issues listed below, read before installing FIT221379.exe patch:
 - None.
- 3. The following prerequisites must be installed in the order specified before the **FIT221379**.exe patch is applied:
 - 1-14N2CZ.exe
- 4. Do NOT install any of the following patch(es) after installing the **FIT221379**.exe patch. If you must install any of the patch(es) below, do so before installing the **FIT221379**.exe patch:
 - None.
- 5. This patch is not exclusive, it can be installed along with other patches concurrently, and one server Reboot or Restart is sufficient for all patches to take effect on the system.
- 6. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute **FIT221379**.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- 5. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 7. Verify that the System Updates Log section contains the patch number **FIT221379**.



PAGE: 2/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178174

PAGE: 3/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178174

Fiery Patch Addendum

This patch will make the Fiery compatible with Java Runtime Environment (JRE) 1.7u51 and above versions installed in client machine. After applying patch to the Fiery Servers, Fiery Configure application for Fiery Servers can be launched from Microsoft Windows and Apple Inc. Macintosh OSX client machine as well.

Known Limitations:

- After installing/updating the JRE 1.7u51 on Macintosh OSX client machine, sometimes Safari browser does not recognize newly installed Java due to this user may unable to launch Configure application from Safari browser. To resolve this problem, please try the below mentioned options:
 - Reboot the Macintosh OSX client machine manually, after installing/updating the JRE 1.7u51.
 - Enable the Java Web contents from Safari browser Preferences -> Security tab.
 Please see the below Screenshot 1.



(Screenshot - 1)

Enable the Java from System Preferences -> Java Control Panel -> Security tab.
 Please see the below Screenshot - 2.



PAGE: 4/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178174




(Screenshot - 2)

- If Safari 5.x browser does not recognize Java 7, please update the Safari 5.x to Safari 6.x version. Or use Firefox browser to launch Configure application.
- To avoid security vulnerability, Apple has added restriction on Safari browser for signed Java applet to access local directories. Backup/Restore functionality of Configure requires access to local directory to read/write file. To remove the above restriction please do the following steps:
 - 1. Launch Preferences window from Safari and open the Security tab.
 - 2. Click on "Manage Website Settings..." button.
 - 3. Select "Java" from left hand side applications list.
 - 4. Select "Run in Unsafe Mode" from drop down for a particular Fiery.
 - 5. Click "Trust" button on pop-up window for confirmation.



PAGE: 5/5

Model: **AG-P1/C1** Date: 18-Mar-15 No.: RG178174



(Screenshot - 3)

Technical Bulletin

PAGE: 1/19

Model: AG-P1 / C1			Date: 13-Apr-15			No.: RG178175	
Subject: LDU replacement procedure (Aegis)				Prepared by: T.Miyamoto			
From: PPBG Service Planning Dept.							
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	Part info Electrica Transmit	al			required e manual revision it information	

IMPORTANT NOTES REGARDING LASER DIODE UNIT REPLACEMENT


Please check the following notes.	

When installing a new LD unit

NOTE

When replacing with a new laser diode (LD) unit procured as a service part, spacer seals may have to be attached to the LD unit before its replacement, which depends upon the lot number. Make sure to check the lot number of the new LD unit before installation.

- If the lot number is ARS141000253 or greater (for example, ARS141000270), spacer seals are included as accessory parts to the LD unit. See instructions below to install the spacer seals.
- If the lot number is ARS141000252 or smaller (for example, ARS140900005), spacer seals are not included. Disregard the instructions below.



Technical Bulletin


PAGE: 2/19

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

Where to attach and how many to attach

Spacer seals [C] are provided together with an instruction sheet [A]. Numbers 1~4 in table [B] on the instruction sheet correspond to the call-outs in the photo indicating to where the spacer seals need to be attached. Quantities of the spacer seals are handwritten in the table to indicate how many seals need to be attached.

The example below shows that 2 spacer seals need to be attached to location 3.



NOTE: The spacer seals may have 4 different types of thickness, but all spacer seals need to be attached to the same location according to the instruction sheet [A].



Technical Bulletin


Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

PAGE: 3/19

IMPORTANT

You may find spacer(s) attached to the laser unit when removing the original LD unit as shown in the photo below. (Spacer is attached to location $\bigcirc{}$.)

DO NOT remove spacer(s) originally attached. When installing the new LD unit, attach new spacer(s) on top of the original spacer(s).



General

Recovery from LD Errors (SC240, 241, 242, 243) required the entire replacement of the imaging unit and was costly.

To reduce the cost and allow recovery by replacing only the LDU (Laser Diode Unit), the LDU has been registered as a standard service part.

Please refer to the following procedure for LDU replacement.

Part Information

The LDUs have been registered with the following p/n.

Part Number	Description
G1782043	Laser Diode Unit:MK:Ass'y
G1782044	Laser Diode Unit:YC:Ass'y


Model: AG-P1 / C1

Technical Bulletin


Date: 13-Apr-15 No.: RG178175

The LDUs are described as "MK" and "YC", but does NOT mean one "MK" LDU will cover both magenta and black.

LDUs to be installed in the Laser Unit are as shown in the diagram below.



"ST1" and "ST2" indicate the installing position in the Laser Unit.



PAGE: 5/19

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

LDU Replacement Procedure


Notes on the replacement work

 Do NOT touch the PCB with bare hands. Grip the bracket made of die-cast aluminum when holding the LDU.





• Check the LDU serial number indicated under the barcode (see the photo below) and mark the corresponding serial number on the data sheet (see the diagram of the data sheet below) to avoid mixing up the installation position. The serial number is indicated as ST1 or ST2 on the data sheet depending on the position. In addition to this marking, indicate the color. Indication of the color on the data sheet will be very important in the latter procedure when inputting the information on the data sheet into the SP.




The barcode attached to the top-right of the LDU corresponds to the 11 digit LDU serial number indicated on the top-left of the data sheet.

Ex) AGA on the barcode is read as 61.

Barcode: AGA091200001

 \downarrow \uparrow

Data sheet: 61091200001



PAGE: 6/19


Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

Work Flow

NOTE

Approx work time is indicated in the brackets.


"N" indicates the total number of LDUs requiring the replacement.



Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

Step 1 Disconnecting the LCT-MF


- 1-1. Remove the I/F connector cover [A]. (screw x 2) 1-2. Remove the LCT-MF I/F connectors [B] from the mainframe.





PAGE: 7/19

1-3. Open the front cover of the LCT-MF and remove the screw [C].




Model: AG-P1 / C1

Technical Bulletin

Date: 13-Apr-15 No.: RG178175

PAGE: 8/19

- 1-4. Separate the LCT-MF from the mainframe.
- 1-5. Disconnect the ground cable [E] from the mainframe. (M4x8 screw x 1)
- 1-6. If connected, disconnect the LCT-MF heater relay harness [D] from the mainframe.




Technical Bulletin

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

Step 2 Removing the Exterior Parts

2-1 Removing the Front Top Cover



- 2-1-1. Open the right and left front doors.
- 2-1-2. Open the toner hopper door [A]. 2-1-3. Remove the front top cover [B]. (screw x 2)








PAGE: 9/19

2-2 Removing the Rear Top Cover

2-2-1. Remove the rear top cover [A]. (screw x 3)




Technical Bulletin

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175


- 2-3 Removing the Control Panel Arm 2-3-1. Remove the cap [A].
- 2-3-2. Remove the arm top cover [B]. (screw x 2)







PAGE: 10/19


- 2-3-3. Remove the screw [C]. 2-3-4. Remove the arm left cover [D]. (screw x 2)
- 2-3-5. Remove the arm right cover [E]. (screw x 2)





2-3-6. Remove the arm [F]. (screw x 4, connector x 1)






Technical Bulletin

Date: 13-Apr-15 Model: AG-P1 / C1 No.: RG178175


- 2-4 Removing the Toner Hopper Unit
- 2-4-1. Open the toner hopper door.2-4-2. Release the toner lock levers [A].
- 2-4-3. Remove the toner bottles.



2-4-4. Remove the top right cover [A]. (screw x 2)








PAGE: 11/19

- 2-4-6. Disconnect the harness [C].
- 2-4-7. Remove the four screws.
- 2-4-8. Grip the handles [D] and remove the toner hopper unit.




Technical Bulletin

PAGE: 12/19

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

2-5 Removing the Metal Cover of the Laser Unit


2-5-1. Remove the metal cover of the laser unit [A]. (screw x 4)




Step 3 Replacing the LDU

3-1. Remove the laser unit top cover [A]. (screw x 9) Note

- Do NOT touch any optical parts inside the LD unit.
- Be careful not to pinch the chains located on both sides when reattaching the laser unit top cover.
- First, fasten screw "1", and then screw "2". The seven other screws can be fastened in any order.



- 3-2. Remove the LD Unit. (connector x4, roundhead screw x2)
 - * Do NOT remove the spacer(s). Spacers are installed to correct the deviation unique to each unit. Spacers may or may not be applied depending on the unit, and their positions and types are unique to each unit.





Technical Bulletin

Date: 13-Apr-15 No.: RG178175

Model: AG-P1 / C1
*Spacer types







parent



White

Brown Black Transparent White

25μm 50μm 75μm 100μm

PAGE: 13/19

3-3. Install the new LD Unit, and close the top cover. (connector x4, roundhead screw x2)

Step 4 Reattaching the Outer Covers

Reattach the outer covers following the reverse order of removal.

Step 5 Connecting the LCT-MF

Connect the LCT-MF following the reverse order of disconnection.

Step 6 Inputting the SP Data

- 6-1. Disable the automatic MUSIC and Process Control adjustment by changing SP2-193-001 to "0" and SP3-501-001 to "1".
- 6-2. Disable the 2-point detection by changing SP2-186-001 to "0".
- 6-3. Input the LD unit adjustment settings.

Refer to APPENDIX 1-4 to write in the <u>values indicated in PINK</u> (which correspond to the <u>SP values indicated in GREEN</u>) into the table below, and then input those values into the SP.

NOTE

- These values are needed for resetting the Laser Unit related SP values in case the SP values are initialized.
- Please keep the data sheet together with the "SP MODE FACTORY SET" sheet, which should be attached as an accessory to the mainframe, inside the machine.
- If the "SP MODE FACTORY SET" sheet has been lost, print out SP5990-002 and keep it together with the data sheet inside the machine.

^{*} Reconfirm the LD Unit serial number to avoid installation in the wrong slot.

Technical Bulletin

PAGE: 14/19

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

EXAMPLE 1 Yellow LDU <<See APPENDIX 1>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01				

EXAMPLE 2 Cyan LDU <<See APPENDIX 2>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-046	+002	2-105-009	109	2-130-009	654
2-102-040	-008	2-105-010	105	2-130-010	653
2-102-041	-015	2-105-011	109	2-130-011	656
2-102-042	-024	2-105-012	107	2-130-012	660
2-102-043	-005	2-105-013	111	2-130-013	647
2-102-044	-011	2-105-014	105	2-130-014	655
2-102-045	-016	2-105-015	109	2-130-015	664
2-115-005	-04	2-105-016	106	2-130-016	634
2-115-006	-01				

EXAMPLE 3 Black LDU <<See APPENDIX 3>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03				
2-115-002	-00				



Model: AG-P1 / C1

Technical Bulletin

Date: 13-Apr-15 No.: RG178175

PAGE: 15/19

EXAMPLE 4 Magenta LDU <<See APPENDIX 4>>

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-056	+000	2-105-017	108	2-130-017	632
2-102-050	+005	2-105-018	105	2-130-018	670
2-102-051	+010	2-105-019	108	2-130-019	648
2-102-052	+015	2-105-020	106	2-130-020	639
2-102-053	-004	2-105-021	109	2-130-021	634
2-102-054	+010	2-105-022	105	2-130-022	652
2-102-055	+014	2-105-023	106	2-130-023	639
2-115-003	-03	2-105-024	105	2-130-024	666
2-115-004	+00				

- 6-4. Reset the "Main Magnification Table" setting by inputting "1" in SP2-180-007.
- 6-5. Power cycle the machine.
- 6-6. Execute SP2-180-003 to clear the "MUSIC Result" setting.
- 6-7. Execute the 2-point detection for each color in SP2-184-001 (for Black), -002 (for Magenta), -003 (for Cyan) and -004 (for Yellow).
- 6-8. Enable the 2-point detection by changing the SP2-186-001 value to "1" (Auto).
- 6-9. Execute the manual MUSIC adjustment; SP2-153-004 (for rough adjustment) and SP2-153-001 (for fine adjustment).
- 6-10. Enable the automatic MUSIC and Process Control adjustment; set the SP2-193-001 value to "1" (Music ON) and SP3-501-001 value to "0" (Process Control ON).

Step 7 Confirming the Image Quality

Finish the replacement procedure by printing out the PS Test Page and confirming its image quality.




Technical Bulletin

Date: 13-Apr-15 No.: RG178175

Model: AG-P1 / C1

<<APPENDIX 1>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.





EXAMPLE 1 Yellow LDU

SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)
2-102-066	+002	2-105-025	109	2-130-025	654
2-102-060	-008	2-105-026	105	2-130-026	653
2-102-061	-015	2-105-027	109	2-130-027	656
2-102-062	-024	2-105-028	107	2-130-028	660
2-102-063	-005	2-105-029	111	2-130-029	647
2-102-064	-011	2-105-030	105	2-130-030	655
2-102-065	-016	2-105-031	109	2-130-031	664
2-115-007	-04	2-105-032	106	2-130-032	634
2-115-008	-01				



位置が正しいこと 正しい銘板であること



Technical Bulletin


Date: 13-Apr-15 No.: RG178175

PAGE: 17/19

<<APPENDIX 2>>

Model: AG-P1 / C1

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.







EXAMPLE 2 Cyan LDU						
SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	
2-102-046	+002	2-105-009	109	2-130-009	654	
2-102-040	-008	2-105-010	105	2-130-010	653	
2-102-041	-015	2-105-011	109	2-130-011	656	
2-102-042	-024	2-105-012	107	2-130-012	660	
2-102-043	-005	2-105-013	111	2-130-013	647	
2-102-044	-011	2-105-014	105	2-130-014	655	
2-102-045	-016	2-105-015	109	2-130-015	664	
2-115-005	-04	2-105-016	106	2-130-016	634	
2-115-006	-01					

カバー:オプティカルハウジング: 祖立の 組み付け状態に異常なきこと


☆ 銘板の位置および内容確認: 位置が正しいこと 正しい銘板であること

PAGE: 18/19

Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

<<APPENDIX 3>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.





EXAMPLE 3 Black LDU


SP No.	Value	SP No.	Value	SP No.	Value
(GREEN)	(PINK)	(GREEN)	(PINK)	(GREEN)	(PINK)
2-101-001	-62	2-105-001	108	2-130-001	632
2-102-036	+000	2-105-002	105	2-130-002	670
2-102-030	+005	2-105-003	108	2-130-003	648
2-102-031	+010	2-105-004	106	2-130-004	638
2-102-032	+015	2-105-005	109	2-130-005	634
2-102-033	+004	2-105-006	105	2-130-006	652
2-102-034	+010	2-105-007	106	2-130-007	639
2-102-035	+014	2-105-008	105	2-130-008	665
2-115-001	-03				
2-115-002	-00				

PAGE: 19/19


Model: AG-P1 / C1 Date: 13-Apr-15 No.: RG178175

<<APPENDIX 4>>

SP Values are indicated in GREEN, and Values in PINK. These values correspond one-on-one in order, described in the same row.









EXAMPLE 4 Magenta LDU						
SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	SP No. (GREEN)	Value (PINK)	
2-102-056	+000	2-105-017	108	2-130-017	632	
2-102-050	+005	2-105-018	105	2-130-018	670	
2-102-051	+010	2-105-019	108	2-130-019	648	
2-102-052	+015	2-105-020	106	2-130-020	639	
2-102-053	-004	2-105-021	109	2-130-021	634	
2-102-054	+010	2-105-022	105	2-130-022	652	
2-102-055	+014	2-105-023	106	2-130-023	639	
2-115-003	-03	2-105-024	105	2-130-024	666	
2-115-004	+00					

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date	Date: 21-Aug-15		No.: RG178176
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared	d by: M.	Yoshikawa
From: 1st PP Ted	ch Service Sect., PP Tech Serv	ice Dept.				
Classification:	☐ Troubleshooting	☐ Part info	ormat	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Servic	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT101045442.exe	- If Composite overprint is enabled, crop marks are printed in the
	wrong color.

Before installing FIT101045442.exe:

- 1. Known issues listed below, read before installing **FIT101045442.exe** patch:
- 2. The following prerequisite(s) must be installed in the order specified before applying the **FIT101045442.exe** patch:
 - 1-14N2CZ.exe
- 3. Do NOT install any of the following patch(es) after installing the FIT101045442.exe patch. If you must install any of the patch(es) below, do so before installing the FIT101045442.exe patch:
- 4. This patch is not exclusive, it can be installed along with other patches concurrently, and one server Reboot or Restart is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions:

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute FIT101045442.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.

 - b. Password is the Fiery administrator login password.c. Hostname can be the IP address or the Fiery server name.
- 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- 5. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 7. Verify that the System Updates Log section contains the patch number FIT101045442.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C	:1		Dat	e: 14-Sep	-15	No.: RG178177
Subject: Release note for Aegis-P1/C1 EFI Patch				Prepared	d by: M.	Yoshikawa
From: 1st PP Ted	ch Service Sect., PP Tech Serv	vice Dept.				
Classification:	☐ Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	it information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT101056050.exe	- Patch to upgrade PHP, Apache and OpenSSL v5.4.41, v2.2.29 and
	v0.98zf respectively.
	- PHP: 5.3.29 -> 5.4.41
	- Apache: 2.2.29 -> 2.2.29
	- OpenSSL: 0.9.8zb -> 0.9.8zf

Before installing FIT101056050.exe

- 1. Known issues listed below, read before installing **FIT101056050.exe** patch:
 - None.
- The following prerequisite(s) must be installed in the order specified before applying the FIT101056050.exe patch:
 - 1-14N2CZ.exe
 - 1-1KPSM2.exe
 - FIT204758.exe
 - FIT100556467.exe
 - FIT221379.exe
- 3. Do <u>NOT</u> install any of the following patch(es) <u>after</u> installing the **FIT101056050.exe** patch. If you must install any of the patch(es) below, do so <u>before</u> installing the **FIT101056050.exe** patch:
 - None.
- 4. This patch is not exclusive, it can be installed along with other patches concurrently, and one server Reboot or Restart is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute FIT101056050.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- 5. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 7. Verify that the System Updates Log section contains the patch number FIT101056050.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date: 17-Sep-15		-15	No.: RG178178
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared by: M. Yoshikawa			
From: 1st PP Ted	ch Service Sect., PP Tech Service	vice Dept.				
Classification:	Troubleshooting	☐ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for ProC900(P1)/ProC900s(C1).

Patch File	Issue(s)		
FIT101063085.exe	Certificate Update for XPe. This is required for system updates to download new updates.		

Before installing FIT101063085.exe

- 1. Known issues listed below, read before installing **FIT101063085**.exe patch:
 - When this patch is not applied, after September 20th, 2015, the Fiery controller is no longer able to receive automatic system updates from EFI.
 - For the above reason, if the system software has been re-installed, make sure to apply this patch manually BEFORE running the automatic system updates.
- 2. The following prerequisites must be installed in the order specified before the **FIT101063085**.exe patch is installed:
 - None.
- 3. Do NOT install the following patch after installing the **FIT101063085**.exe patch.
 - 1-1CO771.exe Note: The 1-1CO771.exe is no longer distributed.

Patch installation on FACI system instructions

- 1. Execute **FIT101063085**.exe and follow the instructions.
- Fiery must be rebooted in order for changes to take effect.

Patch installation on non-FACI system instructions

- 1. Enable remote desktop on the server.
- 2. With a Windows XP client, using remote desktop to the Fiery controller.
- 3. Execute FIT101063085.exe and follow the instructions.
- 4. Fiery must be rebooted in order for changes to take effect.
- 5. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 7. Verify that the System Updates Log section contains the patch number **FIT101063085**.

Technical Bulletin

PAGE: 1/1

Model: AG-P1/C1			Date: 29-Jun-16		16	No.: RG178179
Subject: Release note for Aegis-P1/C1 EFI Patch			Prepared by: M. Yoshikawa			
From: 1st PP Ted	h Service Sect., PP Tech Serv	rice Dept.				
Classification:	Troubleshooting	☐ Part information		on Action required		
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	it information
	☐ Product Safety	\boxtimes Other ()		

This RTB is the release note for System Software Version 4.0 for Pro C900(P1)/ProC900s(C1).

Patch File	Issue(s)
FIT101145633.exe - Files so	anned using the Scan to SMB feature on a Windows XP
Server b	ased Fiery controller cannot be saved in Mac OSX 10.10

Before installing FIT101145633.exe

- 1. Known issues listed below, read before installing FIT101145633.exe patch:
 - None.
- 2. The following prerequisite(s) must be installed in the order specified before applying the **FIT101145633.exe** patch:
 - 1-14N2CZ.exe
 - FIT100556467.exe
- 3. Do <u>NOT</u> install any of the following patch(es) <u>after</u> installing the **FIT101145633.exe** patch. If you must install any of the patch(es) below, do so <u>before</u> installing the **FIT101145633.exe** patch:
 - None
- 4. This patch is not exclusive, it can be installed along with other patches concurrently, and one server Reboot or Restart is sufficient for all patches to take effect on the system.
- 5. In the case where the customer needs to install a patch which was previously skipped in the patch order, it is necessary to reinstall the system.

Patch installation instructions

- 1. Make sure that the Fiery printer controller reaches Idle.
- 2. Execute FIT101145633.exe and follow the instructions in the Fiery Patch Downloader.
- 3. Notes about the Fiery Patch Downloader
 - a. Logon must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be the IP address or the Fiery server name.
- 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- 5. Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6. If the controller does not eventually reach Idle, please manually start the Fiery service.
- 7. Verify that the System Updates Log section contains the patch number FIT101145633