

**Technical Bulletin**  
**No. AF-001**Issued on  
January 16th, 1992**Subject:**  
**Pulse width setting****Model(s):** AF0/AF2FAX T.S. Section T.S. Department  
Assistant General Manager  
H. Motojima**Classification**

Control No. for Each Area

R.C.	01	Asia	01
SAVIN	01	LAM	01
Europe	01	AT&T	--
HCS	01		

This is additional information for the service manual.

The above models have two kinds of thermal heads, and the pulse width is fixed for each head as follows.

Kyocera head (for AF0) - 0.68 ms	P/N - H0845210
Toshiba head (for AF2) - 0.72 ms	P/N - H0845211

When replacing the head or the MBU in the field, check that the correct value is stored in the machine.



# Technical Bulletin No.AFO-002

Issued on  
February 15, 1992

**Subject:** AFO Software Problem

**Model(s):** AFO/AF2/CSO

FAX T.S. Section T.S. Department  
Assistant General Manager  
H. Motojima

## Classification

Control No. for Each Area

R.C.	002	Asia	--
SAVIN	--	LAM	--
Europe	--	AT&T	--
HCS	--		

## [Problem]

The first printing page for a reception, a substitute file output, a report or a pattern output may be blank.

## [Cause]

By a software fault, the command for 24V power supplying to the thermal head may be turned off instantly.

However, the printing sequence continues to result in a blank page outputted.

This is caused by the faulty priority assignment of the signals of 24V power on, of status check and of RXSTART trigger.

It may occur at random as  $36 \mu\text{s}/160 \text{ ms} \cong 1/4400$ .

## [Countermeasure]

The program is corrected.

So, exchange the ROM or the MBU to the new one.

## Part numbers

	Version by volt.	old	new
AFO	115V (Asia)	H0847130C	H0847130D
AF2	115V (USA, Asia))	H0867130C	H0867130D

## [Affected machines]

The machines produced in Nov and Dec '91 and in Jan '92.

**Note:** Some of the above machines have been modified in Japan before shipment.

Subject:

**NCU parameter setting for Holland****Model(s): AFO/AF2**  
**CSO**FAX T.S. Section T.S. Department  
Assistant General Manager  
H. Motojima**Classification**

Control No. for Each Area

R.C.	--	Asia	--
SAVIN	--	LAM	--
Europe	003	AT&T	--
HCS	003		

When installing the above models in Holland/Italy/Belgium, change the NCU parameter to meet the PTT requirement as follows.

1. Change the country codes for NCU parameter and bitswitch.
2. Change the following parameters and RAM addresses as follows.

**[Holland]**

NCU Parameter 002=020  
NCU Parameter 003=080  
NCU Parameter 004=020  
NCU Parameter 005=080  
NCU Parameter 006=002  
NCU Parameter 010=058  
NCU Parameter 011=058  
NCU Parameter 012=042  
NCU Parameter 013=042  
Address 4144=5EH  
Address 4152=5EH  
Address 416A=5EH  
Address 417F=02H

**[Italy]**

Address 4157=06H  
Address 4158=00H  
Address 4159=01H  
Address 415A=00H  
Address 4158=15H  
Address 415C=15H  
Address 4164=40H

**[Belgium]**

Address 413F=05H  
Address 4140=20H  
Address 4141=03H  
Address 4142=00H  
Address 414D=05H  
Address 414E=20H  
Address 414F=03H  
Address 4150=00H  
Address 4151=1EH  
Address 4152=13H  
Address 4153=1EH  
Address 4154=04H

The above correction will be applied into the software from the 1st productions of March '92.



# Technical Bulletin No. AF-003

Issued on  
March 10, 1992

**Subject:** Remote Control Features

**Model(s):** AF2

FAX T.S. Section, T.S. Department  
Assistant General Manager  
H. Motojima

## Classification

Control No. for Each Area

R.C.	03	Europe	02
SAVIN	--	HCS	02
NRG-USA	--	NRG	02
		Asia/LAM	02

The explanation concerning Remote Control features in the operator's manual contains a mistake.

The service codes which are related with polling files mentioned in the Remote Control Service Code Table are not correct.

If you are receiving some calls from customers about this, please give them the correct information.

These features are available in the AF2 models only.

Dial your machine. → Press **#** when you hear a high-pitched tone.

→ Press **a b c d** (Remote ID), then press **#**. After that, do the following.

### - Current -

Remote Transfer of a Polling File	<b>2 0 # i j k l #</b> Fax Number <b>#</b>
Remote Printing of a polling File	<b>2 1 # i j k l #</b> <b>Start</b>

### - Correct-

Remote Transfer of a Free Polling File	<b>2 0 #</b> Fax Number <b>#</b>
Remote Printing of a Free Polling File	<b>2 1 #</b> <b>Start</b>
Remote Transfer of a Secured Polling File	<b>2 2 # i j k l #</b> Fax Number <b>#</b>
Remote Printing of a Secured Polling File	<b>2 3 # i j k l #</b> <b>Start</b>

To disconnect the line, press **#** twice.

**i j k i** : ID Code (Polling)

We will try to revise the manuals from the next printing run.



# Technical Bulletin No. CSO-008

Issued on  
March 18th, 1992

Subject:

## Dedicated Tx parameter programming problem

Model(s): AFO/AF2/CSO

FAX T.S. Section, T.S. Department  
Assistant General Manager  
H. Motojima

### Classification

Control No. for Each Area

R.C.	004	Europe	007
SAVIN	004	HCS	007
NRG- USA	001	NRG	001
		Asia/LAM	005

### -Problem-

If the T1 timer is set with a value of over 100 for a speed dial code by dedicated Tx parameter programming, the other parameter for the speed dial codes will not be programmed.

### -Cause-

Software bug.

### -Countermeasure-


Temporary- Set the T1 timer with a value less than 100 for speed dial codes.

Permanent - We will correct the software from the May mass production.

Reissued

**RICOH****Technical Bulletin**

No. CSO - 009

Issued on  
March 19th, 1992**Subject: NCU parameter setting for Sweden****Model(s):** AFO/AF2  
CS0FAX T.S. Section T.S. Department  
Assistant General Manager ,,  
H. Motojima **Classification**

- ☐ Action Required  
☐ Troubleshooting  
☐ Retrofit Information  
☒ Revision of Service Manual  
☐ Information Only  
☐ Others

Control No. for Each Area

R.C.	--	Europe	008
SAVIN	--	HCS	008
NRG-USA	--	NRG	002
		Asia/LAM	--

When installing the above models in Sweden, change the NCU parameter in accordance with the PTT/sales requirements as follows.

1. Change the country codes for NCU parameter and bitswitches.
2. Change the and RAM addresses and bit switch as follows.

**(PTT requirement)**

Address 4172 = 60H  
 Address 4173 = 20H  
 Address 4174 = 60H  
 Address 4175 = 03H  
 Address 4176 = 19H

**(Sales requirement)**

Address 406C bit 5 = 0, bit 6 = 1  
 Address 4063 bit 7 = 0  
 Bit sw SW06 = F0H

The above correction will be applied into the software from the 1st productions of May '92.

Also, we have changed the following Addresses, in accordance with additional request from PTT, from the 1st productions of July '92.

**4143=28H****4145=28H****4151=28H****4153=28H****4172=28H****4174=28H****418E=12H**

**Technical Bulletin**  
**No.AFO-004**Issued on  
April 23rd, 1992**Subject:**  
**Modification of cutter unit****Model(s):** AFO/AF2FAX T.S. Section, T.S. Department  
Assistant General Manager**Classification**H. Motojima

From the July, 1991 production, to prevent from paper jam at the cutter exit, a mylar has been attached to the cutter blade (Diagram A).

The affected models and cutters are shown below.

No.	Cutter Unit	Part No.
1	Cutter - A4 for model C (Hitachi)	H0532161H
2	Cutter - A4 for model C (Ooyane)	H0532150G
3	Cutter - B4 for FAX 82	H0542156C
4	Cutter - A4 for AFO	H0845028C

With this modification, the guide plate of the cutter exit was discontinued after the old cutter assembly was out of stock (Diagram B).

This discontinuance has been applied from the February, 1992 production.

However, we found in the production line that few machines experienced paper jam due to the discontinuance of the guide plate.

**[Cause]**

The cause of this paper jam is as follows.

In some machines there might be a clearance between the guide plate for paper feed-out and the mylar (Diagram C).

Therefore, the printed page gets into the clearance and then a paper jam occurs.

The number of cases of paper jam in the production line were 5/2035(0.2%).

**[Countermeasure]**

We have applied the following countermeasures in order to ensure the paper feeds correctly.



# Technical Bulletin No.AFO-004

Issued on  
April 23rd, 1992

**Subject: Modification of cutter unit**

## -Temporary-

Two (four) spacers were attached between the feed-out roller holder and the feed-out guide plate, to get rid of the clearance (Diagram D).

This was done in the March production.

## -Permanent-

The guide plate of the cutter exit has been reattached.

This was done all the way from the April production.

No.	Old P/# of cutter	Temporary Action	Permanent Action	New P/# of cutter
1	H0532161H	To be attached 0.9mm spacer (P/# H0542153)	To be attached the guide plate of the cutter exit (no part number)	H0532161J
2	H0532150G	To be attached 0.9mm spacer (P/# H0542153)	To be attached the guide plate of the cutter exit (no part number)	H0532150H
3	H0542156C	Not countermeasure	To be attached the guide plate of the cutter exit (no part number)	H0542156D
4	H0845028C	To be attached 0.9 +0.5mm spacer (P/#: •0.9mm spacer ... H0542153 •0.5mm spacer ... 07080030B)	To be attached the guide plate of the cutter exit and 0.9mm spacer (P/#: •Guide plate ... no part number •0.9mm spacer ... H0542153)	H0845028D

If you need the above parts for countermeasure, please deal with the following way.

0.9mm and 0.5mm spacer ... Please order from SPC

Guide plate of the cutter exit ... Please contact our section attention to Mr. H.Motojima.

## [Affected models in the field]

The machines which have not had any countermeasures applied before being shipped out are as follows.

- From Tokyo
  - To Asia ... Less than 1230 units
  - To USA ... Less than 805 units
- From RIF (France)
  - To Europe ... A few units



**Technical Bulletin**  
**No.AFO-004**Issued on  
April 23rd, 1992**Subject:           Modification of cutter unit****[Solution]**

The design section tested the machine under abnormal conditions (They tested 4 units of AFO after adjusting the clearance to the widest.)

The result of testing is shown below.


No.	Clearance (mm)	Occurrence Rate
1	-2.0	0/3685
2	-1.75	0/3786
3	-1.8	0/3759
4	-1.65	0/3685

We guess that paper jams caused by this tolerance problem would occur rarely, according to the test result.


Also, the frequency should almost be within the specification (less than 1/1000).

However, if paper jam occurs in the field, and if the guide plate of the cutter exit is not used in the cutter, you should attach the guide plate to the cutter or attach the spacers between the feed-out roller holder and the feed-out guide plate.

Subject: **Modification of cutter unit**




[Diagram A]



[Diagram B]

[Diagram C]



[Diagram D]

**Subject:****NCU Modification for Switzerland****Model(s): AFO AF2/CSO**  
**(Europe only)**FAX T.S. Section, T.S. Department  
Assistant General Manager**Classification**

- ☒ Action Required  
☐ Troubleshooting  
☐ Retrofit Information  
☐ Revision of Service Manual  
☐ Information Only  
☐ Others

H. Motojima

When installing the above models in Switzerland, you have to apply the modification as the following steps.

1. Prepare the following parts at your side.

- (1) Resister -  $10\Omega$ : 1/10W
- (2) Capacitor -  $0.047\mu\text{F}$  /250V
- (3) Coil - TDK ELF 1010 SKI-332k (3.3mH)

2. Remove the NCU from the machine, then apply the modification.

- (1) Replace the R17 with the above resister ( $10\Omega$ )
- (2) Add the capacitor and coil, and cut the pattern as shown on the next page.

3. Put the NCU back, and reassemble the machine.

4. Check the machine for the following items.

- Dialling (PD/DTMF)
- Transmission
- Reception

---

**Subject:**                    **Communication Problem**

---

**Model(s):** AFO / AF2 / CSOFAX T.S. Section, T.S. Department  
Assistant General Manager**Classification**H. Motojima

---

---

**[Problem]**

The above models may not transmit to the following models.

(Error code 0 - 21 / 0 - 23)

The document may stop during scanning, then the machine will reset after 1 ~ 2 min, and the power failure report will be printed.

During transmission, the stop key does not function.

Condition : I / O rate 40ms (standard), 20ms (Detail)

Models : UF32H • UF23 (Matsushita)

**[Cause]**

A software error

On the Tx side, the fill bit will be added if the 1 line data is less than the min Tx time for 1 line, however on the above AFO / AF2 / CSO, the counting may be incorrect.

**[Countermeasure]**

Temporary : Using the dedicated Tx parameter, select 4800bps of the initial modem rate.

Permanent : The 1st production of March '92 will contain the correct software.

---

**Subject:**                    **Communication Problem**

---

**Model(s):** AFO / AF2 / CSOFAX T.S. Section, T.S. Department  
Assistant General Manager**Classification**H. Motojima

---

---

**[Problem]**

The above models can not receive using ECM from the machines which use 64 frames, such as Canofax 470.

**[Cause]**

A software error

The frame size (256 / 64 frame) can not be changed in the software.

**[Countermeasure]**

Temporary

If you face this problem, switch off the ECM function.

(Bit sw 07, bit 5    0 → 1)

In the field, most of facsimile machines use 256 frame, so, this problem may occur rarely.

Permanent

The 1st production of May '92 will contain the correct software.

**Subject:****NCU parameter setting for Denmark, Switzerland and Austria****Model(s): AFO / AF2 / CSO (Europe)**FAX T.S. Section, T.S. Department  
Assistant General Manager**Classification**H. Motojima

---

**[Problem]**

When installing the above models in Denmark, Switzerland and Austria, change the following addresses in accordance with the PTT requirements if the machine Serial Number is prior to the following execution date.

1. Change the country codes for NCU parameter and bit switch.
2. Change the RAM addresses as follows.

**[Denmark]**

4149 =04H, 414A =60H, 414B =03H, 414C =90H, 415B =0CH, 415C =0CH,  
415D =08H, 415E =17H, 414D =05H, 414E =12H, 414F =03H, 4150 =40H,  
4151 = 41H, 4152 = 3FH, 4153 = 41H, 4154 = 04H, 4155 = 19H, 4157 = 04H,  
4158 =60H, 4159 =03H, 415A =90H, 4164 =42H

These corrections have been applied from the 1st production of March '92.

**[Switzerland]**

4181 =05H, 4143 =28H, 4145 =28H, 4164 =51H, 415B =18, 415C =1EH,  
415D =0FH, 415E =16H, 415F =0BH, 4160 =0BH, 4161 =08H, 4162 =1EH,  
4064(bit 5) =1

These corrections have been applied from the 1st production of May '92.

**Subject:****NCU parameter setting for Denmark, Switzerland and Austria****[Austria]****AFO/AF2/CSO****Addr.**

4058:	→	0AH
4059:	→	01H
4143:	→	28H
4178:	→	64H
417D:	→	0EH
417E:	→	0AH
417F:	→	01H
4182:	→	14H
4183:	→	50H
4187:	→	09H
4190:	→	50H
4191:	→	50H
4192:	→	07H

**CSO****Bit SW**

Bit SW 01:	→	03H
Bit SW 02:	→	40H
Bit SW 03:	→	4AH
Bit SW 05:	→	27H
Bit SW 07:	→	46H
Bit SW 0B:	→	06H

Depending on the sales requirement, change the followings.

**User SW**

User Bit SW 01:	→	41H
User Bit SW 02:	→	0BH
User Bit SW 03:	→	F5H
User Bit SW 06:	→	0BH

**AFO/AF2****Bit SW**

Bit SW 01:	→	07H
Bit SW 02:	→	58H
Bit SW 03:	→	4AH
Bit SW 05:	→	27H
Bit SW 07:	→	06H
Bit SW 0B:	→	06H

Depending on the sales requirement, change the followings.

**User SW**

User SW 03:	→	F5H
-------------	---	-----

After correcting the software, we will apply to the machine(except user SW).

<b>RICOH</b>		<b>Technical Bulletin</b>	<b>No. CSO-022</b>
<b>SUBJECT:</b> Modem Capture Range Problem			<b>DATE:</b> August 21st, 1992 Reissued: Sept 29, 1992
PREPARED BY: N.Mihara CHECKED BY:		FROM: FAX T.S. Section	
<b>CLASSIFICATION:</b> <input type="checkbox"/> Action Required <input checked="" type="checkbox"/> Troubleshooting <input type="checkbox"/> Retrofit Information		MODEL: CSO, AFO, AF2 <input type="checkbox"/> Revision of service manual <input type="checkbox"/> Information only <input type="checkbox"/> Other	

**[Problem]**

The CSO/AFO/AF2 may not receive at 9600bps/7200bps from the certain machines, with the following phenomenon.

- Error code: 0-21, 23
- Only the 1st few inches (cm) of the image data would be received and then the line would be disconnected, or the error would occur as the usual Line fail.

**[Cause]**

On the CCITT recommendation, the signalling rate of the TX terminal is defined to be 9600bps  $\pm$  0.01% (100ppm), and all makers design the facsimile models in accordance with the CCITT recommendation. However, on the some of the models (Tx side), the signalling rate may be out of CCITT recommendation, due to the possible production variation of modem, or other factors.

The capture range (Rx capability) of the CSO/AFO/AF2 is designed as 9600bps  $\pm$  100ppm (there is no margin). Therefore, if the signalling rate of Tx terminal is out of CCITT recommendation, the CSO/AFO/AF2 can not receive the V29 signal correctly. It means that, if a modem is produced precisely, there will not be the problem.

Tx side: Signalling rate of CCITT recommendation - 9600bps  $\pm$  100ppm  
 Rx side: Capture range of CCITT recommendation - none

**[Countermeasure]**

Permanent: We have re-designed the modem, to have certain margin for reception and the new modem will be applied from Oct. productions of '92 except the following.

CSO (Productions at RIF factory) → From November, 1992

AFO/AF2 (Productions at RIF factory) → From December, 1992.

The P/Ns of the FCUs will be changed as follows.

Old		New	
H08160xx	→	H08161xx	(The last two digits will not be changed)
H08460xx	→	H084603x	
H08660xx	→	H086603x	(The last digit will not be changed)





## Technical Bulletin

## No. CSO-022

**SUBJECT:** Modem Capture Range Problem

**DATE:** August 21st, 1992

Reissued: Sept 29, 1992

### [Action in the field]

- (1) **Make sure the exact causes** of the communication problem. By referring to the attached troubleshooting flow, because there are other communication problems which are caused by other reasons. If the problem is caused by this modem capture range problem, go to the next steps.
- (2) Drop the starting modem rate of the terminal for Rx or Tx.
- (3) Ask the Tx terminal to replace the modem.
- (4) If (3) is not possible, replace the FCU with the new FCU which contains the new modem.

### [Sample]


Until now, we have been reported on this problem with the following models at few rate, and as the result of our investigation, the signalling rates of the machines are as follows.

Models	Signalling rate
SANFAX 2100	Unknown (The modem has been replaced on the tx side)
SANFAX 1	-163ppm
SANFAX 515	Unknown
Panafax UF1000	-120ppm
PC98 FAX (Star FAX)	+ 120ppm
PC FAX Mac	-180ppm
IBM PC FAX	Unknown

Please note that the above table is just the samples of the problem, and the problem should not always occur with the above models in your field.

The estimated occurrence rate is as low as 0.05%/mo.  
 However, we like to keep watching the field performance.  
 We like you to log this case monthly.

**DATE: August 21st, 1992**  
Reissued: Sept 29, 1992



**SUBJECT: Addition of Mitsubishi Thermal Head****DATE:**  
Sep, 28th, 1992PREPARED BY: Ishiyama  
CHECKED BY:

FROM: FAX T.S. Section

The thermal head will be changed from a Kyocera head (AFO)/Toshiba head (AF2) to a Mitsubishi head from the October production only in RIF (our factory in France).

We, in fact, will not register the Mitsubishi head as a service part, because the head is manufactured in France, and it is difficult for our SPC to supply it.

Refer to the following table for details.

	Kyocera Head	Toshiba Head	Mitsubishi Head
Pulse Width	0.68 msec	0.75 msec	0.62 msec
Part Number	H084 5210	H084 5211	H084 5212
Applied Model	AFO	AF2	AFO/AF2
Factory	Tokyo	Tokyo	France
Service Part	Yes	Yes	No

Consequently, you should order either the Kyocera or Toshiba head for replacement in the field, and check that the appropriate pulse width setting is stored in the machine when replacing the head or the MBU.

To distinguish the manufacturer of the head, see the part number attached to the head.



# Technical Bulletin No. AFO-006

**SUBJECT:** Software Problem

**DATE:**  
December, 3rd, 1992

 PREPARED BY: A. Ishiyama  
CHECKED BY:

FROM: FAX T.S. Section

**CLASSIFICATION:**
☐ Action Required

☐ Troubleshooting

☒ Retrofit Information

☐ Revision of service manual

☐ Information only

☐ Other

**MODEL:**

AFO/AF2 for Ricoh and NRG

## [ Problem]

When receiving, the machine always sends out a CFR (Confirmation to Receive) as a response to modem training.

As a result, communication fails (reception error) if the telephone line is poor, because the transmission modem rate never falls back.

(This will not happen with ECM communication)

## [Cause]

When some of the software modifications were executed, a bug was introduced.

## [Countermeasure]

The program has been corrected.

So, change the ROM or the MBU.

## ROM Part Numbers

	Version	Old P/No.	New P/No.
<b>AFO</b>	USA(115V)	H084 7130H	H084 7130J
	Europe	H084 7140H	H084 7140J
	Asia	H084 7141H	H084 7141J
<b>AF2</b>	USA(115V)	H086 7130H	H086 7130J
	Europe	H086 7140H	H086 7140J
	Asia	H086 7141H	H086 7141J

## [Affected Machines]

The machines produced in November 1992.

**Note:** Most of the above machines have been modified in Japan before shipment.

Model: General		Date: 31-Oct-97	No: 011
Subject: Year 2000 Problem		Prepared by: Y.Okunishi	
From: QAC 2nd Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Other (      )		

### Check Items

The following functions for which the clock timer is used were checked to see whether or not they will function correctly at 0:00 on Jan. 1, 2000.

- 1) Display and print of the date and time  
The year must be changed to 2000 or 00 from 1999 or 99 and the date must be kept correctly after the start of the year 2000.
- 2) Clock adjustment  
The date and time can be adjusted after the start of the year 2000.
- 3) Send later mode with memory and without memory  
The dialling time must be at the set time after the start of the year 2000.
- 4) Automatic re-transmission.  
When a communication error happens, the machine dials the same destination again automatically at an interval. This must function correctly after the start of the year 2000.
- 5) Weekly timer and night timer  
The energy saver mode (fusing unit) control must work correctly.
- 6) Displayed date after a power failure  
The correct date must be kept by the battery back-up feature.

### Models Checked

- 1) K50 series (FAX10, 20, 60, etc.)
- 2) K70 series (FAX90, 95, 105, etc.)
- 3) K90 series (FAX80, 85, 75, 86, etc.)
- 4) LE series (FAX08, 09, Phone fax for ATT, etc.)
- 5) B series (B1, RF810, FAX12, FAX300, etc.)
- 6) ZB series (FAX220, FAX240, Innfax, etc.)
- 7) BARBARA series (RF01, 02, 03, 05, 06, etc.)
- 8) OX series (FAX21, 22)
- 9) PF series (PF-1, PF-2)
- 10) A series (FAX500, 550, etc.)

Model: General

Date: 31-Oct-97

No: 011

- 11) B60 series (FAX170, 180, etc.)
- 12) K100 series (FAX1000L, 1010L, etc.)
- 13) K105 series (FAX4000L, etc.)
- 14) K200 series (FAX7000L, etc.)
- 15) KV series (FAX2800L, 1200L, etc.)
- 16) C series (FAX3000L, 4500L, 5600L, etc.)
- 17) L80 (MV715)
- 18) I series (FAX800, 880, 680, etc.)
- 19) FL series (FAX2700L, 4700L, MV310, etc.)
- 20) FX7, LX7 (FAX1700L, MV106, FAX1750MP, etc.)
- 21) L20 series (Aficio FX10)

#### Problems found

- 1) AF0 (FAX500, 550, etc.), CS0 (FAX3000L, 3100L, 3200L, etc.)
  - a) The day of week that appears on the display only in the clock adjustment mode goes back to SUNDAY every time the clock is adjusted after the start of the year 2000.  
  
So, the programmed weekly timer does not work correctly.  
  
If the clock is not adjusted after the start of the year 2000, the date and the day of the week are kept correctly.
  - b) Clock adjustment is available only for years 91 through 99. The other years cannot be set. (Month, day, and time can be adjusted.)
- 2) K200 (FAX7000L)
  - a) Clock adjustment is available only for years 88 through 99. The other years cannot be set. (Month, day, and time can be adjusted.)
  - b) The send later mode does not function (no dialling occurs) if it passes the time into the year 2000.  
No report is printed and the remaining message in the memory is not cleared automatically but it can be cleared by user operation.
  - c) Automatic re-transmission is not done if the year 2000 starts after the transmission failure.  
The remaining message in the memory is not cleared automatically but it can be cleared by user operation.
  - d) The display year is returned back to 88 after a power failure after the start of the year 2000.

Model: General

Date: 31-Oct-97

No: 011

The other functions in these models work correctly.

Schedule for the countermeasure ROMs

- 1) AF0 (FAX500, 550, etc.), CS0 (FAX3000L, 3100L, 3200L, etc.)  
In January 1998.
- 2) K200 (FAX7000L)  
In April 1998.

RC	RE	ASIA	

**MB Correction**

Reissue date: 15-Nov-97

The items in bold italic have been corrected or added.

Model: General		Date: 31-Oct-97	No: 011A
Subject: Year 2000 Problem		Prepared by: Y.Okunishi	
From: QAC 2nd Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other ( <b><i>Info only</i></b> )		

Check Items

The following functions for which the clock timer is used were checked to see whether or not they will function correctly at 0:00 on Jan. 1, 2000.

- 1) Display and print of the date and time  
The year must be changed to 2000 or 00 from 1999 or 99 and the date must be kept correctly after the year 2000.
- 2) Clock adjustment  
The date and time can be adjusted after the time becomes the year 2000.
- 3) Send later mode with memory and without memory  
The calling time must be the set time after the time becomes the year 2000.
- 4) Automatic re-transmission.  
When the communication error happens, the machine calls to the same destination again automatically with an interval. This must function correctly after the time becomes the year 2000.
- 5) Weekly timer and night timer  
The energy saver mode (heater) control must work correctly.
- 6) Displayed date after a power failure  
The correct date must be kept by the battery.

Models Checked

- 1) K50 series (FAX10, 20, 60, etc.)
- 2) K70 series (FAX90, 95, 105, etc.)
- 3) K90 series (FAX80, 85, 75, 86, etc.)
- 4) LE series (FAX08, 09, Phone fax for ATT, etc.)
- 5) B series (B1, RF810, FAX12, FAX300, etc.)
- 6) ZB series (FAX220, FAX240, Innfax, etc.)
- 7) BARBARA series (RF01, 02, 03, 05, 06, etc.)



Model: General	Date: 31-Oct-97	No: 011A
----------------	-----------------	----------

- 8) OX series (FAX21, 22)
- 9) PF series (PF-1, PF-2)
- 10) A series (FAX500, 550, etc.)
- 11) B60 series (FAX170, 180, etc.)
- 12) K100 series (FAX1000L, 1010L, etc.)
- 13) K105 series (FAX4000L, etc.)
- 14) K200 series (FAX7000L, etc.)
- 15) KV series (FAX2800L, 1200L, etc.)
- 16) C series (FAX3000L, 4500L, 5600L, etc.)
- 17) L80 (MV715)
- 18) I series (FAX800, 880, 680, etc.)
- 19) FL series (FAX2700L, 4700L, MV310, etc.)
- 20) FX7, LX7 (FAX1700L, MV106, FAX1750MP, etc.)
- 21) L20 series (Aficio FX10)

## Problem found

Most of the models except the following models, will not experience any problems.

- 1) AFO (FAX 500/550/580, NGR 9620, Infotec 3301/3305, Nashua F492)  
CSO (FAX 3000/3100/3200, NGR 9660/9661/9662, Omnifax L40/41,  
Savin FAX 3660/3620, Infotec 3660)  
CS1 (FAX 3500L, NRG 9665, Omnifax L46, Savin FAX 3670)  
CRO (FAX 2500L/2600L, NRG 9650, Omnifax L42, Savin FAX 3630, Infotec 3661)
  - a) The day of week, that appears on the display only in the clock adjustment mode, is returned back to SUNDAY every time when the clock adjustment is done after the time becomes the year 2000.  
  
So, the programmed weekly timer does not work correctly. **(AFO' s do not have the weekly timer.)**  
  
If the clock adjustment is not done after the time becomes the year 2000, the date and the day of week is kept correctly.
  - b) Clock adjustment is available only for the year 91 through 99. The other years cannot be set. (Month, day and time can be adjusted.)

Model: General

Date: 31-Oct-97

No: 011A

- 2) K200 (FAX7000L)
- a) Clock adjustment is available only for the years 88 through 99. The other years cannot be set. (Month, day and time can be adjusted.)
  - b) The send later mode does not function (no calling happens) if it passes the time into the year 2000.  
No report is printed and the rest message in the memory is not cleared automatically but it is cleared by the user operation.
  - c) Automatic re-transmission is not done if the time becomes the year 2000 in the interval after the transmission failure.  
The rest message in the memory is not cleared automatically but it is cleared by the user operation.
  - d) The display year is returned back to 88 after the power failure after the time becomes the year 2000.

The other functions in these models work correctly.

Schedule of the countermeasure ROMs

- 1) AFO, CSO, CS1, CRO:  
In January 1998.
- 2) K200(FAX7000L):  
In April 1998.

RC	RE	ASIA	
*	*	*	

**MB Correction**

Reissue date: 15-Jan-98

The items in bold italic have been corrected or added.

Model: General		Date: 15-Jan-98	No: 011 <i><b>B</b></i>
Subject: Year 2000 Problem		Prepared by: Y.Okunishi	
From: QAC 2nd Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other (Info only)		

Check Items

The following functions for which the clock timer is used were checked to see whether or not they will function correctly at 0:00 on Jan. 1, 2000.

- 1) Display and print of the date and time  
The year must be changed to 2000 or 00 from 1999 or 99 and the date must be kept correctly after the year 2000.
- 2) Clock adjustment  
The date and time can be adjusted after the time becomes the year 2000.
- 3) Send later mode with memory and without memory  
The calling time must be the set time after the time becomes the year 2000.
- 4) Automatic re-transmission.  
When the communication error happens, the machine calls to the same destination again automatically with an interval. This must function correctly after the time becomes the year 2000.
- 5) Weekly timer and night timer  
The energy saver mode (heater) control must work correctly.
- 6) Displayed date after a power failure  
The correct date must be kept by the battery.

Models Checked

- 1) K50 series (FAX10, 20, 60, etc.)
- 2) K70 series (FAX90, 95, 105, etc.)
- 3) K90 series (FAX80, 85, 75, 86, etc.)
- 4) LE series (FAX08, 09, Phone fax for ATT, etc.)
- 5) B series (B1, RF810, FAX12, FAX300, etc.)
- 6) ZB series (FAX220, FAX240, Innfax, etc.)
- 7) BARBARA series (RF01, 02, 03, 05, 06, etc.)

Model: General

Date: 15-Jan-98

No: 011 **B**

- 8) OX series (FAX21, 22)
- 9) PF series (PF-1, PF-2)
- 10) A series (FAX500, 550, etc.)
- 11) B60 series (FAX170, 180, etc.)
- 12) K100 series (FAX1000L, 1010L, etc.)
- 13) K105 series (FAX4000L, etc.)
- 14) K200 series (FAX7000L, etc.)
- 15) KV series (FAX2800L, 1200L, etc.)
- 16) C series (FAX**2500L**, 3000L, **3500L**, 4500L, 5600L, etc.)
- 17) L80 (MV715)
- 18) I series (FAX800, 880, 680, **MV74**, etc.)
- 19) FL series (FAX2700L, **3700L**, 4700L, MV310, etc.)
- 20) FX7, LX7 (FAX1700L, MV106, FAX1750MP, etc.)
- 21) L20 series (Aficio FX10)

#### Problem found

Most of the models except the following models, will not experience any problems.

- 1) AFO (FAX 500/550/580, **NRG** 9620, Infotec 3301/3305, Nashua F492)  
CSO (FAX 3000/3100/3200, **NRG** 9660/9661/9662, Omnifax L40/41,  
Savin FAX 3660/3620, Infotec 3660)  
CS1 (FAX 3500L, NRG 9665, Omnifax L46, Savin FAX 3670)  
CRO (FAX 2500L/2600L, NRG 9650, Omnifax L42, Savin FAX 3630, Infotec 3661)
  - a) The day of week, that appears on the display only in the clock adjustment mode, is returned back to SUNDAY every time when the clock adjustment is done after the time becomes the year 2000.  
  
So, the programmed weekly timer does not work correctly. (AFO's do not have the weekly timer.)  
  
If the clock adjustment is not done after the time becomes the year 2000, the date and the day of week is kept correctly.
  - b) Clock adjustment is available only for the year 91 through 99. The other years cannot be set. (Month, day and time can be adjusted.)

Model: General	Date: 15-Jan-98	No: 011 <b>B</b>
----------------	-----------------	------------------

- 2) K200 (FAX7000L)
  - a) Clock adjustment is available only for the years 88 through 99. The other years cannot be set. (Month, day and time can be adjusted.)
  - b) The send later mode does not function (no calling happens) if it passes the time into the year 2000.  
No report is printed and the rest message in the memory is not cleared automatically but it is cleared by the user operation.
  - c) Automatic re-transmission is not done if the time becomes the year 2000 in the interval after the transmission failure.  
The rest message in the memory is not cleared automatically but it is cleared by the user operation.
  - d) The display year is returned back to 88 after the power failure after the time becomes the year 2000.

The other functions in these models work correctly.

## Schedule of the countermeasure ROMs

- 1) AFO, CSO, CS1, CRO:  
In January 1998.
- 2) K200(FAX7000L):  
In April 1998.

RC	RE	ASIA	
*	*	*	

Model: General		Date: 15-Apr-98	No: 014
Subject: Action Plan for the Year 2000 Issues		Prepared by: Y.Okunishi	
From: QAC Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other (Info only)		

The year 2000 issue was explained in RTB No. General-011B.

That RTB explains only the technical matters of what will happen after the year 2000 in some models, and the countermeasures.

At this time, we would explain how to talk with customers about the year 2000 issues related to fax machines.

Basically, we can say to the customers that there is no major issue related to basic operation after the year 2000, and they don't need to take any preventative action before the year 2000.

The only thing that the customers need to know is that the following operations will be changed after the year 2000.

1. AF0 (FAX 500/550/580, NRG 9620, Infotec 3301/3305, Nashua F492)  
CS0 (FAX 3000/3100/3200, NRG 9660/9661/9662, Omnifax L40/41,  
Savin FAX 3660/3620, Infotec 3660)  
CS1 (FAX 3500L, NRG 9665, Omnifax L46, Savin FAX 3670)  
CR0 (FAX 2500L/2600L, NRG 9650, Omnifax L42, Savin FAX 3630, Infotec 3661)

First, please do not forget to inform the customers that they don't need to do anything if they do not go into the clock adjustment mode.

#### A) Adjustment of the year

##### A-1) For the year 2000

- ① Set the clock to 11:59 PM (or 23:59) on December 31 1999, and wait for one minute.
- ② The year changes to 2000 automatically, then set the current time.  
(Do not change the year.)

##### A-2) For the year 2001

- ③ After the above step ①, set the clock to 11:59 PM (or 23:59) on December 31 2000, and wait for one minute.
- ④ The year changes to 2001 automatically, then set the current time.  
(Do not change the year.)

##### A-3) For years 2002 and later, repeat the same procedure as above.

Model: General

Date: 15-Apr-98

No: 014

**B) Adjustment of the weekly timer (Heater timer) ....Except AF0**

This is only for customers who use the weekly timer. (We do not think that many customers are using this function.)

Please recommend adjusting the timer on Sunday if the customer can do it.

If they cannot do it on Sunday, the ROM should be changed to the new one.

The new ROM includes the countermeasure for the above A) also.

**2. K200 (FAX7000L)****A) Adjustment of the year**

First, please do not forget to inform the customers that they don't need to do anything if they do not go into the clock adjustment mode.

**A-1) For the year 2000**

①Set the clock to 11:59 PM (or 23:59) on December 31 1999, and wait for one minute.

②The year changes to 2000 automatically, then set the current time.

(Do not change the year.)

**A-2) For the year 2001**

③After the above step ①, set the clock to 11:59 PM (or 23:59) on December 31 2000, and wait for one minute.

④The year changes to 2001 automatically, then set the current time.

(Do not change the year.)

**A-3) For years 2002 and later**

Repeat the same procedure as above.

If the customer switches off the machine after the year 2000, the year displayed returns to 1988. In this case, follow the above procedure to adjust the clock.

**B) Send later mode**

Please notify the customer that they should not use send later mode on December 31st 1999, if the transmission will be done on the next day.

If the customer cannot guarantee that they will follow this advice, the ROM should be changed.

Model: General	Date: 15-Apr-98	No: 014
----------------	-----------------	---------

Schedule of the countermeasure ROMs

- 1) AFO, CSO, CS1, CRO:  
In May 1998.
- 2) K200 (FAX7000L):  
In May 1998.

\*Both are delayed.

RC	RE	ASIA	
*	*	*	



Model: LSO, CRO, CS1, AFO, AF2, K200		Date: 31-May-98	No: Multi - 008
Subject: ROMs for the year 2000 problem		Prepared by: Y.Okunishi	
From: QAC Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input checked="" type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Other (      )		

Attached please find the list of the ROMs for the year 2000 problem and the procedure for making R200 ROMs from the ROM files.

Note:

- Please refer to RTB nos. General 11 and 14 for details.
- 8 ROMs for the K200 are combined in one file.

RC	RE	ASIA	
*	*	*	

Model: LSO, CRO, CS1, AFO, AF2, K200	Date: 31-May-98	No: Multi - 008
--------------------------------------	-----------------	-----------------

ROMs for the year 2000

May 29, 1998  
Y.Okunishi

Product Code	New ROM No.	Test	File name	Check sum	ROM Code	Model code	Model	Brand	Area	Sold from	Sold by	No. of sold units	Note
CSO	H0817138	yes	CSO7138	8552	c30usa	H081-20	3000L	RICOH	US	91/12	93/4	16,747	2M ROM (1ROM/unit)
						23	3200L			91/12	95/11	18,242	
						24	3100L			93/2	95/2	21,863	
						21	9660	NRG		92/3	92/7	71	
						22	9661			92/3	94/2	1,651	
						26	3660	SAVIN		92/2	93/4	1,372	
						27	3620			92/1	93/4	1,917	
						TOTAL							
	H0817136A	yes	CSO7136S	77A7	c30usa•	25	2600L	RICOH	US	94/9	95/3	8,000	
	H0817139E	yes	CSO7139E	3C77	c30tel	28	L40 L41	Omnifax	US	92/1	93/5	5,181	
						29	L41			92/1	93/5	8,008	
						TOTAL							
	H0817124A	yes	CSO7124A	0772	c30eur	40	3000L 3000L	RICOH	Europe	92/3	95/11	37,716	
						46	3000L	RICOH	Switzerland	92/10	95/6	4,179	
						60	9660	NRG	Europe	93/3	95/8	15,659	
						TOTAL							
	H0817123A	no	CSO7123A	0078	c30fra	70	3000LF	RICOH	France	93/4	95/9	393	
						80				92/4	95/9	6,206	
						90	9660F	NRG		92/4	95/9	2,164	
						TOTAL							
	H0817121A	yes	CSO7121A	FA57	c30hcs	30	3660	Infotec	Europe	92/10	94/8	15,528	
	H0817122A	yes	CSO7122A	D225	c30asi	51	3000L	RICOH	Asia	92/3	96/10	18,523	
						59	9660	NRG		94/3	96/4	2,837	
						55	-	Ricoh	Korea			?	
						TOTAL							
	H0817140M	yes	CSO7140M	859C	c30tai	23	3000L	RICOH	Taiwan	92/3	95/11	1,251	
	H0817128B	no	CSO7128B	E8C5	c30chi	54	3000L	RICOH	China	93/7	95/11	981	
	H0817159N	yes	CSO7159N	C3CE	c30opt	H151-65•SW:HCS•,H151-73(•:RE),H151-83(•:GES)		Option	Europe			?	
CS1	H5117150B	yes	CS17150B	6A91	c31usa	H511-20	3500L	RICOH	US	93/6	96/3	31,766	
						21	9669	NRG		93/6	95/9	700	
						22	L46	Omnifax		93/6	95/12	11,472	
						27	3670	SAVIN		93/7	95/9	3,106	
						TOTAL							
CR0	H5107121B	yes	CRO7121B	23AB	c60usa	H510-20	2500L	RICOH	US	3/8 93/5	95/4	26,535	
						21	9650	NRG		93/7	95/7	832	

						22	L42	Omnifax		93/9	95/3	6,848	
						27	3630	SAVIN		93/7	95/3	2,136	
						TOTAL						36,351	
	H5107120B	yes	CRO7120B	F5BF	c60eur	30	3661	Infotec	Europe	93/9	94/9	5,564	
						40	2500L	RICOH		93/9	95/7	11,418	
						60	9650	NRG		93/9	95/8	5,632	
						TOTAL						22,614	
	H5107123B	yes	CRO7123B	0E88	c60fra	33	3661F	Infotec	France	94/4	95/9	242	
						43	2500LF	RICOH		93/10	95/9	2,012	
						63	9650F	NRG		93/10	95/9	931	
						TOTAL						3,185	
	H5107132G	yes	CRO7132G	37F5	c60asi	51	2500L	RICOH	Asia	93/12	96/1	5,955	
						59	9650	NRG		94/1	95/9	1,107	
						TOTAL						7,062	
	H5107131B	yes	CRO7131B	23A3	c60tai	53	2500L	RICOH	Taiwan	94/10	97/6	777	
AFO	H0847130K	yes	AFO7130K	D8D3	a20usa	H084-20	500	RICOH	Taiwan	92/4	93/4	365	
	H0847140L	yes	AFO7140L	6B6A	a20eur	44	500	RICOH	Europe	91/8	94/10	6,817	
	H0847142H	no	AFO7142H	94D0	a20fra	83	500	RICOH	France	92/4	94/3	1,231	
	H0847143L	yes	AFO7143L	350F	a20hcs	34	3301	Infotec	Europe	91/8	95/4	2,892	
	H0847141L	yes	AFO7141L	3F13	a20asi	51	500	RICOH	Asia	91/10	96/11	13,696	
						56	500	RICOH	Vietnam	92/11	94/5	1,650	KD
						TOTAL						15,346	
	H0847150K	yes	AFO7150K	2A40	a20opt	H15146(•:RICOH),H151-54(SW:HCS)	-	Option	Europe			?	Language Kit
AF1	H0857135B	yes	AF17135B	FCDF	a21chi	H085-54	580	RICOH	China	93/8	96/5	5,040	
AF2	H0867130K	yes	AF27130K	9BDF	a22usa	20	550	RICOH	US	92/1	96/2	14,934	
	H0867140L	yes	AF27140L	3C35	a22eur	44	550	RICOH	Europe	91/8	95/3	10,824	
						90	9620	NRG		92/4	93/9	1,446	
						TOTAL						12,270	
	H0867142H	checki ng	AF27142H	583D	a22fra	73	3305	Infotec	France	-	-	0	RIF is checking the ROM.
						83	550	RICOH		95/4	95/9	100	
						93	9620	NRG		92/4	94/9	170	
						TOTAL						270	
	H0867143L	yes	AF27143L	0CE0	a22hcs	34	3305	Infotec	Europe	91/8	95/9	6,583	
	H0867141L	yes		DAD8	a22asi	51	550	RICOH	Asia	92/2	96/2	12,181	
						59		Nashua	Asia	92/2	96/1	1,662	
						TOTAL						13,843	
	H0867131A	yes	AF27131A	9BC3	a22tai	53	550	RICOH	Taiwan	94/8	96/2	109	
	H0867150L	yes	AF27150L	E725	a22opt	H15147(•:RICOH),H151-55(SW:HCS),H151-93(•:NASHUA)	-	Option	Europe			?	Language Kit

K200	H0087260J H0087261J H0087262J H0087263J H0087264J H0087265J H0087266J H0087267J	yes	H0087260	FC1E EBE0 B88F 08B2 7AA0 C2F0 28D7 CE5E	USA	20	7000L	RICOH	US	89/9	95/6	790	1M ROM (8 ROMs/unit)
	H0087270F H0087271F H0087272F H0087273F H0087274F H0087275F H0087276F H0087277F	yes	H0087270	451C 78BA 3FA2 C44F 7B14 4DA3 7C16 380B	GMN	30	7000L	RICOH	Germany	89/10	93/7	119	
	H0087320F H0087321F H0087322F H0087323F H0087324F H0087325F H0087326F H0087327F	yes	H0087320	4527 7967 3FA2 C44F 7B14 4DA3 7C16 380B	GMN	40	6765	Infotec	Germany	89/9	90/8	180	
	H0087280H H0087281H H0087282H H0087283H H0087284H H0087285H H0087286H H0087287H	yes	H0087280	1956 CB16 4E46 C3F4 799D 33A8 3EE5 6478	ENG	41	7000L	RICOH	UK	89/10	94/8	85	
	H0087330H H0087331H H0087332H H0087333H H0087334H H0087335H H0087336H H0087337H	yes	H0087330	1D20 64B7 4FAF D4A1 7830 1EBB C591 854A	ENG	31	6765	Infotec	UK	89/10	92/12	125	
	H0087290C H0087291C H0087292C H0087293C H0087294C H0087295C H0087296C H0087297C	yes	H0087290	4A5D 5B24 416A C54D 8882 683D D331 E525	ITY	42	7000L	RICOH	Italy	89/10	91/10	29	

H0087340C H0087341C H0087342C H0087343C H0087344C H0087345C H0087346C H0087347C	yes	H0087340	4A68 5BD1 416A C54D 8882 683D D331 E525	ITY	32	6765	Infotec	Italy	89/10	92/9	41
H0087300E H0087301E H0087302E H0087303E H0087304E H0087305E H0087306E H0087307E	yes	H0087300	4A2A 3680 403B 9F7C 8900 DB80 6C4A 1B91	FRN	43	7000L	RICOH	France	89/10	92/3	137
H0087350E H0087351E H0087352E H0087353E H0087354E H0087355E H0087356E H0087357E	yes	H0087350	4A35 372D 403B 9F7C 8900 DB80 6C4A 1B91	FRN	33	6765	Infotec	France	90/7	91/3	156
H0087310H H0087311H H0087312H H0087313H H0087314H H0087315H H0087316H H0087317H	yes	H0087310	196E CB4C 4E46 C3F4 799A 3385 3EE5 6478	UNV	44	7000L	RICOH	Europe/Asia	89/9	94/1	387
H0087360H H0087361H H0087362H H0087363H H0087364H H0087365H H0087366H H0087367H	yes	H0087360	1D38 64ED 4FAF D4A1 782D 1E98 C591 854A	UNV	34	6765	Infotec	Europe	90/1	92/11	38

END

## ROM writing procedure for K200 ROMs

### 1. ROM Writing

This will vary depending on the ROM writer buffer capacity.

This is an example with a buffer RAM capacity of 512KB.

During the first load, 512KB is sent.

During the first load, 0H~7FFFFH can be loaded.

During the second, 800000H~FFFFFH can be loaded.

Since the K200 is 1MB, the sending is completed after 512KB worth has been sent twice.

#### First Time

##### 1-1) Transfer to the ROM writer.

Motorola-S Format

Receiving location address 00000000

Send/Receive buffer RAM start 00000000

Sending buffer RAM end Device capacity

##### 1-2) Program on the ROM

Set program 16-bit series

Device Count 4

Device Start 00000000

Buffer RAM Start 00000000

Data Type BIGENDIAN

#### Second Time

##### 2-1) Transfer to the ROM writer.

Motorola-S Format

Receiving location address 00080000

Send/Receive buffer RAM start 00000000

Sending buffer RAM end Device capacity

##### 2-2) Program on the ROM

Set program 16-bit series

Device Count 4

Device Start 00000000

Buffer RAM Start 00000000

Data Type BIGENDIAN

When the buffer RAM capacity is 1MB, the RAM writing is as follows.

1MB can be sent during the first load.

0H~FFFFFH can be loaded.

Since the K200 is 1MB, it can be transferred all at once.

## First Time

### 1-1) Transfer to the ROM writer.

Motorola-S Format

Receiving location address	00000000
Send/Receive buffer RAM start	00000000
Sending buffer RAM end	Device capacity

### 1-2) Program on the ROM

Set program	16-bit series
Device Count	4
Device Start	00000000
Buffer RAM Start	00000000
Data Type	BIGENDIAN

## Second Time

### 2-1) Transfer to the ROM writer.

Since 1MB can be sent the first time, this is not necessary.

### 2-2) Program on the ROM

Set program	16-bit series
Device Count	4
Device Start	00000000
Buffer RAM Start	00080000
Data Type	BiGENDIAN

## ROM locations (Top view of MBU)

3-8 (3')	3-0 (4')
2-8 (1')	2-0 (2')
1-8 (3)	1-0 (4)
0-8 (1)	0-0 (2)

() The number in the parentheses is the ROM writer socket number.

['] The second time is indicated.

The ROM part numbers start from 0-8.

(Ex: For the FAX7000L(US), 0-8:H00872**60**, 3-0:H00872**67**)

## Check Sum Chart

ROM location Model	0-8	0-0	1-8	1-0	2-8	2-0	3-8	3-0
K200USA	FC1E	EBE0	B88F	08B2	7AA0	C2F0	28D7	EC5E
K200GMN-R	451C	78BA	3FA2	C44F	7B14	4DA3	7C16	380B
K200G<M-K	4527	7967	3FA2	C44F	7B14	4DA3	7C16	380B
K200ENG-R	1956	CB16	4E46	C3F4	799D	33A8	3EE5	6478
K200ENG-K	1D20	64B7	4FAF	D4A1	7830	1EBB	C591	854A
K200ITY-R	4A5D	5B24	416A	C54D	8882	683D	D331	E525
K200ITY-K	4A68	5BD1	416A	C54D	8882	683D	D331	E525
K200FRN-R	4A2A	3680	403B	9F7C	8900	DB80	6C4A	1B91
K200FRN-K	4A35	372D	403B	9F7C	8900	DB80	6C4A	1B91
K200UNV-R	196E	CB4C	4E46	C3F4	799A	3385	3EE5	6478
K200UNV-K	1D38	64ED	4FAF	D4A1	782D	1E98	C591	854A

R: Ricoh, K : Kalle (Infotec)



**RTB Correction**

Reissue date: 30-Jun-98

The items in bold italic have been corrected or added.

Model: General		Date: 15-Jan-98	No: 011C
Subject: Year 2000 Problem		Prepared by: Y.Okunishi	
From: QAC 2nd Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other (Info only)		

Check Items

The following functions for which the clock timer is used were checked to see whether or not they will function correctly at 0:00 on Jan. 1, 2000.

- 1) Display and print of the date and time  
The year must be changed to 2000 or 00 from 1999 or 99 and the date must be kept correctly after the year 2000.
- 2) Clock adjustment  
The date and time can be adjusted after the start of the year 2000.
- 3) Send later mode with memory and without memory  
The calling time must be the set time after the start of the year 2000.
- 4) Automatic re-transmission.  
When a communication error occurs, the machine calls the same destination again automatically after an interval. This must function correctly after the start of the year 2000.
- 5) Weekly timer and night timer  
The energy saver mode (heater) control must work correctly.
- 6) Displayed date after a power failure  
The correct date must be kept by the battery.

Models Checked

- 1) K50 series (FAX10, 20, 60, etc.)
- 2) K70 series (FAX90, 95, 105, etc.)
- 3) K90 series (FAX80, 85, 75, 86, etc.)
- 4) LE series (FAX08, 09, Phone fax for ATT, etc.)
- 5) B series (B1, RF810, FAX12, FAX300, etc.)
- 6) ZB series (FAX220, FAX240, Innfax, etc.)
- 7) BARBARA series (RF01, 02, 03, 05, 06, etc.)

Model: General	Date: 15-Jan-98	No: 011C
----------------	-----------------	----------

- 8) OX series (FAX21, 22)
- 9) PF series (PF-1, PF-2)
- 10) A series (FAX500, 550, etc.)
- 11) B60 series (FAX170, 180, etc.)
- 12) K100 series (FAX1000L, 1010L, etc.)
- 13) K105 series (FAX4000L, etc.)
- 14) K200 series (FAX7000L, etc.)
- 15) KV series (FAX2800L, 1200L, etc.)
- 16) C series (FAX2500L, 3000L, 3500L, 4500L, 5600L, etc.)
- 17) L80 (MV715)
- 18) I series (FAX800, 880, 680, MV74, etc.)
- 19) FL series (FAX2700L, 3700L, 4700L, MV310, etc.)
- 20) FX7, LX7 (FAX1700L, MV106, FAX1750MP, etc.)
- 21) L20 series (Aficio FX10)
- 22) K10 series (FX120, Rapicom120, FX210/230, Rapicom210/230, etc.)**
- 23) K20 series (FX5000, Rapicom5000, etc.)**
- 24) K60 series (FAX610, Rapicom610, etc.)**
- 25) K83 series (FAX830, Rapicom830, etc.)**
- 26) FR4, FR6 (FAX4800L, FAX3800L, etc.)**

## Problem found

Most models, except the following models, will not experience any problems.

- 1) AFO (FAX 500/550/580, NRG 9620, Infotec 3301/3305, Nashua F492)  
CSO (FAX 3000/3100/3200, NRG 9660/9661/9662, Omnifax L40/41,  
Savin FAX 3660/3620, Infotec 3660)  
CS1 (FAX 3500L, NRG 9665, Omnifax L46, Savin FAX 3670)  
CRO (FAX 2500L/2600L, NRG 9650, Omnifax L42, Savin FAX 3630, Infotec 3661)
  - a) The day of week, that appears on the display only in the clock adjustment mode, is returned back to SUNDAY whenever the clock adjustment is done after the start of the year 2000.  
  
So, the programmed weekly timer does not work correctly. (AFO's do not have the weekly timer.)  
  
If the clock adjustment is not done after the start of the year 2000, the date and the day of week is kept correctly.
  - b) Clock adjustment is available only for the year 91 through 99. The other years cannot be set. (Month, day and time can be adjusted.)

Model: General

Date: 15-Jan-98

No: 011C

- 2) K200 (FAX7000L)
- a) Clock adjustment is available only for the years 88 through 99. The other years cannot be set. (Month, day, and time can be adjusted.)
  - b) The send later mode does not function (no calling happens) if it passes the time into the year 2000.  
No report is printed. The message in the memory is not cleared automatically but must be cleared by user operation.
  - c) Automatic re-transmission is not done if the year 2000 starts in the interval after the transmission failure.  
The message in the memory is not cleared automatically but must be cleared by user operation.
  - d) The display year is returned back to 88 after a power failure after the start of the year 2000.
- 3) **K60 series (FAX610, Rapicom610, Infotec6550)**  
**K83 series (FAX830, Rapicom830, Infotec6750)**
- a) ***The day of week is not displayed correctly after the start of the year 2000.***
  - b) ***The send later mode does not function (calling at 0:00AM January 1st 2000).***
  - c) ***The display year is returned back to 85 when the power fails after the start of the year 2000.***

The other functions in these models work correctly.

Schedule for the countermeasure ROMs

- 1) AFO, CSO, CS1, CRO:  
In **April** 1998.
- 2) K200 (FAX7000L):  
In May 1998 (***The corrected version will be in July 1998.***)
- 3) **K60, K83: A ROM will not be available.**

RC	RE	ASIA	
*	*	*	

## RTB Correction

Reissue date: 30-Jun-98

The items in bold italic have been correction or added.

Model: CSO, CRO, CS1, AFO, AF2, K200		Date: 31-May-98	No: Multi-008A
Subject: ROMs for the year 2000 problem		Prepared by: Y. Okunishi	
From: QAC Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

Attached please find the list of ROMs for the year 2000. ***(The list was updated.)***

***The ROM files have been saved in the Ricoh QAC server except for the K200 ROMs.  
(EP ROMs for the K200 will be prepared by the beginning of June.)***

Note:

- Please refer to RTB nos. General 11 and 14 for details.

RC	RE	ASIA	
*	*	*	

Model: CSO, CRO, CS1, AFO, AF2, K200	Date: 31-May-98	No: Multi-008
--------------------------------------	-----------------	---------------

## ROMs for the year 2000

25-Jun-98

Product Code	New ROM No.	Check sum	Model code	Model	Brand	Area	Note
CSO	H0817138	8552	H081-20	3000L	RICOH	US	2M ROM (1ROM/unit)
			23	3200L			
			24	3100L			
			21	9660			
			22	9661	SAVIN		
			26	3660			
			27	3620			
	H0817136A	77A7	25	2600L	RICOH	US	
	H0817139E	3C77	28	L40	Omnifax	US	
			29	L41			
	H0817124A	0772	40	3000L	RICOH	Europe	
			46	3000L	RICOH	Switzland	
			60	9660	NRG	Europe	
	H0817123A	0078	70	3000LF	RICOH	France	
			80				
			90	9660F	NRG		
	H0817121A	FA57	30	3660	Infotec	Europe	
	H0817122A	D225	51	3000L	RICOH	Asia	
			59	9660	NRG		
			55	-	Ricoh	Korea	
	H0817140M	859C	23	3000L	RICOH	Taiwan	
	H0817128B	E8C5	54	3000L	RICOH	China	
	H0817159N	C3CE	H151-65•SW:HCS• H151-73(FRN:Ricoh) H151-83(FRN:GES)			Option	
CS1	H5117150B	6A91	H511-20	3500L	RICOH	US	
			21	9669	NRG		
			22	L46	Omnifax		
			27	3670	SAVIN		
CR0	H5107121B	23AB	H510-20	2500L	RICOH	US	
			21	9650	NRG		
			22	L42	Omnifax		
			27	3630	SAVIN		
	H5107120B	F5BF	30	3661	Infotec	Europe	
			40	2500L	RICOH		
			60	9650	NRG		
	H5107123B	0E88	33	3661F	Infotec	France	
			43	2500LF	RICOH		
			63	9650F	NRG		
	H5107132G	37F5	51	2500L	RICOH	Asia	
			59	9650	NRG		
H5107131B	23A3	53	2500L	RICOH	Taiwan		

Model: CSO, CRO, CS1, AFO, AF2, K200	Date: 31-May-98	No: Multi-008
--------------------------------------	-----------------	---------------

AFO	H0847130K	D8D3	H084-20	500	RICOH	Taiwan	KD Language Kit
	H0847140L	6B6A	44	500	RICOH	Europe	
	H0847142H	94D0	83	500	RICOH	France	
	H0847143L	350F	34	3301	Infotec	Europe	
	H0847141L	3F13	51	500	RICOH	Asia	
			56	500	RICOH	Vietnam	
	H0847150K	2A40	H151-46(FRN:RICOH) H151-54(SW:HCS)		Option	Europe	KD Language Kit
AF1	H0857135B	FCDF	H085-54	580	RICOH	China	
AF2	H0867130K	9BDF	20	550	RICOH	US	
	H0867140L	3C35	44	550	RICOH	Europe	
			90	9620	NRG		
	H0867142H	583D	73	3305	Infotec	France	
			83	550	RICOH		
			93	9620	NRG		
	H0867143L	0CE0	34	3305	Infotec	Europe	
	H0867141L	DAD8	51	550	RICOH	Asia	
			59	9620	NRG	Asia	
	H0867131A	9BC3	53	550	RICOH	Taiwan	
	H0867150L	E725	H151-47(FRN:RICOH) H151-55(SW:HCS) H151-93(FRN:NASHUA)		Option	Europe	

K200	H0087260J	FC1E	H008-20	7000L	RICOH	US	1M ROM (8 ROMs/unit)
	H0087261J	EBE0					
	H0087262J	B88F					
	H0087263J	08B2					
	H0087264J	7AA0					
	H0087265J	C2F0					
	H0087266J	28D7					
	H0087267J	CE5E					
	H0087270F	451C	30	7000L	RICOH	Germany	
	H0087271F	78BA					
	H0087272F	3FA2					
	H0087273F	C44F					
	H0087274F	7B14					
	H0087275F	4DA3					
	H0087276F	7C16					
	H0087277F	380B					
	H0087320F	4527	40	6765	Infotec	Germany	
	H0087321F	7967					
	H0087322F	3FA2					
	H0087323F	C44F					
	H0087324F	7B14					
	H0087325F	4DA3					
	H0087326F	7C16					
	H0087327F	380B					

Model: CSO, CRO, CS1, AFO, AF2, K200

Date: 31-May-98

No: Multi-008

H0087280H H0087281H H0087282H H0087283H H0087284H H0087285H H0087286H H0087287H	1956 CB16 4E46 C3F4 799D 33A8 3EE5 6478	41	7000L	RICOH	UK
H0087330H H0087331H H0087332H H0087333H H0087334H H0087335H H0087336H H0087337H	1D20 64B7 4FAF D4A1 7830 1EBB C591 854A	31	6765	Infotec	UK
H0087290C H0087291C H0087292C H0087293C H0087294C H0087295C H0087296C H0087297C	4A5D 5B24 416A C54D 8882 683D D331 E525	42	7000L	RICOH	Italy
H0087340C H0087341C H0087342C H0087343C H0087344C H0087345C H0087346C H0087347C	4A68 5BD1 416A C54D 8882 683D D331 E525	32	6765	Infotec	Italy
H0087300E H0087301E H0087302E H0087303E H0087304E H0087305E H0087306E H0087307E	4A2A 3680 403B 9F7C 8900 DB80 6C4A 1B91	43	7000L	RICOH	France
H0087350E H0087351E H0087352E H0087353E H0087354E H0087355E H0087356E H0087357E	4A35 372D 403B 9F7C 8900 DB80 6C4A 1B91	33	6765	Infotec	France
H0087310H H0087311H H0087312H H0087313H H0087314H H0087315H H0087316H H0087317H	196E CB4C 4E46 C3F4 799A 3385 3EE5 6478	44	7000L	RICOH	Europe/Asia

	H0087360H	1D38	34	6765	Infotec	Europe	
	H0087361H	64ED					
	H0087362H	4FAF					
	H0087363H	D4A1					
	H0087364H	782D					
	H0087365H	1E98					
	H0087366H	C591					
	H0087367H	854A					

END



## RTB Correction

Reissue date: 31-Jul-98

The items in bold italic have been correction or added.

Model: CSO, CRO, CS1, AFO, AF2, K200		Date: 31-May-98	No: Multi-008 <b><i>B</i></b>
Subject: ROM's for the year 2000		Prepared by: Y.Okunishi	
From: QAC Field Information Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

***(B) : The attached ROM List has been corrected.***

Attached please find the list of the ROM's for the year 2000 problem. (The list was updated.)

The ROM files have been saved in the Ricoh QAC server, except for the K200 ROMs. (EPROMs for the K200 will be prepared by the beginning of June.)

Note:

- Please refer to RTBs General 11 and 14 for details.

RC	RE	ASIA	
*	*	*	

Model: CSO, CRO, CS1, AFO, AF2, K200

Date: 31-May-98

No: Multi-008B

## ROMs for the year 2000

25-Jun-98

Product Code	New ROM No.	Check sum	Model cord	Model	Brand	Area	Note
CSO	H0817138	8552	H081-20	3000L	RICOH	US	2M ROM (1ROM/unit)
			23	3200L			
			24	3100L			
			21	9660	NRG		
			22	9661			
			26	3660	SAVIN		
			27	3620			
	H0817136A	77A7	25	2600L	RICOH	US	
	H0817139E	3C77	28	L40 L41	Omnifax	US	
			29	L41			
	H0817124A	0772	40	3000L 3000L	RICOH	Europe	
			46	3000L	RICOH	Switzerland	
			60	9660	NRG	Europe	
	H0817123A	0078	70	3000LF	RICOH	France	
			80				
			90	9660F	NRG		
	H0817121A	FA57	30	3660	Infotec	Europe	
	H0817122A	D225	51	3000L	RICOH	Asia	
			59	9660	NRG		
			55	-	Ricoh	Korea	
H0817140M	859C	23	3000L	RICOH	Taiwan		
H0817128B	E8C5	54	3000L	RICOH	China		
H0817159N	C3CE	H151-65 (SW:HCS) , H151-73(FRN:Ricoh) H151-83(FRN:GES)			Option	Europe	Language Kit
CS1	H5117150B	6A91	H511-20	3500L	RICOH	US	
			21	9669	NRG		
			22	L46	Omnifax		
			27	3670	SAVIN		
CRO	H5107121B	23AB	H510-20	2500L	RICOH	US	
			21	9650	NRG		
			22	L42	Omnifax		
			27	3630	SAVIN		
	H5107120B	F5BF	30	3661	Infotec	Europe	
			40	2500L	RICOH		
			60	9650	NRG		
	H5107123B	0E88	33	3661F	Infotec	France	
			43	2500LF	RICOH		
			63	9650F	NRG		
H5107132G	37F5	51	2500L	RICOH	Asia		
		59	9650	NRG			
H5107131B	23A3	53	2500L	RICOH	Taiwan		

Model: CSO, CRO, CS1, AFO, AF2, K200	Date: 31-May-98	No: Multi-008B
--------------------------------------	-----------------	----------------

AFO	H0847130K	D8D3	H084-20		500	RICOH	Taiwan	KD	
	H0847140L	6B6A	44		500	RICOH	Europe		
	H0847142H	94D0	83		500	RICOH	France		
	H0847143L	350F	34	3301	Infotec	Europe			
	H0847141L	3F13	51	500	RICOH	Asia			
			56	500	RICOH	Vietnam			
H0847150K	2A40	H151-46(FRN:RICOH) H151-54(SW:HCS)		-	Option	Europe	Language Kit		
AF1	H0857135B	FCDF	H085-54		580	RICOH	China		
AF2	H0867130K	9BDF	20		550	RICOH	US	Language Kit	
			H0867140L	3C35	44	550	RICOH		Europe
					90	9620	NRG		
	H0867142H	583D	73	3305	Infotec	France			
			83	550	RICOH				
			93	9620	NRG				
			H0867143L	0CE0	34	3305	Infotec		Europe
	H0867141L	DAD8	51	550	RICOH	Asia			
			59		Nashua	Asia			
	H0867131A	9BC3	53	550	RICOH	Taiwan			
	H0867150L	E725	H151-47(FRN:RICOH), H151-55(SW:HCS), H151-93(FRN:NASHUA)		-	Option	Europe		
	K200	H0087260J	FC1E	20	7000L	RICOH	US		1M ROM (8 ROMs/unit)
H0087261J		E886							
H0087262J		B88E							
H0087263J		084C							
H0087264J		7ABF							
H0087265J		C07F							
H0087266J		29B0							
H0087267J		F658							
H0087270F		451C	30	7000L	RICOH	Germany			
H0087271F		7566							
H0087272F		3FA2							
H0087273F		C2ED							
H0087274F		7A62							
H0087275F		1C05							
H0087276F		7D08							
H0087277F		2830							
H0087320F		4527	40	6765	Infotec	Germany			
H0087321F		7613							
H0087322F		3FA2							
H0087323F		C2ED							
H0087324F		7A62							
H0087325F		1C05							
H0087326F		7D08							
H0087327F		2830							
H0087280H		1956	41	7000L	RICOH	UK			
H0087281H		C7BC							
H0087282H		4E45							
H0087283H		C394							
H0087284H		7A16							
H0087285H		2A4E							
H0087286H		3F82							
H0087287H		56B3							

Model: CSO, CRO, CS1, AFO, AF2, K200

Date: 31-May-98

No: Multi-008B

H0087330H H0087331H H0087332H H0087333H H0087334H H0087335H H0087336H H0087337H	1D20 615D 4FAE D441 78A7 1761 C62A 7B85	31	6765	Infotec	UK
H0087290C H0087291C H0087292C H0087293C H0087294C H0087295C H0087296C H0087297C	4A5D 57CA 4169 C4EB 889D 69BC D427 D12D	42	7000L	RICOH	Italy
H0087340C H0087341C H0087342C H0087343C H0087344C H0087345C H0087346C H0087347C	4A68 5877 4169 CE4B 889D 69BC D427 D12D	32	6765	Infotec	Italy
H0087300E H0087301E H0087302E H0087303E H0087304E H0087305E H0087306E H0087307E	4A2A 3326 403B 9E1A 8968 CC0C 6DF3 18D7	43	7000L	RICOH	France
H0087350E H0087351E H0087352E H0087353E H0087354E H0087355E H0087356E H0087357E	4A35 33D3 403B 9E1A 8968 CC0C 6DF3 18D7	33	6765	Infotec	France
H0087310H H0087311H H0087312H H0087313H H0087314H H0087315H H0087316H H0087317H	196E C7F2 4E45 C394 7A13 2A2B 3F82 56B3	44	7000L	RICOH	Europe/Asia
H0087360H H0087361H H0087362H H0087363H H0087364H H0087365H H0087366H H0087367H	1D38 6193 4FAE D441 78A4 173E C62A 7B85	34	6765	Infotec	Europe

Reissued: 30-Apr-99

Model: General	Date: 15-Jan-99	No.: RGene011d
----------------	-----------------	----------------

## RTB Correction

The items in bold italics have been corrected or added.

Subject: Year 2000 Problem		Prepared by: Y. Okunishi	
From: Technical Service Dept., GTS Division			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input checked="" type="checkbox"/> Other (      )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

### Check Items

The following functions for which the clock timer is used were checked to see whether or not they will function correctly at 0:00 on Jan. 1, 2000.

- 1) Display and printing of the date and time  
The year must be changed to 2000 or 00 from 1999 or 99 and the date must be kept correctly after the year 2000.
- 2) Clock adjustment  
The date and time can be adjusted after the year 2000.
- 3) Send later mode with memory and without memory  
The calling must be made at the set time after the year 2000.
- 4) Automatic re-transmission.  
When a communication error occurs, the machine calls the same destination again automatically after an interval. This will function correctly after the year 2000.
- 5) Weekly timer and night timer  
The energy saver mode (fusing unit) control will work correctly.
- 6) Displayed date after a power failure  
The correct date will be kept by the battery.
- 7) ***Leap year***  
***Machines must recognize the year 2000 as a leap year and the above 1) – 6) will function.***
- 8) ***The year 2001***  
***The above 1) – 6) will function in the year 2001.***

**Reissued: 30-Apr-99**

Model: General

Date: 15-Jan-99

No.: RGene011d

Models Checked

- 1) K50 series (FAX10, 20, 60, etc.)
- 2) K70 series (FAX90, 95, 105, etc.)
- 3) K90 series (FAX80, 85, 75, 86, etc.)
- 4) LE series (FAX08, 09, Phone fax for ATT, etc.)
- 5) B series (B1, RF810, FAX12, FAX300, etc.)
- 6) ZB series (FAX220, FAX240, Innfax, etc.)
- 7) BARBARA series (RF01, 02, 03, 05, 06, etc.)
- 8) OX series (FAX21, 22)
- 9) PF series (PF-1, PF-2)
- 10) A series (FAX500, 550, etc.)
- 11) B60 series (FAX170, 180, etc.)
- 12) K100 series (FAX1000L, 1010L, etc.)
- 13) K105 series (FAX4000L, etc.)
- 14) K200 series (FAX7000L, etc.)
- 15) KV series (FAX2800L, 1200L, etc.)
- 16) C series (FAX2500L, 3000L, 3500L, 4500L, 5600L, etc.)
- 17) L80 (MV715)
- 18) I series (FAX800, 880, 680, MV74, etc.)
- 19) FL series (FAX2700L, 3700L, 4700L, MV310, etc.)
- 20) FX7, LX7 (FAX1700L, MV106, FAX1750MP, etc.)
- 21) L20 series (Aficio FX10)
- 22) K10 series (FX120, Rapicom120, FX210/230, Rapicom210/230, etc.)
- 23) K20 series (FX5000, Rapicom5000, etc.)
- 24) K60 series (FAX610, Rapicom610, etc.)
- 25) K83 series (FAX830, Rapicom830, etc.)
- 26) FR4, FR6 (FAX4800L, FAX3800L, etc.)
- 27) *Schmidt 1(FAX2000L)***
- 28) *Schmidt 3***

Reissued: 30-Apr-99

Model: General	Date: 15-Jan-99	No.: RGene011d
----------------	-----------------	----------------

## Problems found

Most models, except the following, will not experience any problems.

- 1) AFO (FAX 500/550/580, NRG 9620, Infotec 3301/3305, Nashua F492)  
 CSO (FAX 3000/3100/3200, NRG 9660/9661/9662, Omnifax L40/41,  
 Savin FAX 3660/3620, Infotec 3660)  
 CS1 (FAX 3500L, NRG 9665, Omnifax L46, Savin FAX 3670)  
 CRO (FAX 2500L/2600L, NRG 9650, Omnifax L42, Savin FAX 3630, Infotec 3661)
  - a) The day of the week that appears on the display only in the clock adjustment mode is returned back to SUNDAY every time the clock adjustment is done after the year 2000.  
  
 So, the programmed weekly timer does not work correctly. (AFO does not have the weekly timer.)  
  
 If the clock adjustment is not done after the year 2000, the date and the day of week is kept correctly.
  - b) Clock adjustment is available only for the year 91 through 99. The other years cannot be set. (Month, day and time can be adjusted.)
- 2) K200 (FAX7000L)
  - a) Clock adjustment is available only for the years 88 through 99. The other years cannot be set. (Month, day and time can be adjusted.)
  - b) The send later mode does not function (no calling happens) if time passes into the year 2000.  
 No report is printed and the rest of the message in the memory is not cleared automatically, but it is cleared by user operation.
  - c) Automatic re-transmission is not done if the year 2000 starts in the interval after the transmission failure.  
 The rest of the message in the memory is not cleared automatically but it is cleared by user operation.
  - d) The displayed date is reset and turned back to '88 in the event of a power failure after the year 2000.
  - e) ***The day of the week will be wrong if the clock or date information is adjusted after the year 2000.***

**Reissued: 30-Apr-99**

Model: General	Date: 15-Jan-99	No.: RGene011d
----------------	-----------------	----------------

- 3) K60 series (FAX610, Repicom610, Infortec6550)  
K83 series (FAX830, Repicom830, Infortec6750)
  - a) The day of the week is not displayed correctly after the year 2000.
  - b) The send later mode does not function (calling at 0:00AM January 1st 2000)
  - c) The display year is returned back to 85 when the power fails after the year 2000.

The other functions in these models work correctly.

#### Schedule of the countermeasure ROMs

- 1) AFO, CSO, CS1, CRO:  
In April 1998.
- 2) K200(FAX7000L):  
In May 1998. (Corrected version will be in July 1998.)
- 3) K60, K83:  
The ROM will not be available.

RC	REBV	ASIA	
*	*	*	