Technical Bulletin

PAGE: 1/1

Model: Multi-Folding Unit FD5000 Da				:e: 12-Jun-	09	No.: RD454001		
Subject: Correct procedures for pulling out inner folding unit / Grip modification					Prepared by: T.Tadokoro			
From: PPMC Service Planning Department 1G								
Classification:	Troubleshooting	Part info	orma	ation 🛛 Action required				
	Mechanical	Electric	al		Servic	e manual revision		
Paper path Transmit/rec			eive	Retrof	fit information			
	Product Safety	🛛 Other ()	Tier2			

REQUEST

Upon machine installation or your next service visit, please make sure to notify your customers of the correct procedures for opening and pulling out the folding unit to prevent damage to the Pre-stack Guide Plate **Grip (attached with Decal N10)**.

REASON

To pull out the folding unit, the Pre-stack Guide Plate (attached with Decal N10) requires a "clinch" as seen on Decal N10 (figure 1). When forced to open without the "clinch", the Pre-stack Guide Plate Grip could bend or even break (figure 2).






Figure 2

Figure 1

REQUIRED ACTION / SOLUTION

Along with thorough notification to customers of correct procedures for pulling out the unit, the Pre-stack Guide Plate Grip will be modified for improved durability. The modified Grip will be reflected from July - August production.



Reissued: 03-Dec-09

Model: Multi-Folding Unit FD5000 Da			Dat	e: 08-Jul-09	No.: RD454002a			
RTB Reissue The items in bold italics have been corrected.								
Subject: Firmware Release Note: Folder_DONAU				Prepared by: T. Tadokoro				
From: PPBG QA/Service Planning Dept.								
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part informa		Ser	ion required vice manual revision rofit information			

This RTB has been issued to announce the firmware release information for the **Folder_DONAU.**

Version	Program No.	Effective Date				
01.140:12	D4545132A	September 2009 production				
01.110:12	D4545132	1st Mass production				

Version	Modified Points or Symptom Corrected
01.140:12	Symptom Corrected:
	 Fold position adjustment is not reflected.
01.110:12	1st Mass production



Reissued: 29-Dec-09

Model: Multi-Folding Unit FD5000 Da			Date: 08-Jul-09			No.: RD454002b		
RTB Reissue The items in bold italics have been corrected.								
Subject: Firmware Release Note: Folder_DONAU				Prepared by: T. Mimura				
From: PPBG QA/Service Planning Dept.								
Classification:	Troubleshooting	🗌 Part info	ormat	tion	Action	required		
	Mechanical Electrical			🗌 Service manual revi				
Paper path Transmit/re			it/receive Retrofit information			it information		
	Product Safety	🛛 Other ()	🗌 Tier 2			

This RTB has been issued to announce the firmware release information for the **Folder_DONAU.**

Version	Program No.	Effective Date
01.180:12	D4545132B	December 2009 production
01.140:12	D4545132A	September 2009 production
01.110:12	D4545132	1st Mass production

Version	Modified Points or Symptom Corrected
01.180:12	Symptom Corrected:
	 Default adjustment value has been changed.
	 When paper size is changed in the same job and using gate fold, the jam problem has been fixed.
	 When the NRS system is connected and jammed paper is not removed, the warn screen unshown problem has been fixed.
	 When folding pattern, paper size had been changed in the same job, the jam problem has been fixed.
	 Jogger encounter with the paper has been fixed.
	 When z-folding and outputted to a down stream peripheral, changing shift tray output and proof tray output jam problem has been fixed.
01.140:12	Symptom Corrected:
	Fold position adjustment is not reflected.
01.110:12	1st Mass production

Technical Bulletin

Reissued: 18-Aug-10

Model: Multi-Folding Unit FD5000			Date: 08-Jul-09			No.: RD454002c		
RTB Reissue The items in bold italics have been corrected.								
Subject: Firmware Release Note: Folder_DONAU			Prepared by: T. Mimura					
From: PPBG/Service Plannning Dept.								
Classification:	Troubleshooting	🗌 Part info	ormat	tion [Action	required		
Mechanical Electrical			al	I Service manual revi				
Paper path Transmit/rev			it/rec	eive [it information			
	Product Safety	🛛 Other () [Tier 2			

This RTB has been issued to announce the firmware release information for the **Folder_DONAU.**

Version	Program No.	Effective Date
01.190:12	D4545132C	August 2010 production
01.180:12	D4545132B	December 2009 production
01.140:12	D4545132A	September 2009 production
01.110:12	D4545132	1st Mass production

Version	Modified Points or Symptom Corrected					
01.190:12	ymptom fixed: Jam recovery problem fixed.					
	Other changes:					
	- Venus-C3 corresponded					
01.180:12	Symptom Corrected:					
	 Default adjusted value has been changed. 					
	 When paper size is changed in the same job and using gate fold, the jam problem has been fixed. 					
	 When the NRS system is connected and jam paper is not removed, the warn screen unshown problem has been fixed. 					
	 When folding pattern, paper size had been changed in the same job, the jam problem has been fixed. 					
	 Jogger encounter with the paper has been fixed. 					
	 When z-folding and outputted to the down stream, changing shift tray output and proof tray output jam problem has been fixed. 					
01.140:12	Symptom Corrected:					
	Fold position adjustment is not reflected.					
01.110:12	1st Mass production					

Technical Bulletin

PAGE: 1/1


Model: Multi-Folding Unit FD5000 (D454) Dat				e: 16-Nov	-10	No.: RD454003		
Subject: Part Changes - Guide Plate			Prepared by: T. Komori					
From: PP Service Planning Department 1G								
Classification:	Troubleshooting	🛛 Part inf	orma	tion	Action required			
	🗌 Mechanical	Electric	ctrical 🗌 Serv		Servic	vice manual revision		
Paper path Transmit/rec			nit/receive Retrofit information			fit information		
	Product Safety	Other ()	Tier 2			

Change: Shape of the parts and screw types

Reason: To prevent misalignment of the brackets (D4554216 & D4554217) in the manufacturing process

Old Part Number	New Part Number	Description	Q'ty	Ir	nt	Page	Index	Note
D4553611	D4543615	GUIDE PLATE:NO.1	1	X/O		29	1	
D4544101	D4544105	PAPER CRIMP SUB- UNIT:NO.1:ASS'Y	1	X/O	X/O	31, 35	*	
D4544216	D4544218	GUIDE PLATE:NO.1:ENTRANCE	1	X/O	as a set	39	13	
D4544217	D4544219	SHEET:GUIDE:NO.1	1	X/O	Sel	39	12	
	09513006N	SCREW - M3X6	2			39	108	Add

19.Fold Unit 13 (D454)



Technical Bulletin

PAGE: 1/2

Model: Multi-Folding Unit FD5000 (D454) Date					·10	No.: RD454004		
Subject: Jogger Fence modified to prevent false detection					Prepared by: T. Komori			
From: PP Service	e Planning Department 1G							
Classification:	Troubleshooting	Part info	ormat	tion	Action	n required		
	🗌 Mechanical	Electric	al		Servic	e manual revision		
	Paper path	🗌 Transm	it/rec	eive	Retrof	fit information		
	Product Safety	Other ()	Tier 2			


Change: Part was added

Reason: To prevent the paper detection sensor from falsely detecting the jogger fence

Old Part Number	New Part Number	Description	Q'ty	Ir	nt	Page	Index	Note
D4543693	D4543672	JOGGER FENCE:FRONT	1	X/O	X/O	25	6	
	D4543673	PAD:SENSOR	1		as a set	25	22	Add


A pad has been added to the jogger fence to optimize the distance between the paper detection sensor and the jogger fence which will give a larger margin of error.

12.Fold Unit 6 (D454)





Model: Multi-Folding Unit FD5000 (D454) Date: 18-Nov-10 No.: RD454004



Technical Bulletin


PAGE: 1/1

Model: Multi-Folding Unit FD5000 (D454) Date			e: 22-Apr-	·11	No.: RD454005		
Subject: Part Changes – proof tray				Prepared by: T. Komori			
From: PP Service	e Planning Department 1G						
Classification:	Troubleshooting	🛛 Part inf	ormat	tion	Action	n required	
	🗌 Mechanical	Electric	al		Servic	e manual revision	
	Paper path	🗌 Transm	iit/rec	eive	Retro	fit information	
	Product Safety	Other ()	🗌 Tier 2		

Change: Shape of the part

Reason: As a result of the bracket modification (D4546332 \rightarrow D4546333), interference occurred as shown in the following diagram. This modification is to standardize for releasing Multi-Folding Unit FD5010.

Old Part Number	New Part Number	Description	Q'ty	I	/C	Page	Index
D4546152	D4546153	PROOF TRAY	1	X/O	20.0	59	4
D4546332	D4546333	BRACKET:COVER:TAKE OFF:FRONT	1	X/O	as a set	3	8



Tray's shape has been changed. (D4546152 - \rightarrow D4546153)

Technical Bulletin

PAGE: 1/1

Model: Multi-Folding Unit FD5000 (D454)			Dat	e: 27-Jan-	12	No.: RD454006		
Subject: Part Changes – parts standardization with FD5010					Prepared by: T. Komori			
From: PP Service	e Planning Department 1G							
Classification:	Troubleshooting	🛛 Part inf	ormat	tion	Action	required		
	Mechanical	Electric	al		Servic	e manual revision		
	Paper path	Transm	it/rec	eive	Retrof	it information		
	Product Safety	Other ()	🗌 Tier 2			

Change: Shape of the parts **Reason:** Standardization of parts according to the release of the Multi-Folding Unit FD5010 (D521)

Old P/N	New P/N	Description	Q'ty	[/	С	Page	Index	Note
D4546511	D4546512 D4546516	INNER COVER:PAPER CRIMP SUB- UNIT	1	X/O	as a			
D4547123	D4547129	DECAL:LEVER:TURN:N13	1	~0	set			

Old P/N	New P/N	Description	Q'ty]/	С	Page	Index	Note
D4544419	D4544422	COVER:DC MOTOR:NO.1	1			55	21	
	11050623	CLAMP - LBWS-0206S-V0	1	X/O	as a set	15	13	
D4545262	D4545263	HARNESS:SENSOR:PULL OUT: SENSOR	1			45	10	

Old P/N	New P/N	Description	Q'ty	/	С	Page	Index	Note
D4542515	D4542581	GUIDE PLATE:PROOF TRAY: RIGHT UPPER: ASS'Y	1			61	16	
D4542527	D4542586	SHAFT:DRIVEN:MOVE	1	X/O	as a set	61	20	
D4543433	D4542555	GUIDE PLATE:PROOF TRAY: MIDDLE:LEFT:ASS'Y	1			6	22	

Old P/N	New P/N	Description	Q'ty	I/0	С	Page	Index	Note
D4543842	D4543845	GUIDE:LEFT LOWER				43	23	
D4543841	D4543844	GUIDE PLATE:NO.3:OPEN AND CLOSE		X/O	as a	43	26	
D4544666	D4544654	GUIDE PLATE:LEFT LOWER: ENTRANCE:OPEN AND CLOSE	1	~~	set	41	14	
D4544710	D4544718	GUIDE:PAPER CRIMP SUB- UNIT:NO.2				45	16	


Technical Bulletin

PAGE: 1/1

Model: Multi-Folding Unit FD5000 (D454) Date				e: 27-Jan	-12	No.: RD454007		
Subject: Part Changes – Lever and Inner Cover					Prepared by: T. Komori			
From: PP Service	e Planning Department 1G							
Classification:	Troubleshooting	Part inf	ormat	tion	Action	n required		
	Mechanical	Electric	al		Servic	e manual revision		
	Paper path	Transm	it/rec	eive	Retrof	fit information		
	Product Safety	Other ()	Tier 2			

Change: Shape of the lock lever **Reason:** To ensure complete shut of the guide plate to prevent possible jams

Old Part Number	New Part Number	Description	Q'ty	Ir	nt	Page	Index	Note
D4543463	D5213463	LEVER:LOCK:UPPER	1	X/O		17	20	
D4543464	D5213464	LEVER:LOCK:LOWER	1	X/O	as a set	17	21	
D4546512	D4546516	INNER COVER:PAPER CRIMP SUB-UNIT	1	X/O		15	6	





Reissued: 18-Apr-12

Model: Multi-Fol	ding Unit FD5000		Date	e: 08-Jul-09	No.: RD454002d	
RTB Reissue The items in bol	d italics have been cor	rected.				
Subject: Firmwar	re Release Note: Folder_DO	UANC		Prepared by: J. Ohno		
From: 1st PP Teo	ch Service Sect., PP Tech S	Service Dept.				
Classification:	Troubleshooting	Part info	ormatio	on 🗌 Actior	n required	
	Mechanical	Electric	al	Servio	ce manual revision	
	Paper path	🗌 Transm	it/rece	ive 🗌 Retro	fit information	

🛛 Other (

)

Tier 2

This RTB has been issued to announce the firmware release information for the **Folder_DONAU.**

Version	Program No.	Effective Date	Availability of RFU
01.200:12	D4545132D	March 2012 production	Available
01.190:12	D4545132C	August 2010 production	Available
01.180:12	D4545132B	December 2009 production	Available
01.140:12	D4545132A	September 2009 production	Available
01.110:12	D4545132	1st Mass production	Available

Note: Definition of Availability of RFU via @Remote

Product Safety

"Available" The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected						
01.200:12	Symptoms Corrected: After feeding a cover sheet from the Cover Interposer, the first sheet fed from the mainframe to be Z-folded results in a jam at the Multi- folder unit.						
01.190:12	Symptom fixed: - Jam recovery problem fixed. Other changes: - Venus-C3 corresponded						
01.180:12	 Symptom Corrected: Default adjusted value has been changed. When paper size is changed in the same job and using gate fold, the jam problem has been fixed. When the NRS system is connected and jam paper is not removed, the warn screen unshown problem has been fixed. When folding pattern, paper size had been changed in the same job, the jam problem has been fixed. Jogger encounter with the paper has been fixed. When z-folding and outputted to the down stream, changing shift tray output and proof tray output jam problem has been fixed. 						
01.140:12	Symptom Corrected: - Fold position adjustment is not reflected.						



Reissued: 18-Apr-12

Model: Multi-Fe	olding Unit FD5000	Date: 08-Jul-09	No.: RD454002d			
Version	Modified Points or Symptom Corrected					
01.110:12	1st Mass production					

Technical Bulletin

PAGE: 1/1

Model: Multi-Folding Unit FD5000 (D454) Date			e: 05-Jun-	12	No.: RD454008			
Subject: Door Stopper P/N				Prepared by: J. Ohno				
From: PP Tech Service Dept., 1st PP Tech Service Sect.								
Classification:	Troubleshooting	🛛 Part informat		tion	Action	n required		
	🗌 Mechanical	Electrical		Electrical			Servic	e manual revision
	Paper path	Paper path 🗌 Transmit/rece		t/receive 🗌 Retr		fit information		
	Product Safety Other ())	Tier 2				

Change: The following parts were added as service parts. **Reason:** To increase magnetic strength for secure closing of the door.

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
-	D4546381	LEVER:GUIDE PLATE:LEFT LOWER:OPEN AND CLOSE	1	-	3	22	Add
-	D4546382	BRACKET:LEVER:GUIDE PLATE:LEFT LOWER:OPEN AND CLOSE	1	-	3	23	Add
-	D4546385	TORSION SPRING:LEVER:GUIDE PLATE:55N	1	-	3	24	Add



PM: D4546385 TORSION SPRING: LEVER: GUIDE PM: D4546381 LEVER: GUIDE PLATE: LEFT COVER: OPEN AND CLOSE

Technical Bulletin


PAGE: 1/1


Model: Multi-Folding Unit FD5000 (D454) Date					12	No.: RD454009		
Subject: New P/I		Prepared	d by: J. C)hno				
From: PP Tech Service Dept., 1st PP Tech Service Sect.								
Classification:	ification: Troubleshooting Zert information		ormat	tion	Action required			
	Mechanical	Electrical		Electrical			Servic	ce manual revision
	Paper path	Paper path Transmit/rece		it/receive		fit information		
	Product Safety Other ())	Tier 2				

Change: P/N modification of the motor cover and harness **Reason:** To allow application of common parts with the Multi-Folding Unit FD5010

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
D4544419	D4544422	COVER:DC MOTOR:NO.1	1	X/O	55	21	-
D4545262	D4545263	HARNESS:SENSOR:PULL OUT:SENSOR	1	X/O	45	10	-

When replacing the above parts for the first time, replace as a set.





Technical Bulletin

PAGE: 1/1

Model: Folder FD5000 Dat			e: 28-Nov-14	No.: RD454010	
Subject: Parts ca	talog correction – Paper Feed Gu)	Prepared by: J.	Ohno	
From: PP Tech S	ervice Dept., 3rd PP Tech Servic				
Classification:	Mechanical	 ☑ Part inforr □ Electrical □ Transmit/r □ Other (Servi	n required ce manual revision ofit information

The following parts were modified to prevent the drive gear of the first fold roller from breaking as a result of jams.

Old p/n	New p/n	Description	Q'ty	Ir	nt	Page	Index	Note
D4544198	D5214198	GUIDE PLATE:MIDDLE:GATE: OPEN AND CLOSE	1	X/O	As a	39	9	Change
-	D5214199	ROLLER:GUIDE PLATE:MIDDLE: OPEN AND CLOSE	1	-	set	39	14	Add

19.Fold Unit 13 (D454)

