

Model: Model K-C2 Printer/Scanner Option (B622)		Date: 19-Nov-04	No.: RB121009
Subject: Wrong Installer on LAN-FAX Driver CD-ROM		Prepared by: A. Ishiyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (       )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input checked="" type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

**This RTB only applies to the China/Taiwan versions of the Printer/Scanner option (B622-21).**

## Symptom

The LAN-FAX does not work if it is installed with “Auto Run” on the CD-ROM v1.00 or v1.01.

## Cause

Firmware bug:

The installer program for “Auto-run” installs the wrong driver (M3).

**Note:** The LAN-FAX works fine if it is installed with “Add Printer,” because this program installs the correct driver (M4).

## Workaround in the field

Install the LAN-FAX driver with “**Add Printer**” (not “Auto-run”).

## Solution

Firmware modification.

Applied from: CD-ROM **v1.02**, December 2004 production

Model: Kir-C2		Date: 26-Jun-06	No.: RB121001
Subject: Important Notes for the replacement of the controller board		Prepared by: Hiromoto Saitoh	
From: 1st Tech. Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (      )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input checked="" type="checkbox"/> Retrofit information

**This RTB applies to the following models:**

Model K-C2, K-C2.5 (B121, B122, B123, B259, B260, B261)

## Important Note Regarding the Replacement of the Controller Board

Do the following procedure after you replace the controller board.

**Note:** This is necessary for the machine to support @Remote (NRS).

1. Execute **Sp5870-3** (Common Key Info Initialize).
2. Execute **Sp5870-1** (Common Key Info Writing).
3. Turn the machine main power OFF/ON.