Technical Bulletin

PAGE: 1/1

Model: V-C2 RT4000 (SIBERIA)	Date:24-Jun-09	No.: RD350001
,		


Subject: Paper	Size Sensor		Prepared	d by: T.Toriumi
From: 2nd Tech.	Support Sec. Service Support	Dept.		
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information
	Other ()			

10. Paper Tray 8 (D350)

Old part	New part	Description		Int	Page	Index	Note
number	number						
B8343169	D3553169	PAPER SIZE SENSOR PLATE	1-1	X/O	21	9	-
B8344593	D3553168	PAPER SIZE SENSOF	1-1	X/O	21	4	-
		BRACKET – LONG					
-	04514008N	Tapping Screw:4x8	1-2	-	21	102	-

Change: The following parts (Index#4 and #9) were changed.

Reason: To correct the bug in which the paper size is not displayed on the operation panel correctly.



RCL (Japan) Production (D350)

1102 (Gapan) 1 (Gaganan (Gagan								
MODEL NAME	DESTINATION	CODE	SERIAL NO.					
LCIT RT4000	North America	D350-17	M8690600001					
LCIT RT4000	Europe/Asia	D350-27	M8690600168					

Model: V-C2 RT4000

Technical Bulletin

Date:24-Jul-09 No.: RD350002


PAGE: 1/1

Subject: Parts F	Registration (RT4000 Rela	Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informat ☐ Electrical ☐ Transmit/rec	Service manual revision

15. Transfer Section 3 (D350)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	D3502800	Joint Unit: Ass'y	1	-	31	*	-

Change/Reason: The RT4000 Relay Unit was registered as a service part.



Technical Bulletin

PAGE: 1/4

Model: V-C2 RT4000 Date:09-Nov-09 No.: RD350003

Subject: Precautionary Statement for RT4000				d by: T.Toriumi
From: 2nd Tech. Support Sec. Service Support Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part information ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information


SYMPTOM

The machine tries to move the tray bottom plate (P/N: D3554620) past the upper limit, creating noise. As a result, the paper tray cannot be opened and the tray bottom plate (P/N: D3554620), bottom plate support (P/N: D3554621), and/or paper feed sensor (P/N: AW020160) breaks.

See the illustrations below

CAUSE

The customer loads A4/A5/LT-sized paper in the LCT in the "non-feed area" shown in the photograph, instead of in the correct space on the left side of the tray.




ACTION

- If the bottom plate, bottom plate support, or paper feed sensor is damaged due to the above cause, replace the damaged part(s).
- Remind customers of the correct way to load paper in the tray, emphasizing that paper should not be loaded in the "non-feed area" shown in the photo.



PAGE: 2/4


Model: V-C2 RT4000 Date:09-Nov-09 No.: RD350003



Tray Bottom Plate (P/N: D3554620)




Model: V-C2 RT4000 Date:09-Nov-09 No.: RD350003



Tray Bottom Plate – Support (P/N: D3554621)

PAGE: 3/4






Model: V-C2 RT4000 Date:09-Nov-09 No.: RD350003

Paper Feed Sensor (P/N: AW020160)

PAGE: 4/4



Technical Bulletin

PAGE: 1/2

Model: V-C2 RT4000	Date:30-Nov-09	No.: RD350004	

Subject: Duct: Upper: Front/Rear: Blower				d by: T.Toriumi
From: 1st Overseas Tech Support Sec., 1st PQM Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information

4. Paper Tray 2 (D350)

Old pa	rt New part	Description	Q'ty	Int	Page	Index	Note
numbe	r number						
D35533	63 D3553365	DUCT:UPPER	1-1	X/O	9	*23	Note.1
D35533	61	FRONT:BLOWER:ASS'Y		as a			
D35533	72			set			

^{*}New Index

5. Paper Tray 3 (D350)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
D3553363	D3553375	DUCT:UPPER	1-1	X/O	11	*29	Note.2
D3553371		REAR:BLOWER:ASS'Y		as a			
D3553372				set			

^{*}New Index

Note.1

Cover: Duct (D3553363 Index#14), DUCT:UPPER FRONT:BLOWER (D3553361 Index#15) and Duct: Lower: Brower (D3553372 Index#16) can't be replaced independently. If these parts need to be replaced, please install DUCT: UPPER FRONT: BLOWER: ASS'Y (D3553365 Index#23).

Note.2


Cover: Duct (D3553363 Index#4), DUCT:UPPER REAR:BLOWER (D3553361 Index#6) and Duct: Lower: Brower (D3553372 Index#5) can't be replaced independently. If these parts need to be replaced, please install DUCT: UPPER REAR: BLOWER: ASS'Y (D3553375 Index#29).



PAGE: 2/2


Model: V-C2 RT4000 Date:30-Nov-09 No.: RD350004

Note.1



Note.2

5.Paper Tray 3 (D350)



DUCT: UPPER REAR: BLOWER: ASS'Y (D3553375 Index#29)

Technical Bulletin

PAGE: 1/1

Model: V-C2/C3 RT4000			Dat	e: 24-Feb-	10	No.: RD350005
Subject:: Tolerance for Image Skew of LCT				Prepared by: Takeshi Toriumi		
From: 1st Overseas Tech Support Sec, 1 st PQM Dept						
Classification:	Troubleshooting	☐ Part info	ormat	tion	☐ Action	required
		☐ Electrica	al		Service	e manual revision
	⊠ Paper path	☐ Transmit/red		eive	Retrof	it information
	Other ()					

Information about image skew when using the LCT RT4000

Image skew may occur when using the LCT RT4000 with the D014/D015/D078/D079/D081/D082 copier. The following is the specification (allowed margin of error) for image skew when using the LCT:

+/- 1mm (B5 SEF, A4 SEF, LT SEF, A3, DLT)

PAGE: 1/2


Model: V-C2/C3	R4000		Dat	e: 30-May	<i>'</i> -11	No.: RD350006		
Subject: New gui	ide part for LCIT			Prepared by: Takeshi Toriumi				
From: 1st Overse								
Classification:	☐ Troubleshooting	⊠ Part info	orma	tion	☐ Action	n required		
	☐ Mechanical	☐ Electric	al		☐ Service	ce manual revision		
	☐ Paper path	☐ Transmit/rece		eive	Retro	fit information		
	☐ Product Safety	Other ()	☐ Tier 2			

This RTB has been issued to announce that the tray part for the LCIT has been changed

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
04533006N	-	TAPPING SCREW - M3X6	1-0	-	11	104	X/O
B8343358	B8343356	COVER:UPPER REAR	1	X/X	11	10	as a set
B8343334	B8343343	GUIDE:UPPER REAR	1	X/X	11	14	
B8343349	B8343345	RACK:UPPER	1	X/X	11	16	

B8343345, B8343343, B8343356, 04533006N

5.Paper Tray 3 (D350)



Technical Bulletin


PAGE: 2/2

Model: V-C2/C3 R4000 Date: 30-May-11 No.: RD350006

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
04533006N	-	TAPPING SCREW - M3X6	1-0	-	9	101	X/O
D3503339	D3503345	RACK:UPPER	1	X/X	9	9	as a set
B8343332	B8343341	GUIDE:UPPER FRONT	1	X/X	9	10	
B8343357	B8343355	GUIDE:LM-6:UPPER FRONT:PEEN	1	X/X	9	11	

D3503339, B8343341, B8343355, 04533006N

4.Paper Tray 2 (D350)



Model: V-C2/C3 RT4000 Date: 11-Nov-11 No.: RD350007


Subject: Parts (Catalog Correction(RT400	00)	Prepared by: Chihiro Shimaji
From: 1st Tech S	ervice Sect., MFP/P Tech Ser		
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☑ Part informate☐ Electrical☐ Transmit/rec	Service manual revision

3. Paper Tray 1 (D350)

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
07413808	07423808	Ball Bearing - 8x16x5MM	2	-	7	108	-

Change/Reason: The part number in the Parts Catalog was incorrect.

3.Paper Tray 1 (D350)




Technical Bulletin

PAGE: 1/2

Model: Aries-C1.	Model: Aries-C1.5 (D095)				-11	No.: RD095010		
Subject: Part Cha	Subject: Part Changes (Bearing & Plates)					akada		
From: PP Tech S	ervice Dept., 1st PP Tech Ser							
Classification:	☐ Troubleshooting	□ Part info	ormat	tion	Action	required		
	☐ Mechanical	☐ Electrication	al		Service	e manual revision		
	☐ Paper path	☐ Transmit/rece		☐ Transmit/receive		fit information		
	☐ Product Safety	Other ()	☐ Tier 2			

Change: Bearing and the shape of the accompanying plates **Reason:** To share common parts with the LCIT RT5060 (D516)

1, The bearing was changed as shown in the photo below.



2, The size of the holes on the plates were reduced to correspond with the modified bearings.



Model : LCIT RT5040 (D095)

		•					
Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
07423808	D5161537	Plain Shaft Bdaring:DIA8	2	X/O	266	103	
B8343395	B8343391	Plate:Left:No.2	1	X/O	266	3	
B8343396	B8343392	Plate:Right:No.2	1	X/O	266	22	


- · Make sure all 3 parts shown in the above table are replaced as a set.
- The modification described in this bulletin also applies to Aegis-C1 (D016), Aries-C1 Lt (D097), LCT RT4000 (D350), LCT RT5020 (D355), and LCT RT5050 (D532).



PAGE: 2/2

Model: Aries-C1.5 (D095) Date: 28-Nov-11 No.: RD095010

121.Paper Tray 1 (D095)



Technical Bulletin

PAGE: 1/1

							_	
Model: V-C2/C3	RT4000		Date: 09-Dec-11			No.: RD350008		
Subject: Parts In	formation (Bearing & Plates)			hiro Shimaji				
From: 1st Tech Service Sect., MFP/P Tech Service Dept.								
Classification:	☐ Troubleshooting	□ Part inference □	orma	tion	Action required			
	☐ Mechanical	☐ Electric	al		Service	ce manual revision		
			nit/receive		☐ Retrof	fit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2			


Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
07423808	D5161537	PLAIN SHAFT BEARING:DIA8	2	X/X	7	108	
B8343395	B8343391	PLATE:LEFT:NO.2	1	X/X	7	:3	X/O as a set
B8343396	B8343392	PLATE:RIGHT:NO.2	1	X/X	7	22	ac a 661

• Make sure all 3 parts in the above table are replaced as a set.

Change: Bearing and the shape of the accompanying plates

Reason: Vendor change

3.Paper Tray 1 (D350)



Technical Bulletin

PAGE: 1/2

							_	
Model: V-C2/C3	RT4000		Dat	e: 09-Dec	-11	No.: RD350009		
Subject: Parts In	Subject: Parts Information (Holder and Side fence bracket)					hiro Shimaji		
From: 1st Tech S	Service Sect., MFP/P Tech Ser							
Classification:	Troubleshooting	□ Part infe	orma	tion Actio		n required		
	☐ Mechanical	☐ Electric	al		Service	ce manual revision		
	- · ·		nit/receive		Retro	fit information		
	☐ Product Safety	☐ Other ()	☐ Tier 2			


Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
B8343323	B8343363	HOLDER:UPPER FRONT	1	X/X	9	7	
B8343329	B8343364	HOLDER:UPPER REAR	1	X/X	11	21	X/O
B8343351	B8343353	BRACKET:UPPER FRONT:SIDE FENCE	1	X/X	9	8	as a set
B8343352	B8343354	BRACKET:UPPER REAR:SIDE FENCE	1	X/X	11	22	

• When replacing the above parts, replace all 4 parts as a set.

Change: Holder and Side fence bracket

Reason: To allow usage of common parts for different products

4.Paper Tray 2 (D350)






PAGE: 2/2

Model: V-C2/C3 RT4000 Date: 09-Dec-11 No.: RD350009

5.Paper Tray 3 (D350)



Technical Bulletin


PAGE: 1/5

Model:V-C2/C3	RT4000		Dat	e: 24-Jul-					
Subject: Parts In	formation (Paper Feed)			Prepare	ed by: Chihiro Shimaji				
From: 1st Tech Service Sect., MFP/P Tech Service Dept.									
Classification:	☐ Troubleshooting	□ Part inference □	orma	tion	Action	required			
	☐ Mechanical	☐ Electric	al		Service	e manual revision			
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information			
	☐ Product Safety	☐ Other ()	☐ Tier 2		ļ		

11. Paper Feed Section 1 (D350)

Old part number	New part number	Description	Q'ty	Int	Pg.	Index	Note
B8322574	D4522574	PICKUP ARM	1-1	X/X	23	8	X/O
D3502585	D5162586	SHAFT:FEED ROLLER:ASS'Y	1-1	X/X	23	15	as a set
D3552571	D4522573	PAPER FEED ROLLER:GUARD	1-1	X/X	23	23	
					23	5	
AA100014	D0592620	Retaining Ring C - Separate	3-3	X/X	25	1	
08050088	08050088	Retaining Ring - M6	4-5		23	105	

1. Remove the following parts.







PAGE: 2/5

Model:V-C2/C3 RT4000 Date: 24-Jul-12 No.: RD350010

2. Remove the following parts.




3. Remove the following parts. (x3)



08050088 (RETAINING RING – M6)

4. Remove the following part.




AA066677 (TENSION SPRING)

Date: 24-Jul-12 No.: RD350010

PAGE: 3/5

5. Remove the following part.


Model:V-C2/C3 RT4000



D3502585(SHAFT:FEED ROLLER:ASS'Y)

Old parts


6. Remove the following three parts from Old parts (D3502585/SHAFT:FEED ROLLER) , and assemble to New parts(D5162586/SHAFT:FEED ROLLER:ASS'Y)



PAGE: 4/5


Model:V-C2/C3 RT4000 Date: 24-Jul-12 No.: RD350010

7. Set the following part to bracket



07413708 (BALL BEARING – 8X12X3.5MM)

8. Set the following parts.



D5162586 (SHAFT:FEED ROLLER:ASS'Y)

.. New Parts


AA083015 (ROLLER CLUTCH)

07413708

(BALL BEARING - 8X12X3.5MM)

D4522574 (PICKUP ARM)
··New Parts

9. Set the following parts. (x4)



08050088 (RETAINING RING - M6)


PAGE: 5/5

Model:V-C2/C3 RT4000 Date: 24-Jul-12 No.: RD350010

10. Set the following parts.



11. Set the following part.



12. Set the following parts.



Technical Bulletin

PAGE: 1/3

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060 (D516) / RT5030 (D452)				e: 2-Jul-10	No.: RD453008		
Subject: Broken Casters on LCIT Prepared by: S. Sasaki							
From: 1 st PP Ted							
Classification:		☐ Part informat		tion		required	
	☐ Mechanical	☐ Electrical		☐ Service		ce manual revision	
	☐ Paper path	☐ Transmit/rece		eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☐ Tier2		

Symptom

Broken caster on the following LCITs:

RT4000 (D350), RT5040 (D453), RT5060 (D516), RT5030 (D452)



Cause

One lot of casters was manufactured with an incorrect molding process, resulting in lower durability.

Occurrence Rate

Extremely Low

Among 118 affected casters, 2.8% (= approx 3 pcs) may break according to factory test results.

Action

Replace the caster (p/n: AH012050) when a unit with a broken caster is found. See the following page for the replacement procedure.

Date: 2-Jul-13 No.: RD453008

PAGE: 2/3

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060 (D516) / RT5030 (D452)

Caster Replacement Procedure


IMPORTANT: 3 persons are required to secure working safety.

- Remove all trays from the LCT. See the following section of the field service manual. LCIT RT5040, LCIT RT5060
 - 1. Replacement and Adjustment > Removing Trays

LCIT RT4000

1. Replacement and Adjustment > Common Procedures > Trays
LCIT RT5030

- 1. Replacement and adjustment > Trays
- 2. Lay the LCT down so that the side to which the mainframe docks faces up.



3. Replace the broken caster with a new one. (Screw x4)





- 4. Put the LCT back to its normal position.
- 5. Install the trays into the LCT to complete the procedure.

PAGE: 3/3

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060 (D516) / RT5030 (D452)

Date: 2-Jul-13

No.: RD453008

Serial Numbers of the Possibly Affected Units

Units with the following serial numbers may have the affected casters.

LCIT RT5030

NA	EU/AP
V5621100001 to V5621100160	V5621100161 to V5621100175
V5621200001 to V5621200051	V5621100176 to V5621100197
V5630100015 to V5630100160	V5621200052 to V5621200085
V5630200001 to V5630200073	V5630100161 to V5630100172
V5630300001 to V5630300083	V5630200074 to V5630200113
V5630300139 to V5630300147	V5630300084 to V5630300123
	V5630300124 to V5630300138

LCIT RT5040

NA	EU/AP
V5721100001 to V5721100019	V5721100020 to V5721100051
V5721200001 to V5721200043	V5721200044 to V5721200110
V5730100001 to V5730100116	V5730200032 to V5730200063
V5730200001 to V5730200031	V5730300051 to V5730300102
V5730300001 to V5730300050	

LCIT RT5060

NA	EU/AP
W0121100001 to W0121100181	
W0121100182 to W0121100207	
W0121200001 to W0121200224	None
W0130100001 to W0130100178	None
W0130200001 to W0130200043	
W0130300001 to W0130300113	

LCIT RT4000

NA	EU/AP
	M8621200056 to M8621200065
None	M8630200007 to M8630200013
	M8630300001 to M8630300004

1	П

|--|

Model: V-C2/C3 RT4000		Date	te: 23-May-14		No.: RD350011	
Subject: Part Info	rmation (STAY: END FENCE)			Prepare	d by: Ch	ihiro Shimaji
From: 1st Tech Se	ervice Sect., MFP/P Tech Servi	ice Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part in☐ Electric☐ Transr☐ Other	cal nit/rec		☐ Serv	n required ice manual revision ofit information 2

Please add the following part to your parts catalog.

P/N	Description	Q'ty	Int	Page	Index	Note
D3554586	STAY:END FENCE	2	ı	20	17	Add

10.Paper Tray 8 (D350)

