

Model: LCIT RT5060 (D516)	Date: 20-Jun-11	No.: RD516001
---------------------------	-----------------	---------------

Subject: Firmware Release Note: LCIT RT5060		Prepared by: K.Tsutsui	
From: PPBG Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **LCIT**.

Version	Program No.	Effective Date	Availability of RFU
01.030:04	D5165510B	1st Mass production	Available

**Note: Definition of Availability of RFU via @Remote**

**“Available”:** The firmware can be updated via RFU or SD card.

**“Not available”:** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
01.030:04	1st Mass production

Model: Aegis-C1 (D016)		Date: 23-Jan-12	No.: RD016018
Subject: Part Changes; Handle assembly and Shoe		Prepared by: A. Takada	
From: PP Tech Service Dept., 1st PP Tech Service Sect.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

**Change:** Shape of the Handle assembly and Shoe

**Reason:** To enable usage of common parts with different products


Changed parts

A : Shoe: Handle: Release

Shape of the Shoe was partially modified.

B : Handle: Ass'y

Handle was also modified in accordance with the shape change of the Shoe.  
(Shape of the plate was also modified.)



Model: Aegis-C1 (D016)

Date: 23-Jan-12


No.: RD016018

## Model : Aegis-C1 (D016)

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
D3553566	D3553567	Handle:Ass'y	2	X/O	287	11	-
-	D5163847	Shoe:Handle:Release	4		287	17	-

- If the unit is now installed with D3553566, replace with D3553567. D5163847 is not needed.
- D5163847 can be attached ONLY to D3553567.
- The modification described in this bulletin also applies to Aries C-1.5 (D095), LCT RT5020 (D355), LCIT RT5050 (D532), and LCIT RT5060 (D516).


### 134.Transfer Section 1 (D016)



Model: Taurus-C1/P1 (D074/D075/M044)		Date: 15-Feb-12	No.: RD516002
Subject: Parts Number Information (Tray Heater for Taurus-C1/P1 LCIT RT5060)		Prepared by: T. Komori	
From: 1st Tech Service Sect., PP Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

The tray heater kit has been registered with the following part number.  
This tray heater can be used in both 230V and 120V areas.

## D4530900 (HEATER:DEHUMIDIFIER:230V:KIT)



No.	Description	Qty
1.	Cover Plate	1
2.	Heaters (230V 18W)	2
3.	Screws (M4x6)	7
4.	Harness Clamps (small)	2
5.	Harness Clamps (large)	2
6.	Relay Harness (long)	1
7.	Relay Harness (short)	1

For the installation procedure, refer to the following section of the Field Service Manual:  
2. Installation > A3/DLT LCIT > LCIT (D516) Tray Heaters

Model: Large Capacity Tray RT5060 (D516)		Date: 26-Mar-12	No.: RD516003
Subject: Part Changes (Slide Rails)		Prepared by: S. Sasaki	
From: 1st PP Tech Service Sec., PP Tech Service Dept.,			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

Please apply the following part number modifications to your Large Capacity Tray RT5060 (D516) parts catalog.

## Main Frame (D516)


Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
D5161145	D5161125	SLIDE RAIL:LEFT:1K:ASS'Y	2	O / O As a set		-	
D5161155	D5161135	SLIDE RAIL:RIGHT:1K:ASS'Y	2			-	

## Details

The part numbers of the rails for the 1k trays (Trays 3 and 5) have changed. Part number of the rails for the 2k tray (Tray 4) remains the same.

## Note

Rails for both sides of the tray must be replaced as a set. Replace [A] & [B] as a set, and [C] & [D] as a set.



Model: Large Capacity Tray RT5060 (D516)		Date: 22-May-2012	No.: RD516004
Subject: Post card fence attachment procedure		Prepared by: K. Tsutsui	
From: 1st PP Tech Service Section, PP Tech Service Dep.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

## General

Procedure for installing the auxiliary “post card” fences onto the A3/DLT LCIT (RT5060) – for feeding short edge paper stocks such as post cards– is missing in the current Taurus Users Manual.

If installation of the post card fences is requested by the customer, please provide instructions on how to install/remove the post card fences by referring to the procedure in this bulletin.


## Procedure: Installing the auxiliary “post card” fences in the LCIT (RT5060)

1. Open the front door.





Model: Large Capacity Tray RT5060 (D516)	Date: 22-May-2012	No.: RD516004
--	-------------------	---------------

2. Pull to remove the snap-fit retainer ring.



3. Lift up to clear the auxiliary post card fences from the 2 shafts.  
Remove the fences (x4) one at a time.



4. Unscrew to remove the green knob screws (x4).




Model: Large Capacity Tray RT5060 (D516)

Date: 22-May-2012

No.: RD516004


5. Check that the removed parts are as shown below.



6. Apply the short fences for Trays 3 or 5, and the long fences for Tray 4. Attachment procedures are identical for all trays. The fences are attached to Tray 3 in the following procedure.

Post card fence -REAR

Distinguish the fences by locating the cushion piece which is attached only on the REAR fence.




Post card fence -FRONT

Model: Large Capacity Tray RT5060 (D516)

Date: 22-May-2012

No.: RD516004

7. Attach the U-shaped hook to the bolt located at the bottom of the side plate (rear).



8. Fix the post card fence by aligning the boss and screwing the green knob screw.

Align the hole on the fence with the boss on the side plate.




Model: Large Capacity Tray RT5060 (D516)	Date: 22-May-2012	No.: RD516004
--	-------------------	---------------

9. Check that the post card fence is installed as shown in the photos below.



Install the opposing fence (front) similarly.



NOTE: To remove the post card fences, follow the above steps in the reverse order.

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060 (D516) / RT5030 (D452)		Date: 2-Jul-13	No.: RD453008
Subject: Broken Casters on LCIT		Prepared by: S. Sasaki	
From: 1 <sup>st</sup> PP Tech Service Sec., PP Tech Service Dept.			
Classification:	<input checked="" type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier2

## Symptom

Broken caster on the following LCITs:

RT4000 (D350), RT5040 (D453), RT5060 (D516), RT5030 (D452)



## Cause

One lot of casters was manufactured with an incorrect molding process, resulting in lower durability.

## Occurrence Rate

Extremely Low

Among 118 affected casters, 2.8% (= approx 3 pcs) may break according to factory test results.

## Action

Replace the caster (p/n: AH012050) when a unit with a broken caster is found.  
See the following page for the replacement procedure.

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060 (D516) / RT5030 (D452)	Date: 2-Jul-13	No.: RD453008
---	----------------	---------------

## Caster Replacement Procedure

**IMPORTANT:** 3 persons are required to secure working safety.

1. Remove all trays from the LCT. See the following section of the field service manual.  
LCIT RT5040, LCIT RT5060

*1. Replacement and Adjustment > Removing Trays*


LCIT RT4000

*1. Replacement and Adjustment > Common Procedures > Trays*


LCIT RT5030

*1. Replacement and adjustment > Trays*

2. Lay the LCT down so that the side to which the mainframe docks faces up.



3. Replace the broken caster with a new one. (Screw x4)



4. Put the LCT back to its normal position.
5. Install the trays into the LCT to complete the procedure.

Model: LCIT RT4000 (D350) / RT5040 (D453) / RT5060  
(D516) / RT5030 (D452)

Date: 2-Jul-13

No.: RD453008

## Serial Numbers of the Possibly Affected Units

Units with the following serial numbers may have the affected casters.

### LCIT RT5030

NA	EU/AP
V5621100001 to V5621100160	V5621100161 to V5621100175
V5621200001 to V5621200051	V5621100176 to V5621100197
V5630100015 to V5630100160	V5621200052 to V5621200085
V5630200001 to V5630200073	V5630100161 to V5630100172
V5630300001 to V5630300083	V5630200074 to V5630200113
V5630300139 to V5630300147	V5630300084 to V5630300123
	V5630300124 to V5630300138

### LCIT RT5040

NA	EU/AP
V5721100001 to V5721100019	V5721100020 to V5721100051
V5721200001 to V5721200043	V5721200044 to V5721200110
V5730100001 to V5730100116	V5730200032 to V5730200063
V5730200001 to V5730200031	V5730300051 to V5730300102
V5730300001 to V5730300050	

### LCIT RT5060

NA	EU/AP
W0121100001 to W0121100181	None
W0121100182 to W0121100207	
W0121200001 to W0121200224	
W0130100001 to W0130100178	
W0130200001 to W0130200043	
W0130300001 to W0130300113	

### LCIT RT4000

NA	EU/AP
None	M8621200056 to M8621200065
	M8630200007 to M8630200013
	M8630300001 to M8630300004

Reissued:5-Dec-13

Model: Large Capacity Tray RT5060 (D516)	Date: 6-Nov-13	No.: RD516005
--	----------------	---------------

## RTB Reissue

The items in ***bold italics*** were corrected or added.

Subject: Procedure for preventing JAM80 and Skews on LCT		Prepared by: Shinnosuke Sasaki	
From: 1st PP Tech Service Sec., PP Tech Service Dept.,			
Classification:	<input checked="" type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input type="checkbox"/> Other ( )	<input checked="" type="checkbox"/> Tier 2

## Symptom


Jam 80 or paper skew with paper longer than 423.8mm (SRA3, DLT, etc.)

## Cause

The drive and idle rollers on the LCT exit guide plate do not completely separate to release the paper for the side-to-side registration adjustment.

The above symptoms could occur with LCTs manufactured after March 2013, because these are side effects of the modification to the LCT exit guide plate in March 2013.


### Before the modification in Mar 2013



Exit Guide Plate was originally arched in the direction indicated with the arrow.

### After the modification in Mar 2013

The gap between the drive and idle rollers is insufficient and paper could get caught.



Exit Guide Plate was arched in the opposite direction for higher feed ability, but caused side effects.

## S/N of affected units

See the last pages of this bulletin.

**Reissued:5-Dec-13**

Model: Large Capacity Tray RT5060 (D516)

Date: 6-Nov-13

No.: RD516005

## Solution

The exit guide plate will be re-modified in Nov 2013.

## Request

Check the serial number to see if the LCT is affected or not on your next visit. If affected, perform the rework described below. RCL will supply the following parts/tools required for the rework free of charge.

- **D0749911: BEARING:KIT**

### **IMPORTANT: Information exclusive for Ricoh Europe**

***In addition to the s/n, check if a green dot (as shown in the photo below) is attached to the left side of the s/n label. If attached, the machine has already been reworked at RPL and therefore rework is unneeded even if the machine has an affected s/n.***



## Rework procedure for the affected units

1. Disconnect the LCT from the mainframe. Turn the LCT 90 degrees as shown and connect the I/F cable to the mainframe.



2. Turn on the main power.


**Reissued:5-Dec-13**

Model: Large Capacity Tray RT5060 (D516)

Date: 6-Nov-13


No.: RD516005

3. Follow the instructions below to replace the white plastic roller with a set of 2 ball-bearings (p/n: D0749910). Keep the front left door closed during this procedure.



Old part


New part



Replace the old part with these ball-bearings (p/n 07403903)

**How to install the bearings**

- 3-1) Align the 2 ball-bearings side-by-side and place them on top of the retraction cam. Place them to the frontmost position as shown.




**Reissued:5-Dec-13**

Model: Large Capacity Tray RT5060 (D516)

Date: 6-Nov-13


No.: RD516005

- 3-2) Insert a tool approximately 3mm wide in between the retraction arm (white part) and the ball-bearings from the bottom so that the bearings shift to the rear.




Slide in a tool with a diameter of approx 3mm, for example, a screwdriver.

- 3-3) Slightly lift up the retraction arm (white part), insert the pin and fix the pin with the E-ring.



Pin can be inserted from either right or left.

4. Insert the 300gsm paper supplied for the rework (or thickest paper in use by the customer) in the guide plate and move the paper sideways to check if the paper slides smoothly without any resistance.
- If no resistance, complete the procedure.
  - If any resistance, go to Step 5.



**Reissued:5-Dec-13**


Model: Large Capacity Tray RT5060 (D516)

Date: 6-Nov-13

No.: RD516005




5. Insert the jig (made of hard styrene foam) in the guide plate at the center, and wait for approx 30 seconds. Then, repeat the Step 4 to check the results.



Fully insert the jig until it stops.

6. If there is any resistance even after performing the previous step, insert the jig in the guide plate to the two positions shown in the photos below, and wait approx 30 seconds for each position. Repeat Step 4 to check the results.



Insert the jig in the positions corresponding to the outer edges of the rollers.  
Fully insert the jig until it stops.

7. Connect the LCT to the mainframe to complete the procedure.

**Reissued:5-Dec-13**
**Model: Large Capacity Tray RT5060 (D516)**
**Date: 6-Nov-13**
**No.: RD516005**

## Affected Serial Numbers

### RE

W0130300073	W0130300101	W0130400069	W0130500050	W0130600046	W0130600119	W0130600157
W0130300074	W0130300102	W0130400070	W0130500051	W0130600047	W0130600120	W0130600158
W0130300075	W0130300103	W0130400071	W0130500055	W0130600048	W0130600121	W0130600159
W0130300076	W0130300105	W0130400072	W0130500056	W0130600049	W0130600122	W0130600160
W0130300077	W0130300106	W0130400073	W0130500057	W0130600050	W0130600123	W0130600161
W0130300078	W0130300107	W0130400084	W0130500058	W0130600051	W0130600124	W0130600162
W0130300079	W0130300108	W0130400085	W0130500061	W0130600052	W0130600125	W0130600173
W0130300082	W0130300109	W0130400091	W0130500062	W0130600054	W0130600126	W0130600174
W0130300087	W0130300110	W0130400096	W0130500129	W0130600055	W0130600127	W0130600175
W0130300088	W0130300111	W0130500001	W0130500130	W0130600056	W0130600129	W0130600176
W0130300089	W0130300112	W0130500002	W0130500131	W0130600057	W0130600130	W0130600177
W0130300090	W0130300113	W0130500004	W0130500136	W0130600058	W0130600131	W0130600178
W0130300093	W0130400003	W0130500006	W0130500137	W0130600059	W0130600132	W0130600179
W0130300094	W0130400004	W0130500015	W0130500138	W0130600088	W0130600133	W0130600180
W0130300095	W0130400005	W0130500024	W0130500139	W0130600089	W0130600134	W0130600181
W0130300096	W0130400006	W0130500025	W0130600015	W0130600092	W0130600147	W0130600182
W0130300097	W0130400065	W0130500028	W0130600017	W0130600093	W0130600148	W0130600183
W0130300098	W0130400066	W0130500044	W0130600018	W0130600115	W0130600154	W0130600184
W0130300099	W0130400067	W0130500045	W0130600019	W0130600117	W0130600155	W0130600185
W0130300100	W0130400068	W0130500047	W0130600044	W0130600118	W0130600156	W0130600186

### RA

W0130300072	W0130400078	W0130500107	W0130600009	W0130600071
W0130300080	W0130400080	W0130500108	W0130600011	W0130600072
W0130300081	W0130400083	W0130500109	W0130600012	W0130600073
W0130300083	W0130400086	W0130500110	W0130600020	W0130600074
W0130300084	W0130400092	W0130500111	W0130600021	W0130600151
W0130300085	W0130400097	W0130500124	W0130600022	
W0130300086	W0130400104	W0130500125	W0130600023	
W0130300104	W0130500029	W0130500126	W0130600024	
W0130400001	W0130500066	W0130500127	W0130600025	
W0130400002	W0130500076	W0130500128	W0130600026	
W0130400007	W0130500077	W0130500132	W0130600027	
W0130400008	W0130500078	W0130500133	W0130600028	
W0130400010	W0130500079	W0130500134	W0130600029	
W0130400062	W0130500080	W0130500135	W0130600060	
W0130400063	W0130500099	W0130600002	W0130600064	
W0130400064	W0130500100	W0130600003	W0130600066	
W0130400074	W0130500103	W0130600005	W0130600067	
W0130400075	W0130500104	W0130600006	W0130600068	
W0130400076	W0130500105	W0130600007	W0130600069	
W0130400077	W0130500106	W0130600008	W0130600070	

**Reissued:5-Dec-13**

Model: Large Capacity Tray RT5060 (D516)	Date: 6-Nov-13	No.: RD516005
--	----------------	---------------

## RAC

W0130400009	W0130400051	W0130500019	W0130500075	W0130600041	W0130600112
W0130400011	W0130400052	W0130500020	W0130500081	W0130600042	W0130600113
W0130400012	W0130400053	W0130500021	W0130500082	W0130600043	W0130600116
W0130400013	W0130400054	W0130500022	W0130500083	W0130600045	W0130600128
W0130400014	W0130400055	W0130500023	W0130500084	W0130600053	W0130600142
W0130400015	W0130400056	W0130500026	W0130500085	W0130600061	W0130600144
W0130400016	W0130400057	W0130500027	W0130500086	W0130600062	W0130600145
W0130400017	W0130400058	W0130500030	W0130500087	W0130600063	W0130600146
W0130400018	W0130400059	W0130500031	W0130500088	W0130600065	W0130600149
W0130400019	W0130400060	W0130500032	W0130500089	W0130600075	W0130600150
W0130400020	W0130400061	W0130500033	W0130500090	W0130600076	W0130600152
W0130400021	W0130400079	W0130500034	W0130500091	W0130600077	W0130600153
W0130400022	W0130400081	W0130500035	W0130500092	W0130600078	W0130600163
W0130400023	W0130400082	W0130500036	W0130500093	W0130600079	W0130600164
W0130400024	W0130400087	W0130500037	W0130500094	W0130600080	W0130600165
W0130400025	W0130400088	W0130500038	W0130500095	W0130600081	W0130600166
W0130400026	W0130400089	W0130500039	W0130500096	W0130600082	W0130600167
W0130400027	W0130400090	W0130500040	W0130500097	W0130600083	W0130600168
W0130400028	W0130400093	W0130500041	W0130500098	W0130600084	W0130600169
W0130400029	W0130400094	W0130500042	W0130500112	W0130600085	W0130600170
W0130400031	W0130400095	W0130500043	W0130500113	W0130600086	W0130600171
W0130400032	W0130400098	W0130500046	W0130500114	W0130600087	W0130600172
W0130400033	W0130400099	W0130500048	W0130500115	W0130600090	
W0130400034	W0130400100	W0130500049	W0130500116	W0130600091	
W0130400035	W0130400101	W0130500052	W0130500117	W0130600094	
W0130400036	W0130400102	W0130500053	W0130500118	W0130600095	
W0130400037	W0130400103	W0130500054	W0130500119	W0130600096	
W0130400038	W0130500003	W0130500059	W0130500120	W0130600097	
W0130400039	W0130500005	W0130500060	W0130500121	W0130600098	
W0130400040	W0130500007	W0130500063	W0130500122	W0130600099	
W0130400041	W0130500008	W0130500064	W0130500123	W0130600100	
W0130400042	W0130500009	W0130500065	W0130600001	W0130600101	
W0130400043	W0130500010	W0130500067	W0130600004	W0130600102	
W0130400044	W0130500011	W0130500068	W0130600010	W0130600103	
W0130400045	W0130500012	W0130500069	W0130600013	W0130600106	
W0130400046	W0130500013	W0130500070	W0130600014	W0130600107	
W0130400047	W0130500014	W0130500071	W0130600016	W0130600108	
W0130400048	W0130500016	W0130500072	W0130600033	W0130600109	
W0130400049	W0130500017	W0130500073	W0130600038	W0130600110	
W0130400050	W0130500018	W0130500074	W0130600040	W0130600111	

Model: Large Capacity Tray RT5060 (D516)		Date: 17-Dec-13	No.: RD516006
Subject: Threading the screw holes for mounting the Multi Bypass Tray unit		Prepared by: Shinnosuke Sasaki	
From: 1st PP Tech Service Sec., PP Tech Service Dept.,			
Classification:	<input checked="" type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

## SYMPTOM

The joint pins for mounting the Multi Bypass Tray unit onto the LCT cannot be fixed to the docking bracket.

Below are photos of the joint pins and bracket shown in the Taurus field service manual in the section:

*2. Installation > Multi Bypass Tray (D517) > Installation > Mounting and Connecting the Bypass Unit*

### Mounting and Connecting the Bypass Unit



1. Attach the joint pins [A] and [B].


Model: Large Capacity Tray RT5060 (D516)

Date: 17-Dec-13

No.: RD516006

## CAUSE

Screw holes in the bracket are not threaded due to a fault in the manufacturing process.




## Affected Serial Numbers

See the last page of this bulletin.

## SOLUTION

- 1) Before visiting customer sites to install the Multi Bypass Tray unit, procure the following self-tapping screws (p/n: D0749912) in advance.
- 2) Check the S/N and the screw holes on the bracket to verify if the unit is affected or not.
- 3) If the unit is affected, thread the screw holes by referring to the procedure on the next page.

### D0749912: SELF TAPPING SCREW SET



**NOTE:** The self-tapping screw is supplied free of charge.

## Procedure


1. Remove the top left cover.



2. Locate the affected screw holes(s) for the joint pins and thread them by screwing in the self-tapping screws.



**IMPORTANT:** Screw in the self-tapping screw straight against the bracket, without an angle.



3. Refer to the following section of the Taurus service manual for the remaining installation procedure of the Multi Bypass Tray unit:  
*2. Installation > Multi Bypass Tray (D517) > Installation*

## Affected Serial Number List

### RAC: 97 Units

W0130500003	W0130500023	W0130500046	W0130500073	W0130500095	W0130600004
W0130500005	W0130500026	W0130500048	W0130500074	W0130500096	W0130600010
W0130500007	W0130500027	W0130500049	W0130500075	W0130500097	W0130600013
W0130500008	W0130500030	W0130500052	W0130500081	W0130500098	W0130600014
W0130500009	W0130500031	W0130500053	W0130500082	W0130500112	W0130600016
W0130500010	W0130500032	W0130500054	W0130500083	W0130500113	W0130600033
W0130500011	W0130500033	W0130500059	W0130500084	W0130500114	W0130600037
W0130500012	W0130500034	W0130500060	W0130500085	W0130500115	W0130600038
W0130500013	W0130500035	W0130500063	W0130500086	W0130500116	W0130600039
W0130500014	W0130500036	W0130500064	W0130500087	W0130500117	W0130600040
W0130500016	W0130500037	W0130500065	W0130500088	W0130500118	W0130600041
W0130500017	W0130500038	W0130500067	W0130500089	W0130500119	W0130600042
W0130500018	W0130500039	W0130500068	W0130500090	W0130500120	
W0130500019	W0130500040	W0130500069	W0130500091	W0130500121	
W0130500020	W0130500041	W0130500070	W0130500092	W0130500122	
W0130500021	W0130500042	W0130500071	W0130500093	W0130500123	
W0130500022	W0130500043	W0130500072	W0130500094	W0130600001	

### RE: 30 Units

W0130500001	W0130500050	W0130500136
W0130500002	W0130500051	W0130500137
W0130500004	W0130500055	W0130500138
W0130500006	W0130500056	W0130500139
W0130500015	W0130500057	W0130600015
W0130500024	W0130500058	W0130600017
W0130500025	W0130500061	W0130600018
W0130500028	W0130500062	W0130600019
W0130500044	W0130500129	
W0130500045	W0130500130	
W0130500047	W0130500131	

### RA: 52 Units

W0130500029	W0130500103	W0130500124	W0130600002	W0130600020	W0130600029
W0130500066	W0130500104	W0130500125	W0130600003	W0130600021	W0130600030
W0130500076	W0130500105	W0130500126	W0130600005	W0130600022	W0130600031
W0130500077	W0130500106	W0130500127	W0130600006	W0130600023	W0130600032
W0130500078	W0130500107	W0130500128	W0130600007	W0130600024	W0130600034
W0130500079	W0130500108	W0130500132	W0130600008	W0130600025	W0130600035
W0130500080	W0130500109	W0130500133	W0130600009	W0130600026	W0130600036
W0130500099	W0130500110	W0130500134	W0130600011	W0130600027	
W0130500100	W0130500111	W0130500135	W0130600012	W0130600028	