

=====
*** Basic Information ***
=====

[Create date] 2018/08/07

[Program Name] Finisher_SR4120/4130

[Version] 01.140:05

[PCB No.] D3CG5101Q,D3CH5100W

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3CH5300V

[File Information]

File Name D3CH5300V.fwu

File Type Module for Service

Size 0.50 MB (524792 byte)

[Availability of RFU] No

[Production reflection] 2018/07

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom corrected:

- JAM 156 might occur if the button to print a booklet on A3 paper is pressed while printing a booklet on A4 paper.
- If a print job on B4 paper with corner stapling is interrupted by a job on A4 paper, both jobs might stop.

[Modification history]

Version 01.130:05

Rank C

Symptom corrected:

- JAM154 or JAM155 might occur when printing a booklet on A3 paper.

Version 01.120:05

Symptom corrected:

- Paper may get caught between the paper guide and the shift tray.
- If JAM 360 (Horizontal Path Exit Sensor) occurs, the transfer motor may not stop and continue to rotate.

Version 01.110:05

Other changes:

- Minor bug correction

Version 01.100:05

Symptom corrected:

- Minor bug correction

Version 01.080:05

Symptom corrected:

- Minor bug correction

Version 01.070:05

Symptom corrected:

- Minor bug correction

Version 01.060:05

Symptom corrected:

- Staple misalignment

1. Stapled booklet gets stuck and caught by the paper detection feeler on the output tray.
2. Printing stapled booklets with a stack remained on the shift tray may cause the paper guide to interfere with the booklets.

Version 01.050:05

Symptom corrected:

- Noise is loud when the jogger retrieves home position after completing a job or during its initialization process.
- Staple misalignment occurs, if switched from shift mode to edge staple mode.

Version 01.00B:04

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2019/12/27

[Program Name] Finisher_SR4120/4130

[Version] 01.160:05

[PCB No.] D3CG5101S,D3CH5100Y

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3CH5300X

[File Information]

File Name D3CH5300X.fwu

File Type Module for Service

Size 0.50 MB (524792 byte)

[Availability of RFU] No

[Production reflection] 2020/02

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- Jam197 when printed 1260mm banner sheets on Pro C53XX.
- Output jogger malfunctions and cannot stack cleanly.

Other changes:

- Changes made to cope with the successor model

[Modification history]

Version 01.150:05

Rank C

Symptom corrected:

- Paper exiting the Corner Stapling Unit might hit the Paper Guide Unit in a job with the following conditions.
 - Corner Stapling
 - Mixed Paper Sizes
 - Z-Folding

Version 01.140:05

Rank C

Symptom corrected:

- JAM 156 might occur if the button to print a booklet on A3 paper is pressed while printing a booklet on A4 paper.
- If a print job on B4 paper with corner stapling is interrupted by a job on A4 paper, both jobs might stop.

Version 01.130:05

Rank C

Symptom corrected:

- JAM154 or JAM155 might occur when printing a booklet on A3 paper.

Version 01.120:05

Symptom corrected:

- Paper may get caught between the paper guide and the shift tray.
- If JAM 360 (Horizontal Path Exit Sensor) occurs, the transfer motor may not stop and continue to rotate.

Version 01.110:05

Other changes:

- Minor bug correction

Version 01.100:05

Symptom corrected:

- Minor bug correction

Version 01.080:05
Symptom corrected:
- Minor bug correction

Version 01.070:05
Symptom corrected:
- Minor bug correction

Version 01.060:05
Symptom corrected:
- Staple misalignment
1. Stapled booklet gets stuck and caught by the paper detection feeler on the output tray.
2. Printing stapled booklets with a stack remained on the shift tray may cause the paper guide to interfere with the booklets.

Version 01.050:05
Symptom corrected:
- Noise is loud when the jogger retrieves home position after completing a job or during its initialization process.
- Staple misalignment occurs, if switched from shift mode to edge staple mode.

Version 01.00B:04
1st Mass production