

Model: Aldebaran 2		Date:	No.: RM506004
Subject: Announcement of the packaged service parts		Prepared by: Y.Okano	
From: Sales Strategy Sect., 1st CP Business Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (      )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

This bulletin provides information on the “packaged parts” registered for TotalFlow Print Server R-61/R-61A and Prinect DFE Ver 2.0. The purpose is to make parts procurement easier without mistakes, as many of the parts for TotalFlow Print Server R-61/R-61A and Prinect DFE Ver 2.0 need to be replaced together with other parts as a set.

Description	Part Number	Q'ty
SERVICE PARTS RDTU-IF	M2728501	1
SCREW:M3X6	03603006N	4
BRACKET:RDTU:REAR	M2721001	1
BRACKET:PCI:RDTU	M2721002	1
ELECTRICAL TAPE:DP:RDTU-IF	M2726804	2
PCB:RDTU-IF	M2727000	1
LABEL:CHANNEL:A	M2731003	1
LABEL:CHANNEL:B	M2731004	1
SERVICE PARTS:SET:CPU	M2737203	1
FAN:CPU:DEL-0013-N1-GP	R0086679	1
MPU:XEON:E5-2630V2:2.6GHZ	R0106846	1
SERVICE PARTS:SET:PSU	M2737204	1
ELECTRICAL TAPE:20(W)X60(L)	M2721039	1
SERVICE PARTS:PSU:ASS'Y	M2737205	1
SERVICE PARTS:MOTHER BOARD:ALDEBARAN2	M5077200	1
ELECTRICAL TAPE:10(W)X45(L)	M2731044	1
PCB:S7053GM2NR-HE:RICOH:SERVICE	M2737106	1
USB FLASH DRIVE:DONGLE:ALD2:RIC***	M5076701	1
SERVICE PARTS: HDD: ALDEBARAN2	M5077202	1
ACCESSORY:DVD-R:RECOVERY:ALDEBARAN2	M5070880	1
HDD:DT01ACA100:1TB	RE010425	1
SERVICE PARTS:MOTHER BOARD:HDM:ALDEBARAN2	M5077203	1
ELECTRICAL TAPE:10(W)X45(L)	M2731044	1
USB FLASH DRIVE:DONGLE:ALD2:HDM***	M5076702	1
SERVICE PARTS:S7053GM2NR-HE:HDM	M5077100	1

Model: Aldebaran 2

Date:

No.: RM506004

Note: Parts indicated with the asterisks \*\*\* cannot be procured independently and must be procured in packages.

Model: Aldebaran 2		Date: 26-Apr-17	No.: RM506005
Subject: USB FLASH DRIVE:DONGLE:ALD2:HDM		Prepared by: Y.Okano	
From: Sales Strategy Sect., 1st CP Business Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (      )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

**Change:** The following USB flash drive dongle was deleted.

**Reason:** To meet requests from the field.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
M5076702	-	USB FLASH DRIVE:DONGLE:ALD2:HDM	1	-	4, 8	2	

Reissued: 28-Mar-18

Model: Aldebaran 2	Date: 26-Apr-18	No.: RM506006a
--------------------	-----------------	----------------

## RTB Reissue

The items in ***bold italics*** have been corrected or added.

Subject: MOTHER BOARD, USB FLASH DRIVE: DONGLE		Prepared by: Y.Okano	
From: Sales Strategy Sect., 1st CP Business Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other (     )	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

***This bulletin is targeted only for the Aldebaran 2 of the Ricoh model.***

**Change:** The following mother board information was changed. ***The part description for the mother board was changed to include “RICOH” to avoid confusion with the Heidelberg model.***

**Reason:** To correct information.

Wrong part number	Correct part number	New Description	Q'ty	Int	Page	Index	Note
M5077203	M5077200	SERVICE PARTS:MOTHER BOARD: <b><i>RICOH</i></b> :ALDEBARAN2	1	-	4, 8	1	

**Change:** The following USB flash drive dongle was deleted.

**Reason:** To meet requests from the field.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
M5076701	-	USB FLASH DRIVE:DONGLE:ALD2:RIC	1	-	4, 8	2	

Model: <b>Aldebaran2</b>		Date: 3-Jul-17	No.: RM506007
Subject: Security concern through the IPMI feature.		Prepared by: Hiroshi Wada	
From: PPCS Sect, PP Field Quality Management Dept.			
Classification:	<input checked="" type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input checked="" type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input type="checkbox"/> Other (      )	<input checked="" type="checkbox"/> Tier 2 <input type="checkbox"/> Tier 0.5

## SYMPTOM

Job properties and preview images for print jobs stored in the print server may be accessible from a terminal outside the customer's LAN.

**Affected models: Ricoh model (R-61/R-61A) only.**

**Leo-C1/P1 (TotalFlow Print Server R-61A),  
Andromeda-P1 (TotalFlow Print Server R-61)**

## CAUSE

By default, it's possible to access the local console screen through the motherboard's **IPMI** (Intelligent Platform Management Interface) feature without authentication. As a result, an external access point can use this feature to access this screen via the LAN.

### Note:

- This local console screen is normally displayed using the R-61/R-61A's onboard video board.
- This does not occur on the Heidelberg Model (Prinect DFE) because this model uses an additional video board for Windows VM, and the local console is disabled. As a result, the screen for this additional video board cannot be displayed using the IPMI feature.

## SOLUTION

### Production line

Disable the motherboard's **IPMI** (Intelligent Platform Management Interface) feature.

Cut-in S/N for Ricoh (R-61/R-61A) models: **TBA**

### In the field

Do the **PROCEDURE** below to prevent unauthenticated external access.

Model: Aldebaran2


Date: 3-Jul-17

No.: RM506007

## PROCEDURE

1. Launch the web browser on the client computer.
2. Access the following: [http://\(IP address or host name of the print server\)/](http://(IP address or host name of the print server)/)
3. Log in to the remote console with **Administrator** or **Service** level credentials.
4. Set the following to “**Yes**”.  
[Configuration] > [Security] > [Basic] > [Authentication required for local console] = **Yes**

Basic


Settings that control access to the printer.

Authentication required to submit jobs

No

Default role for authenticated users

No access

Authentication required for local console

No

Default local console user

Administrator

Job data in traces

Allowed

OK

Cancel