Technical Bulletin

PAGE: 1/1

Model: Trimmer Unit TR5040 (D520) Date: 14-Jul-11 No.: RD520001

Subject: Firmwar	e Release Note: Trimmer Unit	Prepared	d by: K.Tsutsui	
From: PPBG Service Planning Dept.				
Classification:	Troubleshooting	Part information	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other (Firmv	vare)	☐ Tier 2

This RTB has been issued to announce the firmware release information for the **Trimmer_Unit.**

Version	Program No.	Effective Date
01.070:05	D5205510	1st Mass production

Version	Modified Points or Symptom Corrected
01.070:05	1st Mass production

Technical Bulletin

PAGE: 1/4

Model: Trimmer Unit TR5020 (D455) Dat					t-11	No.: RD455005
Subject: Adjustment of the trim volume					d by: T. K	Komori
From: PP Service						
Classification:	Troubleshooting	⊠ Part inf	orma	tion	☐ Action	required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path ☐ Transmit/r			eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Change: Addition of a part

Reason: To adjust the trim volume

New Part Number	Description		Page	Index	Note
D4551350	HOLDER:SENSOR:YZ4-08407218	1	13	8	Add

There are two ways to calibrate the trim volume as follows.

#1 Shifting the current sensor bracket


#2 Replacing the current sensor bracket with the "modified" sensor bracket Please try method#1 first. If this cannot solve the problem, please do #2.

NOTE

The blade could be damaged if the trim volume is set too low.
 Please inform your customers that the adjustment on the operation panel must be made carefully to avoid poor cuts after replacing with the modified bracket.

Method #1 Shifting the current sensor bracket

1. Turn off the machine, and disconnect the cable.



2. Remove the covers as shown in the diagram.




Technical Bulletin

PAGE: 2/4

No.: RD455005

Model: Trimmer Unit TR5020 (D455)



3. Identify the sensor.



4. Move the bracket in the direction of the arrow (decrease in trim volume). Check the trim volume.

NOTE

DO NOT shift the sensor bracket in the opposite direction (increase in trim volume) as this may cause damage to the machine due to interference with the registration unit.

5. Reassemble the unit when the desired volume is obtained. If not satisfy the customer's demand, please go method #2.



Technical Bulletin

PAGE: 3/4

Method#2 Replacing the current sensor bracket with the "modified" sensor bracket



- 1. Mark the bracket position. Place a mark at the position shown below by scoring the surface of the plate with a tool as shown in the photo.
- 2. Unfasten the screw and remove the sensor with the bracket.




3. Reattach the sensor to the modified bracket, **D4551350**.



Technical Bulletin

PAGE: 4/4



- Install the modified sensor bracket.
 Shift the bracket sideways according to the desired adjustment using the marked line for guidance.
- 5. Check the trim volume.
- 6. Reassemble the unit when the desired volume is obtained.

Technical Bulletin

PAGE: 1/2

Model: Trimmer Unit TR5040 D				lar-17	No.: RD5200002
Subject: FSM corr	ection: How to enable Limit	Prepared I	by: J. Ohno		
From: 1st Tech Se	rvice Sect., PP Tech Servic				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	Part inform Electrical Transmit/re Other (☐ Action red ☐ Service n ☐ Retrofit in ☐ Tier 2	nanual revision

Please correct the following procedure in the Trimmer Unit TR5040 FSM, in this section:

2. Details > Operation > Operation Flow > Limitless Output


Incorrect:

Limitless Output

The trimmer can be set up for limitless output.



1. First, remove the end stopper from the output tray.



- 2. Next, disable booklet sensor 3. This requires a service call by a trained service technician to disconnect the sensor.
 - With booklet sensor 3 disabled, the trimmer will not detect tray full.
 - The trimmer will operate continuously without interruption. The booklets will fall off the end of the tray into a container placed at the end of the tray.

Technical Bulletin

PAGE: 2/2

Model: Trimmer Unit TR5040 Date: 09-Mar-17 No.: RD5200002

Correct:

Limitless Output

The trimmer can be set up for limitless output.



Remove the end stopper from the output tray. This will automatically disable the output tray full sensor (Booklet Sensor 3) and enable "Limitless Output."

Classification:

Model: Trimmer Unit TR5040

Technical Bulletin

	Dat	e: 11-Jan-18		No.: RD520003	
		Prepared b	y: Rie	Shohda	
pt.					
□ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inferen	ormat	ion	Action	required	
☐ Electric		☐ Service manual revision			
☐ Transmit/receive] Retro	fit information	

☐ Tier 2

PAGE: 1/1

Old part number	New part number	Description		Int	Page	Index	Note
-	D4551286	SHAFT:RELEASE:YZ3-08407011	1	-	25	11	Add

Other (

Change: Addition of the part

Reason: To meet requests from the field.


Subject: Parts information - SHAFT:RELEASE From: Sales Strategy Sect., 1st CP Business Dept.

☐ Troubleshooting

☐ Paper path

☐ Product Safety





Technical Bulletin


PAGE: 1/1

Model: Trimmer	Unit TR5040	ct-19	No.: RD520004		
Subject: Parts info	Prepared	by: S. Tomoe			
From: Service Pla	nning Sect., Global Engir	rt Dept.			
Classification:	Classification: Troubleshooting Mechanical		nation eceive)	☐ Action re☐ Service n☐ Retrofit ir☐ Tier 2	nanual revision

The following part are registered as new service parts to meet requests received from the field.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	D4551176	STOPPER:ENTRANCE:YZ4-08405302	1	-	7	7	Add

3.Paper Feed Unit 2 (D520)




Technical Bulletin

PAGE: 1/1

Model: Trimmer Unit TR5040 (D520) Dat				te: 8-Oct-	19	No.: RD520005
Subject: Parts in	formation - Paper Exit Section		Prepared	d by: S.T	omoe	
From: 1st Tech S	ervice Sect., MFP/P Tech Service	vice Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part info ☐ Electrica ☐ Transmi ☐ Other (al		Servic	required e manual revision it information

The following part are registered as new service parts to meet requests received from the field.

Old part	New part	Description Q		Int	Page	Index	Note
number	number						
-	D4551272	BRACKET:FRONT:YZ3-08407005	1	-	27	21	Add
-	D4551278	SHAFT:ROLLER:FRONT:Z4-08407008	1	-	27	22	Add



Technical Bulletin

PAGE: 1/1

Model: Trimmer Unit TR5040 (D520) Da					v-19	No.: RD520006			
Subject: Parts information - shaft					Prepared by: S.Tomoe				
From: Service Planning Sect., Global Engineering Support									
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	□ Part info □ Electrica □ Transm □ Other (al		Servic	required e manual revision it information			

The following part are registered as new service parts to meet requests received from the field.

This information was also provided by the PCIL issued on July 2014.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	D4551268	SHAFT:YZ3-08407001	1	-	27	20	Add

