Classification:

Technical Bulletin

PAGE: 1/1

☐ Action required

☐ Service manual revision

☐ Retrofit information

Reissued: 7-Apr-05

☐ Troubleshooting

☐ Paper path

Other (

Model: Model K-P4	Date: 17	-Feb-05	No.: RG116001a
RTB Reissue			
The items in bold italics have been added.			
Subject: Controller Firmware Release History (System)	Prep	pared by: A. I	shiyama
From: 1st Tech. Support Sec. Service Support Dept.			

☐ Part information

☐ Transmit/receive

☐ Electrical

This RTB has been issued to announce the firmware history for the System of the Model K-P4 (G116 model).

Version	Program No.	C. SUM	Effective Date
1.03	G1165430B	B52D	April '05 production
1.01	G1165430A	F297	1st mass production (Jan 2005)

Descriptions of changes

Dooon pur	on on angeo
Version	Symptom Corrected
1.03	(Minor change applied for the Japan model only).
1.01	1st Mass Production

Technical Bulletin

PAGE: 1/1

Reissued: 29-Jun-05

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002b
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

The items in bold italies have been added.					
Subject: Controller Firmware Release History (Printer)		Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informate ☐ Electrical ☐ Transmit/rec	Service manual revision		
	_ ` '				

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	C. SUM	Effective Date
1.04.2	G1165441C	1AFF	July '05 production
1.03	G1165441B	5703	April '05 production
1.01	G1165441A	D99C	1st mass production (Jan 2005)

Version	Symptom Corrected
1.04.2	 Sometimes, the keys on the operation panel do not work when the machine is in the Toner End condition. Sometimes, the machine stalls when a duplex job is sent from an RPCS driver and then the job is cancelled.
	Other changes:
	3. Some features of a customization were added as standard: - The IP address is displayed on the LCD.
	- The iP address is displayed on the ECD Thai and non-English Latin characters can be printed with the PS driver
	Important: To use these new features, you need to install all of the following firmware together as a set.
	System v1.04 or later (P/N #G1165430C)
	Printer v1.04.2 or later (P/N #G1165441C) Websys v1.02 or later (P/N #G1165433B)
1.03	No changes (version standardization with System firmware only).
1.01	1st Mass Production

Technical Bulletin

PAGE: 1/1

Reissued: 29-Jun-05

Model: Model K-P4 Date: 17-Feb-05 No.: RG116003a	B 1 1 N
--	-----------

RTB Reissue

The items in bold italics have been added

THE ITEMS IT DOID ITAILS HAVE DEEN AUGEU.					
Subject: Controller Firmware Release History (NCS)		Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☒ Other ()	☐ Part informat		☐ Action required ☐ Service manual revision ☐ Retrofit information	

This RTB has been issued to announce the firmware release information for the NCS.

Version	Program No.	C. SUM	Effective Date
4.14.1	G1165432B	A964	July '05 production
4.08.1	G1165432A	12A6	1st mass production (Jan 2005)

Version	Symptom Corrected
4.14.1	 If the paper type setting is changed with WIM while "Permit Settings by SNMPv1 and v2" is disabled, the browser will timeout. The paper type setting change will not be saved. SNMPv1/v2 will still send SNMP traps even if the SNMPv1/v2 function is disabled. Sometimes after a power cycle, the device will be unable to accept jobs from standard TCP/IP or SDM ports. The SNMP buffer may become full when a lot of SNMP traffic is sent to the device. As a result, the device cannot reply to SNMP requests. SDM for Admin cannot retrieve 1394 hostnames and devices when it is installed on a client PC with 1394 and Ethernet interfaces. The SNMP service may not start when the device is turned on. Utilities using SNMP do not receive status updates from the device. Other changes: Some features of a customization were added as standard: The device can accept more than one diprint (port9100) session. Communication via diprint (port 9100) is asynchronous.
4.08.1	1st Mass Production



PAGE: 1/1

Reissued:21-Apr-06

Model: Model K-P4	Date: 21-Apr-06	No.: RG116004b
Model. Model K-F4	Date. 21-Apr-00	110 KG 1 100040

RTB Reissue

The items in **bold italics** have been added.

Subject: Controller Firm	5 1 111 / 4			
Subject: Controller Firmware Release History (Websys)			Prepared by: H. Saitoh	
From: 1st Tech. Support Sec. Service Support Dept.				
□ Ме	oubleshooting chanical per path ner ()	☐ Part informate ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information

This RTB has been issued to announce the firmware release information for the Websys.

Version	Program No.	C. SUM	Effective Date
1.02	G1165433B	E686	July '05 production
1.00	G1165433A	9274	1st mass production (Jan 2005)

Version	Symptom Corrected
1.02	Note: Websys firmware Ver 1.02 or later must be used with System firmware v1.04 or later and Printer firmware v1.04.2 or later and NCS firmware v4.14.1 or later. System v1.04 (P/N #G1165430C) or later Printer v1.04.2 (P/N #G1165441C) or later NCS v4.14.1 (P/N #G1165432B) or later Websys v1.02 or later (P/N #G1165433B)
	The following features from a customization were added to WIM as standard:
	 Display IP Address on the Display Panel: The device's IP address is displayed on the LCD. (Sp5-055-001; [Configuration – Device Settings – System]) Permit ROM Update: Allows the ROM firmware to be updated remotely via the local network. (Sp5-886-001; [Configuration – ROM Update]
1.00	1st Mass Production

Technical Bulletin

PAGE: 1/1

Reissued: 30-Nov-05

Model: Model K-P4 Date: 17-Feb-05 No.: RG116005a	Model: Medel K D4	No : PC1160052
--	-------------------	----------------

RTB Reissue

The items in bold italics have been added.

ne teme in bold tailed have been added.					
Subject: Firmware Release History (Netfile)			Prepared by: A. Ishiyama		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path	☐ Part information ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information	
	Other ()				

This RTB has been issued to announce the firmware release information for the Netfile.

Version	Program No.	Effective Date
1.00	G1165435B	November '05 production
0.25	G1165435A	1st mass production (Jan 2005)

Version	Symptom Corrected
1.00	The following operations may not be completed if two or more PCs access the printer at the same time: - Configuring the device with the "User Management Tool" of SDM for Admin Printing to an SDM port.
0.25	1st Mass Production

	ПП
(G(I)	吅

D	Λ	C	┏.	4	14
Г.	м	J	E:	- 1	<i>,</i> ,

Model: Model K-P4 Dat			e: 17-Feb-05 No.: RG11600		No.: RG116006	
Subject: Firmware Release History (Font)			Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	Troubleshooting	☐ Part informat		tion		required
		☐ Electrical			☐ Servic	ce manual revision
	☐ Paper path	☐ Transmit/rece		eive	☐ Retrof	fit information
	⊠ Other ()					

This RTB has been issued to announce the firmware release information for the Font.

Ī	Version	Program No.	C. SUM	Effective Date
	1.01	G1165444A	21F7	1st mass production (Jan 2005)

Version	Symptom Corrected	
1.01	1st Mass Production	

Technical Bulletin

PAGE: 1/1

Reissued: 30-Nov-05

Model: Model K-P4 Date: 17-Feb-05 No.: RG116007a	Model: Model K-P4	Date: 17-Feb-05	No.: RG116007a
--	-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

The terms in bold italies have been added.						
Subject: Firmware Release History (Engine)			Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part information ☐ Electrical ☐ Transmit/rec	Service manual revision			

This RTB has been issued to announce the firmware release information for the Engine.


Version	Program No.	Effective Date
1.03:20	G1115136C	November 2005 production
1.02:20	G1115136B	1st mass production (Jan 2005)

Version		Symptom Corrected					
1.03:20	SP5930-2	was added to Meter Charge Mode:					
	5930	Meter charge mode					
	5930 1	No, Yes Enables or disables meter-charge mode.					
	5930 2	No, Yes Displays or does not display "Replace Maintenance Kit"					
		Important: Turn the main switch off/on after changing this setting.					
		Meter charge mode disabled (Default):					
		 The meter charge counter is not shown when the Menu key is pressed. The PM counter resets automatically after the user replaces the fusing unit. 					
		 Regardless of setting of SP5930 2, the machine displays "Replace Maintenance Kit" (the user replaces the maintenance kit items). Meter charge mode enabled: 					
	The meter charge counter is shown immediately after the Menu key is pressed.						
		 The technician must reset the PM counter after finishing PM. Display of "Replace Maintenance Kit" (SP5930 2): 					
		When enabling meter charge mode, you can select display/not display of "Replace Maintenance Kit" by SP5930 2.					
		If it is set to "Yes", "Replace Maintenance Kit" is displayed on the operation panel when the PM counter runs out.					
	 If it is set to "No", "Replace Maintenance Kit" is not displayed on the operation panel when the PM counter runs out. 						
	firmware t Systen Printer	To use the above new feature, you need to install all of the following together as a set. n v1.05 or later (P/N #G1165430D) v1.05 or later (P/N #G1165441D					
1.02:20	1st Mass F	v1.03:20 or later (P/N #G1115136C)					
1.02:20	TST IVIASS F	roduction					

Model: Model K-P4			Dat	Date: 25-Mar-05		No.: RG116008
Subject: Right Cover			Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting	ooting Part informa		ation		required
	☐ Mechanical ☐ Electrical		Service manual rev		ce manual revision	
	☐ Paper path ☐ Transmit/red		ransmit/receive		fit information	
	Other ()					

The procedure below was changed from the beginning of mass production: One screw (x 1) was added to the step for removing the right cover. See the **bold**, underlined area.

3.3.6 EXTERIOR COVERS [G116] To remove the left or right cover, separate the machine from the optional paper tray unit first. Open the front cover. [C] [B] [A] G091R703.WMF G091R702.WMF [A]: Left cover (x 2) [B]: Front cover (3 clamps, 2 harnesses) [C]: Right cover (3 hooks and F x 1)



One screw was added

PAGE: 1/2

Reissued: 21-Jun-07

Model: Model K-P4	Date: 25-Mar-05	No.: RG116009a
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics were added or changed, and some items were deleted

The Reme in Dera realise were daded or enanged, and come Reme were deleted.						
Subject: Bypass Tray Paper Pick-up Mechanism			Prepared by: Y.Yoshida			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informa ☐ Electrical ☐ Transmit/rec	Service manual revision			


Important Note on the Bypass Feed Mechanism

The paper feed mechanism for the bypass tray was *permanently changed* to a solenoid system. *This is to ensure high reliability of the paper feed mechanism.*

Note:

- This is the same solenoid system that is used on the C-P1/K-P3.
- See MB MG116005 for the P/N details.

Solenoid System: Same as the C-P1/K-P3 system



- [A] Bypass feed gear
- [B] Solenoid
- [C] Bypass feed roller




PAGE: 2/2

Reissued: 21-Jun-07

Model: Model K-P4 Date: 25-Mar-05 No.: RG116009a

Clutch System: Originally designed for the C-P2/K-P4



- [A] Bypass feed clutch
- [B] Stopper
- [C] Bypass feed roller

	ጠ	ПП
மு	w	屸

Technical Bulletin

116010
revision
ion

PAGE: 1/1

Important Note: Blank NVRAM Service Parts

Mechanical ☐ Paper path Other (

When you replace the controller NVRAM in the field, use the part shown below. This part is already listed in the Parts Catalog.

Model	Part No.	Description	IC No.	Product Code	Parts Catalog Information	
				Code	Page	Index
K-P1	14075335	RAM - STK12C68-P55	IC27	G056/G058	27, 29	119
K-P2	14075497	497 RAM – FM1808-120-P		G073	27, 29	124
K-FZ	14075497 RAM - FM1808-120-P	IC54	G074	31, 33	121	
K-P3	14075856	RAM - FM18L08-70-P	IC68	G091	29, 35	126
K-P4	14076465	RAM:FM25L256-PG(REV.AG)	IC5	G116	40, 45	130
C-P1	14075856	856 RAM - FM18L08-70-P		G094	31, 37	122
C-F I	C-P1 140/5856 RAM - FM18L08-/0-P	RAIN - FINITOLUO-70-P	IC68	G095	41, 47	126
C-P2b	14075856	RAM - FM18L08-70-P	IC68	G112	53, 57	121
C-P2c	14076465	RAM:FM25L256-PG(REV.AG)	IC5	G113	60, 65	130

- This is **completely blank** NVRAM. When you get this part from the Parts Center, it does not have a value of "0".
- After you install this NVRAM and turn the power OFF/ON, the machine will put a value of "0" inside the NVRAM.

IMPORTANT: When you install this NVRAM, make sure it is a completely new service part. DO NOT install the NVRAM if it was already used. If you do, machine problems can occur.

Technical Bulletin

PAGE: 1/15

Reissued: 15-Apr-05

Model: General RTB	Date: 15-Nov-04	No.: RGene019a
--------------------	-----------------	----------------

RTB Correction

The items in bold italics have been corrected or added.

Subject: Remote Firmware Update			Prepared by: H. Someya		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	Troubleshooting	☐ Part informat	tion	Action required	
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	⊠ Other ()				

1. OVERVIEW

The remote firmware update function (referred to as RFU) is used to update the firmware remotely. Service representatives do this over the network. Note that this information is intended for service representatives only and not for end users.

2. SUPPORTED MODELS AND FIRMWARE

The models supporting RFU and the types of firmware that can be updated are shown in Fig. 1:

"04A": Autumn 2004

Printers

Model	Group	System	Network	WebSys	Printer	Engine
Model J-P2	Before 04A	OK	OK		OK	OK
Model J-P2CF	Before 04A	OK	OK		OK	OK
Model K-P3	Before 04A	OK	OK	OK	OK	OK
Model C-P1	Before 04A			OK	OK	OK
Model J-P3	Before 04A	OK	OK	OK	OK	OK
Model PL-P1	Before 04A	OK	OK	OK	OK	NG
Model G-P1	04A and later	ок	ОК	ок	ок	ок
Model C-P2	04A and later	ок	ОК	ок	ОК	ОК
Model K-P4	04A and later	ок	ОК	ок	ОК	ОК

MFPs

Model	Group	System	Network	WebSys	Printer	PS	Engine
Model A-C3e/f	Before 04A	OK	OK	OK	OK	OK	OK
Model R-C3	Before 04A	OK	OK	OK	OK	OK	OK
Model K-C2	Before 04A	OK	OK	OK	OK	OK	OK
Model S-C2	Before 04A	OK	OK	OK	OK	OK	OK
Model B-C2e	Before 04A	OK	OK	OK	OK	OK	OK
Model J-C1	Before 04A	OK	OK	OK	OK	OK	OK
Model MT-C2	04A and later	OK	ок	ОК	ОК	ОК	ОК

Fig. 1 Models supporting RFU

OK: Remote firmware update via the network is possible.

NG: Remote firmware update via the network is not possible.

Reissued: 15-Apr-05

Technical Bulletin

UIIETIN PAGE: 2/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

The following models do not support RFU:

Printers:

Model K-P1/P2, Model J-P1, Model A-P3, Model U-P1, Model AR-P1, and not GW products

MFPs:

Model A-C2/C3, Model R-C2, Model U-C1, Model MT-C1, and not GW products

3. SYSTEM REQUIREMENTS

Network Interface:

- 10 Base-T or faster Ethernet LAN
- IEEE1284 (Centronics) (A setting must be changed in SP mode.)

Note: IEEE1284 does not support error recovery after a power loss.

For Recovery Mode:

 10 Base-T or faster Ethernet LAN – the note above says that only 1284 doesn't support it.

Protocols:

For RFU Mode & Recovery Mode:

• FTP (The port must be open)

Operating System:

- Windows Server 2003
- Windows XP
- Windows 2000
- Windows NT 4.0
- Windows 9x/Me
- Mac OS
- UNIX/Linux (Any version)

Note: RFU is available for any OS from which FTP is possible.

Unsupported environments:

- IPP
- SMB over TCP/IP
- Direct port
- AutoNet (169.254.x.x) with DHCP

Reissued: 15-Apr-05

Technical Bulletin

PAGE: 3/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

Ftp settings and commands:

• User name (default):

Before 04A: rsysupdate

> 04A and later: admin

Password (default):

> Before 04A: password

> 04A and later: (no password)

Note: These default passwords are the same as the administrator passwords.

- Transfer mode: binary
- FTP commands supported:
 - binary (Transfer data in binary mode)
 - dir (List files and directories)
 - > put "file name"
 - get version.txt (Obtain the version.txt file and display its contents.)
 - get errlog.txt (Obtain the errlog.txt file and display its contents.)

4. STATUS OF UNUPDATEABLE MACHINE

If the printer is in any of the following statuses, RFU will not work.

- Print job in progress (copier, printer, fax, network)
- Scan job in progress (copier, scanner, fax)
- Receiving a print image from the network
- Operation panel is in use
- Incoming/Outgoing fax message
- SC condition

You can check the status of the target machine using WebImageMonitor or SmartDeviceMonitor.



PAGE: 4/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

5. UPDATING PROCEDURE

Recommendation:

It is strongly recommended that RFU be performed on-site, to minimize the chances of a power-down during RFU.

5.1 Auto Rebooting

After receiving new firmware, the machine firmware is updated and the machine is automatically rebooted using the updated firmware. Fig.2 shows the kind of reboot required after the firmware is updated.

Printers

Model	System	Network	WebSys	Printer	Engine
Model J-P2	Auto	Auto		Auto	Auto
Model J-P2CF	Auto	Auto		Auto	Auto
Model K-P3	Αι	uto	Auto	Auto	Auto
Model C-P1	Auto		Auto	Auto	Auto
Model J-P3	Auto	Auto	Auto	Auto	Auto
Model PL-P1	Auto	Auto	Auto	Auto	N/A
Model G-P1	Auto	Auto	Auto	Auto	Auto
Model C-P2	Auto	Auto	Auto	Auto	Auto
Model K-P4	Auto	Auto	Auto	Auto	Auto

MFPs

Model	System	Network	WebSys	Printer	PS	Engine
Model A-C3e/f	Auto	Auto	Auto	Auto	Auto	Manual
Model R-C3	Auto	Auto	Auto	Auto	Auto	Manual
Model K-C2	Auto	Auto	Auto	Auto	Auto	Auto
Model S-C2	Auto	Auto	Auto	Auto	Auto	Auto
Model B-C2e	Auto	Auto	Auto	Auto	Auto	Auto
Model J-C1	Auto	Auto	Auto	Auto	Auto	Auto
Model MT-C2	Auto	Auto	Auto	Auto	Auto	Auto

Fig. 2 Reboot Method

Auto: Automatically rebooted after updating the firmware.

Manual: The machine must be manually rebooted after updating the firmware.



PAGE: 5/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

5.2 Preparation

Before you update the firmware by RFU, carry out three items as shown below.

5.2.1 Checking the IP address

For a machine with static IP address:

- Search for the IP address using SmartDeviceMonitor for Admin or Web
- SmartDeviceMonitor.
- If the hostname of the machine is registered in a DNS server, use the nslookup command with the machines hostname. This can also be used for dynamic IP addresses if you are using DDNS.
- If the computer name of the machine is registered in a WINS server use the <......> command.

For a machine with a dynamic IP address:

- Print the config sheet or the SMC for the machine.
- Check the IP address in the DHCP server.

5.2.2 Firmware

 Please download firmware (*.rru or *.rfu files) from our support site and store it in a folder on a local PC to be used for RFU.

5.2.3 Checking the machine status

 Please check the status of the target machine using WebImageMonitor or SmartDeviceMonitor.

PAGE: 6/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

5.3 RFU for Windows

- 1. Open a command prompt.
 - o [Start]-[Program]-[Accessories]-[Command Prompt]
- 2. Logon to the machine using ftp.

```
C: > ftp xxx.xxx.xxx

Specify the machine's IP address

Connected to xxx.xxx.xxx.

220 (Product name) FTP server (1.00)ready.

User (IP address:(none)):
```

3. Enter the user name.

```
User (IP address:(none)):rsysupdate

331 Password required for rsysupdate.

Password:
```

4. Enter the password.

```
Password: XXXXXX

230 User rsysupdate logged in. Login successful.

ftp>
```

5. Enter "dir" to check that version.txt exists.

```
ftp> dir

200 PORT command successful.

150 Opening ASCII mode data connection for '/'.

-r--r--r-oot root 200 Jan 1 01:08 help

-r--r--r-oot root 200 Jan 1 01:08 info

-r--r--r-oot root 200 Jan 1 01:08 install

-r--r--r-oot root 200 Jan 1 01:08 prnlog

-r--r--r-oot root 200 Jan 1 01:08 stat

-r--r--r-oot root 200 Jan 1 01:08 syslog

-r--r--r-oot root 200 Jan 1 01:08 version.txt

-r--r--r-oot root 200 Jan 1 01:08 errlog.txt

226 Transfer complete.

ftp:372 bytes received in n.nn Seconds n.nn Kbytes/sec.

ftp>
```



PAGE: 7/15

Model: General RTB	Date: 15-Nov-04	No.: RGene019a
--------------------	-----------------	----------------

6. Enter "get version.txt -" to check the machine's firmware version.

200 PORT command successful.						
150 Opening ASCII mode data connection for 'version.txt'.						
PartNo.	Module Name	Version	Module ID			
G0000000	os & copy	0.20	XXXXXX_copy			
G0000000	os & pf	0.20	XXXXXX_system			
G570xxxx	Onboard Scn	2.04	XXXXXX_scn			
G5705387A	OptDIMM Fax	1.07	XXXXXX_fax			
G5700000	printer	0.19	XXXXXX_printer			
G5705383D	Network DocBox	2.00	XXXXXX_netfile			
G0805920A	Network	0.71	XXXXXX_net			
G0805601	ENGINE	R0.14:06	XXXXXX_eplot			
226 Transfer comp	226 Transfer complete.					
ftp>						

7. Enter "binary" to set the file transfer mode to binary.

```
ftp> binary
200 Type set to I.
ftp>
```

- 8. Navigate to the directory on your PC containing the file xxx.rru.
- 9. Transmit the firmware module file (*.rru or *.rfu) using the "put" command.

```
ftp> put xxx.rru

200 PORT command successful.

150 Opening BINARY mode data connection for 'xxx.rru'.

226 Transfer complete.

ftp:nnnnnn bytes sent in s.ss Seconds pp.pp Kbytes/sec.

ftp>
```


Note: Do not turn off the power of the machine while updating the firmware.

PAGE: 8/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

When the machine starts to receive the file, the following message appears on the machine's control panel and normal machine functions are disabled.

Display panel (MFPs)




o Display (Printers)

ROM Update Receiving Data

10. Once the machine has received the entire firmware module file, the firmware update starts automatically.

The following message appears:

Display panel (MFPs)



o Display (Printers)

Updating

Note: If the controller firmware is being updated, this message is displayed in English only.

Reissued: 15-Apr-05

Model: General RTB

Technical Bulletin

Date: 15-Nov-04 No.: RGene019a

PAGE: 9/15

- 11. After the firmware has been updated, the machine must restart. This may be automatic depending on the firmware and model.
- 12. Enter "bye" to exit ftp.

ftp> bye
C:∖>

- 13. Check the firmware version as shown in step 6.
- 14. Update all required firmware by repeating steps 1 to 13 as necessary.

5.4 RFU for UNIX(LINUX)

1. Logon to the machine using ftp.

host% ftp "ip address"

User ("ip address"): User Name (for Administrator)

230 User xxxx logged in.

331 Password required for rsysupdate.

Password: Password (for Administrator)

230 User xxxx logged in.

Connected to "ip address"

Remote system type is UNIX.

Using binary mode to transfer files.

2. Change to binary mode.

ftp> binary
200 Type set to I.

3. Send the firmware data (*.rru or *.rfu) to the machine.

ftp> put "File Name of Firmware"

200 PORT command successful.

150 Opening BINARY mode data connection for "File Name of Firmware".

226 Transfer complete.

ftp: nnnnnn bytes sent in s.ss Seconds pp.p Kbytes/sec.

ftp>

4. Close the ftp session.

ftp> bye
host%

Reissued: 15-Apr-05

Technical Bulletin

Chnical Bulletin Page: 10/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

5.5 Firmware Update for Centronics (IEEE1284)

Note:

- Firmware update via a centronics interface does not require a password.
- The only method of recovery available via a centronics interface is an IC or SD card.
- 1. Check the target firmware version by printing out the SMC sheet with SP5-990-4.
- 2. Set SP5-856-2 to a value of **1**. This will configure the machine for firmware update via the Centronics I/F.
- 3. Send the firmware to the target machine with the copy command.

C:\>copy/b "file name"

- 4. Cycle the machine's power (off then on).
- 5. Confirm the firmware version as shown in step 1.
- 6. Update all required firmware by repeating steps 1 to 5 as necessary.

PAGE: 11/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

5.6 Checking the Result of the Update

Check that the firmware has been updated.

Note:

- After transmitting the firmware file from the computer, it takes approximately 3 to 5 minutes for updating to complete and the machine to restart.
- To check the result, you need to logon to the machine again using ftp. However, you cannot log on during the update process, so you are unable to check that the update has completed until the machine has restarted.

If the update was successful

• Once the firmware has been updated successfully, the system automatically restarts using the new firmware.

After the restart, verify that the firmware has been updated to the new version. Check that the error code in the error data file (errlog.txt) is "0" by performing procedure 7.1 "Checking the error status" (below).


If an error occurs

• If an error occurs during the update, the system automatically restarts, the message shown below appears, and the machine waits to receive the firmware file again. If the update is interrupted by a power failure, the same thing happens once the power is restored.

Log on to the machine again using ftp and then resend the firmware file to the machine.

The following message appears for Type 1 firmware:

Display panel (MFPs)



Display (Printers)

Reissued: 15-Apr-05

Technical Bulletin

Chnical **B**ulletin Page: 12/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

6. ERROR RECOVERY

There are three ways to recover from a loss of power during RFU.

6.1 Recovery Procedure

There are three types for recovery after a power loss during RFU. (This will depend on the firmware and model). Procedures for types 1, 2 and 3 are on the next page.

Find the firmware and model you are downloading to, and <u>begin with the type</u> shown in the table below.

Recommendation:

As mentioned in *5. Updating Procedure*, it is strongly recommended that RFU be performed on-site, to minimize the chances of a power-down during RFU.

Printers

Model	System	Network	WebSys	Printer	Engine	Card Type
Model J-P2	Type1	Type1		Type1	Type1	IC
Model J-P2CF	Type1	Type1		Type1	Type1	IC
Model K-P3	Ту	pe1	Type1	Type1	Type1	IC
Model C-P1	Type1		Type1	Type1	Type1	IC
Model J-P3	Type1	Type3	Type3	Type3	Type1	SD
Model PL-P1	Type1	Type1	Type1	Type1	N/A	SD
Model G-P1	Type1	Type1	Type1	Type1	Type1	SD
Model C-P2	Type1	Type1	Type1	Type1	Type1	SD
Model K-P4	Type1	Type1	Type1	Type1	Type1	SD

MFPs

Model	System	Network	WebSys	Printer	PS	Engine	Card Type
Model A-C3e/f	Type2	Type2	Type2	Type2	Type2	Type1	IC
Model R-C3	Type2	Type2	Type2	Type2	Type2	Type1	IC
Model K-C2	Type1	Type1	Type1	Type3	Type3	Type3	SD
Model S-C2	Type1	Type1	Type1	Type3	Type3	Type1	SD
Model B-C2e	Type2	Type2	Type2	Type3	Type3	Type3	SD
Model J-C1	Type1	Type1	Type1	Type3	Type3	Type1	SD
Model MT-C2	Type2	Type2	Type1	Type1	Type1	Type1	SD

Fig. 3 Recovery Method

Reissued: 15-Apr-05

Technical Bulletin

PAGE: 13/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

Important: Do not turn the main power off while you perform any of the procedures.

Procedure for type 1:

- 1. Restore power to the machine. The machine will wait for the operator to start the update.
- 2. Connect to the machine by FTP and upload the *.rru or *.rfu files.

Procedure for type 2:

- 1. Try 'Procedure for type 1'.
- 2. If this does not work, restore power to the machine.
- 3. Upload the firmware from an SD card or IC card.

Procedure for type 3:

- 1. Try 'Procedure for type 1'.
- 2. If this does not work, try 'Procedure for type 2'.
- 3. If this does not work, replace the internal SD card or circuit board.

PAGE: 14/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

7. TROUBLESHOOTING

7.1 Checking the error status

You can check the error status using ftp.

Check whether an error occurred by viewing errlog.txt. This file is in the same directory as version.txt.

- 1. Logon to the machine using ftp.
- 2. Enter "dir" to check that errlog.txt exists.

```
ftp> dir

200 PORT command successful.

150 Opening ASCII mode data connection for '/'.

-r--r--r-- root root 200 Jan 1 01:08 help

-r--r--r-- root root 200 Jan 1 01:08 syslog

-r--r--r-- root root 200 Jan 1 01:08 version.txt

-r--r--r-- root root 200 Jan 1 01:08 errlog.txt

226 Transfer complete.

ftp: 191 bytes received in n.nn Seconds n.nn Kbytes/sec.

ftp>
```

3. Enter "get errlog.txt -" to check the error code.

```
ftp> get errlog.txt -

200 PORT command successful.

150 Opening ASCII mode data connection for 'errlog.txt'.

Module ID: xxxxxxx

Error Code: 51

226 Transfer complete.

ftp: 31 bytes received in n.nn Seconds n.nn Kbytes/sec.

ftp>
```

The information in errlog.txt consists of the module IDs of the firmware modules that caused errors and the corresponding error codes.

For what the error codes mean and how to respond to them, see section 7.2 (below).

4. Enter "bye" to exit ftp.

ftp> bye			
C:\>			



PAGE: 15/15

Model: General RTB Date: 15-Nov-04 No.: RGene019a

7.2 Error Code List

Error Code	Description/Causes	Solutions
51	 The machine cannot be updated. The machine is processing a print job. The machine is processing a scan job. The machine is receiving image data from the network. The control panel is in use. The machine is sending or receiving a fax. The machine has detected a problem corresponding to an SC (service call) number (SC640 to SC649, SC670 to SC679, SC691, SC818, SC819, SC820 to SC839, and SC990). 	Check that the machine is idle, and then try updating again. If an SC number appears, contact your service representative.
52	 The file contains erroneous data. The data is too large or too small. The CRC (cyclic redundancy check) value and the checksum do not match. The firmware does not match the target machine. The firmware was not completely uploaded or is corrupt. 	Download the correct file from the website, and then try updating again.
53	An error occurred while updating. The machine is off.	If using a DNS server, the machine's IP address might have been changed. Check the IP address, and then try updating again.

Technical Bulletin

PAGE: 1/2

Reissued: 29-Jun-05

Model: Model K-P4 Date: 17-Feb-05 No.: RG116001b	Model: Model K-P4	Date: 17-Feb-05	No - RG116001b
--	-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added

The Rome in Bold Railed Have Been added.				
Subject: Controller Firmware Release History (System)		Prepared by: A. Ishiyama		
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	Troubleshooting	Part information	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	⊠ Other ()			

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	C. SUM	Effective Date
1.04	G1165430C	8E8C	July '05 production
1.03	G1165430B	B52D	April '05 production
1.01	G1165430A	F297	1st mass production (Jan 2005)

Descriptions of changes

•	ons of changes
Version	Symptom Corrected
1.04	1. A communication error occurs between the mainframe and RC Gate.
	2. Sometimes, the firmware cannot be updated via RC Gate.
	The firmware cannot be updated if the administrator password is blank.
	4. The image shifts when the left margin is set to 3mm.
	Other changes:
	 Some features of a customization were added as standard: SP5-055-001 (Display IP Address):
	Displays the IP address on the second line of the operation panel when the printer is in the Ready condition.
	0: OFF (default)
	1: ON
	- SP5-886-001 (ROM Update):
	Allows the ROM firmware to be updated remotely via the local network.
	0: ON (default)
	1: OFF
	NOTE: The settings for the two SP modes above can be changed with
	Web Image Monitor.
	Important: To use these new features, you need to install all of the following
	firmware together as a set.
	System v1.04 or later (P/N #G1165430C)
	Printer v1.04.2 or later (P/N #G1165441C)
	Websys v1.02 or later (P/N #G1165433B)

Technical **B**ulletin

3ulletin Page: 2/2

Reissued: 29-Jun-05

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001b
Version Symptom Corrected			
1.03	(Minor change applied for Japan model only).		
1.01	1st Mass Production		

Technical Bulletin

PAGE: 1/2

Reissued: 30-Nov-05

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001c

RTB Reissue

The items in bold italics have been added

The Reine III Bela Railes Have been added.			
Subject: Controller Firmware Release History (System)		Prepared by: A. Ishiyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path	☐ Part informa ☐ Electrical ☐ Transmit/rec	Service manual revision
	⊠ Other ()		

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.05	G1165430D	November '05 production
1.04	G1165430C	July '05 production
1.03	G1165430B	April '05 production
1.01	G1165430A	1st mass production (Jan 2005)

Descriptions of changes

Version	Symptom Corrected
1.05	1. SP5930-2 has newly been added.
	Note: See RTB RG116007a (Engine firmware history) for details.
	<u>Important</u> : To use the above new feature, you need to install all of the
	following firmware together as a set.
	* System v1.05 or later (P/N #G1165430D)
	* Printer v1.05 or later (P/N #G1165441D
	* Engine v1.03:20 or later (P/N #G1115136C)
	2. Sometimes, the firmware cannot be updated via RC Gate by FTP.
	<u>Important</u> : To apply this correction, you need to install all of the following firmware together as a set.
	* System v1.05 or later (P/N #G1165430D)
	* NCS v4.15.2 or later (P/N #G1165432C)
	3. When the printer receives more than 300 login attempts since the last power ON:
	- The administrator cannot login to the printer via WIM.
	- Users cannot print if User Authentication is enabled.
	4. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002)



PAGE: 2/2

Reissued: 30-Nov-05

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001c	
Version	Symptom Corrected			
1.04	 A communication error occurs between Sometimes, the firmware cannot be up The firmware cannot be updated if the The image shifts when the left margin is Other changes: Some features of a customization were Sp5-055-001 (Display IP Address): Displays the IP address on the secon printer is in the Ready condition. OFF (default) ON Sp5-886-001 (ROM Update):	the mainframe and RC dated via RC Gate. administrator password is set to 3mm. added as standard: cond line of the operation dated remotely via the lead to install all of the operation of the changed to install all of the dated remotell all of the operation of	is blank. In panel when the ocal network. Via Web Image	
	Printer v1.04.2 or later (P/N #G1165441C) Websys v1.02 or later (P/N #G1165433B)			
4.00	, ,	,		
1.03	(Minor change applied for Japan model on	ly).		
1.01	1st Mass Production			

Technical Bulletin

PAGE: 1/2

Reissued: 30-Nov-05

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002c

RTB Reissue

The items in bold italics have been added

The items in bold italics have been added.				
Subject: Controller Firmware Release History (Printer)		Prepared by: A	A. Ishiyama	
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	Troubleshooting	☐ Part informat	tion	ion required
	☐ Mechanical	Electrical	☐ Sei	rvice manual revision
	☐ Paper path	☐ Transmit/rec	eive 🗌 Re	trofit information
	⊠ Other ()			

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.05	G1165441D	November '05 production
1.04.2	G1165441C	July '05 production
1.03	G1165441B	April '05 production
1.01	G1165441A	1st mass production (Jan 2005)

Version	Symptom Corrected		
1.05	1. SP5930-2 has newly been added.		
	Note: See RTB RG116007a (Engine firmware history) for details.		
	Important: To use the above new feature, you need to install all of the		
	following firmware together as a set.		
	* System v1.05 or later (P/N #G1165430D)		
	* Printer v1.05 or later (P/N #G1165441D		
	* Engine v1.03:20 or later (P/N #G1115136C)		
	1. The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode.		

Technical **B**ulletin

PAGE: 2/2

Reissued: 30-Nov-05

Model: Model K-P4		Date: 17-Feb-05	No.: RG116002c	
Version	Symptom Corrected			
1.04.2	 Sometimes, the keys on the operation panel do not work when the machine is in the Toner End condition. Sometimes, the machine stalls when a duplex job is sent from an RPCS driver and then the job is cancelled. 			
	Other changes: 3. Some features of a customization were added as standard: - The IP address is displayed on the LCD Thai and non-English Latin characters can be printed with the PS driver			
	Important: To use these new features, you need to install all of the following firmware together as a set. System v1.04 or later (P/N #G1165430C) Printer v1.04.2 or later (P/N #G1165441C) Websys v1.02 or later (P/N #G1165433B)			
1.03	No changes (version standardization with System firmware only).			
1.01	1st Mass Production			

RICOH

Model: Model K-P4

Technical Bulletin

PAGE: 1/2 Reissued:21-Apr-06

Date: 21-Apr-06

No.: RG116003c

RTB Reissue

The items in **bold italics** have been added.

Subject: Controller Firmware Release History (NCS)			Prepared	d by: H. Saitoh
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Other ()	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information

This RTB has been issued to announce the firmware release information for the NCS.

Version	Program No.	Effective Date	
4.15.2	G1165432C	November '05 production	
4.14.1	G1165432B	July '05 production	
4.08.1	G1165432A	1st mass production (Jan 2005)	

Version	Symptom Corrected		
4.15.2	Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C)		
	2. Firmware update via WIM fails if the administrator uses a password or username that is 24 bytes or larger. After this, WIM may not connect to the device.		



PAGE: 2/2

Reissued: 30-Jun-05

Model: Model K-P4		Date: 21-Apr-06	No.: RG116003c		
Version	Symptom Corrected				
4.14.1	Note: NCS firmware Ver 4.14.1 or later must be used with websys firmware Ver1.02 or later. Websys v1.02 (P/N #G1165433B) or later NCS v4.14.1 (P/N #G1165432B) or later				
	 If the paper type setting is changed via and v2" is disabled, the browser will tim not be saved. SNMPv1/v2 will still send SNMP traps 	leout. The paper type	setting change will		
	 disabled. 3. Sometimes after a power cycle, the device will be unable to accept jobs from standard TCP/IP or SDM ports. 4. The SNMP buffer may become full when a lot of SNMP traffic is sent to the 				
	 device. As a result, the device cannot r 5. SDM for Admin cannot retrieve 1394 ho on a client PC with 1394 and Ethernet 6. The SNMP service may not start when SNMP do not receive status updates fr 	ostnames and devices nterfaces. the device is turned or	when it is installed		
	Other changes: Some features of a customization were added as standard: The device can accept more than one diprint (port9100) session. Communication via diprint (port 9100) is asynchronous.				
4.08.1	1st Mass Production				

RICOH

Technical Bulletin

PAGE: 1/2

Reissued: 25-May-06

Model R-P4 Date: 17-Feb-05 No.: RG116001d	Model: Model K-P4	Date: 17-Feb-05	No.: RG116001d
---	-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added

THE REITS III DOI	d Italics Have been added	4.		
Subject: Controller Firmware Release History (System)			Prepared	l by: H. Saitoh
From: 1st Tech. S	Support Sec. Service Support [Dept.		
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☒ Other ()	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date	
1.06	G1165430E	April '06 production	
1.05	G1165430D	November '05 production	
1.04	G1165430C	July '05 production	
1.03	G1165430B	April '05 production	
1.01	G1165430A	1st mass production (Jan 2005)	

Descriptions of changes

Version	Symptom Corrected
1.06	Sometimes, RC Gate cannot get the counter data from the device.
1.05	Sp5930-2 has been newly added. Note: See RTB RG116007a (Engine firmware history) for details.
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C)
	2. Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C)
	 3. When the printer receives more than 300 login attempts since the last power ON: The administrator cannot login to the printer via WIM. Users cannot print if User Authentication is enabled. 4. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002)

RICOH

Technical **B**ulletin

PAGE: 2/2

Reissued: 25-May-06

Model: Mo	odel K-P4	Date: 17-Feb-05	No.: RG116001d		
Version	Symptom Corrected				
1.04	 A communication error occurs between Sometimes, the firmware cannot be upon The firmware cannot be updated if the ansage shifts when the left margin is Other changes: Some features of a customization were - Sp5-055-001 (Display IP Address): Displays the IP address on the secondition. OFF (default) ON - Sp5-886-001 (ROM Update):	the mainframe and RC dated via RC Gate. administrator password is set to 3mm. added as standard: ond line of the operation dated remotely via the lead to install all of the C) 1C)	is blank. In panel when the ocal network. Via Web Image		
1.03	(Minor change applied for Japan model only).				
1.01	1st Mass Production				

Technical Bulletin

PAGE: 1/2

Reissued: 25-May-06

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002d

RTB Reissue

The items in bold italics have been added

The items in bold italics have been added.					
Subject: Controller Firmware Release History (Printer)		Prepared by: Hiromoto S	aitoh		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informate ☐ Electrical ☐ Transmit/rec	☐ Service manu	al revision	
	_ ,				

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date		
1.06	G1165441E	April '06 production		
1.05	G1165441D	November '05 production		
1.04.2	G1165441C	July '05 production		
1.03	G1165441B	April '05 production		
1.01	G1165441A	1st mass production (Jan 2005)		

Version	Symptom Corrected
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001)
	Other changes: 1. The Summary Report can be printed out by turning ON the main power switch while holding down the Start key.
1.05	2. Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine firmware history) for details. Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C) 1. The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode.

Technical **B**ulletin

PAGE: 2/2

Reissued: 25-May-06

Model: Mo	odel K-P4	Date: 17-Feb-05	No.: RG116002d
Version	Version Symptom Corrected		
1.04.2	 Sometimes, the keys on the operation of the Toner End condition. Sometimes, the machine stalls when a and then the job is cancelled. Other changes: Some features of a customization were The IP address is displayed on the LCE Thai and non-English Latin characters of the important: To use these new features, you together as a set. System v1.04 or later (P/N #G11654304 Printer v1.04.2 or later (P/N #G11654334 Websys v1.02 or later (duplex job is sent from added as standard: o. can be printed with the length of the control of	an RPCS driver
1.03	No changes (version standardization with System firmware only).		
1.01	1st Mass Production		

Technical Bulletin

PAGE: 1/1

Reissued: 13-Jul-06

Other (

Model: Model K-	.P4	·	Date	: 13-Jul-06	No.: RG116011b
RTB Reissue					
The items in bo	ld italics have been ac	dded.			
Subject: Firmwai	re Release History (DESS	S)	F	Prepared by: A. I	shiyama
From: 1st Tech. S	Support Sec. Service Supp	ort Dept.			
Classification:	☐ Troubleshooting	☐ Part inf	ormatic	on 🗌 Action	required
	☐ Mechanical	☐ Electric	al	☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/recei	ve ☐ Retrot	fit information

This RTB has been issued to announce the firmware release information for the <u>DESS</u>.

Version	Program No.	Effective Date
3.07	G1396097A	March 2006 Production
3.06A.1	G1396097	March 2006 Production
2.06	G8206917	1st mass production

Version	Symptom Corrected
3.07	Symptom corrected: The SSL/TLS rollback vulnerability. (TechMail#TS060225).
3.06A.1	Other changes: The maximum encryption level was increased from 56 bit to 256 bit (see RTB RG116012 for details).
2.06	1st Mass Production

Technical Bulletin

PAGE: 1/1

Model: Model K-	P4		Dat	e: 25-Jul-0	06	No.: RG116012
Subject: Optiona	I DESS Module			Prepared	d by: A. I	shiyama
From: 1st Technic	cal Support Sec. Service Suppo	ort Dept.				
Classification:	☐ Troubleshooting	☐ Part inf	ormat	tion	☐ Action	required
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☑ Other ()					

Change in Specifications of the DESS Module (Network Data Protection Unit Type B)

Summary

The following specification was changed, and as a result, the option name, product code, EDP code and firmware P/N were also changed.

Specification change:

The maximum encryption level was increased from 56 bit to 256 bit.

Note: See RTB RG116011a.

Affected Models

Model C-P2c: G113Model K-P4d: G116

Applied From

• March 2006

Affected Options:	Old DESS Module (Before Specification Change):	New DESS Module (After Specification Change):
Option Name	Network Data Protection Unit	Network Data Protection Unit Type C Note
Product Code	G820-01	G880-01
EDP Code	402363	402530
Firmware Part No.	Old Part No.	New Part No.
	G8206917	G1396097

Note: This is the same option as the one used on Model Ar-P2.

Technical Bulletin

PAGE: 1/2

Reissued: 28-Sep-06

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002e

RTB Reissue

The items in bold italics have been added.

Subject: Controller Firmware Release History (Printer)		Prepared by: Hiromoto Saitoh			
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting	☐ Part information	tion	☐ Action required	
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☑ Other ()				

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date	
1.07	G1165441F	October 2006 production	
1.06	G1165441E	April '06 production	
1.05	G1165441D	November '05 production	
1.04.2	G1165441C	July '05 production	
1.03	G1165441B	April '05 production	
1.01	G1165441A	1st mass production (Jan 2005)	

Version	Symptom Corrected
1.07	A test print is not correctly counted.
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001)
	Other changes: 1. The Summary Report can be printed out by turning ON the main power switch while holding down the Start key.
1.05	Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine firmware history) for details.
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C)
	The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode.

Technical **B**ulletin

PAGE: 2/2

Reissued: 28-Sep-06

Model: Model K-P4		Date: 17-Feb-05	No.: RG116002e
Version	Symptom Corrected		
1.04.2	 Sometimes, the keys on the operation of the Toner End condition. Sometimes, the machine stalls when a and then the job is cancelled. Other changes: Some features of a customization were The IP address is displayed on the LCE Thai and non-English Latin characters of the IP in the IP in	panel do not work when duplex job is sent from added as standard: can be printed with the fineed to install all of the C)	an RPCS driver
	Websys v1.02 or later (P/N #G1165433	(סו	
1.03	No changes (version standardization with S	System firmware only).	
1.01	1st Mass Production		

Technical Bulletin

PAGE: 1/2

Reissued: 26-Jan-07

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001e
Wodel Net 4	Date. 17-1 CD-03	1401100010

RTB Reissue

The items in bold italics have been added.

no komo in pola kanco navo poen adaca.				
Subject: Controller Firmware Release History (System)		Prepared	d by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information
	⊠ Other ()			

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date		
1.07	G1165430F	October 2006 production		
1.06	G1165430E	April '06 production		
1.05	G1165430D	November '05 production		
1.04	G1165430C	July '05 production		
1.03	G1165430B	April '05 production		
1.01	G1165430A	1st mass production (Jan 2005)		

Descriptions of changes

Version	Symptom Corrected
1.07	1. Sometimes, an image problem occurs or the machine stalls while printing a job with a large number of sheets.
1.06	Sometimes, RC Gate cannot get the counter data from the device.
1.05	Sp5930-2 has been newly added. Note: See RTB RG116007a (Engine firmware history) for details.
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C)
	2. Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C)
	 3. When the printer receives more than 300 login attempts since the last power ON: The administrator cannot login to the printer via WIM. Users cannot print if User Authentication is enabled. 4. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002)

Technical **B**ulletin

PAGE: 2/2

Reissued: 26-Jan-07

Model: Model K-P4 Date: 17-Feb-05			No.: RG116001e
Version 1.04	1.04 1. A communication error occurs between the mainframe and RC Gate. 2. Sometimes, the firmware cannot be updated via RC Gate. 3. The firmware cannot be updated if the administrator password is blank. 4. The image shifts when the left margin is set to 3mm. Other changes: 5. Some features of a customization were added as standard: - Sp5-055-001 (Display IP Address): Displays the IP address on the second line of the operation panel when the printer is in the Ready condition. 0: OFF (default) 1: ON		
	Important: To use these new features, you together as a set. System v1.04 or later (P/N #G1165430 Printer v1.04.2 or later (P/N #G116544 Websys v1.02 or later (P/N #G1165433	C) 1C)	e following firmware
1.03	(Minor change applied for Japan model on	ly).	
1.01	1st Mass Production		



PAGE: 1/2

Reissued: 13-Jun-07

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001f
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Controller Firmware Release History (System)		Prepare	d by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☑ Other ()	☐ Part informat ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date		
1.09	G1165430H	July 2007 production		
1.08	G1165430G	April 2007 production		
1.07	G1165430F	October 2006 production		
1.06	G1165430E	April '06 production		
1.05	G1165430D	November '05 production		
1.04	G1165430C	July '05 production		
1.03	G1165430B	April '05 production		
1.01	G1165430A	1st mass production (Jan 2005)		

Descriptions of changes

Version	Sumptom Corrected
	Symptom Corrected
1.09	Symptom corrected:
	1. The image is shifted downward (as it should), but sometimes the bottom of the image appears on the next page.
	(example: When the Header/Footer/Adjust image position/Binding margins
	setting in the printer driver is changed)
	Note: Normally, the image is shifted downward and the bottom part is
	deleted (does not appear on the next page).
	Other changes:
	2. New SP mode: SP5828-045.
	With this SP mode, Centronix can be enabled/disabled.
1.08	Other changes:
	1. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.
	2. SC868 occurrence conditions: From this version, the SC will not be
	•
	displayed if a damaged SD card is inside the card slot when the main power is turned on.
1.07	1. Sometimes, an image problem occurs or the machine stalls while printing a job with a large number of sheets.
1.06	Sometimes, RC Gate cannot get the counter data from the device.
1.05	1. Sp5930-2 has been newly added.
	Note: See RTB RG116007a (Engine firmware history) for details.
1	l * * * * * * * * * * * * * * * * * * *



PAGE: 2/2

Reissued: 13-Jun-07

Model: Mo	odel K-P4	Date: 17-Feb-05	No.: RG116001f			
Version	Symptom Corrected					
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C)					
	2. Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C)					
	 3. When the printer receives more than 300 login attempts since the last power ON: The administrator cannot login to the printer via WIM. Users cannot print if User Authentication is enabled. 4. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002) 					
1.04	 A communication error occurs between Sometimes, the firmware cannot be upon The firmware cannot be updated if the ansate an ansate an arrow of the image shifts when the left margin is other changes: Some features of a customization were - Sp5-055-001 (Display IP Address): Displays the IP address on the second printer is in the Ready condition. OFF (default) ON Sp5-886-001 (ROM Update): 	dated via RC Gate. administrator password s set to 3mm. added as standard:	is blank.			
	Allows the ROM firmware to be upon 0: ON (default) 1: OFF NOTE: The settings for the two SP modes Monitor.	·				
	Important: To use these new features, you together as a set. System v1.04 or later (P/N #G1165430 Printer v1.04.2 or later (P/N #G116544 Websys v1.02 or later (P/N #G1165433	C) 1C)	e following firmware			
1.03	(Minor change applied for Japan model on	ly).				
1.01	1st Mass Production					



PAGE: 1/2

Reissued: 13-Jun-07

Model: Model K-P4 Da	Date: 17-Feb-05	No.: RG116002f
----------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Controller Firmware Release History (Printer)			Prepared by: Y.Murata		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informate ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information	

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date	
1.09	G1165441H	July 2007 production	
1.08	G1165441G	April 2007 production	
1.07	G1165441F	October 2006 production	
1.06	G1165441E	April '06 production	
1.05	G1165441D	November '05 production	
1.04.2	G1165441C	July '05 production	
1.03	G1165441B	April '05 production	
1.01	G1165441A	1st mass production (Jan 2005)	

Version	Symptom Corrected
1.09	No changes (version standardization with System firmware only).
1.08	Symptom corrected: [RPCS] 1. A P2 memory error occurs when using originals that use many clips. 2. A memory leak occurs when the resolution or bit number is changed. 3. Thin lines are not printed out when using 90-degree rotation in Mode 3. [PS3] 4. When a simplex job is performed in between two duplex jobs, the booklet direction from the first duplex job is automatically applied to the second duplex job. Other changes: 5. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.
1.07	A test print is not correctly counted.



PAGE: 2/2

Reissued: 13-Jun-07

Model: Mo	Model: Model K-P4 Date: 17-Feb-05 No.: RG116002					
Version						
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001) 					
	Other changes: 1. The Summary Report can be printed ou while holding down the Start key.	ut by turning ON the ma	in power switch			
1.05	Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine fine)	mware history) for detai	ls.			
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C)					
	The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode.					
1.04.2	 Sometimes, the keys on the operation pathe Toner End condition. Sometimes, the machine stalls when a and then the job is cancelled. Other changes: Some features of a customization were 	duplex job is sent from added as standard:				
	 The IP address is displayed on the LCE Thai and non-English Latin characters of 		PS driver			
	Important: To use these new features, you need to install all of the following firmware together as a set. System v1.04 or later (P/N #G1165430C) Printer v1.04.2 or later (P/N #G1165441C) Websys v1.02 or later (P/N #G1165433B)					
1.03	No changes (version standardization with S	System firmware only).				
1.01	1st Mass Production					



PAGE: 1/2

Reissued: 15-Jun-07

Model: Model K-P4 Date:	21-Apr-06 No.: RG116003d
-------------------------	--------------------------

RTB Reissue

The items in **bold italics** have been added.

Subject: Controller Firmware Release History (NCS)			Prepared by: Y.Murata		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Other ()	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required ☐ Service manual revision ☐ Retrofit information	

This RTB has been issued to announce the firmware release information for the NCS.

Version	Program No.	Effective Date		
4.15.4	G1165432D	July 2007 production		
4.15.2	G1165432C	November '05 production		
4.14.1	G1165432B	July '05 production		
4.08.1	G1165432A	1st mass production (Jan 2005)		

Version	Symptom Corrected
4.15.4	Symptom corrected:
	1. An IEEE 1284 job might result in the device to becoming locked in the
	Waiting state.
4.15.2	Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C)
	2. Firmware update via WIM fails if the administrator uses a password or username that is 24 bytes or larger. After this, WIM may not connect to the device.



PAGE: 2/2

Reissued: 30-Jun-05

Model: Mo	Model: Model K-P4 Date: 21-Apr-06 No.: RG116					
Version	Symptom Corrected					
4.14.1	Note: NCS firmware Ver 4.14.1 or later Ver1.02 or later. Websys v1.02 (P/N #G1165433B) or later NCS v4.14.1 (P/N #G1165432B) or later 1. If the paper type setting is changed via and v2" is disabled, the browser will time not be saved. 2. SNMPv1/v2 will still send SNMP traps of disabled. 3. Sometimes after a power cycle, the devistandard TCP/IP or SDM ports. 4. The SNMP buffer may become full whe device. As a result, the device cannot result to a client PC with 1394 and Ethernet in the SNMP service may not start when SNMP do not receive status updates from the device can accept more than one communication via diprint (port 9100)	with we will be used with we will be used with we will be unable to accomply to SNMP traffic it eply to SNMP requests. It is device is turned on the device is turned on the device.	ings by SNMPv1 etting change will function is cept jobs from s sent to the when it is installed Utilities using			
4.08.1	1st Mass Production					

Technical Bulletin

PAGE: 1/2

Model: Model K-P4			Date: 17-July-07		-07	No.: RG116013
Subject: Incorrect format of ID2				Prepared by: A. Ishiyama		
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:		☐ Part inform		tion		required
		☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path ☐ Transmit/red		mit/receive		fit information	
	☐ Product Safety	Other ()		

SYMPTOM

- 1. The format of the ID2 is incorrect on the SMC printout (SP5811-003) and in the RC Gate UI when trying to register a device as "managed".
- 2. The target device cannot be found in the @Remote Center GUI when trying to perform a remote firmware update (RFU).

Example: The device serial number is Q3356100001 (SP5811-001).

Incorrect ID2 format: Q335 (six spaces) 6100001
Correct ID2 format: Q33 (six spaces) 56100001

Q33: Device prefix

561: YMM (production year and month)

CAUSE

The ID2 was programmed in the device at the factory in the incorrect format. Affected units: From first production to March 2007 production.

Note: There are some limited cases in which the ID2 is in the correct format. In these cases, the ID2 was then restored using the @Remote Center GUI (e.g., after the NV-RAM was replaced in the field).

SOLUTION

As shown in the table below, only Symptom 2 has an effect on @Remote Center operations (and this effect is minor):

@Remote Monitoring/Function	Meter Reading	Reporting	Toner Replenishment	Call Handling	RFU
Correct ID2 (e.g. Q33)	Yes	Yes	Yes	Yes	Yes
Incorrect ID2 (e.g. Q335)	Yes	Yes	Yes	Yes	(Symptom 2)

Therefore,

Symptom 1: No action required in the field

Symptom 2: Try searching for the target device using the incorrect ID2 format (e.g. Q335).

If you cannot find it, try using the correct ID2 format (e.g. Q33).

See next page for a screenshot of the Model Select List.



PAGE: 2/2


No.: RG116013

Date: 17-July-07

Model Select List

Model: Model K-P4

Note: Most devices are listed with the incorrect ID2 format (e.g. Q335, Q336 or Q337), but some are listed with the correct ID2 format (e.g. Q33).



Technical Bulletin

PAGE: 1/2

Reissued: 15-Nov-07

Other (

Model: Model K-	P4		Date	e: 17-Feb-05	No.: RG116007b
RTB Reissue The items in bol	d italics have been add	ded.			
Subject: Firmware Release History (Engine)			1	Prepared by: Y.Murata	
From: 1st Tech. S	Support Sec. Service Suppo	ort Dept.			
Classification:	☐ Troubleshooting	☐ Part info	rmati	on 🗌 Actio	on required
	☐ Mechanical	☐ Electrica	al	☐ Serv	rice manual revision
	☐ Paper path	☐ Transmi	it/rece	eive 🔲 Retr	ofit information

This RTB has been issued to announce the firmware release information for the Engine.

Version	Program No.	Effective Date
1.04:20	G1115136D	October 2007 production
1.03:20	G1115136C	November 2005 production
1.02:20	G1115136B	1st mass production (Jan 2005)

Version	Symptom Corrected
1.04:20	(Minor modifications applied).

Technical **B**ulletin

PAGE: 2/2

Reissued: 15-Nov-07

Model: Model K-P4 Date: 17-Feb-05 No.: RG116007b

Wodon W	Duel K-P4			Date. 17-Feb-05	NO RG116007b		
Version	Symptom Corrected						
1.03:20	Sp5930-2 was a	2 was added to Meter Charge Mode:					
	5930	Meter charg	je mode				
	5930 1	No, Yes	Enables or o	lisables meter-charge m	ode.		
	5930 2	No, Yes		ot display of "Replace M			
		•		switch off/on after chang	ing this setting.		
			_	bled (Default):	Manage India		
		I ne meter pressed.	r cnarge count	er is not shown when the	Menu key is		
		•		automatically after the use	er replaces the		
		Maintenar	nce Kit" (the us	SP5930 2, the machine der replaces the maintena			
			ge mode enal	biea: er is shown immediately a	ofter the Manukov		
		is pressed		er is snown infinediately a	anter the Menu key		
		The techn	ician must res	et the PM counter after fir			
				ntenance Kit" (SP5930			
				ge mode, you can select o (it" by SP5930 2.	display/not display		
				ace Maintenance Kit" is d	isplayed on the		
				e PM counter runs out.	at displayed on the		
		If it is set to "No", "Replace Maintenance Kit" is not displayed on the operation panel when the PM counter runs out.					
	Important: To use the above new feature, you need to install all of the following						
	firmware together as a set.						
		stem v1.05 or later (P/N #G1165430D) nter v1.05 or later (P/N #G1165441D					
		3:20 or later (P/N #G1115136C)					
1.02:20	1st Mass Produ	iction					

Technical Bulletin

PAGE: 1/3

Model: Kir-P4 duplex unit			Dat	e: 9-Sep-0)8	No.: RG116014
Subject: Duplex Jam				Prepared by: Yasuo Yoshida		
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:		☐ Part informa		tion	Action	required
	☐ Mechanical ☐ Electrical		al		☐ Service	ce manual revision
	☐ Paper path ☐ Transmit/re		it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	⊠ Tier2	

Symptom

A duplex jam occurs or the paper folds at the leading edge.

Cause

The paper may hit the paper guide, especially when it is curled.

Solution

Install the following Mylar, which will make the paper feed more smoothly.

P/N: **G1684473**– Mylar

Quantity: 2


See the procedure on the next page.

PAGE: 2/3


Model: Kir-P4 duplex unit Date: 9-Sep-08 No.: RG116014

Mylar Installation Procedure

- 1. Turn the main power of the printer OFF, and then remove the duplex unit.
- 2. Put the duplex unit on a flat surface.
- 3. Remove the metal guide plate (2 screws).



4. Attach the two Mylars to the **left and right** sides of the duplex unit, as shown below.



Important:


- Before you attach the Mylar, clean the attachment surface with alcohol.
- Make sure to align the Mylar against the rib as shown.
- Make sure the block does not touch the shaft [A].



PAGE: 3/3

Model: Kir-P4 duplex unit Date: 9-Sep-08 No.: RG116014

5. Reattach the guide plate (2 screws).



- 6. Reattach the duplex unit.
- 7. Print out some samples and check the image quality.

Technical Bulletin

PAGE: 1/2 Reissued: 09-Sep-08

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001g

RTB Reissue

The items in bold italics have been added

THE REITIE III DE	a italioo havo boon aaaot			
Subject: Controller Firmware Release History (System)			Prepared by: Y.Gaman	
From: 1st Tech. Support Sec. Service Support Dept.				
Classification:	Troubleshooting	☐ Part informa	tion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	⊠ Other ()			

This RTB has been issued to announce the firmware history for the **System** of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.10	G1165430J	August 2008 production
1.09	G1165430H	July 2007 production
1.08	G1165430G	April 2007 production
1.07	G1165430F	October 2006 production
1.06	G1165430E	April '06 production
1.05	G1165430D	November '05 production
1.04	G1165430C	July '05 production
1.03	G1165430B	April '05 production
1.01	G1165430A	1st mass production (Jan 2005)

Descriptions of changes

Version	Symptom Corrected
1.10	Other changes:
	The firmware was modified to support the new Fujitsu hard disk drive.
1.09	 Symptom corrected: The image is shifted downward (as it should), but sometimes the bottom of the image appears on the next page. (ex. When the Header/Footer/Adjust image position/Binding margins setting in the printer driver is changed) Note: Normally, the image is shifted downward and the bottom part is deleted (does not appear on the next page).
	Other changes: 2. New SP mode: SP5828-045. With this SP mode, Centronix can be enabled/disabled.
1.08	 Other changes: 1. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes. 2. SC868 occurrence conditions: From this version, the SC will not be displayed if a damaged SD card is inside the card slot when the main power is turned on.
1.07	1. Sometimes, an image problem occurs or the machine stalls while printing a job with a large number of sheets.
1.06	Sometimes, RC Gate cannot get the counter data from the device.

Technical **B**ulletin

PAGE: 2/2

Reissued: 09-Sep-08

Model: Mo	odel K-P4	Date: 17-Feb-05	No.: RG116001g			
Version		n Corrected				
1.05	 Sp5930-2 has been newly added. Note: See RTB RG116007a (Engine firmware history) for details. Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C) Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C) 					
	 3. When the printer receives more than 3 The administrator cannot login to t Users cannot print if User Authent 4. Sometimes, the ROM Update menu is #RC05070002) 	the printer via WIM. ication is enabled.	·			
1.04	 A communication error occurs between Sometimes, the firmware cannot be upon The firmware cannot be updated if the ansatz and the image shifts when the left margin is Other changes: Some features of a customization were - Sp5-055-001 (Display IP Address): Displays the IP address on the secondition. OFF (default) ON - Sp5-886-001 (ROM Update):	dated via RC Gate. administrator password is set to 3mm. added as standard: ond line of the operation dated remotely via the lead to install all of the operation of the changed to install all of the operation of the operation above can be changed one of the operation of the ope	is blank. In panel when the ocal network. Via Web Image			
4.00	System v1.04 or later (P/N #G1165430 Printer v1.04.2 or later (P/N #G116544) Websys v1.02 or later (P/N #G1165433	1Ć) BB)				
1.03	(Minor change applied for Japan model on	ly).				
1.01	1st Mass Production					

Technical Bulletin

PAGE: 1/2

Reissued: 09-Sep-08

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002g

RTB Reissue

The items in bold italics have been added.

The items in bold italies have been added.					
Subject: Controller Firmware Release History (Printer)			Prepared by: Y.Gaman		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	Troubleshooting	☐ Part informat	- '		
	☐ Mechanical	☐ Electrical	Service manual revision		
	☐ Paper path	☐ Transmit/rec	ceive Retrofit information		
	⊠ Other ()				

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.10	G1165441J	August 2008 production
1.09	G1165441H	July 2007 production
1.08	G1165441G	April 2007 production
1.07	G1165441F	October 2006 production
1.06	G1165441E	April '06 production
1.05	G1165441D	November '05 production
1.04.2	G1165441C	July '05 production
1.03	G1165441B	April '05 production
1.01	G1165441A	1st mass production (Jan 2005)

Version	Symptom Corrected
1.10	Other changes:
	The firmware was modified to support the new Fujitsu hard disk drive.
1.09	No changes (version standardization with System firmware only).
1.08	 Symptom corrected: [RPCS] A P2 memory error occurs when using originals that use many clips. A memory leak occurs when the resolution or bit number is changed. Thin lines are not printed out when using 90-degree rotation in Mode 3. [PS3] When a simplex job is performed in between two duplex jobs, the booklet direction from the first duplex job is automatically applied to the second duplex job. Other changes: The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.
1.07	A test print is not correctly counted.

Technical **B**ulletin

PAGE: 2/2

Reissued: 09-Sep-08

Model: Model K-P4		Date: 17-Feb-05	No.: RG116002g		
Version	Symptom Corrected				
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001) Other changes: The Summary Report can be printed out by turning ON the main power switch while holding down the Start key. 				
1.05	Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine fire	•			
	 Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03:20 or later (P/N #G1115136C) The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode. 				
1.04.2	 Sometimes, the keys on the operation panel do not work when the machine is in the Toner End condition. Sometimes, the machine stalls when a duplex job is sent from an RPCS driver and then the job is cancelled. Other changes: Some features of a customization were added as standard:				
1.03	No changes (version standardization with S	System firmware only).			
1.01	1st Mass Production				

Technical Bulletin

PAGE: 1/3 Reissued: 09-Jun-09

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001h
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

The Reme III bela Railee Have been added.					
Subject: Controller Firmware Release History (System)			Prepared by: Y.Murata		
From: 1st Tech. Support Sec. Service Support Dept.					
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path	☐ Part informated ☐ Electrical ☐ Transmit/rec		☐ Action required☐ Service manual revision☐ Retrofit information	
	⊠ Other ()				

This RTB has been issued to announce the firmware history for the **System** of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.11	G1165430K	July 2009 production
1.10	G1165430J	August 2008 production
1.09	G1165430H	July 2007 production
1.08	G1165430G	April 2007 production
1.07	G1165430F	October 2006 production
1.06	G1165430E	April '06 production
1.05	G1165430D	November '05 production
1.04	G1165430C	July '05 production
1.03	G1165430B	April '05 production
1.01	G1165430A	1st mass production (Jan 2005)

Descriptions of changes

Version	Symptom Corrected		
1.11	Symptom corrected: 1. The device might not be able to access the network under the following conditions: - The device is connected to a hub that has link flapping enabled The device "Ethernet speed" is not "Auto".		
1.10	Other changes: The firmware was modified to support the new Fujitsu hard disk drive.		
1.09	Symptom corrected: 1. The image is shifted downward (as it should), but sometimes the bottom of the image appears on the next page. (Ex. When the Header/Footer/Adjust image position/Binding margins setting in the printer driver is changed) Note: Normally, the image is shifted downward and the bottom part is deleted (does not appear on the next page).		
	Other changes: 2. New SP mode: SP5828-045. With this SP mode, Centronix can be enabled/disabled.		

Technical **B**ulletin

PAGE: 2/3

Reissued: 09-Jun-09

Model: Model K-P4 Date: 17-Feb-05 No.: RG116					
Version	Symptom Corrected				
1.08	 Other changes: 1. The default setting for the Energy Save minutes. 2. SC868 occurrence conditions: From the damaged SD card is inside the card slow 	is version, the SC will n	ot be displayed if a		
1.07	Sometimes, an image problem occurs or the machine stalls while printing a job with a large number of sheets.				
1.06	Sometimes, RC Gate cannot get the count	er data from the device	•		
1.05	Sp5930-2 has been newly added. Note: See RTB RG116007a (Engine firmware history) for details. Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D				
	 * Engine v1.03: 20 or later (P/N #G1115136C) 2. Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmwatogether as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C) 3. When the printer receives more than 300 login attempts since the last power Correction. - The administrator cannot login to the printer via WIM. - Users cannot print if User Authentication is enabled. 4. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002) 				
1.04	 A communication error occurs between Sometimes, the firmware cannot be upon The firmware cannot be updated if the ansatz and the image shifts when the left margin is other changes: Some features of a customization were - Sp5-055-001 (Display IP Address): Displays the IP address on the section printer is in the Ready condition. OFF (default) ON Sp5-886-001 (ROM Update):	dated via RC Gate. administrator password is set to 3mm. added as standard: ond line of the operation dated remotely via the leadance.	is blank. In panel when the ocal network. Via Web Image		
	Important: To use these new features, you together as a set.	need to install all of the	tollowing firmware		

Technical **B**ulletin

PAGE: 3/3

Reissued: 09-Jun-09

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001h

Version	Symptom Corrected
	System v1.04 or later (P/N #G1165430C)
	Printer v1.04.2 or later (P/N #G1165441C)
	Websys v1.02 or later (P/N #G1165433B)
1.03	(Minor change applied for Japan model only).
1.01	1st Mass Production

Technical Bulletin

Chnical **B**ulletin Page: 1/2

Reissued: 09-Jun-09

Model: Model K-P4	Date: 17-Feb-05	No.: RG116002h

RTB Reissue

The items in bold italics have been added.

Subject: Controller Firmware Release History (Printer)			Prepared by: Y.Murata				
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:	Troubleshooting	☐ Part informat	ion	Action required			
	☐ Mechanical	☐ Electrical		☐ Service manual revision			
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information			
	☐ Product Safety	⊠ Other ()	⊠ Tier 2			

This RTB has been issued to announce the firmware history for the <u>Printer</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.11	G1165441K	July 2009 production
1.10	G1165441J	August 2008 production
1.09	G1165441H	July 2007 production
1.08	G1165441G	April 2007 production
1.07	G1165441F	October 2006 production
1.06	G1165441E	April '06 production
1.05	G1165441D	November '05 production
1.04.2	G1165441C	July '05 production
1.03	G1165441B	April '05 production
1.01	G1165441A	1st mass production (Jan 2005)

Version	Symptom Corrected
1.11	The default setting for the Energy Saver timer was changed from 5 minutes to 1
	minute.
1.10	Other changes:
	The firmware was modified to support the new Fujitsu hard disk drive.
1.09	No changes (version standardization with System firmware only).
1.08	Symptom corrected: [RPCS] 1. A P2 memory error occurs when using originals that use many clips. 2. A memory leak occurs when the resolution or bit number is changed. 3. Thin lines are not printed out when using 90-degree rotation in Mode 3. [PS3]
	 4. When a simplex job is performed in between two duplex jobs, the booklet direction from the first duplex job is automatically applied to the second duplex job. Other changes: 5. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.
1.07	A test print is not correctly counted.

Technical **B**ulletin

PAGE: 2/2

Reissued: 09-Jun-09

Model: Mo	odel K-P4	Date: 17-Feb-05	No.: RG116002h			
Version	Symptom Corrected					
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001) Other changes: The Summary Report can be printed out by turning ON the main power switch 					
1.05	while holding down the Start key. 2. Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine fire	mware history) for detai	ls.			
	Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03: 20 or later (P/N #G1115136C) 1. The printer sometimes stalls after it continuously prints out about 65K pages in duplex mode.					
1.04.2	 Sometimes, the keys on the operation per the Toner End condition. Sometimes, the machine stalls when a and then the job is cancelled. Other changes: Some features of a customization were - The IP address is displayed on the LCD - Thai and non-English Latin characters of the important: To use these new features, you together as a set. System v1.04 or later (P/N #G11654300 Printer v1.04.2 or later (P/N #G1165433) 	duplex job is sent from added as standard: can be printed with the I need to install all of the C)	an RPCS driver			
1.03	No changes (version standardization with S	System firmware only).				
1.01	1st Mass Production					

Technical Bulletin

PAGE: 1/2

Model: K-P4			Dat	e: 18-Sep-0)9	No.: RG116015
Subject: SC code	e correction			Prepared	by: Y. N	⁄lurata
From: 1st Tech.	Support Sec. Service Support I	Dept.				
Classification:		☐ Part informa		tion	Action	required
	☐ Mechanical	☐ Electric	al		⊠ Servic	e manual revision
	☐ Paper path	Transm	it/rec	eive	Retrof	fit information
	Other ()			ļ	⊠ Tier2	

Change/Reason: SC code correction.

1. Please delete the following SCs from the service manual. 640/641/800/822/835/836/837/862/955/999

2. Please add the following SCs to the service manual.

SC	Description	Cause / Required action
826	Self-diagnostic Error: RTC/optional	RTC defective.
	NVRAM	NVRAM without RTC installed.
	The RTC device is not detected.	Backup battery discharged.
		Replace the NVRAM with another
		NVRAM with an RTC device.
861	HDD: Reboot error	Loose connection.
	The HDD does not become ready	Defective cables.
	within 30 seconds after the power is	Defective HDD.
	supplied to the HDD.	Defective controller.
		Check the connection between the
		HDD and controller.
		2. Check and replace the cables.
		3. Replace the HDD.
		4. Replace the controller board.
866	SD card authentication error	SD-card data is corrupted.
	A correct license is not found in the	
	SD card.	Store correct data in the SD card.
867	SD card ejection error	The SD card is ejected from the slot.
		1. Install the SD card.
		2. Turn the main switch off and on.
868	The SD card is ejected from the slot.	An error report is sent from the SD card
		reader.
		 An error is detected in the SD card.
	• -13 to -3: File system error.	1. For a file system error, format the SD
	Other number: Device error.	card on your PC.
		2. For a device error, turn the mains
		switch off and on.
		3. Replace the SD card.
		4. Replace the controller board.



PAGE: 2/2

Model: K-P4 Date: 18-Sep-09 No.: RG116015

SC	Description	Cause / Required action
870	Address book error	Defective software program.Defective HDD.Incorrect path to the server.
	An error is detected in the data copied to the address book over a network.	 Initialize the address book data. Initialize the user information. Replace the HDD.
920	Printer application error An error is detected in the printer application program.	Defective software Unexpected hardware resource (e.g., memory shortage) Software defective; switch off/on, or change the controller firmware if the problem is not solved Install an optional memory.
921	Printer font error A necessary font is not found in the SD card.	 A necessary font is not found in the SD card. The SD card data is corrupted. Check that the SD card has the correct data.
992	Undefined error	Defective software program An error undetectable by any other SC code occurred

K	

RICOH	Tec	hnical B	<u>ulletin</u>		PAGE:	1/1
Model: K-P4			Date: 14-	Oct-09	No.: RG116016	
Subject: Part cat	alog correction		Prep	ared by: Y.	Murata	
From: 1st Tech.	Support Sec. Service Supp	port Dept.				
Classification:	Troubleshooting	⊠ Part info	rmation	Actio	on required	
	☐ Mechanical	☐ Electrica	al	☐ Ser	vice manual revisio	n
	☐ Paper path	☐ Transmi	it/receive	☐ Retro	ofit information	
	Other ()			☐ Tier2	2	

Change/Reason: Part catalog correction.

Incorrect	Correct	Description	Q'ty	Int	Page	Index
Part Number	Part Number	•			J	
G0881506	G1111203	COVER:FRONT:EU:ASS'Y(G116)	1	-	3	50
-	G1111206	COVER:FRONT:NA:ASS'Y(G116)	1	-	3	50

Technical Bulletin

PAGE: 1/3

Reissued: 28-Jan-10

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001i
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

· · · · · · · · · · · · · · · · · · ·							
Subject: Controller Firmware Release History (System)		Prepared by: K.Nakano					
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.							
Classification:	Troubleshooting	Part informa	_	Action required			
	☐ Mechanical	☐ Electrical	L	Service manual revision			
	☐ Paper path	☐ Transmit/rec	eive [Retrofit information			
	⊠ Other ()						

This RTB has been issued to announce the firmware history for the <u>System</u> of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.12	G1165430L	March 2010 production
1.11	G1165430K	July 2009 production
1.10	G1165430J	August 2008 production
1.09	G1165430H	July 2007 production
1.08	G1165430G	April 2007 production
1.07	G1165430F	October 2006 production
1.06	G1165430E	April '06 production
1.05	G1165430D	November '05 production
1.04	G1165430C	July '05 production
1.03	G1165430B	April '05 production
1.01	G1165430A	1st mass production (Jan 2005)

Descriptions of changes

Version	Symptom Corrected
1.12	Symptom corrected:
	Unable to connect to the network when the MAC address Ricoh vendor code is
	changed from 00-00-74 to the new address 00-26-73.
1.11	Symptom corrected:
	1. Device might not be able to access the network under the following conditions:
	 The device is connected to a HUB that has link flapping enabled.
	 The device "Ethernet speed" is not "Auto".
1.10	Other changes:
	The firmware was modified to support the new Fujitsu hard disk drive.
1.09	Symptom corrected:
	1. The image is shifted downward (as it should), but sometimes the bottom of the
	image appears on the next page.
	(Ex. When the Header/Footer/Adjust image position/Binding margins setting in
	the printer driver is changed)
	Note: Normally, the image is shifted downward and the bottom part is deleted
	(does not appear on the next page).
	Otherwale
	Other changes:
	2. New SP mode: SP5828-045.
	With this SP mode, Centronix can be enabled/disabled.

Technical Bulletin

PAGE: 2/3

Reissued: 28-Jan-10

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001i	
Version	Symptom Corrected			
1.08	Other changes: 1. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes. 2. SC868 occurrence conditions: From this version, the SC will not be displayed if a damaged SD card is inside the card slot when the main power is turned on.			
1.07	Sometimes, an image problem occurs with a large number of sheets.			
1.06	Sometimes, RC Gate cannot get the count	er data from the device		
1.05	 Sp5930-2 has been newly added. Note: See RTB RG116007a (Engine firmware history) for details. Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03: 20 or later (P/N #G1115136C) Sometimes, the firmware cannot be updated via RC Gate by FTP. Important: To apply this correction, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * NCS v4.15.2 or later (P/N #G1165432C) When the printer receives more than 300 login attempts since the last power ON: The administrator cannot login to the printer via WIM. Users cannot print if User Authentication is enabled. Sometimes, the ROM Update menu is not displayed in WIM (GFPR #RC05070002) 			
1.04 1. A communication error occurs between the mainframe 2. Sometimes, the firmware cannot be updated via RC G 3. The firmware cannot be updated if the administrator p 4. The image shifts when the left margin is set to 3mm. Other changes: 5. Some features of a customization were added as stan - Sp5-055-001 (Display IP Address): Displays the IP address on the second line of the printer is in the Ready condition. 0: OFF (default) 1: ON - Sp5-886-001 (ROM Update): Allows the ROM firmware to be updated remotely 0: ON (default) 1: OFF NOTE: The settings for the two SP modes above can be of Monitor. Important: To use these new features, you need to install together as a set.		dated via RC Gate. administrator password is set to 3mm. added as standard: cond line of the operation dated remotely via the load above can be changed	is blank. n panel when the cal network. via Web Image	

Technical Bulletin

PAGE: 3/3

Reissued: 28-Jan-10

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001i		
Version	on Symptom Corrected				
	System v1.04 or later (P/N #G1165430	,			
	Printer v1.04.2 or later (P/N #G1165441C)				
	Websys v1.02 or later (P/N #G1165433B)				
1.03	(Minor change applied for Japan model only).				
1.01	1st Mass Production				

Technical Bulletin

PAGE: 1/2

Reissued: 29-Jan-10

Model: Model (14 - 140: Halloude	Model: Model K-P4	Date: 21-Apr-06	No.: RG116003e
----------------------------------	-------------------	-----------------	----------------

RTB Reissue

The items in **bold italics** have been added.

The Reme in Dela Manee have been added.				
Subject: Controller Firmware Release History (NCS)			Prepared	d by: K.Nakano
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.				
Classification:	Troubleshooting	☐ Part informa	tion	Action required
		☐ Electrical		Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Other ()			

This RTB has been issued to announce the firmware release information for the NCS.

Version	Program No.	Effective Date
4.15.5	G1165432E	January 2010 production
4.15.4	G1165432D	July 2007 production
4.15.2	G1165432C	November '05 production
4.14.1	G1165432B	July '05 production
4.08.1	G1165432A	1st mass production (Jan 2005)

Version	Symptom Corrected
4.15.5	Other changes:
	1. Scan to Folder destinations located on Windows 7 or Windows Server 2008
	R2 can now be selected by browsing.
	2. The MFP now supports CIFS, DFS and NTLM v2.
4.15.4	Symptom corrected:
	1. IEEE 1284 job might result in the device to becoming locked in the Waiting state.
4.15.2	1. Sometimes, the firmware cannot be updated via RC Gate by FTP.
	Important: To apply this correction, you need to install all of the following firmware
	together as a set.
	* System v1.05 or later (P/N #G1165430D)
	* NCS v4.15.2 or later (P/N #G1165432C)
	2. Firmware update via WIM fails if the administrator uses a password or username
	that is 24 bytes or larger. After this, WIM may not connect to the device.
4.14.1	Note: NCS firmware Ver 4.14.1 or later must be used with websys firmware
	Ver1.02 or later.
	Websys v1.02 (P/N #G1165433B) or later
	NCS v4.14.1 (P/N #G1165432B) or later
	If the paper type setting is changed via WIM while "Permit Settings by SNMPv1 and v2" is disabled, the browser will timeout. The paper type setting change will
	not be saved.
	2. SNMPv1/v2 will still send SNMP traps even if the SNMPv1/v2 function is disabled.
	Sometimes after a power cycle, the device will be unable to accept jobs from standard TCP/IP or SDM ports.

Technical Bulletin

PAGE: 2/2

Reissued: 30-Jun-05

Model: Model K-P4		Date: 21-Apr-06	No.: RG116003c
Version	Sympton	n Corrected	
	 4. The SNMP buffer may become full when a lot of SNMP traffic is sent to the device. As a result, the device cannot reply to SNMP requests. 5. SDM for Admin cannot retrieve 1394 hostnames and devices when it is installed on a client PC with 1394 and Ethernet interfaces. 6. The SNMP service may not start when the device is turned on. Utilities using SNMP do not receive status updates from the device. Other changes: Some features of a customization were added as standard: The device can accept more than one diprint (port9100) session. Communication via diprint (port 9100) is asynchronous. 		
4.08.1	1st Mass Production		

Technical Bulletin

PAGE: 1/2 Reissued: 02-Feb-10

Date: 17-Feb-05

No.: RG116002i

Model: Model K-P4	
RTB Reissue	

The items in bold italics have been added

The Reme in Bola Railed have been added.				
Subject: Controller Firmware Release History (Printer)			Prepared	d by: K.Nakano
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.				
Classification:	☐ Troubleshooting	☐ Part informat	ion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	Other ()	☑ Tier 2

This RTB has been issued to announce the firmware history for the Printer of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.12	G1165441L	March 2010 production
1.11	G1165441K	July 2009 production
1.10	G1165441J	August 2008 production
1.09	G1165441H	July 2007 production
1.08	G1165441G	April 2007 production
1.07	G1165441F	October 2006 production
1.06	G1165441E	April '06 production
1.05	G1165441D	November '05 production
1.04.2	G1165441C	July '05 production
1.03	G1165441B	April '05 production
1.01	G1165441A	1st mass production (Jan 2005)

Version	Symptom Corrected
1.12	Symptom corrected:
	Following a paper jam caused by a paper size mismatch, the "Load the correct
	paper size" alert message is cleared when the paper tray is opened and closed.
1.11	The default setting for the Energy Saver timer was changed from 5 minutes to 1
	minute.
1.10	Other changes:
	The firmware was modified to support the new Fujitsu hard disk drive.
1.09	No changes (version standardization with System firmware only).
1.08	Symptom corrected: [RPCS] 1. A P2 memory error occurs when using originals that use many clips. 2. A memory leak occurs when the resolution or bit number is changed. 3. Thin lines are not printed out when using 90-degree rotation in Mode 3. [PS3] 4. When a simplex job is performed in between two duplex jobs, the booklet direction from the first duplex job is automatically applied to the second duplex job.

Technical Bulletin

PAGE: 2/2

Reissued: 02-Feb-10

Model: Mo	No.: RG116002i				
Version		n Corrected			
	Other changes: 5. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.				
1.07	A test print is not correctly counted.				
1.06	 Sending jobs to IBS (Intelligence Barcode Solution) might cause the device to stall if submitted via USB, Centronix or Bluetooth. When PCL data is printed using HDD fonts, print speed might be reduced. After a certain number of PCL jobs are printed using HDD fonts, the device may stall. (GFPR#RE05060001) Other changes: The Summary Report can be printed out by turning ON the main power switch 				
	while holding down the Start key.				
1.05	2. Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine firmware history) for details. Important: To use the above new feature, you need to install all of the following firmware together as a set. * System v1.05 or later (P/N #G1165430D) * Printer v1.05 or later (P/N #G1165441D * Engine v1.03: 20 or later (P/N #G1115136C)				
	The printer sometimes stalls after it conduplex mode.	ntinuously prints out ab	out 65K pages in		
1.04.2	 Sometimes, the keys on the operation per the Toner End condition. Sometimes, the machine stalls when a and then the job is cancelled. Other changes: Some features of a customization were - The IP address is displayed on the LCD - Thai and non-English Latin characters of the tone of the ton	duplex job is sent from added as standard:	an RPCS driver		
	Important: To use these new features, you together as a set. System v1.04 or later (P/N #G11654300 Printer v1.04.2 or later (P/N #G1165443 Websys v1.02 or later (P/N #G1165433	C) IC)	e following firmware		
1.03	No changes (version standardization with S	System firmware only).			
1.01	1st Mass Production				

7	_

RICOH	l echr	nical B	ull	<u>etın </u>		PAGE: 1/1
Model: K-P4			Date: 24-Feb-10		No.: RG116017	
Subject: Service Manual Correction				Prepare	d by: K. N	Nakano
From: 2nd Overs	eas Tech Support Sec. 2nd F	PQM Dept				
Classification:		☐ Part inf	orma	tion	Action	n required
	☐ Mechanical	☐ Electric	al		⊠ Servic	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	Other ()				⊠ Tier2	

Service Manual Correction

5.3.1 SERVICE MODE TABLE (pg. 5-3)

Corrected the fusing temperature range to "150~190".

		
1105	Fusing Temp.	
	Adjusts the fusing temperatu	res fol\printing and standby mode.
1105 1	Fusing temp	[150 ~ 200/ 170 / 5 deg.] DFU
		re for printing on normal paper.
1105 2	Fusing T Stand	[140 ~ 175 / 168 / 1 deg.] DFU
	Adjusts the fusing temperatu	re for standby mode.

Note: If you try to set the fusing temperature to a value higher than 190, the machine will not accept the setting.

Model: Model K-P4

Technical Bulletin

PAGE: 1/2 Reissued: 21-Sep-10

Date: 17-Feb-05

No.: RG116002j

RTB Reissue

The items in bold italics have been added

The Reme in Sele Railes have Seen added.					
Subject: Controller Firmware Release History (Printer)			Prepare	d by: K.Nakano	
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.					
Classification:	☐ Troubleshooting	☐ Part informat	tion	Action required	
	☐ Mechanical	☐ Electrical		☐ Service manual revision	
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information	
	☐ Product Safety	Other ()	☐ Tier 2	

This RTB has been issued to announce the firmware history for the Printer of the Model K-P4 (G116 model).

Version	Program No.	Effective Date
1.13	G1165441M	October 2010 production
1.12	G1165441L	March 2010 production
1.11	G1165441K	July 2009 production
1.10	G1165441J	August 2008 production
1.09	G1165441H	July 2007 production
1.08	G1165441G	April 2007 production
1.07	G1165441F	October 2006 production
1.06	G1165441E	April '06 production
1.05	G1165441D	November '05 production
1.04.2	G1165441C	July '05 production
1.03	G1165441B	April '05 production
1.01	G1165441A	1st mass production (Jan 2005)

Version	Symptom Corrected					
1.13	Symptom corrected:					
	If the Auto Continue setting is "Immediate" and the source tray runs out of					
	paper, the device will stall. This only occurred if the paper ran out after several					
	small jobs (30 or 40) were submitted back to back.					
1.12	Symptom corrected:					
	Following a paper jam caused by a paper size mismatch, the "Load the correct paper					
	size" alert message is cleared when the paper tray is opened and closed.					
1.11	The default setting for the Energy Saver timer was changed from 5 minutes to 1					
	minute.					
1.10	Other changes:					
	The firmware was modified to support the new Fujitsu hard disk drive.					
1.09	No changes (version standardization with System firmware only).					
1.08	Symptom corrected:					
	[RPCS]					
	1. A P2 memory error occurs when using originals that use many clips.					
	2. A memory leak occurs when the resolution or bit number is changed.					
	3. Thin lines are not printed out when using 90-degree rotation in Mode 3.					
	·					

Technical Bulletin

PAGE: 2/2

Reissued: 21-Sep-10

Model: Model K-P4 Date: 17-Feb-05 No.: RG116002j					
Version	, .	n Corrected			
	[PS3]4. When a simplex job is performed in between two duplex jobs, the booklet direction from the first duplex job is automatically applied to the second duplex job.				
	Other changes: 5. The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes.				
1.07	A test print is not correctly counted.				
1.06	 Sending jobs to IBS (Intelligence Barch stall if submitted via USB, Centronix or 2. When PCL data is printed using HDD and the stall. (GFPR#RE05060001) 	Bluetooth. fonts, print speed might	be reduced.		
	Other changes: 1. The Summary Report can be printed out while holding down the Start key.	ut by turning ON the ma	in power switch		
1.05	Sp5930-2 has newly been added. Note: See RTB RG116007a (Engine firmware history) for details.				
	Important: To use the above new feature firmware together as a set. * System v1.05 or later (P/N #G116543) * Printer v1.05 or later (P/N #G116544) * Engine v1.03: 20 or later (P/N #G111) 1. The printer sometimes stalls after it co	30D) 1D 5136C)			
	duplex mode.		, 0		
1.04.2	 Sometimes, the keys on the operation panel do not work when the machine is in the Toner End condition. Sometimes, the machine stalls when a duplex job is sent from an RPCS driver and then the job is cancelled. Other changes: 				
	3. Some features of a customization were added as standard: - The IP address is displayed on the LCD. - Thai and non-English Latin characters can be printed with the PS driver				
	Important: To use these new features, you together as a set. System v1.04 or later (P/N #G1165430 Printer v1.04.2 or later (P/N #G116544 Websys v1.02 or later (P/N #G1165433	C) 1C)	e following firmware		
1.03	No changes (version standardization with System firmware only).				
1.01	1st Mass Production				
1.01	IST Wass Production				

Technical Bulletin

PAGE: 1/3

Reissued: 29-Jul-14

Model: Model K-P4	Date: 17-Feb-05	No.: RG116001j
-------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

The following that a second descent						
Subject: Controll	er Firmware Release History (Prepared by: Y. Nishida				
From: 3rd Tech Service Sect., MFP/Printer Tech Service Dept.						
Classification:	☐ Troubleshooting	☐ Part information	☐ Action required			
	☐ Mechanical	☐ Electrical	☐ Service manual revision			
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information			
	☐ Product Safety	Other (Firmware)	⊠ Tier 2			

This RTB has been issued to announce the firmware history for the **System** of the Model K-P4 (G116 model).

Version	Program No.	Effective Date	Availability of RFU
1.12k1	G1165430L_LRP02572	July 2014 production	Available
1.12	G1165430L	March 2010 production	Available
1.11	G1165430K	July 2009 production	Available
1.10	G1165430J	August 2008 production	Available
1.09	G1165430H	July 2007 production	Available
1.08	G1165430G	April 2007 production	Available
1.07	G1165430F	October 2006 production	Available
1.06	G1165430E	April '06 production	Available
1.05	G1165430D	November '05 production	Available
1.04	G1165430C	July '05 production	Available
1.03	G1165430B	April '05 production	Available
1.01	G1165430A	1st mass production (Jan 2005)	Available

Note: Definition of Availability of RFU via @Remote

Descriptions of changes

Version	Symptom Corrected		
1.12k1	Symptom corrected: 1. If a host on the network (not the LP) has 2 network cards with the same IP		
	address, the LP's print/copy quality might be reduced or an SC818 error will be shown on the operation panel.		
1.12	Symptom corrected: Unable to connect to the network when the MAC address Ricoh vendor code is changed from 00-00-74 to the new address 00-26-73.		
1.11	Symptom corrected: 1. Device might not be able to access the network under the following conditions: - The device is connected to a HUB that has link flapping enabled. - The device "Ethernet speed" is not "Auto".		
1.10	Other changes: The firmware was modified to support the new Fujitsu hard disk drive.		
1.09	Symptom corrected: 1. The image is shifted downward (as it should), but sometimes the bottom of the image appears on the next page.		

[&]quot;Available" The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Technical **B**ulletin

PAGE: 2/3

Reissued: 29-Jul-14

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001j		
Version	Symptom Corrected				
	(Ex. When the Header/Footer/Adjust image position/Binding margins setting in the printer driver is changed) Note: Normally, the image is shifted downward and the bottom part is deleted (does not appear on the next page).				
	Other changes: 2. New SP mode: SP5828-045. With this SP mode, Centronix can be e	nabled/disabled.			
1.08	 Other changes: The default setting for the Energy Saver timer was changed from 15 minutes to 5 minutes. SC868 occurrence conditions: From this version, the SC will not be displayed if a damaged SD card is inside the card slot when the main power is turned on. 				
1.07	 Sometimes, an image problem occurs or the machine stalls while printing a job with a large number of sheets. 				
1.06	Sometimes, RC Gate cannot get the counter data from the device.				
1.05	Note: See RTB RG116007a (Engine firmware history) for details.				
	Important: To use the above new featur firmware together as a set. * System v1.05 or later (P/N #G116543 * Printer v1.05 or later (P/N #G116544 * Engine v1.03: 20 or later (P/N #G111	30D) 1D	TOT THE TOHOWING		
	2. Sometimes, the firmware cannot be upd Important: To apply this correction, you together as a set. * System v1.05 or later (P/N #G116543: * NCS v4.15.2 or later (P/N #G116543: * NC	need to install all of the			
	 3. When the printer receives more than 3 The administrator cannot login to t Users cannot print if User Authent 4. Sometimes, the ROM Update menu is #RC05070002) 	he printer via WIM. ication is enabled.	·		
1.04	 A communication error occurs between Sometimes, the firmware cannot be upod The firmware cannot be updated if the additional error occurs between The firmware cannot be updated if the additional error occurs between The image shifts when the left margin is other changes: Some features of a customization were - Sp5-055-001 (Display IP Address): Displays the IP address on the security printer is in the Ready condition. OFF (default) ON Sp5-886-001 (ROM Update): 	dated via RC Gate. administrator password is set to 3mm. added as standard:	is blank.		

Technical Bulletin

PAGE: 3/3

Reissued: 29-Jul-14

Model: Model K-P4		Date: 17-Feb-05	No.: RG116001j		
Version	Symptom Corrected				
	Allows the ROM firmware to be updated remotely via the local network. 0: ON (default) 1: OFF				
	NOTE: The settings for the two SP modes above can be changed via Web Image Monitor.				
	Important: To use these new features, you need to install all of the following firmware together as a set.				
	System v1.04 or later (P/N #G1165430C)				
	Printer v1.04.2 or later (P/N #G1165441C)				
	Websys v1.02 or later (P/N #G1165433	3B)			
1.03	(Minor change applied for Japan model on	ly).			
1.01	1st Mass Production				