

Reissued: 05-Oct-16

| | | |
|----------------|----------------|----------------|
| Model: BRG-G1b | Date: 8-May-12 | No.: RJ028001k |
|----------------|----------------|----------------|

RTB Reissue

The items in ***bold italics*** have been corrected or added.

| | | | |
|--|---|---|---|
| Subject: Firmware Release Note: Engine/Controller | | Prepared by: Y. Saitoh | |
| From: 1 st Tech Service Sect., MFP/Printer Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Engine/Controller**.

| Version | Program No. | Effective Date | Availability of RFU |
|---------------------|----------------------------------|---------------------------------------|-----------------------------|
| <i>2.4.0</i> | <i>J0285610L_P1b_v240</i> | <i>October 2016 production</i> | <i>Not Available</i> |
| 2.3.1 | J0285610K_P1b_v231 | June 2016 production | Not Available |
| 2.3.0 | J0285610J_P1b_v230 | April 2016 production | Not Available |
| 2.1.1 | J0285610G_P1b_211 | October 2014 production | Not Available |
| 2.0.9 | J0285614F_v209 | March 2014 production | Not Available |
| 2.0.6 | J0285614F_TC120617 | June 2013 production | Not Available |
| 2.0.4 | J0285614F | April 2013 production | Not Available |
| 1.2.2 | J0285614E_RPCSE1020 | March 2013 production | Not Available |
| 1.2.0 | J0285614E | December 2012 production | Not Available |
| 1.1.2 | J0285614D | October 2012 production | Not Available |
| 1.1.0 | J0285614C | July 2012 production | Not Available |
| 1.0.8 | J0285614B | May 2012 production | Not Available |
| 1.0.0 | J0285614 | 1st Mass production | Not Available |

Note: Definition of Availability of RFU via @Remote
"Available" The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------------------|---|
| <i>2.4.0</i> | <i>Other Changes:</i> - <i>Support for the Lot 6 regulation.</i> <i>Symptom Corrected:</i> - <i>The system cannot recover from the energy saving mode, if a USB cable is connected to the machine during energy saving mode.</i> |
| 2.3.1 | Symptom Corrected: The LED does not light up in the correct sequence, if the network cable is connected to the machine. |
| 2.3.0 | Specification Change: - Support for the Portuguese orthography. Error Correction: - The printer may not recover from Energy Saver mode. - Version information of Web Image Monitor for Windows 10 appears in garbled |

Reissued: 05-Oct-16

| Model: BRG-G1b | | Date: 8-May-12 | No.: RJ028001k |
|----------------|---|----------------|----------------|
| Version | Modified Points or Symptom Corrected | | |
| | characters. - Printer may stall when printing particular websites using Internet Explorer. | | |
| 2.1.1 | Symptoms corrected: 1. Occasionally printing stops between pages. 2. Left edge of image is erased when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 3. Occasionally image is printed outside of the paper width (on the belt) when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 4. Other minor bugs. | | |
| 2.0.9 | Symptoms corrected: 1. The image may shift about 1mm from the second page on. 2. The printer may not power up after the firmware is updated. (To clear the condition, the power cord needs to be unplugged and plugged back in). 3. The printer may not recover from Energy Saver mode if a cover is opened right after the machine enters the mode. 4. The System Timer of the printer is not accurate. 5. Other minor bugs were fixed. | | |
| 2.0.6 | Symptoms corrected: 1. Occasionally one of the two option trays is not recognized when the printer is turned on. 2. The drive motor may not stop rotation after opening the duplex unit cover for jam removal. 3. Paper size error may occur when using the by-pass tray. 4. The printer stalls when ink end and paper end occurs at the same time. 5. Some settings are not reset when initializing the network setting. 6. Occasionally the ink status is not correctly indicated on Web Image Monitor. 7. Other minor bugs. | | |
| 2.0.4 | Symptoms corrected: 1. A firmware update may be interrupted if a print job is sent via WIM while the update is in progress. 2. The incorrect IP address is sent to the @Remote center server when DHCP is selected. 3. Other minor bugs were corrected. Other changes: Supports Embedded RC Gate functions. | | |
| 1.2.2 | Symptoms corrected: 1. Printer hangs after ejecting a blank sheet. 2. Occasionally a print job is automatically canceled during network printing. 3. E-mails are sent out even if Off is selected for the mail notification setting. 4. Half tone on the right edge of print becomes partially uneven. 5. Printer hangs during a long print job. 6. Other minor bugs | | |
| 1.2.0 | Specification Change: 1. Functions of user code registration and access control have been added. 2. User operation for wireless LAN setting has been improved. Symptom corrected: "Tray 3 rear cover open" is mis-detected even if the optional tray is not installed. | | |

Reissued: 05-Oct-16

| Model: BRG-G1b | | Date: 8-May-12 | No.: RJ028001k |
|----------------|---|----------------|----------------|
| Version | Modified Points or Symptom Corrected | | |
| 1.1.2 | Symptoms corrected: Occasionally black counter counts up for duplex prints of color image. Occasionally main power turns off during energy saver mode. Other minor bugs | | |
| 1.1.0 | Symptoms corrected: The printer performs unnecessary head cleaning if the user changes the time setting from the operation panel. The Finnish wording for "Duplex Print" has been corrected. An incorrect font is used for some languages. Vertical magenta lines may appear broken (not continuous) when printing out the nozzle check pattern. Other minor bugs were corrected. | | |
| 1.0.8 | Symptoms corrected from version 1.0.1 to 1.0.8: Auto tray switching sometimes does not work when paper runs out. Polish characters on the counter page are garbled. "Printing" message does not disappear when duplex prints are made with "mixed size" original. Paper end message is displayed after printing one page if another tray is selected to continue the print after paper runs out of the tray. LCD display turns off when detaching the optional bypass tray or paper tray. The machine rarely does not recover from Energy Saver mode when receiving a print job. Characters are slightly blurred if the width of the image area in main scan direction is narrow. The drive motor control has been modified to improve the stability of the carriage movement. Other minor bugs | | |
| 1.0.0 | 1st Mass production | | |

Reissued: 31-Mar-17

| | | |
|----------------|-----------------|----------------|
| Model: BRG-G1c | Date: 08-May-12 | No.: RJ028002n |
|----------------|-----------------|----------------|

RTB Reissue

The items in ***bold italics*** have been corrected or added.

| | | | |
|--|--|--|--|
| Subject: Firmware Release Note: Engine/Controller | | Prepared by: Y. Saitoh | |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information | <input type="checkbox"/> Action required |
| | <input type="checkbox"/> Mechanical | <input type="checkbox"/> Electrical | <input type="checkbox"/> Service manual revision |
| | <input type="checkbox"/> Paper path | <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Retrofit information |
| | <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Engine/Controller**.

| Version | Program No. | Effective Date | Availability of RFU |
|---------------------|----------------------------------|-------------------------------------|-----------------------------|
| <i>2.4.1</i> | <i>J0285610L_P1c_v241</i> | <i>March 2017 production</i> | <i>Not Available</i> |
| 2.4.0 | J0285610L_P1c_v240 | October 2016 production | Not Available |
| 2.3.1 | J0285610K_P1c_v231 | June 2016 production | Not Available |
| 2.3.0 | J0285610J_P1c_v230 | April 2016 production | Not Available |
| 2.2.0 | J0285610H_P1c_220 | October 2015 production | Not Available |
| 2.1.1 | J0285610G_P1c_211 | October 2014 production | Not Available |
| 2.0.9 | J0295614F_v209 | March 2014 production | Not Available |
| 2.0.6 | J0295614F_TC120617 | June 2013 production | Not Available |
| 2.0.4 | J0295614F | April 2013 production | Not Available |
| 1.2.2 | J0295614E_RPCSE1020 | March 2013 production | Not Available |
| 1.2.0 | J0295614E | December 2012 production | Not Available |
| 1.1.2 | J0295614D | October 2012 production | Not Available |
| 1.1.0 | J0295614C | July 2012 production | Not Available |
| 1.0.8 | J0295614B | May 2012 production | Not Available |
| 1.0.0 | J0295614 | 1st Mass production | Not Available |

Note: Definition of Availability of RFU via @Remote
"Available" The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------------------|---|
| <i>2.4.1</i> | <i>Other Change:</i> <i>Improved the connectivity of wireless LAN.</i> |
| 2.4.0 | Other Changes: - Support for the Lot 6 regulation. Symptom Corrected: - The system cannot recover from the energy saving mode, if a USB cable is connected to the machine during energy saving mode. |
| 2.3.1 | Symptom Corrected: The LED does not light up in the correct sequence, if the network cable is connected to the machine. |
| 2.3.0 | Specification Change: - Support for the Portuguese orthography. |

Reissued: 31-Mar-17

| Model: BRG-G1c | | Date: 08-May-12 | No.: RJ028002n |
|----------------|--|-----------------|----------------|
| Version | Modified Points or Symptom Corrected | | |
| | Error Correction: <ul style="list-style-type: none"> - The printer may not recover from Energy Saver mode. - Version information of Web Image Monitor for Windows 10 appears in garbled characters. - Printer may stall when printing particular websites using Internet Explorer. | | |
| 2.2.0 | Error Correction: Network security was enhanced. | | |
| 2.1.1 | Symptoms corrected: <ol style="list-style-type: none"> 1. Occasionally printing stops between pages. 2. Left edge of image is erased when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 3. Occasionally image is printed outside of the paper width (on the belt) when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 4. Other minor bugs. | | |
| 2.0.9 | Symptoms corrected: <ol style="list-style-type: none"> 1. The image may shift about 1mm from the second page on. 2. The printer may not power up after the firmware is updated. (To clear the condition, the power cord needs to be unplugged and plugged back in). 3. The printer may not recover from Energy Saver mode if a cover is opened right after the machine enters the mode. 4. The System Timer of the printer is not accurate. 5. Other minor bugs were fixed. | | |
| 2.0.6 | Symptoms corrected: <ol style="list-style-type: none"> 1. Occasionally one of the two option trays is not recognized when the printer is turned on. 2. The drive motor may not stop rotation after opening the duplex unit cover for jam removal. 3. Paper size error may occur when using the by-pass tray. 4. The printer stalls when ink end and paper end occurs at the same time. 5. Some settings are not reset when initializing the network setting. 6. Occasionally the ink status is not correctly indicated on Web Image Monitor. 7. Other minor bugs. | | |
| 2.0.4 | Symptoms corrected: <ol style="list-style-type: none"> 1. A firmware update may be interrupted if a print job is sent via WIM while the update is in progress. 2. The incorrect IP address is sent to the @Remote center server when DHCP is selected. 3. Other minor bugs were corrected. Other changes: Supports Embedded RC Gate functions. | | |
| 1.2.2 | Symptoms corrected: <ol style="list-style-type: none"> 1. Printer hangs after ejecting a blank sheet. 2. Occasionally a print job is automatically canceled during network printing. 3. E-mails are sent out even if Off is selected for the mail notification setting. 4. Half tone on the right edge of print becomes partially uneven. 5. Printer hangs during a long print job. 6. Other minor bugs | | |

Reissued: 31-Mar-17

| Model: BRG-G1c | | Date: 08-May-12 | No.: RJ028002n |
|----------------|---|-----------------|----------------|
| Version | Modified Points or Symptom Corrected | | |
| 1.2.0 | Specification Change: 1. Functions of user code registration and access control have been added. 2. User operation for wireless LAN setting has been improved. Symptom corrected: "Tray 3 rear cover open" is mis-detected even if the optional tray is not installed. | | |
| 1.1.2 | Symptoms corrected: Occasionally black counter counts up for duplex prints of color image. Occasionally main power turns off during energy saver mode. Other minor bugs | | |
| 1.1.0 | Symptoms corrected: The printer performs unnecessary head cleaning if the user changes the time setting from the operation panel. The Finnish wording for "Duplex Print" has been corrected. An incorrect font is used for some languages. Vertical magenta lines may appear broken (not continuous) when printing out the nozzle check pattern. Other minor bugs were corrected. | | |
| 1.0.8 | Symptoms corrected from version 1.0.1 to 1.0.8: Auto tray switching sometimes does not work when paper runs out. Polish characters on the counter page are garbled. "Printing" message does not disappear when duplex prints are made with "mixed size" original. Paper end message is displayed after printing one page if another tray is selected to continue the print after paper runs out of the tray. LCD display turns off when detaching the optional bypass tray or paper tray. The machine rarely does not recover from Energy Saver mode when receiving a print job. Characters are slightly blurred if the width of the image area in main scan direction is narrow. The drive motor control has been modified to improve the stability of the carriage movement. Other minor bugs | | |
| 1.0.0 | 1st Mass production | | |

Reissued: 19-Apr-16

| | | |
|----------------|-----------------|----------------|
| Model: BRG-G1L | Date: 08-May-12 | No.: RJ028003j |
|----------------|-----------------|----------------|

RTB Reissue

The items in ***bold italics*** have been corrected or added.

| | | | |
|--|--|--|--|
| Subject: Firmware Release Note: Engine/Controller | | Prepared by: Y. Saitoh | |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information | <input type="checkbox"/> Action required |
| | <input type="checkbox"/> Mechanical | <input type="checkbox"/> Electrical | <input type="checkbox"/> Service manual revision |
| | <input type="checkbox"/> Paper path | <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Retrofit information |
| | <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Other (Firmware) | <input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Engine/Controller**.

| Version | Program No. | Effective Date | Availability of RFU |
|--------------|------------------------------------|------------------------------------|-----------------------------|
| 2.3.0 | <i>J0255620A_P1LEXP_230</i> | <i>June 2016 production</i> | <i>Not Available</i> |
| 2.1.1 | J0255620_P1LEXP_211 | October 2014 production | Not Available |
| 2.0.9 | J0255614E_209 | February 2014 production | Not Available |
| 2.0.7 | J0255614E_207 | August 2013 production | Not Available |
| 2.0.6 | J0255614E_TC120617 | June 2013 production | Not Available |
| 2.0.4 | J0255614E | April 2013 production | Not Available |
| 1.2.2 | J0255614D_RPCSE1020 | March 2013 production | Not Available |
| 1.2.0 | J0255614C | December 2012 production | Not Available |
| 1.1.1 | J0255614A-SYOUENE | October 2012 production | Not Available |
| 1.0.9 | J0255614A | July 2012 production | Not Available |
| 1.0.8 | J0255614 | May 2012 production | Not Available |
| 1.0.0 | J0255604 | 1st Mass production | Not Available |

Note: Definition of Availability of RFU via @Remote
"Available" The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|--------------|--|
| 2.3.0 | <i>Specification Change:</i> - <i>Support of the revised Portuguese orthography.</i> <i>Error Correction:</i> - <i>Version information of Web Image Monitor for Windows 10 appears in garbled characters.</i> - <i>Security enhanced for Logjam Attack.</i> |
| 2.1.1 | Symptoms corrected: 1. Occasionally printing stops between pages. 2. Left edge of image is erased when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 3. Occasionally image is printed outside of the paper width (on the belt) when "Use Preprinted/Prepunched Paper" is selected on the Paper tab. 4. Other minor bugs. |
| 2.0.9 | Symptoms corrected: 1. The image may shift about 1mm from the second page on. |

Reissued: 19-Apr-16

| Model: BRG-G1L | | Date: 08-May-12 | No.: RJ028003j |
|----------------|---|-----------------|----------------|
| | 2. The printer may not power up after the firmware is updated. (To clear the condition, the power cord needs to be unplugged and plugged back in). 3. The printer may not recover from Energy Saver mode if a cover is opened right after the machine enters the mode. 4. The System Timer of the printer is not accurate. 5. Other minor bugs were fixed. | | |
| 2.0.7 | Symptoms corrected: Printer may stall when a print Job is sent during Energy Saver mode. | | |
| 2.0.6 | Symptoms corrected: 1. Occasionally one of the two option trays is not recognized when the printer is turned on. 2. The drive motor may not stop rotation after opening the duplex unit cover for jam removal. 3. Paper size error may occur when using the by-pass tray. 4. The printer stalls when ink end and paper end occurs at the same time. 5. Some settings are not reset when initializing the network setting. 6. Occasionally the ink status is not correctly indicated on Web Image Monitor. 7. Other minor bugs. | | |
| 2.0.4 | Symptoms corrected: 1. A firmware update may be interrupted if a print job is sent via WIM while the update is in progress. 2. The incorrect IP address is sent to the @Remote center server when DHCP is selected. 3. Other minor bugs were corrected. Other changes: Supports Embedded RC Gate functions. | | |
| 1.2.2 | Symptoms corrected: 1. Printer hangs after ejecting a blank sheet. 2. Occasionally a print job is automatically canceled during network printing. 3. E-mails are sent out even if Off is selected for the mail notification setting. 4. Half tone on the right edge of print becomes partially uneven. 5. Printer hangs during a long print job. 6. Other minor bugs | | |
| 1.2.0 | Specification Change: 1. Functions of user code registration and access control have been added. 2. User operation for wireless LAN setting has been improved. Symptom corrected: "Tray 3 rear cover open" is mis-detected even if the optional tray is not installed. | | |
| 1.1.1 | Modifications from ver. 1.0.9 to 1.1.1. Symptoms corrected: Occasionally main power turns off during energy saver mode. | | |
| 1.0.9 | Symptoms corrected: 1. The printer performs unnecessary head cleaning if the user changes the time setting from the operation panel. 2. The Finnish wording for "Duplex Print" has been corrected. 3. An incorrect font is used for some languages. 4. Vertical magenta lines may appear broken (not continuous) when printing out the nozzle check pattern. 5. Other minor bugs were corrected. | | |

Reissued: 19-Apr-16

| | | |
|----------------|--|----------------|
| Model: BRG-G1L | Date: 08-May-12 | No.: RJ028003j |
| 1.0.8 | <p>Symptoms corrected from version 1.0.1 to 1.0.8:</p> <ol style="list-style-type: none">1. Auto tray switching sometimes does not work when paper runs out.2. Polish characters on the counter page are garbled.3. "Printing" message does not disappear when duplex prints are made with "mixed size" original.4. Paper end message is displayed after printing one page if another tray is selected to continue the print after paper runs out of the tray.5. LCD display turns off when detaching the optional bypass tray or paper tray.6. The machine rarely does not recover from Energy Saver mode when receiving a print job.7. Characters are slightly blurred if the width of the image area in main scan direction is narrow. The drive motor control has been modified to improve the stability of the carriage movement.8. Other minor bugs | |
| 1.0.0 | 1st Mass production | |

| | | |
|---------------|-----------------|---------------|
| Model: BRG-G1 | Date: 19-Dec-12 | No.: RJ028004 |
|---------------|-----------------|---------------|

| | | | |
|---|---|---|--|
| Subject: No display on the operation panel | | Prepared by: Yoh Ohi | |
| From: 3rd Tech Service Sect.,MFP/P Tech Service Dept. | | | |
| Classification: | <input checked="" type="checkbox"/> Troubleshooting | <input type="checkbox"/> Part information | <input type="checkbox"/> Action required |
| | <input type="checkbox"/> Mechanical | <input type="checkbox"/> Electrical | <input type="checkbox"/> Service manual revision |
| | <input type="checkbox"/> Paper path | <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Retrofit information |
| | <input type="checkbox"/> Product Safety | <input type="checkbox"/> Other () | <input checked="" type="checkbox"/> Tier 2 |

SYMPTOM

Nothing is displayed on the LCD after the main switch is turned on, and the main power cannot be turned off with the main switch.

CAUSE

The customer mistakenly connects a USB cable or LAN cable to the drawer connector of the by-pass tray while the machine power is still on. As a result, over-current may flow through the controller board circuit and damage the transistor.

Note: There is no possibility of damage to the PC.

The following show the correct and incorrect ways to connect the drawer connector (photos show the rear side of the machine):

CORRECT connection of the drawer connector:



INCORRECT connection of the drawer connector:



LAN cable



USB cable (small end)



USB cable (large end)

Model: BRG-G1

Date: 19-Dec-12

No.: RJ028004

SOLUTION**Production line**

The controller board circuit has been modified to protect the board from over-current.

Applied from: March 2012 production

In the field

Do the following if the symptom occurs:

- Replace the controller board.
- Advise the customer never to connect a USB or LAN cable to the drawer connector port. Also advise the customer on the correct ports to connect the LAN and USB cables, as shown in the photos below.
-

The following show the correct ports to connect the USB and LAN cables to (photos show the left side of the machine):



LAN cable



USB cable (small end)

Reissued:8-Feb-13


| | | | |
|---|--|---|---|
| Model: BRG-G1L | | Date: 20-Dec-12 | No.: RJ028005a |
| Subject: Broken Pivot of Roller Tension Spring | | Prepared by: Junji Mochizuki | |
| From: 3rd Tech Service Sect.,MFP/P Tech Service Dept. | | | |
| Classification: | <input checked="" type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2 |

RTB Reissue: A retrofit part number has been registered.

SYMPTOM

The fulcrum for the roller tension spring breaks.

Note: With normal paper types, paper jams and paper skew do not occur. With thick or small-sized paper types, a paper jam may occur.



CAUSE

The oil on the tension spring causes the plastic pivot to corrode, reducing its strength.

SOLUTION

Production line

The tension spring was changed to an oil-free nickel-plated spring (Applied from: Sept. 2012 production).

In the field

If a paper jam or paper skew occurs due to a broken fulcrum, replace the guide plate assembly (**J0252758**). [If this problem occurs, a replacement part can be ordered with a retrofit part number J0271551 \(=J0252758\).](#)

Note: All service parts in stock have been replaced with modified ones.

| | | |
|---------------|-----------------|---------------|
| Model: BRG-G1 | Date: 18-Mar-13 | No.: RJ028006 |
|---------------|-----------------|---------------|


| | | |
|---|---|---|
| Subject: Collar – Paper Feed Roller | | Prepared by: Junji Mochizuki |
| From: 3rd Tech Service Sect.,MFP/P Tech Service Dept. | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () |
| | | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2 |

To eliminate the scraping noise of the feed roller collars [A], the stopper [B] of the collar has been changed to a retaining ring [C]. The shaft [D] of the roller has also been changed to fit the groove with the retaining ring.


The part numbers have been changed as follows.

| Old P/N | New P/N | Description | Q'ty | I/C |
|----------|----------|----------------------------|------|-----------------------|
| J0253014 | J0343014 | Collar - Paper Feed Roller | 2 | X/X X/O as a set |
| J0253045 | J0253043 | Shaft – Paper Feed | 1 | X/X |
| | A0100011 | Retaining Ring | 2 | |

Old



New



Model: BRG-G1

Date: 18-Mar-13

No.: RJ028006

Cut-in S/N

| Model | Cut-in SN |
|---------|-------------|
| J027-22 | R602Q40001~ |
| J027-27 | R602Q40001~ |
| J028-17 | R612Q40001~ |
| J028-22 | R612Q40001~ |
| J028-27 | R612Q30035~ |
| J029-17 | R613Q40001~ |
| J029-22 | R613Q40001~ |
| J029-27 | R613Q40001~ |

| | | | |
|---|---|--|--|
| Model: BRG-G1 | | Date: 12-Apr-12 | No.: RJ028007 |
| Subject: Installation Manual for Embedded RC Gate | | Prepared by: Junji Mochizuki | |
| From: 3rd Tech Service Sect, MFP/P Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (@Remote) | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2 |

Device Registration Procedure for Embedded RC Gate

- @Remote connection via Embedded RC Gate is supported from firmware v2.0.4.
- This RTB contains the procedure for newly registering the device with the @Remote system via Embedded RC Gate.

Before registration

Obtain a Request Number using the @Remote Center GUI.

See the Center GUI Operator's Manual for how to do this.

The image displays two screenshots of the @Remote Communication Server GUI in a Windows Internet Explorer browser window.

Left Screenshot: Shows the main menu with the "Registration" section highlighted. The "New Registration" link is circled in red.

Right Screenshot: Shows the "New Registration" form. The "Register" button is circled in red. The form contains the following fields:

- Customer Name/ID:** ABC Company
- Site Name:** STG01
- Service Depot Name:** STG01 Inc. Svc
- Operation Calendar:** DEF
- Registration Number Option:**
 - Number Of Registrations: 4 (with a note: "- Input the number between 1 and 100.")
- Option:**
 - Address: 1-2-3, NY
 - Location: 12th Floor
 - Appliance Administrator Name: Mr. Smith
 - Appliance Administrator Phone: 123-456
 - Appliance Administrator E-mail Address: smith@abc.com
 - Note 1, Note 2, Note 3: (Empty text areas)

Fields marked with an asterisk (*) are required.

Model: BRG-G1

Date: 12-Apr-12

No.: RJ028007

Main registration procedure

1. Confirm that firmware **v2.04 or newer** is installed.

Note: The value of SP5816-201 (Regist Status) should be “0”, which means the device has not yet been registered with @Remote.

| Value of SP5816-201 | Description | Possibility to install as embedded RC Gate |
|---------------------|--|--|
| 0 | This device is not registered as either Cumin or RC Gate. | Yes, possible |
| 1 | This device is in the process of being registered as embedded RC Gate. | No, not possible |
| 2 | This device is registered as embedded RC Gate already. | No, not possible |
| 3 | This device is registered as a managed device under an RC Gate. | No, not possible |
| 4 | NRS module is not functioned in this device. | No, not possible |

2. Access **SP5816-202** (Letter Number) and enter the 18-digit **request number** that you obtained from the @Remote Center GUI.
3. Press [Enter (OK)] 14 times until the display returns to the SP number indication.
4. Access **SP5816-203** (Confirm Execute) and press [Enter (OK)].
5. After “Running” disappears, press [Escape] until the display returns to the SP number indication.
6. Execute **SP5816-204** (Confirm Result) to check the results.
Note: If the registration number is confirmed, “000” is displayed.

SP5816-204 Confirmation Result:

| Value | Meaning | Solution/Workaround |
|------------|---|---|
| 000 | Succeeded | Congratulations! |
| 001 | Request number error | Check request number again. |
| 003 | Communication error (proxy enabled) | Check network condition. |
| 004 | Communication error (proxy disabled) | Check network condition. |
| 005 | Proxy error (illegal user name or password) | Check proxy name and password. |
| 006 | Communication error | Check network condition |
| 008 | Other error | See SP5816-208 for concrete error codes |
| 009 | Request number confirmation executing | Processing... Please wait |

7. Execute **SP5816-206** (Register Execute).
8. After “Running” disappears, press [Escape] until the display returns to the SP number indication.

Model: BRG-G1

Date: 12-Apr-12

No.: RJ028007

9. Execute **SP5816-207** (Resister Result) to check the results.

Note: If the registration number is confirmed, "000" is displayed.

SP5816-207 Confirmation Result:

| Value | Meaning | Solution/Workaround |
|------------|---|---|
| 000 | Succeeded | Congratulations! |
| 001 | Request number error | Check request number again. |
| 003 | Communication error (proxy enabled) | Check network condition. |
| 004 | Communication error (proxy disabled) | Check network condition. |
| 005 | Proxy error (illegal user name or password) | Check proxy name and password. |
| 006 | Communication error | Check network condition |
| 008 | Other error | See SP5816-208 for concrete error codes |
| 009 | Request number confirmation executing | Processing... Please wait |

10. Confirm that the value of **SP5816-201** (Regist Status) is "2".

Note: This means that the printer has been registered successfully.

New SP Modes Added from v2.0.4 for @Remote

The following SP modes were added from v2.0.4 for @Remote support.

| SP No. | Description | Setting Range | Default Setting |
|--------------|--|-------------------------------------|-----------------|
| 5-504 | Jam Alarm Interval | | |
| 5-504-001 | Jam Alarm | 0: N 1: L 2: M 3: H | 3 |
| 5-507 | Supply Alarm | | |
| 5-507-003 | Ink S/A Set (Ink End Alarm) | 0: OFF 1: ON | 1 |
| 5-507-006 | Waste Ink S/A Set (Waste Ink Tank Alarm) | 0: OFF 1: ON | 1 |
| 5-507-021 | Supply Call Display | 0: OFF 1: ON | 0 |
| 5-507-080 | Supply Trigger | 0: At Replacement 1: At Near End | 0 |
| 5-515 | SC/Alarm Setting | | |
| 5-515-001 | SC Call Setting | 0: OFF 1: ON | 1 |
| 5-515-002 | Parts Near End Set | 0: OFF 1: ON | 0 |
| 5-515-003 | Parts End Set | 0: OFF 1: ON | 0 |
| 5-515-004 | User Call Set | 0: OFF 1: ON | 1 |
| 5-515-006 | Comm Test Set | 0: OFF 1: ON | 1 |
| 5-515-007 | Dev Notice Set | 0: OFF 1: ON | 1 |
| 5-515-008 | Alarm Notice | 0: OFF 1: ON | 0 |

| | | | |
|---------------|--|--|---------------------------------|
| Model: BRG-G1 | | Date: 12-Apr-12 | No.: RJ028007 |
| 5-515-009 | Non Genuine Ink Set | 0: OFF 1: ON | 1 |
| 5-515-010 | Supply Auto Set | 0: OFF 1: ON | 1 |
| 5-515-011 | Supply Manage Set | 0: OFF 1: ON | 1 |
| 5-515-012 | Jam/ Door Open Set | 0: OFF 1: ON | 0 |
| 5-515-101 | Error Alarm Level | 0 to 10 | 5 |
| 5-515-102 | Jam Count Level | 0 to 255 | 20 |
| 5-811 | Machine Serial | | |
| 5-811-003 | ID2 Code | Up to 17 characters | - |
| 5-812 | Service Tel. No. Setting | | |
| 5-812-001 | Service Tel No. | Up to 20 characters | - |
| 5-812-003 | Supply Tel No. | Up to 20 characters | - |
| 5-816 | Remote Service | | |
| 5-816-002 | Exec CE Call | 0: Start of the service 1: End of the service | |
| 5-816-003 | Function Flag (Remote service function) | 0: Disabled 1: Enabled | 0 |
| 5-816-021 | RCG-C Registered | 0: Not completed 1: Completed | 0 |
| 5-816-025 | GW URL | Up to 81 characters | "https://210.173.216.40/i02/AS" |
| 5-816-026 | Polling Interval | 60 to 99999 | 60 |
| 5-816-027 | Connect Timeout | 1 to 90 | 30 |
| 5-816-028 | Send Timeout | 1 to 100 | 30 |
| 5-816-029 | Receive Timeout | 1 to 100 | 30 |
| 5-816-030 | Retry Interval | 0 to 65535 | 3 |
| 5-816-031 | Retry Count | 0 to 255 | 3 |
| 5-816-032 | Send Delay | 0 to 255 | 5 |
| 5-816-033 | Max Multipart | 0 to 10 | 10 |
| 5-816-039 | Rescue URL | Up to 81 characters | "https://210.173.216.47/Rescue" |
| 5-816-040 | Reg. Notify Type | 0: None 1: Monthly 2: Weekly 3: Dayly | 0 |
| 5-816-041 | Count Notify Type | 0: None 1: Monthly 2: Weekly 3: Dayly | 0 |
| 5-816-062 | Use Proxy | 0: Not use 1: Use | 0 |
| 5-816-063 | Proxy Host | Up to 128 characters | - |
| 5-816-064 | Proxy Port Number | 0 to 65535 | 8080 |
| 5-816-065 | Proxy User Name | Up to 31 characters | - |
| 5-816-066 | Proxy Password | Up to 31 characters | - |
| 5-816-067 | CERT: Up State | 0 to 255 | 0 |
| 5-816-068 | CERT: Error | 0 to 255 | 0 |
| 5-816-069 | CERT: Up ID | Up to 63 characters | - |
| 5-816-087 | CERT: Macro Ver. | Up to 8 characters | - |
| 5-816-088 | CERT:PAC Ver. | Up to 16 characters | - |
| 5-816-102 | Cipher Strength | 0: 512 bit 2: 2048 bit | 0 |

| Model: BRG-G1 | | Date: 12-Apr-12 | No.: RJ028007 |
|---------------|-------------------|--|---------------|
| 5-816-121 | CERT:GW URL | Up to 81 characters | - |
| 5-816-122 | CERT: Use Pass | 0: Not use 1: Use | 0 |
| 5-816-123 | CERT: Pass Phrase | Up to 31 characters | - |
| 5-816-124 | CERT: Use MAC | 0: Not use 1: Use | 0 |
| 5-816-135 | Reg. Notify Int. | 0 to 4294967295 | 0 |
| 5-816-136 | Reg. Notify Week | 0: Sun 1: Mon 2: Tue 3: Wed 4: Thu 5: Fri 6: Sat | 0 |
| 5-816-137 | Count Notify Int. | 0 to 4294967295 | 0 |
| 5-816-138 | Count Notify Week | 0: Sun 1: Mon 2: Tue 3: Wed 4: Thu 5: Fri 6: Sat | 0 |
| 5-816-200 | Execute Polling | - | - |
| 5-816-201 | Regist Status | Refer to page 2 of this document. | 0 |
| 5-816-202 | Letter Number | Up to 31 characters | - |
| 5-816-203 | Confirm Execute | - | - |
| 5-816-204 | Confirm Result | Refer to page 2 of this document. | 0 |
| 5-816-205 | Confirm Place | Up to 127 characters | - |
| 5-816-206 | Register Execute | - | - |
| 5-816-207 | Register Result | Refer to page 3 of this document. | 0 |
| 5-816-208 | Error Code | - | 0 |
| | -2387 | Not supported at the service center | |
| | -2389 | Database out of service | |
| | -2390 | Program out of service | |
| | -2391 | Too registrations for same device | |
| | -2392 | Parameter error | |
| | -2393 | Basil not managed | |
| | -2394 | Device not managed | |
| | -2395 | Box ID for basil illegal | |
| | -2396 | Device ID for Basil is illegal | |
| | -2397 | Incorrect ID2 format | |
| | -2398 | Incorrect request number format | |
| | -12003 | Attempt registration without execution of an inquiry and no previous registration. | |
| | -12004 | Attempt setting with illegal entries for certification and ID2. | |
| | -12006 | A confirmation request was made after the confirmation had already been completed. | |
| | -12008 | Update certification failed because mainframe is in use. | |
| 5-816-209 | Instl Clear | - | - |

Reissued: 05-Oct-16

| | | |
|----------------|-----------------|----------------|
| Model: BRG-G1K | Date: 19-Sep-13 | No.: RJ028008c |
|----------------|-----------------|----------------|

RTB Reissue

The items in ***bold italics*** have been corrected or added.

| | | | |
|--|---|---|---|
| Subject: Firmware Release Note: Engine/Controller | | Prepared by: Y. Saitoh | |
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware) | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2 |

This RTB has been issued to announce the firmware release information for the **Engine/Controller**.

| Version | Program No. | Effective Date | Availability of RFU |
|---------------------|-----------------------------|---------------------------------------|-----------------------------|
| <i>1.2.0</i> | <i>J0355613C_120</i> | <i>October 2016 production</i> | <i>Not available</i> |
| 1.1.0 | J0355610B_110 | January 2016 production | Not available |
| 1.0.3 | J0355610A_103 | March 2014 production | Not available |
| 1.0.2 | J0355610A_102 | - | Not available |

Note: Definition of Availability of RFU via @Remote
"Available": The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

| Version | Modified Points or Symptom Corrected |
|---------------------|--|
| <i>1.2.0</i> | <i>Other Changes:</i> - <i>Support for the Lot 6 regulation.</i> <i>Symptom Corrected:</i> - <i>The system cannot recover from the energy saving mode, if a USB cable is connected to the machine during energy saving mode.</i> |
| 1.1.0 | Specification Change: 1. Support of the revised Portuguese orthography. Error Correction: 1. The printer may not recover from Energy Saver mode. 2. Version information of Web Image Monitor for Windows 10 appears in garbled characters. 3. Security enhanced for Logjam Attack. 4. Printing may not resume even after recovering from a no-feed jam. 5. Machine may stall, if printed with particular settings. 6. Cannot print properly, if "Use Preprinted/Prepunched Paper" is selected in the "Detailed Setting" tab. 7. Printing envelopes or thick paper causes the printer to stall. 8. Print position is incorrect, if two images are imposed on the same page. 9. Bug in debug log. 10. Printer may stall when printing particular websites using Internet Explorer. |
| 1.0.3 | Symptoms corrected: 1. The image may shift about 1mm from the second page on. |

Reissued: 05-Oct-16

| Model: BRG-G1K | | Date: 19-Sep-13 | No.: RJ028008c |
|----------------|---|-----------------|----------------|
| Version | Modified Points or Symptom Corrected | | |
| | <ol style="list-style-type: none">2. The printer may not power up after the firmware is updated. (To clear the condition, the power cord needs to be unplugged and plugged back in).3. The printer may not recover from Energy Saver mode if a cover is opened right after the machine enters the mode.4. The System Timer of the printer is not accurate.5. Other minor bugs were fixed. | | |
| 1.0.2 | <p>Symptoms corrected:</p> <ol style="list-style-type: none">1. Occasionally the print does not recover from Energy Saver mode when sending a print job or when pressing a key on the operation panel.2. Occasionally the printer stalls when ink end is detected during printing (PCL only).3. Occasionally a wrong tray is selected after recovering from paper end condition.4. Paper size error may occur when using the by-pass tray.5. Occasionally one of two option trays is not recognized when turning the printer on.6. Other minor bugs. | | |

Reissued:4-Jul-14

| | | |
|-------------------------|----------------|----------------|
| Model: BRG-G1 / BRG-P1W | Date: 3-Jun-14 | No.: RJ028009a |
|-------------------------|----------------|----------------|

RTB Reissue: The subject of this RTB has been changed.

| | | | |
|---|---|---|---|
| Subject: Power Supply Unit and Harness | | Prepared by: Junji Mochizuki | |
| From: 3rd Tech Service Sect.,MFP/P Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2 |

| Old part number | New part number | Description | Q'ty | Int | Note |
|-----------------|-----------------|----------------------------|-------|-----|--------------|
| J0255200 | J0255202 | POWER SUPPLY UNIT:100-120V | 1 - 1 | X/X | O/O as a set |
| J0255201 | J0255203 | POWER SUPPLY UNIT:220-240V | 1 - 1 | | |
| J0255480 | J0255481 | HARNESS:INLET | 1 - 1 | X/X | |

Change:

- 1) The shape of the PSU primary connector (CN1) was changed.
- 2) In accordance with this change, the shape of the harness connector that connects to CN1 was changed.

Reason: PSU vendor change

Important: If you need to replace the old PSU, order the new PSU and new harness and replace them **together as a set**.

Note: There are two pin holes in the old connector and three in the new one. The center hole of the new connector is not used.

Cut-in S/N:

| Model | Serial No. |
|--------|--------------|
| J02722 | R603Q8XXXXX |
| J02727 | R603Q701923 |
| J02817 | R613Q701896 |
| J02822 | R613Q8XXXXX |
| J02827 | R613Q800518 |
| J02917 | R623QA00001 |
| J02922 | R623QAXXXXXX |
| J02927 | R623Q800001 |
| J03417 | R673Q800001 |
| J03422 | R673Q8XXXXX |
| J03427 | R673Q800331 |
| J03527 | R703Q800001 |

| | | | |
|---|---|---|---|
| Model: BRG-G1 / BRG-P1W | | Date: 22-Oct-14 | No.: RJ0280010 |
| Subject: Harness - Carriage | | Prepared by: Junji Mochizuki | |
| From: 3rd Tech Service Sect.,MFP/P Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2 |

| Old part number | New part number | Description | Q'ty | Int | Note |
|-----------------|-----------------|-------------------------|-------|-----|--------------|
| J0255390 | J0355390 | Harness:Carriage:A:SIG | 1 - 1 | X/X | O/O as a set |
| J0255391 | J0355391 | Harness:Carriage:B:VCOM | 1 - 1 | | |

Change:

The flat harnesses of the printer head have been changed.

Reason: Harness vendor change

Important: Due to the differences of length between the old and new harnesses, the two harnesses need to be replaced **as a set**.

| | | | |
|---|---|---|---|
| Model: BRG-G1 | | Date: 21-Oct-15 | No.: RJ028011 |
| Subject: FSM revision: SC57001 description added | | Prepared by: J.Kitagawa | |
| From: 1st Tech Service Sect.,MFP/P Tech Service Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2 |

Please add the following SC description in the field service manual in section:
 6.Troubleshooting > Service Call Code Tables (p222)

| SC | Pattern | Error Name / Detection Criteria / Major Cause / Solution |
|-------|---------|---|
| 57001 | D | Power Pack failure |
| | | The machine detects the power pack (PSU or HVPS) error. |
| | | Defective power pack |
| | | Turn the main power switch off and then back on. Replace the PSU or HVPS. |