	П

PAGE: 1/1

Subject: Firmware Release Note: Engine Firmware (Package)		Prepared by: Yuji Mimura	
From: 1st Tech. S	Support Sec. Service Support I	Dept.	
Classification:	Troubleshooting	☐ Part information	<u> </u>
	Mechanical	☐ Electrical	Service manual revision
	Paper path	☐ Transmit/rec	ceive Retrofit information
	⊠ Other ()		

Version	Program No.	Effective Date
1.50.00.77	G1868630A	July 2007 production
1.50.00.72	G1888630A	1st Mass production.

Version	Modified Points or Symptom Corrected
1.50.00.77	 Modified a fuser reference temperature in Ready mode for Blue Angel. Output format of fonts does not align with table in form printing. (GFPR#RA07040001) Abnormal printing of ruled lines in form printing.
	(GFPR#RA7060001)
1.50.00.72	1st Mass production.

Technical Bulletin

PAGE: 1/1

Reissued: 21-Jan-09

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001c
--------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: Engine Firmware (Package)			Prepare	d by: K. Hamada
From: 2nd Tech.	Support Sec. Service Support	Dept.		
Classification:	☐ Troubleshooting	☐ Part informat	ion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	⊠ Other ()	☐ Tier 2

Version	Program No.	Effective Date
1.50.00.99	G1868630C	August 2008 production
1.50.00.92	G1868630B	January 2008 production
1.50.00.77	G1868630A	July 2007 production
1.50.00.72	G1888630A	1st Mass production.

Version	Modified Points or Symptom Corrected
1.50.00.99	 Symptom corrected: The status of the operation returns to "Ready" but this is not reflected in SDM for Admin's Device properties Fixed the paper source problem that occurs if the option tray initialization is delayed. Fixed the red question mark display in Power Save mode Fixed a problem in which the Default Type of PS driver and default Type of PCL driver work differently. Delay to inform the status of the option tray.
1.50.00.92	Minor bug correction.
1.50.00.77	 Modified a fuser reference temperature in Ready mode for Blue Angel. Output format of fonts does not align with table in form printing. (GFPR#RA07040001) Abnormal printing of ruled lines in form printing. (GFPR#RA7060001)
1.50.00.72	1st Mass production.

Technical Bulletin

PAGE: 1/2

Reissued: 21-Jul-09

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001d
--------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: Engine Firmware (Package)			Prepare	d by: K. Hamada
From: 2nd Tech.	Support Sec. Service Support	Dept.		
Classification:	☐ Troubleshooting	☐ Part informat	ion	Action required
	☐ Mechanical	☐ Electrical		☐ Service manual revision
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information
	☐ Product Safety	⊠ Other ()	☐ Tier 2

Version	Program No.	Effective Date
1.50.00.114	G1868630D	May 2009 production
1.50.00.99	G1868630C	August 2008 production
1.50.00.92	G1868630B	January 2008 production
1.50.00.77	G1868630A	July 2007 production
1.50.00.72	G1888630A	1st Mass production.

Version	Modified Points or Symptom Corrected					
1.50.00.114	Engine: 1.00.37 →1.00.39					
	1. To tighten controls on fusing error conditions when the machine					
	is warming up or ready.					
	2. Improve text density by LD power in dark mode.					
	PCL5e: 5.67 → 5.92					
	1. Minor bug correction					
	PCL6: 5.72 → 5.93					
	1. Minor bug correction					
	PS: 1.85 → 1.94					
	1. Minor bug correction					
	Network: 3.02.04 → 3.02.05					
	1. Minor bug correction					
1.50.00.99	Symptom corrected:					
	The status of the operation returns to "Ready" but this is not reflected in SDM for Admin's Device properties					
	2. Fixed paper source problem in case option tray's delayed initialization.					
	3. Fixed Red question mark display in status of Power Save mode					
	4. Fixed a problem that Default Type of PS driver and default Type of					
	PCL driver works differently.					
	5. Delay time to inform status of option tray.					
1.50.00.92	Minor bug correction.					

Technical Bulletin

PAGE: 2/2

Reissued: 21-Jul-09

Model: Model SY-P1		Date: 07-Jan-08	No.: RG186001c	d
Version	Modified Points or Symptom Correct	ted		
1.50.00.77	 Modified a fuser reference temper Output format of fonts does not ali (GFPR#RA07040001) Abnormal printing of ruled lines in 	gn with table in form pri	nting.	
1.50.00.72	1st Mass production.			

1		

PAGE: 1/1

Model: SY-P1 Da			Dat	te: 17-Aug-09		No.: RG186002
Subject: Parts information			Prepared by: K. Hamada			
From: 2nd Tech	Support Sec. Service Support	Dept.				
Classification:	☐ Troubleshooting	⊠ Part info	orma	tion	Action	n required
		☐ Electric	al		☐ Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retro	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G1868755	Decal	0-1	-	5	8	

Change/Reason: The above part is added.

G1868755:



Technical Bulletin

PAGE: 1/2

Reissued: 13-Oct-09

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001e
--------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: Engine Firmware (Package)				Prepared by: K. Hamada		
From: 2nd Tech. Support Sec. Service Support Dept.						
Classification:	Troubleshooting	☐ Part informat	ion	Action required		
		☐ Electrical		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☑ Tier 2		

Version	Program No.	Effective Date
1.50.00.121	G1868630E	August 2009 production
1.50.00.114	G1868630D	May 2009 production
1.50.00.99	G1868630C	August 2008 production
1.50.00.92	G1868630B	January 2008 production
1.50.00.77	G1868630A	July 2007 production
1.50.00.72	G1888630A	1st Mass production.

Version	Modified Points or Symptom Corrected						
1.50.00.121	Engine: 1.00.39 →1.00.43						
	1.Minor bug correction.						
1.50.00.114	Engine: 1.00.37 →1.00.39						
	To tighten controls on fuser error condition when the machine is						
	warming up or ready.						
	Improve text density by LD power in dark mode.						
	PCL5e: 5.67 → 5.92						
	Minor bug correction						
	PCL6: 5.72 → 5.93						
	Minor bug correction						
	PS: 1.85 → 1.94						
	Minor bug correction						
	Network: 3.02.04 → 3.02.05						
	1. Minor bug correction						
1.50.00.99	Symptom corrected:						
	1. The status of the operation returns to "Ready" but this is not reflected						
	in SDM for Admin's Device properties						
	2. Fixed paper source problem in case option tray's delayed initialization.						
	3. Fixed Red question mark display in status of Power Save mode						
	4. Fixed a problem that Default Type of PS driver and default Type of						
	PCL driver works differently.						
	5. Delay time to inform status of option tray.						

Technical **B**ulletin

PAGE: 2/2

Reissued: 13-Oct-09

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001e
--------------------	-----------------	----------------

Version	Modified Points or Symptom Corrected
1.50.00.92	Minor bug correction.
1.50.00.77	 Modified a fuser reference temperature in Ready mode for Blue Angel. Output format of fonts does not align with table in form printing. (GFPR#RA07040001) Abnormal printing of ruled lines in form printing. (GFPR#RA7060001)
1.50.00.72	1st Mass production.

Technical Bulletin

PAGE: 1/2


Model: SY-P1			Dat	Date: 16-Oct-09		No.: RG186003
Subject: added part				Prepared	d by: ĸ. ⊦	Hamada
From: 2nd Tech Support Sec. Service Support Dept.						
Classification:	☐ Troubleshooting	□ Part info	orma	tion	Action	n required
	☐ Mechanical	☐ Electrica	al		Service	ce manual revision
	☐ Paper path	Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G1861306	MEA_Unit-Exit	1	-	7	41	
	G1861360	Gear-Feed	1	-	9	98	
	G1861362	Spring_ETC_SEP	5		11	1-28	

Change: These parts in the table were added. **Reason:** To meet requests received from the field.


G1861306: (The illustration below is on Page 6 in the parts catalog.)

3.Frame Assembly 1 (G186)




Model: SY-P1 Date: 16-Oct-09 No.: RG186003

G1861360: (The illustration below is from Page 8 in the parts catalog.)




G1861362: (The illustration below is from Page 10 in the parts catalog.)



Model: SY-P1		Dat	:e: 10-Nov	-09	No.: RG186004	
Subject: Thermis	stor	Prepared by: K. Hamada				
From: 2nd Tech						
Classification:	Troubleshooting	□ Part informat		ation Action		n required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path ☐ Transmit/rece		eive	☐ Retrof	fit information	
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description		Int	Page	Index	Note
Hamber	G1861363	Thermistor	0-1	-	10	1-8	
	G1861364	Electrode	0-1	-	10	1-6	

Change: These parts in the table were added. **Reason:** To meet requests received from the field.





Technical Bulletin

Model: SY-P1	Model: SY-P1			e: 30-Apr-	10	No.: RG186005	
Subject: Replace	Subject: Replacement of bushing for pressure roller					Hamada	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.							
Classification:		☐ Part info	ormation				
	☐ Mechanical	☐ Electric	al		Service	ce manual revision	
☐ Paper path ☐ Transmit		it/rec	eive	☐ Retrof	fit information		
	☐ Product Safety	$\hfill \square$ Other ()	☐ Tier 2		

SYMPTOM

Noise is generated after jammed paper is removed from the fusing unit.





PAGE: 1/9

CAUSE

The vendor that produces the pressure roller bushing used the wrong material on the production line. As a result, the bushing breaks when the fusing lever is pushed upward to remove the jammed paper.

SOLUTION

If this symptom is reported on the affected units (see below), replace the bushing with the following part (replacement procedure below):

P/N G1869900 Bushing: Pressure roller

Note: This service part includes two bushings.

Important: The bushing has already been replaced on some affected units before they were shipped to the field. You **DO NOT** need to replace fusing units that are marked with a **blue dot** (see below).

Model: SY-P1 Date: 30-Apr-10 No.: RG186005

PAGE: 2/9

Affected units:

This issue affects the following Sy-P1 mainframes.

Model Name						
Sv-P1	G186-17	S2108500001 to S2108500600 S2108600001 to S2108600120				
3y-1 1	G186-27	S2108520001 to S2108520240 S2108620001 to S2108620480				

Important: Bushings have already been replaced on fusing units that are marked with a blue dot (see the photo). You DO NOT need to replace these units for this symptom.



PAGE: 1/9

Model: SY-P1 Date: 30-Apr-10 No.: RG186005

Bushing Replacement Procedure


1. Remove the lower cover.



2. Open the rear cover



3. Remove the strip shown in the photo from the rear cover.








Model: SY-P1 Date: 30-Apr-10 No.: RG186005


- 4. Pull the left side of the cover toward you.
- 5. Lift the right side of the cover and pull it toward you.



RIGHT

PAGE: 1/9






6. Remove the four screws shown from the fusing unit.





PAGE: 2/9 Model: SY-P1 Date: 30-Apr-10 No.: RG186005

7. Pull down the two levers shown at the same time.



8. Pull out the fusing unit.

Important: Set the unit down so that the gear is on your right side.






PAGE: 3/9

Model: SY-P1 Date: 30-Apr-10 No.: RG186005


9. Remove the screw shown.



10. Pull the release lever on the right side of the unit.



11. Slide the release lever in the direction of the arrow.



12. Rotate the Holder-M-PR-Shaft in the direction of the arrow.







PAGE: 1/9

Model: SY-P1 Date: 30-Apr-10 No.: RG186005

13. Remove the pressure roller bushing.



- 14. Attach the new pressure roller bushing (P/N G1869900).
- 15. Rotate the new bushing to fix it in place.





16. Attach the release lever to the right side of the unit (screw x 1).









PAGE: 2/9

Model: SY-P1 Date: 30-Apr-10 No.: RG186005

17. Remove the release lever on the left side of the unit (screw x 1).







18. Rotate the pressure roller bushing in the direction of the arrow.



19. Remove the pressure roller bushing.





Model: SY-P1

Technical Bulletin

Date: 30-Apr-10 No.: RG186005

PAGE: 3/9

20. Attach the new pressure roller bushing (P/N: G1869900).




21. Rotate the new bushing to fix it in place.



22. Attach the release lever to the left side of the unit (screw x 1).







Technical Bulletin


PAGE:	1/1	

Model: SY-P1 D				te: 15-Jun-	·10	No.: RG186006				
Subject: PCB:Pd	Subject: PCB:Power Supply-HVPS					Prepared by: T. Nihei				
From: 1st Overse	eas Tech Support Sec., 1st PC									
Classification:	Troubleshooting	□ Part inf	orma	tion		n required				
	☐ Mechanical	☐ Electric	al		Service	ce manual revision				
	☐ Paper path	☐ Transmit/rec		eive	Retro	fit information				
	☐ Product Safety	Other ()	☐ Tier 2					

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G1861382	RZL: HVPS: JC44-00112A	1		3	40	

Change: This part was newly added.

Reason: To meet requests received from the field.




Technical Bulletin

PAGE: 1/1

Model: SY-P1	Model: SY-P1 Da				10	No.: RG186007
Subject: Rear Co	Subject: Rear Cover Guide					Nihei
From: 1st Overseas Tech Support Sec., 1st PQM Dept.						
Classification:	Troubleshooting	□ Part info	orma	tion	Action	n required
		☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part	New part	Description		Int	Page	Index	Note
number	number						
	G1861228	RZL:COVERMREARGUIDE:JC6 300726A	1		11	4-5	

Change: This part was newly added. **Reason:** To meet requests received from the field.



Model: SY-P1

Classification:

Subject: Ground cassettte

Technical Bulletin

	Dat	e: 15-Jun-	10	No.: RG186008		
		Prepare	d by: K. H	Hamada		
M Dept.						
☐ Part information			☐ Action	required		
☐ Electrical			☐ Service manual revision			
☐ Transm	it/rec	eive	☐ Retrofit information			

☐ Tier 2

PAGE: 1/1

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G1861380	GROUNDCASSETTE:	0-1	-	21	27	

Other (

)


Change: This part in the table was added.

Reason: To meet requests received from the field.

From: 1st Overseas Tech Support Sec., 1st PQM Dept. ☐ Troubleshooting

☐ Product Safety

☐ Mechanical ☐ Paper path



Technical Bulletin


PAGE: 1/1

Model: SY-P1 Date				e: 28-Jun-	No.: RG186009		
Subject: Top Cover P				Prepare	d by: T. N	Nihei	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.							
Classification:	☐ Troubleshooting	🛚 Part info	orma	tion	☐ Action	n required	
	☐ Mechanical	☐ Electrica	al	☐ Servi		ice manual revision	
	 · ·	☐ Transm	it/rec	eive	Retrof	fit information	
	☐ Product Safety	☐ Other ()	☐ Tier 2		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G1861381	RZL:COVER-M_TOP:JC63- 00699B	1		5	1-19	

Change: This part was newly added.

Reason: To meet requests received from the field.



Technical Bulletin


PAGE: 1/1

Model: SY-P1 Date					0	No.: RG186010
Subject: Gear-Fu	ıser			Prepared	d by: T. N	lihei
From: 2nd Overs	eas Tech Support Sec. 2nd PC	QM Dept				
Classification:	☐ Troubleshooting	□ Part info	orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	ce manual revision
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G1861383	RZL:GEAR-FUSER:JC66-1266A	0-1		11	1-20	

Change: This part was newly added.

Reason: To meet requests received from the field.





in Page: 1/1

Reissued:16-Aug-1

Model: SY-P1	Date: 07-Jul-10	No.: RG186011a

RTB Reissue

The items in **bold italics** have been corrected.


Subject: Added parts				Prepared by: T. Nihei		
From: 1st Overseas Tech Support Sec., 1st PQM Dept.						
Classification:	☐ Troubleshooting	□ Part information	tion	☐ Action required		
	☐ Mechanical	☐ Electrical		☐ Service manual revision		
	☐ Paper path	☐ Transmit/rec	eive	☐ Retrofit information		
	☐ Product Safety	Other ()	☐ Tier 2		

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	C1061250	DUDLEY UNIT, ICOGO2/12E	0.1		2	27	
	G1001055	DOI LEX GIVIT.0030034121	0-7			0,	
	G1861320	DEV MOTOR HARNESS:JC3900438A	0-1		17	9	

Change: These parts were newly added.

Reason: To meet requests received from the field.

(1) G1861320



Model: SY-P1

Classification:

Subject: Cassette guide

Technical Bulletin

Date: 22-Nov-10 No.: RG1860					
		Prepare	d by: T. N	lihei	
И Dept.					
□ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inference □ Part inferen	orma	tion	Action	n required	
☐ Electric	al		Service	ce manual revision	

☐ Tier 2

☐ Retrofit information

PAGE: 1/1

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	G1861384	RZL:GUIDR_M:JC61-01226C	0-1		21	28	

Other (

☐ Transmit/receive

)

Change: This part was newly added.


Reason: To meet requests received from the field.

From: 1st Overseas Tech Support Sec., 1st PQM Dept. ☐ Troubleshooting

☐ Mechanical

☐ Paper path

☐ Product Safety



Technical Bulletin

PAGE: 1/1

Model: SY-P1			Dat	e: 05-Jan-	11	No.: RG186013	
Subject: Bushing	& Sensor			Prepared	d by: T. N	lihei	
From: 1st Overse	eas Tech Support Sec., 1st PQ	M Dept.					
Classification:	Troubleshooting	□ Part info	ormat	tion	Action	required	
	☐ Mechanical	☐ Electrica	al		Service	ce manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	Retrof	fit information	
	☐ Product Safety	\square Other ()	☐ Tier 2		

(1)


Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G1861141	EXIT ROLLER BUSHING:JC7241191B	0-2	-	7	43	


Change: This part in the table was added.

Reason: To meet requests received from the field.

(2) Please correct your parts catalog as follows.

Wrong part	Correct part	Description	Q'ty	Int	Page	Index	Note
number	number						
G1861141	G1861385	RZL:ELAUNITCHECK:JC96-			9	41	
		04120A					





Technical Bulletin

PAGE: 1/1

Model: SY-P1			Dat	te: 20-Jul-1	11	No.: RG186014
Subject: Parts Catalog Correction (Plate Pad)				Prepared	d by: T. N	lihei
From: 1st Overseas Tech Support Sec., 1st PQM Dept.						
Classification:	sification: Troubleshooting		orma	tion	Action	required
	☐ Mechanical	☐ Electric	al		Service	e manual revision
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information
	☐ Product Safety	Other ()	☐ Tier 2	

Part Number	Description	Q'ty	Int	Page	Index	Note
G1861335	IPR-Plate Pad	1-0		21	19-4	

Change: The part shown was deleted.

Reason: Parts Catalog error.

14	G186 1007	Gear-Pinion	1 1	
15	G186 1301	Cap-M-Guide Side,L	1	
 17	G186 1303	PMO-Locker Plate	1	
19	G186 1305	MEA Unit-Holder Pad	1	
40.4	0400 4335	IDD Dista Dad	4	
15-4	0 100 1555	IFK-Flate Fau	'	
20	G186 1108	Spring Etc-Exit Roll FD	1	
21	G186 1307	Holder-M-Pad_Housing	1	
24	G186 1310	Spring Etc-Plate K/Up	1	
26	G186 1312	RPR-Pad Cassette	1	

Technical Bulletin

PAGE: 1/2

Reissued: 20-May-13

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001g
--------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmwar	re Release Note: Engine Firmv	vare (Package)	Prepared by: J. Mochizuki	
From: 3rd Tech S	Service Sect., MFP/Printer Tec			
Classification:	☐ Troubleshooting	☐ Part information	on Action required	
	☐ Mechanical	☐ Electrical	☐ Service manual revision	
	☐ Paper path	☐ Transmit/rece	ive	
	☐ Product Safety	Other ()	⊠ Tier 2	

Version	Program No.	Effective Date
1.50.00.140	G1868630G	Production discontinued
1.50.00.128	G1868630F	January 2010 production
1.50.00.121	G1868630E	August 2009 production
1.50.00.114	G1868630D	May 2009 production
1.50.00.99	G1868630C	August 2008 production
1.50.00.92	G1868630B	January 2008 production
1.50.00.77	G1868630A	July 2007 production
1.50.00.72	G1888630A	1st Mass production

Version	Modified Points or Symptom Corrected
1.50.00.140	Symptom corrected:
	Main: 1.50.00.128 -> 1.50.00.140
	1. iDPT failure issue has been fixed.
	2. Other minor bug corrections.
1.50.00.128	Symptom corrected:
	Main : 1.50.00.122 -> 1.50.00.128
	1. Only separator pages are printed. The rest of the job is not output.
	This only affected devices with the optional
	HDD. PCL 5e: 5.92 -> 5.92.01
	1. Black barcodes might be printed in grey.
	Network: 3.02.05 -> 3.02.06
	The device might become unreachable if a static IP
	address is used in a CIDR environment.
1.50.00.121	Engine: 1.00.39 ->1.00.43
	1.Minor bug correction.
1.50.00.114	Engine: 1.00.37 ->1.00.39
	To tighten controls on fuser error condition when the machine is
	warming up or ready.
	Improve text density by LD power in dark mode.
	PCL5e: 5.67 -> 5.92
	Minor bug correction



PAGE: 2/2

Reissued: 20-May-13

Model: Model SY-P1	Date: 07-Jan-08	No.: RG186001g
--------------------	-----------------	----------------

Version	Modified Points or Symptom Corrected			
	PCL6: 5.72 -> 5.93 1. Minor bug correction PS: 1.85 -> 1.94 1. Minor bug correction			
	Network: 3.02.04 -> 3.02.05 1. Minor bug correction			
1.50.00.99	 Symptom corrected: The status of the operation returns to "Ready" but this is not reflected in SDM for Admin's Device properties Fixed paper source problem in case option tray's delayed initialization. Fixed Red question mark display in status of Power Save mode Fixed a problem that Default Type of PS driver and default Type of PCL driver works differently. Delay time to inform status of option tray. 			
1.50.00.92	Minor bug correction.			
1.50.00.77	 Modified a fuser reference temperature in Ready mode for Blue Angel. Output format of fonts does not align with table in form printing. (GFPR#RA07040001) Abnormal printing of ruled lines in form printing. (GFPR#RA7060001) 			
1.50.00.72	1st Mass production			