

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2017/11/15  
-----

[Program Name] Engine  
-----

[Version] 1.01:03  
-----

[PCB No.]  
-----

[Interchangeability] X / O  
-----

[Other Firmware Requirements] None  
-----

[PCB Requirements] None  
-----

[Software category] Normal Release  
-----

[Release category] Normal Release  
-----

[Program category] Firmware  
-----

Exported to(language) GEN(all)

[Firmware No.] M0B05151C

[File Information]

File Name      M0B05151C.fwu

File Type      Module for Service

Size           0.94 MB ( 983540 byte )

[File Information]

File Name      M0B05151C.rfu

File Type      Module for Remote Upgrade

Size           0.95 MB ( 991488 byte )

[Availability of RFU] Yes  
-----

[Production reflection] 1st Mass Production  
-----

=====  
\*\*\* Note \*\*\*  
=====

[Note]  
-----

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]  
-----

=====  
\*\*\* Modification History \*\*\*  
=====  
[Modifications made:]  
1st Mass production

-----  
[Modification history]

=====  
**\*\*\* Basic Information \*\*\***  
=====

[Create date] 2018/11/15

-----  
[Program Name] CTL System

-----  
[Version] 1.08.1

-----  
[PCB No.]

-----  
[Interchangeability] X / O

-----  
[Other Firmware Requirements] None

-----  
[PCB Requirements] None

-----  
[Software category] Normal Release

-----  
[Release category] Normal Release

-----  
[Program category] Firmware

-----  
Exported to(language) GEN(all)

[Firmware No.] M0B05250R

[File Information]

File Name        M0B05250R.fwu

File Type        Module for Service

Size             118.58 MB ( 124342612 byte )

[File Information]

File Name        M0B05250R.rfu

File Type        Module for Remote Upgrade

Size             118.59 MB ( 124350720 byte )

[Availability of RFU] Yes

-----  
[Production reflection] 2018/11

=====  
**\*\*\* Note \*\*\***  
=====

[Note]

=====  
**\*\*\* Important Notes \*\*\***  
=====

[Important Notes]

=====  
**\*\*\* Modification History \*\*\***  
=====

=====  
[Modifications made:]

Rank C

Other changes:

- A country selection menu has been added to the initial setting for Wireless LAN.
- Only the ad-hoc channels for the selected country are displayed in the initial setting menu for Wireless LAN.
- Support for Google Cloud Print.
- The following values can be set with solution software that uses SOAP I/F.
- "SNMPv3 Setting"
  - SNMPv3 Trap Communication
  - Encryption Algorithm
  - Permit SNMPv3 Communication
- "Program/Change Administrator"
  - Encryption Password

-----  
[Modification history]

-----  
Version 1.06

Rank C

Symptom corrected:

- When the SMC List is saved to the SD card as a CSV file, SP7507 (Latest Jam History) is not correctly recorded.
- Remote installation of a SOP application while a user is logged into the device might fail.

-----  
Version 1.05.2

Rank C

Symptom corrected:

- The machine might reboot automatically if repeatedly rebooted.
- Both ends of the watermark might be cut off when printing from the V4 driver.
- Some characters might print in the wrong position when printing a PDF containing certain fonts.
- The top and bottom ends might be missing if the size is scaled when PDF printing.
- The scaling might be wrong when printing PDF data that contains the FITTOPAGESIZE command but not PRINTSCALING.
- Linux print jobs in Stored Print might be canceled.
- Pages printed as a booklet might be centered incorrectly.
- With booklet printing or N-Up printing, the scaling ratio might be wrong.
- Characters might become too thick if the transparency is specified.
- When printing a PDF with a specific command, an invalidfont error might occur.
- Some Symbolic fonts in a PDF might not print correctly.
- The image might be rotated 180 degrees when printing Landscape document via the SmartSDK.
- Some Type 0 fonts in a PDF might not print correctly.
- If log tracing on Web Image Monitor is cancelled just after using the function, the machine enters into off-line mode.

- Printing job might hang after recovering from a paper feed error.

-----  
Version 1.04.2

Rank C

Other changes:

The version was upgraded for firmware management purpose on the server.

No changes made to the firmware.

-----  
Version 1.04.1

Rank A

Symptom corrected:

- Fixed CVE-2017-13077, CVE-2017-13078, CVE-2017-13079, CVE-2017-13080, and CVE-2017-13081.
- Fixed an issue with NFC communication failure.
- The following fixes were implemented in models for China:
  - When the machine receives signals on W56 channels (100-140) for Wi-Fi in the 5Ghz range from an access point, it generates the signal of the same channel despite a regulation in the Chinese market prohibiting office devices from generating signals in this range.
  - When setting the security method to inactive or WEP, the machine cannot connect with W52 channels(36-48ch) and W53 channels(52-64ch).
  - When connecting with Ad-hoc, even if the machine is set to W52 channels(36-48ch), the machine cannot connect to wireless LAN devices.
- The printer keeps rebooting after detecting an SC condition.

-----  
Version 1.03.1

Rank A

Symptom corrected:

- When the machine receives signals on channels 12-14 for Wifi in the 2.4Ghz range from an access point, it generates the signal of the same channel despite a regulation in market prohibiting office devices from generating signals in this range.

-----  
Version 1.03

Rank C

Symptom corrected:

- When displaying the IPv6 settings on the Web Image Monitor without logging in, some items are not displayed.
- Some of the text displayed on the screen when entering the SSID and password for Wi-Fi Direct in Spanish, Dutch, Catalan, or Greek is missing.

Other changes:

- Deleted information that wasn't necessary for debug log analysis.
-

Version 1.02

Rank C

Symptom corrected:

- Some of the text is not displayed on the Wi-Fi Direct connection screen in some languages.
- An image might print incorrectly because of a failure in memory resource allocation.
- A magenta horizontal band might appear on printouts due to improper image processing in the controller.
- The machine cannot send calls via the RC A2 gate or the DMNX+ @Remote connector to the @Remote center server when the SSL/TLS of the VE-P2 is set to TLS 1.2 and the certification encryption strength is 512 bits.

-----  
Version 1.01.1

Symptom corrected:

- If user code authentication is enabled when printing from USB memory, the device will stall if trying to print after canceling the input of the user code.
- A job printed from USB memory might be canceled when a custom paper size is fed from the bypass tray.

Other changes:

- Debug logs can be obtained via @Remote.

-----  
Version 1.00.7

1st Mass production

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2018/07/23  
-----

[Program Name] CTL System  
-----

[Version] 1.06  
-----

[PCB No.]  
-----

[Interchangeability] X / O  
-----

[Other Firmware Requirements] None  
-----

[PCB Requirements] None  
-----

[Software category] Normal Release  
-----

[Release category] Normal Release  
-----

[Program category] Firmware  
-----

Exported to(language) GEN(all)

[Firmware No.] M0B05250P

[File Information]

File Name        M0B05250P.fwu

File Type        Module for Service

Size            118.58 MB ( 124342608 byte )

[File Information]

File Name        M0B05250P.rfu

File Type        Module for Remote Upgrade

Size            118.59 MB ( 124350720 byte )

[Availability of RFU] Yes  
-----

[Production reflection] 2018/06  
-----

=====  
\*\*\* Note \*\*\*  
=====

[Note]  
-----

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]  
-----

=====  
\*\*\* Modification History \*\*\*  
=====

[Modifications made:]

Rank C

Symptom corrected:

- When the SMC List is saved to the SD card as a CSV file, SP7507 (Latest Jam History) is not correctly recorded.
- Remote installation of a SOP application while a user is logged into the device might fail.

-----  
[Modification history]

-----  
Version 1.05.2

Rank C

Symptom corrected:

- The machine might reboot automatically if repeatedly rebooted.
- Both ends of the watermark might be cut off when printing from the V4 driver.
- Some characters might print in the wrong position when printing a PDF containing certain fonts.
- The top and bottom ends might be missing if the size is scaled when PDF printing.
- The scaling might be wrong when printing PDF data that contains the FITTOPAGESIZE command but not PRINTSCALING.
- Linux print jobs in Stored Print might be canceled.
- Pages printed as a booklet might be centered incorrectly.
- With booklet printing or N-Up printing, the scaling ratio might be wrong.
- Characters might become too thick if the transparency is specified.
- When printing a PDF with a specific command, an invalidfont error might occur.
- Some Symbolic fonts in a PDF might not print correctly.
- The image might be rotated 180 degrees when printing Landscape document via the SmartSDK.
- Some Type 0 fonts in a PDF might not print correctly.
- If log tracing on Web Image Monitor is cancelled just after using the function, the machine enters into off-line mode.
- Printing job might hang after recovering from a paper feed error.

-----  
Version 1.04.2

Rank C

Other changes:

The version was upgraded for firmware management purpose on the server.  
No changes made to the firmware.

-----  
Version 1.04.1

Rank A

Symptom corrected:

- Fixed CVE-2017-13077, CVE-2017-13078, CVE-2017-13079, CVE-2017-13080, and CVE-2017-13081.
- Fixed an issue with NFC communication failure.
- The following fixes were implemented in models for China:
  - When the machine receives signals on W56 channels (100-140) for Wi-Fi in the 5Ghz range from an access point, it generates the signal of the same channel despite a regulation in the Chinese market prohibiting office devices from generating signals in this range.
  - When setting the security method to inactive or WEP, the machine cannot connect with W52 channels(36-48ch) and W53 channels(52-64ch).
  - When connecting with Ad-hoc, even if the machine is set to W52 channels(36-48ch), the machine cannot connect to wireless LAN devices.
- The printer keeps rebooting after detecting an SC condition.

-----  
Version 1.03.1

Rank A

Symptom corrected:

- When the machine receives signals on channels 12-14 for Wifi in the 2.4Ghz range from an access point, it generates the signal of the same channel despite a regulation in market prohibiting office devices from generating signals in this range.

-----  
Version 1.03

Rank C

Symptom corrected:

- When displaying the IPv6 settings on the Web Image Monitor without logging in, some items are not displayed.
- Some of the text displayed on the screen when entering the SSID and password for Wi-Fi Direct in Spanish, Dutch, Catalan, or Greek is missing.

Other changes:

- Deleted information that wasn't necessary for debug log analysis.

-----  
Version 1.02

Rank C

Symptom corrected:

- Some of the text is not displayed on the Wi-Fi Direct connection screen in some languages.
- An image might print incorrectly because of a failure in memory resource allocation.