K	L	U	П

Model: QU-D1

Technical Bulletin

Date: 12-Aug-16 No.: RC284001

PAGE: 1/1

Subject: Firmware	Prepared by: A. Ishida		
From: 1st Tech Se			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	☐ Part information ☐ Electrical ☐ Transmit/receive ☐ Other (Firmware)	☐ Action required ☐ Service manual revision ☐ Retrofit information ☐ Tier 2

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
1.13	C2845115A	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via USB flash memory.

Version	Modified Points or Symptom Corrected	
1.13	1st Mass production	

[&]quot;Available": The firmware can be updated via RFU or SD card.

	п.				
₹	ľ	L	. L	_	П

Model: QU-D1			Date: 10-	-Nov-17	No.: RC284002
Subject: Firmware	Release Note: Main			Prepared	by: K.Yamamoto
From: 1st Tech Se	rvice Sect., MFP/Printer Tech	n Service Dept.			
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	Part informati Electrical Transmit/rece Other (Firmwa	eive		equired manual revision nformation

PAGE: 1/3

This RTB has been issued to announce the firmware release information for the Main.

Version	Program No.	Effective Date	Availability of RFU
117	C2845115E	October 2017	Not available
116	C2845115D	August 2017	Not available
115	C2845115C	March 2017	Not available
114	C2845115B	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via USB flash memory.

Version	Modified Points or Symptom Corrected						
117	Symptom Corrected:						
	- The wrong screen was displayed when the "E030: Standard EEPROM" error occurred.						
	This package contains the following versions:						
	Version 1.16 : Main PCB Software						
	Version 2.16 : Main PCB Software (Long Paper)						
	Version 1.01 : Panel PCB Software						
	Version 1.01 : Relay PCB Software						
	Version 1.04 : Tape Dispenser PCB Software (with Printing Function)						
	Version 2.01 : Tape Dispenser PCB Software (without Printing Function)						

[&]quot;Available": The firmware can be updated via RFU or SD card.



PAGE: 2/**3**

Model: QU-D1	Date: 10-Nov-17 No.: RC284002					
Version	Modified Points or Symptom Corrected					
116	Symptom Corrected: 1. The following error messages have been added: [E045: Drum position-1 sensor error] When the drum position-1 sensor does not detect the drum removal detection edge within 40 seconds of the drum rotation signal being output.					
	 [E046: Drum position-2 sensor error] When the drum position-2 sensor does not detect the master post-detachment position edge and the master attachment position edge. [E047: Press roller sensor] When the press roller sensor does not detect the lower edge of the press lever even though the drum has rotated 3 times since the printing operation. 2. The lower part of the lamp on the operation panel was blinking in red even if the error occurred when replacing consumables. 3. Only the background of the first page was scanned correctly when using the ADF. 					
	This package contains the following versions: Version 1.15: Main PCB Software Version 2.15: Main PCB Software (Long Pap Version 1.01: Panel PCB Software Version 1.01: Relay PCB Software Version 1.04: Tape Dispenser PCB Software Version 2.01: Tape Dispenser PCB Software	e (with Printing Function				



PAGE: 3/**3**

Model: QU-D1		Date: 10-Nov-17	No.: RC284002			
Version	Modified Points or Symptom Corrected					
115	Symptom Corrected: 1. The detection time of the "Main motor lock" error has been corrected. 2. The following error messages on the operation panel have been changed: - If the drum unit is pulled out when it is not in position: The alternating error messages of "Insert drum until it stops" and "To remove drum, insert drum until it stops and press drum removal button" are displayed. - If the drum unit is pulled out when it is not in position, and the front cover is closed: The error message, "Open front cover and insert drum until it stops" is displayed. 3. The following error message has been changed: - When master making is interrupted: The alternating error messages of "Remove any master wastes" and "Open master roll cover and set master roll properly" are displayed. 4. The power to the thermal head is cut off after master making. 5. The print image is adjusted without displaying the error message when the connector of the vertical reg. center sensor and the vertical reg. encoder sensor are wrongly inserted. 6. In HELP-73, the Format function has been deleted. 7. In the USB printer option, the Format alert message has been changed.					
	This package contains the following versions: Version 1.14: Main PCB Software Version 2.14: Main PCB Software (Long Paper) Version 1.01: Panel PCB Software					
	Version 1.01: Panel PCB Software Version 1.01: Relay PCB Software Version 1.04: Tape Dispenser PCB Software (with Printing Function) Version 2.01: Tape Dispenser PCB Software (without Printing Function)					
114	1st Mass production					

RICOH

Technical Bulletin


Date: 25-Jul-19	No.: RC284003

PAGE: 1/2

Wodel. QO-D1			Date: 23 out 13	140110204000
Subject: Cloth scr	een of drum is torn	Prepar	ed by: K.Yamamoto	
From: Oversea Field				
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	✓ Part informati✓ Electrical✓ Transmit/rece✓ Other (Firmw	Servi	n required ce manual revision fit information

SYMPTOM

Ink leaks from the drum.



CAUSE

The edge of the cloth screen contacts the drum guide during printing, causing it to tear.



RICOH

Technical Bulletin

Model: QU-D1			Date: 25-Jul-19		No.: RC284004	
Subject: Image problem due to shift (Slip out position) cloth screen					Prepared by: K.Yamamoto	
From: Oversea Field Sect., OP Product Quality Dept.						
Classification:	☐ Troubleshooting☐ Mechanical☐ Paper path☐ Product Safety	☐ Part informati☐ Electrical☐ Transmit/rece☐ Other (Firmw	eive		equired manual revision nformation	

PAGE: 1/3

SYMPTOM

Image problems occur.

- The registration position shifts back

or

- The image skews

CAUSE

- The master slips out of place.
- The cloth screen slips from the cloth screen bar.
- The hook of the cloth screen bar does not catch the bar firmly.



Model: **QU-D1** Date: 25-Jul-19 No.: RC284004

PAGE: 2/3

SOLUTION


Replace the following with the new parts, which have improved reliability.

Old part	New part	Description	Q'ty	Int	Note
number	number				
C2842262	C2842306	DP:W9-A1121:BAR:F/A3:ASSY	1	X/O	For A3 Model
C2842263	C2842307	DP:W9-A1131:BAR:R/A3:ASSY	1	X/O	For A3 Model
C2832262	C2832306	DP:W9-A1141:BAR:F/B4:ASSY	1	X/O	For B4 Model
C2832263	C2832307	DP:W9-A1151:BAR:R/B4:ASSY	1	X/O	For B4 Model
C2842276	C2842277	DP:R8-A1522:ANGLE	2	X/O	Common


Note:

- The bar features a new high-friction sheet.

A3: C2842262(Front)/ C2842263(Rear), B4: C2832262(Front)/ C2832263(Rear)



A3: C2842306(Front)/ C2842307(Rear), B4: C2832306(Front)/ C2832307(Rear)






Model: **QU-D1** Date: 25-Jul-19 No.: RC284004

PAGE: 3/3

- The new hook features a corrected angle, as shown.






Model: **QU-D1** Date: 25-Jul-19 No.: RC284003

PAGE: 2/2

SOLUTION

Replace the cloth screen with the new part.

Old part	New part	Description	Q'ty	Int	Note
number	number				
C2842261	C2842245	DP:R8-A1113:SCREEN:A3	1	X/O	For A3 Model
C2832261	C2832245	DP:R8-A1213:SCREEN:B4	1	X/O	For B4 Model



A3: C2842261 C2842245 B4: C2832261 C2832245