Technical Bulletin

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5					te: 31-Jun-08 No.: RD28400		
Subject: Trouble	shooting	Prepare	d by: R. T	Tsurumi			
From: 1st Tech. Support Sec. Service Support Dept.							
Classification:	ation: 🗵 Troubleshooting 🔲 Part inform		ormat	tion	☐ Action	required	
	☐ Mechanical	☐ Electric	al		☐ Service	e manual revision	
	☐ Paper path	☐ Transm	it/rec	eive	☐ Retrof	fit information	
	☐ Product Safety	\square Other ()			

This bulletin is a troubleshooting guide for symptoms that have occurred in the past, all with known solutions. For most items below, there are related MBs and RTBs containing modification details and adjustment procedures.

Note: This RTB is numbered "000" since the information contained in it has already been announced.

Technical Bulletin

PAGE: 2/34

Updated: End of June 2018: Changes in bold italics

_			_		_	
T_{2}	h	\sim	ΛŦ	00	nt/	ents
10		112				51 I I 2

1 (able of contents
1.	Paper Feed Errors 5 Wrong paper size Cannot select paper type Wrong feed mode Bent paper Roller marks Jam Custom paper
2.	Copy Process7
3.	Connectivity
4.	Printing/Scanning

Technical Bulletin

PAGE: 3/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5		Date: 31-Jun-08	No.: RD284000d
Icons Reboots Applications appear und Wrong paper size displayed Wrong screen displayed Resets to default Freezes Touch panel not respendent to the series Button does not work Animation Information display errol Legacy mode Black screen	expectedly ayed d onding		
6. Security Login/logout Authentication Service mode lock Logs Unauthorized users car			19
	819, 845, 899, 990, 991, 9	92, 997, 998	21
8. Optional Units	20		25
9. Image Problems Image density Part of image missing Centering Scaling Rotation			28
10. Mechanical/Electrical. LD unit Noise Motor does not stop			29

Technical Bulletin

PAGE: 4/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

System reset

Settings not reflected

Cannot make settings

Can make disallowed settings

Machine stalls

Firmware update

Energy saver mode

Counters

Insects

Reboot

Machine is slow

Function not working

Machine not responding to a command

Copying does not start

Reports

Logs

Capture

Machine reboots

User cannot operate the machine

Technical Bulletin

PAGE: 5/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

1. Paper Feed Errors

Subject	Symptom	RTB#	Cause	Solution	Note
Wrong paper size	The paper size of the bypass tray set from a widget is not applied to	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Wrong paper size	print jobs An incorrect paper size is fed while printing via AirPrint.	D289 5595F	IRIPS PDF firmware	Install version 1.05 or later	
Cannot select paper type	12x18 cannot be selected for the bypass tray	D289 5560D D289 5561C D284 002e	Web Support firmware Web Uapl firmware System/Copy firmware	Install version 1.03 or later Install version 1.03 or later Install version 1.05 or later	
Cannot select paper type	When printing from AirPrint, the paper weight "Plain 2 (75 to 81g/square metre)" is out of the search target of "Auto Tray Select"	D284 003c	Printer firmware	Install version 1.03 or later	
Cannot select paper type	A3 size cannot be specified in macOS when scanning by using AirPrint	D284 008a	Scanner firmware	Install version 01.01 or later	
Wrong feed mode	The job starts up in manual feed mode even if set to auto paper mode	D284 002e	System/Copy firmware	Install version 1.04 or later	
Bent paper	The paper tends to bend in the center	D284 026	Folder_THAMES- B_C_EXP/LP firmware	Install version 01.030:11 or later	
Roller marks	Roller marks appear at the bottom of the paper	D284 026	Folder_THAMES- B_C_EXP/LP firmware	Install version 01.030:11 or later	
Jam	Jam 001 after replacing the fusing unit on a machine that has an external click-charge counter device	D284 032	The current used to detect a new fusing unit goes to the counter, so the system cannot detect the new fusing unit.	Before installing a new fusing unit, temporarily remove the charge counter device	
Jam	Paper caught between the paper guide and the shift tray	D3BB 5300Q D3B8 5300G D3B9 5300J	Finisher SR3230 firmware Finisher SR3210 firmware Booklet Finisher SR3220 firmware	Install version 01.100:07 or later Install version 01.060:05 or later Install version 01.070:04 or later	

Technical Bulletin

PAGE: 6/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Jam	Original Jam 001 if another document is fed into the ADF while a single-sided document is being scanned	D779 5300L	ARDF 3090 firmware	Install version 01.330:03 or newer.	
Jam	JAM154 or JAM155 when printing a booklet on A3 paper.	D3BB 5300R	Finisher SR3230 firmware	Install version 01.110:07 or later	
Custom paper	The minimum and maximum settable values of a custom paper size are wrong if the unit of measurement is set to millimeters	D241 1443T D241 1447T	SimpleCopy firmware MediaPrtScn firmware	Install version 1.21 or later Install version 1.20 or later	

Technical Bulletin

PAGE: 7/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

2. Copy Process

Subject	Symptom	RTB#	Cause	Solution	Note



Technical Bulletin

PAGE: 8/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

3. Connectivity

Subject	Symptom	RTB#	Cause	Solution	Note
SSL	After applying a security	Gene	Java VM v12	Install version 12.45.00 or	
	update, SSL	087o	Update Tool	newer.	
	communication fails	Gene	Java VM v12 for		
	between Windows and an	088m	eDC firmware		
	application that includes				
	an SSL server function				
SSL	Even if SSL3.0	D284	Network Support	Install version 16.45.1 or	
	communication is disabled	005b	firmware	later	
	in device security settings,				
	SSL3.0 communication is				
	possible from the NRS				
	port (7443/7444)	D004			
@Remote	@Remote registration via	D284	Engine firmware	Install version 1.04:05 or	
	external appliances not	001a		later	
	working	D000		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
@Remote	The Supply Call for Toner	D289	Engine firmware	Install version 1.06:05 or	
	Bottle is not sent to the	5500E		newer.	
	@Remote Center if the	D284			
	toner bottle is replaced at	037			
@Domoto	Toner Near End The value of SP8-781-001	D289	Engine firmware	Install version 1.06:05 or	
@Remote	(Toner Replacement	5500E	Engine minware	Install version 1.06:05 or	
	Counter) does not count	D284		newer.	
	up if the toner bottle is	037			
	replaced at Toner Near	037			
	End				
WIM	Cannot access the	D284	NetworkDocBox	Install version 1.02 or later	
	machine with WIM	004a	firmware		
WIM	The list of installed	D289	System/Copy	Install version 1.11 or later	
	applications is not	5550P	firmware		
	displayed in Extended				
	Feature Info				
WIM	Incorrect wording for	D289	Web Support	Install version 1.08 or later	
	"Remote Panel Operation"	5560J	firmware		
	in the menu				
Fax	Cannot receive after	D284	GWFCU3.8-	Install version 03.00.00 or	
	attempting to send a	012a	16(WW)	later	
	folder		firmware		
Fax	The fax function does not	D289	Fax firmware	Install version 05.00.00 or	
	work, if the SNTP time	5557F		later	
	setting and STR setting				
_	are enabled	Docc	D . -	1	
Fax	Cannot receive an IP-Fax	D289	Remote Fax	Install version 04.00.00 or	
	(SIP) transmitted from a	5558E	firmware	later	
Гом	Canon machine.	Dooc	OMEGUO	Install version 04 00 00 c	
Fax	If [Store and Print] is	D289	GWFCU3.8-	Install version 04.00.00 or	
	enabled and a document	5559D	16(WW)	later	
	is deleted from		firmware		
	GlobalScan, the fax				
	function becomes				
	inoperable	1			

Technical Bulletin

PAGE: 9/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Fax	After continuously using	D289	GWFCU3.8-	Install version 04.00.00 or	
	Remote Fax, "FAX jobs	5559D	16(WW)	later	
	are full" appears and		firmware		
	Remote Fax becomes				
	disabled				
Fax	Fax not sent, with the	D289	GWFCU3.8-	Install version 04.00.00 or	
	status showing	5559D	16(WW)	later	
	"processing", possibly		firmware		
	followed by a SC843-02				
Fax	Cannot send if CAP v2 is	D289	Java VM v12	Install version 12.56.00 or	
	installed	5567H	Update Tool	newer.	
			Java VM v12 for		
			eDC firmware		
Fax	Fax app stalls	D289	Fax firmware	Install version 06.00.00 or	
		5557G		later	
Fax	Cannot get the fax	D289	Network Support	Install version 16.51.1 or	
-	transmission result using	5564L	firmware	later	
	FTP	- - -		-	
Fax	If temporary memory	D289	GWFCU3.8-	Install version 05.00.00 or	
	overflows when storing a	5559E	16(WW)	later	
	fax, the machine cannot	*****	firmware	1.010	
	use fax for two days		i i i i i i i i i i i i i i i i i i i		
Fax	If temporary memory	D289	GWFCU3.8-	Install version 05.00.00 or	
	overflows when the	5559E	16(WW)	later	
	machine receives a fax,	00002	firmware	late	
	fax reception is canceled				
	and the Job Log records a				
	user cancellation				
Fax	Cannot send, receive, or	D289	RemoteFax	Install version 05.00.00	
	print the transmitted fax	5558F	firmware	or later	
	if the sending machine				
	disconnects during IP-				
	FAX transmission				
Fax	A sending error occurs	D289	RemoteFax	Install version 05.00.00	
	with PC-FAX.	5558F	firmware	or later	
Fax	When sending a fax via	D289	Fax firmware	Install version 07.00.01	
	the SmartSDK, images	5557H		or later	
	might be missing or				
	output at the wrong size				
Fax	When Hook Dial is	D289	Fax firmware	Install version 07.00.01	
- 4.51	pressed or when Manual	5557H		or later	
	Entry is selected, the				
	SmartFax application				
	might crash.				
Fax	The image is vertically	D289	IRIPS PDF	Install version 1.04 or	
- 477	extended and the upper	5595K	firmware	later	
	part is missing when				
	faxing via Remote Fax				
Fax	When sending a fax via	D289	IRIPS PDF	Install version 1.04 or	
ı ax	the SmartSDK, images	5595K	firmware	later	
	are missing or output at	JUJUK	III III Wai C	later	
	the wrong size.				
	uie wiong size.	<u> </u>	<u> </u>		

Technical Bulletin

PAGE: 10/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Correct value	When showing the device	D289	Java VM v12	Install version 12.50.01 or	
not displayed	status with a Solution	5567F	Update Tool	newer.	
	Product (Streamline and		Java VM v12 for		
	CAP/ELP), the device's		eDC firmware		
	HDD capacity is not				
	displayed correctly				
MIB	An invalid value is	D289	System/Copy	Install version 1.07 or later	
	returned when obtaining	5550K	firmware		
	the counter MIB,				
	ricohEngCounterValue,				
	during device shutdown				
Cannot	If using Google Chrome	D289	Web Uapl	Install version 1.04 or later	
download	when downloading	5561D	firmware		
	scanned data from a URL,				
	the PDF file cannot				
Coon to	download	D200	Notice of Company	Install version 4C 40 or	
Scan to Folder	Communication fails	D289 5564H	Network Support firmware	Install version 16.48 or later	
Scan to	If a host name is resolved	D289	Network Support	Install version 16.51.1 or	
Folder	to multiple IP addresses	5564L	firmware	later	
1 Oluei	by NBNS, the device tries	3304L	Illiliwale	latei	
	to connect to only the first				
	resolved IP address				
Scan to	Fails when a HP device is	D289	Network Support	Install version 16.51.1 or	
Folder	working on the same	5564L	firmware	later	
	subnet				
Scan to	Network browsing fails	D289	Network Support	Install version 16.51.1 or	
Folder		5564L	firmware	later	
Scan to	When conducting Scan	D289	Network	Install version 16.52 or	
Folder	to Folder using	5564M	Support	later	
	SMBv2/v3, if the device		firmware		
	receives UDP				
	communication from the				
	outside to the port used by SMBv2/v3, Scan to				
	Folder might fail				
Scan to	Fails when OCR is set	D289	Scanner	Install version 01.05 or	
Email	and a document over 51	5571G	firmware	later	
2	pages is sent by Scan to		i i i i i i i i i i i i i i i i i i i		
	Email				
Wrong	When sending a scanned	D289	Network Support	Install version 16.49 or	
document	or fax document using the	5564J	firmware	later	
sent	Hotfolder plug-in for				
	GlobalScan or				
	StreamlineNX, the wrong				
	document was sent and				
	the original document may				
	be lost.				
Machine	If log tracing on Web	D289	System/Copy	Install version 1.11 or later	
goes offline	Image Monitor is	5550P	firmware		
	cancelled just after using				
	the function	<u> </u>			

Technical Bulletin

PAGE: 11/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Address	After exporting the	D289	System/Copy	Install version 1.11 or later	
book	address book from Device	5550P	firmware		
	Manager NX, the exported				
	data cannot be imported				
Other	WebAPI bug when	D289	Network Support	Install version 16.50 or	
	obtaining network	5564K	firmware	later	
	property information				

Technical Bulletin

PAGE: 12/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

4. Printing/Scanning

Subject	Symptom	RTB#	Cause	Solution	Note
Cannot	When trying to control	D259	PrinterInfo for	Install version 1.11 or	
print	jobs while a job is	020i	eDC firmware	later	
	suspended				
Cannot	When many scan jobs	D289	Scanner firmware	Install version 01.02 or	
scan	are scanned from an	5571D		later	
	application that is based				
	on SmartSDK				
Cannot	When "Download File	D284	Scanner firmware	Install version 01.01 or	
scan	Directly From URL Link"	008a		later	
	is enabled and scan to				
	URL is conducted	D.000			
Cannot	The Scanner application	D289	Scanner firmware	Install version 01.02 or	
scan	cannot be used	5571D		later	
Cannot	When OCR is set and a	D289	Scanner firmware	Install version 01.05 or	
scan	document over 256	5571G		later	
	pages is scanned, the				
	Scanner application				
Connet	freezes When the device is	D289	Cooppor firms	Install version 04.06 an	
Cannot			Scanner firmware	Install version 01.06 or	
scan	accessed from Web	5571H		later	
	Image Monitor just before scanning is				
	finished, cannot start the				
	scanner application				
Cannot	When conducting Scan	D289	Network Support	Install version 16.52 or	
scan	to Folder in a high-load	5564M	firmware	later	
Scall	network environment,	3304IVI	IIIIIWaie	later	
	the device's status				
	gets stuck on sending				
	and the scanner				
	becomes unusable.				
Job not	When the display	D259	PrinterInfo for	Install version 1.11 or	
completed	language is changed	020i	eDC firmware	later	
	while controlling a job	0_0.			
Job not	Printing does not finish	D284	IRIPS PDF	Install version 1.02 or	
completed	when a job that contains	021a	firmware	later	
	multiple PDLs is printed				
Job not	Printing does not finish if	D284	IRIPS PDF	Install version 1.02 or	
completed	the previous print job	021a	firmware	later	
,	from a storage device is				
	cancelled immediately				
				Install version 1.17 or	
File not	PDF files that have long,	D259	MediaPrtScn for	IIIStali version 1.17 or	
File not printed		D259 022k	MediaPrtScn for eDC firmware	later	
	PDF files that have long,				
	PDF files that have long, multibyte filenames are				
printed	PDF files that have long, multibyte filenames are not printed	022k	eDC firmware	later	
printed Cannot	PDF files that have long, multibyte filenames are not printed When "Tracking	022k Gene	eDC firmware Java VM v12	later Install version 12.45.00	
printed Cannot	PDF files that have long, multibyte filenames are not printed When "Tracking Permission" and "Stop	022k Gene 087o	eDC firmware Java VM v12 Update Tool	later Install version 12.45.00	
printed Cannot	PDF files that have long, multibyte filenames are not printed When "Tracking Permission" and "Stop Printing" are enabled in	O22k Gene 087o Gene	eDC firmware Java VM v12 Update Tool Java VM v12 for	later Install version 12.45.00	
printed Cannot	PDF files that have long, multibyte filenames are not printed When "Tracking Permission" and "Stop Printing" are enabled in "Enhanced Print Volume	O22k Gene 087o Gene	eDC firmware Java VM v12 Update Tool Java VM v12 for	later Install version 12.45.00	

Technical Bulletin

PAGE: 13/34

Updated: End of June 2018: Changes in bold italics

0.11.1	0 1	D.T.D. !!		0.1.0	NI 4
Subject	Symptom	RTB#	Cause	Solution	Note
Job	When printing PDF data	D3DW	PDF firmware	Install version 1.01 or	
cancelled	that includes	5733A		later	
	overprinting via PDF				
Lab	Direct Print	D004	0	lantally ansign 4.05 an	
Job	When attempting to print	D284	System/Copy	Install version 1.05 or	
cancelled	a banner job	002e	firmware	later	
Job	When print a job with a	D284	IRIPS PDF	Install version 1.02 or	
cancelled	custom paper size that does not have an	021a	firmware	later	
Job	orientation specified When the "Unauthorized	D284	IRIPS PDF	Install version 1.02 or	
cancelled	Copy Prevention	021a	firmware	later	
Caricelled	Setting" is enabled in the	UZIA	Illiliwaic	later	
	device but not				
	configured in the print				
	data				
Job	The printing of a PDF file	D289	IRIPS PDF	Install version 1.05 or	
cancelled	created by "Microsoft	5595F	firmware	later	
cariociica	Print to PDF"	00001	IIIIIWare	later	
Job	When printing PCL6 jobs	D289	PCL firmware	Install version 1.04 or	
cancelled	containing a TrueType	5566E	. 62	later	
	Font				
Job	Linux print jobs in Stored	D289	IRIPS PDF	Install version 1.07 or	
cancelled	Print might be canceled	5595J	firmware	later	
Remaining	Display is incorrect for	D284	System/Copy	Install version 1.03 or	
print time	jobs printed from the	002c	firmware	later	
•	document server.				
Fonts	A PCL font numbered 64	D284	Printer firmware	Install version 1.04 or	
	or later cannot be used	003d		later	
	as the default font				
Fonts	When printing PDF data	D284	IRIPS PDF	Install version 1.02 or	
	that includes an Adobe	021a	firmware	later	
	font that will be replaced				
	with an IRIPS font, the				
	replaced font overlaps				
Fonts	When printing with	D284	IRIPS PDF	Install version 1.02 or	
	"Unauthorized Copy	021a	firmware	later	
	Prevention" enabled				
	from MacOS, an Adobe				
	font will be replaced with				
E	an IRIPS font	Docc	IDIDO DES	In a fall complete 4 05	
Fonts	Some characters are	D289	IRIPS PDF	Install version 1.05 or	
Forsto	printed upside down	5595F	firmware	later	
Fonts	"Invalidfont" error	D289	IRIPS PDF	Install version 1.05 or	
Eanta	Somo Timo O fonto in a	5595F	firmware	later Install version 1.04 or	
Fonts	Some Type 0 fonts in a	D289 5595K	IRIPS PDF		
	PDF do not print	2292K	firmware	later	
Fonts	correctly. Some Symbolic fonts	D289	IRIPS PDF	Install version 1.04 or	
runts	in a PDF do not print	5595K	firmware	later	
	correctly.	JJJJK	in iliwal e	iatei	
	Correctly.				
	1	<u> </u>	1	<u> </u>	<u> </u>

Technical Bulletin

PAGE: 14/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
PDF	When printing a PDF	D289	IRIPS PDF	Install version 1.04 or	
	with an embedded	5595K	firmware	later	
	TrueType font, some				
PDF	characters are garbled. When printing a PDF	D289	IRIPS PDF	Install version 1.04 or	
PDF	with a specific	5595K	firmware	later	
	command, an	JJ9JK	Illiliware	later	
	invalidfont error				
	occurs				
Printing	When the device is in	D284	Network Support	Install version 16.46 or	
stops	STR mode; device must	005c	firmware	later	
	be rebooted				
Printing	PS printing stalls if PS	D289	IRIPS PDF	Install version 1.06 or	
stops	jobs are printed	5595G	firmware	later	
	continuously				
Characters	When conducting host	D284	PCL firmware	Install version 1.03 or	
missing or	printing, if a resident font	015b	IDIDO E (later	
damaged	is specified in the data,	D284	IRIPS Font	Install version 1.13 or	
	cedillas will not print as expected	020a D284	firmware IRIPS PDF	later Install version 1.03 or	
	expected	021b	firmware	later	
Characters	Some characters are	D289	IRIPS PDF	Install version 1.06 or	
missing or	garbled when using a	5595G	firmware	later	
damaged	TrueType Font	00000	iiiiiwaro		
Problems	Characters in italics are	D289	IRIPS PDF	Install version 1.07 or	
with	unrecognizable	5595H	firmware	later	
characters					
Problems	Wrong size when	D289	IRIPS PDF	Install version 1.07 or	
with	printing a PDF	5595H	firmware	later	
characters	containing certain fonts				
Problems	Characters printed with	D289	IRIPS PDF	Install version 1.07 or	
with	the wrong magnification	5595J	firmware	later	
characters	if a CID font is used	D200	IRIPS PDF	Install version 1.07 or	
Problems with	Characters are too thick	D289 5595J	firmware	Install version 1.07 or later	
characters	if the transparency is specified.	55955	IIIIIware	ialei	
Macros	PCL macros that were	D284	PCL firmware	Install version 1.03 or	
Madros	uploaded to the HDD	015b	1 OL IIIII Wale	later	
	cannot be printed				
Pages not	If an original jams in the	D284	System/Copy	Install version 1.05 or	
printed	sample copy of a	002e	firmware	later	
	stapled job, the first set				
	is not printed				
Pages not	Printing of the	D284	IRIPS PDF	Install version 1.02 or	
printed	Configuration / Font	021a	firmware	later	
E 11 (Page is canceled	D004	0	Leafall consists Od Od	
Files not	When a scan job is	D284	Scanner firmware	Install version 01.01 or	
deleted	conducted from the	008a		later	
Viewer	simplified screen When scanning from	D284	Scanner firmware	Install version 01.01 or	
v icwei	Mac OS X 10.12 by	008a	Jeanner IIIIIwale	later	
	using AirPrint, the output	500a			
	file cannot be opened in				
	the viewer				
		l	I	I	

Technical Bulletin

PAGE: 15/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Page order	Incorrect	D284	IRIPS PDF	Install version 1.02 or	11010
		021a	firmware	later	
Image size	Print size miscalculation	D284	IRIPS PDF	Install version 1.02 or	
	when the printer reduces	021a	firmware	later	
	or enlarges the paper				
	size.				
Result not	The printed result of a	D284	IRIPS PDF	Install version 1.02 or	
same as	PDF file with Banner	021a	firmware	later	
preview	Page might be different				
0.00	from the preview	Dooo	0 1 10	1 1 1 1 2 2	
OCR	OCR cannot recognize	D289	System/Copy	Install version 1.07 or	
	characters if converting	5550K	firmware	later	
	a scanned image to				
IDDC	searchable PDF	D200	Drinter firmerrane	Install version 4 07 or	
IPDS	IPDS form creation fails	D289 5573J	Printer firmware	Install version 1.07 or later	
	when specifying a	33733		later	
IPDS	custom paper size The Default Punch	D289	Printer firmware	Install version 1.07 or	
IFDS	Pattern cannot be set to	5573J	Filliter illiliware	later	
	"two holes" for IPDS	55755		latei	
	printing.				
IPDS	"Back copied paper" isn't	D289	Printer firmware	Install version 1.07 or	
" 50	listed under the media	5573J	1 mile minware	later	
	type for IPDS forms.	00700			
IPDS	IPDS printing stalls if	D289	Printer firmware	Install version 1.07 or	
2 0	IPDS jobs are printed	5573J		later	
	continuously.				
IPDS	Characters in the IPDS	D289	Printer firmware	Install version 1.07 or	
	form name are distorted	5573J		later	
IPDS	IPDS Form not created	D289	Printer firmware	Install version 1.08 or	
	when the machine has	5573K		later	
	an Internal Multi-fold				
	Unit FD3000				
IPDS	IPDS printing fails when	D289	Printer firmware	Install version 1.08 or	
	the machine has an	5573K		later	
	Internal Multi-fold Unit				
	FD3000				
Wrong	When scanning from	D289	Scanner firmware	Install version 01.05 or	
format	SmartSDK applications,	5571G		later	
	files are stored in PDF/A				
	format when trying to				
	store in TIFF/JPEG				
Wrong	format	D289	Scanner firmware	Install version 01.06 or	
Wrong format	When scanning with AirPrint in MacOS X	5571H	Scarnier millware	later	
ioiiilat	10.12 or later, the device	337 IT		ialei	[
	sends a full color JPEG				
	even if specifying a				
	black and white JPEG.				
AirPrint	An incorrect paper size	D3DW	PDF firmware	Install version 1.02 or	
	is fed	5733B	. 5	later	
					
		•		<u> </u>	

Technical Bulletin

PAGE: 16/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
AirPrint	When conducting AirPrint, if port 80/TCP (HTTP) or port 631/TCP (IPP) in the printer is closed, the Apple device cannot find the printer	D289 5564M	Network Support firmware	Install version 16.52 or later	
Others	Cancelling a scan job while the preview is displayed causes the information of the captured image file to be recorded incorrectly	D289 5571K	Scanner firmware	Install version 01.08 or later	



Technical Bulletin

PAGE: 17/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

5. Operation Panel

Subject	Symptom	RTB#	Cause	Solution	Note
Icons	SDKJ application icon	D241	Cheetah System	Install version 1.23 or	
	not displayed on the	1425	firmware	later	
	home screen	D241			
		1429			
Icons	The SDK application	D289	Java VM v12 std	Install version 12.54.00	
	icon is not displayed	5567G	for eDC firmware	or later	
	after recovering from	D289	Java VM v12 std	Install version 12.54.00	
	energy saving mode	5567G	UpdateTool	or later	
Icons	The yellow mark not	D241	SmartCopy	Install version 1.25 or	
	displayed on the 'Other	1454X	firmware	later	
	Settings' icon even if				
	one of the 'Other				
D 1 1	Settings' is enabled	DOEG	01 1 1 0 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Reboots	While entering sleep	D259	Cheetah System	Install version 1.22.2 or	
	mode; may be	012u	firmware	later	
	followed by				
Applications	SC819/SC672	D259	Cheetah System	Install version 1.22.2 or	
		012u	firmware	later	
appear unexpectedly		0120	Illiliwale	latei	
Wrong paper	Tray 1, after the	D259	PrinterInfo for	Install version 1.11 or	
size	display language is	020i	eDC firmware	later	
displayed	changed	0201	CDO IIIIIWaic	later	
Wrong	After printing, the file	D259	MediaPrtScn for	Install version 1.17 or	
screen	selection screen is not	022k	eDC firmware	later	
displayed	displayed				
Resets to	The screen switches to	D259	LegacyUI for eDC	Install version 1.15.1 or	
default	the default setting of	035m	firmware	later	
	Function Priority when				
	connected to a USB				
	device such as a				
	keyboard				
Freezes	If the Start button is	D284	System/Copy	Install version 1.04 or	
	pressed immediately	002e	firmware	later	
	after recovering from				
	the energy saver mode				
Freezes	When the SOP and	D241	Cheetah System	Install version 1.27.2	
	the application	1425F	firmware	or later	
	settings are exported	D241 1429F			
	using the backup function	1429F			
Touch panel	After the machine	D241	Legacy UI	Install version 1.22 or	
not	stalled during ARFU	1427Z	firmware	later	
responding	Janea aarmy / ii ii o				
Button does	Start button does not	D284	System/Copy	Install version 1.04 or	
not work	work after a jam occurs	002e	firmware	later	
Animation	Jam animation error	D289	System/Copy	Install version 1.06 or	
	related to folder	5550J	firmware	later	
	FD3000	D289	Animation	Install version 1.02 or	
		5562D	firmware	later	

Technical Bulletin

PAGE: 18/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Information	Remaining toner	D289	System/Copy	Install version 1.06 or	
display error	display error	5550J	firmware	later	
Legacy mode	Problems with the	D284	Do not use	Use v1.19 or earlier.	
	Smart Operation Panel	041	Legacy UI		
	when Legacy mode is		Firmware v1.20		
	use				
Black	After switching the	D241	PrinterSJob	Install version 1.75 or	
screen	user or the display	1446R	firmware	later	
	language, a black				
	screen is displayed				
	for a few seconds				
	when opening Quick				
	Print Release				



Technical Bulletin

PAGE: 19/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

6. Security

Subject	Symptom	RTB#	Cause	Solution	Note
Login/logout	Login screen shown after swiping with an IC card	D241 1425 D241 1429	Cheetah System firmware	Install version 1.23 or later	
Login/logout	Users forcefully logged off while printing or previewing a print.	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Login/logout	Cannot logout	D289 5571D	Scanner firmware	Install version 01.02 or later	
Login/logout	Cannot logout when the device is accessed from Web Image Monitor just before scanning is finished	D289 5571H	Scanner firmware	Install version 01.06 or later	
Login/logout	Cannot log in if the machine repeatedly enters and exits Energy Saver Mode	D289 5550R	System/Copy firmware	Install version 1.13 or later	
Authentication	The user code is cleared when transitioning to the Home screen	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Authentication	The DSDK application fails to connect to the LDAP server when using Kerberos authentication	Gene 087p Gene 088n	Java VM v12 for eDC Java VM v12 Update Tool	Install version 12.47.01 or later Install version 12.47.01 or later	
Authentication	User authentication in SDK application not working	D284 001a	Engine firmware	Install version 1.04:05 or later	
Authentication	After entering the user code to start up the Copy application, the user code input screen does not disappear	D284 002e	System/Copy firmware	Install version 1.04 or later	
Authentication	If some characters are included in a user name, login authentication is not correctly done	D289 5550P	System/Copy firmware	Install version 1.11 or later	
Service mode lock	Can be unlocked by the user	D284 002a	System/Copy firmware	Install version 1.02.1 or later	

Technical Bulletin

PAGE: 20/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Logs	When changing the password policy in the "Extended Security" menu through WIM, it is not recorded in the access log	D289 5560E	Web Support firmware	Install version 1.04 or later	
Unauthorized users can operate	User usage restrictions do not work if authentication is enabled in Quick Card Authentication	D289 5550P	System/Copy firmware	Install version 1.11 or later	

Technical Bulletin

PAGE: 21/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

7. Error Codes

Subject	Symptom	RTB#	Cause	Solution	Note
SC672	Reboots after entering	D259	Cheetah System	Install version 1.22.2 or	
	sleep mode	012u	firmware	later	
SC672	After recovering from	D289	System/Copy	Install version 1.06 or	
	sleep mode	5550J	firmware	later	
SC672-11	Cannot recover from	D284	System/Copy	Install version 1.02 or	
	entering sleep mode	002a	firmware	later	
SC673-10	When turning ON the	D284	System/Copy	Install version 1.05 or	
	machine power	002e	firmware	later	
SC701-08		D779	ARDF 3090	Install version	
		5300M	firmware	01.340:03 or newer.	
SC816-98	While the system	D289	System/Copy	Install version 1.06 or	
	enters the STR mode	5550J	firmware	later	
SC816-98	While the system is in	D289	PowerSaving Sys	Install version F.L3.06.1	
	STR mode	5554A	firmware	or later	
SC819	Reboots after entering	D259	Cheetah System	Install version 1.22.2 or	
	sleep mode	012u	firmware	later	
SC819	If the auto log-out timer	D284	System/Copy	Install version 1.04 or	
	and the energy saving	002e	firmware	later	
	timer are set to the				
	same value				
SC819	After removing a jam	D284	System/Copy	Install version 1.04 or	
	that occurred while	002e	firmware	later	
	printing a large job				
SC819	After a reboot	D289	System/Copy	Install version 1.06 or	
		5550J	firmware	later	
SC819	After updating firmware	D289	Network Support	Install version 16.51.1 or	
	remotely	5564L	firmware	later	
SC845	While updating using a	D289	System/Copy	Install version 1.06 or	
	firmware package	5550J	firmware	later	
SC899	When doing location-	Gene	Java VM v12 for	Install version 12.47.01	
	free printing or	087p	eDC	or later	
	authentication by using	Gene	Java VM v12	Install version 12.47.01	
	a solution product	088n	Update Tool	or later	
SC899	When printing a PDF	D3DW	PDF firmware	Install version 1.01 or	
	file that contains	5733A		later	
	graphics or text via				
	PDF Direct				
SC899	During use of an	D284	System/Copy	Install version 1.02 or	
	application on	002a	firmware	later	
	@Remote connected				
	machines				
SC899	After updating with the	D284	System/Copy	Install version 1.02 or	
	packaged firmware	002a	firmware	later	
SC899	When installing	D284	System/Copy	Install version 1.02 or	
	@Remote	002a	firmware	later	
SC899	When the "Erase All	D284	Network Support	Install version 16.45.1 or	
	Memory" function is	005b	firmware	later	
	used				
SC899	When logging out from	D284	Fax firmware	Install version 03.00.00	
	a machine with user	009a		or later	
	authentication enabled	•	1	•	

Technical Bulletin

PAGE: 22/34

Updated: End of June 2018: Changes in bold italics

			1	-	
Subject	Symptom	RTB#	Cause	Solution	Note
SC899	When receiving IP FAX	D284 010b	RemoteFax firmware	Install version 03.00.00 or later	
SC899	When printing a PCL5 job that contains commands for selecting a Raw TrueType font	D284 015a	PCL firmware	Install version 1.02 or later	
SC899	When scanning a document with the OCR setting configured	D289 5571D	Scanner firmware	Install version 01.02 or later	
SC899	When the printer receives invalid PDF data	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
SC899	While printing multiple PS jobs that contain Adobe fonts with Authentication Management	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
SC899	When canceling one of multiple spooled PDFs that contain more than 3,000 pages sent via FTP	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
SC899	When printing	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
SC899	When a watermark is printed from the V4 driver	D289 5595G	IRIPS PDF firmware	Install version 1.06 or later	
SC899	If logging in from a keyboard	D289 5567H	Java VM v12 Update Tool Java VM v12 for eDC firmware	Install version 12.56.00 or newer.	
SC899	In wireless LAN infrastructure mode, if changing the settings when the PSK in WPA2-PSK is empty	D289 5564K	Network Support firmware	Install version 16.50 or later	
SC899	The document being faxed is targeted for capture	D289 5565D	Network Doc Box firmware	Install version 1.03 or later	
SC899	If a large number of different characters are used in a print job	D3DW 5733B	PDF firmware	Install version 1.02 or later	
SC899	When printing via PDF Direct if a job includes more than 500 pages	D3DW 5733B	PDF firmware	Install version 1.02 or later	
SC899	While PDF printing	D289 5595H	IRIPS PDF firmware	Install version 1.07 or later	
SC899	When doing Scan to Folder	D289 5564L	Network Support firmware	Install version 16.51.1 or later	
SC990	After an SC reboot occurs	D284 003b	Printer firmware	Install version 1.02 or later	

Technical Bulletin

PAGE: 23/34

Updated: End of June 2018: Changes in bold italics

			<u> </u>	<u> </u>	
Subject	Symptom	RTB#	Cause	Solution	Note
SC990	After cancelling scanning	D289 5550P	System/Copy firmware	Install version 1.11 or later	
SC991	During use of an application on @Remote connected machines	D284 002a	System/Copy firmware	Install version 1.02 or later	
SC991	When the "Erase All Memory" function is used	D284 005b	Network Support firmware	Install version 16.45.1 or later	
SC991	After cancelling scanning	D289 5550P	System/Copy firmware	Install version 1.11 or later	
SC991	The document being faxed is targeted for capture	D289 5565D	Network Doc Box firmware	Install version 1.03 or later	
SC992		D284 038	The controller freezes while in Energy Saver mode.	Update the PowerSaving Sys firmware to version F.L3.06.1 or later.	
SC997	When OCR is set and a document over 256 pages is scanned	D289 5571G	Scanner firmware	Install version 01.05 or later	
SC998	When powering on if an ESA application is set as a function priority	D289 5550K	System/Copy firmware	Install version 1.07 or later	
SC998	If Streamline NX and CAP v2 are installed	D289 5567G D289 5567G	Java VM v12 std for eDC firmware Java VM v12 std UpdateTool	Install version 12.54.00 or later Install version 12.54.00 or later	
After replacing a fusing unit	An SC occurs after replacing the fusing unit on a machine that has an external click-charge counter device; see the RTB for a list of SCs that can occur	D284 032	The current used to detect a new fusing unit goes to the counter, so the system cannot detect the new fusing unit.	Before installing a new fusing unit, temporarily remove the charge counter device	
Java VM related SC	When doing location- free printing or authentication by using a solution product	Gene 087p Gene 088n	Java VM v12 for eDC Java VM v12 Update Tool	Install version 12.47.01 or later Install version 12.47.01 or later	
Error not displayed	After the device is restarted, error messages are not displayed	D259 020i	PrinterInfo for eDC firmware	Install version 1.11 or later	
Error not displayed	Error messages briefly appear and then disappear	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Error not displayed	If the Bypass tray is set to Auto paper detection, jam alert does not appear	D284 002e	System/Copy firmware	Install version 1.04 or later	
	1	<u> </u>	l		

Technical Bulletin

PAGE: 24/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
"Please wait"	When the Printer application is opened after the device resumes from sleep	D259 020i	PrinterInfo for eDC firmware	Install version 1.11 or later	
	mode				
'Please wait'		D241 1427Y	Legacy UI firmware	Install version 1.21 or later	
Wrong error message	A message about the Application Site closing appears after correcting a setting error for the drum unit	D259 037h	Application Site for eDC firmware	Install version 1.04.05 or later	
Wrong error message	Connection error message may appear mistakenly on @Remote connected machines	D284 002a	System/Copy firmware	Install version 1.02 or later	
Wrong error message	Unrelated error message when the printer receives data that contains unconfigurable folding settings	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
Unspecified error	AirPrint (FaxOut) results in an error	D284 009b	Fax firmware	Install version 04.00.00 or later	
PS error	Printing highly compressed PDF data	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
"undefinedre sult" error	Printing a PDF	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	



Technical Bulletin

PAGE: 25/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

8. Optional Units

Subject	Symptom	RTB#	Cause	Solution	Note
Applications	Scanner application	D259	SmartScan for	Install version 1.13 or	
	ends abnormally	019k	eDC firmware	later	
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
	17 x 22 paper in the	021g	eDC firmware	later	
	input tray is displayed as 11 x 17				
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
	The application screen is blacked out when it is reopened	021g	eDC firmware	later	
Applications	Quick Print Release:	D259	PrinterSJob for	Install version 1.59 or	
, , , , , , , , , , , , , , , , , , , 	Cannot start after the device resumes operating from energy-saving mode	021g	eDC firmware	later	
Applications	Printer Bit Switch #12-	D259	PrinterSJob for	Install version 1.59 or	
7 (\$\rho\)	5 does not behave properly	021g	eDC firmware	later	
Applications	Wrong Product ID	D259	PrinterSJob for	Install version 1.60 or	
• •	used	021h	eDC firmware	later	
Applications	The application aborts	D259	MediaPrtScn for	Install version 1.17 or	
	while trying to print via the bypass tray.	022k	eDC firmware	later	
Applications	The application is	D259	MediaPrtScn for	Install version 1.17 or	
	unresponsive when many jobs via ADF are scanned.	022k	eDC firmware	later	
Applications	Destinations missing	D259	SimpleScan for	Install version 1.12 or	
F1	from Quick Scanner	030j	eDC firmware	later	
Applications	SDK applications do	Gene	Java VM v12	Install version 12.45.00	
• •	not behave properly	087o	Update Tool	or newer.	
		Gene	Java VM v12 for		
		088m	eDC firmware		
Applications	Cannot use required	Gene	Java VM v12 for	Install version 12.47.01	
	version of Java VM	087p	eDC	or later	
	after replacing the controller board	Gene 088n	Java VM v12 Update Tool	Install version 12.47.01 or later	
Applications	Java VM does not recognize a change in	Gene 087p	Java VM v12 for eDC	Install version 12.47.01 or later	
	relationship between	Gene	Java VM v12	Install version 12.47.01	
	the host name and the IP address on the DNS	088n	Update Tool	or later	
	server				
Applications	Notifications are not displayed even if key counter management or external charge unit management is enabled	D284 003c	Printer firmware	Install version 1.03 or later	

Technical Bulletin

PAGE: 26/34

Updated: End of June 2018: Changes in bold italics

Subject Applications	Symptom	RTB#	Cause	Solution	
4	Some Smart SDK	D284	Firmware bug	Install newer Cheetah	Note
	applications are	027		System firmware	
	deleted with	-			
	CheetahSystem v1.21.				
Applications	SDK applications do	D284	Java VM firmware	Install version 12.45.00	
1.1.	not behave properly	028	bug	or newer.	
Applications	SDK applications	D289	Java VM v12 std	Install version 12.54.00	
1.1.	cannot start during the	5567G	for eDC firmware	or later	
	boot process due to a	D289	Java VM v12 std	Install version 12.54.00	
	Java VM error	5567G	UpdateTool	or later	
Applications	Cannot install	D289	Java VM v12 std	Install version 12.54.00	
• •	applications remotely	5567G	for eDC firmware	or later	
		D289	Java VM v12 std	Install version 12.54.00	
		5567G	UpdateTool	or later	
Applications	Cannot apply profiles	D289	Java VM v12 std	Install version 12.54.00	
• •	or retrieve device	5567G	for eDC firmware	or later	
	information	D289	Java VM v12 std	Install version 12.54.00	
		5567G	UpdateTool	or later	
Applications	The quota notification	D289	System/Copy	Install version 1.11 or	
	cannot be displayed on	5550P	firmware	later	
	some SmartSDK				
	applications				
Applications	Remote un-installation	D289	System/Copy	Install version 1.11 or	
	for Streamline NX fails	5550P	firmware	later	
Applications	Java VM does not	D289	System/Copy	Install version 1.11 or	
	recognize a change in	5550P	firmware	later	
	the relationship				
	between the host				
	name and the IP				
	address on the DNS				
	server.				
Applications	The SDK application	D289	Java VM v12 std	Install version 12.54.00	
	stops suddenly	5567J	for eDC firmware	or later	
		D289	Java VM v12 std		
		5567J	UpdateTool		
Applications	Legacy applications do	D241	Legacy UI	Install version 1.21 or	
	not open	1427Y	firmware	later	
Finisher	SR3220: The staple on	D3B9	Booklet Finisher	Install version 01.050:04	
SR3210/SR3	the booklet is bent,	001c	SR3220 firmware	or later	
220	because the stapler				
	does not activate at the				
	correct time.				
Finisher	Information such as	D284	System/Copy	Install version 1.03 or	
SR3210/	stapling position may	002c	firmware	later	
SR3220	be incorrect				
Finisher	Banner paper and	D3BA	The sheets hit the	Attach a mylar (P/N	
SR3230/	envelopes are stacked	005	top cover when	D3BB7495). See the	
SR3240	poorly.		fed out.	RTB for the procedure.	
Stapler	The stapleless stapler	D284	Printer firmware	Install version 1.04 or	
	on the finisher cannot	003d		later	
	be used when the				
	staple cartridge is				
	empty				

Technical **B**ulletin

PAGE: 27/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Folding	Even though letter fold with text and/or images facing out is configured to open to the left, the result will be open to the right	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	

Technical Bulletin

PAGE: 28/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

9. Image Problems

Subject	Symptom	RTB#	Cause	Solution	Note
Image density	Too dark or too light because process control was not done at power-up	D284 002a	System/Copy firmware	Install version 1.02 or later	
Part of image missing	The top and bottom ends are missing if the size is scaled when PDF printing	D289 5595H	IRIPS PDF firmware	Install version 1.07 or later	
Part of image missing	Both ends of the watermark are cut off when printing from the V4 driver	D289 5595H	IRIPS PDF firmware	Install version 1.07 or later	
Centering	Pages printed as a booklet are centered incorrectly	D289 5595J	IRIPS PDF firmware	Install version 1.07 or later	
Scaling	With booklet printing or N-Up printing, the scaling ratio is wrong	D289 5595J	IRIPS PDF firmware	Install version 1.07 or later	
Scaling	The scaling is wrong when printing PDF data that contains FITTOPAGESIZE but not PRINTSCALING	D289 5595J	IRIPS PDF firmware	Install version 1.07 or later	
Rotation	The image is rotated 180 degrees when printing a Landscape document via the SmartSDK	D289 5595K	IRIPS PDF firmware	Install version 1.04 or later	

Technical Bulletin

PAGE: 29/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

10. Mechanical/Electrical

Subject	Symptom	RTB#	Cause	Solution	Note
LD unit	Breaks	D284	Engine firmware	Install version	
		001a		1.04:05 or later	
Noise	Metallic clank between	D284	Folder_THAMES-	Install version	
	FD3000 and	026	B_C_EXP/LP	01.030:11 or later	
	SR3210/3220		firmware		
Motor does not	If JAM 360 occurs, the	D3BB	Finisher SR3230	Install version	
stop	transfer motor does not	5300Q	firmware	01.100:07 or later	
	stop	D690	InnerFin_SR3130	Install version	
		5300M	firmware	01.100:02 or later	
		D3B8	Finisher	Install version	
		5300G	SR3210 firmware	01.060:05 or later	
		D3B9	Booklet Finisher	Install version	
		5300J	SR3220 firmware	01.070:04 or later	



Technical Bulletin

PAGE: 30/34

Updated: End of June 2018: Changes in bold italics

Model: Model Cor-C1.5 Date: 31-Jun-08 No.: RD284000d

11. Others

Subject	Symptom	RTB#	Cause	Solution	Note
System reset	System auto-reset not working	D259 022k	MediaPrtScn for eDC firmware	Install version 1.17 or later	
Settings not reflected	The "Change Print Settings" configuration is not	Gene 0870 Gene	Java VM v12 Update Tool Java VM v12 for	Install version 12.45.00 or newer.	
Settings not reflected	set correctly When scanning from Mac OS X 10.12 by using AirPrint, the resolution is always	088m D284 008a	eDC firmware Scanner firmware	Install version 01.01 or later	
Settings not reflected	200 dpi When printing from Quick Print Release, if the "16 in 1" and "Punch" settings are specified, the "Punch" setting is canceled	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
Settings not reflected	Adjusting the color balance in the driver doesn't work as expected	D289 5595F	IRIPS PDF firmware	Install version 1.05 or later	
Settings not reflected	SMB client timeout configuration is not correctly applied	D289 5564L	Network Support firmware	Install version 16.51.1 or later	
Cannot make settings	User settings cannot be accessed	D241 1427Y	Legacy UI firmware	Install version 1.21 or later	
Can make disallowed settings	When SP5-836-143 is enabled, the combination of "Black and White" and "High Compression PDF" can be selected even though it should not be selectable.	D289 5571L	Scanner firmware	Install version 01.09 or later	
Machine stalls	When printing many pages and using specific fonts	D289 5595E	IRIPS PDF firmware	Install version 1.04 or later	
Machine stalls	During use of an application on @Remote connected machines	D284 002a	System/Copy firmware	Install version 1.02 or later	
Machine stalls	When an application accesses the HDD after turning ON the power	D284 002a	System/Copy firmware	Install version 1.02 or later	

Technical Bulletin

PAGE: 31/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Machine stalls	If the Cover	D284	System/Copy	Install version 1.05 or later	
	Interposer runs out of	002e	firmware		
	paper during the job				
	and the tray is				
	reloaded with paper				
	incorrectly				
Machine stalls	When image log	D289	Network Doc Box	Install version 1.03 or later	
Machine Stans	capture is enabled	5565D	firmware	mistan version 1.00 or later	
	and a large number	33032	Illiliwaic		
	of jobs are				
	performed, the				
	1 •				
	capture cannot be				
	executed and the				
	device will freeze	D O D I A /	DD 5 ()		
Machine stalls	If a job includes text	D3DW	PDF firmware	Install version 1.02 or later	
	outside the printable	5733B			
	area of the page				
Machine stalls	During PDF direct	D3DW	PDF firmware	Install version 1.02 or later	
	printing if a spot color	5733B			
	is used				
Machine stalls	During PDF direct	D3DW	PDF firmware	Install version 1.02 or later	
	printing if a job	5733B			
	contains a Bezier				
	curve				
Machine stalls	During data	D289	Network Support	Install version 16.51.1 or	
	transmission when	5564L	firmware	later	
	doing Scan to Folder				
	with SMBv2/v3.				
Machine stalls	In Energy Saver	D284	Bug with the	Don't install ver 1.27. If the	
	mode, freezes during	043	operation panel	error occurs, disable the	
	the first backup after		backup feature	operation panel backup	
	the firmware is		after Cheetah	feature in the Cheetah SP	
	installed		System firmware	mode	
	motanou		ver 1.27 is	mede	
			installed		
Machine stalls	In a device with no	D289	Scanner firmware	Install version 01.07 or later	
Machine Stalls	ADF, if document	5571J	ocaline illiliware	mistali version onton or later	
	size is detected	337 13			
	automatically and the				
	TWAIN driver is used				
	for scanning, the				
Maakina	device will freeze	D244	Language Affelors	Install version 4.40 cm	
Machine	If the widgets	D241	LanguageWidget	Install version 1.10 or	
stalls	reboot during a	1431K	firmware	later	
	firmware update	D241	TonerWidget	Install version 1.06 or	
		1434H	firmware	later	
		D241	FaxInfoWidget	Install version 1.04 or	
		1435F	firmware	later	
		D241	EcoInfoWidget	Install version 1.07 or	
		1437G	firmware	later	
Firmware	Does not complete	D284	Engine firmware	Install version 1.04:05 or	
update	when updated via	001a		later	
	RFU				

Technical Bulletin

PAGE: 32/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Firmware	Error 22 during	D284	System/Copy	Install version 1.03 or later	
update	ARFU	002c	firmware		
Firmware	If RFU is done while	D289	System/Copy	Install version 1.10 or later	
update	SC672 is occurring,	5550N	firmware		
	RFU fails and the				
	machine cannot				
	recover until main				
	power is turned				
	OFF/ON				
Energy saver	Cannot recover	D284	System/Copy	Install version 1.02 or later	
mode		002a	firmware		
Energy saver	If scanning is	D289	Scanner firmware	Install version 01.06 or later	
mode	cancelled three times	5571H			
	within five minutes				
	when scanning with				
	the IC Card Scan &				
	Copy Application, the device cannot enter				
	Energy Saver Mode				
Counters	Documents printed	D284	RemoteFax	Install version 02.00.00 or	
Counters	from PCFAX are not	010a	firmware	later	
	counted up.	0100	IIIIIWaic	later	
Insects	Small insects get	D284		Install the new lower right	
	inside the machine	025		cover (D1491268).	
	from the open space			,	
	at the bottom right.				
Reboot	When attempted to	D284	System/Copy	Install version 1.05 or later	
	reboot the machine	002e	firmware		
	to resolve an SC, the				
	machine is not				
	rebooted.				
Machine is	When printing one or	D284	IRIPS PDF	Install version 1.02 or later	
slow	more PDF files that	021a	firmware		
	contain raster data	Dooo	1 104 40	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Machine is	Printing is slow if	D289	Java VM v12	Install version 12.56.00 or	
slow	CAP V2 is installed	5567H	Update Tool	newer.	
			Java VM v12 for		
Machine is	It takes time to	D289	eDC firmware Printer firmware	Install version 1.09 or later	
slow	It takes time to	5573L	riiilei iiiffiware	mstall version 1.09 of later	
SIUW	resume a job if it is suspended while the	3373L			
	device is in Energy				
	Saver mode				
Machine is	It takes time to output	D3DW	PDF firmware	Install version 1.02 or later	
slow	the first page using	5733B			
	PDF Direct Print				
	when the print data				
	contains a lot of				
	pages				
		,	ı		

Technical Bulletin

PAGE: 33/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Function not working	The default copy prevention text is not printed when printing with "Unauthorized Copy Prevention" enabled	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
Function not working	Toner saving does not work when printing from SDK applications	D284 021a	IRIPS PDF firmware	Install version 1.02 or later	
Machine not responding to a command	Machine does not respond to job cancel request via remote just before a copy job ends	D289 5550J	System/Copy firmware	Install version 1.06 or later	
Copying does not start	When the device has just gone into energy saver mode, if a copy job is sent from a SmartSDK application	D289 5550K	System/Copy firmware	Install version 1.07 or later	
Reports	Wrong finisher name printed on the Configuration sheet	D289 5573H	Printer firmware	Install version 1.06 or later	
Logs	If the device is abnormally turned off, the collect logs settings might be initialized and the log data might not be transferred after that.	D289 5565E	Network Doc Box firmware	Install version 1.04 or later	
Capture	Does not work if capture processing and either thumbnail or preview processing occur at the same time	D289 5550N	System/Copy firmware	Install version 1.10 or later	
Capture	When image log capture is enabled and a large number of jobs are performed, the capture cannot be executed and the device will freeze	D289 5565D	Network Doc Box firmware	Install version 1.03 or later	
Capture	Unnecessary retransmissions occur during image log capture	D289 5565D	Network Doc Box firmware	Install version 1.03 or later	

Technical **B**ulletin

PAGE: 34/34

Updated: End of June 2018: Changes in bold italics

Subject	Symptom	RTB#	Cause	Solution	Note
Capture	When scanning repeatedly from a SmartSDK application that enables image log capture, the captured image file is not deleted and remains on the hard disk	D289 5571G	Scanner firmware	Install version 01.05 or later	
Capture	The image logs of jobs scanned by GlobalScan NX are not captured	D289 5571G	Scanner firmware	Install version 01.05 or later	
Machine reboots	After cancelling scanning	D289 5550P	System/Copy firmware	Install version 1.11 or later	
Machine reboots	When doing Scan to Folder	D289 5564L	Network Support firmware	Install version 16.51.1 or later	
User cannot operate the machine	When using the DHCP Option204 function; "Setting change" is displayed	D289 5564K	Network Support firmware	Install version 16.50 or later	