RIGOH

Modification Bulletin

PAGE: 1/4 Reissued: 27-Jul-04

Model: Stella-C2	Date: 29-Jun-04	No.: MB129001a
------------------	-----------------	----------------

MB Correction


The items in bold italics have been corrected or added.

Modified Article: Parts Catalog Correction			Prepared by: M. Ishihara		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Other			

Please correct your Parts Catalogs as follows:

Page 6

- Illustration Correction -



Page 7 - Description Correction -


Part number	Incorrect description	Correct description	Q'ty	Index	Note
B1297508	Model Name Plate (B129 RIC	Model Name Plate – GES	1	32	
	TWN)	DSM415			
B1307508	Model Name Plate (B130 RIC	Model Name Plate - GES	1	32	
	TWN)	DSM415PF			
B1687508	Model Name Plate (B168 GES)	Model Name Plate - GES	1	32	
		DSM415F			
B1687514	Model Name Plate (B168 GES)	Model Name Plate - REX	1	32	
	,	DSM415F			



PAGE: 2/4


Model: Stella-C2 Date: 29-Jun-04 No.: MB129001a

Page 18 - Illustration Correction -



Page 28

- Illustration Correction -



RIGOH

Modification Bulletin

PAGE: 3/4

Reissued: 27-Jul-04

Model: Stella-C2 Date: 29-Jun-04 No.: MB129001a


Page 29

- Addition -

Part number	Description	Q'ty	Index	Note
04533006N	Tapping Screw – M3x6		109	

Page 38

- Illustration Correction -



- Addition -

Part number	Description	Q'ty	Index	Note
09543008B	Philips Screw – M3x8		108	




PAGE: 4/4

Model: Stella-C2 Date: 29-Jun-04 No.: MB129001a


Page 40

- Illustration Correction -



Page 44

- Illustration Correction -



- Addition -

Part number	Description	Q'ty	Index	Note
14075856	RAM – FM18L08-70-P	1	102	

	M	П
الالال	ועש	لال


РΔ	GE:	1	/1
Γ	GE.		/

Model: Stella-C2 Date						No.: MB129002
Modified Article: Parts Catalog Correction Prep					by: M.	Ishihara
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Othe	r			

Please correct your Parts Catalogs as follows:

Page 38, 39 - Addition -

I	Part number	Description	Q'ty	Index	Note
	B1295170	PCB DFB	1	29	



Model: Stella-C2

Modified Article: Parts Catalog Correction
From: 1st Tech. Support Sec. Service Support Dept.

Reason for Modification:

Parts catalog correction Vendor change To meet standards


Other

Please correct your Parts Catalogs as follows:

Page 38, 39

Please correct the parts catalog as follows.

Part number	Description	Q'ty	Int	Index	Note
B1295223	Harness – Paper Feed Table	1		17	
11028534	Connector – OR/P17 – 14S - B	1		109	



RIGOH

Model: Stella-C2

Reason for

Modification:

Modification Bulletin

☐ Other

	Date	e: 14-Sep-0	4	No.: MB1290	004
t.		Prepared	by: M.	Ishihara	
☐ Vendor change ☐ To improve reliability		☐ To n	neet standards)	;	

PAGE: 1/1

Please correct your Parts Catalogs as follows:

From: 1st Tech. Support Sec. Service Support Dept.

Modified Article: Parts Catalog Correction

Page 49

- Addition -

Incorrect: IC, SYMBOL NO. IC23, INDEX NO. 131 Correct: IC, SYMBOL NO. IC23, INDEX NO. 131,319

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Page 55, 57

Part	Description	Symbol No.	Q'ty	Index	Note
number					
14075299	RAM-FM1608-120-P	IC23	1	131	
11040588	DIP Socket-28P	IC23	1	131→319	



PAGE: 1/1

Reissued: 28-Dec-04

Model: Model S-C2	Date: 17-Dec-04	No.: MB129005a

MB Correction

The items in bold italics have been corrected or added.


Modified Article: ADF Base				Prepared by: A. Ishiyama		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for Modification:	☑ Parts catalog correction☐ To facilitate assembly☐ Part standardization	☐ Vendor change of the change	-	☐ To meet standards ()		
Modification Schedule:						

Note: This bulletin is for the following models only. *Model S-F1/F1.5, S-C1, S-C2 (H555, B049, B129, B130, B168, B444, B696)*

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	B0444891	Base	0→1	-/-	25	30	

Change: This part was added.

Reason: It was missing from the Parts Catalog.



RIGOH

Modification Bulletin

PAGE: 1/1

Model: Stella-C2 (B	130:MFP and B168:CF models	e: 2-Feb-05		No.: MB129006			
Modified Article: P	Prepared	by: M.	Ishihara				
From: 1 st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification: ☐ To facilitate assembly ☐ To imp		nprove	e reliability	()		
	☐ Part standardization ☐ Other						

<Modification 1>

Part number changes for the PCB GWFCU3 were made to increase the latitude of the EMI standard and the communication function.

You can interchange the old and the new parts and use them in the field.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B6205172	B1685172	PCB GWFCU3 NA Ass'y	1	0/0	45	11	
B6205174	B1685174	PCB GWFCU3 EU Ass'y	1	0/0	45	11	

<Modification 2>

Symptom

Blurred image shows at the time of fax transmission.

Fax unit is not recognized or does not function correctly.

SC820

Modification

- 1 x Resistor has been removed
- 1 x Jumper has been added

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B1685172	B1685182	PCB GWFCU3 NA Ass'y	1	X/O	45	11	
B1685174	B1685184	PCB GWFCU3 EU Ass'y	1	X/O	45	11	

Cut in Serial Number

This modification was applied to mass production from July 1st.

The cut in serial number information is as follows.

B130-17: K2149102073 (*) B130-22: K2149100073 B130-24: K2149100001 B130-26: 5A98740001 B130-27: K2149100697 B130-29: K2149101826 B168-17: K2249101164

B168-22: K2249100001

B168-24: No Production in July 2004 (From next production: K2249200001)

B168-26: 5A78740001 B168-27: K2249100225 B168-29: K2249100908

(*) The following machines contain the modified FCU.

B130-17: K2149002790 - 2958 (169 units)

	ΙПЛ
(G(O))[[]

PA	G	E:	1	11

Model: Stella-C2 Date			e: 22-Apr-0	5	No.: MB129007		
Modified Article: PCB CTL EXP					by: M.	Ishihara	
From: 1 st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vend ☐ To im ☐ Othe	nprove	ange e reliability	☐ To n	neet standards)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6835700	B6835701	PCB CTL EXP	1-1	X/O	45	2	

Change: A jumper wire was added and a resistor (R524) was removed from the controller

board.

Reason: To improve the power distribution to the Piccolo ASIC.

Note: This change was applied to the machine production line from October 2004.

RIGOH

Modification **B**ulletin


PΑ	GE:	1/1
	\sim – .	

Model: Stella-C2 Date			ate: 21-Jul-0	5	No.: MB129008
Modified Article	Parts Catalog Correction	Prepared	d by: M.	Ishihara	
From: 1 st Tech. S	upport Sec. Service Support Dep				
Reason for	□ Parts catalog correction	☐ Vendor	change	☐ To r	neet standards
Modification:	☐ To facilitate assembly ☐ To improve		ove reliability	()
	☐ Part standardization	☐ Other			

Please correct your Parts Catalogs as follows:

Page 12

- Illustration (Index number) -



Page 13 - Addition -

Part number	Description	Q'ty	Index	Note
12042529	Switch-V-5F912DN		105	

Modification Bulletin

PAGE: 1/1

Model: Stella-C2 Da			ate: 4-Apr-06		No.: MB129009	
Modified Article: Fusing unit				Prepared by: M. Ishihara		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly ☐ To improve		e reliability	☐ To me	et standards	
	☐ Part standardization	☐ Product	t Sa	afety	()

Old P/N	New P/N	Description	Q'ty	Int	Page Index	Note
AE031034	AE031044	Fusing Bushing	1-1	X/O	P.35, Index 39	See below.
B1294111	-	Hot Roller Spacer	1-0		P.35, Index 59	See below

Change:

- 1. The shape of the fusing bushing was changed.
- 2. The hot roller spacer was deleted.

Reason:

- 1. To increase the durability of the fusing bushing.
- 2. To ensure noise does not occur in the fusing bushing area.

IMPORTANT: Replace [AE031034 + B1294111] together as a set with AE031044

Note: These changes were applied from January 2005 machine production.

Modification Bulletin

PAGE: 1/1

Model: S-C2			Date: 7-Aug-06		No.: MB129010	
Modified Article:	Paper Tray:Ass'y			Prepared	by: Y.Muı	rata
From: 1st Tech. Su	pport Sec. Service Support D	ept.				
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	☐ Other	
Modification:	lodification: To facilitate assembly To improve		re reliability 🛛 To meet standards			
	☐ Part standardization	☐ Product	Sa	afety	(RoHs	compliant)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0442503	B0442509	Paper Tray:Ass'y	1	0/0	17	*	

	V	

PAGE: 1/1

Reissued:21-Aug-06

Model: S-C2	Date: 7-Aug-06	No.: MB129011a

MB Reissue

The items in bold italics have been corrected or added.

Modified Article: Density Sensor:Longdist:Adhesion			Prepared by: Y.Murata		
From: 1st Tech. Su	ipport Sec. Service Support D	ept.			
Reason for	☐ Parts catalog correction	U Vendor cha	ange	☐ Other	
Modification:	☐ To facilitate assembly	☐ To improve	e reliability	□ To meet standards	
	☐ Part standardization	☐ Product Sa	afety	(RoHs compliant)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0443892	B0443894	Density Sensor:Longdist:Adhesion	1	0/0	15	15	



PAGE: 1/1

Reissued:21-Aug-06

Model: S-C2	Date: 7-Aug-06	No.: MB129012a
	J	

MB Reissue

The items in bold italics have been corrected or added.

Modified Article: Feeder Unit:ADF:Ass'y			Prepared by: Y.Murata		
From: 1st Tech. Su	pport Sec. Service Support D	ept.			
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange	☐ Other	
Modification:	☐ To facilitate assembly	☐ To improve	e reliability		
	☐ Part standardization	☐ Product Sa	afety	(RoHs compliant)	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0444811	B0444832	Feeder Unit:ADF:Ass'y	1	0/0	23	42	

Modification Bulletin

PAGE: 1/1

Model: S-C2	Model: S-C2			ate: 7-Aug-	06	No.: MB129013			
Modified Article:	Modified Article: Laser Unit Ass'y				Prepared by: Y.Murata				
From: 1st Tech. Support Sec. Service Support Dept.									
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	☐ Other				
Modification:	☐ To facilitate assembly ☐ To impro		ove	e reliability		et standards			
		☐ Product Safety		(RoHs	compliant)				

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1291901	B1291902	Laser Unit Ass'y	1	O/O	31	*	

Modification Bulletin

PAGE: 1/1

Model: S-C2			Da	ate: 7-Aug-	06	No.: MB129014
Modified Article:	Toner Supply Unit Ass'y			Prepared	by: Y.Mui	rata
Reason for Modification:	☐ To facilitate assembly	☐ Vendor ☐ To impr ☐ Product	OVE	e reliability	=	et standards compliant)

I	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B1293020	B1293021	Toner Supply Unit Ass'y	1	0/0	33	22	

Modification Bulletin

PAGE: 1/1

Model: S-C2					06	No.: MB129015	
Modified Article:	Modified Article: Guide Plate:Revers:Duplex:Ass'y					rata	
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	☐ Other		
Modification:	☐ To facilitate assembly	☐ To impr	ove	e reliability		et standards	
	☐ Part standardization	☐ Product		afety	(RoHs	compliant)	

	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
ı	H5564154	H5564158	Guide Plate:Revers:Duplex:Ass'y	1	0/0	15	26	

	.C	

PAGE: 1/1

Model: S-C2			Da	ate: 15-Jun	-07	No.: MB129016			
Modified Article:	Modified Article: PCB BICU EXP Ass'y				Prepared by: M. Ishihara				
From: 1st Tech. Support Sec. Service Support Dept.				I					
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other				
Modification:	Modification: ☐ To facilitate assembly ☐		ove	e reliability		et standards			
	☐ Part standardization	☐ Product	Sa	afety	(RoHs	compliant)			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B1295101	B1295121	PCB BICU EXP Ass'y	1-1	0/0	55	*	
B2305101	B1305121	PCB BICU MFP EXP Ass'y	1-1	0/0	67	*	

Modification Bulletin

Model: S-C2			Da	ate: 15-Jur	n-07	No.: MB129017			
Modified Article:	Modified Article: PCB CTL EXP				Prepared by: M. Ishihara				
From: 1st Tech. Support Sec. Service Support Dept.									
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other				
Modification:	☐ To facilitate assembly	☐ To impr	ove	e reliability	_	et standards			
	☐ Part standardization	☐ Product Safety		afety	(RoHs	compliant)			

PAGE: 1/1

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6835701	B6835702	PCB CTL EXP y	1-1	0/0	45	*	

Change: The PCB itself remains unchanged. The caution "Do not use any component

parts not to meet the RoHS Directive" was added to the drawing. **Reason:** To comply with the RoHS Directive.

	U	

Model: S-C2		ate: 19-Jun	ı-07	No.: MB129018		
Modified Article:	Parts Catalog correction (SD	Prepared	by: M. Ish	nihara		
From: 1st Tech. Su	pport Sec. Service Support D					
Reason for	□ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly	ove	e reliability	☐ To me	et standards	
	☐ Part standardization	☐ Product	Sa	afety	()	

PAGE: 1/1

Please correct the part number in your parts catalog.

Incorrect	Correct part	Description	Q'ty	Int	Page	Index	Note
part number	number						
B6835670	B6835770	SD-Card EXP Ass'y			45	1	

Modification **B**ulletin

Model: S-C2		ate: 21-Ded	c-07	No.: MB129019					
Modified Article:	Power Supply Unit	Prepared by: M. Ishihara							
From: 1st Tech. Su	pport Sec. Service Support D								
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other				
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability		et standards			
	☐ Part standardization	☐ Product	☐ Product Safety		(RoHs	compliant)			

PAGE: 1/1

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AZ230135	AZ230203	Power Supply Unit 200V	1-1	O/O	39	20	
AZ230134	AZ230202	Power Supply Unit 100V	1-1	O/O	39	20	
AZ320131	AZ320161	Power Pack BCT	1-1	O/O	39	2	

Change: The materials of these parts were changed to lead-free types.

Reason: To comply with the RoHS Directive.

Modification Bulletin

Model: S-C2		ate: 29-Oct	:-08	No.: MB129020		
Modified Article:	Spring Plate-Pickoff Pawl Ro	Prepared	by: M. Ish	nihara		
From: 1st Tech. Su	pport Sec. Service Support [
Reason for	☐ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly	OVE	e reliability	☐ To me	et standards	
	☐ Part standardization	☐ Product	t Sa	afety	()	

PAGE: 1/1

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B1294139	-	Spring Plate – Pickoff Pawl Roller	3-0	•	35	48	
B0394170	-	Stripper Pawls Roller	3-0	-	35	49	

Change: The above two parts have become obsolete (not used any more and no

replacement parts for those parts.).

Reason: To avoid the noise from those parts.



Date: March 18	. 2009
----------------	--------

		PCIL	PCIL	Old	New												
Model	Code	Number	Correction	part number	part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int F	RTB	Note	Ref Number
Stella-C2	B129	200903		B0441279	B0441278	RIGHT UPPER COVER	1	1	0/0		7	17					V0803587
Stella-C2	B130	200903		B0441279	B0441278	RIGHT UPPER COVER	1	1	0/0		7	17					V0803587
Stella-C2	B168	200903		B0441279	B0441278	RIGHT UPPER COVER	1	1	0/0		7	17					V0803587



Date: April 30, 200	Date:	oril 30, 2	2009
---------------------	-------	------------	------

		PCIL	PCIL	Old	New												
Model	Code	Number	Correction	part number	part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Stella-C2	B129	200904		B0441394	B0441393	PLATEN COVER	1	1	0/0		7	4					V0804689
Stella-C2	B130	200904		B0441394	B0441393	PLATEN COVER	1	1	O/O		7	4					V0804689
Stella-C2	B168	200904		B0441394	B0441393	PLATEN COVER	1	1	O/O		7	4					V0804689
Stella-C2	B129	200904		B0442710	D0672710	FRICTION PAD:ADHESION	1	1	O/O		17	13					V0900680
Stella-C2	B130	200904		B0442710	D0672710	FRICTION PAD:ADHESION	1	1	O/O		17	13					V0900680
Stella-C2	B168	200904		B0442710	D0672710	FRICTION PAD:ADHESION	1	1	0/0		17	13					V0900680
Stella-C2	B169	200904		B0442710	D0672710	FRICTION PAD:ADHESION	1	1	O/O		17	13					V0900680
Stella-C2	B129	200904		AX060284	AX060342	POLYGON SCANNER MOTOR-DC24V	1	1	O/O		31	5					
Stella-C2	B130	200904		AX060284	AX060342	POLYGON SCANNER MOTOR-DC24V	1	1	0/0		31	5					
Stella-C2	B168	200904		AX060284	AX060342	POLYGON SCANNER MOTOR-DC24V	1	1	0/0		31	5					
Stella-C2	B169	200904		AX060284	AX060342	POLYGON SCANNER MOTOR-DC24V	1	1	O/O		31	5					



 Model
 Code PCIL Nr. Correction number number
 Description
 Old Q'ty New Q'ty Int 3DPC Page Index Set Set Int RTB
 Note
 Ref. Nr.
 ECN Nr.

 IS-C2
 B129 | 200906 | B0443425 | B0443427 | Slide Shaft
 1 1 0/O 33 25 | B0443427 | B044342

Date: June 30, 2009

Part Change Information List

Date: October 30, 2009

	Model	Codo	DOIL Nr	PCIL	Old part	New part	Description	Old O'ty	Now O'ty	Int 3DPC) Dogo	Indov S	t 60t	Int	RTB	Note	Ref. Nr.	ECN Nr.
	Model	Code	FUIL INI.	Correction	number	number		Old Q ty	New Q ty	ווונ טטרכ	raye	illuex 3	el Sei	IIIL	NIB	Note	nei. Ni.	ECIVINI.
S-C2	В	129	200910		B1295216	D0675216	HARNESS:MOTOR:MAIN	1	1	0/0	39	9					V0900588	
S-C2	В	130	200910		B1295216	D0675216	HARNESS:MOTOR:MAIN	1	1	0/0	39	9					V0900588	
S-C2	В	168	200910		B1295216	D0675216	HARNESS:MOTOR:MAIN	1	1	0/0	39	9					V0900588	
S-C2	B	169	200910		B1295216	D0675216	HARNESS:MOTOR:MAIN	1	1	0/0	39	9					V0900588	



Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part	New part	Description	Old Q'ty	New Q'ty	Int 3DF	PC Page	Index Se	t Set Int	RTB	Note	Ref. Nr.	ECN Nr.
			Correction	number	number											
S-C2	B129	201004		B1685182	B1685173	PCB GWFCU3 NA Ass'y	1	1	0/0	45	11				T0600546	5070436
S-C2	B129	201004		B1685184	B1685175	PCB GWFCU3 EU/Asia Ass'y	1	1	0/0	45	11				T0600546	5070436



Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL	Old part number	New part number	Description	Old Q'ty	New Q'ty Int	3DPC	Page II	ndex Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
S-C2	B129	201005		B0444165		DISCHARGE BRUSH:EXIT	1	1 0/0		35	1				V1000294	
S-C2	B130	201005		B0444165	D0674165	DISCHARGE BRUSH:EXIT	1	1 0/0		35	1				V1000294	
S-C2	B168	201005		B0444165	D0674165	DISCHARGE BRUSH:EXIT	1	1 0/0		35	1				V1000294	
S-C2	B169	201005		B0444165	D0674165	DISCHARGE BRUSH:EXIT	1	1 0/0		35	1				V1000294	



Date: Jul 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
S-C2	B129	201007		B0444935	B1294935	Guide Plate - Exposure Glass	1	1		21	28	Α	X/O	RB129024		T0401967	4080488
S-C2	B129	201007			B1294913	Cap - Guide Plate	0	1		21	35	Α	X/O	RB129024		T0401967	4080488



Date: December 29, 2010

Model	Code PCIL Nr.	PCIL Old part	New part	Description	Old Q'ty Ne	w O'tv Int	3DBC	Page Index Set Set Int	RTR	Note	Ref. Nr.	ECN Nr.
Model	C	Correction number	number		Old Q ty 146	w Cety IIII	JDI O	rage maex det det mit	IIID	Note	Hen. IVI.	
S-C2	B129 201012	AZ500073	AZ500077 STA	LIZER:XENON LAMP:CHN	1	1 0/0		27 3			V1001925	10070525
S-C2	B130 201012	AZ500073	AZ500077 STA	LIZER:XENON LAMP:CHN	1	1 0/0		27 3			V1001925	10070525
S-C2	B168 201012	AZ500073	AZ500077 STA	LIZER:XENON LAMP:CHN	1	1 0/0		27 3			V1001925	10070525
S-C2	B169 201012	AZ500073	AZ500077 STA	LIZER:XENON LAMP:CHN	1	1 0/0		27 3			V1001925	10070525



Date: January 31, 2011

Model	Code PCIL Nr. PCIL	Old part New part	Description	Old Q'tv New Q'tv Int 3DP	C Page Index Set Set Int	RTB Note Ref. Nr. ECN N	Mr
	Correction	ı number number		old atly Hell atly lift obt	o rage mack out out mit		
S-C2 ADF (DF80)	B696 201101	H5211350 H3101360 PAD:PICKUP	·	1 1 0/0	23 11	V1002156	1



Date: January 31, 2011

Model	Code PCIL Nr. Correction	Old part New part number	Description	Old Q'ty	New Q'ty Int 3	3DPC Page	e Index Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
S-C2	B129 201101		PAD:PICKUP	1	1 0/0	2	23 11				V1002156	
S-C2	B130 201101	H5211350 H3101360	PAD:PICKUP	1	1 0/0	2	23 11				V1002156	
S-C2	B168 201101	H5211350 H3101360	PAD:PICKUP	1	1 0/0	2	23 11				V1002156	



Date: February 28, 2011

Model	Codo	PCIL Nr.	PCIL	Old part	New part	Description	Old O'ty	New Q'ty	Int	3DPC	Page	Index	Sat	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Model	Code	I OIL INI.	Correction	number	number	Description	Old Q ty	New Qty	1111	JDI O	i age	IIIuex	361	Jet IIIt	IIID	Note	Hel. IVI.	LON IVI.
S-C2	B130	201102		B6456830		SD-CARD:USB:WRITER:BN-SDCGTY	1	(X/O		85	11			RGene043		V1100185	11010728
S-C2	B168	201102		B6456830		SD-CARD:USB:WRITER:BN-SDCGTY	1	(X/O		85	11			RGene043		V1100185	11010728
S-C2	B169	201102		B6456830		SD-CARD:USB:WRITER:BN-SDCGTY	1	(X/O		85	11			RGene043		V1100185	11010728

Part Change Information List

Date: March 31, 2011

Model	Code	PCIL Nr.	PCIL Correcti on	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
S-C2	B130	201103		B6456705	B6456830	SD-CARD:USB:WRITER:BN-SDCGTY	2	2	0/0		85	10			RB129025		V0901192	
S-C2	B168	201103		B6456705	B6456830	SD-CARD:USB:WRITER:BN-SDCGTY	2	2	0/0		85	10			RB129025	•	V0901192	
S-C2	B169	201103		B6456705	B6456830	SD-CARD:USB:WRITER:BN-SDCGTY	2	2	0/0		85	10			RB129025		V0901192	

Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Set Int	RTB	Note	Ref. Nr.	ECN Nr.
S-C2	B130	201110				CERAMIC CHIP CAPACITOR:560PF:+-5%:630V	2	2	0/0		79	16	D			V1101296	08010189
S-C2	B168	201110		16051397	16051762	CERAMIC CHIP CAPACITOR:560PF:+-5%:630V	2	2	0/0		79	16	0			V1101296	08010189

Part Change Information List

Date: January 31, 2012

	Model Cod	de F	PCIL Nr.	PCIL	Old part	New part	Description	Old O'ty	New Q'ty	Int	3DPC	Page	Index Set	Set Int	RTR	Note	Ref. Nr.	ECN Nr.
			0.2	Correction	number	number		0.0 0.1			05. 0	. ago	middx ddt	001	5			2011111
S-	-C2 B130	30	201201		11027604	11035377	CONNECTOR:MJ-62J-RD315	2	2	0/0		73	103				V1102576	11091329
S.	-C2 B168	88	201201		11027604	11035377	CONNECTOR:MJ-62J-RD315	2	2	0/0		73	103				V1102576	11091329



Date: March 30, 2012

	Model C	`odo	DOIL NE	PCIL	Old part	New part	Description	Old Otty	Now O'ty	Int	3DBC	Page	Indov	Sat	Sot Int	RTB	Noto	Ref. Nr.	ECN Nr
						number		Old Q ty	New City	1111	3DI C	raye	IIIuex	361	Jet IIIt	MID	Note		LON INI.
S-C	C2 B1	129	201203		B1295210	D0675210	HARNESS:DOOR SWITCH		1	0/0		39	11					V1103385	
S-0	C2 B1	130	201203		B1295210	D0675210	HARNESS:DOOR SWITCH	1	1	O/O		39	11					V1103385	
S-0	C2 B1	168	201203		B1295210	D0675210	HARNESS:DOOR SWITCH	1	1	O/O		39	11					V1103385	
S-0	C2 B1	169	201203		B1295210	D0675210	HARNESS:DOOR SWITCH	1	1	O/O		39	11					V1103385	

Part Change Information List

Date:	November	29, 2013
-------	----------	----------

			PCIL	PCIL	Old part	New part		Old	New						Set				ECN
	Model C	Code	Number	Correction	number	number	Description	Q'ty	Q'ty	Int	3DPC	Page	Index	Set	Int	RTB	Note	Ref Number	Number
S-C2	B1	129	201311		B2623802	D1273802	TRANSFER ROLLER:ASS'Y	1	1	O/O		15	8	3				V1302126	
S-C2	B1	130	201311		B2623802	D1273802	TRANSFER ROLLER:ASS'Y	1	1	O/O		15	8	3				V1302126	
S-C2	B1	168	201311		B2623802	D1273802	TRANSFER ROLLER:ASS'Y	1	1	O/O		15	8	3				V1302126	
S-C2	B1	169	201311		B2623802	D1273802	TRANSFER ROLLER:ASS'Y	1	1	O/O		15	8	3				V1302126	

Part Change Information List

Date: February 28, 2014

		PCIL	PCIL	Old part	New part		Old	New						Set				ECN
Model	Code	Number	Correction	number	number	Description	Q'ty	Q'ty	Int	3DPC	Page	Index	Set	Int	RTB	Note	Ref Number	Number
S-C2	B130	201402		G0219350		LOOPBACK CONNECTOR - PARALLEL	1	0	O/O		85	6	ô				V1303633	



Date: July 31, 2014

		PCIL	PCIL	Old part	New part		Old	New					Set			ECN
Mo	odel Code	e Numb	er Correction	n number	number	Description	Q'ty	Q'ty	Int	3DPC	Page Ir	ndex S	et Int	RTB	Note	Ref Number Number
S-C2	B129	20140	7	B0444925	B0444924 REAR UPPER COVER		1	1	O/O		21	11				V0804689
S-C2	B130	20140	7	B0444925	B0444924 REAR UPPER COVER		1	1	O/O		21	11				V0804689
S-C2	B168	20140	7	B0444925	B0444924 REAR UPPER COVER		1	1	O/O		21	11				V0804689



Date: August 3, 2015

Model C	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
S-C2 B1	129	201507		14075299	14077818	RAM:FM1608B-PG(REV.AA)	1	1	O/O	N	55	131					V1400643	



Dat	te: April	28,	2016	

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
S-C2	B129	201604		B0444921	B0444920	FRONT UPPER COVER	1	1	O/O	N	21	30					V0804689	
S-C2	B130	201604		B0444921	B0444920	FRONT UPPER COVER	1	1	0/0	N	21	30					V0804689	
S-C2	B168	201604		B0444921	B0444920	FRONT UPPER COVER	1	1	0/0	N	21	30					V0804689	