

Model: Russian-C3		Date: 22-Jan-04	No.: MB089001
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B089 7062		PANEL: EMBLEM: SVN: 4022	1		9	4	*1
B089 7065		PANEL: EMBLEM: GES: 622	1		9	4	*1
B089 7066		PANEL: EMBLEM: NSA: 622	1		9	4	*1
B089 7067		PANEL: EMBLEM: REX: 622	1		9	4	*1
B093 7062		PANEL: EMBLEM: SVN: 4027	1		9	4	*1
B093 7065		PANEL: EMBLEM: GES: 627	1		9	4	*1
B093 7066		PANEL: EMBLEM: NSA: 627	1		9	4	*1
B093 7067		PANEL: EMBLEM: REX: 627	1		9	4	*1
B097 7064		PANEL: EMBLEM: LAN: LD132	1		9	4	*1
B097 7065		PANEL: EMBLEM: GES: 632	1		9	4	*1
B097 7066		PANEL: EMBLEM: NSA: 632	1		9	4	*1
B097 7067		PANEL: EMBLEM: REX: 632	1		9	4	*1
B093 5360		EEPROM: CTL: C3: CONFIG	1		71	2	*2
A267 1080	B027 1080	Scanner Stay – Lower Right	1		57	21	*3
A028 9300	A257 9300	Grease Barrierta JFE 55/2	1		83	8	*3
A029 9387	VSSM 9000	Digital Multimeter – FLUKE87	1		83	7	*3

*1: Emblems for the generic model are affixed locally, and have therefore been deleted from service parts.

*2: This EEPROM was deleted from the service parts, because this part should be replaced together with the controller PCB (not individually).

*3: P/N corrections (the incorrect P/N was listed in the Parts Catalog).

Reissued: 22-Mar-04

Model: Russian-C3	Date: 4-Feb-04	No.: MB089002a
-------------------	----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☐ Other	

Please apply the following changes to your Parts Catalogs.

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
	B089 7068	EMBLEM - IS2122	1		9	4	*1
	B093 7068	EMBLEM - IS2127	1		9	4	*1
	B097 7068	EMBLEM - IS2132	1		9	4	*1
B027 5041	B093 5041	LCDC BOARD (NA)	1		13	27	*2
B027 5042	B093 5042	LCDC BOARD (EU)	1		13	27	*2
B027 5041	B093 5043	LCDC BOARD (ASIA/TWN)	1		13	27	*2
B027 1802	B093 1801	SCANNER BASE	1		19	16	*2
AX06 0198	B093 0198	POLYGON MIRROR MOTOR – 230V	1		23	26	*3
B027 5816	B093 5816	GRIP	1		55	3	*2
B027 1080	B093 1080	SCANNER STAY – LOWER RIGHT	1		57	21	*2

*1: These emblems were previously missing from service parts.

*2: P/N corrections (incorrect P/N were listed in Parts Catalog).

*3: P/N B0930198 is only used on the 230V model. Also, P/N AX060181 (100V model) remains unchanged, as the above P/N change only applies to the 230V model.

Model: Russian-C3		Date: 16-Mar-04	No.: MB089003
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

The following have been added with the release of the China model.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B093 5044	LCDC (CHN)	1		13	27	
	B097 6506	Operation Instructions-System (CHN)	1		81	14	
	B097 6636	Operation Instructions-Copy (LAN CHN)	1		81	13	
	B097 6536	Operation Instructions-System (LAN CHN)	1		81	14	

Model: Russian-C3		Date: 23-Mar-04	No.: MB089004
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following P/N correction to your Parts Catalogs.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B004 5216	B101 5257	LCD HVGA SH BL	1		13	5	
B027 5815	B031 5815	SHADEING PLATE	1		55	1	

Model: Russian-C3		Date: 25-Mar-04	No.: MB089005
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following part number correction to your Parts Catalogs.

Note: SC144 will occur if the **B0271673** assembly is installed on this model, as this part is made for a different model.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B027 1673	B031 1673	LENS HOLDER	1	X/O	19	8	*

Model: Russian-C3		Date: 26-Apr-04	No.: MB089006
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply the following changes to your Parts Catalogs.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B089 1900	Laser Unit Assembly (220VAC model)	1		23	1	
	B097 1900	Laser Unit Assembly (B097)	1		23	1	
AX20 0165	B091 1186	Magnetic Clutch	1		47	9	
	B097 1186	Magnetic Clutch (B097)	1		47	9	

Note:

- Due to a difference in the polygon mirror motor among RC3 versions, the two Laser Unit Assemblies above have been newly added for 1) the 220V RC3 version and 2) the B097 version, which has a different cpm. Including the assembly already listed in the P/C (B027 1900), this makes a total of three Laser Unit Assemblies.
- Also due to the difference in cpm with the B097, the magnetic clutches have been registered as two separate parts.

Reissued: 2-Aug-04

Model: Russian-C3	Date: 7-Jul-04	No.: MB089007a
-------------------	----------------	----------------

MB Correction

The items in bold italics have been changed. (Page and Index are corrected)

Modified Article: Exposure Glass Cushion		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☒ To improve reliability	
	☐ Part standardization	☐ Other	

The material of the cushion has been changed to further ensure proper positioning of the exposure glass.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
5442 1924	B093 1862	CUSHION GLASS	1-1	X/O	17	1	

Model: Russian-C3	Date: 7-Jul-04	No.: MB089007
-------------------	----------------	---------------

[Sindo Ricoh (Korea) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Savin 4022 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	USA, Canada	B089-17	J8332000001
Gestetner DSm622 RICOH Aficio 2022	Taiwan	B089-19	J8341300001
Infotec IS2122	Europe, etc	B089-26	4R10930001
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B089-27	J8332103401
Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Asia	B089-29	J8332103901
Savin 4027 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	USA, Canada	B093-17	J8432000001
Gestetner DSm627 RICOH Aficio 2027	Taiwan	B093-19	J8441303353
Infotec IS2127	Europe, etc	B093-26	4R20930001
Nashutec DSm627 RexRotary DSm627 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Europe, etc	B093-27	J8432101321
Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Asia	B093-29	J8432101521
Infotec IS2132	Europe, etc	B097-26	4R30930001
Nashutec DSm632 RexRotary DSm632 Gestetner DSm632 LANIER LD132 RICOH Aficio 2032	Europe, etc	B097-27	J8532100001

Model: Russian-C3		Date: 18-Aug-04	No.: MB089008
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please apply these changes to your Parts Catalogs.

Old Part Number	New Part Number	Description	Q'ty	Int	Page	Index	Note
B027 5226	B093 5226	Harness – Scanner (NA)	1		19	1	*
B027 5230	B093 5230	Harness – Scanner (EU/ASIA)	1		19	1	*

* This correction is due to connector type differences of CN441.

Reissued: 5-Nov-04

Model: Russian-C3	Date: 25-Oct-04	No.: MB089009a
-------------------	-----------------	----------------



Serial Number Update

The Serial Number information has been updated.

Modified Article: Decals		Prepared by: S. Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☒ Other	

These decals were added to ensure correct user operation of paper size setting and removing paper jams:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0904460	Decal – Jam Removal – Right Cover	0–1		25	28	Fig 1
					81	16	Fig 4
	B0904461	Decal – B	0–1		25	29	Fig 1
					81	15	Fig 4
	B0904462	Decal – C	0–1		43	24	Fig 2
					81	17	Fig 4
	B0902961	Decal – Paper Size Select	0–1		37	36	Fig 3
					81	18	Fig 4



Reissued: 5-Nov-04

Model: Russian-C3	Date: 25-Oct-04	No.: MB089009a
-------------------	-----------------	----------------




Fig. 3




Fig. 4

Reissued: 5-Nov-04

Model: Russian-C3	Date: 25-Oct-04	No.: MB089009a
-------------------	-----------------	----------------

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Savin 4022 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	USA, Canada	B089-17	J8342101127
Gestetner DSm622 RICOH Aficio 2022	Taiwan	B089-19	J8342101927
Infotec IS2122	Europe, etc	B089-26	4R1124xxxx
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B089-27	J8342200354
Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Asia	B089-29	J8342102002
Savin 4027 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	USA, Canada	B093-17	J8442200345
Gestetner DSm627 RICOH Aficio 2027	Taiwan	B093-19	J8442300420
Infotec IS2127	Europe, etc	B093-26	4R2124xxxx
Nashutec DSm627 RexRotary DSm627 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Europe, etc	B093-27	J8442100280
Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Asia	B093-29	J8442200001
Infotec IS2132	Europe, etc	B097-26	4R3124xxxx
Nashutec DSm632 RexRotary DSm632 Gestetner DSm632 LANIER LD132 RICOH Aficio 2032	Europe, etc	B097-27	J8542100001

Reissued: 5-Nov-04

Model: Russian-C3	Date: 25-Oct-04	No.: MB089009a
-------------------	-----------------	----------------

[RIF (France) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Infotec IS2122	Europe, etc	B089-66	4R17140001
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B089-67	J8344700823
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B144-27	J8644601517
Infotec IS2127	Europe, etc	B093-66	4R27040067
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B093-67	J8444600627
Infotec IS2132	Europe, etc	B097-66	4R37140001
Nashutec DSm627 RexRotary DSm627 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Europe, etc	B093-67	J8544700087

Reissued: 9-Feb-05

Model: Russian-C3	Date: 10-Dec-04	No.: MB089010a
-------------------	-----------------	----------------


Serial Number Update

The Serial Number information has been updated.

Modified Article: Protection Sheets		Prepared by: Y.Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☒ Other	

To prevent the handles from coming out of the machine, protection sheets have been added.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B1541325	Protection Sheet - Handle	0-4		11	36	



Reissued: 9-Feb-05

Model: Russian-C3	Date: 10-Dec-04	No.: MB089010a
-------------------	-----------------	----------------

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Savin 4022 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	USA, Canada	B089-17	J8342200955
Gestetner DSm622 RICOH Aficio 2022	Taiwan	B089-19	J8342200928
Infotec IS2122	Europe, etc	B089-26	4R1015xxxx
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B089-27	J8342200354
Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Asia	B089-29	J8342102002
Savin 4027 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	USA, Canada	B093-17	J8442200342
Gestetner DSm627 RICOH Aficio 2027	Taiwan	B093-19	J8442300420
Infotec IS2127	Europe, etc	B093-26	4R2015xxxx
Nashutec DSm627 RexRotary DSm627 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Europe, etc	B093-27	J8442200133
Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Asia	B093-29	J8442200001
Infotec IS2132	Europe, etc	B097-26	4R3015xxxx
Nashutec DSm632 RexRotary DSm632 Gestetner DSm632 LANIER LD132 RICOH Aficio 2032	Europe, etc	B097-27	J8542200001

Reissued: 9-Feb-05

Model: Russian-C3	Date: 10-Dec-04	No.: MB089010a
-------------------	-----------------	----------------

[RIF (France) Production]

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Infotec IS2122	Europe, etc	B089-66	4R16150027
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B089-67	J8353600617
Nashutec DSm622 RexRotary DSm622 Gestetner DSm622 LANIER LD122 RICOH Aficio 2022	Europe, etc	B144-27	J8644701796
Infotec IS2127	Europe, etc	B093-66	4R27240001
Nashutec DSm627 RexRotary DSm627 Gestetner DSm627 LANIER LD127 RICOH Aficio 2027	Europe, etc	B093-67	J8444700349
Infotec IS2132	Europe, etc	B097-66	4R36150001
Nashutec DSm632 RexRotary DSm632 Gestetner DSm632 LANIER LD132 RICOH Aficio 2032	Europe, etc	B097-67	J8553700001

Model: Russian-C3		Date: 2-Nov-05	No.: MB089011
Modified Article: Pressure Roller		Prepared by: S. Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AE020138	AE020161	Pressure Roller :27	1-1	O/O	39	11	

Change: The shape of the pressure roller was changed.

Reason: To further minimize wrinkles in the paper.

Model: Russian-C3		Date: 6-Jan-06	No.: MB089012
Modified Article: Hot Roller		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AE011058	AE011100	Hot Roller	1-1	O/O	39	23	

Change: This change has been implemented for Rohs compliance.

Model: Russian-C3		Date: 15-Jun-06	No.: MB089013
Modified Article: Scanner Base		Prepared by: S. Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0931801		Scanner Base	1-0		19	16	

Change: This part was deleted from service parts.

Reason: If this part is replaced in the field, sometimes an image quality issue can occur.
This part should only be replaced at the factory.

Model: Russian-C3		Date: 3-Oct-06	No.: MB089014
Modified Article: Hot Roller		Prepared by: S. Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AE011100	AE011103	Hot Roller	1-1	O/O	39	23	

Change: The coating for the inner surface of the hot roller core was changed.

Reason: To facilitate assembly on the hot roller production line.

Model: Russian-C3		Date: 23-Oct-08	No.: MB089015
Modified Article: Operation Panel Board		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0271460	B0271465	Operation Panel Board-Right	1-1	O/O	13	20	

Change: This change has been implemented for Rohs compliance.



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B097	200910		B0971186	D0191188	MAGNETIC CLUTCH:0.5N M:Z35	1	1	O/O		47	9					V0900767	



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	200911		AX040119	AX040220	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					T0502253	
R-C3	B089	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					V0804693	8101773
R-C3	B093	200911		AX040119	AX040220	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					T0502253	
R-C3	B093	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					V0804693	8101773
R-C3	B097	200911		AX040119	AX040220	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					T0502253	
R-C3	B097	200911		AX040220	D3312680	DC MOTOR:PAPER FEED:ASSY	2	2	O/O		45	1					V0804693	8101773



Part Change Information List

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201002		B0911186	AX200165	MAGNETIC CLUTCH	1	1	O/O		47	9			RB089017		V0900767	
R-C3	B093	201002		B0911186	AX200165	MAGNETIC CLUTCH	1	1	O/O		47	9			RB089017		V0900767	
R-C3	B089	201002		B0912617	B2092617	MAGNETIC CLUTCH - 38Z	2	2	O/O		49	12					T0701381	
R-C3	B089	201002		B2092617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	2	2	O/O		49	12					V0900767	
R-C3	B093	201002		B0912617	B2092617	MAGNETIC CLUTCH - 38Z	2	2	O/O		49	12					T0701381	
R-C3	B093	201002		B2092617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	2	2	O/O		49	12					V0900767	
R-C3	B097	201002		B0912617	B2092617	MAGNETIC CLUTCH - 38Z	2	2	O/O		49	12					T0701381	
R-C3	B097	201002		B2092617	AX200290	MAGNETIC CLUTCH:0.25N M:Z38	2	2	O/O		49	12					V0900767	
R-C3	B089	201002		B0912616	B2092616	MAGNETIC CLUTCH - 50Z	2	2	X/O		49	13					T0701381	
R-C3	B089	201002		B2092616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	2	2	O/O		49	13					V0900767	
R-C3	B093	201002		B0912616	B2092616	MAGNETIC CLUTCH - 50Z	2	2	X/O		49	13					T0701381	
R-C3	B093	201002		B2092616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	2	2	O/O		49	13					V0900767	
R-C3	B097	201002		B0912616	B2092616	MAGNETIC CLUTCH - 50Z	2	2	X/O		49	13					T0701381	
R-C3	B097	201002		B2092616	D0192816	MAGNETIC CLUTCH:0.35N M:Z50	2	2	O/O		49	13					V0900767	
R-C3	B089	201002		B0915730	AZ320146	POWER PACK:BCTD	1	1	X/O		51	1					V0803101	4100856
R-C3	B093	201002		B0915730	AZ320146	POWER PACK:BCTD	1	1	X/O		51	1					V0803101	4100856
R-C3	B097	201002		B0915730	AZ320146	POWER PACK:BCTD	1	1	X/O		51	1					V0803101	4100856



Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201003		AZ500059	AZ500068	STABILIZER:XENON LAMP	1	1	O/O		19	14					V0902042	
R-C3	B093	201003		AZ500059	AZ500068	STABILIZER:XENON LAMP	1	1	O/O		19	14					V0902042	
R-C3	B097	201003		AZ500059	AZ500068	STABILIZER:XENON LAMP	1	1	O/O		19	14					V0902042	



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201005		B4061383	B4841383	BRACKET - PLATEN COVER	1	1	X/O		15	10					T0500725	5030350
R-C3	B093	201005		B4061383	B4841383	BRACKET - PLATEN COVER	1	1	X/O		15	10					T0500725	5030350
R-C3	B097	201005		B4061383	B4841383	BRACKET - PLATEN COVER	1	1	X/O		15	10					T0500725	5030350



Part Change Information List

Date: Jul 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201007		04513030B	04513030N	TAPPING SCREW - 3X30	4	4	X/O		45	102					T0402633	4090340
R-C3	B093	201007		04513030B	04513030N	TAPPING SCREW - 3X30	4	4	X/O		45	102					T0402633	4090340
R-C3	B097	201007		04513030B	04513030N	TAPPING SCREW - 3X30	4	4	X/O		45	102					T0402633	4090340



Part Change Information List

Date: March 31, 2011

Model	Code	PCIL Nr.	PCIL Correcti on	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C3	B093	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C3	B097	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		39	2					V1002478	10090261
R-C3	B089	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		81	6					V1002478	10090261
R-C3	B093	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		81	6					V1002478	10090261
R-C3	B097	201103		AA000301	GA000058	DECAL:H-TEMP WARNING:115:CUD	1	1	O/O		81	6					V1002478	10090261



Part Change Information List

Date: June 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B097	201106		B0971129	D0191129	BRUSHLESS MOTOR-DC 30W	1	1	O/O		51	9					V1101027	11050131



Part Change Information List

Date: October 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	3					V1101086	11050641
R-C3	B093	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	3					V1101086	11050641
R-C3	B097	201110		AA120094	D0194453	DISCHARGE BRUSH:PAPER EXIT SUB-UNIT	1	1	O/O		43	3					V1101086	11050641



Part Change Information List

Date: November 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201111		AX050170	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	3					V1002821	10110803
R-C3	B093	201111		AX050170	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	3					V1002821	10110803
R-C3	B097	201111		AX050170	D0853616	DC MOTOR:TONER BOTTLE:Z:2.52W:ASS'Y	1	1	O/O		33	3					V1002821	10110803



Part Change Information List

Date: October 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
R-C3	B089	201210		B0242773	D3312775	BRACKET:RISE:2	2	2	X/O		45	4					V1202445	
R-C3	B093	201210		B0242773	D3312775	BRACKET:RISE:2	2	2	X/O		45	4					V1202445	
R-C3	B097	201210		B0242773	D3312775	BRACKET:RISE:2	2	2	X/O		45	4					V1202445	



Part Change Information List

Date: March 29, 2013

Model	Code	PCIL		Old part number	New part number	Description	Old		New	3DPC	Page	Index	Set	RTB	Note	Ref Number	ECN
		Number	Correction				Qty	Qty	Int								
R-C3	B089	201303		A2672596	D3312596	GUARD-DRIVE-PAPER FEED-RIGHT	2	2	O/O		49	11				V1000763	
R-C3	B093	201303		A2672596	D3312596	GUARD-DRIVE-PAPER FEED-RIGHT	2	2	O/O		49	11				V1000763	
R-C3	B097	201303		A2672596	D3312596	GUARD-DRIVE-PAPER FEED-RIGHT	2	2	O/O		49	11				V1000763	



Part Change Information List

Date: April 28, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C3	B089	201604		B0935720	AZ230083	POWER SUPPLY UNIT -197W AC100-120V	1	1	X/O	N	53	12					V1601179	
R-C3	B093	201604		B0935720	AZ230083	POWER SUPPLY UNIT -197W AC100-120V	1	1	X/O	N	53	12					V1601179	



Part Change Information List

Date: June 5, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C3	B089	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	1	1	O/O	N	37	19					V1700087	16121166
R-C3	B093	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	1	1	O/O	N	37	19					V1700087	16121166
R-C3	B097	201705		D0102822	D0182832	FRICTION PAD:F2:ADHESION	1	1	O/O	N	37	19					V1700087	16121166