

Model: Adonis-C3V2		Date: 1-Aug-03	No.: MB135001
Modified Article: P/N differences: A-C3 c/d vs. e/f mainframe		Prepared by: Y.Urushihara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Please note the following P/N differences between the Model A-C3c/d and e/f mainframes, and the P/C title revisions on the last page of this bulletin.

Model A-C3c/d	Model A-C3e/f	Description	Q'ty	Int	Page	Index	Note
B0826506	B1386506	Operating:Instructions:Main:CHN	1-1	X/X	9	13	
B0826510	B1386507	Operating:Instructions:Main:NA	1-1	X/X	9	13	
B0826508	B1386508	Operating:Instructions:Main:ASIA	1-1	X/X	9	13	
B0826509	B1386509	Operating:Instructions:Main:TWN	1-1	X/X	9	13	
	B1386606	Operating:Instructions:COPY:CH N	1-1	X/X	9	13	
B0826610	B1386607	Operating:Instructions:COPY:NA	1-1	X/X	9	13	
B0826608	B1386608	Operating:Instructions:COPY:ASI A	1-1	X/X	9	13	
B0826609	B1386609	Operating:Instructions:COPY:TW N	1-1	X/X	9	13	
B0796431	B1356431	Decal – Emblem (RIC) (B135)	1-1	X/X	11	2	
B0796433	B1356433	Decal – Emblem (GES NA) (B135)	1-1	X/X	11	2	
B0796434	B1356434	Decal – Emblem (GES EU) (B135)	1-1	X/X	11	2	
B0796435	B1356435	Decal – Emblem (NSA) (B135)	1-1	X/X	11	2	
B0796436	B1356436	Decal – Emblem (REX) (B135)	1-1	X/X	11	2	
B0796437	B1356437	Decal – Emblem (INF) (B135)	1-1	X/X	11	2	
B0796438	B1356438	Decal – Emblem (LAN) (B135)	1-1	X/X	11	2	
B0826431	B1386431	Decal – Emblem (RIC) (B138)	1-1	X/X	11	2	
B0826433	B1386433	Decal – Emblem (GES NA) (B138)	1-1	X/X	11	2	
B0826434	B1386434	Decal – Emblem (GES EU) (B138)	1-1	X/X	11	2	
B0826435	B1386435	Decal – Emblem (NSA) (B138)	1-1	X/X	11	2	
B0826436	B1386436	Decal – Emblem (REX) (B138)	1-1	X/X	11	2	
B0826437	B1386437	Decal – Emblem (INF) (B138)	1-1	X/X	11	2	
B0826438	B1386438	Decal – Emblem (LAN) (B138)	1-1	X/X	11	2	
B0826350	B1386351	Operation Sub – Unit NA Assembly	1-1	X/X	17	1	
B0826360	B1386361	Operation Sub – Unit EU Assembly	1-1	X/X	17	1	
B0826370	B1386371	Operation Sub – Unit TW Assembly	1-1	X/X	17	1	
B0826375	B1386376	Operation Sub – Unit CHN Assembly	1-1	X/X	17	1	
B0826380	B1386386	Operation Sub – Unit KOR Assembly	1-1	X/X	17	1	
B0826385	B1386388	Operation Sub – Unit AA Assembly	1-1	X/X	17	1	

Model: Adonis-C3V2	Date: 1-Aug-03	No.: MB135001
--------------------	----------------	---------------

Model A-C3c/d	Model A-C3e/f	Description	Q'ty	Int	Page	Index	Note
B0825203	B1385203	PCB:LCDC:NA:Assembly	1-1	X/X	17	8	
B0825204	B1385204	PCB:LCDC:EU:Assembly	1-1	X/X	17	8	
B0825205	B1385205	PCB:LCDC:TWN:Assembly	1-1	X/X	17	8	
B0825206	B1385206	PCB:LCDC:CHN:Assembly	1-1	X/X	17	8	
B0825207	B1385207	PCB:LCDC:KOR:Assembly	1-1	X/X	17	8	
B0825065	B1385065	PCB BICU Assembly	1-1	X/X	71	18	
B0825101	B1385101	PCB:Adonis-C3:Main:35:Sub-Assembly	1-1	X/X	77	3	
B0825102	B1385102	PCB:Adonis-C3:Main:45:Sub-Assembly	1-1	X/X	77	3	
B5485863	B5145960	HDD	1-1	X/X	77	17	

Parts Catalogue Title Revisions

Correct:

- Pg. 40: 17. DEVELOPMENT UNIT (B079/B082)
- Pg. 42: 18. PHOTOCONDUCTOR UNIT 1
- Pg. 44: 19. PHOTOCONDUCTOR UNIT 2

Incorrect:

- Pg. 40: 17. DEVELOPMENT UNIT 1 (B079/B082)
- 18. DEVELOPMENT UNIT 2 (B079/B082)
- 19. OPC UNIT (B079/B082)

Reissued: 21-Oct-04

Model: Adonis-C3e/f	Date: 26-Jul-04	No.: MB135002a
---------------------	-----------------	----------------

Serial Number Update

The Serial Number information has been updated.

Modified Article: Fusing Cleaning Roller		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☒ To improve reliability	
	☐ Part standardization	☐ Other	

A coating was applied to the cleaning roller surface.

Reason: To ensure toner melting on the cleaning roller does not occur. Melting can cause grays bands or fusing jams.

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
AE042054	AE042070	Fusing Cleaning Roller	1	X/O	49	17	

Reissued: 21-Oct-04

Model: Adonis-C3e/f	Date: 26-Jul-04	No.: MB135002a
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79471xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7947000254
Ricoh Aficio 2035e	220/50	China	B135-21	J7946900282
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79471xxxxx
LANIER LD135	220/50	Europe	B135-24	J79471xxxxx
IS2135	220/50	Europe	B135-26	4T3814xxxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7946900252
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79471xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7946900001
LANIER LD135	220/50	China	B135-34	J7946900250
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J8046900286
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8046900228
Ricoh Aficio 2045e	220/50	China	B138-21	J8047000295
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80471xxxxx
LANIER LD145	220/50	Europe	B138-24	J80471xxxxx
IS2145	220/50	Europe	B138-26	4T4814xxxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8046900221
Ricoh Aficio 2045e	220/60	Korea	B138-28	J80471xxxxx
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8046800407
LANIER LD145	220/50	China	B138-34	J8046900226

Reissued: 21-Oct-04

Model: Adonis-C3e/f	Date: 26-Jul-04	No.: MB135002a
---------------------	-----------------	----------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J804330XXXX
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J794330XXXX
IS2135	220/50	Europe	B135-66	4T3294XXXX
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J804330XXXX
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J804330XXXX
IS2145	220/50	Europe	B138-66	4T4294XXXX



Modification Bulletin

PAGE: 1/1

Model: Adonis-C3e/f		Date: 17-Aug-04	No.: MB135003
Modified Article: LCD HVGA		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☒ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

The following has been changed due to a vendor change

Old part number	New part number	Description	Q'ty	int	Page	Index	Note
B0825218	B101 5257	LCD HVGA SH BL	1	O/O	17	6	


Model: Adonis-C3e/f		Date: 16-Sep-04	No.: MB135004
Modified Article: Upper Inner Cover Seals		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
	B0821371	Inner Cover: Upper: Sub Assy	0-1		13	38	
B0821372	B0821372	Inner Cover: Upper	1	-	13	23	
	B0821373	Seal: Inner Cover: Middle	0-1		13	39	
	B0821374	Seal: Inner Cover: Upper	0-1		13	40	
	B0821375	Seal: Inner Cover: Left	0-1		13	41	
	B0821379	Seal: Side Plate: Front: Switch	0-1		13	42	

Change: Four seals were added to the upper inner cover and frame.

Reason: To ensure that toner does not cover the contacts of the upper right cover switch.

- This can cause random black lines along the main scan direction, a laser synchronization error, or "Door open" to be displayed.



Model: Adonis-C3e/f	Date: 16-Sep-04	No.: MB135004
---------------------	-----------------	---------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79467xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7946400572
Ricoh Aficio 2035e	220/50	China	B135-21	J7946400360
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J7946400229
LANIER LD135	220/50	Europe	B135-24	J7946400325
IS2135	220/50	Europe	B135-26	4T38440001
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7946400415
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79467xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7946400001
LANIER LD135	220/50	China	B135-34	J7946400410
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J8046400288
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8046400536
Ricoh Aficio 2045e	220/50	China	B138-21	J8046400345
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J8046400183
LANIER LD145	220/50	Europe	B138-24	J8046400253
IS2145	220/50	Europe	B138-26	4T48440001
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8046400375
Ricoh Aficio 2045e	220/60	Korea	B138-28	J8046400295
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8046400001
LANIER LD145	220/50	China	B138-34	J8046600430

Model: Adonis-C3e/f	Date: 16-Sep-04	No.: MB135004
---------------------	-----------------	---------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J79ymm(+24)xxxxx
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J79ymm(+24)xxxxx
IS2135	220/50	Europe	B135-66	4T3mm(+20)xxxx
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J80ymm(+24)xxxxx
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J80ymm(+24)xxxxx
IS2145	220/50	Europe	B138-66	4T4mm(+20)xxxxx

Reissued: 19-Jan-05

Model: Adonis-C3e/f	Date: 14-Dec-04	No.: MB135005a
---------------------	-----------------	----------------

Serial Number Update

The Serial Number information has been updated.

Modified Article: Spring - Cleaning Blade		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☒ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

The following part has been changed to add proper contact pressure between the cleaning blade and OPC drum.

Note: Spring pressure decreased from 5.8 -> 3.0N. The new spring has a silver (metallic) color, as opposed to the older springs which are black.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AA062255	AA062258	Spring – Cleaning Blade	2	X/O	45	24	

Reissued: 19-Jan-05

Model: Adonis-C3e/f	Date: 14-Dec-04	No.: MB135005a
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79561xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7947100267
Ricoh Aficio 2035e	220/50	China	B135-21	J7947100282
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79561xxxxx
LANIER LD135	220/50	Europe	B135-24	J79561xxxxx
IS2135	220/50	Europe	B135-26	4T3815xxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7947100257
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79561xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7947100001
LANIER LD135	220/50	China	B135-34	J79561xxxxx
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J80561xxxxx
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8047100223
Ricoh Aficio 2045e	220/50	China	B138-21	J8047100242
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80561xxxxx
LANIER LD145	220/50	Europe	B138-24	J80561xxxxx
IS2145	220/50	Europe	B138-26	4T4815xxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8047100238
Ricoh Aficio 2045e	220/60	Korea	B138-28	J8047200169
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8047100303
LANIER LD145	220/50	China	B138-34	J80561xxxxx

Reissued: 19-Jan-05

Model: Adonis-C3e/f

Date: 14-Dec-04

No.: MB135005a

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J794350XXXX
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J7952500561
IS2135	220/50	Europe	B135-66	4T3314XXXX
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J804350XXXX
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J805250XXXX
IS2145	220/50	Europe	B138-66	4T4215XXXX

Reissued: 19-Jan-05

Model: Adonis-C3e/f	Date: 17-Dec-04	No.: MB135006a
---------------------	-----------------	----------------

Serial Number Update

The Serial Number information has been updated.


Modified Article: Pressure Lever		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☒ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0774056	B0824160	Lever: Pressure	2	X/O	51	23	

Change: Shape of the pressure lever.

Reason: To further ensure that the gap between the fusing hot roller and fusing pressure roller is normal.

Note: If the gap is too wide, streaks can occur on copies.



Reissued: 19-Jan-05

Model: Adonis-C3e/f	Date: 17-Dec-04	No.: MB135006a
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79471xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7947000254
Ricoh Aficio 2035e	220/50	China	B135-21	J7946900282
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79471xxxxx
LANIER LD135	220/50	Europe	B135-24	J79471xxxxx
IS2135	220/50	Europe	B135-26	4T3914xxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7946900252
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79471xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7946900001
LANIER LD135	220/50	China	B135-34	J7946900250
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J8046900286
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8046900228
Ricoh Aficio 2045e	220/50	China	B138-21	J8047000295
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80471xxxxx
LANIER LD145	220/50	Europe	B138-24	J80471xxxxx
IS2145	220/50	Europe	B138-26	4T4914xxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8046900221
Ricoh Aficio 2045e	220/60	Korea	B138-28	J80471xxxxx
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J80471xxxxx
LANIER LD145	220/50	China	B138-34	J8046900226

Reissued: 19-Jan-05

Model: Adonis-C3e/f	Date: 17-Dec-04	No.: MB135006a
---------------------	-----------------	----------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J7943400701
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J7943400001
IS2135	220/50	Europe	B135-66	4T33040001
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J804340XXXX
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J804350XXXX
IS2145	220/50	Europe	B138-66	4T43040001

Reissued: 22-Mar-05

Model: Adonis-C3e/f	Date: 7-Feb-05	No.: MB135007a
---------------------	----------------	----------------

MB Correction

The items in bold italics have been corrected.

Modified Article: OPERATION SUB-UNIT		Prepared by: Yuji Urushihara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☒ Part standardization	☐ Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1386351	B1386350	OPERATION SUB-UNIT NA SUB-ASS'Y	1-1	O/O	17	1	
B1386361	B1386360	OPERATION SUB-UNIT EU SUB-ASS'Y					
B1386371	B1386370	OPERATION SUB-UNIT TWN ASS'Y					
B1386376	B1386375	OPERATION SUB-UNIT CHN ASS'Y					
B1386386	B1386380	OPERATION SUB-UNIT KOR ASS'Y					
B1386388	B1386385	OPERATION SUB-UNIT ASIA SUB-ASS'Y					

Change/Reason: Parts standardization with the A-C3.

Reissued: 8-Aug-05

Model: Adonis-C3e/f	Date: 27-Jul-05	No.: MB135008a
---------------------	-----------------	----------------

Serial Number Update

The Serial Number information has been updated.

Modified Article: Fusing Roller		Prepared by: Y.Urushihara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other		
	☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards		
	☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AE011092	AE011102	HOT ROLLER:T0.4:HB	1-1	O/O	51	15	

Change: The materials for this part were changed to more environmentally-friendly types.

Reason: (Ricoh internal environmental standards).

Reissued: 8-Aug-05

Model: Adonis-C3e/f	Date: 27-Jul-05	No.: MB135008a
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79565xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J79565xxxxx
Ricoh Aficio 2035e	220/50	China	B135-21	J7956400233
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79565xxxxx
LANIER LD135	220/50	Europe	B135-24	J79565xxxxx
IS2135	220/50	Europe	B135-26	4T3855xxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7956400056
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79565xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7956400081
LANIER LD135	220/50	China	B135-34	J7956400076
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J80565xxxxx
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J80565xxxxx
Ricoh Aficio 2045e	220/50	China	B138-21	J8056400102
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80565xxxxx
LANIER LD145	220/50	Europe	B138-24	J80565xxxxx
IS2145	220/50	Europe	B138-26	4T4855xxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8056400025
Ricoh Aficio 2045e	220/60	Korea	B138-28	J8056400031
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8056400162
LANIER LD145	220/50	China	B138-34	J8056400100

Reissued: 8-Aug-05

Model: Adonis-C3e/f	Date: 27-Jul-05	No.: MB135008a
---------------------	-----------------	----------------


RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J7952901150
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J7952900001
IS2135	220/50	Europe	B135-66	4T32550001
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J8052901348
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J80530XXXX
IS2145	220/50	Europe	B138-66	4T42550001

Model: Adonis-C3e/f		Date: 28-Sep-05	No.: MB135009
Modified Article: Developer Cartridge – sub ass'y		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Please note the following revision made to the A-C3e/f Parts Catalog, which was applied from the beginning of mass production.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0823255	Developer Cartridge – sub ass'y	0-1		43	31	



Model: Adonis-C3 e/f		Date: 8-Nov-05	No.: MB135010
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Part number	Description	Q'ty	Int	Page	Incorrect Index	Correct Index	Note
A2323069	Rear Bias Terminal - Development	1	-	41	22	28	
B0043062	Ground Plate – Doctor Blade	1	-	41	28	22	

Change/Reason: The index was corrected.

Model: Adonis-C3 e/f		Date: 8-Nov-05	No.: MB135011
Modified Article: Fusing Cleaning Roller		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☒ To improve reliability ☐ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
AE042070	AE042084	Fusing Cleaning Roller	1	X/O	49	17	

Change: The surface coating for the fusing cleaning roller was changed.

Reason: To ensure that the fusing cleaning roller functions correctly, and black spots do not appear on the outputs.

REISSUED:13-Dec-05

Model: Adonis-C3e/f	Date: 10-Nov-05	No.: MB135012a
---------------------	-----------------	----------------

SERIAL NUMBER UPDATE

The serial number information has been updated.

Modified Article: Fusing Cleaning Roller		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☒ To improve reliability	
	☐ Part standardization	☐ Other	

Old part number	New part number	Description	Q'ty	Int.	Page	Index	Note
AE042070	AE042084	Fusing Cleaning Roller	1	X /O	49	17	

Change: The surface coating for the fusing cleaning roller was changed.

Reason: To ensure that the fusing cleaning roller functions correctly, and black spots do not appear on the outputs.

REISSUED:13-Dec-05

Model: Adonis-C3e/f	Date: 10-Nov-05	No.: MB135012a
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79567xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7956500001
Ricoh Aficio 2035e	220/50	China	B135-21	J7956400326
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79567xxxxx
LANIER LD135	220/50	Europe	B135-24	J79567xxxxx
IS2135	220/50	Europe	B135-26	4T3875xxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7956500186
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79567xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7956400198
LANIER LD135	220/50	China	B135-34	J7956500502
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J8056600061
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8056500001
Ricoh Aficio 2045e	220/50	China	B138-21	J8056400170
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80567xxxxx
LANIER LD145	220/50	Europe	B138-24	J80567xxxxx
IS2145	220/50	Europe	B138-26	4T4875xxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8056600056
Ricoh Aficio 2045e	220/60	Korea	B138-28	J8056500106
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8056400327
LANIER LD145	220/50	China	B138-34	J8056500156

REISSUED:13-Dec-05

Model: Adonis-C3e/f	Date: 10-Nov-05	No.: MB135012a
---------------------	-----------------	----------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J7953100001
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J7953100001
IS2135	220/50	Europe	B135-66	4T32650001
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J80530XXXXX
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J8053000001
IS2145	220/50	Europe	B138-66	4T42650001

REISSUED:10-Apr-06

Model: Adonis-C3e/f	Date: 24-Nov-05	No.: MB135013b
---------------------	-----------------	----------------

MB Update

The areas in ***bold italics*** were changed or added.

Modified Article: Fusing unit assembly		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☒ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0827320	B0827321	Fusing Unit Assembly : NA	1-1	O/O	49	1	
B0827720	B0827721	Fusing Unit Assembly : EU	1-1	O/O	49	1	

Change: The P/N was changed.
Reason: P/N management (the P/N suffix of the old part was Z).

REISSUED:10-Apr-06

Model: Adonis-C3e/f	Date: 24-Nov-05	No.: MB135013b
---------------------	-----------------	----------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79562xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J7956100001
Ricoh Aficio 2035e	220/50	China	B135-21	J7956100068
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79562xxxxx
LANIER LD135	220/50	Europe	B135-24	J79562xxxxx
IS2135	220/50	Europe	B135-26	4T3825xxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J7956200077
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79562xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J7956100159
LANIER LD135	220/50	China	B135-34	J7956100452
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645 LANIER LD145	115/60	USA	B138-17	J8056300105
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J8056100001
Ricoh Aficio 2045e	220/50	China	B138-21	J8056100350
Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	Europe, Asia	B138-22	J80562xxxxx
LANIER LD145	220/50	Europe	B138-24	J80562xxxxx
IS2145	220/50	Europe	B138-26	4T4825xxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J8056100023
Ricoh Aficio 2045e	220/60	Korea	B138-28	J8056100031
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J8056100218
LANIER LD145	220/50	China	B138-34	J8056100509

REISSUED:10-Apr-06

Model: Adonis-C3e/f	Date: 24-Nov-05	No.: MB135013b
---------------------	-----------------	----------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035eG SAVIN 4135eG Gestetner DSm635G LANIER LD135	120/60	USA (GSA)	B135-57	J7952900001
Ricoh Aficio 2035e Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635 LANIER LD135	220/50	Europe, Asia	B135-67	J79520XXXXX
IS2135	220/50	Europe	B135-66	4T32350001
Ricoh Aficio 2045eG SAVIN 4145eG Gestetner DSm645G LANIER LD145	120/60	USA (GSA)	B138-57	J80527XXXXX
Ricoh Aficio 2045e Gestetner 4532 Nashuatec 4545 Rex Rotary 4518 LANIER LD145	220/50	Europe, Asia	B138-67	J8052700001
IS2145	220/50	Europe	B138-66	4T42450001

Model: Adonis-C3e/f		Date: 23-Feb-06	No.: MB13501
Modified Article: Transfer Unit		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0049015	Transfer unit	0-1		47	40	

Change: This unit was added as a service part.

Reason: A request was received from the field.

Model: Adonis-C3e/f		Date: 23-Feb-06	No.: MB13501
Modified Article: Photosensor		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Incorrect part number	Correct Part number	Description	Q'ty	Int	Page	Index	Note
AW010048		Photosensor – GP2A28N1	1	O/O	59	3	
↳	AW010049	Photo Reflection Sensor					

Change/Reason: The incorrect P/N and description in the Service Manual were corrected.

Old part number	New Part number	Description	Q'ty	Int	Page	Index	Note
AW010049		Photo Reflection Sensor	1	O/O	59	3	
↳	AW010117	Paper Feed Sensor					
AW010048	AW010106	Photosensor – GP2A28N1	1	O/O	61 37	15 19	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model: Adonis-C3e/f		Date: 5-Apr-06	No.: MB135016
Modified Article: NVRAM		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0229590	NVRAM – ZERO COUNTER	1	-	93	3	

Change: This part was added.

Reason: It was missing from the Parts Catalog.

Note: The initial value of this counter is 0.

Model: Adonis-C3e/f		Date: 6-Apr-06	No.: MB135017
Modified Article: TD Sensor		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0823065	B0823064	Density Sensor: Development	1-1	O/O	41	26	

Change: Materials change.

Reason: Ricoh's ongoing changes toward more environmentally-friendly materials

Model: Adonis-C3e/f		Date: 6-Apr-06	No.: MB135018
Modified Article: TD Sensor		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0823064	B2133065	Density Sensor: Development	1-1	O/O	41	26	

Change/Reason: Parts standardization with the A-C4 (B195).

Model: Adonis-C3e/f		Date: 24-Apr-06	No.: MB135019
Modified Article: Parts catalog correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B0774716		Guide Plate: Right					
	B0774710	Guide Plate: Open and close: Right	1-1	-	57	20	

Change/Reason: The P/N and description written in the Parts Catalog were corrected.

Model: Adonis-C3e/f		Date: 8-May-06	No.: MB135020
Modified Article: Receptacle		Prepared by: K.Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AD021127	B2131127	Receptacle	1-1	O/O	37	35	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model: Adonis-C3e/f		Date:26-Jun-06	No.: MB135021
Modified Article: PCU		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0822202	B0822203	PCU: Adonis-C3: Ass'y	1-1	O/O	43	1	

Change: The materials for this part were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model: Adonis-C3 e/f		Date: 11-Aug-06	No.: MB135022
Modified Article: Clutch		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Product Safety	☒ Other ☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX210081	AX210093	Transfer Unit Clutch	1-1	O/O	63	9	
AW020097	AW020159	Photointerrupter	1-1	O/O	63	10	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 2035e SAVIN 4035e Gestetner DSm635 LANIER LD135	115/60	USA	B135-17	J79ymm(+60)xxxxx
Ricoh Aficio 2035e Gestetner DSm635	Generic	Taiwan	B135-19	J79ymm(+60)xxxxx
Ricoh Aficio 2035e	220/50	China	B135-21	J 7957220001
Gestetner DSm635 Nashuatec DSm635 Rex Rotary DSm635	220/50	Europe, Asia	B135-22	J79ymm(+60)xxxxx
LANIER LD135	220/50	Europe	B135-24	J79ymm(+60)xxxxx
IS2135	220/50	Europe	B135-26	4T3mm(+80)yxxxx
Ricoh Aficio 2035e	220/50	Europe, etc	B135-27	J79ymm(+60)xxxxx
Ricoh Aficio 2035e	220/60	Korea	B135-28	J79ymm(+60)xxxxx
Ricoh Aficio 2035e	220/50,60	Asia	B135-29	J79ymm(+60)xxxxx
LANIER LD135	220/50	China	B135-34	J79ymm(+60)xxxxx
Ricoh Aficio 2045e SAVIN 4045e Gestetner DSm645	115/60	USA	B138-17	J80ymm(+60)xxxxx

Model: Adonis-C3 e/f			Date: 11-Aug-06	No.: MB135022
LANIER LD145				
Ricoh Aficio 2045e Gestetner DSm645	Generic	Taiwan	B138-19	J80ymm(+60)xxxxx
Ricoh Aficio 2045e Gestetner DSm645 Nashuatec DSm645 Rex Rotary DSm645	220/50	China Europe, Asia	B138-21 B138-22	J80ymm(+60)xxxxx J80ymm(+60)xxxxx
LANIER LD145	220/50	Europe	B138-24	J80ymm(+60)xxxxx
IS2145	220/50	Europe	B138-26	4T4mm(+80)yxxxx
Ricoh Aficio 2045e	220/50	Europe, etc	B138-27	J80ymm(+60)xxxxx
Ricoh Aficio 2045e	220/60	Korea	B138-28	J80ymm(+60)xxxxx
Ricoh Aficio 2045e	220/50,60	Asia	B138-29	J80ymm(+60)xxxxx
LANIER LD145	220/50	China	B138-34	J80ymm(+60)xxxxx

Model: Adonis-C3e/f		Date: 23-Aug-06	No.: MB135023
Modified Article: HDD		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☒ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Product Safety	☐ Other ☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5485863		Hard Disk					
	→ B1795995	HDD:HITACHI:40GB:PATH-KAI:ROHS	1-1	O/O	77	17	

Change/Reason: Parts standardization with the A-C4.

Model: Adonis-C3e/f		Date: 11-Sep-06	No.: MB135024
Modified Article: Touch Panel		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0825222	B2135222	Touch Panel: HVGA	1-1	O/O	17	3	

Change: The part number for this part was changed.

Reason: Vendor change.

Note: The function and shape of this part have not been changed.

Model: Adonis-C3e/f		Date: 20-Sep-06	No.: MB135025
Modified Article: Special Tool		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		


Part number	Description	Q'ty	Int	Page	Incorrect Index	Correct Index	Note
A2309003	Adjusting Cam – Laser Unit	-	-	99	2	1	
A2309004	Positioning Pin Laser Unit	-	-	99	1	2	

Change/Reason: The index was corrected.

Model: Adonis-C3e/f		Date: 28-May-07	No.: MB135026
Modified Article: Parts Catalog Correction		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

Part number	Description	Q'ty	Int	Page	Index	Note
G0652233	Seal Drum Front	1		43	32	
G0652234	Seal Drum Rear	1		43	33	
A2322399	Seal – Blade 13x9.5x3	2	-	43	34	
A2322348	Seal Blade 12x7x3	2	-	43	35	
A2322350	Seal - Entrance	2	-	43	36	

Change/Reason: The descriptions for these parts were missing from the Parts Catalog.



Model: Adonis-C3e/f		Date: 21-Sep-07	No.: MB135027
Modified Article: Transfer Belt Cleaning Blade/Sensor		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0823831	B2133831	Cleaning Blade : Transfer Belt	1-1	O/O	47	6	
AW310006	AW310007	Toner Overflow Sensor	1-1	O/O	47	38	

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C3e/f		Date: 25-Sep-07	No.: MB135028
Modified Article: Used Toner Sensor Harness		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0825466	B2135467	Harness: Used Toner Sensor	1-1	O/O	35	35	

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C3e/f		Date: 25-Sep-07	No.: MB135029
Modified Article: PCU Parts		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX500046		Quenching Lamp	1-1	O/O	73	12	
	AX500092	LED Array: QL					
B0822290		Bracket: Idler: Ass'y	1-1	O/O	43	25	
	B2132290	Bracket: Idler					
B0822312		Cleaning blade bracket	1-1	O/O	45	16	
	B2132312	Bracket: Cleaning Blade					
B0822316	B2132316	Stud: Contact Point: Cleaning	1-1	O/O	45	1	
B0822292	B2132292	Toner Collection Coil: Ass'y	1-1	O/O	43	17	
A2322367		ID Sensor	1-1	O/O	37	33	
	B2132367	Density Sensor					

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C3e/f		Date: 26-Sep-07	No.: MB135030
Modified Article: Quenching Lamp		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX500092		LED Array: QL	1-1	O/O	73	12	
→	AX500094	LED Array: QL: Ass'y					

Due to a vendor change, the part number has been changed

Model: Adonis-C3e/f		Date: 26-Sep-07	No.: MB135031
Modified Article: LCD: HVGA		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1015257	B1805259	LCD: HVGA: SH: BL	1-1	O/O	17	6	

Change/Reason: Parts standardization with the Model A-C4 (B195).

Model: Adonis-C3e/f		Date: 26-Sep-07	No.: MB135032
Modified Article: Total Counter		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX310039		Total Counter	1-1	O/O	13	28	
→	AX310046	Total Counter: 7FIG: 24V					

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C3e/f		Date: 28-Sep-07	No.: MB135033
Modified Article: ADF Exposure Glass		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3516522		ADF Exposure Glass	1-1	X/O	19	7	
→	BC012002	Exposure Glass:Sheet Through:344X20					

Change/Reason: The part number in the table was changed, because a coat was added to the exposure glass surface to prevent contamination.

Model: Adonis-C3e/f		Date: 4-Oct-07	No.: MB135034
Modified Article: LCD: HVGA		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1805259	B2135225	LCD: HVGA: SH: BL	1-1	O/O	17	6	

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C3e/f		Date: 14-Feb-08	No.: MB135035
Modified Article: Polygon Scanner Motor		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AX060245 →		POLYGON SCANNER:27300RPM:M	1-1	O/O	25	10	
	AX060303	POLYGON SCANNER MOTOR					

The above part has been changed due to part standardization with the Adonis-C4.

Model: Adonis-C3e/f		Date: 18-Feb-08	No.: MB135036
Modified Article: Cleaning Blade Assy		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2132354		CLEANING BLADE:ASS'Y	1-1	O/O	45	23	
	B2912354	CLEANING BLADE					

The above part has been changed due to part standardization with the Adonis-C4.5.



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C3e/f	B135	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	11					V0803798
Adonis-C3e/f	B138	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	11					V0803798



Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C3e/f	B135	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		17	3					V0804330
Adonis-C3e/f	B138	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		17	3					V0804330



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C3e/f	B135	200912		A2326051	B2136051	DC SOLENOID:PICKUP:SUB-ASS'Y	1	1	X/O		29	27					V0903006	4071464
A-C3e/f	B138	200912		A2326051	B2136051	DC SOLENOID:PICKUP:SUB-ASS'Y	1	1	X/O		29	27					V0903006	4071464



Part Change Information List

Date: February 26, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C3e/f	B135	201002		AW020126	AW020158	PAPER FEED SENSOR	1	1	X/O		61	9					V0903006	4071464
A-C3e/f	B138	201002		AW020126	AW020158	PAPER FEED SENSOR	1	1	X/O		61	9					V0903006	4071464



Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C3e/f	B135	201003		AF020514	AF020649	EXIT ROLLER	1	1	X/O		55	3					V1000184	
A-C3e/f	B135	201003		AF020649	AF020694	EXIT ROLLER	1	1	X/O		55	3					V1000193	
A-C3e/f	B138	201003		AF020514	AF020649	EXIT ROLLER	1	1	X/O		55	3					V1000184	
A-C3e/f	B138	201003		AF020649	AF020694	EXIT ROLLER	1	1	X/O		55	3					V1000193	
A-C3e/f	B135	201003		A2324484	B2134484	DC SOLENOID:EXIT:ASS'Y	1	1	X/O		55	6					V0903006	4071464
A-C3e/f	B138	201003		A2324484	B2134484	DC SOLENOID:EXIT:ASS'Y	1	1	X/O		55	6					V0903006	4071464
A-C3e/f	B135	201003		AF020515	AF020658	TRANSPORT ROLLER	1	1	X/O		55	15					V1000184	
A-C3e/f	B135	201003		AF020658	AF020698	TRANSPORT ROLLER	1	1	X/O		55	15					V1000193	
A-C3e/f	B138	201003		AF020515	AF020658	TRANSPORT ROLLER	1	1	X/O		55	15					V1000184	
A-C3e/f	B138	201003		AF020658	AF020698	TRANSPORT ROLLER	1	1	X/O		55	15					V1000193	
A-C3e/f	B135	201003		B0824472	B2134472	SIDE PLATE:REAR:ASS'Y	1	1	X/O		55	17					V1000184	
A-C3e/f	B138	201003		B0824472	B2134472	SIDE PLATE:REAR:ASS'Y	1	1	X/O		55	17					V1000184	
A-C3e/f	B135	201003		B0774793	B2134793	BRACKET:LINK	2	2	X/O		57	8					V1000184	
A-C3e/f	B138	201003		B0774793	B2134793	BRACKET:LINK	2	2	X/O		57	8					V1000184	
A-C3e/f	B135	201003		AF020512	AF020653	ROLLER:DRIVEN	2	2	X/O		57	17					V1000184	
A-C3e/f	B138	201003		AF020512	AF020653	ROLLER:DRIVEN	2	2	X/O		57	17					V1000184	
A-C3e/f	B135	201003		AF020509	AF020659	REVERSE ROLLER	2	2	X/O		59	12					V1000184	
A-C3e/f	B138	201003		AF020509	AF020659	REVERSE ROLLER	2	2	X/O		59	12					V1000184	
A-C3e/f	B135	201003		B0774642	B2134642	SIDE PLATE:REAR:ASS'Y	1	1	X/O		59	13					V1000184	
A-C3e/f	B138	201003		B0774642	B2134642	SIDE PLATE:REAR:ASS'Y	1	1	X/O		59	13					V1000184	
A-C3e/f	B135	201003		B0774666	B2134666	BRACKET:STEPPER MOTOR:REVERSE	1	1	X/O		59	21					V1000184	
A-C3e/f	B138	201003		B0774666	B2134666	BRACKET:STEPPER MOTOR:REVERSE	1	1	X/O		59	21					V1000184	
A-C3e/f	B135	201003		B0774638	B2134638	SIDE PLATE:FRONT:ASS'Y	1	1	X/O		59	25					V1000184	
A-C3e/f	B138	201003		B0774638	B2134638	SIDE PLATE:FRONT:ASS'Y	1	1	X/O		59	25					V1000184	
A-C3e/f	B135	201003		AF020513	AF020654	TRANSPORT ROLLER:MIDDLE	1	1	X/O		61	6					V1000184	
A-C3e/f	B135	201003		AF020654	AF020697	DUPLEXTRANSPORT ROLLER - MIDDLE	1	1	X/O		61	6					V1000193	
A-C3e/f	B138	201003		AF020513	AF020654	TRANSPORT ROLLER:MIDDLE	1	1	X/O		61	6					V1000184	
A-C3e/f	B138	201003		AF020654	AF020697	DUPLEXTRANSPORT ROLLER - MIDDLE	1	1	X/O		61	6					V1000193	
A-C3e/f	B135	201003		B0774678	B2134678	BRACKET:STEPPER MOTOR:PAPER FEED	1	1	X/O		61	12					V1000184	
A-C3e/f	B138	201003		B0774678	B2134678	BRACKET:STEPPER MOTOR:PAPER FEED	1	1	X/O		61	12					V1000184	
A-C3e/f	B135	201003		B0774790	B2134790	LINK:DUPLEX	1	1	X/O		61	20					V1000184	
A-C3e/f	B138	201003		B0774790	B2134790	LINK:DUPLEX	1	1	X/O		61	20					V1000184	



Part Change Information List

Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C3e/f	B135	201004		A2326049	B2136049	BRACKET:DC SOLENOID	1	1	X/O		29	37					V0903006	4071464
A-C3e/f	B138	201004		A2326049	B2136049	BRACKET:DC SOLENOID	1	1	X/O		29	37					V0903006	4071464
A-C3e/f	B135	201004		AF021059	AF021083	REGISTRATION ROLLER:DRIVEN:MM16	1	1	X/O		37	23					V1000184	
A-C3e/f	B138	201004		AF021059	AF021083	REGISTRATION ROLLER:DRIVEN:MM16	1	1	X/O		37	23					V1000184	
A-C3e/f	B135	201004		B0044486	B2134486	DC SOLENOID:ENTRANCE:ASS'Y	1	1	X/O		55	18					V0903006	4071464
A-C3e/f	B138	201004		B0044486	B2134486	DC SOLENOID:ENTRANCE:ASS'Y	1	1	X/O		55	18					V0903006	4071464
A-C3e/f	B135	201004		AF020653	AF020696	DRIVEN ROLLER-DUPLEX	2	2	X/O		57	17					V1000193	
A-C3e/f	B138	201004		AF020653	AF020696	DRIVEN ROLLER-DUPLEX	2	2	X/O		57	17					V1000193	
A-C3e/f	B135	201004		AF020659	AF020699	DUPLEXREVERSE ROLLER	2	2	X/O		59	12					V1000193	
A-C3e/f	B138	201004		AF020659	AF020699	DUPLEXREVERSE ROLLER	2	2	X/O		59	12					V1000193	
A-C3e/f	B135	201004		B0044664	B2134664	STEPPER MOTOR:DUPLEX:DC24V 28.8W	2	2	X/O		59	22					V0903006	4071464
A-C3e/f	B138	201004		B0044664	B2134664	STEPPER MOTOR:DUPLEX:DC24V 28.8W	2	2	X/O		59	22					V0903006	4071464
A-C3e/f	B135	201004		B0044690	B2134690	DC SOLENOID:UNIT	1	1	X/O		59	24					V0903006	4071464
A-C3e/f	B138	201004		B0044690	B2134690	DC SOLENOID:UNIT	1	1	X/O		59	24					V0903006	4071464
A-C3e/f	B135	201004		B0044664	B2134664	STEPPER MOTOR:DUPLEX:DC24V 28.8W	2	2	X/O		61	14					V0903006	4071464
A-C3e/f	B138	201004		B0044664	B2134664	STEPPER MOTOR:DUPLEX:DC24V 28.8W	2	2	X/O		61	14					V0903006	4071464



201805 Part Change Information List

Date: June 5, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C3e_f	B135	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	2	2	O/O	N	69	11					V1702208	
A-C3e_f	B138	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	2	2	O/O	N	69	11					V1702208	