


Model: Adonis-C4b/c		Date: 18-Oct-05	No.: MB195001
Modified Article: Developer Cartridge – sub ass'y		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B0823255	Developer Cartridge – sub ass'y	0-1		41	53	

Change/Reason: The Parts Catalog was corrected.

Note: This part is used in the machine from the beginning of mass production.



Model: Adonis-C4b/c		Date: 8-Nov-05	No.: MB195002
Modified Article: Power supply code		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2135602	B0045528	Power Supply Cable: EU	1-1	X/O	67	12	

Change/Reason: The power supply cable was changed to one that is made locally.

Model: Adonis-C4b/c		Date: 8-Nov-05	No.: MB195003
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Part number	Description	Q'ty	Int	Page	Incorrect Index	Correct Index	Note
A2323069	Rear Bias Terminal - Development	1	-	39	22	28	
B0043062	Ground Plate – Doctor Blade	1	-	39	28	22	

Change/Reason: The index was corrected.

Model: Adonis-C4		Date: 16-Nov-05	No.: MB195004
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

The following part number was added to the parts catalog as it was not listed in the previous parts catalog.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B1986437	Sheet: Emblem: INF: IS2245	0-1	-	11	2	

Model: Adonis-C4		Date: 6-Dec-05	No.: MB195005
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B1986707	Operating Instructions: Security: GEN	0-1	-	9	20	

Change: The part above was added.

Reason: It was missing from the Parts Catalog.

Model: Adonis-C4		Date: 5-Jun-06	No.: MB195006
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2322343		Pickoff Pawl	1-0	-	43	1	

Change: This part was deleted.

Reason: Parts Catalog error (this part does not exist).

Model: Adonis-C4		Date: 5-Jun-06	No.: MB195007
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Part number	Description	Q'ty	Int	Page	Incorrect Index	Correct index	Note
AB011386	Development Sleeve Gear	1	-	39	7	8	
AB011446	Gear – 29Z	1	-	39	8	7	

Change/Reason: The index was corrected.

Model: Adonis-C4		Date: 2-Aug-06	No.: MB195008
Modified Article: LD Unit		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2131891	B2131892	LD Unit	1-1	X/O	23	8	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Model: Adonis-C4		Date: 24-Aug-06	No.: MB195009
Modified Article: Parts Catalog Correction		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1987720		Fusing Unit: EU	-	-	47	1	

Change: This part was deleted from the Parts Catalog.

Reason: It was listed in the Parts Catalog by mistake (it is not a service part).

Model: Adonis-C4		Date: 1-Sep-06	No.: MB195010
Modified Article: Hot Roller		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1987315	B1987316	Fusing Unit: NA Service Ass'y	1-1	O/O	47	1	
B1987715	B1987716	Fusing Unit: EU Service Ass'	1-1	O/O	47	1	
AE011102	AE011115	Hot Roller: T0.4 HB	1-1	O/O	49	15	

Change: The material of the Hot roller was changed.

Reason: To improve the strength of the Hot Roller.

Model: Adonis-C4		Date: 20-Sep-06	No.: MB195011
Modified Article: Special Tool		Prepared by: K. Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Part number	Description	Q'ty	Int	Page	Incorrect Index	Correct Index	Note
A2309003	Adjusting Cam – Laser Unit	-	-	109	2	1	
A2309004	Positioning Pin Laser Unit	-	-	109	1	2	

Change/Reason: The index number was corrected.

Model: Adonis-C4		Date: 22-Sep-06	No.: MB195012
Modified Article: Fusing		Prepared by: K.Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0824131	B2134131	Fusing Cover: Printing	1-1	X/O	47	5	A
B0824051	B2134171	Frame: Fusing: Ass'y	1-1	X/O	49	25	A
B2134161	B2134263	Lever: Pressure: Front	1-1	X/O	49	23	A
B2134162	B2134264	Lever: Pressure: Rear	1-1	X/O	49	30	A

Change: The shape of the pressure levers was changed.

Reason: To further ensure that the nip width is within target.

Note: The “nip width” is the amount of space between the hot roller and pressure roller.

Important: When you install the new parts for the first time, install them **together as a set**.

Model: Adonis-C4		Date: 15-Sep-06	No.: RB195020
Subject: Harness & BICU		Prepared by: K.Hamada	
From: 1st Tech. Support Sec. Service Support Dept.			
Classification:	☐ Troubleshooting ☐ Mechanical ☐ Paper path ☐ Product Safety	☒ Part information ☐ Electrical ☐ Transmit/receive ☐ Other ()	☐ Action required ☐ Service manual revision ☐ Retrofit information

Important Notes Regarding RoHS Compliant Parts

1. The materials of the Harness and PCB connector were changed to comply with the RoHS Directive.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2135425	B2135426	Harness: BCU: IOB	1	X/O	69	16	
B2135065	B2135066	PCB: BICU	1	X/X	69	18	

2. In the field, handle the parts as shown in the tables below.

Part-to-part interchangeability:

This is to make sure that parts are used in the correct combination.

	Old BICU (Non-RoHS Compliant)	New BICU (RoHS Compliant)
Old Harness (Non-RoHS Compliant)	Usable (*)	<u>DO NOT USE</u>
New Harness (RoHS Compliant)	Usable (*)	Usable (*)

Important:

- **DO NOT** use the old Harness (**non-RoHS** compliant) with PCB (**RoHS** compliant).
When you install the new PCB for the first time, install it with the new Harness **together as a set**.
- (*): See table below.

Part-to-machine interchangeability:

This is to make sure that the correct parts are used on the correct machines.

	RoHS Compliant Parts	Non-RoHS Compliant Parts
RoHS Compliant Machines	OK	<u>DO NOT USE</u>
Non-RoHS Compliant Machines	OK	OK

Model: Adonis-C4b/c		Date: 30-Mar-07	No.: MB195013
Modified Article: Parts Catalog Correction		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Incorrect P/N	Correct P/N	Description	Q'ty	Int	Page	Index	Note
B2135466	B2135467	Harness: Used Toner Sensor	1-1	X/O	33	15	

Change/Reason: The part number was corrected.

Model: Adonis-C4b/c		Date: 30-Mar-07	No.: MB195014
Modified Article: Parts Catalog Correction		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Incorrect P/N	Correct P/N	Description	Q'ty	Int	Page	Index	Note
B1386507	B1986510	Operating Instructions – Main NA	1-1	X/O	9	13	
B1386607	B1986610	Operating Instructions – Copy NA	1-1	X/O	9	13	

Change/Reason: The part numbers were corrected.

Reissued: 23-Apr-07

Model: Adonis-C4	Date: 1-Sep-06	No.:MB195010a_sn
------------------	----------------	------------------

Serial Number Update

The Serial Number information has been updated.

Modified Article: Hot Roller		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1987315	B1987316	Fusing Unit: NA Service Ass'y	1-1	O/O	47	1	
B1987715	B1987716	Fusing Unit: EU Service Ass'y	1-1	O/O	47	1	
AE011102	AE011115	Hot Roller: T0.4 HB	1-1	O/O	49	15	

Change: The material of the hot roller was changed.

Reason: To improve the strength of the Hot Roller.

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166400151
Ricoh Aficio 3035	220/50	China	B195-21	K9166420001
Infotec IS 2235	220/50	Europe	B195-26	9N8MMYxxxx
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9266600156
Ricoh Aficio 3035	220/60	Korea	B195-28	K9266400101
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9266440069
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx

Reissued: 23-Apr-07

Model: Adonis-C4		Date: 1-Sep-06		No.:MB195010a_sn
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe/ Latin America	B265-27	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266400251
Ricoh Aficio 3045	220/50	China	B198-21	K9266420001
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045	220/60	Korea	B198-28	K9266400101
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9266440069
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4		Date: 25-Apr-07	No.: MB195015
Modified Article: Lens Unit, Harness and PCB		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2131831	B2131832	Lens Unit	1	X/X	17	9	
B2135542	B2135544	Harness: FFC: SBU: 50WICK: 80mm	1	X/O	17	15	
B2135340	B2135343	PCB: SIB	1	X/X	17	18	

Change: The materials of the above parts were changed.

Reason: RoHS compliance

Note: See RTB RB195019 for details

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166300091
Ricoh Aficio 3035	220/50	China	B195-21	K9166320001
Infotec IS 2235	220/50	Europe	B195-26	9N8MMYxxxx
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9166300121
Ricoh Aficio 3035	220/60	Korea	B195-28	K9166300101
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9166340001

Model: Adonis-C4			Date: 25-Apr-07	No.: MB195015
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe/ Latin America	B265-27	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266400251
Ricoh Aficio 3045	220/50	China	B198-21	K9266320001
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045	220/60	Korea	B198-28	K9266300101
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9266340001
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4		Date: 25-Apr-07	No.: MB195016
Modified Article: HDD		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5145990		HDD:HITACHI:40GB:PATH:ROHS	1-1	O/O	71	16	
	B1795995	HDD:HITACHI:40GB:PATH-KAI:ROHS					

Change/Reason: Production of the old part was discontinued.

Note: The functions and specifications of this part have not been changed.

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166500121
Ricoh Aficio 3035	220/50	China	B195-21	K9166520001
Infotec IS 2235	220/50	Europe	B195-26	9N8MMYxxxx
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9166500171
Ricoh Aficio 3035	220/60	Korea	B195-28	K92YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9166440309

Model: Adonis-C4			Date: 25-Apr-07	No.: MB195016
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe/ Latin America	B265-27	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266500231
Ricoh Aficio 3045	220/50	China	B198-21	K9266530001
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045	220/60	Korea	B198-28	K9266500031
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9266400429
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4		Date: 25-Apr-07	No.: MB195017
Modified Article: BICU & Harness		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2135425	B2135426	Harness: BICU: IOB	1-1	X/O	69	16	
B2135065	B2135066	PCB: BICU	1-1	X/X	69	18	

Change: The materials of the harness and PCB connector were changed.

Reason: To comply with the RoHS Directive.

Note: See RTB #RB195020 for more details.

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166700101
Ricoh Aficio 3035	220/50	China	B195-21	K9166620052
Infotec IS 2235	220/50	Europe	B195-26	9N8MMYxxxx
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9166700139
Ricoh Aficio 3035	220/60	Korea	B195-28	K92YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9166640100
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx

Model: Adonis-C4		Date: 25-Apr-07		No.: MB195017
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe/ Latin America	B265-27	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266800006
Ricoh Aficio 3045	220/50	China	B198-21	K9266720001~0030
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045	220/60	Korea	B198-28	K9266700001~00050
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9266640200~0275
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4		Date: 25-Apr-07	No.: MB195018
Modified Article: Pressure Plate		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☒ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B7144311	B7144313	Pressure Plate Ass'y	1-1	X/O	19	10	

Change: The shape of this part was changed.

Reason: To make sure the user does not touch the pressure plate.

Model: Adonis-C4		Date: 28-Sep-07	No.: MB195019
Modified Article: IOB		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2135155		PCB: IOB	1-1	O/O	63	9	
→	B2985150	I/O Control Board					

Change/Reason: Parts standardization with the Model A-C4.5 (B195).

Model: Adonis-C4		Date: 11-Oct-07	No.: MB195020
Modified Article: Controller Board and ASIC		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2135101		PCB: Main: 35	1-1	O/O	71	14	
→	B2135105	PCB: AD-C4: Main: 35: Sub-Ass'y					
B2135102		PCB: Main: 45	1-1	O/O	71	14	
→	B2135106	PCB: AD-C4: Main: 45: Sub-Ass'y					
B1805660	B2385720	ASIC	1-1	O/O	81	1	

Change/Reason: Parts standardization of the ASIC.



Model: Adonis-C4		Date: 11-Oct-07	No.: MB195021
Modified Article: PSU		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AZ230186		Power Supply Unit: 285W	1-1	O/O	67	13	
	AZ230217	Power Supply Unit - 120V, 285W					
AZ230187		Power Supply Unit - 285W	1-1	O/O	67	13	
	AZ230218	Power Supply Unit - 230V, 285W					

Change: The shape of the power supply unit was changed.

Reason: The shape of the PSU cooling fan was changed, and the fan is mounted on the PSU.

Model: Adonis-C4		Date: 30-Oct-07	No.: MB195022
Modified Article: Operation Panel and PCB LCDC		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1986360		Operation Panel: EU	1-1	X/O	15	1	
→	B1986362	Operation Sub-Unit: EU: Ass'y					
B1986375		Operation Panel: CHN	1-1	X/O	15	1	
→	B1986376	Operation Sub-Unit: CHN: Ass'y					
B1985204		PCB: LCDC: EU	1-1	X/O	15	8	
→	B1985224	PCB: LCDC: EU: Ass'y					
B1985206		PCB: LCDC: CHN	1-1	X/O	15	8	
→	B1985226	PCB: LCDC: CHN: Ass'y					
B1985203		PCB: LCDC: NA	1-1	O/O	15	8	
→	B1985223	PCB: LCDC: NA: Ass'y					
B1985205		PCB: LCDC: TWN	1-1	O/O	15	8	
→	B1985225	PCB: LCDC: TWN: Ass'y					
B1985207		PCB: LCDC: KOR	1-1	O/O	15	8	
→	B1985227	PCB: LCDC: KOR: Ass'y					

Change: The materials of these parts were changed.

Reason: RoHS compliance

Model: Adonis-C4	Date: 30-Oct-07	No.: MB195022
------------------	-----------------	---------------

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166600101
Ricoh Aficio 3035	220/50	China	B195-21	K9166620034
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9166500171
Ricoh Aficio 3035	220/60	Korea	B195-28	K92YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9166640001
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266600131
Ricoh Aficio 3045	220/50	China	B198-21	K9266720001
Ricoh Aficio 3045	220/50	Latin America	B198-27	K9266300201
Ricoh Aficio 3045	220/60	Korea	B198-28	K9166600031
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9266640001
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4	Date: 30-Oct-07	No.: MB195022
------------------	-----------------	---------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Infotec IS 2235	220/50	Europe	B195-26	9N8MMYxxxx
Ricoh Aficio 3035G Savin 8035g Gestetner DSm735G Lanier LD235	115/60	USA/ Latin America	B195-57	K93YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe	B265-17	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045G Savin 8045G Gestetner DSm745G Lanier LD245	115/60	USA/ Latin America	B198-57	K94YMMxxxxx

REI (U.S.A.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx

Model: Adonis-C4		Date: 30-Oct-07	No.: MB195023
Modified Article: LCD: HVGA		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHS) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1805259	B2135225	LCD: HVGA: SH: BL	1-1	X/O	15	6	

Change: The materials of these parts were changed.

Reason: RoHS compliance

RAI (China) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Gestetner DSm735	110/60	Taiwan	B195-19	K9166100061
Ricoh Aficio 3035	220/50	China	B195-21	K9157220001
Ricoh Aficio 3035	220/50	Latin America	B195-27	K9166300121
Ricoh Aficio 3035	220/60	Korea	B195-28	K92YMMxxxxx
Ricoh Aficio 3035 Gestetner DSm735 Lanier LD235 Infotec IS 2235	220/50,60	Asia	B195-29	K9157240001
Lanier LD235	220/50	China	B195-34	K91YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745	110/60	Taiwan	B198-19	K9266100091
Ricoh Aficio 3045	220/50	China	B198-21	K9257220001
Ricoh Aficio 3045	220/50	Latin America	B198-27	K9266300201
Ricoh Aficio 3045	220/60	Korea	B198-28	K92YMMxxxxx
Ricoh Aficio 3045 Gestetner DSm745 Lanier LD245 Infotec IS 2245	220/50,60	Asia	B198-29	K9257240010
Lanier LD245	220/50	China	B198-34	K92YMMxxxxx

Model: Adonis-C4	Date: 30-Oct-07	No.: MB195023
------------------	-----------------	---------------

RPL (U.K.) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe/ Latin America	B264-27	K93YMMxxxxx
Ricoh Aficio 3035 Nashuatec DSm735 RexRotary DSm735 Gestetner DSm735 Lanier LD235	220/50	Europe (None EU)	B264-67	K93YMMxxxxx
Infotec IS 2235	220/50	TBA	95-26	9N8MMYxxxx
Ricoh Aficio 3035G Savin 8035g Gestetner DSm735G Lanier LD235	115/60		95-57	K93YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe/ Latin America	B265-27	K94YMMxxxxx
Ricoh Aficio 3045 Nashuatec DSm745 RexRotary DSm745 Gestetner DSm745 Lanier LD245	220/50	Europe (None EU)	B265-67	K94YMMxxxxx
Infotec IS 2245	220/50	Europe	B198-26	9N9MMYxxxx
Ricoh Aficio 3045G Savin 8045G Gestetner DSm745G Lanier LD245	115/60	USA/ Latin America	B198-57	K94YMMxxxxx

REI (U.S.A) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Ricoh Aficio 3035 Savin 8035 Gestetner DSm735 Lanier LD235	115/60	USA	B264-17	K93YMMxxxxx
Ricoh Aficio 3045 Savin 8045 Gestetner DSm745 Lanier LD245	115/60	USA	B265-17	K94YMMxxxxx

Model: Model A-C4		Date: 4-Dec-07	No.: MB195024
Modified Article: HDD		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1795995	B2475227	HDD:HITACHI:80GB:PATH2:PATA	1- 1	O/O	71	16	

Change/Reason: Production was stopped on the older version.

Model: Adonis-C4b/c		Date: 7-Jan-08	No.: MB195025
Modified Article: Transfer Unit		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Page	Index	Note
	B0049015	Transfer unit	0-1	45	*	

Change: This unit was added as a service part.

Reason: A request was received from the field.

Model: Adonis-C4		Date: 18-Feb-08	No.: MB195026
Modified Article: Cleaning Blade Assy		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2132354		CLEANING BLADE:ASS'Y	1-1	O/O	41	47	
	B2912354	CLEANING BLADE					

The above part has been changed due to part standardization with the Adonis-C4.5.

Model: Adonis-C4		Date: 5-Jun-08	No.: MB195027
Modified Article: Imaging Unit		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☒ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2131870	B2981870	Imaging Unit	1-1	O/O	23	1	
B2131892	B2981891	LD Unit	1-1	O/O	23	8	

The above part has been changed due to part standardization with the Adonis-C4.5.

Model: Adonis-C4		Date: 23-Feb-09	No.: MB195028
Modified Article: DIMM: 128MB		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5845040	B5845051	PCB:DDR-DIMM:128MB	1-1	O/O	71	15	

Change/ Reason: Vendor change

Model: Adonis-C4		Date: 27-Feb-09	No.: MB195029
Modified Article: Operation Panel		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index
B1986350	B1936352	Operation Sub Unit Panel NA	1	X/O	15	1
B1986362	B1986363	Operation Sub-Unit : EU Ass'y	1	X/O	15	1
B1986385	B1986386	Operation Panel AA	1	X/O	15	1
B2135222	H3106173	TOUCH PANEL:HVGA	1	X/O	15	3

Change: The material of the conductive adhesive used for the FPC (Flexible Printed Circuits) was changed to one with a higher connection reliability.



Reason: To improve reliability of FPC connection.



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C4b/c	B195	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4b/c	B198	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4b/c	B264	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798



Part Change Information List

Date: May 30, 2009

[illegible]



Part Change Information List

Date: Jun 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4b/c	B195	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4b/c	B198	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4b/c	B264	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4b/c	B265	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	



Part Change Information List

Date: November 30, 2010

Model	Code	PCIL Nr.	PCIL Correctio	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B195	201011		AF020648	AF020701	TRANSPORT ROLLER:DRIVE	1	1	O/O		31	1					V0802936	06080422
A-C4	B198	201011		AF020648	AF020701	TRANSPORT ROLLER:DRIVE	1	1	O/O		31	1					V0802936	06080422
A-C4	B264	201011		AF020648	AF020701	TRANSPORT ROLLER:DRIVE	1	1	O/O		31	1					V0802936	06080422
A-C4	B265	201011		AF020648	AF020701	TRANSPORT ROLLER:DRIVE	1	1	O/O		31	1					V0802936	06080422



Part Change Information List

Date: June 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B213	201105		B2131832	B2981832	HOLDER:LENS:ADONIS-C4:ASS'Y	1	1	O/O		17	9					V0700807	
A-C4	B195	201105		B2131832	B2981832	HOLDER:LENS:ADONIS-C4:ASS'Y	1	1	O/O		17	9					V0700807	
A-C4	B198	201105		B2131832	B2981832	HOLDER:LENS:ADONIS-C4:ASS'Y	1	1	O/O		17	9					V0700807	
A-C4	B264	201105		B2131832	B2981832	HOLDER:LENS:ADONIS-C4:ASS'Y	1	1	O/O		17	9					V0700807	
A-C4	B213	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	5					V1002614	10101257
A-C4	B195	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	5					V1002614	10101257
A-C4	B198	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	5					V1002614	10101257
A-C4	B264	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	5					V1002614	10101257



Part Change Information List

Date: September 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4b/c	B195	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	
A-C4b/c	B198	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	
A-C4b/c	B264	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	



Part Change Information List

Date: January 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B195	201201		B0771250	B0776314	COVER:UPPER:EU	1	1	O/O		13	35					V1100089	11010199
A-C4	B198	201201		B0771250	B0776314	COVER:UPPER:EU	1	1	O/O		13	35					V1100089	11010199
A-C4	B213	201201		B0771250	B0776314	COVER:UPPER:EU	1	1	O/O		13	35					V1100089	11010199



Part Change Information List

Date: March 30, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B195	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4	B198	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4	B213	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199



Part Change Information List

Date: April 27, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B195	201204		B2131681	B2981681	SCANNER INNER COVER	1	1	O/O		17	8					V1103753	
A-C4	B198	201204		B2131681	B2981681	SCANNER INNER COVER	1	1	O/O		17	8					V1103753	
A-C4	B213	201204		B2131681	B2981681	SCANNER INNER COVER	1	1	O/O		17	8					V1103753	
A-C4	B264	201204		B2131681	B2981681	SCANNER INNER COVER	1	1	O/O		17	8					V1103753	

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4	B195	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4	B198	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4	B213	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4	B264	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	



Part Change Information List

Date: November 2, 2015

[illegible]



Part Change Information List

Date: July 1, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4b_c	B195	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199
A-C4b_c	B198	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199



Part Change Information List

Date: Octorber 4, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4b_c	B195	201609		B1982203	B1982204	PCU:ADONIS-C4:EXP:ASS'Y	1	1	O/O	N	41	48					V1500743	15021007
A-C4b_c	B198	201609		B1982203	B1982204	PCU:ADONIS-C4:EXP:ASS'Y	1	1	O/O	N	41	48					V1500743	15021007
A-C4b_c	B264	201609		B1982203	B1982204	PCU:ADONIS-C4:EXP:ASS'Y	1	1	O/O	N	41	48					V1500743	15021007



Part Change Information List

Date: June 5, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4	B213	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B195	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B198	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B264	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B265	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	



Part Change Information List

Date: June 5, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4.5	B298	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4.5b_c	B291	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4.5b_c	B295	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4.5b_c	B296	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4.5b_c	B297	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	



201805 Part Change Information List

Date: June 5, 2018

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4b_c	B195	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B198	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4	B213	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B264	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	
A-C4b_c	B265	201805		B2475238	B2479101	HDD:PATH2:40GB_CLIP:MASTER:RC	1	1	O/O	N	71	16					V1702208	