

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin C2 | | Date: 12-Jun-06 | No.: MB188001 |
| Modified Article: Counter:PCB:NOVITA | | Prepared by: F.Noguchi | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Incorrect part number | Correct part number | Description | Q'ty | Page | Index | Note |
|-----------------------|---------------------|----------------------|------|------|-------|------|
| B1889890 | B1889590 | Counter: PCB: NOVITA | 1 | 69 | 33 | |

Change: The part number was corrected.

Reason: The part number in the Parts Catalog was incorrect.

| | | | |
|--|--|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 29-Sep-06 | No.: MB188002 |
| Modified Article: LED Array: QL: Ass'y | | Prepared by: F.Noguchi | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input checked="" type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-----------------------|-------|-----|------|-------|------|
| B0102016 | | LED Array: QL: Ass'y | 2 - 0 | X/ | 27 | 23 | |
| B0102011 | | Discharge Lamp Casing | 1 - 0 | X/ | 27 | 25 | |
| | B1882020 | Quenching Lamp: UNIT | 0 - 1 | /O | 27 | 23 | |

Change: B0102016 and B0102011 were combined into one assembly.

Reason: To further ensure that short circuits do not occur during assembly.

| MODEL NAME | V/Hz | DESTINATION | CODE | SERIAL NO. |
|--|----------------|----------------------------|---------|-------------|
| RICOH Aficio 480W Savin 4800WD LANIER LW411 Gestetner A080 | 120/60 | USA, Canada, S. America | B188-17 | K7651200002 |
| RICOH Aficio 480W | 220-240/50, 60 | China | B188-21 | K76601xxxxx |
| RICOH Aficio 480W Nashuatec A080 Gestetner A080 Rex Rotary A080 | 220-240/50, 60 | Europe, Asia, Oceania, etc | B188-27 | K7651200035 |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 3-Oct-06 | No.: MB188003 |
| Modified Article: Harnesses | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input checked="" type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--|-------|-----|------|-------|------|
| B1885818 | | Harness: DC: Motor: Paper Feed: Upper | 1 - 1 | O/O | 35 | 24 | |
| | B1885817 | Harness: DC: Paper Feed: Upper | | | | | |
| B1885813 | | Harness: DC: Registration Sensor | 1 - 1 | O/O | 45 | 19 | |
| | B1885814 | Harness - Registration Sensor | | | | | |
| B1885884 | | Harness: DC: Separation Unit | 1 - 1 | O/O | 47 | 26 | |
| | B1885864 | Harness - DC Separation Unit | | | | | |
| B1885885 | | Harness: DC: Development Unit | 1 - 1 | O/O | 49 | 5 | |
| | B1885865 | Harness: DC: Development Unit: Connect | | | | | |
| B1885882 | | Harness: DC: Paper Exit Unit | 1 - 1 | O/O | 63 | 5 | |
| | B1885863 | Harness - DC Paper Exit Unit | | | | | |

Change: The material of the harness was changed.

Reason: To facilitate assembly at the factory.

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 3-Oct-06 | No.: MB188004 |
| Modified Article: Gear Pulley | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-----------------------|-------|-----|------|-------|------|
| AB017694 | | Gear Pulley:17Z/50T | 1 - 1 | X/O | 43 | 19 | |
| | AB017731 | Pulley: Gear: MM31.83 | | | | | |

Change: The material of the bearing for the gear was changed.

Reason: To ensure that noise does not occur if the bearing is worn down.

| MODEL NAME | V/Hz | DESTINATION | CODE | SERIAL NO. |
|--|----------------|----------------------------|---------|-------------|
| RICOH Aficio 480W Savin 4800WD LANIER LW411 Gestetner A080 | 120/60 | USA, Canada, S. America | B188-17 | K7660200012 |
| RICOH Aficio 480W | 220-240/50, 60 | China | B188-21 | K76603xxxxx |
| RICOH Aficio 480W Nashuatec A080 Gestetner A080 Rex Rotary A080 | 220-240/50, 60 | Europe, Asia, Oceania, etc | B188-27 | K7660200021 |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 3-Oct-06 | No.: MB188005 |
| Modified Article: Operation Sub Unit etc | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------------------|-------|-----|------|-------|------|
| B1881414 | | Operation Sub Unit: NA | 1 - 1 | X/O | 13 | 1 | 2 |
| | B1881471 | Operation Sub Unit: NA: Ass'y | | | | | |
| B1881415 | | Operation Sub Unit: EU | 1 - 1 | X/O | 13 | 1 | 2 |
| | B1881472 | Operation Sub Unit: EU: Ass'y | | | | | |
| B1881416 | | Operation Panel CHN | 1 - 1 | X/O | 13 | 1 | 2 |
| | B1881473 | Operation Sub Unit: CHN: Ass'y | | | | | |
| B1881429 | | LCD: SUB: Unit | 1 - 1 | X/X | 13 | 4 | 1, 2 |
| | B1881435 | LCD: SUB – Ass'y | | | | | |
| B1885085 | | PCB: LCDC: NA: Ass'y | 1 - 1 | X/X | 13 | 15 | 1, 2 |
| | B1885096 | PCB: LCDC: NA | | | | | |
| B1885086 | | PCB: LCDC: EU | 1 - 1 | X/X | 13 | 15 | 1, 2 |
| | B1885097 | PCB: LCDC: EU: Ass'y | | | | | |
| B1885087 | | PCB LCDC | 1 - 1 | X/X | 13 | 15 | 1, 2 |
| | B1885098 | PCB: LCDC: CHN: Ass'y | | | | | |

Change: The materials of the LCD flat cable and LCDC PCB connector were changed.
Reason: To comply with the RoHs Directive.

Important:

- When you install the new PCB: LCDC for the first time, install it with the new LCD **together as a set.**

Note: If you use the old parts with the new parts, a malfunction of the LCD may occur.

Visual difference between the old/new **LCD:**

New LCD: Color of the flat cable end is **Green.**

Old LCD: Color of the flat cable harness end is **Blue.**

- From the following cut-in serial number machines (see the next page), use only new parts. The old parts can be used on old machines.

| MODEL NAME | V/Hz | DESTINATION | CODE | SERIAL NO. |
|--|----------------|----------------------------|---------|-------------|
| RICOH Aficio 480W Savin 4800WD LANIER LW411 Gestetner A080 | 120/60 | USA, Canada, S. America | B188-17 | K7660100001 |
| RICOH Aficio 480W | 220-240/50, 60 | China | B188-21 | K7660100064 |
| RICOH Aficio 480W Nashuatec A080 Gestetner A080 Rex Rotary A080 | 220-240/50, 60 | Europe, Asia, Oceania, etc | B188-27 | K7660100037 |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 21-Sep-07 | No.: MB188006 |
| Modified Article: Stepper Motor | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|----------------------------|-------|-----|------|-------|------|
| AX060295 | B1882869 | Stepper Motor: DC24V 14.8W | 1 - 1 | O/O | 35 | 20 | |

Change: Part number

Reason: Vender change

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 28-Sep-07 | No.: MB188007 |
| Modified Article: Covers | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

Change/ Reason: Vender change

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|------------------------------|-------|-----|------|-------|------|
| B1881304 | B1881317 | Cover: Original: Upper | 1 - 1 | O/O | 9 | 1 | |
| B0101301 | | Original Left Cover | 1 - 1 | O/O | 9 | 12 | |
| | B1881301 | Cover: Original: Left | 1 - 1 | O/O | 9 | 13 | |
| B0101302 | | Original RIGHT Cover | 1 - 1 | O/O | 9 | 17 | |
| | B1881302 | Cover: Original: RIGHT | 1 - 1 | O/O | 9 | 17 | |
| B1886063 | B1886086 | Original Table: Printing | 1 - 1 | O/O | 9 | 17 | |
| B1886453 | B1886454 | Original Table: Printing: NA | 1 - 1 | O/O | 11 | 2 | |
| B0101257 | | Left Upper Cover | 1 - 1 | O/O | 11 | 4 | |
| | B1881257 | Cover: Left Upper | 1 - 1 | O/O | 11 | 18 | |
| B0101258 | | Left Inner Cover | 1 - 1 | O/O | 11 | 19 | |
| | B1881258 | Cover: Inner: Left | 1 - 1 | O/O | 11 | 23 | |
| B1881352 | B1881350 | Cover: Development | 1 - 1 | O/O | 11 | 25 | |
| B0101355 | | Lower Exit Cover | 1 - 1 | O/O | 11 | 26 | |
| | B1881355 | Cover: Exit: Lower | 1 - 1 | O/O | 25 | 5 | |
| B0101351 | | Entrance Cover - Manual Feed | 1 - 1 | O/O | 29 | 1 | |
| | B1881351 | Cover: Manual Feed: Entrance | 1 - 1 | O/O | 31 | 2 | |
| B0101251 | | Right Inner Cover | 1 - 1 | O/O | | | |
| | B1881251 | Cover: Inner: Right | 1 - 1 | O/O | | | |
| B0101250 | | Upper Right Cover | 1 - 1 | O/O | | | |
| | B1881250 | Cover: Right Upper | 1 - 1 | O/O | | | |
| B0101269 | | Front Exit Tray | 2 - 2 | O/O | | | |
| | B1881268 | Tray: Exit: Front | 2 - 2 | O/O | | | |
| B1882930 | B1882934 | Cover: Front | 2 - 2 | O/O | | | |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 2-Oct-07 | No.: MB188008 |
| Modified Article: Switch - AC250/15A | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------|-------|-----|------|-------|------|
| 12042468 | | Switch - AC250/16A | 1 - 1 | O/O | 45 | 109 | |
| | 12042614 | Switch AC250V/16A | | | | | |

Change/ Reason: Due to parts standardization with new model.

| | | | |
|---|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 2-Oct-07 | No.: MB188009 |
| Modified Article: Heat Insulation: Fusing: Front and Rear | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------------------|-------|-----|------|-------|------|
| AA172017 | AA172021 | Heat Insulation: Fusing: Rear | 1 - 1 | O/O | 55 | 25 | |
| B1881121 | B1881127 | Heat Insulation: Fusing: Front | 1 - 1 | O/O | 59 | 8 | |

Change/ Reason: Vender change

Reissued: 12-Oct-07

| | | |
|-------------------|----------------|----------------|
| Model: Dolphin-C2 | Date: 2-Oct-07 | No.: MB188010a |
|-------------------|----------------|----------------|

MB Reissue

The items in ***bold italics*** have been added.

| | | | |
|--|--|------------------------|--|
| Modified Article: Bracket: Main Switch | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|----------------------|-------|-------------------|------------------|-----------------|------|
| B1881274 | B1881294 | Bracket: Main Switch | 1 - 1 | <i>O/O</i> | <i>45</i> | <i>1</i> | |

Change/ Reason: Due to parts standardization with new model.

| | | | |
|--|--|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 4-Oct-07 | No.: MB188011 |
| Modified Article: Coupling Gear - 48Z/27Z | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------------|-------|-----|------|-------|------|
| AB017534 | | Coupling Gear - 48Z/27Z | 1 - 1 | X/O | 65 | 15 | |
| | AB017749 | Gear: Coupling: T48: Z27 | | | | | |

Change: The shape of the gear was changed.

Reason: To further strengthen the teeth of the gear.

| MODEL NAME | V/Hz | DESTINATION | CODE | SERIAL NO. |
|--|----------------|----------------------------|---------|-------------|
| RICOH Aficio 480W Savin 4800WD LANIER LW411 Gestetner A080 | 120/60 | USA, Canada, S. America | B188-17 | K7670100021 |
| RICOH Aficio 480W | 220-240/50, 60 | China | B188-21 | K76702xxxxx |
| RICOH Aficio 480W Nashuatec A080 Gestetner A080 Rex Rotary A080 | 220-240/50, 60 | Europe, Asia, Oceania, etc | B188-27 | K7670100029 |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 14-Dec-07 | No.: MB188012 |
| Modified Article: Hot Roller | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-------------|-------|-----|------|-------|------|
| AE011055 | AE011118 | Hot Roller | 1 - 1 | O/O | 55 | 18 | |

Change: Part number
Reason: Vender change

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 8-Feb-08 | No.: MB188013 |
| Modified Article: Guide Plate: Upper Front | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-------------------------|-------|-----|------|-------|------|
| B1882720 | B1882753 | GUIDE PLATE:UPPER FRONT | 1 - 1 | O/O | 39 | 8 | |
| B3532766 | | PAPER HOLDER BRAKE | 4 - 4 | O/O | 41 | 10 | |
| | B1882666 | BRAKE:PAPER HOLDER | | | | | |
| B1885973 | | BRACKET:POWER PACK | 1 - 1 | O/O | 71 | 20 | |
| | B1885972 | BRACKET:POWER PACK:T/S | | | | | |

Change/ Reason: Due to part standardization with new model.

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 3-Apr-08 | No.: MB188014 |
| Modified Article: Cover: Left Upper | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-------------------|-------|-----|------|-------|------|
| B1881257 | B1881267 | Cover: Left Upper | 1 - 1 | O/O | 11 | 2 | |

Change/Reason: Parts standardization with the new model.

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 3-Apr-08 | No.: MB188015 |
| Modified Article: HDD: EXP: 2PCS/SET | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|--------------------------------|-------|-----|------|-------|------|
| B1885301 | | HDD: EXP: 2PCS/SET | 1 - 1 | X/O | 69 | 9 | |
| | B1885311 | HDD: DOLPHINC2: EXP (2PCS/SET) | | | | | |

Change/Reason: The manufacturer stopped making the old part.

Important: Before you install the new HDD, make sure to update the **System Copy** firmware (B1885736) to **ver 3.0.6 or newer**.

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 25-Sep-08 | No.: MB188016 |
| Modified Article: Parts Catalog | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

Change/ Reason: Due to parts standardization with new model.

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-----------------------------|-------|-----|------|-------|------|
| B1881284 | B1881289 | Inner Cover: Right Upper | 1 – 1 | O/O | 11 | 24 | |
| B1881271 | B1881276 | Inner Cover: Left | 1 – 1 | O/O | 11 | 13 | |
| B1881267 | B1881347 | Cover: Left Upper | 1 – 1 | O/O | 11 | 2 | |
| B1881270 | B1881275 | Inner Cover: Right | 1 – 1 | O/O | 11 | 33 | |
| B1881250 | B1881340 | Cover: Right Upper | 1 - 1 | O/O | 11 | 26 | |
| B0103982 | | Ozone Filter Case | 1 - 1 | O/O | 51 | 12 | |
| | D0463982 | Case: Ozone Filter | | | | | |
| B1883948 | B1883957 | Guide Plate: Transport | 1 - 1 | O/O | 53 | 16 | |
| B0103954 | | Vacuum Duct | 2 - 2 | O/O | 53 | 3 | |
| | D0463954 | Vacuum: Duct | | | | | |
| B1884141 | B1884146 | Fusing Entrance Guide Plate | 1 - 1 | O/O | 57 | 3 | |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 17-Oct-08 | No.: MB188017 |
| Modified Article: Parts Catalog | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

Change/ Reason: Parts catalog correction

| Incorrect part number | Correct part number | Description | Q'ty | Page | Index | Note |
|-----------------------|---------------------|--------------|-------|------|-------|------|
| B1885743 | B1885725 | PCB: TYPE-BZ | 1 - 1 | 69 | 28 | |

| | | | |
|--|---|------------------------|---------------|
| Model: Dolphin-C2 | | Date: 2-Mar-09 | No.: MB188018 |
| Modified Article: Cleaning Blade | | Prepared by: F.Noguchi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety () | | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|----------------|-------|-----|------|-------|------|
| A1653581 | B2863581 | Cleaning Blade | 1 - 1 | O/O | 47 | 10 | |

Change/Reason: The vender of the cleaning blade holder (Aluminum) has been changed.



Part Change Information List

Date: June 30, 2009

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|-------|------|----------|-----------------|-----------------|-----------------|--------------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|--------------------------|----------|---------|
| D-C2 | B188 | 200906 | | B0104085 | | Pressure Roller Holder | 2 | | | | 57 | 9 | | | Y | P/C Index No. correction | | |
| D-C2 | B188 | 200906 | | 52194624 | | Ball Bearing - 20x42x12 | 2 | | | | 57 | 13 | | | Y | P/C Index No. correction | | |
| D-C2 | B188 | 200906 | | B1885709 | | Fan: Dol-C2: Power Supply Unit | 1 | | | | 67 | 20 | | | Y | P/C Index No. correction | | |



Part Change Information List

Date: Jun 30, 2010

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|-------|------|----------|-----------------|-----------------|-----------------|----------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| D-C2 | B188 | 201006 | | 8025291 | 04543006Q | TAPPING SCREW - M3X6 | 1 | 1 | O/O | | 61 | 103 | | | | | V1000295 | |



Part Change Information List

Date: December 28, 2011

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|-------|------|----------|--------------------|--------------------|--------------------|----------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| D-C2 | B188 | 201112 | | B0101358 | D0461358 | TRAY:EXIT:REAR | 1 | 1 | X/O | | 59 | 1 | | | | | V1102449 | |



Part Change Information List

Date: May 31, 2012

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Qty | New Qty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|-------|------|----------|-----------------|-----------------|-----------------|--------------|---------|---------|-----|------|------|-------|-----|---------|-----|------|----------|---------|
| D-C2 | B188 | 201205 | | B1881435 | B1889501 | LCD:SUB-ASSY | 1 | 1 | O/O | | 13 | 4 | | | | | V1200104 | |



Part Change Information List

Date: April 28, 2016

| Model | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|-------|------|-------------|-----------------|-----------------|-----------------|--------------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| D-C2 | B188 | 201604 | | B0101103 | D2061103 | GROUND PLATE:DEVELOPMENT | 1 | 1 | X/O | N | 25 | 7 | | | | | V1600625 | |



Part Change Information List

Date: October 4, 2016

| Model | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|-------|------|-------------|-----------------|-----------------|-----------------|--------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| D-C2 | B188 | 201609 | | B1881094 | D2121094 | BRACKET:HINGE:LEFT | 1 | 1 | O/O | N | 71 | 7 | | | | | V1602387 | 15061312 |



Part Change Information List

Date: January 6, 2017

| Model | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|-------|------|-------------|-----------------|-----------------|-----------------|-----------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| D-C2 | B188 | 201612 | | B1883957 | D2123957 | GUIDE PLATE:TRANSPORT | 1 | 1 | O/O | N | 53 | 16 | | | | | V1602387 | 15061312 |



Part Change Information List

Date: September 1, 2017

| Model | Code | PCIL Number | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref Number | ECN Number |
|-------|------|-------------|-----------------|-----------------|-----------------|--------------------|----------|----------|-----|------|------|-------|-----|---------|-----|------|------------|------------|
| D-C2 | B188 | 201707 | | 11071110 | | FUSE - SLT 6.3 | 1 | 0 | X/O | N | 80 | 110 | | | | | V1700936 | |
| D-C2 | B188 | 201707 | | 14000754 | | TRANSISTOR - UMG1N | 1 | 0 | X/O | N | 80 | 113 | | | | | V1700936 | |