

Reissued: 03-Oct-11

Model: GW-C4/K-C3.5L(18CPM)/K-C3.5L	Date: 09-Feb-11	No.: RB244001b
-------------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: GDI Basic		Prepared by: M. Saiki	
From: MFP/Printer Tech Service Dept., 2nd Tech Service Sect.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **GDI Basic**.

Version	Program No.	Effective Date	Availability of RFU
<i>1.03</i>	<i>B8655520B</i>	<i>October 2011 production</i>	<i>Not available</i>
1.02	B8655520A	May 2011 production	Not available
1.00	B8655520	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<i>1.03</i>	<i>Symptom Corrected: Printing job speed reduces in the duplex print mode.</i>
1.02	Supports the K-C3.5L Asia 18 CPM model.
1.00	1st Mass production

Model: K-C3.5L(18CPM)	Date: 12-May-11	No.: RB244002
-----------------------	-----------------	---------------

Subject: Firmware Release Note: BICU_IC		Prepared by: M.Saiki	
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **BICU_IC**

Version	Program No.	Effective Date	Availability of RFU
B003M003	B2765532- B2765542	1st Mass production	Not Available

Note: Definition of Availability of RFU

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
B003M003	1st Mass production

Model: K-C3.5L(18CPM)	Date: 12-May-11	No.: RB244003
-----------------------	-----------------	---------------

Subject: Firmware Release Note: BICU_SD		Prepared by: M.Saiki	
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **BICU_SD**

Version	Program No.	Effective Date	Availability of RFU
0.03:06	B2765542	1st Mass production	Available

Note: Definition of Availability of RFU

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
0.03:06	1st Mass production


Model: K-C3.5L		Date: 08-Nov-11	No.: RB244004
Subject: Parts Catalog Correction_Sheet-Operation Panel		Prepared by: M.Saiki	
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B2441473	SHEET:OPERATION PANEL:CHN			13	16	

Change/Reason: The part number was missing from the parts catalog.

See the following diagram for the corrected part.

3.OPERATION PANEL



Model: K-C3.5L		Date: 13-Mar-12	No.: RB244005
Subject: Parts Catalog Correction_PCU Ass'y		Prepared by: M.Saiki	
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other () <input type="checkbox"/> Tier 2		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2831876	B2592210	PCU – Ass'y	1-1		35	*	

Change/Reason: Incorrect part number and the description.