

| | | | |
|---|---|----------------------|---------------|
| Model: K-C3.1a | | Date: 03-Dec-09 | No.: RD096001 |
| Subject: ROM History for BICU for K-C3.1a | | Prepared by: M.Saiki | |
| From: 2nd Overseas Tech Support Sec., 2nd PQM Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input checked="" type="checkbox"/> Other (Firmware) <input checked="" type="checkbox"/> Tier 2 | | |

We hereby inform you of the BICU firmware history for the K-C3.1a.

Note:

Kir-C3.1a: 19cpm simplex machine

For USA/Europe model

| Version | Program No. | Effective Date |
|---------|-------------|---------------------|
| 0.02 | D0965531 | 1st mass production |

| Version | Symptom Corrected |
|---------|---------------------|
| 0.02 | 1st mass production |

For Asia/Taiwan model

| Version | Program No. | Effective Date |
|---------|-------------|---------------------|
| 0.02 | D0965533 | 1st mass production |

| Version | Symptom Corrected |
|---------|---------------------|
| 0.02 | 1st mass production |

| | | | |
|---|---|---|---|
| Model: K-C3.1a | | Date: 24-Feb-10 | No.: RD096002 |
| Subject: Service Manual Correction_SSP mode | | Prepared by: Masato Saiki | |
| From: 2nd Overseas Tech Support Sec., 2nd PQM Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2 |

The following description has been deleted from the Model K-C3.1a Field Service Manual:

- SSP: The program is in the SSP Mode only. Consult your supervisor before you use this program.

This model does not have an SSP mode. The SSP codes listed in the Field Service Manual can be found in the normal SP mode.

| | | | |
|---|---|--|--|
| Model: K-C3.1a | | Date: 18-Jun-10 | No.: RD096003 |
| Subject: Parts Catalog Correction_OP_Case_K-C3.1a | | Prepared by: M.Saiki | |
| From: 2nd Overseas Tech Support Sec., 2nd PQM Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other () | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2 |

| Incorrect part number | Correct part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------------|---------------------|-------------------------|-------|-----|------|-------|------|
| | B2431451 | CASE:OPERATION SUB-UNIT | 0 - 1 | | 9 | #17 | |

#: New index

Change: An index in the illustration was added.

Reason: Correction of illustration and part number.

See the following diagram for the corrected illustration.

