

=====
*** Basic Information ***
=====

[Create date] 2018/04/17

[Program Name] Scanner

[Version] 02.03

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D1155521C

[File Information]

File Name D1155521C.fwu

File Type Module for Service

Size 0.94 MB (982360 byte)

[File Information]

File Name D1155521C.rfu

File Type Module for Remote Upgrade

Size 0.94 MB (987392 byte)

[Availability of RFU] Yes

[Production reflection] 2018/04

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Other changes:

Newly added SMBv2/v3 support.

This firmware is dependent on the following firmware modules.

Please be sure to update all of them:

- Network Support v9.08 (D0675526G)
- Web Support v1.01 (D1155526A)
- Scanner v02.03 (D1155521C)

Please refer to the RTB(No.RGene095) for details.

[Modification history]

Version 02.02

Symptom corrected:

The operational panel suddenly shuts off and hangs, and the condition cannot be cleared without rebooting the machine.

Version 02.01

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2018/04/17

[Program Name] Web Support

[Version] 1.01

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D1155526A

[File Information]

File Name D1155526A.fwu

File Type Module for Service

Size 3.11 MB (3260172 byte)

[File Information]

File Name D1155526A.rfu

File Type Module for Remote Upgrade

Size 3.11 MB (3264768 byte)

[Availability of RFU] Yes

[Production reflection] 2018/04

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Other changes:

- Newly added SMBv2/v3 support.

This firmware is dependent on the following firmware modules.

Please be sure to update all of them:

- Network Support v9.08 (D0675526G)

- Web Support v1.01 (D1155526A)

- Scanner v02.03 (D1155521C)

Please refer to the RTB(No.RGene095) for details.

[Modification history]

Version 1.00.2

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2018/04/27

[Program Name] System/Copy

[Version] 1.09

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D1155532B

[File Information]

File Name D1155532B.fwu

File Type Module for Service

Size 16.70 MB (17507356 byte)

[File Information]

File Name D1155532B.rfu

File Type Module for Remote Upgrade

Size 16.70 MB (17514752 byte)

[Availability of RFU] Yes

[Production reflection] 2018/04

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Other changes:

- Newly added SMBv2/v3 support.

This firmware is dependent on the following firmware modules.

Please be sure to update all of them:

- System/Copy v1.09 (D1155532B)
- Network Support v9.08 (D0675526G)
- Web Support v1.01 (D1155526A)
- Scanner v02.03 (D1155521C)

Please refer to the RTB(No.RGene095) for details.

[Modification history]

Version 1.08

Symptom corrected:

[Embedded RC Gate]: @Remote auto calls (Ex. service calls, supply calls, alarm calls) are not sent from the device if engine-related SC errors occur frequently within a short period of time.

Version 1.07

Other changes:

This firmware was modified to support a new TPM chip on the controller board, as production of the current chip was discontinued.

IMPORTANT: Once you have installed this version, v1.07, DO NOT DOWNGRADE the System/Copy firmware.

Version 1.06

Symptom corrected:

1. Cannot communicate with the @Remote Center if embedded RC Gate is enabled.
2. Although the "Logout Using Card" function of Card Authentication Package v2 is turned on, the user cannot log out when he or she swipes the card.
3. Cannot scan to shared folders in Mac OS X 10.7 or Mac OS X 10.8.

This firmware is dependent on the following firmware modules.

Please be sure to update all of them:

Network Support firmware v9.07 or later

Version 1.05

Symptom corrected:

1. The timer used for the "Access Violation" setting's time interval does not properly compensate for changes to the device timer.
2. If User Code authentication is enabled or if "External Optional Counter Type" != 0, accounts locked by the "Lock out" setting (SP-5413-1) are not locked out of WIM.
3. If the "External Optional Counter Type" setting (SP-5113-002) is not equal to '0', the following problems might occur:
 - Print jobs result in the Data-In LED blinking but nothing is output.
 - Fax jobs are printed successfully but not counted by the counter.
4. The MFP operation panel might go black and not return until the power is cycled. This only occurred if the MFP had a Device Accounting Unit such as a coin collector or charge card reader.
5. After several alternations between Energy Saving mode and Ready mode, the submission of a job to the MFP might cause it to freeze.
6. SC870 may occur while the user is editing the Address Book via WIM if the machine has entered/recovered from Energy Saver mode since the power switch was last turned on.

Version 1.04

Symptom corrected:

SC870 is triggered and cannot be cleared if the main power switch is turned off while data is being written to the Address Book.

Version 1.03

1st Mass production