

# Technical Bulletin

PAGE: 1/1

|  |   |  |  |
|--|---|--|--|
| Model: Brz-P1 HDD option                               |   | Date: 22-Feb-19  | No.: RM500001  |
| Subject: Parts information for HDD option              |   | Prepared by: T. Tachibana  |  |
| From: 1st Tech Service Sect., MFP/P Tech Service Dept. |   |  |  |
| Classification:  | <input type="checkbox"/> Troubleshooting<br><input type="checkbox"/> Mechanical<br><input type="checkbox"/> Paper path<br><input type="checkbox"/> Product Safety | <input checked="" type="checkbox"/> Part information<br><input type="checkbox"/> Electrical<br><input type="checkbox"/> Transmit/receive<br><input type="checkbox"/> Other (     ) | <input type="checkbox"/> Action required<br><input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Tier 2 |

| Old part number | New part number | Description        | Q'ty | Int | Page | Index | Note         |
|-----------------|-----------------|--------------------|------|-----|------|-------|--------------|
| D1365714        | D0BW5527        | CABLE:HDD:SATA:150 | 1-1  | X/X | 2    | 12    | O/O as a set |
| M5005562        | M5005563        | BRACKET:HDD        | 1-1  | O/O | 2    | 14    |              |

**Change:** The HDD cable has been made thicker, and the hole to pass the cable through has been widened.

**Reason:** Compatibility with the successor model.

**Note:** When replacing the HDD cable, the HDD bracket needs to be replaced at the same time.