

MODIFICATION BULLETIN NO. K200-046

ISSUED ON 18th, June, 1992

Model	FAX7000, FAX7000L, Infotec 6765/6865/6866					Date of Modification	
Modified Article	Quick Dial Cover					Expected Date	
Reason for Modification	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					Effective from June.	
						Execution Date	
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
FAX7000							
	H0084563	Quick Dial Cover				64	1-3
FAX7000L							
	H0084563	Quick Dial Cover				62	1-3
Infotec 6765/6865/6866							
	H0084594	Quick Dial Cover: H				62	1-3

Reference No. for this MB

QECR	
ECN No.	92040045

H.Motojima
Assistant General Manager
FTS Sect. TS Dept.

MODIFICATION BULLETIN NO. K200-047ISSUED ON 18th, June, 1992

Model	FAX7000, FAX7000L, Infotec 6765/6865/6866			Date of Modification	
Modified Article	SPU FAN			Expected Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other			After the old parts have become out of stock.	
				Execution Date	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0085215	H3035228	PSU FAN	1 → 1	O / O		2	1-19

Reference No. for this MB

QECR	
ECN No.	92050075

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

MODIFICATION BULLETIN NO.K200-048

ISSUED ON Mar. 15, 1995

Model		Fax 7000L				Date of Modification	
Modified Article		HD Fan				Execution Date	
Reason for Modification		<div><input type="checkbox"/> Parts catalog correction</div> <div><input checked="" type="checkbox"/> Vender change</div> <div><input type="checkbox"/> To meet standards ()</div> <div><input type="checkbox"/> Part standardization</div> <div><input type="checkbox"/> To facilitate assembly</div> <div><input type="checkbox"/> To improve reliability</div> <div><input type="checkbox"/> Other</div>				From the old parts have become out of stock.	
Old Part No.	New Part No.	Description	Q'ty Used Old ↔ New	Interchange-ability	Remarks	Parts Catalog	
						Index No.	Page
H0085238	H0085249	HD Fan	1 ↔ 1	O / O		84	1-23
<div>S.Hamano Assistant General Manager 2nd T.S.Sec. Int'l Marketing Group</div>							

REISSUED ON: Jul. 15, 1995**MODIFICATION BULLETIN NO. K200-049**ISSUED ON May 15, 1995

Model	K200	Date of Modification
Modified Article	Hard Disk Unit	Execution Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vender change <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0085250	H0089020	Hard Disk Unit	1 → 1	O / O		20	23

M. Iwasa
 Manager
 2nd T.S.Sec. Int'l Marketing Group

RE-ISSUED ON Mar.15,1995ISSUED ON Feb.15, 1995MODIFICATION BULLETIN NO. Multi-001

Model	CSO, CFO, CS1, CRO, CGO, K200, AFO (Ricoh brand for North America)					Date of Modification	
Modified Article						Execution Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					From the old part has become out of stock.	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0534808	H5134107	Handset Ass'y	1 → 1	O / O			
(H0534809)	(H5134157)	Handset Table - Upper	(1 → 1)	(O / O)			
(H0535214)	(H5135128)	Handset	(1 → 1)	(O / O)			
	(H1608600)	Installation Manual	(0 → 1)				

S.Hamano
 Assistant General Manager
 2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO. Multi-002ISSUED ON Oct. 15, 1995

Model	US: Fax2800L, 4000L, 7000L, 77, 80, 85, 86, 550 China: Fax3000L, 580					Date of Modification	
Modified Article	Handset					Execution Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other						
Handset and Handset Holder will not be available. Please order Handset Ass'y instead of these.							
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H5134157	H5134107	Handset Holder - US	1 → 0				
H5135128		Handset - US	1 → 0				
		Handset Ass'y - US					
H5134155	H5134105	Handset Holder - China	1 → 0				
H5135126		Handset - China	1 → 0				
		Handset Ass'y - China					
<div style="text-align: right;"> M. Iwasa Manager 2nd T.S.Sec. Int'l Marketing Group </div>							

MODIFICATION BULLETIN NO. Multi - 007

ISSUED ON Sep.15, 1996

Model	K100, K105, K200 (Ricoh and OEM)			Modification Schedule		
Modified Article	Main Switch			After the old part is out of stock.		
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H006 5223	H004 5209	Main Switch	1 - 1	O / O			

S.Fujii
 General Manager
 2nd Field Information Department
 QA Division

Prepared by Y.Okunishi

RC	RE	ASIA	
----	----	------	--

Model: K100, K105, K200		Date: 31-Jul-97	No: Multi - 008
Modified Article: Main Switch		Prepared by: Y.Okunishi	
From: QAC 2nd Field Information Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> To meet standards <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability () <input type="checkbox"/> Part Standardization <input type="checkbox"/> Other		
Modification Schedule	After the old part is out of stock.		

Old part number	New part number	Description	Qty	Int	Page	Index	Note
H006 5223	H004 5209	Main Switch	1 - 1	O/O			

RC	RE	ASIA	

Model: FAX,7000L, Infotec 6765/6865/6866		Date: 30Nov98	No.: 051
Modified Article: SPU Fan		Prepared by: Y.Okunishi	
From: GTSS Field Information Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Old part number	New part number	Description	Qty	Int	Page	Index	Note
H303 5228	H303 5230	SPU Fan	1	O/O	1 – 19	2	

RC	REBV	ASIA	
*	*	*	

Modification Bulletin

PAGE: 1/2

Model: K200 (FAX7000L)		Date: 31-Dec-99	No.: MH008052
Modified Article: Firmware change		Prepared by: Y. Okunishi	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()
Modification Schedule	Spare parts: Shipment in December 1999 (No more production of the machine)		

Firmware will be modified to correct the following bugs.

- 1) A Telephone Charge Control Report (TEL Charge Report), on which the following is printed, is output once a month (one page).

- Sample for English version -

*** TEL. Charge Report/Department Code (••Mar. '00 00:00) ***

1)TTI •1.Mar. '00 •1.Mar.'00•

Dept. code	Dept.	TX No.	RX No.	Tel.Charge
0001	ABCDEF	10	0	0
Total				0

Note:

Originally, only the German version FAX7000L had this report. But the default setting was set to off. (SCU SW10 bit 0: 1= enable)

This report appears on the latest version of the ROMs not only for Germany, but also for other countries.

- 2) After the HD is formatted, the machine will not output the TEL Charge Report even in the German version of the machine and even after the SW for the TEL Charge Report is turned on.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
H0086030K	H0086030L	PCB – MBU – USA	1	X/O	1-19	24	
H0087260J-7J	H0087260K-7K	P.ROM – USA	(8)				
H0086031G	H0086031H	PCB – MBU – GMN	1	X/O	1-19	24	
H0087270F-7F	H0087270G-7G	P.ROM – GMN	(8)				
H0086036G	H0086036H	PCB – MBU – GMN – Info.	1	X/O	1-19	24	
H0087320F-7F	H0087320G-7G	P.ROM – GMN – Info.	(8)				
H0086032J	H0086032K	PCB – MBU – ENG	1	X/O	1-19	24	

Modification Bulletin

PAGE: 2/2

Model: K200 (FAX7000L)

Date: 31-Dec-99

No.: MH008052

H0087280H-7H	H0087280J-7J	P.ROM – ENG	(8)				
H0086037J	H0086037K	PCB – MBU – ENG – Info.	1	X/O	1-19	24	
H0087330H-7H	H0087330J-7J	P.ROM – ENG – Info.	(8)				
H0086033D	H0086033E	PCB – MBU – ITY	1	X/O	1-19	24	
H0087290C-7C	H0087290D-7D	P.ROM – ITY	(8)				
H0086038D	H0086038E	PCB – MBU – ITY– Info.	1	X/O	1-19	24	
H008740C-7C	H008740D-7D	P.ROM – ITY – Info.	(8)				
H0086034F	H0086034G	PCB – MBU – FRN	1	X/O	1-19	24	
H0087300E-7E	H0087300F-7F	P.ROM – FRN	(8)				
H0086039F	H0086039G	PCB – MBU – FRN – Info.	1	X/O	1-19	24	
H0087350E-7E	H0087350F-7F	P.ROM – FRN – Info.	(8)				
H0086035J	H0086035K	PCB – MBU – UNV	1	X/O	1-19	24	
H0087310H-7H	H0087310J-7J	P.ROM – UNV	(8)				
H0086040J	H0086040K	PCB – MBU – UNV– Info.	1	X/O	1-19	24	
H0087360H-7H	H0087360J-7J	P.ROM – UNV – Info.	(8)				

RC	REBV	ASIA	
*	*	*	