

E9100780

MODIFICATION BULLETIN NO. C-056

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, FAX 1040/1045	Date of Modification
Modified Article	PCB Ass'y - SBU	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		Effective from the 1st. production of July.
The PCB Ass'y-SBU has been changed to standardize capacitors with other models.		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0536022B	H0536022C	PCB Ass'y - SBU	1-1	O/O		69	2

Reference No. for this MB

QECR	
ECN No.	91060120

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9000830

MODIFICATION BULLETIN NO. C-057

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85, infotec 6212/6213/6215, NASHUA 1040/1045					Date of Modification					
Modified Article	Spring - Friction					Expected Date					
Reason for Modification	<div><input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other</div> Parts catalog correction.					Execution Date					
						Effective from the 1st. production.					
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0531582	H0531557A	Spring - Friction : Separation Roller	1-1	X/O		19	2				
(Asia, Europe only)											
Reference No. for this MB											
<table border="1"><tr><td>QECR</td><td></td></tr><tr><td>ECN No.</td><td>90030131</td></tr></table>								QECR		ECN No.	90030131
QECR											
ECN No.	90030131										
<div>H.Motojima Assistant General Manager FTS Sect. TS Dept.</div>											

E9100777

MODIFICATION BULLETIN NO. C-058

1/2

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85/82, SAVINFAX 301/331, infotec 6212/6213/6215, NASHUA FAX 1040/1045	Date of Modification
Modified Article	Stepped Screw : Printer	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		Effective from the 1st. production of August.


Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0532123A	H0532213	Stepped Screw - M4 : Printer	1-1	X/O		28	1
--	07110040B	Hexagonal Nut - M4	0-1				

Reference No. for this MB

QECR	
ECN No.	91060072 91060081 91060082

H.Motojima

Assistant General Manager

DETAILS OF MODIFICATION

E9100914

MODIFICATION BULLETIN NO. C-059

1/4

ISSUED ON Apr. 22,1992

Model	FAX 77/80/85/82, infotec 6212/6213/6215, NASHUA FAX 1040/1045, SAVINFAX 301/331					Date of Modification					
Modified Article	PCB Ass'y - FCU					Expected Date					
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input checked="" type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					After the old parts are out of stock.					
	The suffix of the PCB Ass'y - FCU has been changed. The following parts can be supplied from a 2nd. vender. EPROM, SRAM, DRM.					Execution Date					
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
		(FAX 77, infotec 6212)									
H0516007N	H0516007P	PCB Ass'y - FCU : G	1-1	O/O		44	3				
H0517107F	H0517107G	IC - PROM : G	(1-1)								
H0516008M	H0516008N	PCB Ass'y - FCU : UK	1-1	O/O		44	3				
H0517108E	H0517108F	IC - PROM : UK	(1-1)								
H0516009N	H0516009P	PCB Ass'y - FCU : I	1-1	O/O		44	3				
H0517109F	H0517109G	IC - PROM : I	(1-1)								
<p>Reference No. for this MB</p> <table border="1"> <tr> <td>QECR</td> <td></td> </tr> <tr> <td>ECN No.</td> <td>91060160</td> </tr> </table> <p>H.Motojima Assistant General Manager FTS Sect. TS Dept.</p>								QECR		ECN No.	91060160
QECR											
ECN No.	91060160										

Old Parts No.	New Parts No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0516010M	H0516010N	PCB Ass'y - FCU : UN1	1-1	O/O		44	3
H0517110D	H0517110F	IC- PROM : UN1	(1-1)				
H0516014N	H0516014P	PCB - Ass'y - FCU : UN2	1-1	O/O		44	3
H0516011M	H0516011N	PCB Ass'y - FCU : ASIA	1-1	O/O		44	3
H0517111E	H0517111F	IC - PROM : ASIA	(1-1)				
		(FAX80, S-301, i-6213, N-1040)					
H0536006Y	H0536006Z	PCB Ass'y - FCU : RC	1-1	O/O		44	3
H0537006J	H0537006K	IC - PROM : RC	(1-1)				
H0536016Q	H0536016R	PCB Ass'y - FCU : SAVIN	1-1	O/O		44	3
H0537116G	H0537116H	IC - PROM : SAVIN	(1-1)				
H0536007Y	H0536007Z	PCB Ass'y - FCU : G	1-1	O/O		44	3
H0537107K	H0537107L	IC - PROM : G	(1-1)				
H0536008X	H0536008Y	PCB Ass'y - FCU : UK	1-1	O/O		44	3
H0537108J	H0537108K	IC - PROM : UK	(1-1)				
H0536009X	H0536009Y	PCB Ass'y - FCU : I	1-1	O/O		44	3
H0537109J	H0537109K	IC - PROM : I	(1-1)				
H0536010W	H0536010X	PCB Ass'y - FCU : UN1	1-1	O/O		44	3
H0537110H	H0537110J	IC - PROM : UN1	(1-1)				

Old Parts No.	New Parts No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0536014T	H0536014V	PCB Ass'y - FCU : UN2	1-1	O/O		44	3
H0536011X	H0536011Y	PCB Ass'y - FCU : ASIA/NASHUA	1-1	O/O		44	3
H0537111J	H0537111K	IC - PROM : ASIA/NASHUA	(1-1)				
		(FAX 85, S-331, i-6215, N-1045)					
H0556006V	H0556006W	PCB Ass'y - FCU : RC	1-1	O/O		44	3
H0557106H	H0557106J	IC - PROM : RC	(1-1)				
H0556016Q	H0556016R	PCB Ass'y - FCU : SAVIN	1-1	O/O		44	3
H0557116G	H0557116H	IC - PROM : SAVIN	(1-1)				
H0556007Y	H0556007Z	PCB Ass'y - FCU : G	1-1	O/O		44	3
H0557107L	H0557107M	IC - PROM : G	(1-1)				
H0556008X	H0556008Y	PCB Ass'y - FCU : UK	1-1	O/O		44	3
H0557108K	H0556008L	IC - PROM : UK	(1-1)				
H0556009X	H0556009Y	PCB Ass'y - FCU : I	1-1	O/O		44	3
H0557109K	H0557109L	IC - PROM : I	(1-1)				
H0556010W	H0556010X	PCB Ass'y - FCU : UN1	1-1	O/O		44	3
H0557110J	H0557110K	IC - PROM : UN1	(1-1)				
H0556014R	H0556014S	PCB Ass'y - FCU : UN2	1-1	O/O		44	3

MODIFICATION BULLETIN NO. C-059

4/4

ISSUED ON Apr. 22, 1992

[illegible]

E9100776

MODIFICATION BULLETIN NO. C-060

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85, infotec 6212/6213/6215	Date of Modification
Modified Article	PSU Ass'y	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		Effective form the 1st. production of March, '91.
<p>The PSU Ass'y has contained some weak parts in the lower range of the specified rate against a surging high voltage under certain conditions. The parts are broken when the power switch is turned on if the temperature is high and the capacitors in the PSU have discharged fully. Some parts have been changed to higher rated ones.</p>		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange-ability	Remarks	Parts Catalog	
						Index No.	Page
H0535052A	H0535052B	PSU Ass'y - Europe : 220V	1-1	X/O		43	3
H0537156	H0537178	Diode - ESAD92 - 03	(1-1)				
H0537157	H0537177	Transistor - 2SK962 - 01 : MOSFET	(1-1)				

(Europe only)

Reference No. for this MB

QECR	C - 004
ECN No.	91060096

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100775

MODIFICATION BULLETIN NO. C-061

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85/82, NASHUA FAX 1040/1045	Date of Modification
Modified Article	PSU Ass'y	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		Effective form the 1st. production of March, '91.

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange-ability	Remarks	Parts Catalog	
						Index No.	Page
H0535053A	H0535053B	PSU Ass'y - ASIA : 220V	1-1	X/O		43	3
H0537156	H0537178	Diode - ESAD92 - 03	(1-1)				
H0537157	H0537177	Transistor - 2SK962 - 01 : MOSFET	(1-1)				

(Asia only)

Reference No. for this MB

QECR	
ECN No.	91060095

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100778

MODIFICATION BULLETIN NO. C-062

1/1

ISSUED ON Apr. 22, 1992

Model	FA 77/80/85					Date of Modification					
Modified Article	Allen key and screws					Expected Date					
Reason for Modification	<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change </div> <div> <input type="checkbox"/> To meet standards () <input checked="" type="checkbox"/> Part standardization </div> <div> <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other </div> </div> <p>The accessories have been changed. The allen key and screws are special tools. The screws for the sub document tray have been changed to normal screws.</p>					Execution Date					
						Effective form the 1st. production of July.					
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0334806		Allen key	1-0			*	1				
08046097	09513006B	Allen screw	2-2			45	1				
<div style="display: flex; justify-content: space-between;"> <div>(Asia, Europe only)</div> <div> Reference No. for this MB <table border="1" style="margin-top: 10px;"> <tr><td style="padding: 2px;">QECR</td><td style="padding: 2px;"> </td></tr> <tr><td style="padding: 2px;">ECN No.</td><td style="padding: 2px;">91060079</td></tr> </table> </div> <div> H.Motojima Assistant General Manager FTS Sect. TS Dept. </div> </div>								QECR		ECN No.	91060079
QECR											
ECN No.	91060079										

E9100781

MODIFICATION BULLETIN NO. C-063

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 82	Date of Modification									
Modified Article	Stamper Ass'y						Expected Date				
Reason for Modification	<div><input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other</div> <p>The vender of the stamper ass'y has been changed. A stamper kit has been made in order to change the stamper surface easily.</p>						Execution Date				
							Effective from the 1st. production of August.				
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
H0545032B	H0545033	Stamper Ass'y	1-1	X/O		Index No.	Page				
	H0724833	Stamper Kit	0 -1								
(Asia only)											
Reference No. for this MB											
<table border="1"><tr><td>QECR</td><td></td></tr><tr><td>ECN No.</td><td>91060074</td></tr></table>								QECR		ECN No.	91060074
QECR											
ECN No.	91060074										
<div>H.Motojima Assistant General Manager FTS Sect. TS Dept.</div>											

E9100916

MODIFICATION BULLETIN NO. C-064

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 82					Date of Modification	
Modified Article	Cutter Ass'y					Expected Date	
Reason for Modification	<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change </div> <div> <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization </div> <div> <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other </div> </div> <p>To prevent paper jam, a piece of mylar has been attached to the upper blade of the cutter ass'y.</p>					Execution Date	
						Effective from the 1st. production of July.	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0542118G	H0542156	Cutter Ass'y - B4	1-1	X/O		11	3
	H0542155	Sheet - Cutter	(0-1)				

(Asia only)

Reference No. for this MB

QECR	
ECN No.	91070022

H.Motojima

 Assistant General Manager

 FTS Sect. TS Dept.

E9100918

MODIFICATION BULLETIN NO. C-065

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85/86, infotec 6212/6213/6215, SAVIN FAX 301/331	Date of Modification
Modified Article	Cutter Ass'y	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		Effective from the 1st. production of July.
To prevent paper jam, a piece of mylar has been attached to the upper blade of the cutter ass'y.		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0532161D	H0532161E	Cutter Ass'y - A4	1-1	X/O		11	3
	H0532214	Sheet - Cutter	(0-1)				

(North America, Europe only)

Reference No. for this MB

QECR	
ECN No.	91070021

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100917

MODIFICATION BULLETIN NO. C-066

1/1

ISSUED ON Apr. 22, 1992

Model	FAX 77/80/85, NASHUA FAX 1040/1045					Date of Modification					
Modified Article	Cutter Ass'y					Expected Date					
Reason for Modification	<div><input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other</div> <p>To prevent paper jam, a piece of mylar has been attached to the upper blade of the cutter ass'y.</p>					Execution Date					
						Effective from the 1st. production of July.					
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0532150C	H0532150D	Cutter Ass'y - A4	1-1	X/O		11	3				
	H0532215	Sheet - Cutter	(0-1)								
(Asia only)											
Reference No. for this MB											
<table border="1"><tr><td>QECR</td><td></td></tr><tr><td>ECN No.</td><td>91070253</td></tr></table>								QECR		ECN No.	91070253
QECR											
ECN No.	91070253										
<div>H.Motojima Assistant General Manager FTS Sect. TS Dept.</div>											

E9100912, E9101192


MODIFICATION BULLETIN NO. C-067

1/2

ISSUED ON Apr. 22, 1992

Model	FAX 82					Date of Modification					
Modified Article	Sensor Cover - Feed-out					Expected Date					
Reason for Modification	<div style="display: flex; justify-content: space-between;"> <div> <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change </div> <div> <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization </div> <div> <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other </div> </div> <p>To prevent paper jam, the sensor cover has been changed. When the copy tray is installed, the sensor cover is pushed up by the tray. Then a paper jam might occur.</p>					Execution Date					
						Effective from the 1st. production of August.					
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0542102G	H0542157	Sensor Cover - Feed-out	1-1	X/O							
	H0542158	Spacer - Copy Tray	0 -1								
<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="width: 30%;"> <p>(Asia only)</p> </div> <div style="width: 30%; text-align: center;"> <p>Reference No. for this MB</p> <table border="1" style="margin: auto;"> <tr><td style="padding: 2px;">QECR</td><td style="padding: 2px;"> </td></tr> <tr><td style="padding: 2px;">ECN No.</td><td style="padding: 2px;">91070049 91090017</td></tr> </table> </div> <div style="width: 30%; text-align: right;"> <p>H.Motojima</p> <p>Assistant General Manager</p> </div> </div>								QECR		ECN No.	91070049 91090017
QECR											
ECN No.	91070049 91090017										

DETAILS OF MODIFICATION



E9100911

MODIFICATION BULLETIN NO. C-068

1/1

ISSUED ON Apr. 22, 1992

Model	FAX /77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	Holder - Feed-out Roller	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	From the 1st production of August.
		Execution Date

When a page was printed out, the leading edge of the paper occasionally touched the hook (1) for supporting the feed-out roller. So, the hook position has been changed to the opposite side (2).

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0532203	H0842133	Holder - Feed-out Roller : Rear	1-1	X/O		93	2
H0532145A	H0532134	Holder - Feed-out Roller : Front	1-1	X/O		94	2

Reference No. for this MB

QECR	
ECN No.	91070085

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100922

MODIFICATION BULLETIN NO. C-070ISSUED ON May 1st, 1992

Model	FAX77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	Spring-Locking	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	After the old parts are out of stock.
		Execution Date
We have changed the part number of the ADF locking springs for part standardization with new products		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0531554	H0841511	Spring-Locking: Front	1 - 1	O / O		40	2
H0531555	H0841512	Spring-Locking: Rear	1 - 1	O / O		42	2

Reference No. for this MB

QECR	
ECN No.	91070169

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100923

MODIFICATION BULLETIN NO. C-071

1/1

ISSUED ON Apr. 22, 1992

Model	FAX77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX1040/1045	Date of Modification
Modified Article	Disk - Friction : Separation Roller	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		From the 1st. production of August.

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0531581	H0531603	Disk - Friction : Separation Roller	2-2	O/O		17	2

Reference No. for this MB

QECR	
ECN No.	91070202

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9100966

MODIFICATION BULLETIN NO. C-072ISSUED ON May 7th, 1992

Model	FAX 77/80/85/86						Date of Modification				
Modified Article	Upper Cover Ass'y						Expected Date				
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other						From the 1st, production of August.				
	A rubber damper has been added to the upper cover in order to prevent skewing of the original document. Before adding the damper, the space for documents was wider than letter size.						Execution Date				
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
--	H0533232	Rubber spacer - Upper cover	0 - 1								
(North America only)											
Reference No. for this MB											
<table border="1"> <tr> <td>QECR</td> <td></td> </tr> <tr> <td>ECN No.</td> <td>91070245</td> </tr> </table>								QECR		ECN No.	91070245
QECR											
ECN No.	91070245										
<div style="text-align: right;"> H.Motojima Assistant General Manager FTS Sect. TS Dept. </div>											

E9101189

MODIFICATION BULLETIN NO. C-073

ISSUED ON May 7th, 1992

Model	FAX 77/80/85, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045						Date of Modification				
Modified Article	R1 and R2 Rollers						Expected Date				
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other <p>The R1 roller and R2 roller have been changed for improving the framing error of copies and part standardization with new models. Since this is a modification in combination, both rollers have to be replaced when it is necessary to replace one of them.</p>						From the 1st production of October.				
							Execution Date				
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0531130	H0841107	R1 Roller	1 - 1	O / O		84	2				
H0531131	H0531187	R2 Roller	1 - 1	O / O		85	2				
Reference No. for this MB											
<div style="display: flex; justify-content: space-between;"> <table border="1" style="border-collapse: collapse;"> <tr><td style="padding: 5px;">QECR</td><td style="width: 50px;"></td></tr> <tr><td style="padding: 5px;">ECN No.</td><td style="padding: 5px;">91080153</td></tr> </table> <div style="text-align: right;"> H.Motojima Assistant General Manager FTS Sect. TS Dept. </div> </div>								QECR		ECN No.	91080153
QECR											
ECN No.	91080153										

E9101190

MODIFICATION BULLETIN NO. C-074ISSUED ON May 7th, 1992

Model	FAX 77/80/85, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	ADF unit	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	From the 1st production of October.
		Execution Date

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0531584	H0841503	Guide Plate - ADF: Lower	1 - 1	O / O		31	2
--	H0841520	Document rail	0 - 1				
H0531502D	H0841515	Bracket - Pick up Roller	1 - 1	O / O		24	2
H0531507C	H0841518	Shaft - Feed Roller	1 - 1	O / O		25	2
--	54472681A	Snap Ring	0 - 2				

Reference No. for this MB

QECR	
ECN No.	91080178

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9101197

MODIFICATION BULLETIN NO. C-075ISSUED ON May 7th, 1992

Model	FAX77/80/85/82, infotec 6212/6213/6215, NASHUA FAX 1040/1045					Date of Modification	
Modified Article	PCB Ass'y-NCU					Expected Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input checked="" type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					After the old parts are out of stock.	
						Execution Date	
	The IC - Photocoupler on the NCU has been changed. This is because it has been difficult to buy the old photocouplers.						

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0536023D	H0536023E	PCB Ass'y - NCU	1 - 1	O / O		42	3
H0536026E	H0536026F	PCB Ass'y - NCU	1 - 1	O / O		42	3
H0536029B	H0536029C	PCB Ass'y - NCU	1 - 1	O / O		42	3
14030642	14030741	IC - Photocoupler	(1 - 1)				

(Asia, Europe only)

Reference No. for this MB

QECR	
ECN No.	91090082

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9101381

MODIFICATION BULLETIN NO. C-076ISSUED ON May 8th, 1992

Model	FAX77/80/85/86	Date of Modification
Modified Article	Cover-SB-4	Expected Date
Reason for Modification	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date
		From the 1st production of February.
The SB-4 cover has been deleted. The FCU cover has been changed already (Please refer to the MB C-037). The new FCU cover does not need the SB-4 cover		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0532176	--	Cover - SB-4	1 - 0			28	3

(North America only)

Reference No. for this MB

QECR	
ECN No.	91090110

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9101382

MODIFICATION BULLETIN NO. C-077ISSUED ON May 8th, 1992

Model	FAX77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	Exposure Glass Holder	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	From the 1st production of November.
		Execution Date

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
		(All models except FAX82)					
H0531182	H0841113	Holder - Exposure Glass: Front	1 - 1	O / O		58	2
H0531183	H0841114	Holder - Exposure Glass: Rear	1 - 1	O / O		59	2
		(FAX82)					
H0531184	H0841113	Holder - Exposure Glass: Front	1 - 1	O / O		58	2
H0531185	H0841114	Holder - Exposure Glass: Rear	1 - 1	O / O		59	2

Reference No. for this MB

QECR	
ECN No.	91090148

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

E9101386

MODIFICATION BULLETIN NO. C-078ISSUED ON May 8th, 1992

Model	FAX77, infotec 6212/6213					Date of Modification					
Modified Article	Thermal Head					Expected Date					
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					From the 1st production of October.					
						Execution Date					
	The vender of the thermal head has stopped producing the thermal head. So, we have changed the thermal head.										
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0535200	H0535203B	Thermal Head - A4	1 - 1	O / O		97	2				
(Europe only)											
Reference No. for this MB											
<table border="1"> <tr> <td>QECR</td> <td></td> </tr> <tr> <td>ECN No.</td> <td>91100001</td> </tr> </table>								QECR		ECN No.	91100001
QECR											
ECN No.	91100001										
<div style="text-align: right;"> H.Motojima Assistant General Manager FTS Sect. TS Dept. </div>											

E9101393

MODIFICATION BULLETIN NO. C-079ISSUED ON May 8th, 1992

Model	FAX82					Date of Modification					
Modified Article	Stamper Ass'y					Expected Date					
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other					After the old parts are out of stock.					
						Execution Date					
	The stamper ass'y has been changed for part standardization with other models.										
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog					
						Index No.	Page				
H0545033	H0725214A	Stamper Ass'y	1 - 1	O / O		34	2				
(Asia only)											
Reference No. for this MB											
<table border="1"> <tr> <td>QECR</td> <td> </td> </tr> <tr> <td>ECN No.</td> <td>91100022</td> </tr> </table>								QECR		ECN No.	91100022
QECR											
ECN No.	91100022										
<div style="text-align: right;"> H.Motojima Assistant General Manager FTS Sect. TS Dept. </div>											

MODIFICATION BULLETIN NO. C-080

ISSUED ON May 8th, 1992

Model	FAX 77/80/85/82, infotec 6212/6213/6215, SAVINFAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	Stepped screw	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input checked="" type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	From the 1st production of November.
	The stepped screw and the hexagonal nut for fixing the upper unit on the base have been changed to a retaining ring in order to facilitate assembly.	Execution Date

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0532213	--	Stepped screw - M4: Printer	1 - 0			28	1
07110040B	--	Hexagonal Nut	1 - 0				
--	07200050E	Retaining Ring - M5	0 - 1				

Reference No. for this MB


QECR	
ECN No.	91100033

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

DETAILS OF MODIFICATION



E9101396

MODIFICATION BULLETIN NO. C-081ISSUED ON May 8th, 1992

Model	FAX 77/80/85/82, infotec 6212/6213/6215, SAVIN FAX 301/331, NASHUA FAX 1040/1045	Date of Modification
Modified Article	PCB Ass'y - FCU (IC - FPD)	Expected Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly	After the old parts are out of stock. Execution Date
	<input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability	
	<input checked="" type="checkbox"/> Other	
The IC-FPD has been changed. This is because the vender of the IC-FPD has stopped producing the old type H0537102 → H0537102A		

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
		(FAX77, i-6212)					
H0516020D	H0516020E	PCB Ass'y - FCU: USA	1 - 1	O / O		44	3
H0516007P	H0516007Q	PCB Ass'y - FCU: G	1 - 1	O / O		44	3
H0516008N	H0516008P	PCB Ass'y - FCU: UK	1 - 1	O / O		44	3
H0516009P	H0516009Q	PCB Ass'y - FCU: I	1 - 1	O / O		44	3
H0516010N	H0516010P	PCB Ass'y - FCU: UN1	1 - 1	O / O		44	3
H0516014P	H0516014Q	PCB Ass'y - FCU: UN2	1 - 1	O / O		44	3
H0516011N	H0516011P	PCB Ass'y - FCU: ASIA	1 - 1	O / O		44	3

Reference No. for this MB

QECR	
ECN No.	91100111

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

MODIFICATION BULLETIN NO. C-081ISSUED ON May 8th, 1992

Old Parts No.	New Parts No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
		(FAX80, i-6213, S-301, N-1040)					
H0536006Z	H0536056	PCB Ass'y - FCU: USA	1 - 1	O / O		44	3
H0536016R	H0536016S	PCB Ass'y - FCU: SAVIN	1 - 1	O / O		44	3
H0536007Z	H0536057	PCB Ass'y - FCU: G	1 - 1	O / O		44	3
H0536008Y	H0536008Z	PCB Ass'y - FCU: UK	1 - 1	O / O		44	3
H0536009Y	H0536009Z	PCB Ass'y - FCU: I	1 - 1	O / O		44	3
H0536010X	H0536010Y	PCB Ass'y - FCU: UN1	1 - 1	O / O		44	3
H536014V	H536014W	PCB Ass'y - FCU: UN2	1 - 1	O / O		44	3
H0536011Y	H0536011Z	PCB Ass'y - FCU: ASIA	1 - 1	O / O		44	3
		(FAX82)					
H0546011Y	H0546011Z	PCB Ass'y - FCU: FAX82	1 - 1	O / O		44	3
		(FAX85, i-6215, S-331, N-1045)					
H0556006W	H0556006X	PCB Ass'y - FCU:USA	1 - 1	O / O		44	3
H0556016R	H0556016S	PCB Ass'y - FCU:SAVIN	1 - 1	O / O		44	3
H0556037A	H0556037B	PCB Ass'y - FCU:G	1 - 1	O / O		44	3
H0556038A	H0556038B	PCB Ass'y - FCU:UK	1 - 1	O / O		44	3
H0556039A	H0556039B	PCB Ass'y - FCU:I	1 - 1	O / O		44	3
H0556040A	H0556040B	PCB Ass'y - FCU:UN1	1 - 1	O / O		44	3
H0556007Z	H0556057	PCB Ass'y - FCU:G	1 - 1	O / O		44	3
H0556008Y	H0556008Z	PCB Ass'y - FCU:UK	1 - 1	O / O		44	3
H0556009Y	H0556009Z	PCB Ass'y - FCU:I	1 - 1	O / O		44	3
H0556010X	H0556010Y	PCB Ass'y - FCU:UN1	1 - 1	O / O		44	3
H0556014S	H0556014T	PCB Ass'y - FCU:UN	1 - 1	O / O		44	3
H0556041A	H0556041B	PCB Ass'y - FCU:ASIA	1 - 1	O / O		44	3

MODIFICATION BULLETIN NO. C-081

ISSUED ON May 8th, 1992

[illegible]

MODIFICATION BULLETIN NO. C-082ISSUED ON July 7, 1993

Model	FAX 82	Date of Modification
Modified Article	OP-PORT	Expected Date
Reason for Modification	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	Execution Date

The following parts have been registered as a service part.

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
	H054 3112	Cover - Quick Dial	0 → 1			39	1 - 1
	H054 4313	Quick Dial Sheet	0 → 1			40	1 - 1
	H054 4318	Quick Dial Registration Sheet	0 → 1			40	1 - 1

Reference No. for this MB


QECR	--
ECN No.	--

H.Motojima

Assistant General Manager

FTS Sect. TS Dept.

DETAILS OF MODIFICATION



MODIFICATION BULLETIN NO. Multi-002ISSUED ON Oct. 15, 1995

Model	US: Fax2800L, 4000L, 7000L, 77, 80, 85, 86, 550 China: Fax3000L, 580					Date of Modification	
Modified Article	Handset					Execution Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other						
Handset and Handset Holder will not be available. Please order Handset Ass'y instead of these.							
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H5134157	H5134107	Handset Holder - US	1 → 0				
H5135128		Handset - US	1 → 0				
		Handset Ass'y - US					
H5134155	H5134105	Handset Holder - China	1 → 0				
H5135126		Handset - China	1 → 0				
		Handset Ass'y - China					
<div style="text-align: right;"> M. Iwasa Manager 2nd T.S.Sec. Int'l Marketing Group </div>							