

Model: Bellini		Date: 10-Jun-02	No.: RA294054
Subject: Printer Controller (G588) System Firmware History		Prepared by: S.Orita	
From: Technical Services sec. Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Other (Information)		

Modification history of the Printer Controller EB-105 and 105e (G588) system firmware.

Firmware Modification History

1. EB-105

1. System firmware version: 1.0.0

Patch File	Issue(s)
pdfpatch	Win 2000/98: Problems when printing downloaded PDF or PS files.

2. System firmware version: 1.0.1

Note: This version includes the patch (pdfpatch) for Version 1.0.0 and it was released as Version 1.0.1.

Patch File	Issue(s)
1-1TIC1	MSU full for Duplex print jobs.
1-21749	It takes a long time to RIP a document.
1-2HDXH	Jam problem: Part of the print image is missing after recovery.
1-2MK1N_eng	PCL5/300dpi: Print image is not correct after storing at the Document Server.

3. System firmware version: 1.0.2

Note: This version includes the patch (1-1TIC1, 1-21749, 1-2HDXH and 1- 2MK1N_eng) for Version 1.0.1 and it was released as Version 1.0.2

Patch File	Issue(s)
1-2U10T	Edge Smoothing and Auto Continue do not work correctly.

2. EB-105e

1. System firmware version: 1.1.5

Patch File	Issue(s)
1-3R284	DocBuilderPro: Print image is shifted after changing the print size
1-5GWOP	In the case of high volume data, the print performance gets slow during printing.