*** Basic Information ***
[Create date] 2019/09/19
[Program Name] Inserter_CI4040
[Version] 01.000:03
[PCB No.] D3CN5100B
[Interchangeability] X / O
[Other Firmware Requirements] None
[PCB Requirements] None
[Software category] Normal Release
[Release category] Normal Release
[Program category] Firmware
Exported to(language) GEN(all) [Firmware No.] D3CN5310B [File Information] File Name D3CN5310B.fwu File Type Module for Service Size 0.13 MB (131576 byte) [Availability of RFU] No
[Production reflection] 2019/10
*** Note ***
[Note]
*** Important Notes ***
[Important Notes]
*** Modification History ***
[Modifications made:] Rank C

Symptom corrected:When the finisher is equipped with cover interposer, roller stains might be transferred to the paper on horizontal transport path.
[Modification history]
Version 00.100:03 1st Mass production

*** Basic Information ***
[Create date] 2019/09/19
[Program Name] Inserter_CI4040
[Version] 01.000:03
[PCB No.] D3CN5100B
[Interchangeability] X / O
[Other Firmware Requirements] None
[PCB Requirements] None
[Software category] Normal Release
[Release category] Normal Release
[Program category] Firmware
Exported to(language) GEN(all) [Firmware No.] D3CN5310B [File Information] File Name D3CN5310B.fwu File Type Module for Service Size 0.13 MB (131576 byte) [Availability of RFU] No
[Production reflection] 2019/10
*** Note ***
[Note]
*** Important Notes ***
[Important Notes]
*** Modification History ***
[Modifications made:] Rank C

Symptom corrected: - When the finisher is equipped with cover interposer, roller stains mightransferred to the paper on horizontal transport path.	oller stains might be	
[Modification history]		
Version 00.100:03 1st Mass production		