# RIGOH

## Modification Bulletin

**PAGE: 1/1** 

Model: Iris/Lilac Interface kit Date			e: 15-Nov-99		No.: MA848001
Modified Article: P	arts Catalog Correction	Prepared by: T. Itoh			
From: Technical Ser	vices Dept., GTS Division				
Reason for	eason for Parts catalog correction Vendor c			🗌 To n	neet standards
Modification:		e reliability	(	)	
	Part standardization	Other			

Please correct your P/C as shown below.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8485108	A8485105	BUSSW Board			3	9	

**NOTE:** The modification has been applied to the BUSSW board and the part number has been changed from #A8485105 to #A8485108. However, #A8485105 was installed in the I/F Kit from the first mass production. This modification was implemented from March '99 production.

## RIGOH

### Modification Bulletin

#### **PAGE: 1/1**

Model: Iris/Lilac Interface Kit Date				9: 15-Nov-99		No.: MA848002	
Modified Article: B	USSW Board	Prepared by: T.Itoh					
From: Technical Ser	rvices Dept., GTS Division						
Reason for	Parts catalog correction Vendor ch		lor ch	ange	neet standards		
Modification:			e reliability	)			
	Part standardization	🛛 Othe	r				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8485105	A8485108	BUSSW Board	1	O/O	3	9	

The BUSSW board has been modified only for the Japanese version. Since the BUSSW board is a common part for all Japanese and overseas versions, the same modification was applied.

**NOTE:** Refer to RTB #014 for the problem found on the BUSSW Board (#A8485108).

MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Controller Interface	120V/ 60Hz	USA, CANADA,	A848-17	H0990300475
Туре Е		TAIWAN		
Controller Interface	220- 240V 50/60Hz	EUROPE, Asia,	A848-27	H0990300944
Туре Е		Middle East, etc.		
Lanier CI-806 AG	120V/ 60Hz	USA	A848-55	From first mass
Lanier CI-806 AH	220- 240V 50/60Hz	EUROPE, etc.	A848-65	production

## RIGOH

### Modification Bulletin

Model: Iris/Lilac Interface Kit Date				e: 15-Nov-99		No.: MA848003	
Modified Article: B	USSW Board	Prepared by: T. Itoh					
From: Technical Ser	vices Dept., GTS Division						
Reason for Modification:	<ul> <li>Parts catalog correction</li> <li>To facilitate assembly</li> <li>Part standardization</li> </ul>	Vendor cha		0	□ To n (	neet standards )	

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8485108	A8485112	BUSSW Board	1	O/O	3	9	

Some unnecessary components of this PCB, which were necessary only for the Japanese version, have been removed from the overseas versions. The part number has been changed for administration purposes.

**NOTE:** Refer to RTB #014 for the problem found on the BUSSW Board (#A8485108).

MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Controller Interface	120V/ 60Hz	USA, CANADA,	A848-17	H0990600001
Туре Е		TAIWAN		
Controller Interface	220- 240V 50/60Hz	EUROPE, Asia,	A848-27	H0990600176
Туре Е		Middle East, etc.		
Lanier CI-806 AG	120V/ 60Hz	USA	A848-55	L0409060095
Lanier CI-806 AH	220- 240V 50/60Hz	EUROPE, etc.	A848-65	L0409060180