

=====
*** Basic Information ***
=====

[Create date] 2018/07/30

[Program Name] MailBOX_NAKURU

[Version] 01.000:07

[PCB No.] M4815100B

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] M4815300B

[File Information]

File Name M4815300B.fwu

File Type Module for Service

Size 0.13 MB (131572 byte)

[Availability of RFU] No

[Production reflection] 2016/07

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom corrected:

1. After recovering from energy saver mode, the machine might stall when printing to the finisher if the finisher sends an unsupported command to the main unit.
2. The firmware suffix number is not displayed correctly on the operation panel.

[Modification history]

Version 01.000:07

1st Mass production