## RICOH

## Technical Bulletin

Model: ARDF DF2010			Date: 25-May-1		-10	No.: RB814001		
Subject: Parts Catalog Correction_APS Feeler				Prepared by: M.Saiki				
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.								
Classification:	☐ Troubleshooting	□ Part info	Part information Electrical		Action	required		
	☐ Mechanical	☐ Electric			☐ Service manual			
	☐ Paper path	☐ Transmit/rece		eive	Retrof	ofit information		
	☐ Product Safety	Other (		)	☐ Tier 2			

Incorrect	Correct part	Description	Q'ty	Int	Page	Index	Note
part number	number						
B3861121	B3861125	APS FEELER BRACKET	1 - 1	X/O	13	24	
B3861125	B3861121	APS FEELER	1 - 1	X/O	13	6	
B3861121	B3861122	RIGHT SENSOR BRACKET	1 - 1	X/O	13	#37	

#: New index

**PAGE: 1/1** 

**Change**: The indexes of the illustration were changed. **Reason**: Correction of the illustration and part numbers

## See the following diagram for the corrected illustration.

