

=====
*** Basic Information ***
=====

[Create date] 2019/10/25

[Program Name] ARDF DF2020

[Version] 01.090:05

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D6845300H

[File Information]

File Name D6845300H.fwu

File Type Module for Service

Size 0.13 MB (131568 byte)

[Availability of RFU] No

[Production reflection] 2019/11

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- Original jam might happen when custom size is specified as original size.

[Modification history]

Version 01.080:05

Rank C

Other changes:

- When the solenoid stays on for five seconds, the system will be reset and the solenoid will be turned off.

Version 01.070:05

Rank C

Symptom corrected:

- SC701-08 might occur

Version 01.060:05

Other changes:

- The ON/OFF timing of the electromagnetic clutch was changed, to reduce the load on the drive motor.
- The range of detection of Jam 14: Skew Correction Sensor was changed, to reduce the occurrences of the jam.

Version 01.030:05

1st Mass production