RICOH

Technical Bulletin

PAGE: 1/1

Model: K-C2 ADF (DF78)			Date: 21-Jul-10		10	No.: RB616001	
Subject: Parts Catalog Correction_DF78 Left Cover				Prepared by: M.Saiki			
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.							
Classification:	Troubleshooting	🛛 Part inf	Part information		Action required		
	Mechanical	Electrical Transmit/receive			Service manual revision		
	Paper path			ceive Retrofit inform		fit information	
	Product Safety	Other ()	🗌 Tier 2		


Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
	B3874841	LEFT COVER	1		3	3	

Change: An index is added to the illustration.

Reason: An index was missing from the illustration.

See the following diagram for the corrected illustration.

1.Exterior (B616)



RICOH

Technical Bulletin

PAGE: 1/1

Model: K-C2 ADF (DF78)			Date: 1-Jul-15		No.: RB616002	
Subject: Part supply unit change_Cover EXIT GUIDE PLATE				Prepared by: Y.Suzuki		
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.						
Classification:	Mechanical Paper path	 ☑ Part info ☑ Electrica ☑ Transm ☑ Other (al	Servic	n required se manual revision iit information	

Old part	New part	Description	Q'ty	Int	Page	Index
number	number					
B3873410	B3873413	COVER - EXIT GUIDE PLATE	1	O/O	9	16
	B3873414	SHIELD - TRANSMITED	1	O/O	9	16
		RUBBER STAMP				

Change: This part is supplied separately.

Reason: To comply with Import/Export regulations.

