## RICOH


## Technical Bulletin

Model: Model A	el: Model AT-C2 Color Controller E-3100 (D480) Da		Dat	ate: 19-Aug-09		No.: RD480001			
Subject: CPU Cooling Assembly					Prepared by: C.Tsuji				
From: 2nd Tech Support Sec. Service Support Dept.									
Classification:	☐ Troubleshooting	⊠ Part inf	orma	tion	Action required				
	☐ Mechanical	☐ Electric	] Electrical		☐ Service manual revision				
	☐ Paper path	☐ Transm	☐ Transmit/receive		☐ Retrofit information				
	Other ( )	☐ Tier2							

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
5K530713 \		FAN:CPU:COFAN:30-1153-02	1	O/O	5	8	See below
	`5K530714	FAN:CPU:COFAN:30-1153-03	1				

**Change/Reason:** Parts standardization.

**Note:** The new CPU cooling assembly (which is comprised of a heat sink and fan) is attached to the motherboard in the same place as the old assembly, but its orientation has been rotated 90 degrees. This is because the location of the cables on the cooling assembly was changed.



## New cooling assembly (5K530714)

**PAGE: 1/1** 

