## RICOH


## Technical Bulletin

Model: Model AP-C2 Color Controller E-5100 (D479) Dat				e: 19-Aug	-09	No.: RD479001		
Subject: CPU Cooling Assembly					Prepared by: C.Tsuji			
From: 2nd Tech	Support Sec. Service Support							
Classification:	☐ Troubleshooting	□ Part inf	orma	tion	on Action required			
	☐ Mechanical	☐ Electric	☐ Electrical ☐ Transmit/receive		☐ Service manual revision			
	☐ Paper path	☐ Transm			☐ Retrofit information			
	Other ( )	☐ Tier2						

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
5K530713 \		FAN:CPU:COFAN:30-1153-02	1	O/O	5	8	See below
	`5K530714	FAN:CPU:COFAN:30-1153-03	1				

Change/Reason: Parts standardization.

**Note:** The new CPU cooling assembly (which is comprised of a heat sink and fan) is attached to the motherboard in the same place as the old assembly, but its orientation has been rotated 90 degrees. This is because the location of the cables on the cooling assembly was changed.



## New cooling assembly (5K530714)

**PAGE: 1/1** 

