

Model: Iris2/Lilac2 Controller E-310		Date: 21-Mar-01	No.: MG938001
Modified Article: E-310 Parts Catalog Correction		Prepared by: Chisato Tsuji	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The E-310 Ver.1.1 machines (G938-04, G938-05) were released from March 2001. Therefore the Parts Catalog for the Color Controller E-310 should be changed as follows:

For details on the machine release, please refer to RTB No. **RB017008**.

Changed Parts (G938-01/02 only):

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G9389500	G9389501	Service Kit (System CD) Ver.1.1	1	X/O	3	14	
G9389500	-	E-310 Service Manual – English	-	-	3	15	This was mistakenly listed in the Parts catalog.

Cut-In Serial Numbers:

Model	Destination	Code	Serial Number
Color Controller E-310	US	G938-01	P4718700001-
	Others	G938-02	P4718750001-

Model: Iris2/Lilac2 Controller E-310

Date: 21-Mar-01

No.: MG938001

Updated Machine Configuration:

Index No.	G938-01/-02	G938-04/-05	Description:	Quantity:	Note:
1	G936 5000	G936 5000	Mother Board With CPU Fan	1	Same
2	G936 5002	G936 5002	CPU Fan Unit	1	Same
3	G936 5010	G936 5010	8.4GB IDE Hard Drive Kit	1	Same
4	G938 5020	G938 5020	128MB DIMM	G938-01 = 2 G938-02 = 2 G938-04 = 1 G938-05 = 1	Quantity is different
5	G938 5030	G938 5030	Video Board	1	Same
6	G938 5040	G938 5040	Exhaust Fan Kit	1	Same
7	G936 5044	G936 5044	Power Cable Harness	1	Same
8	G938 5060	G938 5060	SCSI Card	1	Same
9	A752 0514	A752 0514	CD- ROM Drive	1	Same
10	A752 5101	A752 5101	SCSI Cable	1	Same
11	A724 5282	A724 5282	Grayscale Strip	1	Same
12	G938 5081	G938 5181 (Ver.1.1)	User Software	1	See *2
13	G938 5082	G938 5182	Doc Pack English	1	See *1
14	G938 9501 Ver.1.1)	G938 9501 (Ver.1.1)	Service Kit (Sytem CD)	1	See *2
16	G938 5200	G938 5200	Ferrite Clamp	1	Same
Option					
17	A848 1451	A848 1451	Operation Panel - NA	1	Same
17	A848 1452	A848 1452	Operation Panel - EU	1	Same

*1: Differences in packaged contents:

Doc Pack English for G938-01, -02 P/N G9385082	Doc Pack English for G938-04,-05 P/N G9385182
Getting Started	
Configuration Guide	
Job Management Guide	
Printing Guide	
Color Guide	
Release Notes Ver.1.0	Release Notes Ver.1.1
-	User Addendum

*2: Software Interchangability (User/System)

	Interchangability	
System Software (Ver.1.0/Ver.1.1)	X/O	X/O as a set
User Software (Ver.1.0/Ver.1.1)	X/X	

Model: Iris2/Lilac2 Controller E-310		Date: 20-Jun-02	No.: MG938002
Modified Article: E-310 Spare Parts Added (BIOS ROM)		Prepared by: Chisato Tsuji	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following item has been newly registered as a spare part.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G9385136	BIOSROM:X3E:RICOH:45019962	1	-	-	-	-

Note: When replacing the motherboard, the BIOS ROM can be removed from the old board and attached to the new board. Please order this part when it is lost or defective.

Model: Iris2/Lilac2 Controller E-310		Date: 15-Oct-02	No.: MG938003
Modified Article: E-310 New System Version Release		Prepared by: Chisato Tsuji	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Due to the release of the E-310 System Ver1.11 (Sept '02), the Document Package and Service Kit have been changed as follows. For further details on the release, please refer to RTB #RG938002.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G9389501	G9389502	E-310 Service Kit V.1.11	1	X/O	2	15	
G9385182	G9385090	DOC PACK ENGLISH	1	X/X	2	13	

Areas in **bold** have been changed or added:

Service Kit

G9389501 (Old)	G9389502 (New)
<ul style="list-style-type: none"> - System CD (V.1.1) - Installation Instructions 	<ul style="list-style-type: none"> - System CD (V.1.11) - Installation Instructions - Addendum (English/German/French/Italian/Spanish)

Document Package (English)

G9385182 (Old)	G9385090 (New)
<ul style="list-style-type: none"> - Getting Started - Color Guide - Job Management Guide - Printing Guide - Release Notes 	<ul style="list-style-type: none"> - Getting Started - Color Guide - Job Management Guide - Printing Guide - Addendum - Release Notes

Production Cut-In Serial Numbers

Model	Destination	Code	Serial Number
Color Controller	US	G938-04	P472922xxxx
E-310	Others	G938-05	P4729270099