

Reissued: 22-Apr-09

Model: Finisher Adapter Type C	Date: 15-Nov-07	No.: RD375001a
--------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: Finisher Adapter Type C		Prepared by: T. Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other ()		

This RTB has been issued to announce the firmware release information for the **Finisher Adapter Type C**.

Version	Program No.	Effective Date
1.020:09	D3755104A	April 2009 production
1.00	D3755104	1st Mass production.

Version	Modified Points or Symptom Corrected
1.020:09	1. Reliability against paper jam caused by alternate output has been improved. 2. Supports the Ring Binder RB5000 used with D014/D015/D078/D079 Copiers.
1.00	1st Mass production.

Model: V-C2

Date: 21-Feb-08

No.: RD375002

Subject: Important note for harness position

Prepared by: H.Matsui

From: 2nd Tech. Support Sec. Service Support Dept.

Classification:

☐ Troubleshooting

☐ Part information

☐ Action required

☐ Mechanical

☐ Electrical

☒ Service manual revision

☐ Paper path

☐ Transmit/receive

☐ Retrofit information


☐ Other ()

Important Note about the Harness Position When Installing the Finisher Adapter Type C (D375)

The Service Manual was changed as follows (Finisher Adapter D375 Installation, pg. 161).


- **Add** the following important note:

When you attach the Finisher Adapter D375 to the Finisher SR5000, make sure to route the harness **along lines [B] and [C]** in the photo. If you do not, the harness may touch the motors ([A] and [D]), which can damage or even disconnect the harness.



INCORRECT

The harness is touching the motor.



Reissued: 15-Jan-10

Model: Finisher Adapter Type C	Date: 15-Nov-07	No.: RD375001b
--------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: Finisher Adapter Type C		Prepared by: T. Toriumi	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other ()		

This RTB has been issued to announce the firmware release information for the **Finisher Adapter Type C**.

Version	Program No.	Effective Date
<i>1.050:10</i>	<i>D3755104B</i>	<i>September 2009 production</i>
1.020:09	D3755104A	April 2009 production
1.00	D3755104	1st Mass production

Version	Modified Points or Symptom Corrected
<i>1.050:10</i>	<i>Symptom Corrected:</i> <i>1. Paper Jam (Jam Code 001 and 115).</i> <i>2. Paper Jam after the stapler is ended with staple mode.</i>
1.020:09	1. Reliability against paper jam caused by alternate output has been improved. 2. Supports the Ring Binder RB5000 used with D014/D015/D078/D079 Copier.
1.00	1st Mass production

Reissued: 19-Jan-10

Model: Finisher Adapter Type C	Date: 15-Nov-07	No.: RD375001c
--------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: Finisher Adapter Type C		Prepared by: T. Toriumi	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input checked="" type="checkbox"/> Other ()	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

This RTB has been issued to announce the firmware release information for the **Finisher Adapter Type C**.

Version	Program No.	Effective Date
<i>1.060:11</i>	<i>D3755104C</i>	<i>January 2010 production</i>
1.050:10	D3755104B	September 2009 production
1.020:09	D3755104A	April 2009 production
1.00	D3755104	1st Mass production

Version	Modified Points or Symptom Corrected
<i>1.060:11</i>	<i>Symptom Corrected:</i> <i>1. Printing can't be started when SC750 and SC721 have occurred.</i> <i>Other Changes:</i> <i>1. Firmware modified to support V-C3.</i>
1.050:10	Symptom Corrected: 1. Reliability against the Paper Jam (Jam Code 001 and 115). 2. Reliability against the Paper Jam after the stapler is ended with staple mode.
1.020:09	1. Reliability against paper jam caused by alternate output has been improved. 2. Supports the Ring Binder RB5000 used with D014/D015/D078/D079 Copier.
1.00	1st Mass production

Reissued: 01-Oct-10

Model: Finisher Adapter Type C	Date: 15-Nov-07	No.: RD375001d
--------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: Finisher Adapter Type C		Prepared by: T. Toriumi	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required		
	<input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision		
	<input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information		
	<input checked="" type="checkbox"/> Other ()		

This RTB has been issued to announce the firmware release information for the **Finisher Adapter Type C**.

Version	Program No.	Effective Date
<i>1.080:12</i>	<i>D3755104D</i>	<i>October 2010 production</i>
1.060:11	D3755104C	January 2010 production
1.050:10	D3755104B	September 2009 production
1.020:09	D3755104A	April 2009 production
1.00	D3755104	1st Mass production

Version	Modified Points or Symptom Corrected
<i>1.080:12</i>	<i>Symptom corrected:</i> <i>SC990 occurs under the following conditions.</i> <i>Occurrence conditions: Original size is 8K, Z-Fold, Stapling.</i> <i>System: V-C3+FD5000+SR5000.</i>
1.060:11	Symptom Corrected: 1. Printing can't be started when SC750 and SC721 has occurred. Other Changes: 1. Firmware modified to support V-C3.
1.050:10	Symptom Corrected: 1. Reliability against the Paper Jam (Jam Code 001 and 115). 2. Reliability against the Paper Jam after the stapler is ended with staple mode.
1.020:09	1. Reliability against paper jam caused by alternate output has been improved. 2. Supports the Ring Binder RB5000 used with D014/D015/D078/D079 Copier.
1.00	1st Mass production

Reissued: 01-Feb-12

Model: Finisher Adapter Type C	Date: 15-Nov-07	No.: RD375001e
--------------------------------	-----------------	----------------

RTB Reissue

The items in bold italics have been added.

Subject: Firmware Release Note: Finisher Adapter Type C		Prepared by: T. Toriumi	
From: 1st Tech Service Sect., MFP/Printer Tech Service Dept			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other ()		

This RTB has been issued to announce the firmware release information for the **Finisher Adapter Type C**.

Version	Program No.	Effective Date
<i>01.090:13</i>	<i>D3755104E</i>	<i>January 2012 production</i>
1.080:12	D3755104D	October 2010 production
1.060:11	D3755104C	January 2010 production
1.050:10	D3755104B	September 2009 production
1.020:09	D3755104A	April 2009 production
1.00	D3755104	1st Mass production

Version	Modified Points or Symptom Corrected
<i>01.090:13</i>	<i>Symptom corrected: Paper Jam occurred at GBC entrance area.</i>
1.080:12	Symptom corrected: SC990 occurs under the following conditions. Occurrence conditions: Original size is 8K, Z-Fold, Stapling. System: V-C3+FD5000+SR5000.
1.060:11	Symptom Corrected: 1. Printing can't be started when SC750 and SC721 has occurred. Other Changes: 1. Firmware modified to support V-C3.
1.050:10	Symptom Corrected: 1. Reliability against the Paper Jam (Jam Code 001 and 115). 2. Reliability against the Paper Jam after the stapler is ended with staple mode.
1.020:09	1. Reliability against paper jam caused by alternate output has been improved. 2. Supports the Ring Binder RB5000 used with D014/D015/D078/D079 Copier.
1.00	1st Mass production