RICOH

Modification Bulletin

PAGE: 1/1

Model: Model U-P1 Hard Disk			Da	Date: 4-Dec-07		No.: MG315001		
Modified Article: HDD				Prepared by: H.K.				
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	☐ Parts catalog correction			ange	Other			
Modification:	☐ To facilitate assembly	☐ To improve reliat		e reliability	☐ To me	et standards		
	☐ Part standardization	☐ Product Safety		afety	()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3085950	B5145960	HDD:HITACHI:40GB:VANCOUV ER2	1- 1	0/0	3	2	
B5145960	B5145970	HDD:HITACHI:40GB:VANCOUV ER3	1- 1	0/0	3	2	
B5145970	B5145990	HDD:HITACHI:40GB:PATH:ROH	1- 1	0/0	3	2	
B5145990	B1795995	HDD:HITACHI:40GB:PATH- KAI:ROHS	1- 1	0/0	3	2	
B1795995	B2475238	HDD:PATH2:40GB_CLIP:MAST ER	1- 1	0/0	3	2	

Change: The vendor has updated the HDD five times. **Reason:** Production was stopped on the older versions.

Important: Do not install an 80GB HDD on this model. If you do, image problems may occur or the machine may stall. The newest HDD (P/N B2475238) functions as a 40GB HDD, even though the actual capacity is 80GB.