

Model: Kir-C2 Fax Option (B620)		Date: 20-Jul-04	No.: MB620001
Modified Article: Fax Cover		Prepared by: M. Ishihara	
From: 1 st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Please note the following changes:

1. A vinyl bag was added to the Fax Cover for more protection.

Note: This is the only difference, so both the new and old parts can be used in the field.

2. The page number for the Fax Cover was corrected:

Incorrect: pg. 12

Correct: pg. 3

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6201421	B6201415	Fax Cover NA	1-1	O/O	3	3	
B6201450	B6201422	Fax Cover EU	1-1	O/O	3	3	

Model: Kir-C2 Fax Option		Date: 4-Aug-04	No.: MB620002
Modified Article: PCB GWFCU3		Prepared by: H.Yokoyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input checked="" type="checkbox"/> To meet standards (EMI)

The PCB GWFCU3 has been modified for the following reasons.

- The noise margin has been increased to meet EMI standards.
- To include a jumper on the PWB pattern.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6205172	B1685172	PCB GWFCU3 NA Ass'y	1	X/O	2	8	
B6205174	B1685174	PCB GWFCU3 EU Ass'y	1	O/O	2	8	

Cut in serial number: April '04 production.

Reissued: 8-Sep-04

Model: Kir-C2 Fax Option	Date: 4-Aug-04	No.: MB620003a
--------------------------	----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: FAX Option : PCB GWFCU3		Prepared by: H.Yokoyama	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Symptom

Black stripe appears at the time of image rotation.
 Fax option (FCU) is not detected
 SC820 (~~still under investigation~~)

Modification

1 x Resistor has been removed
 1 x Jumper has been added

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
<i>B1685172</i>	<i>B1685182</i>	PCB GWFCU3 NA Ass'y	1	X/O	2	8	
<i>B1685174</i>	<i>B1685184</i>	PCB GWFCU3 EU Ass'y	1	X/O	2	8	

Cut in Serial Number

This modification will be applied to mass production from July 1st.
 The cut in serial number information is as follows.

B620-27 : J9346700543
 B620-17 : J9346703578
 B620-29 : J9346700001
 B620-21 : no production in July
 B620-19 : from 22nd July

Additional information for the June production (see below for details)

The following fax options contain the modified FCU

B620-17 (1017 units)

J346604774-4846, 4852, 4860, 4869, 4876, 4915-4984, 4994, 5002, 5011, 5023, 5036, 5048, 5053, 5056-5145, 5147-5157, 5159-5164, 5166-5175, 5177-5182, 5322-5324, 5326-5333, 5335-5341, 5343-5373, 5375-5389, 5391-5401, 5403-5411, 5413-5419, 5421-5425, 5427, 5428, 5430-5438, 5696-5706, 5708-5714, 5716-5721, 5723-5735, 5737-5744, 5746-5751, 5753-5759, 5761-5766, 5909, 5916, 5924, 5932, 5941, 5974, 5982, 5990, 5998-6068, 6070-6077, 6079-6094, 6096-6156, 6159, 6161, 6162, 6165, 6167, 6169, 6170, 6173, 6174, 6176, 6185, 6195, 6203, 6216, 6237, 6259-6648

Reissued: 8-Sep-04

Model: Kir-C2 Fax Option	Date: 4-Aug-04	No.: MB620003a
--------------------------	----------------	----------------

B620-21 (2 units)

J346600106, 0111

B620-27 (1043 units)

J346601795, 1806, 1828, 1845, 1975, 1988, 2005, 2011, 2020, 2032, 2045, 2056,
2071-2231, 2233-2246, 2248-2251, 2253-2261, 2263-2266, 2430, 2527-2535, 2537-
2545, 2547-2564, 2566-2571, 2573-2582, 2584-2594, 2596-2602, 2604-2609, 2611-
2617, 2619-2714, 2716, 2718-2727, 2733, 2734, 2737, 2739-2803, 2819, 2827, 2836,
2845, 2850-3114, 3116, 3125, 3136, 3143, 3154, 3165, 3185, 3195, 3203, 3213, 3222,
3254-3553

B620-29 (20 units)

J346600338, 0403, 0404, 0406-0410, 0412-0414, 0417, 0421, 0424-0428, 0433, 0435



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Kir-C2 Fax Option	B620	200903		B6205080	B1685080	PCB MBU	2	2	O/O		3	9					V0803654