

Model: R-C2 LCT (PS500)		Date: 8-Sep-09	No.: RB391001
Subject: Caster		Prepared by: S. Tomoe	
From: 2nd Tech Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other () <input type="checkbox"/> Tier 2		


Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A5071096		Pan Head Screw M5x5	16-8		3	21	A
AH012036	D3511120	Caster: Dia50H59: Stopper: Yes	4-2	O/O	3	20	A, B
	D3511121	Caster: Dia50H59: Stopper: No	0-2		3	36	A

Note A

Change/Reason: Parts Catalog Correction

Note B

Change/Reason: Parts standardization.



Model: R-C2 LCT (PS500)		Date: 16-Sept-10	No.: RB391002
Subject: Part Number Correction		Prepared by: T. Nihei	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

Please apply the following change to your Parts Catalogs.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
AW020160	AW020175	PHOTOINTERRUPTOR:PAPER VOLUME SENSOR			7	12	

