

=====
*** Basic Information ***
=====

[Create date] 2018/02/02

[Program Name] RingBinder_RB5020_B2

[Version] 01.000:03

[PCB No.] D7375620

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D7375520

[File Information]

File Name D7375520.fwu

File Type Module for Service

Size 0.25 MB (262976 byte)

[Availability of RFU] No

[Production reflection] 1st Mass Production

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====

[Modifications made:]
Rank D

1st Mass production

[Modification history]

=====
*** Basic Information ***
=====

[Create date] 2018/02/07

[Program Name] RingBinder_RB5020_B1

[Version] 01.500:06

[PCB No.] D7375603

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D7375510C

[File Information]

File Name D7375510C.fwu

File Type Module for Service

Size 0.25 MB (262976 byte)

[Availability of RFU] No

[Production reflection] 2014/12

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank D

Software bugs were fixed before the mass production of Leo-C1/P1.

[Modification history]

Version 01.200:05

Error Correction:

The system might continue to be wait mode, when jam occurs on
peripherals connected downstream of RB5020 which is in wait mode.

Version 01.100:05

1st Mass production