

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2018/05/24  
-----

[Program Name] Feed\_IFBox  
-----

[Version] 01.000:03  
-----

[PCB No.] M4625400C  
-----

[Interchangeability] X / O  
-----

[Other Firmware Requirements] None  
-----

[PCB Requirements] None  
-----

[Software category] Normal Release  
-----

[Release category] Normal Release  
-----

[Program category] Firmware  
-----

Exported to(language) GEN(all)

[Firmware No.] M4625520

[File Information]

File Name        M4625520.fwu

File Type        Module for Service

Size             0.17 MB ( 178492 byte )

[Availability of RFU] No  
-----

[Production reflection] 2018/06  
-----

=====  
\*\*\* Note \*\*\*  
=====

[Note]  
  
-----

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]  
  
-----

=====  
\*\*\* Modification History \*\*\*  
=====

=====

[Modifications made:]  
Rank D

1st Release

-----

[Modification history]

=====  
**\*\*\* Basic Information \*\*\***  
=====

[Create date] 2018/10/23  
-----

[Program Name] Fin\_IFBox  
-----

[Version] 01.010:02  
-----

[PCB No.] M4625400C  
-----

[Interchangeability] X / O  
-----

[Other Firmware Requirements] None  
-----

[PCB Requirements] None  
-----

[Software category] Normal Release  
-----

[Release category] Normal Release  
-----

[Program category] Firmware  
-----

Exported to(language) GEN(all)

[Firmware No.] M4625510A

[File Information]

File Name        M4625510A.fwu

File Type        Module for Service

Size             0.20 MB ( 206396 byte )

[Availability of RFU] No  
-----

[Production reflection] 2016/02  
-----

=====  
**\*\*\* Note \*\*\***  
=====

[Note]  
  
-----

=====  
**\*\*\* Important Notes \*\*\***  
=====

[Important Notes]  
  
-----

=====  
**\*\*\* Modification History \*\*\***  
=====

[Modifications made:]

Supported:

- Pro C72xx series

- Pro C92xx series

-----  
[Modification history]

-----  
Version 01.010:02

Specification Change:

1. Line speed data is transferred to third party vendor peripherals.

Symptom corrected:

1. When connected to a third party vendor peripheral, "Printing" status falsely remains displayed on the control panel.
2. Falsely sends on-line status to the engine without receiving on-line status from third party vendor peripheral.
3. If printing stops during a booklet job (stapling, ring binding, perfect binding) and resumes, part of the job is duplicated.
4. Time-out jam (J225) occurs before reaching the set time-out.
5. The operation panel does not display the part number of custom RPIP Interface Box Type S3 firmware.

-----  
Version 01.000:02

1st Mass production