

Model: Russian-C4.5 Printer/Scanner Unit Type 3010(D310/D313)		Date: 7-Jul-08	No.: MD310001
Modified Article: HDD		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety    (      )		

Old part number	New part number	Description	Q'ty	Int	Page	Index
B0955763		HD:TOSHIBA:MK4032GAX:ROHS	1-1	X/O	3	3
	B0955764	HD:FUJITSU:MHW2040AT:ROHS				

**Change:** The part number of the HDD unit was changed.

**Reason:** The old HDD was discontinued from production.

**Important:** When you install the new HDD for the first time, update the Controller firmware to the following version or newer:

Firmware Number: **D0065931H**

Version: **1.07**